

Exhibit No:
Issue: Worn or Deteriorated Condition of
Replaced Facilities
Witness: Timothy H. Goodson
Type of Exhibit: Direct Testimony
Sponsoring Party: Spire Missouri Inc.
Case No.: GO-2021-0030

Date Prepared: August 14, 2020

SPIRE MISSOURI INC.

File No. GO-2021-0030

DIRECT TESTIMONY

OF

TIMOTHY H. GOODSON

August 2020

TABLE OF CONTENTS

I.	PURPOSE OF TESTIMONY & ISRS BACKGROUND	2
II.	CAST IRON AND BARE STEEL GENERALLY	3
III.	FIELD CONDITIONS OF SPIRE'S CAST IRON AND BARE STEEL PIPE	5
IV.	CONDITION OF PHYSICAL EVIDENCE IN THIS CASE	10

DIRECT TESTIMONY OF TIM GOODSON

1 **Q. PLEASE STATE YOUR NAME AND BUSINESS ADDRESS.**

2 A. My name is Timothy Goodson, and my business address is 700 Market Street, St. Louis,
3 Missouri, 63101.

4 **Q. WHAT IS YOUR PRESENT POSITION?**

5 A. I am presently employed by Spire Missouri (“Spire Missouri” or “Company”) as Vice
6 President – Field Operations.

7 **Q. PLEASE STATE HOW LONG YOU HAVE HELD YOUR POSITION AND**
8 **BRIEFLY DESCRIBE YOUR RESPONSIBILITIES.**

9 A. I was appointed to my current position in 2015. In this capacity, I oversee all field
10 operations of the company, including physical pipeline installation and replacement.

11 **Q. PLEASE DESCRIBE YOUR EXPERIENCE WITH SPIRE MISSOURI PRIOR TO**
12 **ASSUMING YOUR CURRENT POSITION.**

13 A. From 2013-2014, I was the Company’s Managing Director of Environmental, Health,
14 Safety and Emergency Management.

15 **Q. WHAT OTHER EXPERIENCE DO YOU HAVE WITH REGARDS TO PIPELINE**
16 **OPERATIONS AND SAFETY?**

17 A. Prior to joining the Company, I held various positions at AGL Resources, Inc. (now part
18 of Southern Company). Most recently, I served as the Vice President of Operations of
19 Nicor Gas, a natural gas LDC serving approximately two million customers in the Chicago
20 area, with over 32,000 miles of pipeline. I previously held the positions of Vice President
21 of Midstream Operations and Projects, and Managing Director of Environmental, Health,

1 Safety and Emergency Management, both for AGL Resources, Inc. In total, I have 42
2 years of experience in the energy, chemicals, and environmental engineering industries.

3 **Q. WHAT IS YOUR EDUCATIONAL BACKGROUND?**

4 A. I received a Bachelor of Science degree from Clemson University in 1976, and a Masters
5 of Science degree from University of South Carolina in 1981.

6 **Q. HAVE YOU PREVIOUSLY TESTIFIED BEFORE THIS COMMISSION?**

7 A. No.

8 **I. PURPOSE OF TESTIMONY**

9 **Q. WHAT IS THE PURPOSE OF YOUR TESTIMONY IN THIS**
10 **PROCEEDING?**

11 A. The purpose of my direct testimony is to provide general background on the condition of
12 cast iron and bare steel pipes in the Spire distribution system, based upon my personal
13 observation of these facilities in the field, my experience with Spire's engineering
14 department findings, my observation of specimens removed for testing and inspection, and
15 the experience of the field teams I oversee.

16 **ISRS STATUTE**

17 **Q. WILL YOU PLEASE DESCRIBE, IN GENERAL TERMS, THE ISRS**
18 **MECHANISM.**

19 A. In 2003, the Missouri legislature enacted the ISRS statute to allow for certain infrastructure
20 replacement costs to be recovered by utilities more quickly and outside of a general rate
21 case. Among other things, the ISRS legislation addressed a safety issue previously
22 identified by the Commission related to aged cast iron and bare steel pipes. It also reduces

1 the regulatory cost of frequent rate cases and ensures that utility companies are able to
2 attract investor capital to fund these multimillion-dollar efforts.

3 **Q. HOW HAS THE ISRS STATUTE IMPACTED SPIRE AND MISSOURI?**

4 A. At Spire, safety is our top priority. The ISRS mechanism has played a valuable role in
5 supporting our efforts to accelerate the replacement of aged cast iron and bare steel
6 infrastructure. In the past 10 years, pipeline replacement in Missouri has accelerated
7 considerably. During this period, Spire has replaced more than 2,400 miles of aging
8 pipeline across the state through the ISRS, and has reduced the anticipated time to complete
9 its cast iron replacement program from 80-plus years to approximately 25 years. Without
10 mechanisms such as the ISRS, which ease the financial burden of deploying large amounts
11 of capital between rate cases, this magnitude of investment would not be possible. At the
12 same time, the systematic replacement approach has substantially reduced the long-term
13 cost of eliminating these problematic facilities while lower commodity costs and lower
14 interest rates have further helped to reduce the burden on our customers.

15 **Q. EXPLAIN HOW THE COMPANY'S ISRS FILINGS AND THE REPLACEMENT**
16 **OF CAST IRON AND BARE STEEL INFRASTRUCTURE ARE RELATED?**

17 A. Spire's systematic cast iron and bare steel main replacement programs are major
18 components of its ISRS filings. These programs are designed to comply with the
19 Commission's rules mandating the replacement of aged cast iron and bare steel
20 infrastructure, found at 20 CSR 4240-40.030(15). These safety rules were promulgated by
21 the Commission in 1989 after several gas explosions involving bare steel service and yard
22 lines; however, as acknowledged by the Commission in Case Nos. GO-2019-0115 and GO-
23 2019-0116, Spire has been actively engaged in replacing cast iron and steel pipes since the

1 1950's. Spire employs a systematic, neighborhood approach to conducting these programs
2 which has resulted in improved system integrity and reliability, efficient operations and
3 customer savings related to not only the replacements themselves, but also by reducing the
4 ongoing maintenance needs and operating costs of the Company's distribution system.

6 **CAST IRON AND BARE STEEL**

7 **Q. PLEASE EXPLAIN THE PROBLEMATIC CHARACTERISTICS OF CAST IRON**
8 **AND BARE STEEL PIPE.**

9 A. There is no question that there are clear safety-related concerns regarding aging cast iron
10 and bare steel infrastructure. The cast iron and bare steel pipes being retired or replaced as
11 part of Spire's ISRS projects are 50-100+ years old. While there has certainly been an
12 increased focus in more recent years on eliminating cast iron and bare steel pipe given
13 some of the very serious incidents that have occurred involving such facilities, it is
14 important to recognize that the problematic characteristics of these facilities has been
15 known for some time. Cast iron facilities experience graphitic corrosion that weakens their
16 integrity without impacting wall thickness, whereas uncoated "bare" steel facilities
17 experience oxidative and reductive corrosion, even where cathodic protection has been
18 later applied.

19 **Q. ARE THE CONCERNS REGARDING CAST IRON AND BARE STEEL PIPE**
20 **SHARED BY FEDERAL REGULATORY ORGANIZATIONS AND THE**
21 **NATURAL GAS INDUSTRY?**

22 A. Yes. It is widely accepted by leading industry experts and organizations, as well as the
23 scientific community, that there are significant risks associated with cast iron and bare steel

1 infrastructure and that there is an acute need to implement aggressive programs to remove
2 this pipe from service. Following tragic incidents in 2010 and 2011, the Secretary of the
3 Department of Transportation, Ray LaHood, sent letters to Governors of each state inviting
4 them and others to a DOT Pipeline Safety Forum at DOT's Washington headquarters to
5 address these issues. Spire representatives attended and participated in this forum.
6 Similarly, a letter was sent to utility commissioners urging them to review their State's
7 replacement plans (for cast iron and bare steel specifically) and "consider what would be
8 necessary to accelerate these plans." (March 31, 2011 letter from Cynthia Quarterman,
9 DOT Administrator). The stated goal of the DOT's April 2011 Pipeline Safety Forum was
10 "accelerating the rehabilitation, repair, and replacement of critical pipeline infrastructure
11 with known integrity risks."

12 **Q. PLEASE CONTINUE.**

13 A. Also in 2011, the federal Pipeline and Hazardous Materials Safety Administration
14 ("PHMSA") issued a White Paper reviewing the programs available in various states "to
15 support efforts to accelerate the repair, rehabilitation and replacement of high-risk
16 infrastructure in pipeline systems..." PHMSA looked favorably upon Missouri's ISRS
17 Statute as one of the programs available to protect the public "by ensuring the prompt
18 rehabilitation, repair, or replacement of high-risk gas distribution infrastructure." PHMSA
19 further urged State commissions to "accelerate the repair, rehabilitation, and replacement
20 of high-risk pipeline infrastructure." (PHMSA White Paper, p. 17). In March 2012,
21 PHMSA issued an Advisory Bulletin to gas operators and state pipeline safety
22 representatives on Cast Iron Pipe. The Bulletin urged pipeline operators, like Spire, to
23 conduct a comprehensive review of their cast iron distribution pipelines and replacement

1 programs, and accelerate the pipeline repair, rehabilitation, and replacement of high-risk
2 pipelines. The Bulletin also requested that agencies consider enhancements to cast iron
3 replacement plans and programs.

4 **Q. HOW HAVE STATES AND THE NATURAL GAS INDUSTRY RESPONDED TO**
5 **THESE CALLS TO ACTION?**

6 A. According to the American Gas Association, over 40 state jurisdictions have mechanisms
7 in place similar to Missouri's ISRS and the heightened awareness of this issue combined
8 with effective cost recovery mechanisms has facilitated billions of dollars in utility
9 investment in replacing aging, high risk cast iron and bare steel pipe. In fact, gas utilities
10 throughout the country have been replacing their cast iron and bare steel facilities on the
11 same accelerated pace as Spire – another factor that broadly confirms the deteriorated
12 condition of such facilities.

13 **FIELD CONDITIONS OF SPIRE'S CAST IRON AND BARE STEEL**

14 **Q. WHAT OPPORTUNITIES HAVE YOU HAD TO VIEW SPIRE'S CAST IRON**
15 **AND BARE STEEL FACILITIES IN PERSON.**

16 A. During my tenure as Vice President of Field Operations for Spire, I have visited hundreds
17 of job sites at which crews under my direction are engaged in strategic replacement of
18 Spire's cast iron and bare steel facilities. I have observed the condition of these facilities
19 on site, as they are exposed for abandonment. I have also observed numerous specimens
20 of these facilities that have been removed from service for testing and analysis.

21 **Q. PLEASE DESCRIBE THE TYPICAL CONDITION OF CAST IRON MAINS IN**
22 **SPIRE'S DISTRIBUTION SYSTEM.**

1 A. Spire’s distribution systems still utilizes cast iron mains, in both the Missouri East and
2 Missouri West operating units. These facilities are typically between 60 and 110 years old,
3 with most exceeding their estimated service life. The facilities tend to be located in older,
4 and often more economically disadvantaged areas of our service territories. Because they
5 utilize lower operating pressures, these pipes are larger in diameter than equivalent modern
6 facilities. They have been subjected to many years of freeze-thaw cycles and associated
7 frost heave. When originally installed, the joints were sealed using a rope-like material
8 called oakum that has now worn out and in many cases is no longer functional. Essentially
9 all of Spire’s cast iron facilities exhibit evidence of graphitic corrosion, in which the
10 structural iron leaches out of the pipe. This leaves the cast iron pipes very brittle and likely
11 to crack easily. Their large diameter, rigidity, and exposure to Midwestern freeze-thaw
12 cycles all exacerbate this problem, and lead to much higher leak rates than any other
13 material in the Spire distribution system.

14 **Q. DO YOU HAVE AN OPINION REGARDING WHETHER CAST IRON PIPES IN**
15 **SPIRE’S SYSTEM ARE “WORN OUT OR IN A DETERIORATED CONDITION”?**

16 A. Yes. Many of the cast iron mains in Spire’s distribution systems are completely worn out
17 and at the end of their useful life. All cast iron mains in Spire’s distribution system are in
18 a deteriorated condition.

19 **Q. WHY DO YOU THINK ALL OF SPIRE’S CAST IRON FACILITIES ARE IN A**
20 **DETERIORATED CONDITION?**

21 A. It’s a combination of age and the action of the elements on these materials over time. I
22 haven’t seen a single piece of cast iron pipe in Spire’s system that did not exhibit signs of
23 graphitic corrosion and oakum deterioration. These materials were simply never intended

1 to last, or remain in service, indefinitely. Our field crews have experienced numerous
2 situations in which the dirt surrounding the cast iron main was the only thing holding the
3 pipe together. As soon as the crew excavated dirt below the pipe, it just collapsed into
4 pieces.

5 **Q. PLEASE DESCRIBE THE TYPICAL CONDITION OF UNCOATED “BARE”**
6 **STEEL FACILITIES IN SPIRE’S DISTRIBUTION SYSTEM?**

7 A. The bare steel pipes in Spire’s system were typically installed between 1920 and 1960.
8 They were not installed with any protective coating, meaning that the steel pipes’ walls are
9 in direct and constant contact with the soil matrix. Steel corrodes when it comes in contact
10 with water, through both oxidative and reductive processes. In the Midwest, soils are
11 typically wet at least part of the year, and exhibit wet-dry cycling. This results in significant
12 corrosion of the uncoated “bare” steel pipe in the Spire distribution system. These
13 corrosive processes weaken the structure of the steel pipe, and compromise its integrity
14 over time. In the worst cases, holes develop in the pipe wall itself where the material has
15 completely corroded through. Over time, this makes uncoated “bare” steel pipe susceptible
16 to leaks and other failures. We experience that frequently in the field. Uncoated “bare”
17 steel pipes have a much higher leak rate than modern pipe materials, and exhibit the second
18 highest leak rate (behind only cast iron) of all materials in the Spire distribution system.

19 **Q. DO YOU HAVE AN OPINION REGARDING WHETHER BARE STEEL PIPES IN**
20 **SPIRE’S SYSTEM ARE “WORN OUT OR IN A DETERIORATED CONDITION”?**

21 A. Yes. Some portion of the uncoated “bare” steel in Spire’s system is worn out. Those would
22 be sections with active leaks resulting from wall failure due to corrosion. But certainly all
23 uncoated “bare” steel pipe in Spire’s distribution system is in a deteriorated condition.

1 These pipes began to deteriorate almost immediately after they were installed, because they
2 were not installed with any type of protective coating that would have slowed or prevented
3 interaction with soil moisture. The oxidative and reductive processes would have begun
4 to work on these facilities immediately, and progressed unabated for many years.

5
6 **CONDITION OF PHYSICAL EVIDENCE IN THIS CASE**

7 **Q. HAVE YOU REVIEWED THE PHYSICAL EVIDENCE SUBMITTED IN THESE**
8 **CASES?**

9 A. Yes. The physical evidence presented in these cases consist of samples of cast iron pipe
10 that were pulled from the field under my direction by field crews in Spire East. After it
11 was removed from the field, the physical samples were assembled at our Shrewsbury
12 Service Center and photographed. I inspected the photographs the week of August 10,
13 2020, and will inspect the physical samples prior to the hearing in these cases

14 **Q. PLEASE DESCRIBE THE PHYSICAL EVIDENCE.**

15 A. The physical evidence consists of two pallets of samples of pipe from Spire East. The
16 pallets include numerous samples of cast iron pipes. These samples are all connected to
17 ISRS projects from the Company's ISRS filings at issue in these cases.

18 **Q. HOW DID THE COMPANY DETERMINE WHAT SAMPLES TO SUBMIT AS**
19 **EVIDENCE IN THESE CASES?**

20 A. We tried to obtain samples from a variety of areas in our service territory as well as samples
21 that represented some of the Company's larger replacement projects. Please see Schedule
22 THG-1 for detailed information pertaining to the pipe samples, including work order
23 numbers, footage of pipe replaced, and location where pipe was removed from.

1 **Q. WHEN WERE THE 2018 PIPE SAMPLES OBTAINED BY SPIRE?**

2 A. The pipe samples were retrieved in July and August 2020.

3 **Q. ARE THE PIPE SAMPLES IN THE SAME OR SUBSTANTIALLY SIMILAR**
4 **CONDITION TODAY AS THEY WERE WHEN REMOVED FROM SERVICE?**

5 A. Yes. Given the advanced age of these pipes, the amount of wear and deterioration in the
6 short time between their removal from service and the present would not have materially
7 changed their condition.

8 **Q. HAVE YOU REVIEWED THE PHOTOGRAPHS OF THESE SAMPLES,**
9 **SUBMITTED WITH YOUR TESTIMONY AND LABELED AS THG- 2 FIGURES**
10 **1 THROUGH 43?**

11 A. Yes.

12 **Q. DO THESE FIGURES CONTAIN A TRUE AND ACCURATE DEPICTION OF**
13 **THE SAMPLES YOU'RE REFERRING TO?**

14 A. Yes.

15 **Q. DO YOU BELIEVE THIS EVIDENCE IS REPRESENTATIVE OF THE FIELD**
16 **CONDITION OF CAST IRON PIPE IN SPIRE'S DISTRIBUTION SYSTEM**
17 **GENERALLY?**

18 A. Yes, absolutely. There is nothing unique about the pipe samples taken for this case. They
19 are very representative of the condition of the facilities replaced in the course of our
20 systematic replacement programs. They aren't the "best of the best" or the "worst of the
21 worst;" they are a representative sample of what we typically see in the field.

1 **Q. DO YOU BELIEVE THIS EVIDENCE DEMONSTRATES THAT THE**
2 **REPLACED FACILITIES AT ISSUE IN THIS CASE WERE WORN OUT OR IN**
3 **A DETERIORATED CONDITION AT THE TIME THEY WERE REPLACED?**

4 A. Yes. You don't have to be a scientist or an engineer to see that these pipes have deteriorated
5 significantly from their original condition. Some of them are completely broken in two.
6 Others show significant, irregular wall thickness degradation. Others have propagating
7 cracks. They aren't all worn out, but they are certainly all significantly deteriorated from
8 their original condition. Our experience with cast iron pipe repairs clearly shows
9 embrittlement of these pipes is also prevalent, consistent with metallurgical analysis filed
10 by the Company in prior ISRS cases

11 **Q. DO YOU HAVE ANY CONCLUDING REMARKS?**

12 A. Yes. At Spire, the safety of our customers is paramount and our primary value. The
13 Company has followed the Missouri legislature and this Commission's lead on addressing
14 the critical safety issue of cast iron and bare steel replacement. Since the inception of the
15 ISRS, Spire has replaced more than 2,500 miles of aging pipeline across the state through
16 the ISRS and has reduced the anticipated time to complete its cast iron replacement
17 program from 80-plus years to approximately 25 years. The Company has continued to
18 employ best practices and pursue these replacements in a strategic, efficient manner that
19 provides customers with not only safety benefits now, but savings and benefits that will
20 continue long into the future. The Commission's continued support of cast iron and bare
21 steel replacement cost recovery through the ISRS is crucial to ensuring that Spire can
22 continue its programs at its current pace and deliver these benefits to its customers.

23

1 Q. DOES THIS COMPLETE YOUR DIRECT TESTIMONY?

2 A. Yes.

**BEFORE THE PUBLIC SERVICE COMMISSION
OF THE STATE OF MISSOURI**

In the Matter of the Application of Spire)
Missouri Inc. to Establish an Infrastructure)
System Replacement Surcharge in its Spire) **File No. GO-2021-0030**
Missouri East Service Territory)


In the Matter of the Application of Spire)
Missouri Inc. to Establish an Infrastructure)
System Replacement Surcharge in its Spire) **File No. GO-2021-0031**
Missouri West Service Territory)

A F F I D A V I T

STATE OF MISSOURI)
)) SS.
CITY OF ST. LOUIS)

Tim Goodson, of lawful age, being first duly sworn, deposes and states:

1. My name is Tim Goodson. I am the Vice President of Field Operations for Spire Missouri Inc. My business address is 700 Market St., St. Louis, Missouri, 63101.
2. Attached hereto and made a part hereof for all purposes is my direct testimony on behalf of Spire Missouri Inc.
3. Under penalty of perjury I hereby swear and affirm that my answers contained in the attached testimony to the questions therein propounded are true and correct to the best of my knowledge and belief.



Tim Goodson

This 14th day of August 2020.

Region	Project	Work Order	WO Description	Sample Location	Pipe Diameter	Year Installed *
South	901765	15621830	Dogtown Cast Iron Main Replacement Grid Phase 4D	Tamm & Wise	4"	1905
South	901765	15621830	Dogtown Cast Iron Main Replacement Grid Phase 4D	Clayton & Childress	4"	1920
South	901726	15515587	Dogtown Cast Iron Main Replacement Grid Phase 4A	Tamm & Nashville	6"	1905
South	902953	19700612	Holly Hills & Leona Strategic Grid Replacement Phase D	Morganford & Tyrolean	6"	1926
South	902690	19251195	Ivanhoe & Pernod Strategic Grid Replacement Phase 1D	Watson & Marquette	6"	1923
South	902139	17133652	Cardinal & Park Grid Main Replacement Phase H	California & Saint Vincent	4"	
South	903424	20655987	Pennsylvania MREPL	3166 Pennsylvania	4"	1903
South	903042	19844852	Bingham & S 37th Replacement	Meramec & 37th	6"	1911
South	902926	19655334	Bates & Virginia Phase D	Fasson & Virginia	6"	1905
South	902927	19655345	Bates & Virginia Grid Replacement Phase E	Bates & Alabama	4"	1909
North	903472	20765542	MLK BILLUPS TO PAGE	MLK & BELLE GRADE	6"	1878
North	902420	18698313	CORA & LEE PHASE G	LEE & NEWSTEAD	6"	1902
North	902960	19653420	FAIR & PENROSE 1A	West Florissant & Adelaide	12"	1905
North	903280	20351410	Fair & Penrose 2A	Athlone & Penrose	6"	1906
North	902419	18698297	CORA & LEE PHASE F	Bessie & Cintra	6"	1927
North	903039	19833676	FAIR & PENROSE PHASE 1C	Green Lea Pl & Warne	6"	1903
North	902822	19444783	22nd & Howard Phase I	Monroe & N. Florissant	4"	1874
North	902820	19444778	22nd & Howard Phase G	St. Louis & N. Florissant	6"	1895
North	902532	18899931	Kingshighway & Natural Bridge Phase C	N. Euclid & Lexington	6"	1929

* Year Installed per information found in GIS records based on sample location

Sponsoring Party: Spire Missouri Inc.
Case No: GO-2021-0030

Date Prepared: August 14, 2020

SPIRE MISSOURI INC.

File No. GO-2021-0030

PHOTOGRAPHS OF REPLACED PIPE

Figure 1, Spire East, North Region, Cast Iron, Work Order #83698313



Figure 2, Spire East, North Region, Cast Iron, Work Order #83698313



Figure 3, Spire East, North Region, Cast Iron, Work Order #19444783



Figure 4, Spire East, North Region, Cast Iron, Work Order #19444783



Figure 5, Spire East, North Region, Cast Iron, Work Order #19444783



Figure 6, Spire East, North Region, Cast Iron, Work Order #18698297



Figure 7, Spire East, North Region, Cast Iron, Work Order #18698297



Figure 8, Spire East, North Region, Cast Iron, Work Order #19444778



Figure 9, Spire East, North Region, Cast Iron, Work Order #18698297



Figure 10, Spire East, North Region, Cast Iron, Work Order #18698297



Figure 11, Spire East, North Region, Cast Iron, Work Order #20765542



Figure 12, Spire East, North Region, Cast Iron, Work Order #20765542



Figure 13, Spire East, North Region, Cast Iron, Work Order #18899931



Figure 14, Spire East, North Region, Cast Iron, Work Order #18899931



Figure 15, Spire East, North Region, Cast Iron, Work Order #20351410



Figure 16, Spire East, North Region, Cast Iron, Work Order #20351410



Figure 17, Spire East, North Region, Cast Iron, Work Order #20351410



Figure 18, Spire East, North Region, Cast Iron, Work Order #20351410



Figure 19, Spire East, North Region, Cast Iron, Work Order #20351410



Figure 20, Spire East, South Region, Cast Iron, Work Order #19251195



Figure 21, Spire East, South Region, Cast Iron, Work Order #19251195



Figure 22, Spire East, South Region, Cast Iron, Work Order #19700612



Figure 23, Spire East, South Region, Cast Iron, Work Order #19700612



Figure 24, Spire East, South Region, Cast Iron, Work Order #20655987



Figure 25, Spire East, South Region, Cast Iron, Work Order #19844852



Figure 26, Spire East, South Region, Cast Iron, Work Order #171733652



Figure 27, Spire East, South Region, Cast Iron, Work Order #171733652



Figure 28, Spire East, South Region, Cast Iron, Work Order #171733652



Figure 29, Spire East, South Region, Cast Iron, Work Order #171733652



Figure 30, Spire East, South Region, Cast Iron, Work Order #171733652



Figure 31, Spire East, South Region, Cast Iron, Work Order #171733652



Figure 32, Spire East, South Region, Cast Iron, Work Order #17984965



Figure 33, Spire East, South Region, Cast Iron, Work Order #17984965



Figure 34, Spire East, South Region, Cast Iron, Work Order #19814663



Figure 35, Spire East, South Region, Cast Iron, Work Order #19814663



Figure 36, Spire East, South Region, Cast Iron, Work Order #19655345



Figure 37, Spire East, South Region, Cast Iron, Work Order #19655345



Figure 38, Spire East, South Region, Cast Iron, Work Order #19655345



Figure 39, Spire East, South Region, Cast Iron, Work Order #15515587



Figure 40, Spire East, South Region, Cast Iron, Work Order #15515587



Figure 41, Spire East, South Region, Cast Iron, Work Order #15515587



Figure 42, Spire East, South Region, Cast Iron, Work Order #196553364



Figure 43, Spire East, South Region, Cast Iron, Work Order #196553364

