

Exhibit No.:
Issues: Water Storage Tank Rehabilitation,
Risks of Providing Water & Sewer
Service
Witness: Matthew A. Lueders
Exhibit Type: Direct
Sponsoring Party: Missouri-American Water Company
Case No.: WR-2024-0320
SR-2024-0321
Date: July 1, 2024

MISSOURI PUBLIC SERVICE COMMISSION

**CASE NO. WR-2024-0320
CASE NO. SR-2024-0321**

DIRECT TESTIMONY

OF

MATTHEW A. LUEDERS

ON BEHALF OF

MISSOURI-AMERICAN WATER COMPANY

AFFIDAVIT

I, Matthew Lueders, under penalty of perjury, and pursuant to Section 509.030, RSMo, state that I am Deputy Director of Engineering for Missouri-American Water Company, that the accompanying testimony has been prepared by me or under my direction and supervision; that if inquiries were made as to the facts in said testimony, I would respond as therein set forth; and that the aforesaid testimony is true and correct to the best of my knowledge and belief.



Matthew Lueders

July 1, 2024
Dated

**DIRECT TESTIMONY
MATTHEW A. LUEDERS
MISSOURI AMERICAN WATER COMPANY
CASE NO.: WR-2024-0320
CASE NO.: SR-2024-0321**

TABLE OF CONTENTS

I. INTRODUCTION 2
II. WATER STORAGE TANK REHABILITATION 4
III. RISKS OF PROVIDING PUBLIC WATER & WASTEWATER SERVICES 11

DIRECT TESTIMONY

MATTHEW A. LUEDERS

I. INTRODUCTION

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21

Q. Please state your name and business address.

A. My name is Matthew A. Lueders. My business address is 727 Craig Road, Creve Coeur, MO 63141.

Q. By whom are you employed and in what capacity?

A. I am employed by Missouri-American Water Company (MAWC or the Company) as Deputy Director of Engineering.

Q. Please summarize your educational background and business experience.

A. I received a Master of Science Degree in Environmental Engineering in 2008, and a Bachelor of Science in Engineering Management in 2004, from the Missouri University of Science and Technology. I am registered as a professional engineer in Missouri and Indiana. I have more than 15 years of experience in water and wastewater system engineering.

From 2008 to 2011, I worked as an engineer for Indiana-American Water Company, and from 2011 to 2019, I worked as an engineer for MAWC. In these two roles I authored or co-authored more than 10 comprehensive planning studies, which guided the capital program for more than 60 water and wastewater systems and developed numerous targeted studies supporting engineering design and operations. In 2019, I was promoted to Engineering Manager for Capital Asset Planning at MAWC, where I was responsible for all water and wastewater capital planning. In 2022, I was promoted to Deputy Director of Engineering for MAWC.

1 **Q. What are your current employment responsibilities?**

2 A. As Deputy Director of Engineering, I oversee and manage the activities and groups
3 supporting comprehensive water and wastewater planning, lead service line replacement,
4 developer related services, and new system acquisitions. My responsibilities include
5 maintaining compliance with state and federal requirements related to the planning of the
6 capital investment program; providing comprehensive system planning for use in
7 developing system needs and projecting capital spending; supporting the development of
8 lead service line inventories and management of replacement activities; and supporting
9 MAWC operations staff in performing plant/system troubleshooting. I am also responsible
10 for the acquisition and integration process for new water and wastewater systems. As a
11 Deputy Director of Engineering, I am familiar with the facilities and operations of the
12 Company in each of its operating areas.

13 **Q. Have you previously testified before the Missouri Public Service Commission**
14 **(Commission)?**

15 A. Yes, I adopted Direct Testimony and submitted Rebuttal Testimony for WR-2002-0303.

16 **Q. What is the purpose of your direct testimony in this proceeding?**

17 A. The purpose of my Direct Testimony is to sponsor and testify on the treatment of water
18 storage tank rehabilitation and specifically the capitalization of tank coating systems and
19 risks related to providing public water and wastewater services. MAWC witness Derek
20 Linam's direct testimony will generally discuss MAWC's capital planning process and
21 support the water and sewer utility plant and equipment that the Company has placed in
22 service or will place in service from January 1, 2023 through May 2026.

23 **Q. Are you sponsoring any Schedules with your Direct Testimony?**

1 A. Yes, I am sponsoring the following Schedules:

2 Schedule MAL-1 – Water storage tank inventory

3 Schedule MAL-2 – Sample water storage tank inspection reports

4 **II. WATER STORAGE TANK REHABILITATION**

5 **Q. What are water storage tanks?**

6 A. In terms of a potable water system, water storage tanks are reservoirs typically located at a
7 water treatment facility or within the distribution system. These tanks hold potable water
8 so that it is available to meet short-term demands for filter wash water at the treatment
9 facility or customer demands that may exceed the instantaneous capacity of the water
10 treatment facility or the distribution system. These tanks are constructed of steel or concrete
11 and are generally classified as ground storage tanks, standpipes, or elevated storage tanks.
12 Each type interacts with the water systems through its unique hydraulic properties but serve
13 the same general purpose of holding water for our customers.

14 **Q. Why are water storage tanks critical to the operation of water systems?**

15 A. Water storage tanks are a key piece of infrastructure allowing water systems to meet peak
16 demands at significant cost savings compared to the design and construction of water
17 treatment facilities to meet peak demands alone. Unlike electric power generation, water
18 treatment plants are not constructed to meet instantaneous peak demands of the customers.
19 Use of storage tanks in a water system is analogous to the use of a battery in an electrical
20 system; storing treated water during non-peak usage periods and then returning it to the
21 system for use during peak usage periods. Peak system demands result from multiple
22 factors, including typical customer usage patterns which may include periods where

1 demands may exceed twice the average and emergencies such as firefighting which are
2 often many times greater than typical demands.

3 MAWC also utilizes storage tanks to improve operational flexibility and reliability. Energy
4 costs are lower by treating and storing finished water when electricity costs are lower and
5 delivering the stored water at reduced energy consumption when electricity costs are
6 higher. Service reliability is increased by using tanks as a backup supply of water in the
7 event of a main break or other disruption in the production or distribution of potable water,
8 helping to maintain service until the problem can be resolved. Without adequate storage,
9 periods of low pressure and the occurrence of boil orders would be common, disruptions
10 of service would be much more frequent, and treatment plants and network transmission
11 would necessarily be constructed much larger to meet peak demands.

12 **Q. Please describe the Company's steel water storage tank rehabilitation program.**

13 A. MAWC currently owns and operates 130 steel water storage tanks across the Company's
14 service areas, ranging in size from 8,000 gallons to 11,000,000 gallons. The integrity of
15 these structures is crucial to helping protect public health and providing safe, clean, and
16 reliable water service to customers. To maintain that integrity, the Company maintains an
17 asset management program to prioritize necessary investment which currently totals
18 approximately \$2 million to \$3 million each year for water storage tank rehabilitation. This
19 tank rehabilitation significantly extends the service life of these critical system assets. The
20 rehabilitation program entails periodic detailed inspections of the interior and exterior
21 structures of the tanks and a statewide prioritization to determine the current and upcoming
22 investment needs. The specific investments may include the replacement of corroded steel
23 components such as walls and roofs, addition of safety and security upgrades such as access

1 ladders and manways, replacement of appurtenances such as vents and overflows, and
2 renewal or replacement of protective coating systems. The work is bid to qualified licensed
3 contractors. To verify that the coatings were properly applied and are performing as
4 specified, the work is inspected during performance, directly after completion, and again
5 following a one-year warranty period. Depending on service conditions and other variables,
6 the entire rehabilitation process is repeated for each tank on a cycle of approximately 15 to
7 20-years, aligning with the expected lifespan of the coating systems utilized.

8 **Q. Please describe the service life considerations for steel water storage tanks.**

9 A. More than one-third of the Company's active steel water storage tanks have been in service
10 for more than 50 years, with the three oldest being in service for more than 85 years. A
11 complete listing of the Company's steel water storage tanks is included in Schedule MAL-
12 1. If properly designed, constructed, and rehabilitated on a regular basis, these tanks can
13 be expected to have service lives of well over 50 years and approaching 100 years. If not
14 properly rehabilitated, the service life of a steel tank may be no more than 30 years.
15 Rehabilitation, through the regular addition or reapplication of coating systems, is required
16 to protect the interior and exterior steel surfaces from corrosion resulting from long-term
17 exposure to harsh environmental conditions. Most of these tanks are exposed to a wide
18 range of air temperature, water temperature, humidity, wind loading, and both seasonal and
19 severe weather conditions. Tank interiors must also withstand ice formation resulting from
20 extreme winter temperatures which can damage the steel and coating systems, and a
21 persistent environment of chlorinated water vapor, which readily corrodes exposed steel.
22 Corrosion, if left unattended, can lead to structural damage and leaks as well as poor
23 aesthetic conditions. Areas damaged by corrosion can potentially result in a breach of the

1 tank which can lead to contamination from intrusion or infiltration. Under severe
2 circumstances, tank structural failure can occur. Proper periodic inspection, ongoing care
3 to address spot corrosion, and regular rehabilitation projects are necessary for these assets
4 to fully serve their expected useful life.

5 **Q. Please describe the importance of structural steel coating systems.**

6 A. As discussed, steel tanks require occasional but significant investment in the protective
7 coating system. The Company utilizes a high-performance engineered coating system on
8 both interior and exterior surfaces of tanks. The service life of the interior and exterior
9 coatings varies depending upon several conditions, but typical high-performance coatings
10 can last from 15 years to about 20 years. Installation of new coating systems on existing
11 tanks typically requires removal of existing coatings to bare metal through abrasive
12 blasting and then installation of a new, three-coat engineered coating system that will
13 protect the structural metal and extend its useful life significantly. Work site containment
14 systems are often constructed around the tank to control dust and overspray during abrasive
15 blasting and the application of coatings. Some existing steel structures may have previously
16 been coated with lead-based paint systems. For those facilities, the project activities are
17 supplemented with lead abatement efforts to contain, collect, and properly dispose of
18 possible lead-based residuals to protect workers, neighboring properties, the general
19 public, and the environment.

20 **Q. Have Engineered Coating Systems proven their value in protecting the Company's**
21 **investment in tanks?**

22 A. Yes. As discussed above, more than one-third of the Company's storage tanks were built
23 prior to 1970 and have been in service for more than 50 years. Our oldest tanks have been

1 in service for more than 85 years. These tanks would have failed or required extensive
2 structural repairs without the installation, maintenance, and regular rehabilitation of
3 effective coating systems.

4 **Q. Please discuss any new innovations in tank coating systems.**

5 A. Over time, the industry has provided significant innovation. From the introduction of
6 polyurethane coatings to organic zinc-rich primers, to the development of fluoropolymer
7 coatings and Volatile Organic Carbon (VOC) free coatings, these innovations extend the
8 lives of the tank coating systems, meet current environmental and safety regulations, and
9 help with aesthetic properties such as reducing color fading and retaining a high gloss
10 durable finish for an extended period of time. The latest innovations allow for coating of
11 tanks during periods of cold weather. While tanks can be more easily removed from service
12 during cold periods due to lower water demands, the coating technology did not allow for
13 application during colder temperatures. This latest innovation will allow more tanks to be
14 coated during the off-peak demand season. The current window available for performing
15 this work falls during higher demand periods (summer) and, in many instances, does not
16 allow for tanks to be removed from service.

17 **Q. How are the tank rehabilitation projects prioritized?**

18 A. Capital improvements and maintenance activities for tanks (e.g., engineered coating
19 replacements, structural repairs, surface cleaning, etc.) are prioritized based on inspection
20 results and projected service lives. Notwithstanding this prioritization of the tanks in most
21 urgent need of rehabilitation, MAWC estimates that it will need to rehabilitate the entire
22 inventory steel water storage tanks, as well as any tanks added through acquisitions, over
23 the next 20 years, or an average of about five to six tanks per year.

1 **Q. Please discuss the cost to rehabilitate these tanks over the next five years.**

2 A. Over the next five years, the estimated total cost to rehabilitate 25-30 steel water storage
3 tanks is between \$10 million and \$15 million.

4 **Q. What factors are taken into consideration when determining this cost?**

5 A. The cost to rehabilitate a tank can vary greatly based on size, type of construction, physical
6 condition and damage, site constraints and working room, environmental considerations,
7 and other factors. The detailed tank inspections and subsequent reports and
8 recommendations will weigh heavily in determining the actual tank rehabilitation needs
9 and priorities. Further, any operational considerations may drive up costs. For instance,
10 small systems that may have only one storage tank may require the use of portable
11 hydropneumatic tanks to maintain pressure and safe operation of the system while the
12 storage tank is out of service. These tanks are typically rented and temporarily piped to
13 the distribution system to help address instantaneous changes in demand that cannot
14 typically be addressed through pumping alone.

15 **Q. Does the Company have detailed inspection reports or other materials to support the
16 cost of tank rehabilitation?**

17 A. Yes. The Company is required by the Missouri Department of Natural Resources (MDNR)
18 to inspect each water storage tank on a three-to-five-year cycle. The Company has
19 numerous detailed inspection reports that include cost estimates for necessary
20 rehabilitation. Copies of the recently completed reports for Crestview and Sappington #2
21 tanks have been included in Schedule MAL-2 and are representative of typical reports.

22 **Q. How does the Company currently record costs incurred for engineered coating
23 systems associated with the rehabilitation program?**

1 A. The Company currently treats these costs as maintenance supplies and services expenses,
2 as described by Company witness Jennifer Grisham and presented in Schedule CAS-9.

3 **Q. Is the Company requesting the Commission authorize a different treatment for**
4 **engineered coatings in this case?**

5 A. Yes. The Company is proposing to capitalize investments in Engineered Coatings in
6 NARUC account 342, and to depreciate those assets over 20 years. This proposed
7 treatment is on a prospective basis, beginning with the effective date of rates in this case.

8 **Q. Has the Company capitalized these costs as part of this rate case?**

9 A. No. The Company has included \$3,403,123 in maintenance expense.

10 **Q. If the Commission approves capitalization of Engineered Coating investments, would**
11 **the Company adjust any components of this filing?**

12 A. Yes. If the Engineered Coatings are capitalized, then the Company would reduce
13 maintenance expense by \$3,403,123.

14 **Q. Why should this rehabilitation work be considered capital expenditure?**

15 A. Consistent rehabilitation of protective coatings is essential to extending the life of a critical
16 water system asset. Without rehabilitation of this component, the structural and
17 environmental integrity of tanks would degrade quickly after the initial coating systems
18 begin to fail and the service life of the tanks would be unnecessarily short. Significant risk
19 to the service level and safety of our customers would be introduced as these assets
20 deteriorate. Comparable to other capital work on long-lived assets such as the rehabilitation
21 of a high-service pump, the tank coating has a significant service life of 15 to 20 years of
22 its own and it maintains the continued viability of the original asset. Lastly, the
23 rehabilitation is a significant expenditure and can be individually accounted for, tracked,

1 and depreciated at a specific location in the Company's property records.

2 **Q. Do customers benefit from capitalizing water tank rehabilitation work?**

3 A. Yes. Allowing capitalization of tank reinvestment projects over time is more equitable to
4 the customer base since the rehabilitation projects can extend tank expected lifespans for
5 decades. As noted above, capitalization of these costs will properly apportion the costs over
6 the life of the asset. Customers who benefit from the application of the coating will
7 appropriately bear the cost spread over many years.

8 **III. RISKS OF PROVIDING PUBLIC WATER & WASTEWATER SERVICES**

9 **Q. Please provide an overview of the risks associated with furnishing safe and adequate**
10 **water quantity and water quality and complying with drinking water and**
11 **environmental regulations that apply to MAWC's water supply facilities and**
12 **operations.**

13 A. Water supply utilities are subject to a complex array of regulations at the federal, state, and
14 local levels with respect to water quantity, water quality, and other environmental aspects
15 of their facilities and operations.

16 With respect to water sources and the quantity of water that can be withdrawn, Missouri in
17 general does not currently suffer serious constraints on its supply of usable water.
18 However, that assessment does not apply uniformly to all parts of the state. Limited surface
19 water supplies, the legacy of mining and other industrial activities, run-off from
20 agricultural land use, depleting ground water sources, brackish (saline) groundwater, and
21 contamination of groundwater with various compounds such as hydrocarbons from fuel
22 supplies, and perchloroethylene (PCE) or trichloroethylene (TCE) used in dry cleaning and
23 metal degreasing, create challenges to obtaining adequate supplies of water in various areas

1 of Missouri.

2 These factors add to the costs of treating existing water sources as well as the costs and
3 uncertainty of obtaining new or increasing existing water resources to meet new demand.
4 These are additional risk factors that directly affect MAWC's ability to furnish safe, clean,
5 and reliable service, and can potentially increase the costs MAWC incurs to provide that
6 service.

7 Drinking water quality is controlled by a combination of federal regulation established
8 under the Safe Drinking Water Act of 1973 and state regulation under the Missouri Safe
9 Drinking Water Act. The federal act established the US EPA as the federal regulatory
10 authority on drinking water. Under that authority, US EPA has created standards for
11 contaminant levels in drinking water¹ and a series of mandatory treatment method
12 standards, coupled with monitoring and reporting requirements, and public notification
13 mandates, in the event of contaminant level or treatment method non-compliance.² In turn,
14 Missouri has adopted the federal regulatory standards, plus certain other rules, which are
15 administered by the MDNR.

16 **Q. Please describe the US EPA's efforts to make disinfectant byproduct regulations**
17 **more stringent.**

18 A. The EPA has continued to make its regulations concerning disinfection byproducts more
19 stringent. Disinfection byproducts are produced by the interaction of disinfection agents
20 (such as chlorine) with constituents (such as organic compounds) that naturally occur in
21 source water. The Stage 2 Disinfectants and Disinfection Byproducts Rule (DBPR)

¹ See: <https://www.epa.gov/sdwa/drinking-water-regulations-and-contaminants#List>

² See: 40 C.F.R. Parts 141-143.

1 adopted in 2006, coupled with increasingly stringent disinfection regulations, requires a
2 very careful balancing of treatment processes and source water monitoring to meet the twin
3 goals of inactivating microbes (such as giardia and e-coli) while avoiding unacceptable
4 concentrations of disinfection byproducts such as chlorite, bromate, trihalomethanes, and
5 halogenic acetic acids.

6 In addition to the Stage 2 DBPR, the US EPA was required by the 1996 Amendments to
7 the Safe Drinking Water Act to develop rules to balance the risks between microbial
8 pathogens and disinfection byproducts (DBPs). The Long Term 2 Enhanced Surface Water
9 Treatment Rule (LT2), adopted in 2006, is the second phase of rules required by Congress
10 to address microbial pathogens. The purpose of the LT2 is to reduce illness linked to the
11 contaminant cryptosporidium and other pathogenic microorganisms in drinking water. The
12 rule supplements existing regulations by targeting additional cryptosporidium treatment
13 requirements in facilities that take steps to decrease formation of disinfection byproducts
14 that result from chemical water treatment. Cryptosporidium is a significant concern in
15 drinking water because it contaminates most surface water used as drinking water sources,
16 it is resistant to chlorine and other disinfectants, and it has caused waterborne disease
17 outbreaks.

18 **Q. Is MAWC's water supply at risk from emerging contaminants?**

19 A. Yes. The community of water purveyors along with scientists and regulators work to
20 understand the prevalence and health-effects of constituents in our water supplies, and then
21 decide whether to regulate appropriately or not to regulate them. With advances in testing
22 and health research, constituents that were previously undetectable are now being
23 discovered in the water supply and at concentrations far lower than previously possible.

1 Additionally, health science continues to develop the body of research around acute and
2 chronic human exposure to constituents now the environment. These chemicals are known
3 as emerging contaminants and include substances such as pharmaceuticals, personal care
4 products, nanomaterials, microplastics and algal toxins.

5 The EPA is required by the Safe Drinking Water Act (SDWA) to develop and publish a
6 Contaminant Candidate List (CCL) every five years and then make a formal determination
7 on whether or not to regulate at least five constituents on that list. This process has been
8 completed five times with potential contaminants for the sixth CCL being under review at
9 this time. The most recent Regulatory Determination based on CCL4, which was published
10 on February 22, 2021, identified perfluorooctanesulfonic acid (PFOS) and
11 perfluorooctanoic acid (PFOA) for regulation. These two chemicals are part of a group of
12 chemicals commonly referred to as Per- and polyfluoroalkyl substances (PFAS).

13 **Q. Has the EPA proposed any recent National Primary Drinking Water Regulations?**

14 A. Yes. On April 10, 2024, the EPA announced the most recent addition to the National
15 Primary Drinking Water Regulations by finalizing regulations for six PFAS compounds,
16 including PFOS and PFOA. Concern over PFAS compounds is a current example of how
17 evolving research and regulatory responses can drive the need for higher levels of treatment
18 and impose demands for increased investment in new and more intensive forms of
19 treatment.

20 In addition to the promulgation of the PFAS primary drinking water regulation, on April
21 19, 2024, the EPA also designated PFOA and PFOS as hazardous substances under the
22 Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA).
23 This designation puts the Company, and many other water utilities, at risk of being held

1 responsible for the presence of these compounds in treatment residual waste. Disposal of
2 these wastes may become more costly, regulatory tracking more onerous, and risk of
3 involvement in clean-up lawsuits higher as the presence of these compounds in source
4 waters makes interaction with them unavoidable.

5 **Q. What steps are being taken by MAWC in regard to PFAS?**

6 A. The Company has completed testing and the results, to date, have not indicated a need for
7 the high levels of investment anticipated in many water systems throughout the country.

8 **Q. Is lead a risk the Company faces in providing water and wastewater service to its**
9 **customers?**

10 A. Yes. On December 6, 2023, the US EPA published proposed revisions to the National
11 Primary Drinking Water Regulations for lead and copper under the Safe Drinking Water
12 Act.³ The new proposed rules will strengthen and build on the 2021 Lead and Copper Rule
13 Revisions and the original 1991 Lead and Cooper Rule. Although the Company continues
14 to evaluate the proposed changes, those changes strengthen key elements of the rule in
15 three main focus areas of the US EPA: replacing all lead service lines, reducing complexity
16 for public health protection, and increasing transparency and informing the public. The
17 most significant change is that the US EPA “is proposing the elimination of all [Lead
18 Service Lines (LSLs)] and certain galvanized service lines from water systems in 10 years
19 or less... EPA proposes that water systems must replace LSLs and certain galvanized
20 service lines regardless of the lead levels occurring in tap or other drinking water samples.
21 This proposal would significantly reduce the potential for lead releases into drinking water.

³ See: <https://www.federalregister.gov/documents/2023/12/06/2023-26148/national-primary-drinking-water-regulations-for-lead-and-copper-improvements-lcri>

1 In addition, while corrosion control is generally effective at reducing lead to low levels,
2 elimination of LSLs can result in even greater public health protection by eliminating a
3 lead exposure source and minimizes the opportunities for error that have often occurred
4 over the years.” Id.

5 In addition, the EPA “is proposing to lower the lead action level to 0.010 mg/L and
6 eliminate the lead trigger level to simplify the rule and require water systems to act earlier”
7 and is proposing to update the tap sampling practice. The EPA is also proposing significant
8 changes in the frequency of communications and enhanced outreach activities to improve
9 transparency and information that provides more proactive messaging about lead in
10 drinking water, along with the introduction of new public education requirements for lead
11 and copper.

12 **Q. Please provide an overview of MAWC’s efforts to address removal of lead service**
13 **lines?**

14 A. The Company, with support provided by Commission decisions, has initiated a program
15 that addresses the concerns addressed by the EPA about the presence of lead service lines.
16 In addition to the replacement of the typically utility-owned portion of the lead service line;
17 under its program, the Company also replaces the customer-owned portion lead service
18 lines across its service territory at no direct cost to the customer. This program is underway
19 and has an established internal Company target to replace all lead service lines and
20 galvanized service lines requiring replacement for its systems ahead of the proposed LCRI
21 deadline of ten years.

22 The Company has initiatives to educate its customers about the risks of lead in drinking
23 water and provides them the information they need to participate in the Company’s

1 customer-owned lead service line replacement program. Generally, the Company
2 schedules and replaces lead and galvanized services lines as they are identified through the
3 development of the lead service line inventory which is an intensive effort prioritized based
4 on estimated age of structures, community equity, and other factors. Additionally, the
5 Company is working to significantly reduce the risk of lead exposure to children by
6 implementing a targeted inspection and verification of service line materials at schools and
7 childcare facilities within its service areas, ahead of other targets, followed by replacement
8 of any lead or galvanized service lines found.

9 The Company is at the forefront of the water industry in proactively eliminating the risks
10 that might accompany the presence of lead service lines. However, these efforts also
11 require the dedication of management time and resources and the commitment of
12 significant investment of capital to achieve the intended results. These factors, in addition
13 to the demands the Company already faces to rehabilitate, replace, and enhance aging
14 infrastructure and meet evolving regulatory demands, add to risk factors that MAWC faces
15 as it works to provide safe, adequate and reliable water service.

16 **Q. Provide an overview of the risks that environmental regulation poses for MAWC as**
17 **the owner and operator of public wastewater systems.**

18 A. As with the provision of public water supply service, the operation of wastewater collection
19 and treatment systems are also regulated at both the federal and state levels pursuant to
20 several statutes and voluminous regulations, and are subject to a range of environmental
21 regulatory risks. At the federal level, wastewater systems are regulated pursuant to the
22 Clean Water Act and numerous regulations adopted by the EPA under that law. At the
23 state level, the MDNR has adopted and enforces those standards under the Missouri Code

1 of State Regulations Title 10, Division 20. These regulations set standards and
2 requirements for virtually every aspect of wastewater system operation.

3 One risk associated with operating wastewater systems is that effluent limitations imposed
4 on WWTP discharges are stringent and can become more stringent over time. The Clean
5 Water Act requires wastewater systems to obtain and comply with National Pollutant
6 Discharge Elimination System (NPDES) permits which, in Missouri, are issued by MDNR.
7 NPDES permits establish stringent effluent limits based upon the stricter of: (1)
8 technology-based effluent limits; and (2) water quality-based effluent limits.

9 Technology-based limits are set by EPA (or, in the absence of EPA guidelines for effluent
10 limits, by the permit writer's best professional judgment) at levels that reflect (depending
11 on the parameter) best conventional control technology (BCT), best practicable control
12 technology currently available (BPT), or best available technology economically
13 achievable (BAT). Determinations of BCT, BPT and BAT can change over time,
14 becoming more stringent as technology evolves.

15 Water quality-based effluent limits (WQBEL) are established to avoid discharges to water
16 bodies that exceed instream water quality criteria, which are set to protect existing and
17 designated uses, such as recreation and various categories of fisheries. WQBEL limits are
18 usually based on the assimilative capacity of a stream to receive and dilute the discharge
19 during extremely low flow – that is, when stream flow is at the 7-day, 10-year low flow
20 (Q7-10). By definition, WQBELs may require treatment beyond technology-based values,
21 even beyond what is considered best available technology. Moreover, as streams become
22 cleaner, there exists a possibility that their classifications may be upgraded such that their
23 protected uses are deemed to be more sensitive, which, in turn, leads to even more stringent

1 WQBEL calculations.

2 As just one example, many of the Company's small wastewater treatment systems are now
3 required to meet ammonia discharge limits. A notable risk in wastewater operations is
4 that limits for some parameters may have conflicting impacts on treatment efforts or may
5 not be attainable with existing treatment systems. Such is the case with respect to fecal
6 coliform standards on the one hand and limits on treatment residuals (residual chlorine and
7 dichlorobromomethane) on the other – where a delicate balancing is required to
8 concurrently meet all applicable standards.

9 Thus, more stringent effluent limits may be imposed when technology evolves or stream
10 conditions change, engendering requirements for significant capital improvements and/or
11 increased operating costs for enhanced treatment performance. Every five years, NPDES
12 permits are up for renewal, and in any such renewal more stringent limits may be triggered.

13 Another risk for the Company is that a number of Missouri streams, including those where
14 the Company is operating wastewater systems, are parts of watersheds that are classified
15 as “impaired” (meaning their instream quality does not meet state standards). Such
16 impaired waters are subject to the development and imposition of Total Maximum Daily
17 Loads (TMDLs) for parameters that contribute to the instream conditions. Where TMDLs
18 are established by EPA or MDNR, stringent waste load allocations are made to point-
19 source discharges (such as WWTPs), and allocations are also made to non-point sources
20 such as agriculture and urban runoff. Where any cap loading exceedance irrespective of
21 the cause (such as increased flows and loadings from system customers or high stormwater
22 flows entering the system) – can potentially lead to penalties and other enforcement
23 actions.

1 Wastewater systems also face significant regulatory and environmental liability risks.
2 Non-compliance with wastewater system effluent limits and other permit conditions can
3 result in severe penalties. Regulatory violations expose the operator to the risk not only of
4 governmental agency enforcement actions, but also of citizen suits in which both injunctive
5 relief and civil penalties can be imposed.

6 Other potential liability risks from wastewater system operations arise from backups,
7 overflows or releases that may occur from the collection system onto private property or
8 into the environment. As an example, some wastewater system operators have been
9 confronted with claims under the federal Comprehensive Environmental Response,
10 Compensation and Liability Act (CERCLA) for cleanup of contamination that occurred
11 when wastewater containing “hazardous substances” leaked from sewer lines into soils or
12 groundwater. While not as extreme, liabilities resulting from wastewater backups into
13 buildings or other unplanned discharges are an inherent part of wastewater system risks.
14 This may become more of a concern in the future given the recent designation of PFOA and
15 PFOS as hazardous substances by the EPA under CERCLA. Wastewater collection
16 systems and treatment processes will inherently collect and concentrate these constituents
17 in effluent discharges and waste residuals which will need to be released or disposed of,
18 potentially opening wastewater purveyors to increased costs and legal risks.

19 **Q. What effects did these rules have on MAWC’s infrastructure investment?**

20 A. To comply with these rules, which evolve along with the science, the Company is required
21 to evaluate and modify its treatment processes, which, in turn, requires the Company to
22 invest in new plant and equipment to enable revised treatment methods. This is another
23 example of the need for the Company to study, monitor, and comply with new and evolving

1 standards that are accompanied by higher costs and increased demands for new investment.
2 The projects implemented depend on the regulation being met, with examples being:
3 completion of demonstration of performance studies to assert compliance with the LT2
4 Rule, replacement of treatment components to maintain compliance with the Safe Drinking
5 Water Act, replacement of lead and galvanized service lines to comply with the Lead and
6 Copper Rule Revisions, and wastewater treatment plant upgrades to comply with discharge
7 limits issued through the Clean Water Act. The continued development of the science
8 around health-effects, advancement of testing methods enabling increasingly low detection
9 limits, and escalation of public concern over particular contaminants, and the subsequent
10 regulatory determinations from the EPA and state drinking water regulators have resulted
11 in increasingly stringent regulatory standards. This process, along with the specific
12 regulatory examples noted earlier, characterizes the regulatory landscape where demands
13 are, in effect, a “moving target” for water suppliers, making them another significant risk
14 factor for MAWC.

15 **Q. Does climate variability pose additional risks for water supply and wastewater system**
16 **utilities such as MAWC?**

17 A. Yes. Whatever the causes of climate variability may be, water supply and wastewater
18 utilities face the reality of changing climatic conditions and attendant stresses on water
19 resources. Although climate models for the midwestern U.S. generally predict overall
20 annual precipitation amounts to remain similar to average historic experience, the EPA has
21 indicated a likelihood for increasingly intense storms and repeated, extended dry periods
22 are anticipated.^{4,5} That means we can expect more droughts of varying degrees of severity

⁴ See: https://www.epa.gov/system/files/documents/2023-11/lcri-fact-sheet-for-the-public_final.pdf

⁵ See: <https://nca2023.globalchange.gov/chapter/24/>

1 and more frequent and intense high-flow events and floods – all of which impact water and
2 wastewater utilities.

3 Water supply systems are fundamentally resource-dependent and, therefore, the effects of
4 climate variability pose a significant on-going risk and create challenges with regard to
5 maintaining a reliable water supply during the full range of potential future conditions,
6 including even what might be assumed to be “normal” periods. The safe yields of water
7 supply sources have historically been evaluated based on historical climatic patterns, data
8 from so called “droughts of record” or dry period frequency analysis. However, changing
9 climatic conditions suggest that historical hydrologic data (which in many cases only
10 reflect 50-100 years of rainfall and stream flow measurement data collection – a quite short
11 period in geologic or climatic time) may not accurately predict future conditions. Thus,
12 the calculated safe yield of streams, reservoirs and groundwater wells are put in question
13 as the effects of climate variability are experienced across the midwestern United States.
14 Thus, in response to climate variability, water supply systems must address the risks posed
15 to the reliability and resilience of their sources.

16 While droughts are the major challenge for water supply systems, heavy precipitation and
17 high-flow events are the concern of wastewater systems. As mentioned previously,
18 wastewater systems of all types are impacted by storm water – directly in the case of
19 combined sewer systems and indirectly (but nevertheless significantly) by I&I in “sanitary
20 only” systems. The prediction of increased intensity of strong storms and high rainfall
21 events in the midwestern United States portends challenges to wastewater systems which
22 must, in turn, cope with and treat higher peak flows while avoiding exceedance of effluent
23 limitations and reducing the potential for untreated overflows. An additional challenge

1 related to high intensity rain events is higher levels and frequency of flooding. Flooding
2 has the potential to impact both water and wastewater treatment facilities which are often
3 located in proximity to water ways. For example, the Company is investing nearly \$20
4 million to enhance the reliability and resiliency of the South Plant (I170200167) in St.
5 Louis in part due to increased flooding in the area. This project is further described in
6 MAWC witness Linam's direct testimony.

7 **Q. Does this conclude your direct testimony?**

8 A. Yes.

Water storage tank inventory

| System | Title | Capacity (MG) | Tank Style | Use | Material | Diameter | Height | Recent Exterior Coating | Recent Interior Coating | Year Erected |
|----------------------|------------------------------------|---------------|-------------------------|-----------------------------|--------------------------|----------|---------|-------------------------|-------------------------|--------------|
| Joplin | 32nd St | 2 | Ground Storage | Finished Water Distribution | Steel | 102 | 33 | 2011 | 2011 | 1997 |
| Joplin | 4th St (elevated) | 1 | Elevated | Finished Water Distribution | Steel | 67 | 108 | 2010 | 2010 | 1962 |
| St. Louis County | Afton 2 (dome) | 1.52 | Ground Storage | Finished Water Distribution | Steel | 72 | 50 | 2013 | 2016 | 1953 |
| St. Louis County | Afton 3 | 4 | Ground Storage | Finished Water Distribution | Steel | 177 | 50 | 2020 | 2021 | 1967 |
| St. Joseph | Agency | 0.07 | Standpipe | Finished Water Distribution | Steel | 10 | 120.5 | 2018 | 2018 | 1976 |
| St. Charles | Anna Meadows | 0.15 | Standpipe | Finished Water Distribution | Steel | 15 | 114 | 2018 | 2018 | 2018 |
| Eureka | Arbors | 0.5 | Floating Ground Storage | Finished Water Distribution | Steel | 69 | 20 | 2017 | 2024 | 2017 |
| St. Louis County | Baxter | 8 | Ground Storage | Finished Water Distribution | Steel | 175 | 45 | 2015 | 2015 | 1968 |
| Eureka | Brock/Palisades | 0.5 | Floating Ground Storage | Finished Water Distribution | Steel | 46 | 40 | | | 2003 |
| Brunswick | Brunswick Hill (elevated) | 0.1 | Elevated | Finished Water Distribution | Steel | 25 | 67 | 2006 | 2006 | 1963 |
| St. Louis County | Carman | 4 | Ground Storage | Finished Water Distribution | Steel | 117 | 50 | 2008 | 2008 | 1975 |
| St. Louis County | Cherry Hills | 4 | Ground Storage | Finished Water Distribution | Steel | 117 | 50 | 2014 | 2014 | 1987 |
| Lawson | City Park Tank | 0.05 | Elevated | Finished Water Distribution | Steel | 20 | 117.167 | | | 1955 |
| St. Louis County | Clayton | 2.54 | Ground Storage | Finished Water Distribution | Steel | 116 | 32 | 2020 | 2012 | 1962 |
| Jefferson City | Clearwell 2 | 1 | Ground Storage | Finished Water Clearwell | Steel | 102 | 18 | 2006 | 2006 | 1959 |
| St. Louis County | Crestview | 0.5 | Elevated | Finished Water Distribution | Steel | 55.5 | 146 | 2016 | 2024 | 1998 |
| Parkville | Crooked Rd | 0.5 | Floating Ground Storage | Finished Water Distribution | Steel | 52 | 32 | 2012 | 2012 | 1969 |
| Joplin | Crossroads | 1 | Hydropillar | Finished Water Distribution | Steel/Concrete Composite | 74 | 140 | 2003 | 2003 | 2003 |
| St. Charles | Ehlmann Rd | 0.5 | Ground Storage | Finished Water Distribution | Steel | 35 | 41 | 2006 | 2006 | 1964 |
| Joplin | Eland | 0.4 | Single Ped | Finished Water Distribution | Steel | 51.5 | 136 | 2006 | 2006 | 2005 |
| Jefferson City | Ellis | 1.5 | Ground Storage | Finished Water Distribution | Steel | 105 | 25 | 2004 | 2004 | 2004 |
| Emerald Point | Emerald Point | 0.175 | Standpipe | Finished Water Distribution | Steel | 15.83 | 110 | 2015 | | 1994 |
| St. Louis County | Fee Fee | 8 | Ground Storage | Finished Water Distribution | Steel | 172 | 46 | 2023 | 2023 | 1966 |
| St. Louis County | Ferguson | 0.25 | Elevated | Finished Water Distribution | Steel | 38 | 143 | 2016 | 2016 | 1939 |
| St. Louis County | Florissant | 2.5 | Ground Storage | Finished Water Distribution | Steel | 110 | 35 | 2023 | 2023 | 1961 |
| St. Louis County | Foerster (dry tank DO NOT INSPECT) | 4 | Ground Storage | Finished Water Distribution | Steel | 117 | 50 | 2013 | 2013 | 1968 |
| Eureka | Forby Road | 0.5 | Floating Ground Storage | Finished Water Distribution | Steel | 46 | 40 | | | 2005 |
| St. Charles | Harvester Rd West (1.5MG) | 1.465 | Ground Storage | Finished Water Distribution | Steel | 50 | 100 | 2009 | 2009 | 1977 |
| St. Charles | Harvester Rd East (3.5MG) | 3.5 | Ground Storage | Finished Water Distribution | Steel | 78 | 99 | 2009 | 2009 | 1990 |
| St. Louis County | Hawkins | 2.46 | Ground Storage | Finished Water Distribution | Steel | 92 | 50 | 2019 | 2019 | 1968 |
| St. Louis County | Hazelwood 1 (dome) | 4 | Ground Storage | Finished Water Distribution | Steel | 120 | 47 | 2019 | 2019 | 1960 |
| St. Louis County | Hazelwood 2 | 4 | Ground Storage | Finished Water Distribution | Steel | 118 | 49 | 2022 | 2022 | 1965 |
| Joplin | Hill St | 1 | Ground Storage | Finished Water Distribution | Steel | 66 | 40 | 2006 | 2006 | 1980 |
| St. Joseph | Huntoon Rd 1 | 3.3 | Floating Ground Storage | Finished Water Distribution | Steel | 110 | 40 | 2018 | 2008 | 1954 |
| St. Joseph | Huntoon Rd 2 | 4 | Floating Ground Storage | Finished Water Distribution | Steel | 117 | 50 | 2022 | 2014 | 1957 |
| Lawson | Hwy 69 Tank | 0.3 | Elevated | Finished Water Distribution | Steel | 45 | 93.583 | | | 1984 |
| Incline Village | Incline Village | 0.2 | Elevated | Finished Water Distribution | Steel | 30 | 91 | 2021 | 2022 | 2005 |
| St. Joseph | Industrial Park | 1 | Elevated | Finished Water Distribution | Steel | 76 | 137 | 2011 | 2011 | 1973 |
| St. Charles | Jaxson Estates | 0.585 | Standpipe | Finished Water Distribution | Steel/Bolted | 29 | 12 | | | 2007 |
| St. Joseph | Karnes Rd | 0.75 | Elevated | Finished Water Distribution | Steel | 64.5 | 115 | 2010 | 2010 | 1970 |
| St. Louis County | Kehrs Mill 1 (elevated) | 0.25 | Elevated | Finished Water Distribution | Steel | 40 | 102 | 2017 | 2017 | 1955 |
| St. Louis County | Kehrs Mill 2 (dome) | 2.46 | Ground Storage | Finished Water Distribution | Steel | 92 | 50 | 2012 | 2012 | 1960 |
| Woodland Manor | Kimberling City Cardinal Ln | 0.018 | Ground Storage | Finished Water Distribution | Steel | 10 | 18.33 | 2016 | 2016 | 2016 |
| St. Joseph | King Hill 1 | 2 | Ground Storage | Finished Water Distribution | Steel | 100 | 35 | 2019 | 2006 | 1954 |
| St. Joseph | King Hill 2 | 2 | Ground Storage | Finished Water Distribution | Steel | 100 | 35 | 2018 | 2006 | 1954 |
| Lake Carmel | Lake Carmel | 0.226 | Standpipe | Finished Water Distribution | Steel | 8 | 100 | | | 2003 |
| Lake Taneycomo Acres | Lake Taneycomo Acres | 0.034 | Standpipe | Finished Water Distribution | Steel | 12 | 36 | 2022 | 2022 | 1973 |
| Lakewood Manor | Lakewood Manor | 0.012 | Ground Storage | Finished Water Distribution | Steel | 12 | 30 | | | 2003 |
| St. Joseph | Landis Rd | 0.06 | Standpipe | Finished Water Distribution | Steel | 10 | 110.6 | 2012 | 2012 | 1987 |
| Eureka | Large/New/West Viola | 0.5 | Floating Ground Storage | Finished Water Distribution | Steel | 52 | 32 | | | 1977 |
| Eureka | Legends | 0.5 | Floating Ground Storage | Finished Water Distribution | Steel | 47 | 40 | 2023 | 2023 | 1996 |
| Maplewood | Maplewood | 0.0865 | Standpipe | Finished Water Distribution | Steel | 11 | 120 | | | 1971 |
| St. Louis County | Mehlville 2 (dome) | 2 | Ground Storage | Finished Water Distribution | Steel | 75 | 60 | 2016 | 2016 | 1956 |
| St. Louis County | Mehlville 3 | 2 | Ground Storage | Finished Water Distribution | Steel | 75 | 60 | 2023 | 2023 | 1970 |

Water storage tank inventory

| System | Title | Capacity (MG) | Tank Style | Use | Material | Diameter | Height | Recent Exterior Coating | Recent Interior Coating | Year Erected |
|---------------------|------------------------------|---------------|-------------------------|-----------------------------|--------------------------|----------|--------|-------------------------|-------------------------|--------------|
| Mexico | Mexico West Tank (elevated) | 0.25 | Elevated | Finished Water Distribution | Steel | 40 | 110 | 2006 | 2006 | 1988 |
| Eureka | Niehoff/Augustine | 0.5 | Floating Ground Storage | Finished Water Distribution | Steel | 40 | 56 | | | 2007 |
| St. Louis County | Norwood | 2.46 | Ground Storage | Finished Water Distribution | Steel | 92 | 49 | 2020 | 2020 | 1963 |
| St. Louis County | Oakville 1 (elevated) | 0.15 | Elevated | Finished Water Distribution | Steel | 32 | 29 | 2013 | 2013 | 1951 |
| St. Louis County | Oakville 2 | 1.5 | Ground Storage | Finished Water Distribution | Steel | 72 | 50 | 2018 | 2018 | 1967 |
| St. Louis County | Old Halls Ferry | 8 | Ground Storage | Finished Water Distribution | Steel | 175 | 44 | 2012 | 2012 | 1971 |
| Ozark Mountain %231 | Ozark Mountain 1 | 0.03 | Standpipe | Finished Water Distribution | Steel | 12 | 36 | | | 1971 |
| Ozark Mountain %232 | Ozark Mountain 2 | 0.058 | Standpipe | Finished Water Distribution | Steel | 10 | 100 | | | 2003 |
| Ozark Mountain %233 | Ozark Mountain 3 | 0.038 | Standpipe | Finished Water Distribution | Steel | 8 | 101 | | | 2003 |
| St. Louis County | Paradise Valley | 0.152 | Standpipe | Finished Water Distribution | Steel | 20 | 65 | 2016 | 2016 | 1979 |
| Parkville | Park College | 1 | Floating Ground Storage | Finished Water Distribution | Steel | 68 | 37.6 | 2000 | 2000 | 1999 |
| Pevely Farms | Pevely Farms Clearwell East | 0.033 | Above-ground Clearwell | Finished Water Clearwell | Steel | 15.33 | 24 | 2020 | 2020 | 2020 |
| Pevely Farms | Pevely Farms Clearwell West | 0.033 | Above-ground Clearwell | Finished Water Clearwell | Steel | 15.33 | 24 | 2020 | 2020 | 2020 |
| Joplin | Plant Washwater | 0.36 | Standpipe | Wash Water | Steel | 26 | 80 | 2008 | 1983 | 1959 |
| Jefferson City | Plant Washwater Standpipe | 0.3 | Standpipe | Wash Water | Steel | 20 | 125 | 2006 | 2006 | 1888 |
| Parkville | Platte Woods | 0.31 | Elevated | Finished Water Distribution | Steel | 44 | 100 | 2010 | 2010 | 1957 |
| Rogue Creek | Pressure Tank | 0.008 | Hydropneumatic | Finished Water Distribution | Steel | | 8 | 2019 | 2019 | 2019 |
| Rankin Acres | Rankin Acres | 0.018 | Hydropneumatic | Finished Water Distribution | Steel | 8 | 48 | 2020 | 2020 | 2020 |
| Redfield | Redfield | 0.044 | Standpipe | Finished Water Distribution | Steel | 8 | 110 | 2016 | 2016 | 2000 |
| Joplin | Rex | 0.5 | Elevated | Finished Water Distribution | Steel | 50 | 125 | 2011 | 2000 | 1955 |
| Parkville | Riverside | 0.5 | Single Ped | Finished Water Distribution | Steel | 50 | 82.5 | 2018 | 2018 | 1987 |
| Riverside Estates | Riverside Estates | 0.01 | Ground Storage | Finished Water Distribution | Steel | 24 | 27 | | | 2004 |
| Jefferson City | Rockhill Tank | 1.5 | Hydropillar | Finished Water Distribution | Steel/Concrete Composite | 86 | 159 | 2014 | 2014 | 2014 |
| St. Louis County | Rockwood | 0.05 | Elevated | Finished Water Distribution | Steel | 20 | 120 | 2018 | 2018 | 1967 |
| St. Joseph | S. 22nd St | 0.5 | Elevated | Finished Water Distribution | Steel | 56 | 103 | 2023 | 2023 | 1965 |
| Saddlebrook | Saddlebrooke | 0.25 | Single Ped | Finished Water Distribution | Steel | 45 | 80 | | | 2003 |
| St. Louis County | Sappington 1 | 2.46 | Ground Storage | Finished Water Distribution | Steel | 92 | 49 | 2014 | 1998 | 1954 |
| St. Louis County | Sappington 2 | 2.46 | Ground Storage | Finished Water Distribution | Steel | 92 | 49 | 2015 | 1992 | 1968 |
| Tri-State | Skyline (Well 4 Standpipe) | 0.3 | Standpipe | Finished Water Distribution | Steel | 30 | 88 | 2015 | 2015 | 1987 |
| Eureka | Small/Old/East Viola | 0.25 | Floating Ground Storage | Finished Water Distribution | Steel | 33 | 32 | | | 1966 |
| Spokane | Spokane Well Tank | 0.01 | Ground Storage | Finished Water Distribution | Steel | 12 | 18 | 2019 | 2019 | 1992 |
| Stonebridge | Stonebridge (elevated) | 0.4 | Single Ped | Finished Water Distribution | Steel | 40 | 69 | 2012 | | 1994 |
| Stonebridge | Stonebridge (Ground) | 0.25 | Ground Storage | Finished Water Distribution | Steel | 22 | 44 | 2018 | | 2003 |
| Pevely Farms | Stonewall Tank 1 | 0.11 | Floating Ground Storage | Finished Water Distribution | Steel | 20 | 40 | | 2001 | 2001 |
| Pevely Farms | Stonewall Tank 2 | 0.2 | Floating Ground Storage | Finished Water Distribution | Steel | 30 | | 2021 | 2021 | 2021 |
| Rogue Creek | Storage Tank | 0.008 | Ground Storage | Finished Water Distribution | Steel | 21.33 | 8 | 2019 | 2019 | 2019 |
| St. Louis County | Stratmann 1 | 11 | Ground Storage | Finished Water Distribution | Steel | 240 | 33 | 2009 | 2009 | 1960 |
| St. Louis County | Stratmann 2 | 11.26 | Ground Storage | Finished Water Distribution | Steel | 264 | 27 | 1996 | 1998 | 1965 |
| St. Louis County | Sunset | 0.25 | Elevated | Finished Water Distribution | Steel | 40 | 122 | | 2020 | 1936 |
| St. Louis County | Tesson Ferry 1 | 3 | Ground Storage | Finished Water Distribution | Steel | 125 | 33 | 2017 | 2017 | 1967 |
| St. Louis County | Tesson Ferry 2 (dome) | 3 | Ground Storage | Finished Water Distribution | Steel | 125 | 33 | 2019 | 2019 | 1996 |
| St. Charles | Towers Rd | 2 | Ground Storage | Finished Water Distribution | Steel | 62 | 90 | 2008 | 2008 | 1981 |
| Tri-State | Well 6 Standpipe | 0.5 | Standpipe | Finished Water Distribution | Steel | 27 | 118 | 2020 | 2020 | 2019 |
| St. Joseph | Union Rd | 0.04 | Standpipe | Finished Water Distribution | Steel | 8 | 110 | 2012 | 2012 | 1973 |
| St. Louis County | Valley Park | 0.75 | Ground Storage | Finished Water Distribution | Steel | 52 | 50 | 2006 | 2006 | 1981 |
| Tri-State | Vineyard (Well 5 Standpipe) | 0.3 | Standpipe | Finished Water Distribution | steel | 29 | 93 | 2014 | | 1994 |
| St. Louis County | Walton | 4 | Ground Storage | Finished Water Distribution | Steel | 117 | 50 | 2011 | 2011 | 1979 |
| Wardsville | Wardsville Elevated | 0.15 | Elevated | Finished Water Distribution | Steel | 25 | 128 | 2021 | 2021 | 1998 |
| Warrensburg | Warrensburg North (elevated) | 0.3 | Elevated | Finished Water Distribution | Steel | 35 | 123 | 2010 | 2010 | 1949 |
| Warrensburg | Warrensburg South (elevated) | 0.5 | Elevated | Finished Water Distribution | Steel | 50 | 125 | 2008 | 2008 | 1989 |

Water storage tank inventory

| System | Title | Capacity (MG) | Tank Style | Use | Material | Diameter | Height | Recent Exterior Coating | Recent Interior Coating | Year Erected |
|------------------|--------------------------------|---------------|-------------------------|-----------------------------|--------------------------|----------|--------|-------------------------|-------------------------|--------------|
| White Branch | White Branch (Benton County) | 0.0865 | Standpipe | Finished Water Distribution | Steel | 11 | 119 | | | 1971 |
| St. Louis County | Wild Horse Creek | 0.5 | Ground Storage | Finished Water Distribution | Steel/Bolted | 48 | 41 | 1998 | 2017 | 1967 |
| Woodland Manor | Woodland Manor Bayfront Middle | 0.02 | Ground Storage | Finished Water Distribution | Steel | 10 | 18.33 | 2017 | | 1986 |
| Woodland Manor | Woodland Manor Bayfront North | 0.02 | Ground Storage | Finished Water Distribution | Steel | 10 | 18.33 | 2017 | | 1986 |
| Woodland Manor | Woodland Manor Bayfront South | 0.02 | Ground Storage | Finished Water Distribution | Steel | 10 | 18.33 | 2017 | | 1986 |
| St. Louis County | CP1 Backwash (elevated) | 0.25 | Elevated | Wash Water | Steel | 35 | 58.5 | 2019 | 2019 | 1969 |
| St. Louis County | CP2 Backwash (dome) | 1.29 | Standpipe | Wash Water | Steel | 61.5 | 60 | 2023 | 2023 | 1999 |
| St. Louis County | CP3 Backwash | 1.33 | Ground Storage | Wash Water | Steel | 90 | 28 | 2010 | 2010 | 1967 |
| St. Louis County | MP Backwash | 1 | Ground Storage | Wash Water | Steel | 65 | 40 | 2012 | 1999 | 1971 |
| St. Louis County | NP-E Backwash (dome) | 0.5 | Ground Storage | Wash Water | Steel | 57 | 35 | 1995 | 2000 | 1963 |
| St. Louis County | NP-W Backwash (dome) | 0.5 | Ground Storage | Wash Water | Steel | 52 | 35 | 2023 | 2023 | 1996 |
| St. Louis County | SP Backwash | 1 | Ground Storage | Wash Water | Steel | 59 | 51 | 1998 | 1998 | 1986 |
| Mexico | Mexico Plant (elevated) | 0.5 | Elevated | Finished Water Distribution | Steel | 56 | 210 | 1998 | 1998 | 1962 |
| Mexico | Mexico East Tank | 0.25 | Elevated | Finished Water Distribution | Steel | 40 | 138 | 2006 | 2006 | 1987 |
| Orrick | Orrick Elevated | 0.15 | Elevated | Finished Water Distribution | Steel | 30 | 138 | | | 2000 |
| Garden City | Stand Pipe | 0.305 | Standpipe | Finished Water Distribution | Steel | 31 | 56 | | | 2000 |
| Garden City | Elevated | 0.055 | Elevated | Finished Water Distribution | Steel | 20 | | | | 1955 |
| Garden City | Clearwell | 0.125 | Above-ground Clearwell | Finished Water Clearwell | Steel/Bolted | 25 | 35 | | | 1989 |
| Ironton | Dent St. | 0.2 | Floating Ground Storage | Finished Water Distribution | Steel | 34 | 32 | | | 1965 |
| Ironton | Ironton North | 0.11 | Floating Ground Storage | Finished Water Distribution | Steel/Bolted | 25.1 | 29.1 | | | 2007 |
| Ironton | Westwood St | 0.11 | Floating Ground Storage | Finished Water Distribution | Steel/Bolted | 25.1 | 29.1 | | | 2007 |
| Stewartsville | Stewartsville | 0.2 | Single Ped | Finished Water Distribution | Steel | 30 | | | | 1994 |
| Purcell | Purcell | 0.05 | Elevated | Finished Water Distribution | Steel | 20 | 85 | | | 1911 |
| Wood Heights | Wood Heights | 0.1 | Elevated | Finished Water Distribution | Steel | 30 | 135 | | | 1995 |
| St. Charles | Knaust | 2 | Hydropillar | Finished Water Distribution | Steel/Concrete Composite | 98 | 133 | 2022 | 2022 | 2022 |
| Smithton | Smithton | 0.05 | Elevated | Finished Water Distribution | Steel | 25 | 84 | 2012 | 2012 | 1956 |



Visual Sanitary Inspection Report

Project Information

Crestview

Prepared For
Mattie Zautner

Prepared On
2/23/2024

Prepared By
Brad Huebner



Coating Inspection Services
PO Box 133 Eureka, MO 63025
coatinginspectionsservices.net





Table of Contents

Table Of Contents

Report produced using www.FastPhotoReports.com

| | |
|-----------------------------------|----|
| Cover | 1 |
| Table of Contents | 2 |
| General Information | 3 |
| Tank Details | 3 |
| Exterior Coatings Condition | 4 |
| Interior Coating Condition | 5 |
| Security | 6 |
| Photo Observations | 7 |
| Exterior Coating Photos | 7 |
| Interior Coating Photos | 27 |
| Tank Recommendations | 32 |
| Recommendations | 32 |



Coating Inspection Services
PO Box 133 Eureka, MO 63025
coatinginspectionsservices.net





General Information

Tank Details

Capacity: 500,000 Gallon.

Construction Style: Single Pedestal.

Builder: Caldwell.

Construction Date: 1998.

Exterior Coating: Urethane.

Interior Coating: Epoxy.

Inspector: Brad Huebner.

Inspection Date: 2/14/2024.

Height: 140' HWL.



Coating Inspection Services
PO Box 133 Eureka, MO 63025
coatinginspectionsservices.net





General Information

Exterior Coatings Condition

Exterior coating condition: Coatings are in good condition with an average of 14.0-17.0 mils DFT. Spot failures with light rust on roof and roof vent. Light mold and mildew growth on lower pedestal. Two pipe chases next to roof hatch for cellular and coax cables to access roof should be sealed to prevent birds and insects from entering dry tube.

| | |
|-------------------|---|
| Foundation : | Concrete, good condition. Lower grade on S. side of foundation. |
| Overflow Pipe: | Concrete vault. |
| Overflow Screen: | Not accessible. |
| Flap Gate: | Yes, not accessible. |
| Splash Pad: | Concrete pad to Rip-Rap. |
| Exterior ladder: | None. |
| Safety Climb: | Safety cable. |
| Ladder Gate: | None. |
| Vent: | Steel, insect screen intact. |
| Manway: | (Wet) 30" round with 6" curb / 24" port side / 18"x24" bowl access. |
| Catwalk: | N/A. |
| Cables: | Multiple cellular and coax cables. |
| Roof Hatch: | (Dry) 30" round with 4" curb. |
| Aviation Light: | None. |
| Roof Ladder: | None, antenna corral. |
| Cellular Carriers | Yes. |



General Information

Interior Coating Condition

Interior Coating Condition: Coatings are in poor condition with spot failures on roof where antenna mounts have been welded and burned coatings. Rusting along roof plate overlapping seams. Multiple spot failures visible on sidewalls. Minimal sediment visible on bowl floor.

Interior Wet Ladder: Yes, top rung has heavy delaminating rust ladder needs replaced.

Safety Climb: Safety cable.

Interior Riser Ladder: Good condition.

Cathodic Protection: None.

Dry Riser: Multiple spot failures with moderate rusting on condensation plates and inside dry riser tube.



Coating Inspection Services
PO Box 133 Eureka, MO 63025
coatinginspectionsservices.net





General Information

Security

Gates and Fences: Chain link fence with locked gate

Ladder Gate: Man door to lower pedestal access locked.

Roof Hatch: Locked.




Coating Inspection Services
PO Box 133 Eureka, MO 63025
coatinginspectionsservices.net





Exterior Coating Photos





Overflow flat gate visible inside of concrete vault








Coating Inspection Services
PO Box 133 Eureka, MO 63025
coatinginspectionsservices.net









Cellular cables














Spot failures in dry rides






Spot failures with rust on upper condensation plate



Spot failures with rust on lower bowl access











Coating Inspection Services
PO Box 133 Eureka, MO 63025
coatinginspectionsservices.net






Coating Inspection Services
PO Box 133 Eureka, MO 63025
coatinginspectionsservices.net











Pipe chase access for cellular cables needs foam sealant



Coax cables mounted to ladder in dry tube







Coating Inspection Services
PO Box 133 Eureka, MO 63025
coatinginspectionsservices.net






Interior Coating Photos







Heavy rusting where antenna mounts were welded to roof



Rusting on roof vent stack



Rusting along overlapping roof plates





Coating Inspection Services
PO Box 133 Eureka, MO 63025
coatinginspectionsservices.net





Tank Recommendations

Recommendations

- Replace bowl ladder at next renovation.
- Lower grade on south side of foundation.
- Seal pipe chases in dry tube for cellular and coax cables closed.
- Relocate cables mounted to ladder in dry tube.
- Consider interior wet and dry riser complete renovation in the next year.



Coating Inspection Services
PO Box 133 Eureka, MO 63025
coatinginspectionsservices.net



MAWC TANK ACTION SUMMARY

Crestview/500,000 Gallon/Single Pedestal

| Category | Exterior Roof | Exterior Sidewall | Interior Roof | Interior Sidewall | Base/Floor |
|----------|---|--|---|--|--|
| 1 | No rust; No steel delamination | Minimal blistering or spot failures | No rust; No steel delamination | Minimal blistering or spot failures | Minimal blistering or spot failures |
| 2 | Light rust; Light steel delamination | 1-5% of spot failures as a percent of surface area | Light rust; Light steel delamination | 1-5% of blisters or spot failures as a percent of surface area | 1-5% of blisters or spot failures as a percent of surface area |
| 3 | Moderate rust; Moderate steel delamination | 5-10% of spot failures as a percent of surface area | Moderate rust; Moderate steel delamination | 5-10% of blisters or spot failures as a percent of surface area | 5-10% of blisters or spot failures as a percent of surface area |
| 4 | Heavy rust; Heavy steel delamination | 10-15% of spot failures as a percent of surface area | Heavy rust; Heavy steel delamination | 10-15% of blisters or spot failures as a percent of surface area | 10-15% of blisters or spot failures as a percent of surface area |
| 5 | Pinholes in the steel beams; Rusted through; Heavy steel delamination | Metal Loss; Existing failure | Pinholes in the steel beams; Rusted through; Heavy steel delamination | Metal Loss; Existing failure | Metal Loss; Existing failure |

| Component | Score | Comments |
|-------------------|-------|---|
| Exterior Roof | 2 | Spot failures, light rust |
| Exterior Sidewall | 1 | Good condition |
| Interior Roof | 4 | Heavy rusting on roof seams and spot failures from welding antenna mounts |
| Interior Sidewall | 3 | Spot failures with rust visible through water |
| Base/Floor | 1 | Minimal sediment visible |

| | |
|---------------|-----|
| Maximum Score | 4 |
| Average Score | 2.2 |

RECOMMENDED TANK ACTION

| ITEM | ESTIMATED COST |
|---|----------------|
| 1 Replace bowl ladder at next renovation. | \$ 8,000.00 |
| 2 Lower grade on south side of foundation. | Estimate |
| 3 Seal pipe chases in dry tube for cellular and coax cables closed. | \$ 1,500.00 |
| 4 Relocate cables mounted to ladder in dry tube. | \$ 2,500.00 |
| 5 Consider interior wet and dry riser complete renovation in the next year. | |
| 6 | |
| 7 | |
| 8 | |
| 9 | |
| 10 | |



Visual Sanitary Inspection Report

Project Information

Sappington #2

Prepared For
Mattie Zautner

Prepared On
2/23/2024

Prepared By
Brad Huebner



Coating Inspection Services
PO Box 133 Eureka, MO 63025
coatinginspectionsservices.net





Table of Contents

Table Of Contents

Report produced using www.FastPhotoReports.com

| | |
|-----------------------------------|----|
| Cover | 1 |
| Table of Contents | 2 |
| General Information | 3 |
| Tank Details | 3 |
| Exterior Coatings Condition | 4 |
| Interior Coating Condition | 5 |
| Security | 6 |
| Photo Observations | 7 |
| Exterior Coating Photos | 7 |
| Interior Coating Photos | 20 |
| Tank Recommendations | 24 |
| Recommendations | 24 |



Coating Inspection Services
 PO Box 133 Eureka, MO 63025
coatinginspectionsservices.net





General Information

Tank Details

Capacity: 2,460,000 Gallon.

Construction Style: Ground Storage.

Builder: Nooter Corp.

Construction Date: 1967.

Exterior Coating: Urethane .

Interior Coating: Epoxy.

Inspector: Brad Huebner.

Inspection Date: 2/14/2024.

Height: 49' H / 92' Dia.



Coating Inspection Services
PO Box 133 Eureka, MO 63025
coatinginspectionsservices.net





General Information

Exterior Coatings Condition

Exterior coating condition: Coatings are in fair condition with an average of 15.0-17.0 mils DFT. Isolated spots of top coat delamination where sidewalls meet lower flange. Spot failures with rust on top of wind girder.

| | |
|-------------------|--|
| Foundation : | Concrete, good condition. |
| Overflow Pipe: | Concrete vault. |
| Overflow Screen: | Not accessible. |
| Flap Gate: | Yes, not accessible. |
| Splash Pad: | Rip-Rap. |
| Exterior ladder: | Good condition, smooth rungs not OSHA compliant. |
| Safety Climb: | None. |
| Ladder Gate: | Aluminum, good condition. |
| Vent: | Aluminum, insect screen intact. |
| Manway: | (1) 24" round. |
| Catwalk: | N/A. |
| Cables: | One coax cable attached to wind girder handrail. |
| Roof Hatch: | 36"x36" with 4" curb. |
| Aviation Light: | None. |
| Roof Ladder: | Handrail up to roof vent. |
| Cellular Carriers | None. |



General Information

Interior Coating Condition

Interior Coating Condition: Coatings are in fair condition with heavy rusting on overflow box and around dome mounts. Rusting on top edge of sidewall. Surface rusting visible on overflow pipe. Isolated spot failures on sidewalls. Minimal sediment visible on tank floor.

Interior Wet Ladder: None.

Safety Climb: None.

Interior Riser Ladder: N/A.

Cathodic Protection: None.

Dry Riser: N/A.



Coating Inspection Services
PO Box 133 Eureka, MO 63025
coatinginspectionsservices.net





General Information

Security

Gates and Fences: Chain link fence with locked gate.

Ladder Gate: Locked.

Roof Hatch: Locked.



Coating Inspection Services
PO Box 133 Eureka, MO 63025
coatinginspectionsservices.net






Exterior Coating Photos



Coating Inspection Services
PO Box 133 Eureka, MO 63025
coatinginspectionsservices.net






Overflow flap gate visible in concrete vault



Peeling paint where lower sidewall meets lower flange














Coating Inspection Services
PO Box 133 Eureka, MO 63025
coatinginspectionsservices.net












Roof vent insect screen intact




Roof vent bird screen
and insect screen
intact






Coating Inspection Services
PO Box 133 Eureka, MO 63025
coatinginspectionsservices.net







Coating Inspection Services
PO Box 133 Eureka, MO 63025
coatinginspectionsservices.net







Interior Coating Photos







Surface rusting on overflow pipe





Tank Recommendations

Recommendations

- Install additional 30" manway during next tank renovation.
- Replace main ladder or install anti skid compound on ladder rungs.
- Install safety cable on main ladder.
- Pressure wash tank to remove mold and mildew.
- Consider complete interior and exterior renovation in the next two years, remove outer dome panels to access rusted dome mounts and top edge of sidewalls.



Coating Inspection Services
PO Box 133 Eureka, MO 63025
coatinginspectionsservices.net



MAWC TANK ACTION SUMMARY

Sappington #2/2,460,000 Gallon/Ground Storage

| Category | Exterior Roof | Exterior Sidewall | Interior Roof | Interior Sidewall | Base/Floor |
|----------|---|--|---|--|--|
| 1 | No rust; No steel delamination | Minimal blistering or spot failures | No rust; No steel delamination | Minimal blistering or spot failures | Minimal blistering or spot failures |
| 2 | Light rust; Light steel delamination | 1-5% of spot failures as a percent of surface area | Light rust; Light steel delamination | 1-5% of blisters or spot failures as a percent of surface area | 1-5% of blisters or spot failures as a percent of surface area |
| 3 | Moderate rust; Moderate steel delamination | 5-10% of spot failures as a percent of surface area | Moderate rust; Moderate steel delamination | 5-10% of blisters or spot failures as a percent of surface area | 5-10% of blisters or spot failures as a percent of surface area |
| 4 | Heavy rust; Heavy steel delamination | 10-15% of spot failures as a percent of surface area | Heavy rust; Heavy steel delamination | 10-15% of blisters or spot failures as a percent of surface area | 10-15% of blisters or spot failures as a percent of surface area |
| 5 | Pinholes in the steel beams; Rusted through; Heavy steel delamination | Metal Loss; Existing failure | Pinholes in the steel beams; Rusted through; Heavy steel delamination | Metal Loss; Existing failure | Metal Loss; Existing failure |

| Component | Score | Comments |
|-------------------|-------|---|
| Exterior Roof | 1 | Aluminum Dome |
| Exterior Sidewall | 2 | Peeling paint |
| Interior Roof | 1 | Aluminum Dome |
| Interior Sidewall | 4 | Heavy rusting around dome mounts and along top edge of sidewall |
| Base/Floor | 3 | Spot failures on floor |

| | |
|---------------|-----|
| Maximum Score | 4 |
| Average Score | 2.2 |

RECOMMENDED TANK ACTION

| ITEM | ESTIMATED COST |
|--|----------------|
| 1 Install additional 30" manway during next tank renovation. | \$ 8,500.00 |
| 2 Replace main ladder or install anti skid compound on ladder rungs. | \$ 8,000.00 |
| 3 Install safety cable on main ladder. | \$ 4,500.00 |
| 4 Pressure wash tank to remove mold and mildew. | \$ 18,000.00 |
| 5 Consider complete interior and exterior renovation in the next two years, remove outer dome panels to access rusted dome mounts and top edge of sidewalls. | |