

APPENDIX C: Photographs



Photograph 1: Photograph looking down into the excavation following the incident. (Source of Photograph: Spire in Response to Staff Data Request 0032). The red arrow (added by Staff) points to electric reciprocating saw shown in Photograph 2. Note: In response to Staff Data Request 0061, Spire answered that the electric reciprocating saw in Photograph 2 is the same electric reciprocating saw at the bottom center of Photograph 1.



**Photograph 2: Photograph of electric reciprocating saw following the incident
(Source: Spire, confirmed in Spire response to Staff Data Request 0061).**



Photograph 3: Photograph was taken on 07-24-2018 looking South along The Paseo. The excavation has been backfilled and its location is marked with a safety cone. (Source: Staff)