

Missouri Water Association

DATE	SYSTEM	VIOLATION TYPE	PARAMETER
3/7/2019	Lakeside at Cross Creek	Inspection Noncompliance	System does not have a permit to dispense
3/7/2019	Lakeside at Cross Creek	Inspection Noncompliance	No backflow prevention test records
3/7/2019	Lakeside at Cross Creek	Inspection Noncompliance	System construction without permission or permit
3/7/2019	Oak Shadows Subdivision Homeowners Association, Inc.	failure to complete detention tank construction	
5/19/2017	Park Place on the Lake	Inspection Noncompliance	failure to maintain system
5/19/2017	Park Place on the Lake	Inspection Noncompliance	potential route for naphthalene contamination identified
6/1/2015	Seven Trails West	Inspection Noncompliance	Develop cross connection control program, currently uncontrolled
6/1/2015	Seven Trails West	Inspection Noncompliance	Missing CCR
6/18/2015	Makalu Estates	Inspection Noncompliance	Develop cross connection control program, currently uncontrolled
6/18/2015	Makalu Estates	Inspection Noncompliance	Abandoned well is not plugged and not documented as abandoned