


May 2005 Furnaces found.

- 05-05-05: 4544 Athlone 1FL- No flu liner in chimney could cause erosion of brick and collapse of chimney.
- 05-06-05: 201 Wooster- Not enough combustion air in room could cause carbonization of furnace.
- 05-07-05: 1826 San Luis Apt. A- Burners covered with rust. Could cause delayed ignition along with rust has to be from exchanger with could be cracked.
- 05-07-05: 932 Pike- Holes in vent pipe. Carbon Monoxide can leak into residence instead of going up chimney.
- 05-09-05: 4400 McPherson- Delayed ignition. Could cause weakening of heat exchanger and roll out of flames.
- 05-14-05: 4401 Strodton- Flu has holes. Carbon monoxide leakage.
- 05-16-05: 6311 Cates- Flu liner not installed correctly. Could cause CO problem.
- 05-16-05: 3922 Lexington- Rust on burners
- 05-17-05: 1844 Bahama- Carbonized heat exchanger.
- 05-18-05: 8643 Brookshire Apt B- Not enough combustion air to run appliances.
- 05-18-05: 4220 Gibson- Flames floating out of chamber. Fire hazard
- 05-18-05: 5732 Goodfellow- Burners covered with debris. Could cause a number of hazardous conditions.
- 05-20-05: 5900 Ferris- Delayed ignition and not sealed at chimney. Possible fire hazard and carbon monoxide leaking into house.
- 05-24-05: 12457 Cohasset- Boiler carbonized.
- 05-24-05: 2155 N New Florissant- Cycling off on high limit and blower will not come on. Could cause weakening of heat exchanger.
- 05-25-05: 13919 Reflection- Carbon monoxide spill switch wired out. If there was CO leaking there would be nothing to detect it.
- 05-26-05: 1631 Sublette- Holes n vent pipe.
- 05-26-05: 12724 Coeur Du Monde Apt 2G- Carbonized heat exchanger.
- 05-26-05: 6932 Bruno Apt C- Reduced vent tee. Could cause improper venting of CO fumes.
- 05-26-05: 4608 Alaska- Holes in vent pipe and bad pilot safety. Could cause leaking CO and bad safety could case furnace to come on and not ignite gas and cause explosion.
- 05-27-05: 1838 Woodbridge- Holes in heat exchanger. Major Co problem causing fumes to leak into house.
- 05-31-05: 628 Geoffrey Apt D- Carbonized heat exchanger.



May 2005 Water Heater Hazards

- 05-03-05: 2135 Cleveland- Holes in vent pipe. Could cause fumes to leak into house.
05-06-05: 201 Wooster- Not enough combustion air to run appliances. Could cause carbonization problems.
05-07-05: 10057 Lilac- Vent pipe rusted. Could cause leaking CO to enter home.
05-07-05: 932 Pike- Holes in vent pipe.
05-07-05: 1826 San Luis Apt A- No relief pipe could cause hot water to relieve and burn anyone standing nearby.
05-07-05: 9903 Jeffrey- relief pipe reduced.
05-13-03: 6758 Nashville- Button type flex connector. Been known to leak.
05-14-05: 433 Olian- Flu fell out of tee stack. CO venting directly into basement.
05-17-05: 5950 Cote Brillante: Tank leaking water. Could cause tank to collapse causing major problems.
05-17-05: 4833 Calvin- No flu liner.
05-18-05: 8643 Brookshire Apt B- Not enough combustion air to run appliances correctly.
05-19-05: 809 Robert- Wrong pitch on vent pipe.
05-20-05: 3083 Santiago- Vented into furnace flu.
05-20-05: 5900 Ferris: Rust holes in vent pipe.
05-24-05: 4634 Whisper Lake- Holes in vent pipe. 05-24-05: 2155 N New Florissant Apt 18- Spilling CO at diverter.
05-26-05: 1631 Sublette- Holes in vent pipe.
05-27-05: 12499 Lyric Apt 110- spillage at diverter, vent not connected, and no control valve. Multiple hazards.
05-27-05: 1838 Woodbridge- Draft diverter installed wrong.

May 2005 Stove Hazards

- 05-11-05: 3382 Ashby- No anti-tip device. Could cause stove to tip over.
05-11-05: 9749 Treadway- No anti-tip device
05-11-05: 2904 Endicott- No anti tip device
05-20-05: 1110 Dillon- Flex connector leaking gas into house.

May 2005 Fuel Run Hazards

05-11-05: 3342 Illinois- Fuel runs will not hold pressure.
05-19-05: 9840 Manchester- Will not hold pressure.
05-20-05: 5900 Ferris- Will not hold pressure.
05-23-05: 5 Creekside- Open fuel run.
05-24-05: 3106 Arrow Rock- Leak at flared copper tee.
05-26-05: 4608 Alaska- Will not hold pressure.
05-26-05: 7561 Hoover- Open fuel run.
05-27-05: 7019 Bentley- Open fuel run.

June 2005 Furnace Hazards

- 06-01-05: 1058 Codington- Heat exchanger and burners rusted. Could cause crack in exchanger and delayed ignition.
- 06-01-05: 9762 Lynntown- Holes in vent pipe and short cycling. Holes could cause CO fumes to escape into house and short cycling could cause weakening of heat exchanger.
- 06-01-05: 506 Village Square- Holes in vent pipe causing fumes to escape into residence.
- 06-01-05: 12558 Ardwick Apt C- Roll out switch bypassed, blockage in exchanger and burnt wiring. Switch is safety and it being bypassed has created a fire hazard and for the wiring to be burnt.
- 06-01-05: 11535 Tivoli- Heavy rust on burners. Could cause delayed ignition and weakening of exchanger.
- 06-02-05: 1556 Knollstone- Holes in vent pipe causing CO fumes to escape in residence.
- 06-02-05: 281 Avant- Holes in vent pipe.
- 06-03-05: 5236 Robin- Carbonized heat exchanger. Could cause serious CO problems and delayed ignition.
- 06-03-05: 10419 Royal- Rusted vent pipe. Could cause vent to fall and vent fumes into residence.
- 06-03-05: 10068 Toelle- Flames rolling out of chamber. Could cause fire or electrical problems.
- 06-04-05: 4226 Carrolton Apt B- Rusted burners could cause delayed ignition.
- 06-04-05: 12540 Arwick Apt A- Improper vent size. Could cause unit to vent improperly and vent into house.
- 06-04-05: 6216 Emma- Rust on burners could cause delayed ignition.
- 06-06-05: 9012 Olden- Holes in vent pipe and no flu liner. Could cause CO problems and vent to malfunction.
- 06-06-05: 2140 Geyer- Water on burners. Could cause burners to delay on ignition or electrical short.
- 06-07-05: 2109 Jannette- Holes in vent pipe.
- 06-07-05: 6902 Dale- Carbonized heat exchanger could cause CO problems.
- 06-08-05: 14358 Summerfield Apt 204- Air disturbance. Probably a crack in exchanger causing CO to leak into ducts.
- 06-09-05: 509 West Kirkham- Improper air for combustion. Could cause unit to carbonize.
- 06-13-05: 1203 Santa Fe- No flu liner. Could cause CO venting problems.
- 06-14-05: 9449 Mary Glen Apt F- Carbonized furnace. Could cause CO problem.
- 06-14-05: 1134 Corumba Walk Apt I- Improper venting. Could cause CO problems.
- 06-14-05: 1103 Lousiville Apt 1N- Not vented properly.
- 06-15-05: 21 Vicksburg- Spilling CO fumes into residence.
- 06-15-05: 2908 Maywood- Rust on burners causing delayed ignition. Numerous problems including weakening of heat exchanger.
- 06-16-05: 6120 West Park 1FL- Boiler door not sealed.
- 06-20-05: 602 San Miguel- Cracked heat exchanger causing CO fumes to leak into residence.
- 06-21-05: 12400 Somerset Apt D- Air disturbance in heat exchanger probably caused by crack which allows fumes to escape into residence.
- 06-21-05: 1834 Woodbridge- Vent pipe rusted. Could cause fumes to escape into residence.
- 06-22-05: 766 West Canterbury Apt D- Carbonized exchanger. Could cause CO problems.

- 06-23-05: 934 N Newstead Apt C- Cracked housing on inducer motor causing fumes to leak into residence.
- 06-23-05: 411 South Geyer Apt 3B- Vented improperly. Could cause CO problem.
- 06-25-05: 3147 Texas- Flu pipe improperly installed. Could cause CO problem.
- 06-25-05: 1002 Coar Apt D- Dirty burners. Could cause delayed ignition.
- 06-30-05: 1226 Oxford Hills Apt 7- Carbonized exchanger could cause CO problem.
- 06-30-05: 12255 Chesapeake- Carbonized exchange could cause CO problems.
- 06-30-05: 733 Bismark- Water dripping on wires. Fire and electrical hazard.

June 2005 Water Heater Hazards

- 06-02-05: 201 Almenior- Wrong relief valve installed.
- 06-02-05: 281 Avant- Holes in vent ipe causing CO fumes to escape into residence.
- 06-02-05: 1556 Knollstone- Holes in vent pipe.
- 06-03-05: 5236 Robin- Vent not sealed at chimney. Could cause CO to escape into house.
- 06-04-05: 3945 Utah 2FL- Rust holes in vent pipe.
- 06-04-05: 2608 Hebert- Holes in vent pipe.
- 06-04-05: 6212 Emma- Flu pipe split. Could cause CO fumes to escape into residence.
- 06-07-05: 211 Dogtown Walk- Vent too close to combustable material. Fire hazard
- 06-07-05: 3408 Oxford- Rust holes in vent pipe causing CO problem.
- 06-10-05: 4753 Cleveland 1FL- Vent pipe installed improperly. Could cause CO leakage.
- 06-11-05: 727 Dodridge- Not vented to chimney. Serious Co problem.
- 06-13-05: 1203 Santa Fe: No flu liner installed. Could cause CO problems.
- 06-14-05: 4216 Russell- Rust hole in vent pipe and vented improperly. Could cause CO problems.
- 06-15-05: 2908 Maywood- Flu too close to combustibile material. Fire hazard:
- 06-16-05: 262 Buddie- Spilling CO fumes at unit.
- 06-16-05: 10353 Beau Jardin Apt 8- Baffle fell on burner. Could cause CO problem.
- 06-16-05: 12046 Charter House- Cracked flex connector and leak on pilot tubing. Leaking gas into town house.
- 06-20-05: 602 San Miqual- Vent pipe pulled away from tee. Causing CO gases to vent into residence.
- 06-21-05: 6916 Colonial Woods Apt 1E- No relief pipe. Could cause customer to get scalded if relief valve relieves.
- 06-25-05: 1010 N 10th Street Apt A- No t-stat valve. Could cause scalding.
- 06-25-05: 10214 Renis Garden- No t-stat valve. Could cause scalding.

June 2005 Fuel Run Hazards

- 06-03-05: 816 Indian Hills- Open fuel run down stream from shut off. If customer turns knob gas would leak into residence causing major problems.
- 06-04-05: 12036 Glen Cove- Shut off passing to open fuel run causing live gas to leak into residence.
- 06-04-05: 4027 Humphrey- Flare-fitting cap leaking on copper line causing gas to leak into house.
- 06-04-05: 6216 Emma- Leaks in fuel runs causing gas to leak into house.
- 06-14-05: 2323 Wengler- Open fuel run downstream from shut off.
- 06-18-05: 3840 South Old Highway 94- Flex connector through floor. Could cause leak in line.
- 06-30-05: 9706 Lynntown- Open fuel line down stream from shut off.

July 2005 Furnace Hazards

- 07-01-05: 5410 Michigan 2FL- Vent installed improperly.
07-01-05: 5223 Beacon- Pilot tubing leaking causing gas to leak into residence.
07-01-05: 1434 Willow Brook- Flames floating out of carbonized heat exchanger. CO hazard.
07-02-05: 175 Duquette- Rust holes in vent pipe. Could cause CO fumes to leak into residence.
07-02-05: 10570 Emerald Ridge- Flames floating out of carbonized exchanger. CO and fire hazard.
07-02-05: 5841 Cabanne Apt G- Carbonized in heat exchanger and flames rolling out. CO and fire hazard.
07-02-05: 1280 Marquis Apt 1- Air disturbance in chamber. Could be crack in exchanger cause CO fumes to escape into residence.
07-05-05: 1643 Meyer- Rusted and carbonized chamber. Could cause Co problems.
07-06-05: 14338 Summerfield Apt 103- Flames floating out of chamber. Fire hazard.
07-06-05: 1226 Oxford Hills Apt 4- Baffle fell on burner. CO hazard.
07-06-05: 2703 Limit Apt E- 2 right cells carbonized. Co hazard.
07-07-05: 5305 5th Street- Carbonized chambers. CO hazard.
07-07-05: 607 Thunderbird Apt 1B- Holes in vent pipe causing fumes to escape into residence.
07-09-05: 12615 Markaire- Flames burning under burners. Fire hazard
07-09-05: 10165 Cabana Apt J- Flu rusted. Could create Co problem.
07-18-05: 8310 Midland- Cracked heat exchanger causing CO fumes to leak into residence.
07-12-05: 4258 Carrolton Apt A- Carbonized chamber in heat exchanger. CO hazard.
07-14-05: 9507 Madelaine Manor- Flu pipe has holes and vent pipe not installed correctly. Could cause fumes to enter home.
07-15-05: 11164 Estrada- Chambers rusted and have standing water in them. CO and delayed ignition hazard.
07-16-05: 5762 Terry apt 1E- Leak at pilot tubing causing gas to leak into residence.
07-22-05: 342 Impala- Flames floating out of chamber causing a fire hazard.
07-25-05: 1309 Henriette Hills- Blower motor locked up. Could cause unit to incur too much heat.
07-25-05: 12442 Ardwick- Cracked heat exchanger. CO fumes leaking into residence.
07-26-05: 2141 Seven Pines- Carbonized chamber. CO hazard.
07-27-05: 806 Teson- Cracked heat exchanger causing CO fumes to escape into residence.
07-28-05: 3510 Dix- Flames floating out of chamber causing a fire hazard.

July 2005 Water Heater Hazards

- 07-05-05: 5026 Bulwer- Two draft hoods installed. Could cause CO problem.
07-06-05: 14338 Summerfield- Flames floating out of burner area. Fire hazard.
07-12-05: 1209 Scott- Flu pipe not connected causing raw CO fumes to leak into residence.
07-16-05: 978 Dawnview- Rust holes in vent pipe. Could cause CO fumes to leak into residence.
07-18-05: 8310 Midland- No relief pipe. Could cause scalding in relief valve activates.
07-19-05: 7324 Colgate- Chimney blocked. Could cause CO hazard.

07-20-05: 10729 Margate Hall- Vent pipe rusted out. Could cause fumes to leak into residence.
07-20-05 ; 1314 Warrior Song Way- No relief pipe. Could cause scalding if relief valve activates.
07-21-05: 1508 Tivoli- Vent pipe too close to combustible material. Fire hazard.
07-21-05: 12836 Haverton- Not enough combustible air to run appliances. CO hazard.
07-27-05: 7520 Ahern- Rust holes in vent pipe could cause CO fumes to leak into residence.
07-27-05: 52 Arbor Village Apt C- Button type flex connector.
07-28-05: 502 Angelique- Gas leak at t-stat causing raw gas to leak into residence.
07-28-05: 365 Pralle- Reduced relief pipe. Could cause block if valve activates.
07-29-05: 4517 Fair 1FL- Needs flu liner. Could cause CO problems.

July 2005 Fuel Run Hazards

07-01-05: 5223 Beacon- Open fuel run downstream from shut off.
07-01-05: 2834 S Jefferson- Leaking fuel run allowing gas to enter residence.
07-02-05: 3624 Brown Rd- Open fuel run down stream from shut off.
07-02-05: 22 Jefferson- Open fuel run downstream from shut off valve.
07-05-05: 1004 Pocono Trail- Two flexes hooked together. Possible leak hazard.
07-14-05: 3338 St Joachim- Open fuel run downstream from shut off. If shut off is turned on by customer raw gas will leak into home.
07-15-05: 1506 Redman- Two flex connectors hooked together through wall. Leak hazard.
07-19-05: 3720 Winnebago 1FL- Flex connector leaking gas into residence.
07-19-05: 9375 Sonora- Open fuel run down stream from shut off valve.
07-23-05: 8625 Jo Court- Open fuel run downstream from shut off valve.
07-26-05: 8221 Brenner- Fuel runs leaking gas into residence.
07-27-05: 1061 N Warson- Two flex connectors hooked together running through a wall. Leak hazard.
07-29-05: 4099 Bridgehampton- Fuel run open downstream from shut off valve.
07-30-05: 733 Bismark- Open fuel run downstream from shut off valv

July 2005 Ranges and Dryer hazards

07-07-05: 607 Thunderbird- No anti tip device. Against AGA code.
07-19-05: 1035 Olive- No anti tip device and two flexes hooked together.
07-19-05: 10 Bel Rae Apt B-207- No anti tip device.
07-21-05: 2237 Rule- Not vented to outside. CO hazard.
07-21-05: 12836 Haverton- Plastic vent pipe. CO hazard.

August 2005 Furnace Hazards

- 08-01-05: 7656 Norstead Apt 3- Flames floating out of chamber. Fire hazard.
- 08-01-05: 314 Chez Paree- Cracked heat exchanger causing CO fumes to leak into residence.
- 08-02-05: 605 West Gate Apt A- Gas valve leaking causing raw gas to leak into home.
- 08-02-05: 8685 Old Bonhomme- Carbonized chamber in heat exchanger.
- 08-03-05: 7210 Stanford- Cracked heat exchanger causing CO fumes to leak into house.
- 08-03-05: 3372 San Seville- Improperly vented creating possible CO problem.
- 08-03-05: 1093 Rue Le Chelle- Blower broken creating excess heat to inner part of furnace.
- 08-04-05: 4040 Flad 1FL- Holes in vent pipe causing fumes to leak into residence.
- 08-04-05: 8914 Kathlyn- Blower motor frozen causing undue heat stress on unit.
- 08-04-05: 2799 Notting Hill Apt G- Flames rolling out causing fire hazard.
- 08-06-05: 14350 New Hallsferry Apt 206- Rusted out heat exchanger creating possible CO problem
- 08-08-05: 1135 Town N Four Parkway- Vent pipe not connected causing CO to leak into residence.
- 08-09-05: 24 Brigworth- Improper venting creating possible CO problem.
- 08-10-05: 415 Waterford- Not enough make up air for proper combustion.
- 08-10-05: 414 Evergreen- Holes in vent pipe causing CO fumes to leak into residence.
- 08-11-05: 9057 McNulty- Holes in vent and no flu liner causing possible CO problem
- 08-11-05: 13 San Miquel Apt C- Air disturbance in chamber creating possible CO hazard.
- 08-11-05: 5230 Villa Rosa- Cracked heat exchanger causing Co fumes to leak into residence.
- 08-12-05: 10144 Royal- Holes in vent pipe causing fumes to escape into residence.
- 08-12-05: 8319 Knollwood- Holes in vent pipe causing fumes to leak into house.
- 08-15-05: 9604 Lynntown- Blocked heat exchanger causing flames to roll out creating a fire hazard.
- 08-15-05: 5445 Union- Carbonized chamber in heat exchanger. Possible CO hazard.
- 08-16-05: 9555 Madelaine Manor 1FL- Duct work not correct.
- 08-16-05: 6036 North Point- No diverter on furnace.
- 08-17-05: 6134 Kingsford- Flames burning under burners. Fire hazard.
- 08-19-05: 6826 Chesapeake- Cracked heat exchanger causing fumes to leak into residence.
- 08-21-05: 1935 Monfort Apt P- Flames floating out of chamber. Could cause fire in unit.
- 08-20-05: 1361 Stonebury Ct- Swivel tee rusted out creating possible CO leak.
- 08-23-05: 14337 Sumerfield- Burner missing. Possible fire hazard and mini-explosion.
- 08-23-05: 1840 Kilred- Holes in vent pipe and broken glass on sace heater- Possible CO problems
- 08-23-05: 6666 Washington Apt 2W- Vent pipe not sealed at wall. Possible CO problem.
- 08-24-05: 4515 Whisper Lake Apt 8- Rusted out chamber of heat exchanger. Could cause flames to float or delayed ignition.
- 08-24-05: 4690 Whisper Lake Apt 3- Vented improperly. Possible CO problems.
- 08-27-05: 7410 Normandie Apt M- Flames floating out of chamber causing fire hazard.
- 08-31-05: 1164 Town N Four- vent pipe not connected. CO fumes leaking directly into residence.
- 08-31-05: 1127 Breakwater Way- Air disturbance in chamber. CO fumes leaking into general air.
- 08-31-05: 1058 Rue La Chelle- Room not big enough for make up air. Could cause CO problem.
- 08-31-05: 7371 Normandie Apt II- Vent too close to combustibile material. Fire hazard.
- 08-31-05: 3300 Cross Keys Apt I- Rust on chambers of heat exchanger. Could cause CO problems.

August 2005 water heaters

08-03-05: 3434 Wismer- Valve passing causing gas to seep into unit.
08-06-05: 3959 Brittany Circle Apt D- No relief pipe causing burn hazard
08-08-05: 3900 Lousianna- Spilling CO at diverter
08-09-05: 12615 Markaire- No relief pipe causing possible burn hazard
08-10-05: 9940 Valley- improper installation of vent pipe causing spillage of fumes
08-11-05: 11302 Bonanza- Vent pipe separated from stack causing CO spillage
08-11-05: 4214 Labadie- Two diverters causing possible CO problem
08-12-05: 9718 Scottsdale- Two diverters causing possible CO problem
08-13-05: 10144 Royal- Holes in vent pipe.
08-13-05: 8818 Harold- Vent within 6 inches of combustable material causing fire hazard
08-16-05: 872 Longacre Apt D- Vent not installed incorrectly.
08-16-05: 9507 Madelaine Manor- Holes in vent pipe
08-17-05: 1359 Kael Apt 11- Spilling CO at diverter
08-18-05: 843 N Florissant- Vent falling out of chimney causing CO spillage.
08-23-05: 1840 Kilrea- Holes in vent pipe causing spillage of fumes into house
08-23-05: 9748 Vickie- Relief pipe leaking and the end is capped off.
08-25-05: 1765 Woodridge- Rusted tank and water leaking
08-26-05: 4708 Locke- Rust holes in vent pipe.
08-30-05: 1201 Backer- Vent pipe falling out of chimney causing CO fumes to leak into house
08-30-05: 9031 Doyle- Vent not attached causing CO fumes to escape
08-30-05: 9008 Ramona- Rust holes in vent pipe
08-31-05: 12805 Town N Four- No relief pipe causing possible burn hazard
08-31-05: 12810 Town N Four- No relief pipe causing burn hazard
08-31-05: 8327 Appleton- Holes in vent pipe

Fuel Runs August 2005

08-06-05: 11937 Sprucehaven- Open fuel run
08-08-05: 3501 N Lindbergh- Leaking fuel runs.
08-10-05: 415 Waterford- Soft solder on copper fuel runs.
08-11-05: 3635 Lee IFL- Won't hold pressure
08-17-05: 459 Scenic- Fuel runs will not hold pressure
08-18-05: 3832 Wyoming- Fuel run goes through return air.
08-26-05: 8027 Patterson- Open fuel run leaking at range

September 2005 Furnaces

09-01-05: 725 W Canterbury Apt B- Carbonized chamber
09-01-05: 1897 Monfort- Delayed ignition.
09-01-05: 12474 Lyric Ct Apt 201- Spillage at diverter.
09-01-05: 12499 Lyric Ct - Carbonized burners
09-02-05: 7728 Delmar 2FL- Not enough secondary air.
09-03-05: 7462 Ahern 1FL- Vent tee rusted out.
09-03-05: 1890 Notting Hill Apt P- Flames rolling out of chamber.
09-06-05: 597 Glenco- Carbonized furnace
9-06-05: 7 Francis- Gas valve passing.
09-06-05: 1765 Woodridge Apt C- Flames rolling out of chamber.
09-07-05: 8028 Gardner- Gas line leaking at furnace.
09-08-05: 2841 Adie Apt 11- Delayed ignition.
09-09-05: 4016 Brittany- Flames rolling out of chamber
09-09-05: 2566 Main Ave- Not enough combustion air.
09-09-05: 2240 Mullanphy- Air disturbance in heat exchanger.
09-10-05: 755 N Woodlawn- Burners dirty.
09-10-05: 144 Logtrail- Cracked heat exchanger and dirty burners
09-10-05: 4555 Newberry Terrace- Faulty gas valve.
09-12-05: 660 Chain of Rocks Apt F- Carbonized chambers and rusted out.
09-12-05: 11531 Tivoli- Leak at pilot tubing.
09-12-05: 160 Ballwin Manor- pilot assembly not connected to burners
09-12-05: 6131 Adeline- Door switch wired out.
09-16-05: 742 W Canterbury Apt D- Faulty gas valve.
09-16-05: 12276 Old Big Bend Apt A- Leak at control valve
09-17-05: 240 St Daniel - Flames rolling out of chambers
09-17-05: 9409 Mirriam- Carbonized burners
09-17-05: 7300 Normandie Ct Apt C- Flames rolling out of chamber.
09-18-05: 833 Sudberry- Leaking gas at controls
09-19-05: 8862 Dragonwyk Apt C- Tee and burners rusted.
09-19-05: 10303 Tuxford Apt 7- Holes in vent pipe.
09-20-05: 14338 Summerfield- Flames rolling out of chamber.
09-20-05: 3627 Summit- Swivel tee fell out of vent tee
09-20-05: 15160 Appalacian Trail- Gas valve passing raw gas.
09-20-05: 6339 Wellsmar- Rusted out vent pipe.
09-20-05: 219 Steamboat Apt 203- Flames rolling out of chamber
09-20-05: 310 Hill Trail- 2 furnaces carbonized
09-20-05: 407 Stephanie- No vents for combustion air.
09-21-05: 14343 Sunswept Park Apt 207- Blocked chamber
09-23-05: 4454 Lexington- Vented incorrectly.
09-24-05: 8105 University Dr- Not enough combustion air
09-24-05: 1895 San Lucas- Delayed ignition causing fire hazard.

09-24-05: 15517 Peach Hill Apt 210- Flames rolling out of dirty burners
09-25-05: 1107 Marie Dale Apt B- Won't hold pressure and burners are dirty.
09-25-05: 9916 Solar- Gas valve passing gas.
09-27-05: 7201 West Park Apt E- Door switch wired out.

September 2005 Water heaters

09-01-05: 5854 Terry- Improper venting and flu blocked.
09-01-05: 4621 Whisper lake- Spillage at diverter.
09-02-05: 8337 Garfield- Leak at t-stat.
09-06-05: 11551 Tivoli- Flames floating out of burner compartment.
09-09-05: 2322 McLaren- Vent pipe rusted out at wall.
09-12-05: 4006 Herbert- In garage and not 16 inches off floor.
09-12-05: 6131 Adelaide- Button type flex connector.
09-12-05: 15426 Jost Estates- Leak at pilot tubing.
09-15-05: 11833 Strand Ct- No relief pipe.
09-17-05: 2727 Kenny- gas leaking at control valve.
09-20-05: 3627 Summit- Swivel tee fell out of vent tee.
09-20-05: 310 Hilltrail- No knob on control valve.
09-20-05: 705 Lynnhaven- No relief pipe and vent too close to combustable materials
09-21-05: 11140 Estrada Apt A- Spilling CO at diverter.
09-24-05: 9767 Terry 2FL- Spillage at diverter.
09-24-05: 5233 Bowler- flu 6 inches from combustable material.
09-25-05: 425 W Woodbine- Pilot will not stay lit

September 2005 Fuel Runs

09-03-05: 11947 Glenwest- Leak on fuel run to range.
09-04-05: 2759 Aberdeen- Leaks on line to light and grill.
09-08-05: 830 Riderwood- Will not hold pressure.
09-08-05: 833 Sudberry- Will not hold pressure
09-09-05: 13100 Barrett Cirle- Will not hold pressure.
09-12-05: 11531 Tivoli- Brass flex leaking.

09-14-05: 4215 Colonial- water gate valve on gas fuel run.
09-14-05: 1035 Canisus- Gas light line leaking.
09-14-05: 3305 Bryn Manor- Fuel run leaking.
09-14-05: 3140 Greenway Chase- open fuelrun and lock cock partially on and leaking in home.
09-15-05: 1356 Cave Springs- open fuel run leaking.
09-15-05: 11966 Baresford- Flex connector through floor.
09-16-05: 949 Tara Oaks- Will not hold pressure
09-17-05: 4320 Butterhill- Cracked and leaking flex connector.
09-18-05: 13201 Thornhill- Will not hold pressure.
09-20-05: 714 Knickerbacker- Won't hold pressure.
09-19-05: 1755 Summerlake- Will not hold pressure.
09-20-05: 79 Boyd- Will not hold pressure.
09-21-05: 14791 Cherrymore- Fuel run to grill leaking.
09-21-05: 3180 W Clay Apt 514- Fuel runs leaking.
09-22-05: 490 Candlelight- open fuel run with tape on end to seal same.
09-24-05: 10 Ritnoir- Open fuel run to dryer.
09-24-05: 1401 Westwind- Will not hold pressure.
09-24-05: 215 Spring Oaks- Will not hold pressure
09-24-05: 25 Oak Tree- Will not hold pressure.
09-24-05: 8533 Betty Lee- Improperly capped fuel run.

September 2005 Gas Ranges

09-13-05: 1967 Pick Fair- Rubber hose for a gas hook up.
09-20-05: 14471 Boytry- Valve passing gas.
09-21-05: 6805 Garner- No anti tip device.
09-24-05: 2514 La Caracas- No anti tip device.
09-24-05: 2961 Kincaid- No anti tip device.
09-24-05: 8105 University- No anti tip device.
09-28-05: 1308: Shanendoah- Oven valve passing gas.