

Missouri Water Association

| DATE | SYSTEM | VIOLATION TYPE | PARAMETER |
|-----------|--|---|--|
| 3/7/2019 | Lakeside at Cross Creek | Inspection Noncompliance | System does not have a permit to dispense |
| 3/7/2019 | Lakeside at Cross Creek | Inspection Noncompliance | No backflow prevention test records |
| 3/7/2019 | Lakeside at Cross Creek | Inspection Noncompliance | System construction without permission or permit |
| 3/7/2019 | Oak Shadows Subdivision Homeowners Association, Inc. | failure to complete detention tank construction | |
| 5/19/2017 | Park Place on the Lake | Inspection Noncompliance | failure to maintain system |
| 5/19/2017 | Park Place on the Lake | Inspection Noncompliance | potential route for naphthalene contamination identified |
| 6/1/2015 | Seven Trails West | Inspection Noncompliance | Develop cross connection control program, currently uncontrolled |
| 6/1/2015 | Seven Trails West | Inspection Noncompliance | Missing CCR |
| 6/18/2015 | Makalu Estates | Inspection Noncompliance | Develop cross connection control program, currently uncontrolled |
| 6/18/2015 | Makalu Estates | Inspection Noncompliance | Abandoned well is not plugged and not documented as abandoned |