BEFORE THE PUBLIC SERVICE COMMISSION OF THE STATE OF MISSOURI

Director of the Manufactured Housing and)
Modular Units Program of the Public)
Service Commission,)
)
Complainant,)
)
vs.)
)
5 Star Homes and Development)
Company, Inc.)
)
Respondent.)

Case No. MC-2010-____

COMPLAINT

COMES NOW the Director of the Manufactured Housing and Modular Units Program of the Missouri Public Service Commission ("Director" and "Department"), by and through the Missouri Public Service Commission's ("Commission") Office of Staff Counsel, pursuant to Section 700.100, RSMo 2000¹. and for his Complaint against 5 Star Homes and Development Company, Inc. ("5 Star") states as follows:

AUTHORITY AND GENERAL ALLEGATIONS

1. The Commission has jurisdiction over manufactured homes, modular unit homes and modular unit home dealers pursuant to Chapter 700.

2. Commission Rule 4 CSR 240-123.020, the Commission delegated to the Director all of its powers pertaining to modular units under Chapter 700 RSMo, except the powers to

¹ All references to the Revised Statutes of Missouri will be to RSMo 2000, as currently supplemented.

revoke, deny, refuse to renew or place on probation a registration under Section 700.090, which are retained by the Commission.

3. 5 Star is a modular unit dealer as defined in Section 700.010(4).

4. In January 2010, the Director did not complete processing of 5 Star's renewal application and a 2010 Certificate of Dealer Registration did not issue because 5 Star had submitted a deficient application in that:

- (a) 5 Star has not paid its \$200 re-inspection fee of the Grady Home as required under 4 CSR 240-123.095; and
- (b) 5 Star does not appear to be operating out of the place of business listed on its renewal application (69 Schaper Road, Foristell, Missouri, 63348), a violation of Section 700.090.3(1)(b)(See attached Exhibit 1); and,
- (c) 5 Star has not informed the Director of a change in place of business and is unable to be contacted by the Director. (Section 700.090.3(1)(b)

5. 5 Star has not cured the deficiencies in its renewal application.

6. 5 Star's failure to pay the Grady Home inspection fee constitutes grounds for the denial, suspension, revocation, or placing on probation of a dealer's certificate of registration under 4 CSR 240-123.095(11).

7. A dealer that fails to correct a code violation² in a new modular unit home within a reasonable period of time not to exceed ninety (90) days after being ordered to do so in writing by the Director has engaged in conduct that is defined as a misdemeanor in Section 700.045(5).

8. Any dealer that engages in conduct that is in violation of Section 700.045 is subject to having its license not renewed, revoked, suspended, or placed on probation by the Commission pursuant to Section 700.100.3(9).

² The "code" is defined by rule 4 CSR 240-120.100 as the federal standards found at 24 CFR Part 3280 and the manufacturer's installation instructions.

9. Any dealer that fails to arrange for the proper initial setup of a new modular unit home is subject to having its registration not renewed, revoked, suspended, or placed on probation by the Commission pursuant to Section 700.100.3(6).

SPECIFIC FACTS IN SUPPORT OF ALLEGATIONS

The Grady Home

10. The Director re-alleges and incorporates herein the allegations contained in paragraphs 1-9.

11. The Director sent a letter to 5 Star dated December 1, 2009, with a copy of the original inspection report of November 24, 2009 on the new modular home purchased by Jeff and Ann Grady (the "Grady Home") located at 25453 Maywood Road, Versailles, Missouri. (Exhibit 2)

12. The November 24, 2009 inspection report revealed several code violations and directed 5 Star to make certain repairs to correct installation deficiencies. (Exhibit 2, Schedule 1)

13. 5 Star failed to make repairs to the Grady Home.

14. The Director sent 5 Star a second letter and second inspection report of the Grady home dated January 8, 2010. (Exhibit 3)

15. 5 Star failed to make repairs to the Grady Home. (Exhibit 3, Schedule 1)

16. The Director sent a third and final letter to 5 Star dated March 11, 2010. (Exhibit 4)

17. 5 Star again failed to make the necessary repairs to the Grady Home. (Exhibit 4, Schedule 1)

18. 5 Star's failure to correct the deficiencies to the Grady Home is a violation of Section 700.100.

3

Three Homes Sold and Not Delivered to Buyers Gordon, White, and Mugler

19. The Director re-alleges and incorporates herein the allegations contained in paragraphs 1-9.

20. On November 3, 2009, the Director sent a letter to 5 Star with a copy of three (3) consumer complaints submitted to the Director against 5 Star for failing to deliver the homes sold to buyers (Exhibit 5):

- a) Timothy Gordon (the "Gordon Home") of 2842 Foxwood Drive, Maryland Heights, Missouri (Exhibit 5, Schedule 1);
- b) Kenneth White (the "White Home") of 175 Criderville, O'Fallon,Missouri (Exhibit 5, Schedule 2); and,
- Michelle and Hans Mugler (the "Mugler Home") of 131 College Avenue,
 Kirkwood, Missouri (Exhibit 5, Schedule 3).

21. The Director sent a follow up letter dated March 11, 2010 to 5 Star directing the dealer to deliver and install the Gordon, White, and Mugler homes.

22. 5 Star has not delivered the homes to their buyers.

23. 5 Star's failure to deliver and install the Gordon, White, and Mugler homes constitute three (3) separate violations of Section 700.100 as described below in Counts 2, 3, and 4.

<u>COUNT 1:</u> Failure to Correct Code Violations of the Grady Home

24. The Director re-alleges and incorporates herein the allegations contained in paragraphs 10 - 18.

25. 5 Star has failed to correct the code violations of the Grady Home within a reasonable period of time after being ordered to do so by the Director and such failure is a violation of Section 700.045(5).

4

26. 5 Star's failure to correct the Grady Home code violations constitutes grounds for the denial of 5 Star's application for renewal of its dealer registration under Section 700.100.3(9).

COUNT 2: Failure to Arrange for the Setup of the Gordon Home

27. The Director re-alleges and incorporates herein the allegations and information contained in paragraphs 19 - 22.

28. 5 Star has failed to arrange for the proper initial setup of the Gordon Home and such failure is a violation of Section 700.100.3(6).

<u>COUNT 3:</u> Failure to Arrange for the Setup of the White Home

29. The Director re-alleges and incorporates herein the allegations and information contained in paragraphs 19 - 22.

30. 5 Star has failed to arrange for the proper initial setup of the White Home and such failure is a violation of Section 700.100.3(6).

COUNT 4: Failure to Arrange for the Setup of the Mugler Home

31. The Director re-alleges and incorporates herein the allegations and information contained in paragraphs 19 - 22.

32. 5 Star has failed to arrange for the proper initial setup of the Mugler Home and such failure is a violation of Section 700.100.3(6).

<u>COUNT 5:</u> Failure to Pay Re-Inspection Fee

33. The Director re-alleges and incorporates herein the allegations and information contained in paragraphs 1-9.

34. 5 Star has failed to pay the \$200 re-inspection fee for the January 5, 2010 second inspection of the Grady Home and such failure to pay is a violation of 4 CSR 240-123.095(6).

5

35. 5 Star's failure to pay the \$200 re-inspection fee constitutes grounds for the denial of 5 Star's application for renewal of its dealer registration under 4 CSR 240-123.095(11)(A) and Section 700.040. (Exhibit 6)

RELIEF SOUGHT

36. The Director re-alleges and incorporates herein the allegations and information contained in paragraphs 1 - 34.

37. Formal non-renewal of 5 Star's 2010 application for renewal of dealer registration is appropriate because 5 Star has (a) failed to provide a current place of business in violation of Section 700.090.3(1)(b); (b) failed to pay the \$200 Grady Home re-inspection fee in violation of 4 CSR 240-123.095(11); (c) failed to correct the code violations of the Grady Home within a reasonable period of time in violation of Section 700.045(5); and (d) failed to arrange for the delivery and initial setup of the three (3) homes purchased by Gordon, White, and Mugler in multiple violations of Section 700.100.3 (6).

38. Based on the above allegations and Counts 1 through 5 against 5 Star, the Director requests the Commission authorize its General Counsel to seek penalties in Circuit Court. Pursuant to Section 700.115.2, each day's violation of Sections 700.100.3(6) and 700.100.3(9) is a separate offense and renders 5 Star liable for a penalty of up to \$1,000 for each offense.³

SERVICE

39. According to the current records on file with the Missouri Secretary of State's Office, Mr. Jeff Kasten is the President and Registered Agent of 5 Star. Because it appears that 5 Star is no longer operating from its principal place of business at 69 Schaper Road, Foristell, MO 63348, the Director will provide an additional service copy of this complaint to

³ Section 700.040(5) provides that "The Commission may issue and promulgate such rules and regulations as necessary to make effective the code and the provisions of sections 700.010 to 700.115." Any modular unit code or commission rule violations fall within the ambit of the civil penalty provisions of Section 700.115.2 RSMo.

Mr. Kasten at 45 Schaper Oaks Court, Foristell, Missouri 63348, which is the physical address he has listed in his roles as President and Registered Agent.

WHEREFORE, the Director prays that the Commission provide notice to the Respondent of this complaint and, after hearing, affirm, authorize, and approve the Director's actions and formally non-renew 5 Star's application for renewal of dealer registration, and authorize the General Counsel to seek penalties in Circuit Court as enumerated in Counts 1 through 5 above, and issue other findings and orders as are just and reasonable.

Respectfully submitted,

<u>s/Robert S. Berlin</u>

Robert S. Berlin Senior General Counsel Missouri Bar No. 51709

Attorney for the Director of the Manufactured Housing and Modular Units Program of the Missouri Public Service Commission P. O. Box 360 Jefferson City, MO 65102 (573) 526-7779 (573) 751- 9285 (Fax) Email: bob.berlin@psc.mo.gov

Certificate of Service

I hereby certify that copies of the foregoing have been mailed or hand-delivered to the persons listed below on this 5th day of May 2010.

s/Robert S. Berlin_

Office of Public Counsel Lewis Mills 200 Madison Street, Suite 650 Jefferson City, MO 65102 opcservice@ded.mo.gov

Missouri Public Service Commission

Application for Manufactured Home or Modular Unit Certificate of Dealer Registration (Any false statement in this application is a violation of the law and may be punished by fine or imprisonment or both)

Transmittal Number (PSC Office Use O 4193080 847	nly) (heck Number (PS	COffice Use Only をちろ」 48	40		C	heck Amount (PSC Of 「シスのく		
New Application A Renewa		If Renewal, Registration Number:					Manufactured (HUD) Home Dealer		
1		1222701				🔊 Modular Unit Dealer			
DEALERSHIP INFORMATION				CORPORATIONS ONLY - ADDRESS					
Dealership Name					Corporate Name				
5 Star Homes & Development Co INC				5 Star Homes & Development Co INC					
Street Address of Bona Fide Established	Place of Busine	ss (Not P.O. Box)	-		Address	ridnies	7 Developmu		
69 Schaper RD		,			69 s	chaper	RD		
City	State	Zip Code	County		City		State	Zip Code	
Foristell	ſhο	63348	St Charles	5	Foristell		mo	63348	
Phone	Fax	0			Phone	1	Fax	FEIN	
636463 2262	636 67	3 1021			636 463 2	262	636 673 1021		
E-mail					E-mail				
homes by SSINT	at YAHOO	Com	d a daalaaahin a				Shrat Kal		
PREVIOUS DEALERSHIP INFO IF YES, please list previously or				under a	name other th	ian what i	s listed abover		
Type of Ownership	and a would be	in the second se			If a Corporation	, State of Inc	corporation		
Individual/Sole Proprietorship	s 🗆 Partnersł	ip k iCorporati	on 🗖 LLC Com	pany	MISSO	ince			
YOU MUST ATTACH: Statement of	f No Taxes Du	e - Call the Dep	artment of Reven	ue @ 57	73-751-9268 to 0	obtain.	AIA		
Corporations, LLC's & Partnersh								1-4153 to obtain.	
Corporations: Must submit a copy LIST ALL OWNERS BELOW								titles of principal officers.	
	li a Fal	mersnip, ist nai			-	auon, ast n	anes, addresses a		
Name (Last, First, MI)		Home Address			City	State	Zip Code	Social Security #	
1. KASLEN JOHN J	45 Scha	PAT OAKS (1 F	onsley		mo	63348		
2.							NECH	<u>eiven</u>	
3.							K		
		*						2 5 2010	
4. UNITS SOLD Number of units	New	Used	List Manufacture	206			JAN	00 2010	
sold in prior 12 months		0300			H HORLS				
INSTALLERS - Certified Installer	(s) performing	your HUD hon				#(s).	MANUFACT	URED HOUSING	
Modular Only Installations? D N	o ⊠ Yes			$= = x \hat{x}^{+} \cdot \hat{z}$		$({\mathbb T}_{{\mathbb T}_{n}}) \to {\mathbb T}_{n}$		RTMENT	
FELONY INFORMATION									
Has owner (or any partner, if part	nership, or off	cer, if corporati	on) within the pre	cedina	ten (10) vears l	been conv	icted in any Federa	l or State court of a felony	
relating to the acquisition or trans	fer of a manuf	actured home of	r any other form	of prop	erty?		íes		
If yes, provide the Date	Court			Convicti	on <i>l</i> ,		Sentence		
following									
MISDEMEANOR INFORMAT			an) within the most		Euro (E) and and b		and in one Foderel	ar State court of a	
Has owner (or any partner, if part misdemeanor relating to the acqu								or state court of a	
If yes, provide the Date	Court	in or a manale		Convicti		<u>, , , , , , , , , , , , , , , , , , , </u>	Sentence		
following								·	
CERTIFICATION									
I do solemnly affirm and verify that sign this application.	t the concern	named herein i	Refiged	denand	i tave be auth	ority to ma	ake the statements	contained herein and to	
Signature of Owner, Partner or C							ate //		
0-	Le		JAN 2	252	010		111/10 -		
Please remit this completed app	dication to the	address belo	w along with the	Regist	tration Fee of	\$200. Ma	ake all checks paya	able to the Missouri	
Director of Revenue.			MO PUBLIC SER	VICE CO	MMISSION				

EXHIBIT 2



Commissioners **ROBERT M. CLAYTON III** Chairman . **CONNIE MURRAY**

JEFF DAVIS

TERRY M. JARRETT

KEVIN GUNN

POST OFFICE BOX 360 **JEFFERSON CITY MISSOURI 65102** 573-751-3234 573-751-1847 (Fax Number) http://www.psc.mo.gov

Missouri Public Service Commission

December 1, 2009

Jeff Kasten 5 Star Homes and Development Company, Inc. 69 Schaper Road Foristell, MO 63348

RE: Grady, Jeff and Ann

Dear Mr. Kasten:

As an authorized inspector for the Manufactured Housing and Modular Units Program, on November 24, 2009, I conducted an inspection of a Contempri Industries modular unit (serial number 2853) purchased from your dealership by Jeff and Ann Grady. A copy of the inspection report is enclosed.

Pursuant to Section 700.100.3(6) of the Missouri Statutes, modular unit dealers are responsible to arrange for the proper initial setup of any manufactured home or modular unit purchased from their dealership, unless the dealer receives a written waiver of that service from the purchaser or his authorized agent.

The inspection conducted by this Department indicated that the referenced modular unit is not properly setup. Please refer to the inspection report for specific details. According to Section 700.045(5) of the Missouri Statutes, you are required to correct the noted setup deficiencies within 20 days from receipt of this notification. In addition, please submit a work order signed by the homeowner verifying that the setup deficiencies have been corrected.

Please note that failure to correct these items within the specified time period could result in a formal complaint being brought before the Public Service Commission for enforcement measures.

Thank you for your prompt attention to this matter. Should you have any questions, please feel free to contact me at 573-881-6813

Sincerely

Im

Tim Haden Manufactured Housing Inspector Manufactured Housing and Modular Units Program Cell: 573-881-6813 Office: 573-526-2833 Fax: 573-522-2509

File

C

Effective January 31, 2005 a \$200 re-inspection fee will be charged to each dealer, manufacturer or. both for re-inspections, if corrections have not been completed by the dealer or manufacturer within 60 days of receipt of the original written complaint from the consumer as filed with the Missouri Public Service Commission. Fee applies to manufactured (HUD) homes and modulat units.

Informed Consumers; Quality Utility Services, and a Dedicated Organization for Missourians in the 21st Century

WESS A. HENDERSON Executive Director-

DANA K. JOYCE Director, Administration and Regulatory Policy

ROBERT SCHALLENBERG Director, Utility Services

NATELLE DIETRICH **Director**, Utility Operations

VACANT Secretary/Chief Regulatory Law Judge

KEVIN A. THOMPSON General Counsel

EXHIBIT 2 SCHEDULE 1



Inspection Report

Send Work Order to: Manufactured Housing & Modular Units Program P.O. Box 360 Jefferson City, MO 65102 Phone: 1-800-819-3180 or Fax to 573-522-2509

Consumer Information JEFF & ANN GRADY 1817 MORVEN OVERLAND, MO 63114 Home Phone: (314) 427-7350 Work Phone: (314) 537-5639

Dealer-MD 5 STAR HOMES & DEV. CO, INC. 69 SCHAPER RD. 1 FORISTELL, MO 63348 Phone: (636) 463-2262

MFG-MD CONTEMPRI INDUSTRIES, INC 1000 WEST WATER ST **PINCKNEYVILLE, IL 62274** Phone: (618) 357-5361

Home Information

Date of Manufacture: 09/04/2009 Model: 2853 Gradycone State Seal: 032598 Serial Number: 2853 Size: 32 x 46 Installation Date: 11/16/2009 Inspection Date: 11/24/2009 Inspector Name: Tim Haden

Responsibilities

Manufacturer to correct items: 1 Dealer to correct items: 2-5

Note: At the time of this inspection the installation of this modular unit was incomplete. Additional inspections will be conducted.

Basement	Poured/Block Foundation	Footings	Runners	🖸 Base Pad	Slab
----------	-------------------------	-----------------	---------	------------	------

Pursuant to section R-104.1 of the IRC, these items are not in compliance.

SUMMARY OF MANUFACTURER DEFECTS:

1) The section of roof built on site to tie the roof sections together is not properly constructed according to the manufactures set up and erection manual and R802, 2006 IRC. Also, there is insufficient construction information provided in the manufactures approved design for the construction of this roof section, finishing the interior walls and insulation. The finished construction of this roof section and interior walls will require on-site inspection and approval by the manufactures approved third party inspection agency.

Dealer to correct the following set up deficiencies within 20 days.

SUMMARY OF DEALER ITEMS:

2) The Wood foundation wall is not properly constructed.

a) The sheathing is not fastened to the studs properly. The sheathing is required to be fastened to studs using 6d nails spaced at 6" on the edges and 12" at intermediate supports.

b) There is no header installed in the wood foundation wall in the bump-out for the fireplace.

c) The sheathing does not cover the window headers.

d) The corners of the wood foundation wall are not fastened together properly. The corner studs are required to be fastened together using 16d nails spaced at 12".

e) The bottom plate of the wall is not bolted to the foundation.

See manufactures set up and erection manual, manufactures approved foundation plan and R602 2006 IRC.

3) The support columns are not fastened in place to prevent lateral displacement as required. R407.3 2006 IRC.

4) There are electric NM cables installed at angles and attached directly to the bottom of the floor joists in the basement. These NM electric cables are required to be run through bored holes in the floor joists or on running boards. E3702.4 2006 IRC.

5) The front half of the home is installed over an unconditioned crawl space. The floor over the crawl space is required to be insulated according to N1102 and table N1102.1 2006 IRC. Also, the basement foundation wood wall and rim joist is required to be insulated and the area conditioned, or the floor over the basement area will require insulation according to N1102 and table N1102.1 2006 IRC.

EXHIBIT 3



Commissioners ROBERT M. CLAYTON III Chairman

CONNIE MURRAY

JEFF DAVIS TERRY M. JARRETT

KEVIN GUNN

POST OFFICE BOX 360 JEFFERSON CITY MISSOURI 65102 573-751-3234 573-751-1847 (Fax Number) http://www.psc.nio.gov

Missouri Public Service Commission

January 8, 2010

Jeff Kasten 5 Star Homes and Development Company, Inc. 69 Schaper Road Foristell, MO 63348

RE: Grady, Jeff and Ann

Dear Mr. Kasten:

On December 1, 2009, you were furnished with a notice of inspection of the Contempri Industries modular home (serial number 2853) owned by Jeff and Ann Grady and directed to correct specified deficiencies in the setup of the manufactured home. I have conducted a re-inspection and found that the deficiencies listed in the inspection report dated November 24, 2009, have not been corrected.

Unless the deficiencies noted in the previous letter are corrected within ten (10) days from the receipt of this letter, and a work order signed by the homeowner indicating that the deficiencies have been corrected is received, this complaint file may be forwarded to the Public Service Commission General Counsel for the preparation of a formal complaint. In the event a complaint is filed, requested remedies may include revocation, suspension, or probation of your dealer's registration, pursuant to Section 700.100.3(6)RSMo, and/or monetary penalties.

If there is any reason that you cannot comply within the 10-day period, you should contact me immediately at 573-526-2833.

Respectfully,

Clack

Tim Haden Manufactured Housing inspector Manufactured Housing and Modular Units Program Office: 573-526-2833 Cell: 573-881-6813 Fax: 573-522-2509

> File General Counsel

> > Informed Consumers, Quality Utility Services, and a Dedicated Organization for Missourians in the 21st Century

WESS A. HENDERSON Executive Director

DANA K. JOYCE Director, Administration and Regulatory Policy

ROBERT SCHALLENBERG Director, Utility Services

NATELLE DIETRICH Director, Utility Operations

VACANT Socretary/Chief Regulatory Law Judgo KEVIN A. THOMPSON

General Counsel

EXHIBIT 3 SCHEDULE 1



Inspection Report

Consumer Information JEFF & ANN GRADY 1817 MORVEN OVERLAND, MO 63114 Home Phone: (314) 427-7350 Work Phone: (314) 537-5639

Dealer-MD

5 STAR HOMES & DEV. CO, INC. 69 SCHAPER RD. FORISTELL, MO 63348 Phone: (636) 463-2262

MFG-MD

CONTEMPRI INDUSTRIES, INC 1000 WEST WATER ST PINCKNEYVILLE, IL 62274 Phone: (618) 357-5361

Send Work Order to: Manufactured Housing & Modular Units Program P.O. Box 360 Jefferson City, MO 65102 Phone: 1-800-819-3180 or Fax to 573-522-2509

Home Information Date of Manufacture: 09/04/2009 Model: 2853 Gradycone State Seal: 032598 Serial Number: 2853 Size: 32 x 46 Installation Date: 11/16/2009 Inspection Date: 11/24/2009 Inspector Name: Tim Haden

Responsibilities Manufacturer to correct items: 1 Dealer to correct items: 2-5

Note: At the time of this inspection the installation of this modular unit was incomplete. Additional inspections will be conducted.

Basement Poured/Block Foundation Footings Runners Base Pad Slab

Pursuant to section R-104.1 of the IRC, these items are not in compliance.

SUMMARY OF MANUFACTURER DEFECTS:

1) The section of roof built on site to tie the roof sections together is not properly constructed according to the manufactures set up and erection manual and R802, 2006 IRC. Also, there is insufficient construction information provided in the manufactures approved design for the construction of this roof section, finishing the interior walls and insulation. The finished construction of this roof section and interior walls will require on-site inspection and approval by the manufactures approved third party inspection agency. Re-inspected 1/5/10, incomplete.

Dealer to correct the following set up deficiencies within 20 days.

SUMMARY OF DEALER ITEMS:

2) The Wood foundation wall is not properly constructed.

a) The sheathing is not fastened to the studs properly. The sheathing is required to be fastened to studs using 6d nails spaced at 6" on the edges and 12" at intermediate supports. Re-inspected 1/5/10, corrected.

b) There is no header installed in the wood foundation wall in the bump-out for the fireplace. Re-inspected 1/5/10, incomplete

c) The sheathing does not cover the window headers. Re-inspected 1/5/10, corrected

d) The corners of the wood foundation wall are not fastened together properly. The corner studs are required to be fastened together using 16d nails spaced at 12". Re-inspected 1/5/10, corrected.

c) The bottom plate of the wall is not bolted to the foundation. Re-inspected 1/5/10, incomplete.

See manufactures set up and erection manual, manufactures approved foundation plan and R602 2006 IRC.

3) The support columns are not fastened in place to prevent lateral displacement as required. R407.3 2006 IRC. Reinspected 1/5/10, incomplete.

4) There are electric NM cables installed at angles and attached directly to the bottom of the floor joists in the basement. These NM electric cables are required to be run through bored holes in the floor joists or on running boards. E3702.4 2006 IRC. Re-inspected 1/5/10, incomplete.

5) The front half of the home is installed over an unconditioned crawl space. The floor over the crawl space is required to be insulated according to N1102 and table N1102.1 2006 IRC. Also, the basement foundation wood wall and rim joist is required to be insulated and the area conditioned, or the floor over the basement area will require insulation according to N1102 and table N1102.1 2006 IRC. Re-inspected 1/5/10, incomplete.





Commissioners

÷2.

ROBERT M. CLAYTON III Chairman

JEFF DAVIS

TERRY M. JARRETT

KEVIN GUNN

ROBERT S. KENNEY

POST OFFICE BOX 360 JEFFERSON CITY MISSOURI 65102 573-751-3234 573-751-1847 (Fax Number) http://www.psc.mo.goy

Missouri Public Service Commission

March 11, 2010

Jeff Kasten 5 Star Homes and Development Company, Inc. 69 Schaper Road Foristell, MO 63348

RE: Final Notice

Dear Mr. Kasten:

This letter is our final notice to you regarding your company's repeated failure to repair the Grady home and to deliver three new homes sold by your dealership.

Please be warned that any further delay on your part to take the corrective actions required of your dealership, under Missouri statute and Commission rule, will result in our taking legal action against your company.

Our records indicate that 5 Star Homes and Development Co., Inc. (5 Star) has four outstanding consumer complaints with our office; one complaint is for a home sold and set up by 5 Star in which our Field Inspector, Tim Haden, identified various installation deficiencies which have not been corrected, and three complaints are for homes sold by 5 Star in which the buyers made a down payment as required, however, 5 Star has repeatedly failed to make delivery to the buyers.

Regarding the Jeff and Ann Grady home located at 25453 Maywood Road, in Versailles, Missouri, 5 Star has repeatedly failed to correct the deficiencies noted by our Field Inspector, Tim Haden, which he communicated to you by a letter dated December 1, 2009, along with a copy of the original inspection report dated November 24, 2009. This first letter gave 5 Star 20 days to make the necessary repairs. 5 Star failed to make the repairs.

We sent 5 Star a second letter and second inspection report of the Grady home dated January 8, 2010, allowing another 10 days to make the required repairs. To date, we have not received any repair or work orders from 5 Star indicating the completion of the required repairs. Failure to correct these deficiencies violates Section 700.100 RSMo.

Informed Consumers, Quality Utility Services, and a Dedicated Organization for Missourians in the 21st Century

WESS A, HENDERSON Executive Director

EXHIBIT 4

DANA K. JOYCE Director, Administration and Regulatory Policy

ROBERT SCHALLENBERG Director, Utility Services

NATELLE DIETRICH Director, Utility Operations

STEVEN C. REED Secretary/General Counsel

KEVIN A. THOMPSON Chief Staff Counsel Jeff Kasten 5 Star Homes and Development Company, Inc. March 11, 2010 Page 2

Furthermore, Section 700.045 (5) states it shall be a misdemeanor to fail to correct a code violation in a modular unit within a reasonable time not to exceed 90 days after being ordered to do so in writing by an authorized representative of the Commission.

In addition, we have not received any information from 5 Star regarding the homes sold and not delivered to their buyers; Timothy Gordon of 2842 Foxwood Drive, Maryland Heights, Missouri, and Kenneth White of 175 Criderville, O'Fallon, Missouri, and Michelle & Hans Mugler of 131 College Avenue, Kirkwood, Missouri.

A letter dated November 3, 2009, along with a copy of each buyer's complaint against your company was mailed to 5 Star requiring the delivery of the homes to each buyer. However, as of this date, the homes still have not been delivered to the buyers. (Copies are attached).

Taking money from buyers and not delivering and setting up the new homes are violations of Section 700.100.3 (4) and (6) and the Missouri Merchandising Practices Act Section 407.020.

If the corrections to the Grady home are not made, and the Gordon, White and Mugler homes are not delivered within 10 days from the date of this third and final letter to you on this matter, a formal complaint will be filed against 5 Star seeking the revocation of the dealer registration and permission to seek penalties against 5 Star in Circuit Court.

Should you have any questions, you may contact me at 1-800-819-3180.

Sincerely,

for Pleus

Ron Pleus Program Director Manufactured Housing & Modular Units Program

RP/slr

cc: R.S. Berlin, Senior Staff Counsel

Enclosures

Certified Mail No: #7008 2810 0001 2932 7891

EXHIBIT 4 SCHEDULE 1



Inspection Report

Send Work Order to: Manufactured Housing & Modular Units Program P.O. Box 360 Jefferson City, MO 65102 Phone: 1-800-819-3180 or Fax to 573-522-2509

Consumer Information

JEFF & ANN GRADY 1817 MORVEN OVERLAND, MO 63114 Home Phone: (314) 427-7350 Work Phone: (314) 537-5639

Dealer-MD

5 STAR HOMES & DEV. CO, INC. 69 SCHAPER RD. FORISTELL, MO 63348 Phone: (636) 463-2262 **Home Information**

Date of Manufacture: 09/04/2009 Model: 2853 Gradycone State Seal: 032598 Serial Number: 2853 Size: 32 x 46 Installation Date: 11/16/2009 Inspection Date: 11/24/2009 Inspector Name: Tim Haden

Responsibilities

Manufacturer to correct items: 1 Dealer to correct items: 2-5

MFG-MD

CONTEMPRI INDUSTRIES, INC 1000 WEST WATER ST PINCKNEY VILLE, IL 62274 Phone: (618) 357-5361

Basement Poured/Block Foundation Footings Runners Base Pad Slab

Pursuant to section R-104.1 of the IRC, these items are not in compliance.

SUMMARY OF MANUFACTURER DEFECTS:

1) The section of roof built on site to tie the roof sections together is not properly constructed according to the manufactures set up and erection manual and R802, 2006 IRC. Also, there is insufficient construction information provided in the manufactures approved design for the construction of this roof section, finishing the interior walls and insulation. The finished construction of this roof section and approval by the manufactures approved third party inspection agency. Reinspected 1/5/10, incomplete. Re-inspected 3/19/10, Manufactured completed the onsite construction of the roof sections. The manufacture also submitted approved drawings for this onsite construction. Third party inspection waived.

Dealer to correct the following set up deficiencies within 20 days.

SUMMARY OF DEALER ITEMS:

2) The Wood foundation wall is not properly constructed. Re-inspected 3/19/10, completed by manufacture.

a) The sheathing is not fastened to the studs properly. The sheathing is required to be fastened to studs using 6d nails spaced at 6" on the edges and 12" at intermediate supports. Re-inspected 1/5/10, corrected by manufacture.

b) There is no header installed in the wood foundation wall in the bump-out for the fireplace. Re-inspected 1/5/10, incomplete. Re-inspected 3/19/10, incomplete.

c) The sheathing does not cover the window headers. Re-inspected 1/5/10, corrected by manufacture.

d) The corners of the wood foundation wall are not fastened together properly. The corner studs are required to be fastened together using 16d nails spaced at 12". Re-inspected 1/5/10, corrected by manufacture.

e) The bottom plate of the wall is not bolted to the foundation. See manufactures set up and erection manual, manufactures approved foundation plan and R602 2006 IRC. Re-inspected 1/5/10, incomplete. Re-inspected 3/19/10, corrected by homeowner.

3) The support columns are not fastened in place to prevent lateral displacement as required. R407.3 2006 IRC. Re-inspected 1/5/10, incomplete. Re-inspected 3/19/10, corrected by homeowner.

4) There are electric NM cables installed at angles and attached directly to the bottom of the floor joists in the basement. These NM electric cables are required to be run through bored holes in the floor joists or on running boards. E3702.4 2006 IRC. Re-inspected 1/5/10, incomplete. Re-inspected 3/19/10, incomplete.

5) The front half of the home is installed over an unconditioned crawl space. The floor over the crawl space is required to be insulated according to N1102 and table N1102.1 2006 IRC. Also, the basement foundation wood wall and rim joist is required to be insulated and the area conditioned, or the floor over the basement area will require insulation according to N1102 and table N1102.1 2006 IRC. Re-inspected 1/5/10, incomplete. Re-inspected 3/19/10, corrected by homeowner.

Commissioner ROBERT M CLAYTON III Chairman JEFF DAVIS TERRY M. JARRETT KEVIN GUNN **ROBERT S. KENNÉY**



Missouri Public Service Commission

POST OFFICE BOX 360 **JEFFERSON CITY MISSOURI 65102** 573-751-3234 573-751-1847 (Fax Number) http://www.psc.mo.gov

EXHIBIT 5

WESS A. HENDERSON **Executive Director** DANA K. JOYCE Director, Administration and Regulatory Policy ROBERT SHALLENBERG **Director**, Utility Services NATELLE DIETRICH Director, Utility Operations STEVEN C. REED Secretary/General Counsel KEVIN A. THOMPSON Chief Staff Counsel

November 03, 2009

5 STAR HOMES & DEV. CO, INC. **69 SCHAPER RD** FORISTELL, MO 63348

RE: GORDON, TIMOTHY J & DONNA M

Dear Sir or Madam:

This is to inform you that the Department of Manufactured Housing and Modular Units has received a consumer complaint involving a manufactured home purchased from your dealership. The consumer's complaint form is enclosed.

Pursuant to Section 700.100.3(6) RSMo 1994, manufactured home dealers are responsible to arrange for the proper initial setup of any manufactured home or modular unit purchased from their dealership, unless the dealer receives a written waiver of that service from the purchaser or his authorized agent.

Please investigate this complaint and refer to any items on the complaint form that may indicate setup problems. You are required to correct any noted setup deficiencies you are responsible for and mail or fax the enclosed work order to this office within 20 days from receipt of this notification. The work order must be signed by the homeowner, and must list any setup deficiencies that have been corrected.

A Manufactured Housing Inspector will contact this homeowner after 20 days to see if their complaint has been resolved. If necessary, the Inspector will schedule a complete inspection of the home, including setup.

Please note that failure to correct setup deficiencies could result in a formal complaint being brought before the Public Service Commission for enforcement measures.

Thank you for your prompt attention to this matter. Should you have any questions, do not hesitate to contact the Manufactured Housing & Modular Unit Program at 800-819-3180.

Sincerely,

Ron Pleus, Director Manufactured Housing & Modular Units Program

Enclosure

SCHEDULE 1 Missouri Public Service Commission Manufactured Housing & Modular Unit Program Inspection Request/Consumer Complaint Form

Manager Phase Phas	09-000158
Please print legibly or type.	OFFICE USE ONLY
CONSUMER INFORMATION (REQUIRED)	
Name TIMOTHY J. + DONNA M. GORDON	File Name GORDON TIMOTHY & DONNAL Inspector Received by: BB
Address 2842 FOXWOOD DR.	THEFINERS
City/State/Zip MARYLAND HEIGHTS, MISSOURI 63043	Date of Inquiry: Date of Receipt: 11/3/09 HOME INFORMATION (REQUIRED)
County ST. LOUIS	
Work Phone N/A (RETIRED)	Set Up cruckasement Foundation Piers
Home Phone 314 - 298-9629	
Other Phone 314 - 737 - 8312	Serial Number (REQUIRED) N/A (NOT MADE YET)
MANUFACTURER INFORMATION (REQUIRED)	HUD Label Number
Name CONTEMPEL HOMES INDUSTRIES, INC.	Model NEW HAVEN II (RANCH)
Address 1000 WEST WATER STREET	Date of Manufacture: N/A Date of Delivery: N/A
City/State/Zip PINCKNEYVILLE, 114. 62274	Has the home been moved from original location? Yes No
DEALER INFORMATION (REQUIRED)	Are you the first owner of the home? Yes No
Name 5STAR HOME & DEVELOPMENT CO. INC.	INSTALLER INFORMATION (IF KNOWN)
Address 69 SCHAPER RD	Name:
City/State/Zip FORISTELL, MISSOURI 63348	Decal #:
REASON FOR REQUEST INCO	UIRED)
List each concern separately. Do not write conce	
1. DEALER HAS \$58,00 OF OUR MONEY (MINUS \$12,500 HES	GENT TO FACTORY
2. FACTORY SAYS \$12,500 IS NOT ONDUCH TO START CONS	TRUCTION (SO, HOME CONST. HAD NOL MILLING)
3. DEALER VERBALLY PROMISED OUR HOME 100% COMP	LOTP BY SET IDINELT 201
A. DEALOR PROMISED A # 5,995.00 VIILITY VEHICLE INCLA	THUE TO STOR OF HOM COULD AT THE
5. DEALER WOAKT ANSWER OFFICE OR HIS CELL PHONE	MERCALIS
C. DESALER WONT RETURN CALLS WHEN WE LEAVE	
^{7.} WE CAN'T SPLL OUR CURRENT HOME ^{8.} WE CAN'T PROCEED ANY FURTHER WITH OUR NEW F	HOMESTIC IT , NO WELL SEATIC, DEINGULATS ETC.)
" WE CAN'T PROCEED AND PUR TIFCIC WITH WAR TOWN (" OUR WALK-DUT BASCOLUT (COMPLETED EARLY AUGUST)	IS REING WEATHERED UNNECESSARILY
10. WIG ARE MAKING INTORUST PAYMENTS ON OUR CON	STRUCTION HOAN, WITH NO CONSTRUCTION
11. OUR CONSTRUCTION LOAN WITH HANNIOR NATL BAL	
$\frac{12}{12}$	YECEIVE
13.	<u> </u>
14.	NOV 0 3 2009
15.	MANUFACTURED HOUSIN
Attach additional sheets if ne	DEPARTMENT
Signature of Consumer (REQUIRED) A. thy A. Mordon	Date 30 October, 2009
This form must be completed in full and submitted with a copy of the Bill of Sale	or Purchase Agreement, (REQUIRED) PHONE: 800-819-3180
RETURN TO: Manufactured Housing & Modular Unit Program P.O. Box 360, Jefferson City, MO 65102	FAX: 573-522-2509

EXHIBIT 5



Missouri Public Service Commission Manufactured Housing & Modular Unit Program Inspection Request/Consumer Complaint Form

Please print legibly or type.	09-000157				
CONSUMERINEORMATION REQUIRED	OFFICE USE ONLY				
Name KENNET W. White	File Name White, Kennoth W				
Address 175 Criderville Dr.	Inspector freeman Received by: BB				
City/State/Zip O'Fallow, MO 63366	Date of Inquiry: $10/21/09$ Date of Receipt: $11/2/09$				
County St. Charles: MO	HOMEINEORMATION (REQUIRED)				
Work Phone 636 262-4660	New or Used Single or Multi-Section				
Home Phone (' , c	Set Up Basement Foundation Piers				
Other Phone (, 1/	Serial Number (<u>REQUIRED</u>)				
MANURACIORER INEORMATION REQUIRED	HUD Label Number				
Name 5 StAR Home and Deve popment Company, Inc.	Model				
Mulliss 69 Schaper Rd. No offer Manufacturer	Date of Manufacture: Date of Delivery:				
City Clarenzip FORISTAL, MO 63348 INTO	Has the home been moved from original location? Yes No				
DEAVERNNFORMATIONN(REQUIRED)X	Are you the first owner of the home? Yes No				
Name 5 Star Home and Development Company Inc.	INSTALLER INFORMATION (IF KNOWN)				
Address 69 Schaper Ril.	Name:				
City/State/Zip Forestell, MO 63348	Decal #:				
REASONE OR REQUEST (REOL List each concern separately. Do not write concern					
 Contract over 1/1 off-g all I have is a hole in the ground promised by word 15. Tried to Fine builded but connect retreive building deposit 37,250.00 Hove another builded but connect afford house without deposit Legan was available since April 14th 2009 broke ground 9-7-09 suppose to street June 15 Six nowthen with par and have to redue hole in ground not deep enough Have been hied to so much I don't trust them to complete job. Have been hied to so much I don't trust them to complete job. Have been paying 250 month in interest For six months for northing Contempri to mes was suppose to be many foctares - No contracts to my knowledge 					
13.	NOV 0 2 2009				
14. 4F					
15.	MANUFACTURED HOUSING				
Attach additional sheets if neces					
Andrew (REQUIRED) Ken White	10/28/09				
	Purchase Agreement. (REQUIRED) PHONE: 800-819-3180 PAX: 573-522-2509				

p.1

EXHIBIT 5 SCHEDULE 3



Missouri Public Service Commission SCHEDULE 3 Manufactured Housing & Modular Unit Program Inspection Request/Consumer Complaint Form

Please print legibly or type.	10-000014
CONSUMER INFORMATION (REQUIRED)	OFFICE USE ONLY
Name MICHELLE + HANS MUGLER	File Name MUSICR, MICHELLE & HANS
Address 131 College AVE	Inspector HADEN Received by: BB
city/state/Zip KIRKWOOD, MO 63122	Date of Inquiry: Date of Receipt: 2-11/10
County St. LOULS	HOME INFORMATION (REQUIRED)
Work Phone 314 984-8312	New or Used Single or Multi-Section
Home Phone 314 909 - 0777	Set Up Basement Foundation Piers
Other Phone 314 304.7854	Serial Number (<u>REQUIRED</u>)
MANUFACTURER INFORMATION (REQUIRED)	HUD Label Number
Name Contempri Homes	Model
Address 1000 West Water	Date of Manufacture: Date of Delivery:
City/state/Zip PINCKNEYVILLE, JL 62274	Has the home been moved from original location? [] Yes [] No
DEALER INFORMATION (REQUIRED)	Are you the first owner of the home? Yes No
Name FIVE Star HOMES	INSTALLER INFORMATION (IF KNOWN)
Address 69 Schaper Rd	Name:
City/State/Zip FOR/Stell, MO 63348	Decal#
REASON FOR REQUEST (REQ)	
List each concern separately. Do not write concern ¹ Contract W/ Five Star Homes dated May 31, 2	2008 Still don't have home
² Site not ready for home to be installed	d; things 5 Stan needs to do
3 Backfill yard	A) MILLINGS O CHALLING IC CO
1. POUR basement Floor + Garage Floor.	
5. Build Garage and KOOF It	
6. Build Porch and ROOF it	
" Build Laindry Room	· · · ·
· Set the home + install the home -	
 Install SILL plate + Beams 10. Basement strikes 	PECEIVEN
DUDDITION STALKS	
12. POUR driveway + sidewarks	FEB 0 1 2010
13.	MANUFACTURED HOUSING DEPARTMENT
14.	DEPARTMENT
15.	· · · · · · · · · · · · · · · · · · ·
Attach additional sheets if nece	ossary.
Signature of Consumer (REQUIRED) MUCHULL MUGLER	Date 2.1.2010
This form must be completed in full and submitted with a copy of the Bill of Sale or	
RETURN TO: Manufactured Housing & Modular Unit Program P.O. Box 360, Jefferson City, MO 65102	PHONE: 800-819-3180 FAX: 573-522-2509

Invoice Number: 3006

EXHIBIT 6

WESS A. HENDERSON Executive Director DANA K. JOYCE Director, Administration and Regulatory Policy ROBERT SHALLENBERG Director, Utility Services NATELLE DIETRICH Director, Utility Operations STEVEN C. REED Secretary/General Counsel KEVIN A. THOMPSON Chief Staff Counsel



Missouri Public Service Commission

POST OFFICE BOX 360 JEFFERSON CITY MISSOURI 65102 573-751-3234 573-751-1847 (Fax Number) http://www.psc.mo.gov

INVOICE

January 11, 2010

Commissioners -

ROBERT M CLAYTON III

JEFF DAVIS

TERRY M. JARRETT

KEVIN GUNN

ROBERT S. KENNEY

Chairman

5 STAR HOMES & DEV. CO, INC. 69 SCHAPER RD. FORISTELL, MO 63348 Registration #: 1232701

Date of Inspection: 11/24/2009

Date of Reinspection: 01/05/2010

Invoice Amount: \$200.00

Payment Due Date: 01/25/2010

Consumers Information: GRADY, JEFF & ANN Registration #: 09-000151

Please detach bottom portion of invoice and return with payment by due date to the Missouri Public Service Commission, Manufactured Housing & Modular Unit Program, P.O. Box 360, Jefferson City, MO 65102. Check to be made payable to the Missouri Director of Revenue.

Transmittal Number (PSC OFFICE)	Check Number	Check Amount	
· · · · · · · · · · · · · · · · · · ·			

Invoice Number: 3006

Dealer Information: 5 STAR HOMES & DEV. CO, INC. 69 SCHAPER RD. FORISTELL, MO 63348 Registration #: 1232701

Payment Due Date: 01/25/2010

Payment Amount:

File #: 1232701

Consumer's Information: GRADY, JEFF & ANN

Registration #: 09-000151

Date of Inspection: 11/24/2009

Date of Reinspection: 01/05/2010