From: Rob [energyhealingarts@gmail.com]
Sent: Friday, February 06, 2009 10:38 AM

To: Baker, Jack; Janson Thomas; Happy, Kim*; Attorneydavek@cs.com

Subject: 11334 Larimore

Attachments: IMG_4792.JPG; IMG_4793.JPG; IMG_4794.JPG; IMG_4795.JPG; IMG_4796.JPG;

IMG_4797.JPG

Jack Hi,

I took these pictures when the weather had been in the teens for a few days. This strip with no snow was not even frozen it was soft and watery when I walked on it and my shoes sank several inches into the soft mud. I noticed that it seems to point right to the corner of the neighboring house where the gas meeter goes in to the basement. I bet the service line for this neighboring property runs under the driveway at 11334 Larimore and enters the basement next to the gas line. Got any thoughts?

Have you heard anything from MAW about this 11334 Larimore leak. Did the test results come back from the MAW lab?

Did the results of the sample that MAW took from the 11334 Larimore match the positive for chlorine results of your mobile test?

What is MAW saying about the water running out of the ground.

Rob

Kim Please add to Case # WC-2009-0277