

---

**From:** Rob [energyhealingarts@gmail.com]  
**Sent:** Wednesday, February 11, 2009 12:02 AM  
**To:** Busch, Jim; Happy, Kim\*  
**Cc:** Janson Thomas; Baker, Jack  
**Subject:** Re: 11334 Larimore Leak

Jim,

On 2/6/09 I sent this email again asking for help. It has been raining heavily and my basement is full of water and the sump pump has been cycling often. Have you heard anything from MAW on if the service lines to these 2 properties on Larimore are leaking or not?  
Please let me know

Thanks Rob

Kim Please add this communication to Case # WC-2009-0277

Rob wrote:

Jim,

Here are more pictures of the 11334 Larimore leak. It is hard to see in the pictures but there was ice between the meeter and the house. If I stood on the meeter and looked at the house there was ice in several places that appeared to be on top of the service line.

The house address next to the 11334 Larimore is 11330. Maybe you could ask MAW to test the service lines to both of these addresses?

Thanks Rob

Kim Please add to Case # WC-2009-0277

---



---



---



---





---

