

**FILE COPY**

March 31, 2004

Meredith Perkins  
535 North New Ballas Road  
St.Louis, MO 63141  
314-996-2352

Re: Pump failure at Well for Incline Village

Meredith,

On March 30, 2004 at 4:40 I received a call from Dan Daugherty 314-416-2960 from DNR requesting me to call Dan with Flynn Well drilling because Flynn Well Drilling was called out to Incline Village for some pump problems.

Called Dan with Flynn Well Drilling 636-441-1400 he told me they looked at the pump and thought pump would not last to the weekend. Asked what would it take to get pump back into service, he said it would take approximately one day to pull pump & reinstall.

Parts should all be available in St. Louis and he would be willing to pull the pump out and help in any way he could, but he does not want to work for Gary Smith. Gary still has not paid Flynn Well Drilling for the work they did installing the new pump in February of 2003 for approximately \$9700.00 plus interest total \$12,000.00. (Said he would pull pump, but not install it until the money issue was resolved).

He also mentioned he told Gary Smith last year the starter would have to be replaced at approximately \$1,000.00, if starter was not replaced pump would not turn on /off efficiently and this would cause pump problems in the future.

Dan Daugherty 314-416-2960 from DNR said he was going to notify the PSC on this issue.

If you need anything else give me a call.

Bill Chandler  
Operations Superintendent St. Charles  
636-922-6164 ex.7