

06/18/2007

08:17:18 *****

Platte-Clay Electric Co-op Inc
EGS-SERV. UPGRADE, OH TO UG, REROUTE LINE

SO: 410890

Requested for: 06/18/2007
Entered by: STEVEJ4

sort of
✓

2036 - 2036
2-0003
10123 COUNTY RD N
EXCELSIOR SPRINGS MO 64024
J FERRIL SOLD CLAY CO TRAILER

District: SJ
Route Seq: 14/0
Area:

Block Lot

Transformer No: 15477
Size: 5

per HB - need to upgrade old 60amp service to install PMI
Let Harold know when complete.

67849-001
ROOF, GARY
PO BOX 153
EXCELSIOR SPRINGS MO
64024

H: 816 630-2201
W: 816 564-1263

Lights

Active Inactive
1 0

***** Meter Information *****

	Meter	Meter	
	Company No.	Mfg No.	
Electric	10560006	15855068	Reading: _____

***** Return Information *****

Return S/O -Yes

Work completed by: #52 Date: 7/2/7

Serviceman comments: Completed
Found blink problem probably doesn't
need PMI. Bad. Connection in
Mtn Base.

