
Karen Smith 8930 Harrison – Curb Damage

Damage to Curbs - #1:




Damage to Curbs - #2







Damage to Curbs - #3



Damage to Curbs - #4




Damage to Curbs - #5




Karen Smith 8930 Harrison – Drive Damage


Driveway prior to water company work:








Drive - Pre work #3



Drive - Pre work #4



Damage to Driveway post, water company work:

Damage to driveway apron:




Marks Left on Driveway by current concrete restoration group:




Driveway Patch






Additional damage to drive from concrete workers



Additional damage to drive from concrete workers



Additional damage to drive from concrete workers



Karen Smith 8930 Harrison - Yards


Example of oirt piled in yard. Shows evidence of additional digging up into my yard after gas and water company left following the Feb. 4^{th} event. On Feb 12^{tr} spent $1\,\%$ hours shoveling dirt off of my yard back into the easement/sidewalk area (i.e., I didn't want excess dirt sitting in my yard ontop of grass causing additional damage).



Same area after I cleaned off excess dirt/rocks.



Evidence of additional damage to yard – marks from shovel of back hoe. These marks were not repaired.





Condition of street from Feb. 4° until June 3° when subcontractors completed work.








Yards and Easements At the end of Summer 2013

Yard still torn up:





Grass did not take due to be planted in June in many places..even with watering:



