

FILED

APR 29 2016

BEFORE THE PUBLIC SERVICE COMMISSION
OF THE STATE OF MISSOURI

Missouri Public
Service Commission

In the Matter of the Application of Laclede)
Gas Company to Change its Infrastructure) Case No. GO-2016-0196
System Replacement Surcharge in its)
Laclede Gas Service Territory)

**VERIFIED APPLICATION AND PETITION OF LACLEDE GAS COMPANY
TO CHANGE ITS INFRASTRUCTURE SYSTEM REPLACEMENT
SURCHARGE IN ITS LACLEDE GAS SERVICE TERRITORY
AND REQUEST FOR WAIVER OF COMMISSION RULE 4.020(2)**

COMES NOW Laclede Gas Company ("Laclede" or "Company"), pursuant to Sections 393.1009, 393.1012 and 393.1015 of the Revised Statutes of Missouri (2009), and 4 CSR 240-2.060, 2.080, 3.265 and 4.020(2)(B) of the Rules of the Missouri Public Service Commission ("Commission"), and for its Verified Application and Petition to Change its Infrastructure System Replacement Surcharge in its Laclede Gas Service Territory (its "Application"), respectfully states as follows:

I. THE APPLICATION

1. Sections 393.1009, 393.1012 and 393.1015 of the Revised Statutes of Missouri authorize eligible gas corporations to recover certain infrastructure replacement costs by establishing and updating an infrastructure system replacement surcharge ("ISRS"). Laclede's current ISRS was established effective April 12, 2014 by Commission Order in Case No. GO-2014-0212, covering ISRS costs incurred through February 28, 2014. At the time Laclede's ISRS was established, the Commission approved Laclede's initial notice, annual notice and the surcharge description on Laclede bills, all as required by 4 CSR 240-3.265(8) and (9). No change to these items is requested by Laclede or required by Commission rule as a result of this Application to change the ISRS.

Laclede Exhibit No. 1
Date 4/26 Reporter RB
File No. GO-2016-0196
GO-2016-0197

2. Since Laclede's ISRS was established, it has been changed three times. The most recent change became effective on December 1, 2015, covering ISRS costs incurred through August 31, 2015. Since August 31, the Company has continued to make ISRS-eligible investments. Laclede submits this Application to change its ISRS to reflect these additional investments covering the period from September 1, 2015 through December 31, 2015, with pro-forma ISRS costs updated through February 29, 2016.

A. THE APPLICANT

3. Laclede is a public utility and gas corporation incorporated under the laws of the State of Missouri, with its principal office located at 700 Market Street, St. Louis, Missouri 63101. A Certificate of Good Standing evidencing Laclede's standing to do business in Missouri was submitted in Case No. GF-2013-0085 and is incorporated by reference herein for all purposes. The information in such Certificate is current and correct.

4. In its Laclede Gas service territory, Laclede is engaged in the business of distributing and transporting natural gas to customers in the City of St. Louis and the Counties of St. Louis, St. Charles, Crawford, Jefferson, Franklin, Iron, St. Genevieve, St. Francois, Madison, and Butler in Eastern Missouri, as a gas corporation subject to the jurisdiction of the Commission.

5. Communications in regard to this Application should be sent to Laclede Gas Company at the addresses listed below.

Rick Zucker
Associate General Counsel
700 Market Street, 6th Floor
St. Louis, MO 63101
(314) 342-0533

07/11/15
07/11/15
07/11/15

Glenn W. Buck
Director, Regulatory and Finance
700 Market Street, 5th Floor
St. Louis, MO 63101
(314) 342-0767

6. Other than cases that have been docketed at the Commission, Laclede has no pending actions or final unsatisfied judgments or decisions against it from any state or federal agency or court which involve customer service or rates within three years of the date of this application.

7. Laclede is current on its annual report and assessment fee obligations to the Commission; no such report or assessment fee is overdue.

B. THE ISRS REQUEST

8. With this Application, Laclede requests an adjustment to its ISRS rate schedule to reflect investments made in connection with ISRS-eligible infrastructure system replacements during the period September 1, 2015 through December 31, 2015. Consistent with the methodology used in several of Laclede's previous ISRS cases, and specifically approved by the Commission in its November 12, 2015 Report and Order in Case No. 2015-0341, this Application also includes pro forma ISRS costs updated through February 29, 2016.

9. In addition, as part of a compromise entered into several years ago regarding an ISRS issue, this Application reflects a reduction in Laclede's ISRS request in exchange for the parties' commitment to implement the Company's ISRS applications "as soon as reasonably possible..." The Application also reflects Laclede's request for the full amount of its ISRS in the event that one or more parties fail to meet this commitment.

10. In accordance with the provisions of Sections 393.1009-1015 and 4 CSR 240-3.265, the revised ISRS rate schedule reflects the appropriate pre-tax ISRS revenues necessary to produce net operating income equal to Laclede's weighted cost of capital multiplied by the net original cost of the requested infrastructure replacements during this period that are eligible for inclusion in the ISRS, including recognition of accumulated deferred income taxes and accumulated depreciation associated with eligible infrastructure system replacements that are included in Laclede's currently effective ISRS. Laclede also seeks to recover all state, federal and local income or excise taxes applicable to such ISRS income, and to recover all other ISRS costs such as depreciation expense and property taxes due within 12 months of this filing.

C. ELIGIBILITY OF COSTS

11. The infrastructure system replacements for which Laclede seeks ISRS recognition are set forth on Appendix A, which is attached hereto and made a part hereof for all purposes. The infrastructure system replacements listed on Appendix A are eligible gas utility plant projects in that they are either: a) mains, valves, service lines, regulator stations, vaults, and other pipeline system components installed to comply with state or federal safety requirements as replacements for existing facilities that have worn out or are in deteriorated condition; or b) main relining projects, service line insertion projects, joint encapsulation projects, and other similar projects extending the useful life, or enhancing the integrity of pipeline system components undertaken to comply with state or federal safety requirements; or c) unreimbursed infrastructure facility relocations resulting from the construction or improvement of a highway, road, street, public way or other public work required by or on behalf of the United States, the State of Missouri, a

political subdivision of the State of Missouri, or another entity having the power of eminent domain.

12. In addition to meeting the foregoing criteria, the infrastructure system replacements listed on Appendix A are also eligible for ISRS treatment because they: (a) did not increase revenues by directly connecting to new customers; (b) are currently in service and used and useful; (c) were not included in Laclede's rate base in its most recently completed general rate case, or in rates in a previous ISRS case; and (d) replaced and/or extended the useful life of existing infrastructure.

D. RATE SCHEDULES AND SUPPORTING INFORMATION

13. Attached hereto as Appendix B is the rate schedule, with supporting documents, proposed by Laclede in order to revise the ISRS to reflect the additional ISRS eligible investments made by Laclede that were not included in its previous ISRS filings. This proposed rate schedule, on an annualized basis, will produce additional ISRS revenues that do not exceed ten percent of Laclede's base revenue level as approved by the Commission in its most recently completed general rate proceeding.

14. In determining the appropriate pre-tax ISRS revenues, the proposed rate schedule utilizes current local, state and federal income tax rates through a combined income tax rate conversion factor of 1.626737.

15. In determining the appropriate pre-tax ISRS revenues, the proposed rate schedule utilizes the capital structure approved by the Commission in its February 21, 2014 Order Approving Late-Filed Exhibit (the "February 21 Order") in Case No. GR-2013-0171 (the "Rate Case"), and reflects an overall rate of return of 7.1855%.

16. In determining the appropriate pre-tax ISRS revenues, the proposed rate schedule utilizes a weighted average cost of debt of 2.0445%, consistent with the February 21 Order.

17. In determining the appropriate pre-tax ISRS revenues, the proposed rate schedule utilizes a cost of common equity of 9.7%, consistent with the February 21 Order.

18. In determining the appropriate pre-tax ISRS revenues, the proposed rate schedule utilizes a current composite property tax rate of 3.00%.

19. In determining the appropriate pre-tax ISRS revenues, the proposed rate schedule utilizes depreciation rates currently applicable to the eligible infrastructure system replacements, as approved by the Commission for Laclede in the Rate Case.

20. In determining the appropriate monthly ISRS charge, the proposed rate schedule is based on a reasonable estimate of billing units in the period in which the charge will be in effect, derived by dividing the appropriate pre-tax revenues, as calculated above, by the average number of customers in the most recent year ended December 31, 2014, and then further dividing this quotient by twelve. (*See Appendix B, p. 14*). Consistent with the methodology used in previous ISRS filings, the monthly ISRS charge is apportioned between customer classes in proportion to the customer charges applicable to those classes.

E. ADDITIONAL INFORMATION

21. In connection with 4 CSR 240-3.265(22), attached hereto and incorporated herein as Appendix C is a description of the Company's call center instructions

pertaining to the ISRS, along with a description of the ISRS information posted on the Company's website.

22. In its November 12, 2015 Report and Order in Case No. GO-2015-0341, the Commission approved, over OPC's unfounded objection, the Staff and Laclede's longstanding practice pursuant to which Laclede filed pro-forma estimates of ISRS investments for July and August 2015, and updated those estimates with actual costs during the case. Despite the lack of any tenable legal basis to support its position, OPC is now seeking judicial review of the Report and Order. The Commission's decision on this issue was in all respects lawful and reasonable and we are confident that it will be affirmed on appeal. However, because the matter is on appeal, Laclede is providing that actual cost information again, as Appendix D to this Application, as a "provisional," in the event a reviewing court determines otherwise. Laclede wants to be clear that the pending appeal is the sole reason it is attaching a separate appendix with ISRS costs that were already approved by the Commission. But for the existence of an appeal, no such appendix would be added, or will be added in future ISRS cases. Finally, because the July and August ISRS investments are already included in Laclede's current ISRS rates, there is no additional revenue requirement associated with Appendix D.

F. REQUEST FOR WAIVER OF RULE 4.020(2)

23. Commission Rule 4 CSR 240-4.020(2) requires a utility to file a notice with the Commission 60 days before filing a case likely to be a contested case. Section 4.020(2)(B) permits utilities to request a waiver of this requirement for good cause. Having just litigated three issues in its previous ISRS case, Laclede does not believe it is

likely that this case will also be contested. However, out of an abundance of caution, Laclede seeks such a waiver of Rule 4.020.

24. The 60 day period in the ex parte rules serves as a notice and identification to the Commission and other parties of an anticipated contested case, triggering disclosure requirements for extra-record communications. Such 60 day notice is not necessary in this case for two reasons. First, ISRS filings are common cases that are routinely filed by gas and water companies. The subject matter of ISRS cases is always the same, that is, the recovery of costs for ISRS eligible investments, and the filings themselves by the utilities are predictably similar. Laclede itself has regularly filed ISRS applications once or twice per year for more than 10 years, and in general tends to file around the end of January and July. As a result, these cases are already well-anticipated by the parties and the Commission, and a 60 day notice requirement would serve no purpose, because it would not afford meaningful information that is not already well known. Second, because Laclede has participated in no such extra record discussions on this topic, either before or after 60 days prior to filing its Application, there is no need in this matter to determine the start of the anticipated contested case deadline. In addition, no public utility will be affected by this waiver. For these reasons, Laclede requests that the Commission waive the 60 day notice requirement of Rule 4.020.

WHEREFORE, pursuant to Commission Rule 4.020(2)(B), 393.1015.2(3) RSMo and Commission Rule 3.265(12), Laclede Gas Company respectfully requests that the Commission grant Laclede a waiver of Commission Rule 4.020(2), if necessary, issue an order approving the ISRS rate schedule as described herein, and grant such other relief

as may be necessary and appropriate to accomplish the purposes of Sections 393.1009 through 393.1015.

Respectfully submitted,

/s/ Rick E. Zucker

Rick E. Zucker #49211

Associate General Counsel

Laclede Gas Company

720 Olive Street, 14th Floor

St. Louis, MO 63101

(314) 342-0533 (telephone)

(314) 421-1979 (fax)

E-mail: rick.zucker@thelacledegrou.com

ATTORNEY FOR LACLEDE GAS COMPANY

CERTIFICATE OF SERVICE


The undersigned certifies that a true and correct copy of the foregoing Application and Petition was served on the Staff and the Office of the Public Counsel on this 1st day of February, 2016 by hand-delivery, fax, electronic mail or U.S. mail, postage prepaid.

/s/ Marcia Spangler

VERIFICATION


State of Missouri)
)
City of St. Louis) ss

I, C. Eric Lobser, being of lawful age state: that I am Vice President, Rates and Regulatory Affairs of Laclede Gas Company; that I have read the foregoing Application and Petition and the documents attached thereto; that the statements and information set forth in such Application and Petition and attached documents are true and correct to the best of my information, knowledge and belief; and, that I am authorized to make this statement on behalf of Laclede Gas Company.




C. Eric Lobser

Subscribed and sworn to before me this 29th day of January, 2016.



Notary Public

My Commission Expires: 9-24-18



MAIN REPLACEMENTS - ADDITIONS

| PLANT ACCOUNT | WORK ORDER | BUDGET PROJECT | DESCRIPTION | IN SERVICE DATE | ADDITION AMOUNT | MONTHS | DEPR. MO. RATE | ACCUM. DEPR. | DEPR. EXPENSE |
|------------------------|------------|----------------|------------------------------------|-----------------|-----------------|--------|----------------|--------------|---------------|
| 376300-Mains - Plastic | 000569 | 3304L | 4015F 6P 2P Lemay Ferry | 201509 | (1.41) | 7 | 0.0013083 | (0.01) | (0.02) |
| 376300-Mains - Plastic | 001040 | 3303L | Install 46F 4P Nashville | 201509 | 0.24 | 7 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 001330 | 3303L | Inst 9084F 2P Aberdeen Pl | 201509 | (2,560.96) | 7 | 0.0013083 | (23.45) | (40.21) |
| 376300-Mains - Plastic | 001535 | 3303L | Repl w/ 9096F 2P Arlington | 201509 | (64.85) | 7 | 0.0013083 | (0.59) | (1.02) |
| 376300-Mains - Plastic | 001711 | 3303L | Inst 7023F 2P Northmoor Wydown Ph5 | 201509 | (3.95) | 7 | 0.0013083 | (0.04) | (0.06) |
| 376300-Mains - Plastic | 001712 | 3303L | Inst 16489F 2P Cote Brilliante | 201509 | 9,221.71 | 7 | 0.0013083 | 64.45 | 144.78 |
| 376300-Mains - Plastic | 001712 | 3303L | Inst 16489F 2P Cote Brilliante | 201510 | (31.23) | 6 | 0.0013083 | (0.25) | (0.49) |
| 376300-Mains - Plastic | 002137 | 3303L | Repl w/ 5955F 2P Boneta | 201509 | (945.64) | 7 | 0.0013083 | (8.66) | (14.85) |
| 376300-Mains - Plastic | 002138 | 3303L | Repl w/ 10203F 2P Manchester | 201509 | (2,642.34) | 7 | 0.0013083 | (24.20) | (41.48) |
| 376300-Mains - Plastic | 002139 | 3303L | Inst 3278F 2P MLK -Wellston 1B | 201509 | (5,826.13) | 7 | 0.0013083 | (53.35) | (91.47) |
| 376300-Mains - Plastic | 002139 | 3303L | Inst 3278F 2P MLK -Wellston 1B | 201510 | 904.98 | 6 | 0.0013083 | 7.10 | 14.21 |
| 376300-Mains - Plastic | 002139 | 3303L | Inst 3278F 2P MLK -Wellston 1B | 201511 | 1,800.80 | 5 | 0.0013083 | 11.78 | 26.27 |
| 376300-Mains - Plastic | 002139 | 3303L | Inst 3278F 2P MLK -Wellston 1B | 201512 | 259.07 | 4 | 0.0013083 | 1.36 | 4.07 |
| 376300-Mains - Plastic | 002140 | 3303L | Inst 6894F 2P Bertha-Wellston 1A | 201509 | (3,734.71) | 7 | 0.0013083 | (34.20) | (58.63) |
| 376300-Mains - Plastic | 002140 | 3303L | Inst 6894F 2P Bertha-Wellston 1A | 201510 | 3,703.14 | 6 | 0.0013083 | 29.07 | 58.14 |
| 376300-Mains - Plastic | 002141 | 3303L | Inst 6161F 2P Marshall-Well. Ph4C | 201509 | (0.90) | 7 | 0.0013083 | (0.01) | (0.01) |
| 376300-Mains - Plastic | 002434 | 3303M | Deer Run main replacement | 201509 | 1,157.63 | 7 | 0.0013083 | 10.60 | 18.17 |
| 376300-Mains - Plastic | 672850 | 3301L | 67285 590F 4P JAMES & SUTTON | 201509 | 21,540.46 | 7 | 0.0013083 | 197.27 | 338.18 |
| 376300-Mains - Plastic | 696000 | 3301M | 69600 MAIN VAR INST MTCE | 201509 | (1,040.93) | 7 | 0.0013083 | (9.53) | (16.34) |
| 376300-Mains - Plastic | 698000 | 3301L | 69800 MAIN VAR INST MTCE | 201509 | 1,345.76 | 7 | 0.0013083 | 12.32 | 21.13 |
| 376300-Mains - Plastic | 698000 | 3301L | 69800 MAIN VAR INST MTCE | 201510 | 1,852.53 | 6 | 0.0013083 | 14.54 | 29.08 |
| 376300-Mains - Plastic | 698000 | 3301L | 69800 MAIN VAR INST MTCE | 201511 | 100.79 | 5 | 0.0013083 | 0.66 | 1.58 |
| 376300-Mains - Plastic | 698000 | 3301L | 69800 MAIN VAR INST MTCE | 201512 | 1,954.95 | 4 | 0.0013083 | 10.23 | 30.69 |
| 376100-Mains - Steel | 699000 | 3301L | 69900 MAIN STL INST MTCE | 201509 | (32.75) | 7 | 0.0012000 | (0.28) | (0.47) |
| 376300-Mains - Plastic | 699220 | 3301L | 69922 MAIN PLS INST MTCE | 201509 | 111,071.44 | 7 | 0.0013083 | 1,017.20 | 1,743.78 |
| 376300-Mains - Plastic | 699220 | 3301L | 69922 MAIN PLS INST MTCE | 201510 | 46,027.60 | 6 | 0.0013083 | 361.31 | 722.61 |
| 376300-Mains - Plastic | 699220 | 3301L | 69922 MAIN PLS INST MTCE | 201511 | 10,719.41 | 5 | 0.0013083 | 70.12 | 168.29 |
| 376300-Mains - Plastic | 699220 | 3301L | 69922 MAIN PLS INST MTCE | 201512 | 7,439.66 | 4 | 0.0013083 | 38.93 | 116.80 |
| 376100-Mains - Steel | 699500 | 3301L | 69950 MAIN STL INST MTCE | 201509 | 2,081.35 | 7 | 0.0012000 | 17.48 | 29.97 |
| 376100-Mains - Steel | 699500 | 3301L | 69950 MAIN STL INST MTCE | 201510 | 1,475.88 | 6 | 0.0012000 | 10.63 | 21.25 |
| 376100-Mains - Steel | 699500 | 3301L | 69950 MAIN STL INST MTCE | 201511 | 39,567.15 | 5 | 0.0012000 | 237.52 | 570.05 |
| 376100-Mains - Steel | 699500 | 3301L | 69950 MAIN STL INST MTCE | 201512 | (721.14) | 4 | 0.0012000 | (3.46) | (10.38) |
| 376300-Mains - Plastic | 699720 | 3301L | 69972 MAIN PLS INST MTCE | 201509 | 12,161.30 | 7 | 0.0013083 | 111.37 | 190.93 |
| 376300-Mains - Plastic | 699720 | 3301L | 69972 MAIN PLS INST MTCE | 201510 | 95,590.12 | 6 | 0.0013083 | 750.36 | 1,500.73 |
| 376300-Mains - Plastic | 699720 | 3301L | 69972 MAIN PLS INST MTCE | 201511 | 43,267.57 | 5 | 0.0013083 | 283.03 | 679.28 |
| 376300-Mains - Plastic | 699720 | 3301L | 69972 MAIN PLS INST MTCE | 201512 | 100,205.95 | 4 | 0.0013083 | 524.40 | 1,573.19 |
| 376300-Mains - Plastic | 900068 | 3303L | Repl w/ 1750F 2P Jefferson Ph 2 | 201509 | (4,343.07) | 7 | 0.0013083 | (39.77) | (68.18) |
| 376300-Mains - Plastic | 900068 | 3303L | Repl w/ 1750F 2P Jefferson Ph 2 | 201509 | (102.69) | 7 | 0.0013083 | (0.94) | (1.61) |
| 376300-Mains - Plastic | 900069 | 3303L | Inst 3539F 2P Jefferson Ph 3 | 201509 | 17,838.94 | 7 | 0.0013083 | 163.37 | 280.06 |
| 376300-Mains - Plastic | 900069 | 3303L | Inst 3539F 2P Jefferson Ph 3 | 201509 | 575.06 | 7 | 0.0013083 | 5.27 | 9.03 |
| 376300-Mains - Plastic | 900069 | 3303L | Inst 3539F 2P Jefferson Ph 3 | 201510 | 1,179.13 | 6 | 0.0013083 | 9.26 | 18.51 |
| 376300-Mains - Plastic | 900069 | 3303L | Inst 3539F 2P Jefferson Ph 3 | 201510 | 38.01 | 6 | 0.0013083 | 0.30 | 0.60 |
| 376300-Mains - Plastic | 900069 | 3303L | Inst 3539F 2P Jefferson Ph 3 | 201511 | (41.72) | 5 | 0.0013083 | (0.27) | (0.65) |
| 376300-Mains - Plastic | 900069 | 3303L | Inst 3539F 2P Jefferson Ph 3 | 201511 | (1.34) | 5 | 0.0013083 | (0.01) | (0.02) |
| 376300-Mains - Plastic | 900069 | 3303L | Inst 3539F 2P Jefferson Ph 3 | 201512 | 59.61 | 4 | 0.0013083 | 0.31 | 0.94 |
| 376300-Mains - Plastic | 900069 | 3303L | Inst 3539F 2P Jefferson Ph 3 | 201512 | 1,848.91 | 4 | 0.0013083 | 9.68 | 29.03 |

| | | | | | | | | | |
|------------------------|--------|-------|-------------------------------------|--------|-------------|---|-----------|----------|-----------|
| 376100-Mains - Steel | 900071 | 3303L | Repl w/ 4240F 2-4P Jefferson Ph5 | 201511 | 13,103.35 | 5 | 0.0012000 | 78.62 | 188.69 |
| 376300-Mains - Plastic | 900071 | 3303L | Repl w/ 4240F 2-4P Jefferson Ph5 | 201511 | 900,252.52 | 5 | 0.0013083 | 5,889.00 | 14,133.60 |
| 376300-Mains - Plastic | 900071 | 3303L | Repl w/ 4240F 2-4P Jefferson Ph5 | 201511 | 62,981.36 | 5 | 0.0013083 | 411.99 | 988.78 |
| 376100-Mains - Steel | 900071 | 3303L | Repl w/ 4240F 2-4P Jefferson Ph5 | 201512 | 43.32 | 4 | 0.0012000 | 0.21 | 0.62 |
| 376300-Mains - Plastic | 900071 | 3303L | Repl w/ 4240F 2-4P Jefferson Ph5 | 201512 | 208.22 | 4 | 0.0013083 | 1.09 | 3.27 |
| 376300-Mains - Plastic | 900071 | 3303L | Repl w/ 4240F 2-4P Jefferson Ph5 | 201512 | 2,976.14 | 4 | 0.0013083 | 15.57 | 46.72 |
| 376300-Mains - Plastic | 900072 | 3303L | Repl w 688F 2P & 2527F 4P Lafayette | 201509 | (0.71) | 7 | 0.0013083 | (0.01) | (0.01) |
| 376300-Mains - Plastic | 900072 | 3303L | Repl w 688F 2P & 2527F 4P Lafayette | 201509 | (0.07) | 7 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900073 | 3303L | Repl w/ 2520F 2P Jefferson Ph 6 | 201509 | (13,672.40) | 7 | 0.0013083 | (125.21) | (214.65) |
| 376300-Mains - Plastic | 900073 | 3303L | Repl w/ 2520F 2P Jefferson Ph 6 | 201509 | 85,369.76 | 7 | 0.0013083 | 781.82 | 1,340.27 |
| 376300-Mains - Plastic | 900073 | 3303L | Repl w/ 2520F 2P Jefferson Ph 6 | 201509 | 1,089.22 | 7 | 0.0013083 | 9.98 | 17.10 |
| 376300-Mains - Plastic | 900073 | 3303L | Repl w/ 2520F 2P Jefferson Ph 6 | 201510 | 577.21 | 6 | 0.0013083 | 4.53 | 9.06 |
| 376300-Mains - Plastic | 900073 | 3303L | Repl w/ 2520F 2P Jefferson Ph 6 | 201510 | 19.92 | 6 | 0.0013083 | 0.16 | 0.31 |
| 376300-Mains - Plastic | 900093 | 3303L | Repl w/ 184F 2P Cass | 201509 | 0.09 | 7 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900093 | 3303L | Repl w/ 184F 2P Cass | 201509 | 0.01 | 7 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900169 | 3304L | Inst 6228F 8P Loughborough | 201509 | (0.58) | 7 | 0.0013083 | (0.01) | (0.01) |
| 376300-Mains - Plastic | 900169 | 3304L | Inst 6228F 8P Loughborough | 201509 | (0.01) | 7 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900170 | 3304L | Inst 3526F 6P Field & Koeln | 201509 | 0.24 | 7 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900170 | 3304L | Inst 3526F 6P Field & Koeln | 201509 | 0.01 | 7 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900262 | 3304L | Inst 7615F 12P Clifton Hill-Columbi | 201509 | (5,684.03) | 7 | 0.0013083 | (52.05) | (89.24) |
| 376300-Mains - Plastic | 900262 | 3304L | Inst 7615F 12P Clifton Hill-Columbi | 201509 | (659.50) | 7 | 0.0013083 | (6.04) | (10.35) |
| 376300-Mains - Plastic | 900264 | 3303L | Int 3087F 4P 2P Baden Grid Ph 5A | 201509 | 69.14 | 7 | 0.0013083 | 0.53 | 1.09 |
| 376300-Mains - Plastic | 900264 | 3303L | Int 3087F 4P 2P Baden Grid Ph 5A | 201509 | 4.36 | 7 | 0.0013083 | 0.04 | 0.07 |
| 376300-Mains - Plastic | 900265 | 3303L | Repl w/ 3337F 2P Baden Ph 5B | 201509 | 2.35 | 7 | 0.0013083 | 0.02 | 0.04 |
| 376300-Mains - Plastic | 900265 | 3303L | Repl w/ 3337F 2P Baden Ph 5B | 201509 | 0.11 | 7 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900266 | 3303L | Inst 4640F 2P Baden Ph 5C | 201509 | (1.37) | 7 | 0.0013083 | (0.01) | (0.02) |
| 376300-Mains - Plastic | 900266 | 3303L | Inst 4640F 2P Baden Ph 5C | 201509 | (0.01) | 7 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900266 | 3303L | Inst 4640F 2P Baden Ph 5C | 201510 | 6.69 | 6 | 0.0013083 | 0.05 | 0.11 |
| 376300-Mains - Plastic | 900266 | 3303L | Inst 4640F 2P Baden Ph 5C | 201510 | 0.16 | 6 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900266 | 3303L | Inst 4640F 2P Baden Ph 5C | 201511 | (0.43) | 5 | 0.0013083 | - | (0.01) |
| 376300-Mains - Plastic | 900266 | 3303L | Inst 4640F 2P Baden Ph 5C | 201511 | (0.01) | 5 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900266 | 3303L | Inst 4640F 2P Baden Ph 5C | 201512 | 0.83 | 4 | 0.0013083 | - | 0.01 |
| 376300-Mains - Plastic | 900266 | 3303L | Inst 4640F 2P Baden Ph 5C | 201512 | 31.28 | 4 | 0.0013083 | 0.16 | 0.49 |
| 376300-Mains - Plastic | 900267 | 3303L | Repl w/ 4536F 2P Baden Ph5D | 201509 | 3.79 | 7 | 0.0013083 | 0.03 | 0.06 |
| 376300-Mains - Plastic | 900267 | 3303L | Repl w/ 4536F 2P Baden Ph5D | 201509 | 0.18 | 7 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900268 | 3303L | Inst 4411F 2P Baden Ph5E | 201509 | 1.80 | 7 | 0.0013083 | 0.02 | 0.03 |
| 376300-Mains - Plastic | 900268 | 3303L | Inst 4411F 2P Baden Ph5E | 201509 | 0.17 | 7 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900269 | 3303L | Inst 1150F 4P Walnut Park Ph 5A | 201509 | (934.60) | 7 | 0.0013083 | (8.56) | (14.67) |
| 376300-Mains - Plastic | 900270 | 3303L | Inst 2942F 2P Walnut Park Ph5B | 201509 | (1,257.45) | 7 | 0.0013083 | (11.52) | (19.74) |
| 376300-Mains - Plastic | 900270 | 3303L | Inst 2942F 2P Walnut Park Ph5B | 201509 | (6.08) | 7 | 0.0013083 | (0.06) | (0.10) |
| 376300-Mains - Plastic | 900270 | 3303L | Inst 2942F 2P Walnut Park Ph5B | 201511 | (3,525.80) | 5 | 0.0013083 | (23.06) | (55.35) |
| 376300-Mains - Plastic | 900270 | 3303L | Inst 2942F 2P Walnut Park Ph5B | 201511 | 182.10 | 5 | 0.0013083 | 1.19 | 2.86 |
| 376300-Mains - Plastic | 900271 | 3303L | Inst 2646F 2P Walnut Park Ph5C | 201509 | (4,190.49) | 7 | 0.0013083 | (38.38) | (65.79) |
| 376300-Mains - Plastic | 900271 | 3303L | Inst 2646F 2P Walnut Park Ph5C | 201509 | (175.33) | 7 | 0.0013083 | (1.61) | (2.75) |
| 376300-Mains - Plastic | 900271 | 3303L | Inst 2646F 2P Walnut Park Ph5C | 201511 | (1,893.59) | 5 | 0.0013083 | (12.39) | (29.73) |
| 376300-Mains - Plastic | 900271 | 3303L | Inst 2646F 2P Walnut Park Ph5C | 201511 | (61.33) | 5 | 0.0013083 | (0.40) | (0.96) |
| 376300-Mains - Plastic | 900272 | 3303L | Inst 4170F 2P Walnut Park Ph 5D | 201509 | 220,111.88 | 7 | 0.0013083 | 2,015.81 | 3,455.67 |
| 376300-Mains - Plastic | 900272 | 3303L | Inst 4170F 2P Walnut Park Ph 5D | 201509 | 13,967.23 | 7 | 0.0013083 | 127.91 | 219.28 |
| 376300-Mains - Plastic | 900272 | 3303L | Inst 4170F 2P Walnut Park Ph 5D | 201511 | (19.02) | 5 | 0.0013083 | (0.12) | (0.30) |
| 376300-Mains - Plastic | 900272 | 3303L | Inst 4170F 2P Walnut Park Ph 5D | 201511 | (1.21) | 5 | 0.0013083 | (0.01) | (0.02) |
| 376300-Mains - Plastic | 900272 | 3303L | Inst 4170F 2P Walnut Park Ph 5D | 201512 | 0.01 | 4 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900272 | 3303L | Inst 4170F 2P Walnut Park Ph 5D | 201512 | 0.26 | 4 | 0.0013083 | - | - |

| | | | | | | | | | |
|------------------------|--------|-------|-------------------------------------|--------|------------|---|-----------|----------|----------|
| 376300-Mains - Plastic | 900273 | 3303L | Repl w/ 4565F 2P Walnut Park Ph5E | 201510 | 179,265.41 | 6 | 0.0013083 | 1,407.12 | 2,814.24 |
| 376300-Mains - Plastic | 900273 | 3303L | Repl w/ 4565F 2P Walnut Park Ph5E | 201510 | 11,376.57 | 6 | 0.0013083 | 89.30 | 178.61 |
| 376300-Mains - Plastic | 900273 | 3303L | Repl w/ 4565F 2P Walnut Park Ph5E | 201511 | (142.08) | 5 | 0.0013083 | (0.93) | (2.23) |
| 376300-Mains - Plastic | 900273 | 3303L | Repl w/ 4565F 2P Walnut Park Ph5E | 201511 | (9.03) | 5 | 0.0013083 | (0.06) | (0.14) |
| 376300-Mains - Plastic | 900273 | 3303L | Repl w/ 4565F 2P Walnut Park Ph5E | 201512 | 3.98 | 4 | 0.0013083 | 0.02 | 0.06 |
| 376300-Mains - Plastic | 900273 | 3303L | Repl w/ 4565F 2P Walnut Park Ph5E | 201512 | 62.81 | 4 | 0.0013083 | 0.33 | 0.99 |
| 376300-Mains - Plastic | 900274 | 3303L | Repl w/ 3390F 2P Wellington Ph 4D | 201509 | (8,673.73) | 7 | 0.0013083 | (79.43) | (136.17) |
| 376300-Mains - Plastic | 900274 | 3303L | Repl w/ 3390F 2P Wellington Ph 4D | 201509 | (461.00) | 7 | 0.0013083 | (4.22) | (7.24) |
| 376300-Mains - Plastic | 900274 | 3303L | Repl w/ 3390F 2P Wellington Ph 4D | 201512 | (7,614.83) | 4 | 0.0013083 | (39.85) | (119.55) |
| 376300-Mains - Plastic | 900274 | 3303L | Repl w/ 3390F 2P Wellington Ph 4D | 201512 | (1,051.67) | 4 | 0.0013083 | (5.50) | (16.51) |
| 376300-Mains - Plastic | 900275 | 3303L | Repl w/ 4989F 2P Wellington Ph4E | 201509 | (5,743.64) | 7 | 0.0013083 | (52.60) | (90.17) |
| 376300-Mains - Plastic | 900275 | 3303L | Repl w/ 4989F 2P Wellington Ph4E | 201509 | (25.04) | 7 | 0.0013083 | (0.23) | (0.39) |
| 376300-Mains - Plastic | 900277 | 3303L | Repl w/ 1725F 2P Walnut Park Ph4B | 201509 | (43.04) | 7 | 0.0013083 | (0.39) | (0.68) |
| 376300-Mains - Plastic | 900277 | 3303L | Repl w/ 1725F 2P Walnut Park Ph4B | 201509 | (2.12) | 7 | 0.0013083 | (0.02) | (0.03) |
| 376300-Mains - Plastic | 900278 | 3303L | Repl w/ 3977F 2P Walnut Park Ph4C | 201509 | (77.43) | 7 | 0.0013083 | (0.71) | (1.22) |
| 376300-Mains - Plastic | 900278 | 3303L | Repl w/ 3977F 2P Walnut Park Ph4C | 201509 | (1.70) | 7 | 0.0013083 | (0.02) | (0.03) |
| 376300-Mains - Plastic | 900279 | 3303L | Repl w/ 3345F 2P Walnut Park Ph4D | 201509 | (1,520.17) | 7 | 0.0013083 | (13.92) | (23.87) |
| 376300-Mains - Plastic | 900279 | 3303L | Repl w/ 3345F 2P Walnut Park Ph4D | 201509 | (2.37) | 7 | 0.0013083 | (0.02) | (0.04) |
| 376300-Mains - Plastic | 900281 | 3303L | Inst 4984F 4PWellston Phase 2B | 201509 | (5.95) | 7 | 0.0013083 | (0.05) | (0.09) |
| 376300-Mains - Plastic | 900281 | 3303L | Inst 4984F 4PWellston Phase 2B | 201509 | (0.08) | 7 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900282 | 3303L | Inst 4400F 2P Wellston 2C | 201509 | (2,206.46) | 7 | 0.0013083 | (20.21) | (34.64) |
| 376300-Mains - Plastic | 900282 | 3303L | Inst 4400F 2P Wellston 2C | 201509 | (15.44) | 7 | 0.0013083 | (0.14) | (0.24) |
| 376300-Mains - Plastic | 900283 | 3303L | Inst 5300F 2P Wellston Ph2D | 201509 | 1.96 | 7 | 0.0013083 | 0.02 | 0.03 |
| 376300-Mains - Plastic | 900283 | 3303L | Inst 5300F 2P Wellston Ph2D | 201509 | 0.12 | 7 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900284 | 3303L | Inst 5466F 2P Wellston Ph2E | 201509 | (1,985.71) | 7 | 0.0013083 | (18.19) | (31.17) |
| 376300-Mains - Plastic | 900284 | 3303L | Inst 5466F 2P Wellston Ph2E | 201509 | (38.81) | 7 | 0.0013083 | (0.36) | (0.61) |
| 376300-Mains - Plastic | 900310 | 3303L | Inst 2250F 2P Yale Ave Maplewood 1C | 201511 | (85.11) | 5 | 0.0013083 | (0.56) | (1.34) |
| 376300-Mains - Plastic | 900375 | 3303L | Inst 1747F 6P Litzsinger | 201509 | 5.18 | 7 | 0.0013083 | 0.05 | 0.08 |
| 376300-Mains - Plastic | 900375 | 3303L | Inst 1747F 6P Litzsinger | 201509 | 0.06 | 7 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900377 | 3303L | Repl w/ 978F 2-4P Big Bend | 201509 | (780.84) | 7 | 0.0013083 | (7.15) | (12.28) |
| 376300-Mains - Plastic | 900377 | 3303L | Repl w/ 978F 2-4P Big Bend | 201509 | (9.65) | 7 | 0.0013083 | (0.09) | (0.15) |
| 376100-Mains - Steel | 900379 | 3303L | Inst 783F 4P & 529F 2POld Bonhomme | 201509 | (4.39) | 7 | 0.0012000 | (0.04) | (0.06) |
| 376300-Mains - Plastic | 900379 | 3303L | Inst 783F 4P & 529F 2POld Bonhomme | 201509 | (34.34) | 7 | 0.0013083 | (0.31) | (0.54) |
| 376300-Mains - Plastic | 900379 | 3303L | Inst 783F 4P & 529F 2POld Bonhomme | 201509 | (0.70) | 7 | 0.0013083 | (0.01) | (0.01) |
| 376300-Mains - Plastic | 900388 | 3303L | Repl w/ 332F 2P Tay Rd | 201509 | (5.15) | 7 | 0.0013083 | (0.05) | (0.08) |
| 376300-Mains - Plastic | 900390 | 3303L | Inst 205F 1 1/4P Gore | 201509 | (4.45) | 7 | 0.0013083 | (0.04) | (0.07) |
| 376300-Mains - Plastic | 900390 | 3303L | Inst 205F 1 1/4P Gore | 201509 | (0.08) | 7 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900392 | 3303L | Inst 580F 4P & 255F 2P Ferguson | 201509 | (2.54) | 7 | 0.0013083 | (0.02) | (0.04) |
| 376300-Mains - Plastic | 900392 | 3303L | Inst 580F 4P & 255F 2P Ferguson | 201509 | (0.05) | 7 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900393 | 3304L | Inst 3745F 8P Clayton Ave | 201509 | (1.72) | 7 | 0.0013083 | (0.02) | (0.03) |
| 376300-Mains - Plastic | 900393 | 3304L | Inst 3745F 8P Clayton Ave | 201509 | (0.09) | 7 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900395 | 3303L | Repl w/ 525F 2P Clay St | 201509 | (1.30) | 7 | 0.0013083 | (0.01) | (0.02) |
| 376300-Mains - Plastic | 900412 | 3303L | Repl w/ 412F 6P Holly Hills | 201509 | (123.62) | 7 | 0.0013083 | (1.13) | (1.94) |
| 376300-Mains - Plastic | 900412 | 3303L | Repl w/ 412F 6P Holly Hills | 201509 | (5.62) | 7 | 0.0013083 | (0.05) | (0.09) |
| 376300-Mains - Plastic | 900415 | 3303L | Repl w/ 1093F 2P Princeton | 201509 | (3.64) | 7 | 0.0013083 | (0.03) | (0.06) |
| 376300-Mains - Plastic | 900415 | 3303L | Repl w/ 1093F 2P Princeton | 201509 | (0.08) | 7 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900420 | 3303L | Repl w/ 520F 2P Oregon | 201509 | (7.28) | 7 | 0.0013083 | (0.07) | (0.11) |
| 376300-Mains - Plastic | 900420 | 3303L | Repl w/ 520F 2P Oregon | 201509 | (0.49) | 7 | 0.0013083 | - | (0.01) |
| 376300-Mains - Plastic | 900421 | 3303L | Repl w/ 970F 2P Winnebago | 201509 | (9.06) | 7 | 0.0013083 | (0.08) | (0.14) |
| 376300-Mains - Plastic | 900422 | 3303L | Repl w/ 780F 2P Taft | 201509 | (6.12) | 7 | 0.0013083 | (0.06) | (0.10) |
| 376300-Mains - Plastic | 900422 | 3303L | Repl w/ 780F 2P Taft | 201509 | (0.24) | 7 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900423 | 3303L | Repl w/ 1373F 2P Dr MLK | 201509 | (0.19) | 7 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900423 | 3303L | Repl w/ 1373F 2P Dr MLK | 201509 | (0.02) | 7 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900424 | 3303L | Repl w/ 520F 3P Red Bud | 201509 | 4.52 | 7 | 0.0013083 | 0.04 | 0.07 |

| | | | | | | | | | |
|------------------------|--------|-------|-------------------------------------|--------|-------------|---|-----------|----------|----------|
| 376300-Mains - Plastic | 900424 | 3303L | Repl w/ 520F 3P Red Bud | 201509 | 0.72 | 7 | 0.0013083 | 0.01 | 0.01 |
| 376300-Mains - Plastic | 900430 | 3303L | Repl w/ 654F 2P Maurice | 201509 | (5.48) | 7 | 0.0013083 | (0.05) | (0.09) |
| 376300-Mains - Plastic | 900430 | 3303L | Repl w/ 654F 2P Maurice | 201509 | (0.41) | 7 | 0.0013083 | - | (0.01) |
| 376300-Mains - Plastic | 900432 | 3303L | Repl w/ 503F 2P Gravois | 201509 | (7.24) | 7 | 0.0013083 | (0.07) | (0.11) |
| 376300-Mains - Plastic | 900432 | 3303L | Repl w/ 503F 2P Gravois | 201509 | (0.17) | 7 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900433 | 3303L | Repl w/ 570F 4P Chippewa | 201509 | (9.50) | 7 | 0.0013083 | (0.09) | (0.15) |
| 376300-Mains - Plastic | 900433 | 3303L | Repl w/ 570F 4P Chippewa | 201509 | (0.47) | 7 | 0.0013083 | - | (0.01) |
| 376300-Mains - Plastic | 900439 | 3303L | Repl w/ 269F 2P Ferguson | 201509 | (3.99) | 7 | 0.0013083 | (0.04) | (0.06) |
| 376300-Mains - Plastic | 900439 | 3303L | Repl w/ 269F 2P Ferguson | 201509 | (0.13) | 7 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900456 | 3304L | Inst 8175F 8P Jamieson McCausland | 201509 | 2.80 | 7 | 0.0013083 | 0.03 | 0.04 |
| 376300-Mains - Plastic | 900456 | 3304L | Inst 8175F 8P Jamieson McCausland | 201509 | 0.13 | 7 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900457 | 3303L | Inst 4546F 2P Baden Ph5F | 201509 | (1.87) | 7 | 0.0013083 | (0.02) | (0.03) |
| 376300-Mains - Plastic | 900457 | 3303L | Inst 4546F 2P Baden Ph5F | 201509 | (0.09) | 7 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900458 | 3303L | Repl w/ 2796F 2P Wellington Grd Ph4 | 201509 | (58,082.40) | 7 | 0.0013083 | (531.92) | (911.87) |
| 376300-Mains - Plastic | 900458 | 3303L | Repl w/ 2796F 2P Wellington Grd Ph4 | 201509 | (571.95) | 7 | 0.0013083 | (5.24) | (8.98) |
| 376300-Mains - Plastic | 900458 | 3303L | Repl w/ 2796F 2P Wellington Grd Ph4 | 201511 | (3,690.24) | 5 | 0.0013083 | (24.14) | (57.94) |
| 376300-Mains - Plastic | 900458 | 3303L | Repl w/ 2796F 2P Wellington Grd Ph4 | 201511 | (36.33) | 5 | 0.0013083 | (0.24) | (0.57) |
| 376300-Mains - Plastic | 900460 | 3303L | Inst 3488F 2P Walnut Park Ph4E | 201509 | (4.12) | 7 | 0.0013083 | (0.04) | (0.06) |
| 376300-Mains - Plastic | 900460 | 3303L | Inst 3488F 2P Walnut Park Ph4E | 201509 | (0.23) | 7 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900461 | 3303L | Inst 893F 2P Walnut Park Ph4F | 201509 | (0.36) | 7 | 0.0013083 | - | (0.01) |
| 376300-Mains - Plastic | 900462 | 3303L | Repl w/ 2240F 2P Walnut Park Ph4G | 201509 | (509.22) | 7 | 0.0013083 | (4.66) | (7.99) |
| 376300-Mains - Plastic | 900462 | 3303L | Repl w/ 2240F 2P Walnut Park Ph4G | 201509 | (12.42) | 7 | 0.0013083 | (0.11) | (0.19) |
| 376300-Mains - Plastic | 900463 | 3303L | Inst 4082F 2P Walnut Park Ph4H | 201509 | (22.15) | 7 | 0.0013083 | (0.20) | (0.35) |
| 376300-Mains - Plastic | 900463 | 3303L | Inst 4082F 2P Walnut Park Ph4H | 201509 | (1.28) | 7 | 0.0013083 | (0.01) | (0.02) |
| 376300-Mains - Plastic | 900464 | 3303L | Inst 4741F 2PWalnut Park Ph 4I | 201509 | (447.33) | 7 | 0.0013083 | (4.10) | (7.02) |
| 376300-Mains - Plastic | 900464 | 3303L | Inst 4741F 2PWalnut Park Ph 4I | 201509 | (7.52) | 7 | 0.0013083 | (0.07) | (0.12) |
| 376300-Mains - Plastic | 900467 | 3303L | Repl w/ 2400F 2-4P Potomac AOR | 201509 | (0.22) | 7 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900467 | 3303L | Repl w/ 2400F 2-4P Potomac AOR | 201509 | (0.01) | 7 | 0.0013083 | - | - |
| 376100-Mains - Steel | 900474 | 3304L | Repl w/ 3774F 8P 8S Mullanphy | 201509 | 10.38 | 7 | 0.0012000 | 0.09 | 0.15 |
| 376300-Mains - Plastic | 900474 | 3304L | Repl w/ 3774F 8P 8S Mullanphy | 201509 | 31.57 | 7 | 0.0013083 | 0.29 | 0.50 |
| 376300-Mains - Plastic | 900474 | 3304L | Repl w/ 3774F 8P 8S Mullanphy | 201509 | 1.31 | 7 | 0.0013083 | 0.01 | 0.02 |
| 376300-Mains - Plastic | 900475 | 3304L | Inst 1895F 6P Koein | 201509 | (10,229.73) | 7 | 0.0013083 | (93.68) | (160.60) |
| 376300-Mains - Plastic | 900475 | 3304L | Inst 1895F 6P Koein | 201509 | (386.96) | 7 | 0.0013083 | (3.54) | (6.08) |
| 376300-Mains - Plastic | 900476 | 3304L | Inst 3350F 6P Ivory | 201509 | (11,473.52) | 7 | 0.0013083 | (105.08) | (180.13) |
| 376300-Mains - Plastic | 900476 | 3304L | Inst 3350F 6P Ivory | 201509 | (1,118.62) | 7 | 0.0013083 | (10.24) | (17.58) |
| 376300-Mains - Plastic | 900476 | 3304L | Inst 3350F 6P Ivory | 201511 | 480.45 | 5 | 0.0013083 | 3.14 | 7.54 |
| 376300-Mains - Plastic | 900476 | 3304L | Inst 3350F 6P Ivory | 201511 | (586.91) | 5 | 0.0013083 | (3.84) | (9.21) |
| 376300-Mains - Plastic | 900476 | 3304L | Inst 3350F 6P Ivory | 201512 | (18.06) | 4 | 0.0013083 | (0.09) | (0.28) |
| 376300-Mains - Plastic | 900476 | 3304L | Inst 3350F 6P Ivory | 201512 | (3.62) | 4 | 0.0013083 | (0.02) | (0.06) |
| 376100-Mains - Steel | 900479 | 3304L | Inst 3525F 8P Union | 201509 | (239.24) | 7 | 0.0012000 | (2.01) | (3.45) |
| 376300-Mains - Plastic | 900479 | 3304L | Inst 3525F 8P Union | 201509 | (8,296.61) | 7 | 0.0013083 | (75.98) | (130.25) |
| 376300-Mains - Plastic | 900479 | 3304L | Inst 3525F 8P Union | 201509 | (532.73) | 7 | 0.0013083 | (4.88) | (8.36) |
| 376100-Mains - Steel | 900479 | 3304L | Inst 3525F 8P Union | 201511 | (14,911.61) | 5 | 0.0012000 | (89.47) | (214.73) |
| 376300-Mains - Plastic | 900479 | 3304L | Inst 3525F 8P Union | 201511 | 27,392.31 | 5 | 0.0013083 | 179.19 | 430.05 |
| 376300-Mains - Plastic | 900479 | 3304L | Inst 3525F 8P Union | 201511 | (12,480.70) | 5 | 0.0013083 | (81.64) | (195.94) |
| 376300-Mains - Plastic | 900480 | 3304L | Inst 4528 8P Minerva | 201509 | (38.45) | 7 | 0.0013083 | (0.35) | (0.60) |
| 376300-Mains - Plastic | 900480 | 3304L | Inst 4528 8P Minerva | 201509 | (1.05) | 7 | 0.0013083 | (0.01) | (0.02) |
| 376300-Mains - Plastic | 900481 | 3304L | Inst 3125F 8P Union | 201509 | (9.78) | 7 | 0.0013083 | (0.09) | (0.15) |
| 376300-Mains - Plastic | 900481 | 3304L | Inst 3125F 8P Union | 201509 | (0.69) | 7 | 0.0013083 | (0.01) | (0.01) |
| 376300-Mains - Plastic | 900484 | 3304L | Inst 5203F 12P Ivanhoe | 201509 | (4,301.07) | 7 | 0.0013083 | (39.39) | (67.53) |
| 376300-Mains - Plastic | 900484 | 3304L | Inst 5203F 12P Ivanhoe | 201509 | (678.02) | 7 | 0.0013083 | (6.21) | (10.64) |
| 376100-Mains - Steel | 900485 | 3304L | Inst 4236F 12P Alaska | 201509 | (0.24) | 7 | 0.0012000 | - | - |
| 376300-Mains - Plastic | 900485 | 3304L | Inst 4236F 12P Alaska | 201509 | (34.47) | 7 | 0.0013083 | (0.32) | (0.54) |
| 376300-Mains - Plastic | 900485 | 3304L | Inst 4236F 12P Alaska | 201509 | (0.61) | 7 | 0.0013083 | (0.01) | (0.01) |

| | | | | | | | | | |
|------------------------|--------|-------|---------------------------------|--------|-------------|---|-----------|----------|----------|
| 376300-Mains - Plastic | 900486 | 3304L | Inst 6210F 8P Jamieson | 201509 | (0.56) | 7 | 0.0013083 | (0.01) | (0.01) |
| 376300-Mains - Plastic | 900486 | 3304L | Inst 6210F 8P Jamieson | 201509 | (0.03) | 7 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900487 | 3304L | Inst 4845F 8P Loughborough | 201509 | (11,894.55) | 7 | 0.0013083 | (108.93) | (186.74) |
| 376300-Mains - Plastic | 900487 | 3304L | Inst 4845F 8P Loughborough | 201509 | 9,963.32 | 7 | 0.0013083 | 91.25 | 156.42 |
| 376300-Mains - Plastic | 900488 | 3304L | Repl w/ 2873F 6P Hodiament | 201509 | 93.52 | 7 | 0.0013083 | 0.86 | 1.47 |
| 376300-Mains - Plastic | 900488 | 3304L | Repl w/ 2873F 6P Hodiament | 201509 | 7.93 | 7 | 0.0013083 | 0.07 | 0.12 |
| 376300-Mains - Plastic | 900520 | 3303L | Repl w/ 6590F 2P Maplewood Ph1C | 201509 | 56,967.70 | 7 | 0.0013083 | 521.72 | 894.37 |
| 376300-Mains - Plastic | 900520 | 3303L | Repl w/ 6590F 2P Maplewood Ph1C | 201509 | 1,032.48 | 7 | 0.0013083 | 9.46 | 16.21 |
| 376300-Mains - Plastic | 900520 | 3303L | Repl w/ 6590F 2P Maplewood Ph1C | 201510 | 496.20 | 6 | 0.0013083 | 3.90 | 7.79 |
| 376300-Mains - Plastic | 900520 | 3303L | Repl w/ 6590F 2P Maplewood Ph1C | 201510 | 9.01 | 6 | 0.0013083 | 0.07 | 0.14 |
| 376300-Mains - Plastic | 900520 | 3303L | Repl w/ 6590F 2P Maplewood Ph1C | 201511 | (1,103.95) | 5 | 0.0013083 | (7.22) | (17.33) |
| 376300-Mains - Plastic | 900520 | 3303L | Repl w/ 6590F 2P Maplewood Ph1C | 201511 | (20.00) | 5 | 0.0013083 | (0.13) | (0.31) |
| 376300-Mains - Plastic | 900520 | 3303L | Repl w/ 6590F 2P Maplewood Ph1C | 201512 | 55.91 | 4 | 0.0013083 | 0.29 | 0.88 |
| 376300-Mains - Plastic | 900520 | 3303L | Repl w/ 6590F 2P Maplewood Ph1C | 201512 | 3,084.21 | 4 | 0.0013083 | 16.14 | 48.42 |
| 376300-Mains - Plastic | 900523 | 3303L | Repl w/ 5304F 2P Maplewood Ph1D | 201512 | 5,348.03 | 4 | 0.0013083 | 27.99 | 83.96 |
| 376300-Mains - Plastic | 900523 | 3303L | Repl w/ 5304F 2P Maplewood Ph1D | 201512 | 510,114.64 | 4 | 0.0013083 | 2,669.53 | 8,008.60 |
| 376300-Mains - Plastic | 900546 | 3303L | Inst 5691F 2P Wellston Ph2F | 201512 | 24,704.27 | 4 | 0.0013083 | 129.28 | 387.85 |
| 376300-Mains - Plastic | 900546 | 3303L | Inst 5691F 2P Wellston Ph2F | 201512 | 331,690.96 | 4 | 0.0013083 | 1,735.81 | 5,207.42 |
| 376300-Mains - Plastic | 900548 | 3303L | Inst 6712F 2P Wellston Ph2H | 201511 | 311,357.07 | 5 | 0.0013083 | 2,036.74 | 4,888.18 |
| 376300-Mains - Plastic | 900548 | 3303L | Inst 6712F 2P Wellston Ph2H | 201511 | 7,800.93 | 5 | 0.0013083 | 51.03 | 122.47 |
| 376300-Mains - Plastic | 900548 | 3303L | Inst 6712F 2P Wellston Ph2H | 201512 | 210.01 | 4 | 0.0013083 | 1.10 | 3.30 |
| 376300-Mains - Plastic | 900548 | 3303L | Inst 6712F 2P Wellston Ph2H | 201512 | 8,361.89 | 4 | 0.0013083 | 43.66 | 131.59 |
| 376300-Mains - Plastic | 900556 | 3303L | Inst 5130F 2P Walnut Park Ph 5F | 201509 | 202,666.25 | 7 | 0.0013083 | 1,856.04 | 3,181.78 |
| 376300-Mains - Plastic | 900556 | 3303L | Inst 5130F 2P Walnut Park Ph 5F | 201509 | 15,492.14 | 7 | 0.0013083 | 141.88 | 243.22 |
| 376300-Mains - Plastic | 900556 | 3303L | Inst 5130F 2P Walnut Park Ph 5F | 201510 | (3,906.39) | 6 | 0.0013083 | (30.66) | (61.33) |
| 376300-Mains - Plastic | 900556 | 3303L | Inst 5130F 2P Walnut Park Ph 5F | 201510 | (298.60) | 6 | 0.0013083 | (2.34) | (4.69) |
| 376300-Mains - Plastic | 900556 | 3303L | Inst 5130F 2P Walnut Park Ph 5F | 201511 | 561.81 | 5 | 0.0013083 | 3.68 | 8.82 |
| 376300-Mains - Plastic | 900556 | 3303L | Inst 5130F 2P Walnut Park Ph 5F | 201511 | 42.94 | 5 | 0.0013083 | 0.28 | 0.67 |
| 376300-Mains - Plastic | 900556 | 3303L | Inst 5130F 2P Walnut Park Ph 5F | 201512 | 1.47 | 4 | 0.0013083 | 0.01 | 0.02 |
| 376300-Mains - Plastic | 900556 | 3303L | Inst 5130F 2P Walnut Park Ph 5F | 201512 | 19.21 | 4 | 0.0013083 | 0.10 | 0.30 |
| 376300-Mains - Plastic | 900557 | 3303L | Inst 2123F 2P Walnut Park Ph6A | 201509 | (6,622.87) | 7 | 0.0013083 | (51.49) | (88.28) |
| 376300-Mains - Plastic | 900557 | 3303L | Inst 2123F 2P Walnut Park Ph6A | 201509 | (106.47) | 7 | 0.0013083 | (0.98) | (1.67) |
| 376300-Mains - Plastic | 900558 | 3303L | Inst 1859F 2P Walnut Park Ph6B | 201509 | (14,853.41) | 7 | 0.0013083 | (136.12) | (233.35) |
| 376300-Mains - Plastic | 900558 | 3303L | Inst 1859F 2P Walnut Park Ph6B | 201509 | (831.46) | 7 | 0.0013083 | (7.61) | (13.05) |
| 376300-Mains - Plastic | 900558 | 3303L | Inst 1859F 2P Walnut Park Ph6B | 201510 | 1,929.26 | 6 | 0.0013083 | 15.14 | 30.29 |
| 376300-Mains - Plastic | 900558 | 3303L | Inst 1859F 2P Walnut Park Ph6B | 201510 | 107.92 | 6 | 0.0013083 | 0.85 | 1.69 |
| 376300-Mains - Plastic | 900558 | 3303L | Inst 1859F 2P Walnut Park Ph6B | 201511 | 146.48 | 5 | 0.0013083 | 0.96 | 2.30 |
| 376300-Mains - Plastic | 900558 | 3303L | Inst 1859F 2P Walnut Park Ph6B | 201511 | 8.19 | 5 | 0.0013083 | 0.05 | 0.13 |
| 376300-Mains - Plastic | 900558 | 3303L | Inst 1859F 2P Walnut Park Ph6B | 201512 | 0.21 | 4 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900558 | 3303L | Inst 1859F 2P Walnut Park Ph6B | 201512 | 3.97 | 4 | 0.0013083 | 0.02 | 0.06 |
| 376300-Mains - Plastic | 900559 | 3303L | Inst 3875F 2P Walnut Park Ph6C | 201509 | (4,396.29) | 7 | 0.0013083 | (40.26) | (69.02) |
| 376300-Mains - Plastic | 900559 | 3303L | Inst 3875F 2P Walnut Park Ph6C | 201509 | (83.21) | 7 | 0.0013083 | (0.76) | (1.31) |
| 376300-Mains - Plastic | 900559 | 3303L | Inst 3875F 2P Walnut Park Ph6C | 201510 | (421.90) | 6 | 0.0013083 | (3.31) | (6.62) |
| 376300-Mains - Plastic | 900559 | 3303L | Inst 3875F 2P Walnut Park Ph6C | 201510 | (7.98) | 6 | 0.0013083 | (0.06) | (0.13) |
| 376300-Mains - Plastic | 900559 | 3303L | Inst 3875F 2P Walnut Park Ph6C | 201511 | (4,760.06) | 5 | 0.0013083 | (31.14) | (74.73) |
| 376300-Mains - Plastic | 900559 | 3303L | Inst 3875F 2P Walnut Park Ph6C | 201511 | 327.17 | 5 | 0.0013083 | 2.14 | 5.14 |
| 376300-Mains - Plastic | 900559 | 3303L | Inst 3875F 2P Walnut Park Ph6C | 201512 | 52.00 | 4 | 0.0013083 | 0.27 | 0.82 |
| 376300-Mains - Plastic | 900559 | 3303L | Inst 3875F 2P Walnut Park Ph6C | 201512 | 429.47 | 4 | 0.0013083 | 2.25 | 6.74 |
| 376300-Mains - Plastic | 900560 | 3303L | Inst 4705F 2P Walnut Park Ph6D | 201509 | 139,228.54 | 7 | 0.0013083 | 1,275.07 | 2,185.83 |
| 376300-Mains - Plastic | 900560 | 3303L | Inst 4705F 2P Walnut Park Ph6D | 201509 | 7,455.22 | 7 | 0.0013083 | 68.28 | 117.04 |

| | | | | | | | | | |
|------------------------|--------|-------|------------------------------------|--------|-------------|---|-----------|----------|----------|
| 376300-Mains - Plastic | 900560 | 3303L | Inst 4705F 2P Walnut Park Ph6D | 201511 | (322.76) | 5 | 0.0013083 | (2.11) | (5.07) |
| 376300-Mains - Plastic | 900560 | 3303L | Inst 4705F 2P Walnut Park Ph6D | 201511 | (17.27) | 5 | 0.0013083 | (0.11) | (0.27) |
| 376300-Mains - Plastic | 900560 | 3303L | Inst 4705F 2P Walnut Park Ph6D | 201512 | 13.93 | 4 | 0.0013083 | 0.07 | 0.22 |
| 376300-Mains - Plastic | 900560 | 3303L | Inst 4705F 2P Walnut Park Ph6D | 201512 | 260.48 | 4 | 0.0013083 | 1.38 | 4.09 |
| 376300-Mains - Plastic | 900561 | 3303L | Repl w/ 6270F 2P Walnut Park Ph6E | 201511 | 564,972.10 | 5 | 0.0013083 | 3,695.76 | 8,869.84 |
| 376300-Mains - Plastic | 900561 | 3303L | Repl w/ 6270F 2P Walnut Park Ph6E | 201511 | 6,448.21 | 5 | 0.0013083 | 42.18 | 101.23 |
| 376300-Mains - Plastic | 900561 | 3303L | Repl w/ 6270F 2P Walnut Park Ph6E | 201512 | 0.54 | 4 | 0.0013083 | - | 0.01 |
| 376300-Mains - Plastic | 900561 | 3303L | Repl w/ 6270F 2P Walnut Park Ph6E | 201512 | 48.37 | 4 | 0.0013083 | 0.25 | 0.76 |
| 376300-Mains - Plastic | 900585 | 3304L | Inst 8458F 8P 8S Lindell | 201509 | (8,875.68) | 7 | 0.0013083 | (81.28) | (139.34) |
| 376300-Mains - Plastic | 900585 | 3304L | Inst 8458F 8P 8S Lindell | 201509 | (172.61) | 7 | 0.0013083 | (1.58) | (2.71) |
| 376300-Mains - Plastic | 900595 | 3304L | Inst 4616F 8P Alaska | 201509 | (115.42) | 7 | 0.0013083 | (1.06) | (1.81) |
| 376300-Mains - Plastic | 900595 | 3304L | Inst 4616F 8P Alaska | 201509 | (2.74) | 7 | 0.0013083 | (0.03) | (0.04) |
| 376100-Mains - Steel | 900596 | 3304L | Inst 3200F 8P Holly Hills | 201509 | (409.17) | 7 | 0.0012000 | (3.44) | (5.89) |
| 376300-Mains - Plastic | 900596 | 3304L | Inst 3200F 8P Holly Hills | 201509 | (4,915.70) | 7 | 0.0013083 | (45.02) | (77.17) |
| 376300-Mains - Plastic | 900596 | 3304L | Inst 3200F 8P Holly Hills | 201509 | (89.34) | 7 | 0.0013083 | (0.82) | (1.40) |
| 376100-Mains - Steel | 900597 | 3304L | Inst 5626F 12P Lindell | 201509 | (37,594.23) | 7 | 0.0012000 | (315.79) | (541.36) |
| 376300-Mains - Plastic | 900597 | 3304L | Inst 5626F 12P Lindell | 201509 | 25,745.08 | 7 | 0.0013083 | 235.78 | 404.19 |
| 376300-Mains - Plastic | 900597 | 3304L | Inst 5626F 12P Lindell | 201509 | (4,580.55) | 7 | 0.0013083 | (41.95) | (71.91) |
| 376300-Mains - Plastic | 900598 | 3304L | Inst 5746F 8P Winnebago-Gravois | 201509 | (11,230.96) | 7 | 0.0013083 | (102.85) | (176.32) |
| 376300-Mains - Plastic | 900598 | 3304L | Inst 5746F 8P Winnebago-Gravois | 201509 | 151.18 | 7 | 0.0013083 | 1.38 | 2.37 |
| 376300-Mains - Plastic | 900603 | 3303L | Inst 4300F 2P Maplewood Ph2A | 201512 | 8,066.95 | 4 | 0.0013083 | 42.22 | 126.65 |
| 376300-Mains - Plastic | 900603 | 3303L | Inst 4300F 2P Maplewood Ph2A | 201512 | 121,862.63 | 4 | 0.0013083 | 637.73 | 1,913.19 |
| 376300-Mains - Plastic | 900605 | 3303L | Inst 2020F 2P Maplewood Ph 2B | 201512 | 15,771.30 | 4 | 0.0013083 | 82.53 | 247.60 |
| 376300-Mains - Plastic | 900605 | 3303L | Inst 2020F 2P Maplewood Ph 2B | 201512 | 216,813.61 | 4 | 0.0013083 | 1,134.63 | 3,403.89 |
| 376300-Mains - Plastic | 900607 | 3303L | Inst 3183F 2P Maplewood Ph2C | 201509 | 181,653.32 | 7 | 0.0013083 | 1,663.60 | 2,851.88 |
| 376300-Mains - Plastic | 900607 | 3303L | Inst 3183F 2P Maplewood Ph2C | 201509 | 7,357.65 | 7 | 0.0013083 | 67.38 | 115.51 |
| 376300-Mains - Plastic | 900607 | 3303L | Inst 3183F 2P Maplewood Ph2C | 201510 | 7,674.49 | 6 | 0.0013083 | 60.24 | 120.49 |
| 376300-Mains - Plastic | 900607 | 3303L | Inst 3183F 2P Maplewood Ph2C | 201510 | 310.84 | 6 | 0.0013083 | 2.44 | 4.88 |
| 376300-Mains - Plastic | 900607 | 3303L | Inst 3183F 2P Maplewood Ph2C | 201511 | 15,747.37 | 5 | 0.0013083 | 103.01 | 247.23 |
| 376300-Mains - Plastic | 900607 | 3303L | Inst 3183F 2P Maplewood Ph2C | 201511 | 637.81 | 5 | 0.0013083 | 4.17 | 10.01 |
| 376300-Mains - Plastic | 900607 | 3303L | Inst 3183F 2P Maplewood Ph2C | 201512 | 8.18 | 4 | 0.0013083 | 0.04 | 0.13 |
| 376300-Mains - Plastic | 900607 | 3303L | Inst 3183F 2P Maplewood Ph2C | 201512 | 201.92 | 4 | 0.0013083 | 1.06 | 3.17 |
| 376300-Mains - Plastic | 900623 | 3303L | Repl w/ 2852' 2P Wydown Ph 6 | 201509 | (9,527.55) | 7 | 0.0013083 | (87.25) | (149.58) |
| 376300-Mains - Plastic | 900623 | 3303L | Repl w/ 2852' 2P Wydown Ph 6 | 201509 | 1,399.22 | 7 | 0.0013083 | 12.81 | 21.97 |
| 376300-Mains - Plastic | 900625 | 3304L | Inst 4530F 8P Newstead | 201509 | (18,244.96) | 7 | 0.0013083 | (167.09) | (286.44) |
| 376300-Mains - Plastic | 900625 | 3304L | Inst 4530F 8P Newstead | 201509 | (1,083.94) | 7 | 0.0013083 | (9.93) | (17.02) |
| 376300-Mains - Plastic | 900625 | 3304L | Inst 4530F 8P Newstead | 201511 | 14,618.22 | 5 | 0.0013083 | 95.63 | 229.50 |
| 376300-Mains - Plastic | 900625 | 3304L | Inst 4530F 8P Newstead | 201511 | 866.48 | 5 | 0.0013083 | 5.68 | 13.63 |
| 376300-Mains - Plastic | 900625 | 3304L | Inst 4530F 8P Newstead | 201512 | 4,904.39 | 4 | 0.0013083 | 25.67 | 77.00 |
| 376300-Mains - Plastic | 900625 | 3304L | Inst 4530F 8P Newstead | 201512 | 82,551.32 | 4 | 0.0013083 | 432.01 | 1,296.02 |
| 376100-Mains - Steel | 900629 | 3304L | Inst 4820F 8P Kingshighway & McRee | 201509 | (1,976.91) | 7 | 0.0012000 | (16.61) | (28.47) |
| 376300-Mains - Plastic | 900629 | 3304L | Inst 4820F 8P Kingshighway & McRee | 201509 | (6,157.45) | 7 | 0.0013083 | (56.39) | (96.67) |
| 376300-Mains - Plastic | 900629 | 3304L | Inst 4820F 8P Kingshighway & McRee | 201509 | (2,161.37) | 7 | 0.0013083 | (19.79) | (33.93) |
| 376300-Mains - Plastic | 900635 | 3304L | Inst 1228F 8P Manchester | 201509 | (5.48) | 7 | 0.0013083 | (0.05) | (0.09) |
| 376300-Mains - Plastic | 900635 | 3304L | Inst 1228F 8P Manchester | 201509 | (0.04) | 7 | 0.0013083 | - | - |
| 376100-Mains - Steel | 900643 | 3304L | Inst 1801F 6P-12P Marmaduke/Hudler | 201509 | 191.63 | 7 | 0.0012000 | 1.61 | 2.76 |
| 376300-Mains - Plastic | 900643 | 3304L | Inst 1801F 6P-12P Marmaduke/Hudler | 201509 | (13,791.93) | 7 | 0.0013083 | (128.31) | (216.53) |
| 376300-Mains - Plastic | 900643 | 3304L | Inst 1801F 6P-12P Marmaduke/Hudler | 201509 | (7,187.64) | 7 | 0.0013083 | (65.83) | (112.84) |
| 376100-Mains - Steel | 900643 | 3304L | Inst 1801F 6P-12P Marmaduke/Hudler | 201510 | 0.03 | 6 | 0.0012000 | - | - |
| 376300-Mains - Plastic | 900643 | 3304L | Inst 1801F 6P-12P Marmaduke/Hudler | 201510 | 84.18 | 6 | 0.0013083 | 0.66 | 1.32 |
| 376300-Mains - Plastic | 900643 | 3304L | Inst 1801F 6P-12P Marmaduke/Hudler | 201510 | 3.63 | 6 | 0.0013083 | 0.03 | 0.06 |

| | | | | | | | | | |
|------------------------|--------|-------|-----------------------------------|--------|-------------|---|-----------|----------|-----------|
| 376300-Mains - Plastic | 900644 | 3304L | Inst 4190F 8P Evans | 201509 | (1,001.18) | 7 | 0.0013083 | (9.17) | (15.72) |
| 376300-Mains - Plastic | 900644 | 3304L | Inst 4190F 8P Evans | 201509 | (24.86) | 7 | 0.0013083 | (0.23) | (0.39) |
| 376300-Mains - Plastic | 900645 | 3304L | Inst 4690F 8P Vandeventer | 201509 | (4,535.80) | 7 | 0.0013083 | (41.54) | (71.21) |
| 376300-Mains - Plastic | 900645 | 3304L | Inst 4690F 8P Vandeventer | 201509 | (135.37) | 7 | 0.0013083 | (1.24) | (2.13) |
| 376300-Mains - Plastic | 900649 | 3304L | Inst 5308F 8P Manchester Header | 201512 | 44,154.33 | 4 | 0.0013083 | 231.07 | 693.21 |
| 376100-Mains - Steel | 900649 | 3304L | Inst 5308F 8P Manchester Header | 201512 | 75,025.50 | 4 | 0.0012000 | 360.12 | 1,080.37 |
| 376300-Mains - Plastic | 900649 | 3304L | Inst 5308F 8P Manchester Header | 201512 | 641,406.15 | 4 | 0.0013083 | 3,356.61 | 10,069.82 |
| 376300-Mains - Plastic | 900650 | 3303L | Inst 3290F 2P St Louis Hills Ph1A | 201509 | (9,128.55) | 7 | 0.0013083 | (83.60) | (143.31) |
| 376300-Mains - Plastic | 900650 | 3303L | Inst 3290F 2P St Louis Hills Ph1A | 201509 | (388.50) | 7 | 0.0013083 | (3.56) | (6.10) |
| 376300-Mains - Plastic | 900650 | 3303L | Inst 3290F 2P St Louis Hills Ph1A | 201512 | (4,310.42) | 4 | 0.0013083 | (22.56) | (67.67) |
| 376300-Mains - Plastic | 900650 | 3303L | Inst 3290F 2P St Louis Hills Ph1A | 201512 | 5,479.81 | 4 | 0.0013083 | 28.68 | 86.03 |
| 376300-Mains - Plastic | 900652 | 3303L | Inst 4435F 2P St Louis Hills Ph1B | 201509 | (3,756.04) | 7 | 0.0013083 | (34.40) | (58.97) |
| 376300-Mains - Plastic | 900652 | 3303L | Inst 4435F 2P St Louis Hills Ph1B | 201509 | (147.45) | 7 | 0.0013083 | (1.35) | (2.31) |
| 376300-Mains - Plastic | 900652 | 3303L | Inst 4435F 2P St Louis Hills Ph1B | 201511 | (5,589.37) | 5 | 0.0013083 | (36.56) | (87.75) |
| 376300-Mains - Plastic | 900652 | 3303L | Inst 4435F 2P St Louis Hills Ph1B | 201511 | 1,596.32 | 5 | 0.0013083 | 10.44 | 25.06 |
| 376300-Mains - Plastic | 900653 | 3303L | Inst 2636F 2P St Louis Hills Ph1C | 201509 | (1,252.76) | 7 | 0.0013083 | (11.47) | (19.67) |
| 376300-Mains - Plastic | 900653 | 3303L | Inst 2636F 2P St Louis Hills Ph1C | 201509 | (12.78) | 7 | 0.0013083 | (0.12) | (0.20) |
| 376300-Mains - Plastic | 900653 | 3303L | Inst 2636F 2P St Louis Hills Ph1C | 201510 | 128.23 | 6 | 0.0013083 | 1.01 | 2.01 |
| 376300-Mains - Plastic | 900653 | 3303L | Inst 2636F 2P St Louis Hills Ph1C | 201510 | 1.31 | 6 | 0.0013083 | 0.01 | 0.02 |
| 376300-Mains - Plastic | 900653 | 3303L | Inst 2636F 2P St Louis Hills Ph1C | 201511 | (3,418.85) | 5 | 0.0013083 | (22.36) | (53.67) |
| 376300-Mains - Plastic | 900653 | 3303L | Inst 2636F 2P St Louis Hills Ph1C | 201511 | 790.06 | 5 | 0.0013083 | 5.17 | 12.40 |
| 376300-Mains - Plastic | 900653 | 3303L | Inst 2636F 2P St Louis Hills Ph1C | 201512 | 0.05 | 4 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900653 | 3303L | Inst 2636F 2P St Louis Hills Ph1C | 201512 | 3.90 | 4 | 0.0013083 | 0.02 | 0.06 |
| 376300-Mains - Plastic | 900668 | 3304L | Inst 5690F 8P Cora | 201509 | (19.02) | 7 | 0.0013083 | (0.17) | (0.30) |
| 376300-Mains - Plastic | 900668 | 3304L | Inst 5690F 8P Cora | 201509 | (0.93) | 7 | 0.0013083 | (0.01) | (0.01) |
| 376300-Mains - Plastic | 900669 | 3304L | Inst 4565F 8P Page & Evans | 201509 | (7.87) | 7 | 0.0013083 | (0.07) | (0.12) |
| 376300-Mains - Plastic | 900669 | 3304L | Inst 4565F 8P Page & Evans | 201509 | (0.31) | 7 | 0.0013083 | - | - |
| 376100-Mains - Steel | 900677 | 3303L | Repl w/ 1795F 2P Cole & 18th PhA | 201509 | (14,440.02) | 7 | 0.0012000 | (121.30) | (207.94) |
| 376300-Mains - Plastic | 900677 | 3303L | Repl w/ 1795F 2P Cole & 18th PhA | 201509 | 5,824.99 | 7 | 0.0013083 | 53.35 | 91.45 |
| 376300-Mains - Plastic | 900677 | 3303L | Repl w/ 1795F 2P Cole & 18th PhA | 201509 | (3,214.96) | 7 | 0.0013083 | (29.44) | (50.47) |
| 376300-Mains - Plastic | 900679 | 3303L | Inst 2312F 4P Cole & 18th PhB | 201509 | (6,760.02) | 7 | 0.0013083 | (61.91) | (106.13) |
| 376300-Mains - Plastic | 900679 | 3303L | Inst 2312F 4P Cole & 18th PhB | 201509 | (414.06) | 7 | 0.0013083 | (3.79) | (6.50) |
| 376300-Mains - Plastic | 900879 | 3303L | Inst 2312F 4P Cole & 18th PhB | 201511 | (26,817.23) | 5 | 0.0013083 | (175.42) | (421.02) |
| 376300-Mains - Plastic | 900879 | 3303L | Inst 2312F 4P Cole & 18th PhB | 201511 | 22,892.15 | 5 | 0.0013083 | 149.75 | 359.40 |
| 376300-Mains - Plastic | 900881 | 3303L | Inst 1637F 2P Cole & 18th Ph C | 201509 | (15,290.97) | 7 | 0.0013083 | (140.04) | (240.06) |
| 376300-Mains - Plastic | 900881 | 3303L | Inst 1637F 2P Cole & 18th Ph C | 201509 | (899.28) | 7 | 0.0013083 | (8.24) | (14.12) |
| 376300-Mains - Plastic | 900883 | 3303L | Inst 1864F 2P Cole & 18th Ph D | 201509 | (27,232.88) | 7 | 0.0013083 | (249.40) | (427.55) |
| 376300-Mains - Plastic | 900883 | 3303L | Inst 1864F 2P Cole & 18th Ph D | 201509 | (2,098.47) | 7 | 0.0013083 | (19.22) | (32.95) |
| 376300-Mains - Plastic | 900883 | 3303L | Inst 1864F 2P Cole & 18th Ph D | 201510 | 67.70 | 6 | 0.0013083 | 0.53 | 1.06 |
| 376300-Mains - Plastic | 900883 | 3303L | Inst 1864F 2P Cole & 18th Ph D | 201510 | 32.24 | 6 | 0.0013083 | 0.25 | 0.51 |
| 376300-Mains - Plastic | 900883 | 3303L | Inst 1864F 2P Cole & 18th Ph D | 201511 | (0.14) | 5 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900883 | 3303L | Inst 1864F 2P Cole & 18th Ph D | 201511 | (0.01) | 5 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900883 | 3303L | Inst 1864F 2P Cole & 18th Ph D | 201512 | 0.20 | 4 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900883 | 3303L | Inst 1864F 2P Cole & 18th Ph D | 201512 | 3.32 | 4 | 0.0013083 | 0.02 | 0.05 |
| 376300-Mains - Plastic | 900885 | 3303L | Inst 1550F 2P Cole & 18th PhE | 201509 | (2,690.67) | 7 | 0.0013083 | (24.64) | (42.24) |
| 376300-Mains - Plastic | 900885 | 3303L | Inst 1550F 2P Cole & 18th PhE | 201509 | (6,784.32) | 7 | 0.0013083 | (62.13) | (106.51) |
| 376300-Mains - Plastic | 900885 | 3303L | Inst 1550F 2P Cole & 18th PhE | 201510 | 177.37 | 6 | 0.0013083 | 1.39 | 2.78 |
| 376300-Mains - Plastic | 900885 | 3303L | Inst 1550F 2P Cole & 18th PhE | 201510 | 57.77 | 6 | 0.0013083 | 0.45 | 0.91 |
| 376300-Mains - Plastic | 900885 | 3303L | Inst 1550F 2P Cole & 18th PhE | 201511 | (0.25) | 5 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900885 | 3303L | Inst 1550F 2P Cole & 18th PhE | 201511 | (0.02) | 5 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900885 | 3303L | Inst 1550F 2P Cole & 18th PhE | 201512 | 0.22 | 4 | 0.0013083 | - | - |

| | | | | | | | | | |
|------------------------|--------|-------|------------------------------------|--------|-------------|---|-----------|----------|----------|
| 376300-Mains - Plastic | 900685 | 3303L | Inst 1550F 2P Cole & 18th PhE | 201512 | 6.93 | 4 | 0.0013083 | 0.04 | 0.11 |
| 376300-Mains - Plastic | 900687 | 3303L | Inst 1096F 2P Cole & 18th PhF | 201509 | (16,803.86) | 7 | 0.0013083 | (153.89) | (263.81) |
| 376300-Mains - Plastic | 900687 | 3303L | Inst 1096F 2P Cole & 18th PhF | 201509 | 6,235.82 | 7 | 0.0013083 | 57.11 | 97.90 |
| 376300-Mains - Plastic | 900689 | 3303L | Inst 2434F 2P Cole & 18th PhG | 201509 | (27,702.44) | 7 | 0.0013083 | (253.70) | (434.92) |
| 376300-Mains - Plastic | 900689 | 3303L | Inst 2434F 2P Cole & 18th PhG | 201509 | 2,289.38 | 7 | 0.0013083 | 20.78 | 35.63 |
| 376300-Mains - Plastic | 900689 | 3303L | Inst 2434F 2P Cole & 18th PhG | 201510 | (184.17) | 6 | 0.0013083 | (1.45) | (2.89) |
| 376300-Mains - Plastic | 900689 | 3303L | Inst 2434F 2P Cole & 18th PhG | 201510 | (132.64) | 6 | 0.0013083 | (1.04) | (2.08) |
| 376300-Mains - Plastic | 900689 | 3303L | Inst 2434F 2P Cole & 18th PhG | 201511 | 0.43 | 5 | 0.0013083 | - | 0.01 |
| 376300-Mains - Plastic | 900689 | 3303L | Inst 2434F 2P Cole & 18th PhG | 201511 | 0.06 | 5 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900689 | 3303L | Inst 2434F 2P Cole & 18th PhG | 201512 | (48.36) | 4 | 0.0013083 | (0.25) | (0.76) |
| 376300-Mains - Plastic | 900689 | 3303L | Inst 2434F 2P Cole & 18th PhG | 201512 | (27.20) | 4 | 0.0013083 | (0.14) | (0.43) |
| 376300-Mains - Plastic | 900691 | 3303L | Repl w/ 3458F 2P Cole & 18th Ph H | 201509 | 768.31 | 7 | 0.0013083 | 7.04 | 12.06 |
| 376300-Mains - Plastic | 900691 | 3303L | Repl w/ 3458F 2P Cole & 18th Ph H | 201509 | 1,084.60 | 7 | 0.0013083 | 9.93 | 17.03 |
| 376300-Mains - Plastic | 900691 | 3303L | Repl w/ 3458F 2P Cole & 18th Ph H | 201510 | 2,874.34 | 6 | 0.0013083 | 22.56 | 45.13 |
| 376300-Mains - Plastic | 900691 | 3303L | Repl w/ 3458F 2P Cole & 18th Ph H | 201510 | 1,551.80 | 6 | 0.0013083 | 12.18 | 24.36 |
| 376300-Mains - Plastic | 900691 | 3303L | Repl w/ 3458F 2P Cole & 18th Ph H | 201511 | (79.98) | 5 | 0.0013083 | (0.52) | (1.26) |
| 376300-Mains - Plastic | 900691 | 3303L | Repl w/ 3458F 2P Cole & 18th Ph H | 201511 | (2.11) | 5 | 0.0013083 | (0.01) | (0.03) |
| 376300-Mains - Plastic | 900691 | 3303L | Repl w/ 3458F 2P Cole & 18th Ph H | 201512 | 1,591.73 | 4 | 0.0013083 | 8.33 | 24.99 |
| 376300-Mains - Plastic | 900691 | 3303L | Repl w/ 3458F 2P Cole & 18th Ph H | 201512 | 9,523.08 | 4 | 0.0013083 | 49.84 | 149.51 |
| 376300-Mains - Plastic | 900692 | 3304L | Inst 3834F 8P Lindell | 201509 | (167.06) | 7 | 0.0013083 | (1.53) | (2.62) |
| 376300-Mains - Plastic | 900692 | 3304L | Inst 3834F 8P Lindell | 201509 | (23.89) | 7 | 0.0013083 | (0.22) | (0.38) |
| 376100-Mains - Steel | 900709 | 3304L | Repl w/ 2662F 8P Natural Bridge | 201509 | (617.58) | 7 | 0.0012000 | (5.19) | (8.89) |
| 376300-Mains - Plastic | 900709 | 3304L | Repl w/ 2662F 8P Natural Bridge | 201509 | (9,906.95) | 7 | 0.0013083 | (90.73) | (155.54) |
| 376300-Mains - Plastic | 900709 | 3304L | Repl w/ 2662F 8P Natural Bridge | 201509 | 2,196.70 | 7 | 0.0013083 | 20.12 | 34.49 |
| 376100-Mains - Steel | 900709 | 3304L | Repl w/ 2662F 8P Natural Bridge | 201510 | (14.12) | 6 | 0.0012000 | (0.10) | (0.20) |
| 376300-Mains - Plastic | 900709 | 3304L | Repl w/ 2662F 8P Natural Bridge | 201510 | (333.38) | 6 | 0.0013083 | (2.62) | (5.23) |
| 376300-Mains - Plastic | 900709 | 3304L | Repl w/ 2662F 8P Natural Bridge | 201510 | (6.63) | 6 | 0.0013083 | (0.05) | (0.10) |
| 376300-Mains - Plastic | 900711 | 3304L | Inst 4010F 8P Natural Bridge | 201509 | (36,871.02) | 7 | 0.0013083 | (337.67) | (578.86) |
| 376300-Mains - Plastic | 900711 | 3304L | Inst 4010F 8P Natural Bridge | 201509 | 19,345.99 | 7 | 0.0013083 | 177.17 | 303.72 |
| 376300-Mains - Plastic | 900713 | 3304L | Inst 4816F 8P Penrod & Sulphur | 201509 | (5,881.60) | 7 | 0.0013083 | (53.86) | (92.34) |
| 376300-Mains - Plastic | 900713 | 3304L | Inst 4816F 8P Penrod & Sulphur | 201509 | (207.96) | 7 | 0.0013083 | (1.90) | (3.26) |
| 376300-Mains - Plastic | 900734 | 3303L | Repl w/ 1717F 2P Hurck | 201509 | (4,653.97) | 7 | 0.0013083 | (42.62) | (73.07) |
| 376300-Mains - Plastic | 900734 | 3303L | Repl w/ 1717F 2P Hurck | 201509 | (251.65) | 7 | 0.0013083 | (2.30) | (3.95) |
| 376300-Mains - Plastic | 900734 | 3303L | Repl w/ 1717F 2P Hurck | 201510 | 35.99 | 6 | 0.0013083 | 0.28 | 0.57 |
| 376300-Mains - Plastic | 900734 | 3303L | Repl w/ 1717F 2P Hurck | 201510 | 1.94 | 6 | 0.0013083 | 0.02 | 0.03 |
| 376300-Mains - Plastic | 900734 | 3303L | Repl w/ 1717F 2P Hurck | 201511 | (2,398.57) | 5 | 0.0013083 | (15.69) | (37.66) |
| 376300-Mains - Plastic | 900734 | 3303L | Repl w/ 1717F 2P Hurck | 201511 | 405.71 | 5 | 0.0013083 | 2.65 | 6.37 |
| 376300-Mains - Plastic | 900734 | 3303L | Repl w/ 1717F 2P Hurck | 201512 | 31.18 | 4 | 0.0013083 | 0.16 | 0.49 |
| 376300-Mains - Plastic | 900734 | 3303L | Repl w/ 1717F 2P Hurck | 201512 | 152.43 | 4 | 0.0013083 | 0.80 | 2.39 |
| 376300-Mains - Plastic | 900738 | 3303L | Repl w/ 780F 2P Kingsland MSD | 201509 | (1,359.61) | 7 | 0.0013083 | (12.45) | (21.35) |
| 376300-Mains - Plastic | 900738 | 3303L | Repl w/ 780F 2P Kingsland MSD | 201509 | (113.02) | 7 | 0.0013083 | (1.04) | (1.77) |
| 376300-Mains - Plastic | 900738 | 3303L | Repl w/ 780F 2P Kingsland MSD | 201511 | (392.60) | 5 | 0.0013083 | (2.57) | (6.16) |
| 376300-Mains - Plastic | 900738 | 3303L | Repl w/ 780F 2P Kingsland MSD | 201511 | 18.62 | 5 | 0.0013083 | 0.12 | 0.29 |
| 376300-Mains - Plastic | 900738 | 3303L | Repl w/ 780F 2P Kingsland MSD | 201512 | 1.52 | 4 | 0.0013083 | 0.01 | 0.02 |
| 376300-Mains - Plastic | 900738 | 3303L | Repl w/ 780F 2P Kingsland MSD | 201512 | 18.40 | 4 | 0.0013083 | 0.10 | 0.29 |
| 376300-Mains - Plastic | 900759 | 3303L | Repl w/ 2836F 2P Hickory Dale | 201509 | (17,053.03) | 7 | 0.0013083 | (156.17) | (267.73) |
| 376300-Mains - Plastic | 900759 | 3303L | Repl w/ 2836F 2P Hickory Dale | 201510 | 30.74 | 6 | 0.0013083 | 0.24 | 0.48 |
| 376300-Mains - Plastic | 900762 | 3303L | Inst 2069F 2P Earthquake Zone Ph1A | 201509 | (3,072.69) | 7 | 0.0013083 | (28.14) | (48.24) |
| 376300-Mains - Plastic | 900762 | 3303L | Inst 2069F 2P Earthquake Zone Ph1A | 201509 | (102.65) | 7 | 0.0013083 | (0.94) | (1.61) |
| 376300-Mains - Plastic | 900763 | 3303L | Inst 3508F 2P Earthquake Zone Ph1B | 201509 | 20,488.93 | 7 | 0.0013083 | 187.64 | 321.67 |
| 376300-Mains - Plastic | 900763 | 3303L | Inst 3508F 2P Earthquake Zone Ph1B | 201509 | (14,166.62) | 7 | 0.0013083 | (129.74) | (222.41) |

| | | | | | | | | | |
|------------------------|--------|-------|-------------------------------------|--------|-------------|---|-----------|----------|------------|
| 376300-Mains - Plastic | 900764 | 3303L | Repl w/758F 2P Earthquake Zone Ph1C | 201509 | 22,173.79 | 7 | 0.0013083 | 203.07 | 348.12 |
| 376300-Mains - Plastic | 900764 | 3303L | Repl w/758F 2P Earthquake Zone Ph1C | 201509 | 1,617.46 | 7 | 0.0013083 | 14.81 | 25.39 |
| 376300-Mains - Plastic | 900764 | 3303L | Repl w/758F 2P Earthquake Zone Ph1C | 201510 | 23.44 | 6 | 0.0013083 | 0.18 | 0.37 |
| 376300-Mains - Plastic | 900764 | 3303L | Repl w/758F 2P Earthquake Zone Ph1C | 201510 | 2.06 | 6 | 0.0013083 | 0.02 | 0.03 |
| 376300-Mains - Plastic | 900765 | 3303L | Inst 1899F 4P Earthquake Zone Ph1D | 201509 | (27,340.10) | 7 | 0.0013083 | (250.38) | (429.23) |
| 376300-Mains - Plastic | 900765 | 3303L | Inst 1899F 4P Earthquake Zone Ph1D | 201509 | (713.99) | 7 | 0.0013083 | (6.54) | (11.21) |
| 376300-Mains - Plastic | 900780 | 3304L | Inst 2180F 6P Union Header Main | 201509 | (4,941.69) | 7 | 0.0013083 | (45.26) | (77.58) |
| 376300-Mains - Plastic | 900780 | 3304L | Inst 2180F 6P Union Header Main | 201509 | (282.64) | 7 | 0.0013083 | (2.59) | (4.44) |
| 376300-Mains - Plastic | 900780 | 3304L | Inst 2180F 6P Union Header Main | 201511 | (68.45) | 5 | 0.0013083 | (0.45) | (1.07) |
| 376300-Mains - Plastic | 900780 | 3304L | Inst 2180F 6P Union Header Main | 201511 | 68.45 | 5 | 0.0013083 | 0.45 | 1.07 |
| 376300-Mains - Plastic | 900786 | 3304L | Inst 6713F 8P Chippewa & Tholozan | 201509 | (18,763.45) | 7 | 0.0013083 | (171.84) | (294.58) |
| 376300-Mains - Plastic | 900786 | 3304L | Inst 6713F 8P Chippewa & Tholozan | 201509 | (210.67) | 7 | 0.0013083 | (1.93) | (3.31) |
| 376300-Mains - Plastic | 900787 | 3304L | Inst 4235F 8P Beck Ave | 201509 | (19,996.85) | 7 | 0.0013083 | (183.13) | (313.94) |
| 376300-Mains - Plastic | 900787 | 3304L | Inst 4235F 8P Beck Ave | 201509 | 6,066.68 | 7 | 0.0013083 | 55.56 | 95.24 |
| 376300-Mains - Plastic | 900789 | 3304L | Inst 3104F 8P Hampton Header | 201509 | (9,094.42) | 7 | 0.0013083 | (83.29) | (142.78) |
| 376300-Mains - Plastic | 900789 | 3304L | Inst 3104F 8P Hampton Header | 201509 | (271.71) | 7 | 0.0013083 | (2.49) | (4.27) |
| 376300-Mains - Plastic | 900789 | 3304L | Inst 3104F 8P Hampton Header | 201510 | 896.19 | 6 | 0.0013083 | 7.03 | 14.07 |
| 376300-Mains - Plastic | 900789 | 3304L | Inst 3104F 8P Hampton Header | 201510 | 26.76 | 6 | 0.0013083 | 0.21 | 0.42 |
| 376300-Mains - Plastic | 900789 | 3304L | Inst 3104F 8P Hampton Header | 201511 | 478.73 | 5 | 0.0013083 | 3.13 | 7.52 |
| 376300-Mains - Plastic | 900789 | 3304L | Inst 3104F 8P Hampton Header | 201511 | (480.00) | 5 | 0.0013083 | (3.14) | (7.54) |
| 376300-Mains - Plastic | 900789 | 3304L | Inst 3104F 8P Hampton Header | 201512 | 0.97 | 4 | 0.0013083 | 0.01 | 0.02 |
| 376300-Mains - Plastic | 900789 | 3304L | Inst 3104F 8P Hampton Header | 201512 | 29.72 | 4 | 0.0013083 | 0.16 | 0.47 |
| 376300-Mains - Plastic | 900823 | 3303L | Repl w/ 659F 2P Baden Ph6A | 201509 | (805.24) | 7 | 0.0013083 | (7.37) | (12.64) |
| 376300-Mains - Plastic | 900823 | 3303L | Repl w/ 659F 2P Baden Ph6A | 201509 | (112.58) | 7 | 0.0013083 | (1.03) | (1.77) |
| 376300-Mains - Plastic | 900830 | 3303L | Repl w/ 5F 8P Florissant | 201509 | (12.65) | 7 | 0.0013083 | (0.12) | (0.20) |
| 376300-Mains - Plastic | 900830 | 3303L | Repl w/ 5F 8P Florissant | 201509 | (1.28) | 7 | 0.0013083 | (0.01) | (0.02) |
| 376300-Mains - Plastic | 900849 | 3304L | Inst 850F 12P Whittier Header | 201509 | (3,389.13) | 7 | 0.0013083 | (31.04) | (53.21) |
| 376300-Mains - Plastic | 900849 | 3304L | Inst 850F 12P Whittier Header | 201509 | (898.89) | 7 | 0.0013083 | (8.23) | (14.11) |
| 376300-Mains - Plastic | 900859 | 3303L | Repl w/ 290F 2P Cabanne | 201509 | (1,062.84) | 7 | 0.0013083 | (9.73) | (16.69) |
| 376300-Mains - Plastic | 900859 | 3303L | Repl w/ 290F 2P Cabanne | 201509 | (44.62) | 7 | 0.0013083 | (0.41) | (0.70) |
| 376300-Mains - Plastic | 900859 | 3303L | Repl w/ 290F 2P Cabanne | 201510 | 12.05 | 6 | 0.0013083 | 0.09 | 0.19 |
| 376300-Mains - Plastic | 900859 | 3303L | Repl w/ 290F 2P Cabanne | 201510 | 1.70 | 6 | 0.0013083 | 0.01 | 0.03 |
| 376300-Mains - Plastic | 900861 | 3303L | Repl w/ 105F 4P McLaran | 201509 | (165.10) | 7 | 0.0013083 | (1.51) | (2.59) |
| 376300-Mains - Plastic | 900861 | 3303L | Repl w/ 105F 4P McLaran | 201509 | (5.54) | 7 | 0.0013083 | (0.05) | (0.09) |
| 376300-Mains - Plastic | 900862 | 3303L | Rep w/ 4552F 2P Broadway AOR | 201509 | (77,130.19) | 7 | 0.0013083 | (706.37) | (1,210.91) |
| 376300-Mains - Plastic | 900862 | 3303L | Rep w/ 4552F 2P Broadway AOR | 201509 | 15,147.92 | 7 | 0.0013083 | 138.73 | 237.82 |
| 376300-Mains - Plastic | 900862 | 3303L | Repl w/ 4552F 2P Broadway AOR | 201510 | (8.69) | 6 | 0.0013083 | (0.07) | (0.14) |
| 376300-Mains - Plastic | 900862 | 3303L | Repl w/ 4552F 2P Broadway AOR | 201510 | (114.20) | 6 | 0.0013083 | (0.90) | (1.79) |
| 376300-Mains - Plastic | 900862 | 3303L | Repl w/ 4552F 2P Broadway AOR | 201511 | 0.15 | 5 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900862 | 3303L | Repl w/ 4552F 2P Broadway AOR | 201511 | (0.02) | 5 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900862 | 3303L | Repl w/ 4552F 2P Broadway AOR | 201512 | (7.27) | 4 | 0.0013083 | (0.04) | (0.11) |
| 376300-Mains - Plastic | 900862 | 3303L | Repl w/ 4552F 2P Broadway AOR | 201512 | (1.00) | 4 | 0.0013083 | (0.01) | (0.02) |
| 376300-Mains - Plastic | 900871 | 3303L | Repl w/ 3201F 2P Baden Ph6F | 201512 | 3,992.84 | 4 | 0.0013083 | 20.90 | 62.69 |
| 376300-Mains - Plastic | 900871 | 3303L | Repl w/ 3201F 2P Baden Ph6F | 201512 | 248,451.55 | 4 | 0.0013083 | 1,300.20 | 3,900.59 |
| 376300-Mains - Plastic | 900873 | 3303L | Repl w/ 538F 2P Longacre | 201509 | (1,321.76) | 7 | 0.0013083 | (12.10) | (20.75) |
| 376300-Mains - Plastic | 900873 | 3303L | Repl w/ 538F 2P Longacre | 201509 | (78.05) | 7 | 0.0013083 | (0.71) | (1.23) |
| 376300-Mains - Plastic | 900873 | 3303L | Repl w/ 538F 2P Longacre | 201510 | 13,315.54 | 6 | 0.0013083 | 104.52 | 209.05 |
| 376300-Mains - Plastic | 900873 | 3303L | Repl w/ 538F 2P Longacre | 201510 | 786.24 | 6 | 0.0013083 | 6.17 | 12.34 |
| 376300-Mains - Plastic | 900876 | 3303L | Repl w/ 1060F 2P Rauschenbach PVC | 201509 | (1,774.32) | 7 | 0.0013083 | (18.25) | (27.86) |
| 376300-Mains - Plastic | 900876 | 3303L | Repl w/ 1060F 2P Rauschenbach PVC | 201509 | (27.80) | 7 | 0.0013083 | (0.25) | (0.44) |
| 376300-Mains - Plastic | 900876 | 3303L | Repl w/ 1060F 2P Rauschenbach PVC | 201510 | 1,218.32 | 6 | 0.0013083 | 9.56 | 19.13 |

| | | | | | | | | | |
|------------------------|--------|-------|-----------------------------------|--------|--------------|---|-----------|------------|------------|
| 376300-Mains - Plastic | 900876 | 3303L | Repl w/ 1060F 2P Rauschenbach PVC | 201510 | 19.09 | 6 | 0.0013083 | 0.15 | 0.30 |
| 376300-Mains - Plastic | 900876 | 3303L | Repl w/ 1060F 2P Rauschenbach PVC | 201511 | (0.93) | 5 | 0.0013083 | (0.01) | (0.01) |
| 376300-Mains - Plastic | 900876 | 3303L | Repl w/ 1060F 2P Rauschenbach PVC | 201511 | (0.02) | 5 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900876 | 3303L | Repl w/ 1060F 2P Rauschenbach PVC | 201512 | (6,247.79) | 4 | 0.0013083 | (32.70) | (98.09) |
| 376300-Mains - Plastic | 900876 | 3303L | Repl w/ 1060F 2P Rauschenbach PVC | 201512 | 29.98 | 4 | 0.0013083 | 0.16 | 0.47 |
| 376300-Mains - Plastic | 900890 | 3303L | Repl w/ 2218F 2P Russell & Flora | 201509 | (153,825.96) | 7 | 0.0013083 | (1,408.75) | (2,415.01) |
| 376300-Mains - Plastic | 900890 | 3303L | Repl w/ 2218F 2P Russell & Flora | 201509 | (1,147.20) | 7 | 0.0013083 | (10.51) | (18.01) |
| 376300-Mains - Plastic | 900890 | 3303L | Repl w/ 2218F 2P Russell & Flora | 201510 | 61.50 | 6 | 0.0013083 | 0.48 | 0.97 |
| 376300-Mains - Plastic | 900890 | 3303L | Repl w/ 2218F 2P Russell & Flora | 201510 | 1.83 | 6 | 0.0013083 | 0.01 | 0.03 |
| 376300-Mains - Plastic | 900893 | 3303L | Repl w/ 2486F 6P Arlington | 201509 | (4,442.05) | 7 | 0.0013083 | (40.68) | (69.74) |
| 376300-Mains - Plastic | 900893 | 3303L | Repl w/ 2486F 6P Arlington | 201509 | (319.29) | 7 | 0.0013083 | (2.92) | (5.01) |
| 376300-Mains - Plastic | 900893 | 3303L | Repl w/ 2486F 6P Arlington | 201511 | (4,163.64) | 5 | 0.0013083 | (27.24) | (65.37) |
| 376300-Mains - Plastic | 900893 | 3303L | Repl w/ 2486F 6P Arlington | 201511 | 4,734.79 | 5 | 0.0013083 | 30.97 | 74.33 |
| 376300-Mains - Plastic | 900893 | 3303L | Repl w/ 2486F 6P Arlington | 201512 | (1,007.99) | 4 | 0.0013083 | (5.28) | (15.83) |
| 376300-Mains - Plastic | 900893 | 3303L | Repl w/ 2486F 6P Arlington | 201512 | (21.91) | 4 | 0.0013083 | (0.11) | (0.34) |
| 376300-Mains - Plastic | 900895 | 3303L | Repl w/ 828F 2P Marquette | 201509 | 22,993.48 | 7 | 0.0013083 | 210.58 | 360.99 |
| 376300-Mains - Plastic | 900895 | 3303L | Repl w/ 828F 2P Marquette | 201509 | 2,456.35 | 7 | 0.0013083 | 22.51 | 38.60 |
| 376300-Mains - Plastic | 900895 | 3303L | Repl w/ 828F 2P Marquette | 201510 | (232.20) | 6 | 0.0013083 | (1.82) | (3.65) |
| 376300-Mains - Plastic | 900895 | 3303L | Repl w/ 828F 2P Marquette | 201510 | 5.79 | 6 | 0.0013083 | 0.05 | 0.09 |
| 376300-Mains - Plastic | 900895 | 3303L | Repl w/ 828F 2P Marquette | 201512 | (15.88) | 4 | 0.0013083 | (0.08) | (0.25) |
| 376300-Mains - Plastic | 900895 | 3303L | Repl w/ 828F 2P Marquette | 201512 | (10.68) | 4 | 0.0013083 | (0.06) | (0.17) |
| 376300-Mains - Plastic | 900896 | 3303L | Repl w/ 2990F 2P 4P Maple | 201509 | (3,391.46) | 7 | 0.0013083 | (31.06) | (53.24) |
| 376300-Mains - Plastic | 900896 | 3303L | Repl w/ 2990F 2P 4P Maple | 201509 | (160.01) | 7 | 0.0013083 | (1.47) | (2.51) |
| 376300-Mains - Plastic | 900896 | 3303L | Repl w/ 2990F 2P 4P Maple | 201510 | 379.02 | 6 | 0.0013083 | 2.98 | 5.95 |
| 376300-Mains - Plastic | 900896 | 3303L | Repl w/ 2990F 2P 4P Maple | 201510 | 17.90 | 6 | 0.0013083 | 0.14 | 0.28 |
| 376300-Mains - Plastic | 900896 | 3303L | Repl w/ 2990F 2P 4P Maple | 201511 | (2,811.35) | 5 | 0.0013083 | (18.39) | (44.14) |
| 376300-Mains - Plastic | 900896 | 3303L | Repl w/ 2990F 2P 4P Maple | 201511 | 789.25 | 5 | 0.0013083 | 5.16 | 12.39 |
| 376300-Mains - Plastic | 900896 | 3303L | Repl w/ 2990F 2P 4P Maple | 201512 | (369.18) | 4 | 0.0013083 | (1.93) | (5.80) |
| 376300-Mains - Plastic | 900896 | 3303L | Repl w/ 2990F 2P 4P Maple | 201512 | (9.99) | 4 | 0.0013083 | (0.05) | (0.16) |
| 376300-Mains - Plastic | 900897 | 3303L | Repl w/ 587F 2P Syracuse | 201509 | 2,783.36 | 7 | 0.0013083 | 25.49 | 43.70 |
| 376300-Mains - Plastic | 900897 | 3303L | Repl w/ 587F 2P Syracuse | 201511 | (1,132.63) | 5 | 0.0013083 | (7.41) | (17.78) |
| 376300-Mains - Plastic | 900897 | 3303L | Repl w/ 587F 2P Syracuse | 201512 | (315.11) | 4 | 0.0013083 | (1.65) | (4.95) |
| 376300-Mains - Plastic | 900898 | 3303L | Repl w/ 1220F 2P Ohio | 201509 | 19,719.80 | 7 | 0.0013083 | 180.60 | 309.59 |
| 376300-Mains - Plastic | 900898 | 3303L | Repl w/ 1220F 2P Ohio | 201509 | 2,579.92 | 7 | 0.0013083 | 23.63 | 40.50 |
| 376300-Mains - Plastic | 900898 | 3303L | Repl w/ 1220F 2P Ohio | 201510 | (13.58) | 6 | 0.0013083 | (0.11) | (0.21) |
| 376300-Mains - Plastic | 900898 | 3303L | Repl w/ 1220F 2P Ohio | 201510 | 1.62 | 6 | 0.0013083 | 0.01 | 0.03 |
| 376300-Mains - Plastic | 900900 | 3303L | Repl w/ 1075F 2P Washington | 201509 | 1,690.84 | 7 | 0.0013083 | 15.48 | 26.55 |
| 376300-Mains - Plastic | 900900 | 3303L | Repl w/ 1075F 2P Washington | 201509 | 7,070.73 | 7 | 0.0013083 | 64.75 | 111.01 |
| 376300-Mains - Plastic | 900900 | 3303L | Repl w/ 1075F 2P Washington | 201510 | 53.62 | 6 | 0.0013083 | 0.42 | 0.84 |
| 376300-Mains - Plastic | 900900 | 3303L | Repl w/ 1075F 2P Washington | 201510 | 7.67 | 6 | 0.0013083 | 0.06 | 0.12 |
| 376300-Mains - Plastic | 900902 | 3303L | Repl w/ 530' 2P Oakland | 201509 | (1,569.92) | 7 | 0.0013083 | (14.38) | (24.65) |
| 376300-Mains - Plastic | 900902 | 3303L | Repl w/ 530' 2P Oakland | 201509 | (3,524.82) | 7 | 0.0013083 | (32.28) | (55.34) |
| 376300-Mains - Plastic | 900902 | 3303L | Repl w/ 530' 2P Oakland | 201510 | (466.36) | 6 | 0.0013083 | (3.66) | (7.32) |
| 376300-Mains - Plastic | 900902 | 3303L | Repl w/ 530' 2P Oakland | 201510 | (4.12) | 6 | 0.0013083 | (0.03) | (0.06) |
| 376300-Mains - Plastic | 900905 | 3303L | Repl w/ 806F 2P Utah | 201509 | 5,653.63 | 7 | 0.0013083 | 51.78 | 88.76 |
| 376300-Mains - Plastic | 900905 | 3303L | Repl w/ 806F 2P Utah | 201509 | (1,503.84) | 7 | 0.0013083 | (13.77) | (23.61) |
| 376300-Mains - Plastic | 900905 | 3303L | Repl w/ 806F 2P Utah | 201510 | 11.12 | 6 | 0.0013083 | 0.09 | 0.17 |
| 376300-Mains - Plastic | 900905 | 3303L | Repl w/ 806F 2P Utah | 201510 | 0.05 | 6 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900908 | 3303L | Repl w/ 460F 2P California | 201509 | (641.99) | 7 | 0.0013083 | (4.96) | (8.51) |
| 376300-Mains - Plastic | 900908 | 3303L | Repl w/ 460F 2P California | 201509 | (20.72) | 7 | 0.0013083 | (0.19) | (0.33) |

| | | | | | | | | | |
|------------------------|--------|-------|-------------------------------------|--------|-------------|---|-----------|----------|------------|
| 376300-Mains - Plastic | 900908 | 3303L | Repl w/ 460F 2P California | 201510 | 7.16 | 6 | 0.0013083 | 0.06 | 0.11 |
| 376300-Mains - Plastic | 900908 | 3303L | Repl w/ 460F 2P California | 201510 | 0.78 | 6 | 0.0013083 | 0.01 | 0.01 |
| 376300-Mains - Plastic | 900912 | 3303L | Repl w/ 745F 2P Shaw | 201509 | (2,144.45) | 7 | 0.0013083 | (19.64) | (33.67) |
| 376300-Mains - Plastic | 900912 | 3303L | Repl w/ 745F 2P Shaw | 201509 | (81.48) | 7 | 0.0013083 | (0.75) | (1.28) |
| 376300-Mains - Plastic | 900912 | 3303L | Repl w/ 745F 2P Shaw | 201510 | 32.31 | 6 | 0.0013083 | 0.25 | 0.51 |
| 376300-Mains - Plastic | 900912 | 3303L | Repl w/ 745F 2P Shaw | 201510 | 0.84 | 6 | 0.0013083 | 0.01 | 0.01 |
| 376300-Mains - Plastic | 900921 | 3303L | Repl w/ 2457F 4P&2P Flad AOR | 201509 | (5,504.14) | 7 | 0.0013083 | (50.41) | (86.41) |
| 376300-Mains - Plastic | 900921 | 3303L | Repl w/ 2457F 4P&2P Flad AOR | 201509 | 178.37 | 7 | 0.0013083 | 1.63 | 2.80 |
| 376300-Mains - Plastic | 900921 | 3303L | Repl w/ 2457F 4P&2P Flad AOR | 201510 | 4,089.37 | 6 | 0.0013083 | 32.10 | 64.20 |
| 376300-Mains - Plastic | 900921 | 3303L | Repl w/ 2457F 4P&2P Flad AOR | 201510 | 195.60 | 6 | 0.0013083 | 1.54 | 3.07 |
| 376300-Mains - Plastic | 900923 | 3303L | Repl w/ 54F 6P West Florissant | 201511 | 58,748.33 | 5 | 0.0013083 | 384.30 | 922.33 |
| 376300-Mains - Plastic | 900923 | 3303L | Repl w/ 54F 6P West Florissant | 201511 | 4,888.86 | 5 | 0.0013083 | 31.98 | 76.75 |
| 376300-Mains - Plastic | 900923 | 3303L | Repl w/ 54F 6P West Florissant | 201512 | 2.23 | 4 | 0.0013083 | 0.01 | 0.04 |
| 376300-Mains - Plastic | 900923 | 3303L | Repl w/ 54F 6P West Florissant | 201512 | 26.65 | 4 | 0.0013083 | 0.14 | 0.42 |
| 376300-Mains - Plastic | 900932 | 3303L | Repl w/ 160F 2P Cler Ave | 201509 | (144.18) | 7 | 0.0013083 | (1.32) | (2.26) |
| 376300-Mains - Plastic | 900932 | 3303L | Repl w/ 160F 2P Cler Ave | 201509 | (2.65) | 7 | 0.0013083 | (0.02) | (0.04) |
| 376300-Mains - Plastic | 900945 | 3304L | Inst 3920F 8P Hampton&Sulpher Headr | 201509 | (10,876.19) | 7 | 0.0013083 | (99.61) | (170.75) |
| 376300-Mains - Plastic | 900945 | 3304L | Inst 3920F 8P Hampton&Sulpher Headr | 201509 | (840.11) | 7 | 0.0013083 | (7.69) | (13.19) |
| 376300-Mains - Plastic | 900945 | 3304L | Inst 3920F 8P Hampton&Sulpher Headr | 201510 | 404.39 | 6 | 0.0013083 | 3.17 | 6.35 |
| 376300-Mains - Plastic | 900945 | 3304L | Inst 3920F 8P Hampton&Sulpher Headr | 201510 | 31.23 | 6 | 0.0013083 | 0.25 | 0.49 |
| 376300-Mains - Plastic | 900945 | 3304L | Inst 3920F 8P Hampton&Sulpher Headr | 201511 | (2,800.39) | 5 | 0.0013083 | (18.32) | (43.97) |
| 376300-Mains - Plastic | 900945 | 3304L | Inst 3920F 8P Hampton&Sulpher Headr | 201511 | 2,799.80 | 5 | 0.0013083 | 18.31 | 43.96 |
| 376300-Mains - Plastic | 900945 | 3304L | Inst 3920F 8P Hampton&Sulpher Headr | 201512 | 1.14 | 4 | 0.0013083 | 0.01 | 0.02 |
| 376300-Mains - Plastic | 900945 | 3304L | Inst 3920F 8P Hampton&Sulpher Headr | 201512 | 13.32 | 4 | 0.0013083 | 0.07 | 0.21 |
| 376300-Mains - Plastic | 900948 | 3303L | Repl w/ 132F 2P Southcote | 201509 | (960.68) | 7 | 0.0013083 | (8.80) | (15.08) |
| 376300-Mains - Plastic | 900948 | 3303L | Repl w/ 132F 2P Southcote | 201510 | 3.58 | 6 | 0.0013083 | 0.03 | 0.06 |
| 376300-Mains - Plastic | 900952 | 3303L | Repl w/ 2606F 2P Clifton Heights-1B | 201512 | 14,963.94 | 4 | 0.0013083 | 78.31 | 234.93 |
| 376300-Mains - Plastic | 900952 | 3303L | Repl w/ 2606F 2P Clifton Heights-1B | 201512 | 295,611.05 | 4 | 0.0013083 | 1,546.99 | 4,640.98 |
| 376300-Mains - Plastic | 900962 | 3304L | Inst 5842F 6P 4P Newstead -Header | 201509 | (9,276.64) | 7 | 0.0013083 | (84.96) | (145.64) |
| 376300-Mains - Plastic | 900962 | 3304L | Inst 5842F 6P 4P Newstead -Header | 201509 | (2,837.00) | 7 | 0.0013083 | (25.98) | (44.54) |
| 376300-Mains - Plastic | 900962 | 3304L | Inst 5842F 6P 4P Newstead -Header | 201511 | (8,923.52) | 5 | 0.0013083 | (58.37) | (140.10) |
| 376300-Mains - Plastic | 900962 | 3304L | Inst 5842F 6P 4P Newstead -Header | 201511 | 8,923.52 | 5 | 0.0013083 | 58.37 | 140.10 |
| 376300-Mains - Plastic | 900977 | 3303L | Repl w/ 1291F 4P Boyle | 201509 | 454.79 | 7 | 0.0013083 | 4.17 | 7.14 |
| 376300-Mains - Plastic | 900977 | 3303L | Repl w/ 1291F 4P Boyle | 201509 | 39.00 | 7 | 0.0013083 | 0.36 | 0.61 |
| 376300-Mains - Plastic | 900978 | 3304L | Inst 3875F 8P Brannon Ave-Header | 201509 | 18,953.48 | 7 | 0.0013083 | 173.58 | 297.56 |
| 376300-Mains - Plastic | 900978 | 3304L | Inst 3875F 8P Brannon Ave-Header | 201509 | 1,380.98 | 7 | 0.0013083 | 12.65 | 21.68 |
| 376300-Mains - Plastic | 900978 | 3304L | Inst 3875F 8P Brannon Ave-Header | 201510 | 556.72 | 6 | 0.0013083 | 4.37 | 8.74 |
| 376300-Mains - Plastic | 900978 | 3304L | Inst 3875F 8P Brannon Ave-Header | 201510 | 40.56 | 6 | 0.0013083 | 0.32 | 0.64 |
| 376300-Mains - Plastic | 900978 | 3304L | Inst 3875F 8P Brannon Ave-Header | 201511 | (0.77) | 5 | 0.0013083 | (0.01) | (0.01) |
| 376300-Mains - Plastic | 900978 | 3304L | Inst 3875F 8P Brannon Ave-Header | 201511 | (0.06) | 5 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900978 | 3304L | Inst 3875F 8P Brannon Ave-Header | 201512 | (84,254.24) | 4 | 0.0013083 | (440.92) | (1,322.76) |
| 376300-Mains - Plastic | 900978 | 3304L | Inst 3875F 8P Brannon Ave-Header | 201512 | 84,274.07 | 4 | 0.0013083 | 441.02 | 1,323.07 |
| 376300-Mains - Plastic | 900979 | 3304L | Inst 2254F 8P Brannon | 201509 | 305,891.76 | 7 | 0.0013083 | 2,801.39 | 4,802.38 |
| 376300-Mains - Plastic | 900979 | 3304L | Inst 2254F 8P Brannon | 201509 | 18,214.16 | 7 | 0.0013083 | 166.81 | 285.96 |
| 376300-Mains - Plastic | 900979 | 3304L | Inst 2254F 8P Brannon | 201510 | 710.09 | 6 | 0.0013083 | 5.57 | 11.15 |
| 376300-Mains - Plastic | 900979 | 3304L | Inst 2254F 8P Brannon | 201510 | 42.29 | 6 | 0.0013083 | 0.33 | 0.66 |
| 376300-Mains - Plastic | 900979 | 3304L | Inst 2254F 8P Brannon | 201511 | (5,949.46) | 5 | 0.0013083 | (38.92) | (93.40) |
| 376300-Mains - Plastic | 900979 | 3304L | Inst 2254F 8P Brannon | 201511 | (354.26) | 5 | 0.0013083 | (2.32) | (5.56) |
| 376300-Mains - Plastic | 900979 | 3304L | Inst 2254F 8P Brannon | 201512 | 4.88 | 4 | 0.0013083 | 0.03 | 0.08 |
| 376300-Mains - Plastic | 900979 | 3304L | Inst 2254F 8P Brannon | 201512 | 81.93 | 4 | 0.0013083 | 0.43 | 1.29 |

| | | | | | | | | | |
|------------------------|--------|-------|-------------------------------------|--------|-------------|---|-----------|----------|----------|
| 376300-Mains - Plastic | 900983 | 3303L | Repl w/ 3143F 2P 4P Shaw AOR | 201512 | 9,922.30 | 4 | 0.0013083 | 51.93 | 155.78 |
| 376300-Mains - Plastic | 900983 | 3303L | Repl w/ 3143F 2P 4P Shaw AOR | 201512 | 400,436.29 | 4 | 0.0013083 | 2,095.56 | 6,266.69 |
| 376300-Mains - Plastic | 900986 | 3303L | Repl w/ 2189F 2P Earthquake Zone 2A | 201509 | 44,753.62 | 7 | 0.0013083 | 409.86 | 702.61 |
| 376300-Mains - Plastic | 900986 | 3303L | Repl w/ 2189F 2P Earthquake Zone 2A | 201509 | 11,424.95 | 7 | 0.0013083 | 104.63 | 179.37 |
| 376300-Mains - Plastic | 900986 | 3303L | Repl w/ 2189F 2P Earthquake Zone 2A | 201510 | (258.39) | 6 | 0.0013083 | (2.03) | (4.06) |
| 376300-Mains - Plastic | 900986 | 3303L | Repl w/ 2189F 2P Earthquake Zone 2A | 201510 | (15.52) | 6 | 0.0013083 | (0.12) | (0.24) |
| 376300-Mains - Plastic | 900988 | 3303L | Repl w/ 3840F 2P Earthquake Zn Ph2B | 201509 | 207,224.86 | 7 | 0.0013083 | 1,897.79 | 3,253.35 |
| 376300-Mains - Plastic | 900988 | 3303L | Repl w/ 3840F 2P Earthquake Zn Ph2B | 201509 | 5,106.34 | 7 | 0.0013083 | 46.76 | 80.17 |
| 376300-Mains - Plastic | 900988 | 3303L | Repl w/ 3840F 2P Earthquake Zn Ph2B | 201510 | 328.21 | 6 | 0.0013083 | 2.58 | 5.15 |
| 376300-Mains - Plastic | 900988 | 3303L | Repl w/ 3840F 2P Earthquake Zn Ph2B | 201510 | 8.10 | 6 | 0.0013083 | 0.06 | 0.13 |
| 376300-Mains - Plastic | 900988 | 3303L | Repl w/ 3840F 2P Earthquake Zn Ph2B | 201511 | (1,453.94) | 5 | 0.0013083 | (9.51) | (22.83) |
| 376300-Mains - Plastic | 900988 | 3303L | Repl w/ 3840F 2P Earthquake Zn Ph2B | 201511 | (35.83) | 5 | 0.0013083 | (0.23) | (0.56) |
| 376300-Mains - Plastic | 900988 | 3303L | Repl w/ 3840F 2P Earthquake Zn Ph2B | 201512 | 0.71 | 4 | 0.0013083 | - | 0.01 |
| 376300-Mains - Plastic | 900988 | 3303L | Repl w/ 3840F 2P Earthquake Zn Ph2B | 201512 | 28.63 | 4 | 0.0013083 | 0.15 | 0.45 |
| 376300-Mains - Plastic | 900993 | 3303L | Repl w/ 2220F 2P CentralWestEndPh1G | 201511 | 1,596.26 | 5 | 0.0013083 | 10.44 | 25.06 |
| 376300-Mains - Plastic | 900993 | 3303L | Repl w/ 2220F 2P CentralWestEndPh1G | 201511 | 66.59 | 5 | 0.0013083 | 0.44 | 1.05 |
| 376300-Mains - Plastic | 901025 | 3303L | Repl w/ 85F 2P Walnut Park | 201509 | (1,193.73) | 7 | 0.0013083 | (10.93) | (18.74) |
| 376300-Mains - Plastic | 901025 | 3303L | Repl w/ 85F 2P Walnut Park | 201509 | (109.02) | 7 | 0.0013083 | (1.00) | (1.71) |
| 376300-Mains - Plastic | 901025 | 3303L | Repl w/ 85F 2P Walnut Park | 201510 | 52.48 | 6 | 0.0013083 | 0.41 | 0.82 |
| 376300-Mains - Plastic | 901025 | 3303L | Repl w/ 85F 2P Walnut Park | 201510 | 4.80 | 6 | 0.0013083 | 0.04 | 0.08 |
| 376300-Mains - Plastic | 901025 | 3303L | Repl w/ 85F 2P Walnut Park | 201511 | (4.56) | 5 | 0.0013083 | (0.03) | (0.07) |
| 376300-Mains - Plastic | 901025 | 3303L | Repl w/ 85F 2P Walnut Park | 201511 | 4.49 | 5 | 0.0013083 | 0.03 | 0.07 |
| 376300-Mains - Plastic | 901025 | 3303L | Repl w/ 85F 2P Walnut Park | 201512 | 1.07 | 4 | 0.0013083 | 0.01 | 0.02 |
| 376300-Mains - Plastic | 901025 | 3303L | Repl w/ 85F 2P Walnut Park | 201512 | 9.66 | 4 | 0.0013083 | 0.05 | 0.15 |
| 376300-Mains - Plastic | 901040 | 3303L | Repl w/ 315F 2P Amherst Ave | 201509 | (754.32) | 7 | 0.0013083 | (6.91) | (11.84) |
| 376300-Mains - Plastic | 901040 | 3303L | Repl w/ 315F 2P Amherst Ave | 201509 | (17.72) | 7 | 0.0013083 | (0.16) | (0.28) |
| 376300-Mains - Plastic | 901059 | 3303L | Repl w/ 680' 2P Gregg | 201509 | 32,723.70 | 7 | 0.0013083 | 299.69 | 513.75 |
| 376300-Mains - Plastic | 901059 | 3303L | Repl w/ 680' 2P Gregg | 201509 | 1,565.71 | 7 | 0.0013083 | 14.34 | 24.58 |
| 376300-Mains - Plastic | 901059 | 3303L | Repl w/ 680' 2P Gregg | 201510 | 659.67 | 6 | 0.0013083 | 5.18 | 10.36 |
| 376300-Mains - Plastic | 901059 | 3303L | Repl w/ 680' 2P Gregg | 201510 | 31.55 | 6 | 0.0013083 | 0.25 | 0.50 |
| 376300-Mains - Plastic | 901059 | 3303L | Repl w/ 680' 2P Gregg | 201511 | (448.14) | 5 | 0.0013083 | (2.93) | (7.04) |
| 376300-Mains - Plastic | 901059 | 3303L | Repl w/ 680' 2P Gregg | 201511 | (21.44) | 5 | 0.0013083 | (0.14) | (0.34) |
| 376300-Mains - Plastic | 901059 | 3303L | Repl w/ 680' 2P Gregg | 201512 | 0.74 | 4 | 0.0013083 | - | 0.01 |
| 376300-Mains - Plastic | 901059 | 3303L | Repl w/ 680' 2P Gregg | 201512 | 15.74 | 4 | 0.0013083 | 0.08 | 0.25 |
| 376300-Mains - Plastic | 901070 | 3304L | Repl w/ 4194F 6P Eichelberger heade | 201512 | 39,428.37 | 4 | 0.0013083 | 206.34 | 619.01 |
| 376300-Mains - Plastic | 901070 | 3304L | Repl w/ 4194F 6P Eichelberger heade | 201512 | 476,956.19 | 4 | 0.0013083 | 2,496.01 | 7,488.02 |
| 376100-Mains - Steel | 901084 | 3304L | Inst 4297F 8P Fair Ave header | 201509 | 6,650.31 | 7 | 0.0012000 | 55.86 | 95.76 |
| 376300-Mains - Plastic | 901084 | 3304L | Inst 4297F 8P Fair Ave header | 201509 | 341,419.16 | 7 | 0.0013083 | 3,126.75 | 5,360.14 |
| 376300-Mains - Plastic | 901084 | 3304L | Inst 4297F 8P Fair Ave header | 201509 | 71,756.88 | 7 | 0.0013083 | 657.16 | 1,126.55 |
| 376100-Mains - Steel | 901084 | 3304L | Inst 4297F 8P Fair Ave header | 201510 | (198.44) | 6 | 0.0012000 | (1.43) | (2.86) |
| 376300-Mains - Plastic | 901084 | 3304L | Inst 4297F 8P Fair Ave header | 201510 | (10,188.42) | 6 | 0.0013083 | (79.98) | (159.95) |
| 376300-Mains - Plastic | 901084 | 3304L | Inst 4297F 8P Fair Ave header | 201510 | (2,141.33) | 6 | 0.0013083 | (16.81) | (33.62) |
| 376100-Mains - Steel | 901084 | 3304L | Inst 4297F 8P Fair Ave header | 201511 | (50.64) | 5 | 0.0012000 | (0.30) | (0.73) |
| 376300-Mains - Plastic | 901084 | 3304L | Inst 4297F 8P Fair Ave header | 201511 | (2,600.88) | 5 | 0.0013083 | (17.01) | (40.83) |
| 376300-Mains - Plastic | 901084 | 3304L | Inst 4297F 8P Fair Ave header | 201511 | (546.64) | 5 | 0.0013083 | (3.58) | (8.58) |
| 376300-Mains - Plastic | 901084 | 3304L | Inst 4297F 8P Fair Ave header | 201512 | (297.42) | 4 | 0.0013083 | (1.56) | (4.67) |
| 376300-Mains - Plastic | 901084 | 3304L | Inst 4297F 8P Fair Ave header | 201512 | (62.51) | 4 | 0.0013083 | (0.33) | (0.98) |
| 376100-Mains - Steel | 901084 | 3304L | Inst 4297F 8P Fair Ave header | 201512 | (5.79) | 4 | 0.0012000 | (0.03) | (0.08) |
| 376300-Mains - Plastic | 901088 | 3303L | Repl w/ 4597F 2P U-City Ph1B | 201512 | 7,810.51 | 4 | 0.0013083 | 40.87 | 122.62 |

| | | | | | | | | | |
|------------------------|--------|-------|---------------------------------|--------|---------------|---|-----------|-----------|------------|
| 376300-Mains - Plastic | 901088 | 3303L | Repl w/ 4597F 2P U-City Ph1B | 201512 | 204,650.36 | 4 | 0.0013083 | 1,070.98 | 3,212.93 |
| 376300-Mains - Plastic | 901111 | 3303L | Repl w/ 955F 2P Hickory | 201509 | 79,845.33 | 7 | 0.0013083 | 731.23 | 1,253.54 |
| 376300-Mains - Plastic | 901111 | 3303L | Repl w/ 955F 2P Hickory | 201509 | 3,741.97 | 7 | 0.0013083 | 34.27 | 58.75 |
| 376300-Mains - Plastic | 901111 | 3303L | Repl w/ 955F 2P Hickory | 201510 | 5,998.99 | 6 | 0.0013083 | 47.09 | 94.18 |
| 376300-Mains - Plastic | 901111 | 3303L | Repl w/ 955F 2P Hickory | 201510 | 281.15 | 6 | 0.0013083 | 2.21 | 4.41 |
| 376300-Mains - Plastic | 901111 | 3303L | Repl w/ 955F 2P Hickory | 201511 | (1,178.26) | 5 | 0.0013083 | (7.71) | (18.50) |
| 376300-Mains - Plastic | 901111 | 3303L | Repl w/ 955F 2P Hickory | 201511 | (55.23) | 5 | 0.0013083 | (0.36) | (0.87) |
| 376300-Mains - Plastic | 901111 | 3303L | Repl w/ 955F 2P Hickory | 201512 | 5.43 | 4 | 0.0013083 | 0.03 | 0.09 |
| 376300-Mains - Plastic | 901111 | 3303L | Repl w/ 955F 2P Hickory | 201512 | 115.70 | 4 | 0.0013083 | 0.61 | 1.82 |
| 376100-Mains - Steel | 901112 | 3303L | UGS Gathering Line Replacement | 201509 | (5,629.12) | 7 | 0.0012000 | (47.28) | (81.06) |
| 376100-Mains - Steel | 901112 | 3303L | UGS Gathering Line Replacement | 201512 | (216.99) | 4 | 0.0012000 | (1.04) | (3.12) |
| 376300-Mains - Plastic | 901114 | 3303L | Repl w/ 1630F 2P Maffitt | 201512 | 6,323.75 | 4 | 0.0013083 | 33.09 | 99.28 |
| 376300-Mains - Plastic | 901114 | 3303L | Repl w/ 1630F 2P Maffitt | 201512 | 154,355.11 | 4 | 0.0013083 | 807.77 | 2,423.31 |
| 376300-Mains - Plastic | 901139 | 3303L | Repl w/ 901F 2P Suburban Ave | 201509 | 40,932.69 | 7 | 0.0013083 | 374.87 | 642.63 |
| 376300-Mains - Plastic | 901139 | 3303L | Repl w/ 901F 2P Suburban Ave | 201509 | 2,690.78 | 7 | 0.0013083 | 24.64 | 42.24 |
| 376300-Mains - Plastic | 901139 | 3303L | Repl w/ 901F 2P Suburban Ave | 201510 | 8,674.51 | 6 | 0.0013083 | 68.09 | 136.19 |
| 376300-Mains - Plastic | 901139 | 3303L | Repl w/ 901F 2P Suburban Ave | 201510 | 570.23 | 6 | 0.0013083 | 4.48 | 8.95 |
| 376300-Mains - Plastic | 901139 | 3303L | Repl w/ 901F 2P Suburban Ave | 201511 | (261.30) | 5 | 0.0013083 | (1.71) | (4.10) |
| 376300-Mains - Plastic | 901139 | 3303L | Repl w/ 901F 2P Suburban Ave | 201511 | (17.19) | 5 | 0.0013083 | (0.11) | (0.27) |
| 376300-Mains - Plastic | 901139 | 3303L | Repl w/ 901F 2P Suburban Ave | 201512 | (5.29) | 4 | 0.0013083 | (0.03) | (0.08) |
| 376300-Mains - Plastic | 901139 | 3303L | Repl w/ 901F 2P Suburban Ave | 201512 | (0.37) | 4 | 0.0013083 | - | (0.01) |
| 376300-Mains - Plastic | 901161 | 3303L | Repl w/ 535F 2P Grantsview | 201512 | 869.82 | 4 | 0.0013083 | 4.55 | 13.66 |
| 376300-Mains - Plastic | 901161 | 3303L | Repl w/ 535F 2P Grantsview | 201512 | 41,404.01 | 4 | 0.0013083 | 216.68 | 650.03 |
| 376300-Mains - Plastic | 901162 | 3303L | Repl w/ 210F 2P St. Leonard Ct. | 201512 | 1,388.83 | 4 | 0.0013083 | 7.27 | 21.80 |
| 376300-Mains - Plastic | 901162 | 3303L | Repl w/ 210F 2P St. Leonard Ct. | 201512 | 32,114.37 | 4 | 0.0013083 | 168.06 | 504.18 |
| 376300-Mains - Plastic | 901178 | 3303L | Repl w/ 185F 2P Evans | 201509 | 7,839.50 | 7 | 0.0013083 | 71.79 | 123.08 |
| 376300-Mains - Plastic | 901178 | 3303L | Repl w/ 185F 2P Evans | 201510 | 604.27 | 6 | 0.0013083 | 4.74 | 9.49 |
| 376300-Mains - Plastic | 901178 | 3303L | Repl w/ 185F 2P Evans | 201511 | (0.60) | 5 | 0.0013083 | - | (0.01) |
| 376300-Mains - Plastic | 901178 | 3303L | Repl w/ 185F 2P Evans | 201512 | 22.98 | 4 | 0.0013083 | 0.12 | 0.36 |
| 376300-Mains - Plastic | 901220 | 3303L | Aband 511F 4C Marcus AOR | 201512 | 606.37 | 4 | 0.0013083 | 3.17 | 9.52 |
| 376300-Mains - Plastic | 901220 | 3303L | Aband 511F 4C Marcus AOR | 201512 | 5,399.81 | 4 | 0.0013083 | 28.26 | 84.77 |
| 376300-Mains - Plastic | | 3303L | MAIN:REPLACEMENTS-ADDITIONS | 201601 | 4,856,000.00 | 3 | 0.0013083 | 19,059.31 | 76,237.26 |
| 376300-Mains - Plastic | | 3303L | MAIN:REPLACEMENTS-ADDITIONS | 201602 | 4,362,000.00 | 2 | 0.0013083 | 11,413.61 | 68,481.66 |
| | | | | | 17,329,951.87 | | | 82,689.78 | 271,993.98 |

SERVICE TRANSFER WORK ORDERS

| PLANT ACCOUNT | WORK ORDER | BUDGET PROJECT | DESCRIPTION | IN SERVICE DATE | ADDITION AMOUNT | MONTHS | DEPR. MO. RATE | ACCUM. DEPR. | DEPR. EXPENSE |
|------------------------|------------|----------------|------------------------------------|-----------------|-----------------|--------|----------------|--------------|---------------|
| 376300-Mains - Plastic | 000569 | 3304L | 4015F 6P 2P Lemay Ferry | 201509 | (0.01) | 7 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 001040 | 3303L | Install 46F 4P Nashville | 201509 | 0.30 | 7 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 001330 | 3303L | Inst 9084F 2P Aberdeen Pl | 201509 | (2,758.95) | 7 | 0.0013083 | (25.27) | (43.31) |
| 376300-Mains - Plastic | 001337 | 3403L | Inst 622F 4P Shenandoah | 201509 | 110,930.59 | 7 | 0.0013083 | 1,015.91 | 1,741.57 |
| 376300-Mains - Plastic | 001337 | 3403L | Inst 622F 4P Shenandoah CJ - Reimb | 201511 | (51,100.99) | 5 | 0.0013083 | (334.28) | (802.27) |
| 376300-Mains - Plastic | 001535 | 3303L | Repl w/ 9098F 2P Arlington | 201509 | (74.71) | 7 | 0.0013083 | (0.68) | (1.17) |
| 376300-Mains - Plastic | 001582 | 3303L | Inst 2986F 2P Elendale-Well Ph 4A | 201509 | (0.01) | 7 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 001711 | 3303L | Inst 7023F 2P Northmoor WYdown Ph5 | 201509 | (2.81) | 7 | 0.0013083 | (0.03) | (0.04) |
| 376300-Mains - Plastic | 001712 | 3303L | Inst 16489F 2P Cote Brilliante | 201509 | 6,666.83 | 7 | 0.0013083 | 61.06 | 104.67 |
| 376300-Mains - Plastic | 001712 | 3303L | Inst 16489F 2P Cote Brilliante | 201510 | (22.96) | 6 | 0.0013083 | (0.18) | (0.36) |
| 376300-Mains - Plastic | 002137 | 3303L | Repl w/ 5955F 2P Boneta | 201509 | (1,621.71) | 7 | 0.0013083 | (14.85) | (25.46) |

| | | | | | | | | | |
|------------------------|--------|-------|--------------------------------------|--------|------------|---|-----------|----------|----------|
| 376300-Mains - Plastic | 002138 | 3303L | Repl w/ 10203F 2P Manchester | 201509 | (2,490.75) | 7 | 0.0013083 | (22.81) | (39.10) |
| 376300-Mains - Plastic | 002139 | 3303L | Inst 3278F 2P MLK -Wellston 1B | 201509 | (8,638.24) | 7 | 0.0013083 | (79.11) | (135.62) |
| 376300-Mains - Plastic | 002139 | 3303L | Inst 3278F 2P MLK -Wellston 1B | 201510 | 1,725.33 | 6 | 0.0013083 | 13.54 | 27.09 |
| 376300-Mains - Plastic | 002139 | 3303L | Inst 3278F 2P MLK -Wellston 1B | 201511 | 2,708.85 | 5 | 0.0013083 | 17.72 | 42.53 |
| 376300-Mains - Plastic | 002139 | 3303L | Inst 3278F 2P MLK -Wellston 1B | 201512 | 387.47 | 4 | 0.0013083 | 2.03 | 6.08 |
| 376300-Mains - Plastic | 002140 | 3303L | Inst 6894F 2P Bertha-Wellston 1A | 201509 | (2,470.33) | 7 | 0.0013083 | (22.62) | (38.78) |
| 376300-Mains - Plastic | 002140 | 3303L | Inst 6894F 2P Bertha-Wellston 1A | 201510 | (3,703.14) | 6 | 0.0013083 | (29.07) | (58.14) |
| 376300-Mains - Plastic | 002141 | 3303L | Inst 6161F 2P Marshall-Well. Ph4C | 201509 | (0.56) | 7 | 0.0013083 | (0.01) | (0.01) |
| 376300-Mains - Plastic | 003763 | 3403M | Repl w/ 3200F 4P Oak Grove Rd-MN | 201509 | 289.62 | 7 | 0.0013083 | 2.65 | 4.55 |
| 376300-Mains - Plastic | 009113 | 3403M | Repl w/ 210F 4P W Congress MN | 201512 | 2,025.67 | 4 | 0.0013083 | 10.60 | 31.80 |
| 376300-Mains - Plastic | 672860 | 3504L | 67286 SVC TRF 67285 | 201510 | 4,021.28 | 6 | 0.0013083 | 31.57 | 63.13 |
| 376300-Mains - Plastic | 900068 | 3303L | Repl w/ 1750F 2P Jefferson Ph 2 | 201509 | (111.72) | 7 | 0.0013083 | (1.02) | (1.75) |
| 376300-Mains - Plastic | 900071 | 3303L | Repl w/ 4240F 2-4P Jefferson Ph5 | 201511 | 180,314.01 | 5 | 0.0013083 | 1,179.52 | 2,830.86 |
| 376300-Mains - Plastic | 900071 | 3303L | Repl w/ 4240F 2-4P Jefferson Ph5 | 201512 | 596.10 | 4 | 0.0013083 | 3.12 | 9.36 |
| 376300-Mains - Plastic | 900073 | 3303L | Repl w/ 2520F 2P Jefferson Ph 6 | 201509 | 217,169.41 | 7 | 0.0013083 | 1,988.86 | 3,409.47 |
| 376300-Mains - Plastic | 900073 | 3303L | Repl w/ 2520F 2P Jefferson Ph 6 | 201510 | 285.49 | 6 | 0.0013083 | 2.24 | 4.48 |
| 376300-Mains - Plastic | 900093 | 3303L | Repl w/ 184F 2P Cass | 201509 | 0.04 | 7 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900099 | 3403L | Repl 1830F 2P McKnight Rd | 201509 | (60.36) | 7 | 0.0013083 | (0.55) | (0.95) |
| 376300-Mains - Plastic | 900104 | 3403L | Repl w/ 3018F Var-Kingshighway Bridg | 201512 | 46,034.50 | 4 | 0.0013083 | 240.91 | 722.72 |
| 376300-Mains - Plastic | 900265 | 3303L | Repl w/ 3337F 2P Baden Ph 5B | 201509 | 0.04 | 7 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900266 | 3303L | Inst 4640F 2P Baden Ph 5C | 201509 | (0.04) | 7 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900266 | 3303L | Inst 4640F 2P Baden Ph 5C | 201510 | 0.14 | 6 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900266 | 3303L | Inst 4640F 2P Baden Ph 5C | 201511 | (0.01) | 5 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900266 | 3303L | Inst 4640F 2P Baden Ph 5C | 201512 | 0.69 | 4 | 0.0013083 | - | 0.01 |
| 376300-Mains - Plastic | 900269 | 3303L | Inst 1150F 4P Walnut Park Ph 5A | 201509 | (613.90) | 7 | 0.0013083 | (5.62) | (9.64) |
| 376300-Mains - Plastic | 900270 | 3303L | Inst 2942F 2P Walnut Park Ph5B | 201509 | (615.30) | 7 | 0.0013083 | (5.63) | (9.66) |
| 376300-Mains - Plastic | 900270 | 3303L | Inst 2942F 2P Walnut Park Ph5B | 201511 | 1,856.30 | 5 | 0.0013083 | 12.14 | 29.14 |
| 376300-Mains - Plastic | 900274 | 3303L | Repl w/ 3390F 2P Wellington Ph 4D | 201512 | 115,841.25 | 4 | 0.0013083 | 606.22 | 1,818.66 |
| 376300-Mains - Plastic | 900275 | 3303L | Repl w/ 4989F 2P Wellington Ph4E | 201509 | (1,631.25) | 7 | 0.0013083 | (14.94) | (25.61) |
| 376300-Mains - Plastic | 900278 | 3303L | Repl w/ 3977F 2P Walnut Park Ph4C | 201509 | (1.42) | 7 | 0.0013083 | (0.01) | (0.02) |
| 376300-Mains - Plastic | 900279 | 3303L | Repl w/ 3345F 2P Walnut Park Ph4D | 201509 | (528.38) | 7 | 0.0013083 | (4.84) | (8.30) |
| 376300-Mains - Plastic | 900282 | 3303L | Inst 4400F 2P Wellston 2C | 201509 | (773.04) | 7 | 0.0013083 | (7.08) | (12.14) |
| 376300-Mains - Plastic | 900284 | 3303L | Inst 5466F 2P Wellston Ph2E | 201509 | (22.33) | 7 | 0.0013083 | (0.20) | (0.35) |
| 376300-Mains - Plastic | 900313 | 3403L | Repl w/ 775F 2P Caulks Hill Rd CJ | 201510 | (232.81) | 6 | 0.0013083 | (1.83) | (3.66) |
| 376300-Mains - Plastic | 900375 | 3303L | Inst 1747F 6P Litzinger | 201509 | 0.22 | 7 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900377 | 3303L | Repl w/ 978F 2-4P Big Bend | 201509 | (250.19) | 7 | 0.0013083 | (2.29) | (3.93) |
| 376300-Mains - Plastic | 900379 | 3303L | Inst 783F 4P & 529F 2P Old Bonhomme | 201509 | (10.51) | 7 | 0.0013083 | (0.10) | (0.17) |
| 376300-Mains - Plastic | 900388 | 3303L | Repl w/ 332F 2P Tay Rd | 201509 | (8.12) | 7 | 0.0013083 | (0.07) | (0.13) |
| 376300-Mains - Plastic | 900390 | 3303L | Inst 205F 1 1/4P Gore | 201509 | (0.47) | 7 | 0.0013083 | - | (0.01) |
| 376300-Mains - Plastic | 900392 | 3303L | Inst 580F 4P & 255F 2P Ferguson | 201509 | (0.09) | 7 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900415 | 3303L | Repl w/ 1093F 2P Princeton | 201509 | (4.11) | 7 | 0.0013083 | (0.04) | (0.06) |
| 376300-Mains - Plastic | 900420 | 3303L | Repl w/ 520F 2P Oregon | 201509 | (14.76) | 7 | 0.0013083 | (0.14) | (0.23) |
| 376300-Mains - Plastic | 900423 | 3303L | Repl w/ 1373F 2P Dr MLK | 201509 | (0.04) | 7 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900430 | 3303L | Repl w/ 654F 2P Maurice | 201509 | (1.31) | 7 | 0.0013083 | (0.01) | (0.02) |
| 376300-Mains - Plastic | 900432 | 3303L | Repl w/ 503F 2P Gravois | 201509 | (6.62) | 7 | 0.0013083 | (0.06) | (0.10) |
| 376300-Mains - Plastic | 900462 | 3303L | Repl w/ 2240F 2P Walnut Park Ph4G | 201509 | (448.53) | 7 | 0.0013083 | (4.11) | (7.04) |
| 376300-Mains - Plastic | 900463 | 3303L | Inst 4082F 2P Walnut Park Ph4H | 201509 | (1.93) | 7 | 0.0013083 | (0.02) | (0.03) |
| 376300-Mains - Plastic | 900464 | 3303L | Inst 4741F 2P Walnut Park Ph 4I | 201509 | (210.42) | 7 | 0.0013083 | (1.93) | (3.30) |
| 376300-Mains - Plastic | 900557 | 3303L | Inst 2123F 2P Walnut Park Ph6A | 201509 | (3,228.70) | 7 | 0.0013083 | (29.57) | (50.69) |
| 376300-Mains - Plastic | 900559 | 3303L | Inst 3875F 2P Walnut Park Ph6C | 201509 | (3,138.92) | 7 | 0.0013083 | (28.75) | (49.28) |
| 376300-Mains - Plastic | 900559 | 3303L | Inst 3875F 2P Walnut Park Ph6C | 201510 | (301.23) | 6 | 0.0013083 | (2.36) | (4.73) |
| 376300-Mains - Plastic | 900559 | 3303L | Inst 3875F 2P Walnut Park Ph6C | 201511 | 2,620.23 | 5 | 0.0013083 | 17.14 | 41.14 |

| | | | | | | | | | |
|------------------------|--------|-------|-------------------------------------|--------|-------------|---|-----------|----------|------------|
| 376300-Mains - Plastic | 900559 | 3303L | Inst 3875F 2P Walnut Park Ph6C | 201512 | 524.81 | 4 | 0.0013083 | 2.75 | 8.24 |
| 376300-Mains - Plastic | 900561 | 3303L | Repl w/ 6270F 2P Walnut Park Ph6E | 201511 | 235,678.12 | 5 | 0.0013083 | 1,541.69 | 3,700.05 |
| 376300-Mains - Plastic | 900561 | 3303L | Repl w/ 6270F 2P Walnut Park Ph6E | 201512 | 20.18 | 4 | 0.0013083 | 0.11 | 0.32 |
| 376300-Mains - Plastic | 900623 | 3303L | Repl w/ 2852' 2P Wydown Ph 6 | 201509 | 347.05 | 7 | 0.0013083 | 3.18 | 5.45 |
| 376100-Mains - Steel | 900633 | 3403L | Rel w/ 321F 4S 2S Progress Parkway | 201509 | 69.23 | 7 | 0.0012000 | 0.58 | 1.00 |
| 376100-Mains - Steel | 900633 | 3403L | Rel w/ 321F 4S 2S Progress Parkway | 201510 | (21.24) | 6 | 0.0012000 | (0.15) | (0.31) |
| 376300-Mains - Plastic | 900643 | 3304L | Inst 1801F 6P-12P Marmaduke/Hudler | 201509 | 3,004.32 | 7 | 0.0013083 | 27.51 | 47.17 |
| 376300-Mains - Plastic | 900643 | 3304L | Inst 1801F 6P-12P Marmaduke/Hudler | 201510 | 0.46 | 6 | 0.0013083 | - | 0.01 |
| 376300-Mains - Plastic | 900650 | 3303L | Inst 3290F 2P St Louis Hills Ph1A | 201512 | 163,168.27 | 4 | 0.0013083 | 853.89 | 2,561.68 |
| 376300-Mains - Plastic | 900652 | 3303L | Inst 4435F 2P St Louis Hills Ph1B | 201509 | (2,688.21) | 7 | 0.0013083 | (24.62) | (42.20) |
| 376300-Mains - Plastic | 900652 | 3303L | Inst 4435F 2P St Louis Hills Ph1B | 201511 | 2,450.79 | 5 | 0.0013083 | 16.03 | 38.48 |
| 376300-Mains - Plastic | 900653 | 3303L | Inst 2636F 2P St Louis Hills Ph1C | 201509 | (1,110.82) | 7 | 0.0013083 | (10.17) | (17.44) |
| 376300-Mains - Plastic | 900653 | 3303L | Inst 2636F 2P St Louis Hills Ph1C | 201510 | 113.69 | 6 | 0.0013083 | 0.89 | 1.78 |
| 376300-Mains - Plastic | 900653 | 3303L | Inst 2636F 2P St Louis Hills Ph1C | 201511 | 5,428.80 | 5 | 0.0013083 | 35.51 | 85.23 |
| 376300-Mains - Plastic | 900653 | 3303L | Inst 2636F 2P St Louis Hills Ph1C | 201512 | 3.58 | 4 | 0.0013083 | 0.02 | 0.06 |
| 376300-Mains - Plastic | 900670 | 3403L | Rel w/ 400F 6P Vogel Rd | 201509 | (3,400.72) | 7 | 0.0013083 | (31.14) | (53.39) |
| 376300-Mains - Plastic | 900679 | 3303L | Inst 2312F 4P Cole & 18th PhB | 201511 | 12,896.70 | 5 | 0.0013083 | 84.36 | 202.47 |
| 376300-Mains - Plastic | 900681 | 3303L | Inst 1637F 2P Cole & 18th Ph C | 201509 | 20,971.99 | 7 | 0.0013083 | 192.06 | 329.25 |
| 376300-Mains - Plastic | 900683 | 3303L | Inst 1864F 2P Cole & 18th Ph D | 201509 | 30,596.05 | 7 | 0.0013083 | 280.20 | 480.35 |
| 376300-Mains - Plastic | 900683 | 3303L | Inst 1864F 2P Cole & 18th Ph D | 201510 | 14.69 | 6 | 0.0013083 | 0.12 | 0.23 |
| 376300-Mains - Plastic | 900683 | 3303L | Inst 1864F 2P Cole & 18th Ph D | 201511 | (0.01) | 5 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900683 | 3303L | Inst 1864F 2P Cole & 18th Ph D | 201512 | 0.48 | 4 | 0.0013083 | - | 0.01 |
| 376300-Mains - Plastic | 900685 | 3303L | Inst 1550F 2P Cole & 18th PhE | 201509 | 11,433.79 | 7 | 0.0013083 | 104.71 | 179.51 |
| 376300-Mains - Plastic | 900685 | 3303L | Inst 1550F 2P Cole & 18th PhE | 201510 | 15.45 | 6 | 0.0013083 | 0.12 | 0.24 |
| 376300-Mains - Plastic | 900685 | 3303L | Inst 1550F 2P Cole & 18th PhE | 201511 | (0.02) | 5 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900685 | 3303L | Inst 1550F 2P Cole & 18th PhE | 201512 | 0.52 | 4 | 0.0013083 | - | 0.01 |
| 376300-Mains - Plastic | 900687 | 3303L | Inst 1096F 2P Cole & 18th PhF | 201509 | 9,530.10 | 7 | 0.0013083 | 87.28 | 149.62 |
| 376300-Mains - Plastic | 900689 | 3303L | Inst 2434F 2P Cole & 18th PhG | 201509 | 15,057.72 | 7 | 0.0013083 | 137.90 | 236.40 |
| 376300-Mains - Plastic | 900689 | 3303L | Inst 2434F 2P Cole & 18th PhG | 201510 | (32.36) | 6 | 0.0013083 | (0.25) | (0.51) |
| 376300-Mains - Plastic | 900689 | 3303L | Inst 2434F 2P Cole & 18th PhG | 201511 | 0.06 | 5 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900689 | 3303L | Inst 2434F 2P Cole & 18th PhG | 201512 | (7.82) | 4 | 0.0013083 | (0.04) | (0.12) |
| 376300-Mains - Plastic | 900723 | 3403L | Rel w/ 3350F 2P Valley Park | 201509 | 1.37 | 7 | 0.0013083 | 0.01 | 0.02 |
| 376300-Mains - Plastic | 900730 | 3403L | Rel w/ 310F 2P Bramblett | 201509 | (167.78) | 7 | 0.0013083 | (1.54) | (2.63) |
| 376300-Mains - Plastic | 900730 | 3403L | Rel w/ 310F 2P Bramblett | 201510 | (0.39) | 6 | 0.0013083 | - | (0.01) |
| 376300-Mains - Plastic | 900734 | 3303L | Repl w/ 1717F 2P Hurck | 201509 | (2,232.41) | 7 | 0.0013083 | (20.44) | (35.05) |
| 376300-Mains - Plastic | 900734 | 3303L | Repl w/ 1717F 2P Hurck | 201510 | 17.27 | 6 | 0.0013083 | 0.14 | 0.27 |
| 376300-Mains - Plastic | 900734 | 3303L | Repl w/ 1717F 2P Hurck | 201511 | 994.93 | 5 | 0.0013083 | 6.51 | 15.62 |
| 376300-Mains - Plastic | 900734 | 3303L | Repl w/ 1717F 2P Hurck | 201512 | 83.23 | 4 | 0.0013083 | 0.44 | 1.31 |
| 376300-Mains - Plastic | 900738 | 3303L | Repl w/ 780F 2P Kingsland MSD | 201509 | (1,251.62) | 7 | 0.0013083 | (11.46) | (19.65) |
| 376300-Mains - Plastic | 900738 | 3303L | Repl w/ 780F 2P Kingsland MSD | 201511 | 194.36 | 5 | 0.0013083 | 1.27 | 3.05 |
| 376300-Mains - Plastic | 900738 | 3303L | Repl w/ 780F 2P Kingsland MSD | 201512 | 17.14 | 4 | 0.0013083 | 0.09 | 0.27 |
| 376300-Mains - Plastic | 900759 | 3303L | Repl w/ 2836F 2P Hickory Dale | 201509 | (64,448.48) | 7 | 0.0013083 | (590.23) | (1,011.82) |
| 376300-Mains - Plastic | 900759 | 3303L | Repl w/ 2836F 2P Hickory Dale | 201510 | 11.48 | 6 | 0.0013083 | 0.09 | 0.18 |
| 376300-Mains - Plastic | 900762 | 3303L | Inst 2069F 2P Earthquake Zone Ph1A | 201509 | (90.58) | 7 | 0.0013083 | (0.83) | (1.42) |
| 376300-Mains - Plastic | 900763 | 3303L | Inst 3508F 2P Earthquake Zone Ph1B | 201509 | 143,475.06 | 7 | 0.0013083 | 1,313.96 | 2,252.50 |
| 376300-Mains - Plastic | 900764 | 3303L | Repl w/758F 2P Earthquake Zone Ph1C | 201509 | 11,272.00 | 7 | 0.0013083 | 103.23 | 176.97 |
| 376300-Mains - Plastic | 900764 | 3303L | Repl w/758F 2P Earthquake Zone Ph1C | 201510 | 4.15 | 6 | 0.0013083 | 0.03 | 0.07 |
| 376300-Mains - Plastic | 900765 | 3303L | Inst 1899F 4P Earthquake Zone Ph1D | 201509 | 40,343.95 | 7 | 0.0013083 | 369.47 | 633.38 |
| 376300-Mains - Plastic | 900775 | 3403L | Rel w/ 1535F 2P Page&Hodiamont AOR | 201509 | (567.54) | 7 | 0.0013083 | (5.20) | (8.91) |
| 376300-Mains - Plastic | 900822 | 3403L | Rel w/ 130F 6S Price Road | 201509 | (726.74) | 7 | 0.0013083 | (6.66) | (11.41) |
| 376300-Mains - Plastic | 900841 | 340RL | Rel w/ 57F 4P Ashland AOR | 201509 | (85.78) | 7 | 0.0013083 | (0.79) | (1.35) |

| | | | | | | | | | |
|------------------------|--------|-------|-------------------------------------|--------|--------------|---|-----------|----------|------------|
| 376300-Mains - Plastic | 900848 | 340RL | Rel w/ 810F 4P Bircher & Newstead | 201509 | (880.86) | 7 | 0.0013083 | (8.07) | (13.83) |
| 376300-Mains - Plastic | 900859 | 3303L | Repl w/ 290F 2P Cabanne | 201509 | (577.52) | 7 | 0.0013083 | (5.29) | (9.07) |
| 376300-Mains - Plastic | 900859 | 3303L | Repl w/ 290F 2P Cabanne | 201510 | 6.99 | 6 | 0.0013083 | 0.05 | 0.11 |
| 376300-Mains - Plastic | 900861 | 3303L | Repl w/ 105F 4P McLaran | 201509 | (32.91) | 7 | 0.0013083 | (0.30) | (0.52) |
| 376300-Mains - Plastic | 900862 | 3303L | Rep w/ 4552F 2P Broadway AOR | 201509 | (32,613.27) | 7 | 0.0013083 | (298.68) | (512.02) |
| 376300-Mains - Plastic | 900862 | 3303L | Repl w/ 4552F 2P Broadway AOR | 201510 | (14.29) | 6 | 0.0013083 | (0.11) | (0.22) |
| 376300-Mains - Plastic | 900862 | 3303L | Repl w/ 4552F 2P Broadway AOR | 201511 | 0.02 | 5 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900862 | 3303L | Repl w/ 4552F 2P Broadway AOR | 201512 | (0.97) | 4 | 0.0013083 | (0.01) | (0.02) |
| 376300-Mains - Plastic | 900871 | 3303L | Repl w/ 3201F 2P Baden Ph6F | 201512 | 123,314.47 | 4 | 0.0013083 | 645.33 | 1,935.99 |
| 376300-Mains - Plastic | 900876 | 3303L | Repl w/ 1060F 2P Rauschenbach PVC | 201509 | (660.31) | 7 | 0.0013083 | (6.05) | (10.37) |
| 376300-Mains - Plastic | 900876 | 3303L | Repl w/ 1060F 2P Rauschenbach PVC | 201510 | 453.39 | 6 | 0.0013083 | 3.56 | 7.12 |
| 376300-Mains - Plastic | 900876 | 3303L | Repl w/ 1060F 2P Rauschenbach PVC | 201511 | (0.34) | 5 | 0.0013083 | - | (0.01) |
| 376300-Mains - Plastic | 900876 | 3303L | Repl w/ 1060F 2P Rauschenbach PVC | 201512 | (4,356.04) | 4 | 0.0013083 | (22.80) | (68.39) |
| 376300-Mains - Plastic | 900890 | 3303L | Repl w/ 2218F 2P Russell & Flora | 201509 | (102,284.82) | 7 | 0.0013083 | (936.73) | (1,605.83) |
| 376300-Mains - Plastic | 900890 | 3303L | Repl w/ 2218F 2P Russell & Flora | 201510 | 53.95 | 6 | 0.0013083 | 0.42 | 0.85 |
| 376100-Mains - Steel | 900892 | 3403L | Rel w/ 180F 2S Elaine Drive | 201509 | (100.57) | 7 | 0.0012000 | (0.84) | (1.45) |
| 376300-Mains - Plastic | 900893 | 3303L | Repl w/ 2486F 6P Arlington | 201509 | (469.56) | 7 | 0.0013083 | (4.30) | (7.37) |
| 376300-Mains - Plastic | 900893 | 3303L | Repl w/ 2486F 6P Arlington | 201511 | (76.45) | 5 | 0.0013083 | (0.50) | (1.20) |
| 376300-Mains - Plastic | 900893 | 3303L | Repl w/ 2486F 6P Arlington | 201512 | (109.51) | 4 | 0.0013083 | (0.57) | (1.72) |
| 376300-Mains - Plastic | 900895 | 3303L | Repl w/ 828F 2P Marquette | 201509 | (64,879.04) | 7 | 0.0013083 | (594.17) | (1,018.57) |
| 376300-Mains - Plastic | 900895 | 3303L | Repl w/ 828F 2P Marquette | 201510 | (6.31) | 6 | 0.0013083 | (0.05) | (0.10) |
| 376300-Mains - Plastic | 900895 | 3303L | Repl w/ 828F 2P Marquette | 201512 | (0.82) | 4 | 0.0013083 | - | (0.01) |
| 376300-Mains - Plastic | 900896 | 3303L | Repl w/ 2990F 2P 4P Maple | 201509 | (1,333.98) | 7 | 0.0013083 | (12.22) | (20.94) |
| 376300-Mains - Plastic | 900896 | 3303L | Repl w/ 2990F 2P 4P Maple | 201510 | 149.08 | 6 | 0.0013083 | 1.17 | 2.34 |
| 376300-Mains - Plastic | 900896 | 3303L | Repl w/ 2990F 2P 4P Maple | 201511 | 1,032.84 | 5 | 0.0013083 | 6.76 | 16.22 |
| 376300-Mains - Plastic | 900896 | 3303L | Repl w/ 2990F 2P 4P Maple | 201512 | (144.91) | 4 | 0.0013083 | (0.76) | (2.28) |
| 376300-Mains - Plastic | 900897 | 3303L | Repl w/ 587F 2P Syracuse | 201509 | 1,441.88 | 7 | 0.0013083 | 13.20 | 22.64 |
| 376300-Mains - Plastic | 900897 | 3303L | Repl w/ 587F 2P Syracuse | 201511 | 657.62 | 5 | 0.0013083 | 4.30 | 10.32 |
| 376300-Mains - Plastic | 900897 | 3303L | Repl w/ 587F 2P Syracuse | 201512 | (162.03) | 4 | 0.0013083 | (0.85) | (2.54) |
| 376300-Mains - Plastic | 900898 | 3303L | Repl w/ 1220F 2P Ohio | 201509 | (13,628.71) | 7 | 0.0013083 | (124.81) | (213.97) |
| 376300-Mains - Plastic | 900898 | 3303L | Repl w/ 1220F 2P Ohio | 201510 | (2.13) | 6 | 0.0013083 | (0.02) | (0.03) |
| 376300-Mains - Plastic | 900900 | 3303L | Repl w/ 1075F 2P Washington | 201509 | 3,602.99 | 7 | 0.0013083 | 33.00 | 56.57 |
| 376300-Mains - Plastic | 900900 | 3303L | Repl w/ 1075F 2P Washington | 201510 | 26.89 | 6 | 0.0013083 | 0.21 | 0.42 |
| 376300-Mains - Plastic | 900902 | 3303L | Repl w/ 530' 2P Oakland | 201509 | (234.17) | 7 | 0.0013083 | (2.14) | (3.68) |
| 376300-Mains - Plastic | 900902 | 3303L | Repl w/ 530' 2P Oakland | 201510 | (63.69) | 6 | 0.0013083 | (0.50) | (1.00) |
| 376300-Mains - Plastic | 900905 | 3303L | Repl w/ 806F 2P Utah | 201509 | (4,938.82) | 7 | 0.0013083 | (45.23) | (77.54) |
| 376300-Mains - Plastic | 900905 | 3303L | Repl w/ 806F 2P Utah | 201510 | 7.97 | 6 | 0.0013083 | 0.06 | 0.13 |
| 376300-Mains - Plastic | 900906 | 3303L | Repl w/ 460F 2P California | 201509 | (455.99) | 7 | 0.0013083 | (4.18) | (7.16) |
| 376300-Mains - Plastic | 900908 | 3303L | Repl w/ 460F 2P California | 201510 | 6.41 | 6 | 0.0013083 | 0.05 | 0.10 |
| 376300-Mains - Plastic | 900911 | 3403L | Rel w/ 300F 2P Edgewood | 201509 | 0.10 | 7 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900912 | 3303L | Repl w/ 745F 2P Shaw | 201509 | (1,496.97) | 7 | 0.0013083 | (13.71) | (23.50) |
| 376300-Mains - Plastic | 900912 | 3303L | Repl w/ 745F 2P Shaw | 201510 | 34.85 | 6 | 0.0013083 | 0.27 | 0.55 |
| 376300-Mains - Plastic | 900921 | 3303L | Repl w/ 2457F 4P&2P Flad AOR | 201509 | (2,176.86) | 7 | 0.0013083 | (19.94) | (34.18) |
| 376300-Mains - Plastic | 900921 | 3303L | Repl w/ 2457F 4P&2P Flad AOR | 201510 | 8,340.17 | 6 | 0.0013083 | 65.47 | 130.94 |
| 376300-Mains - Plastic | 900948 | 3303L | Repl w/ 132F 2P Southcote | 201509 | 822.96 | 7 | 0.0013083 | 7.54 | 12.92 |
| 376300-Mains - Plastic | 900948 | 3303L | Repl w/ 132F 2P Southcote | 201510 | 0.60 | 6 | 0.0013083 | - | 0.01 |
| 376300-Mains - Plastic | 900961 | 3403L | Rel w/ 190F 2P Clay | 201509 | (26.46) | 7 | 0.0013083 | (0.24) | (0.42) |
| 376300-Mains - Plastic | 900977 | 3303L | Repl w/ 1291F 4P Boyle | 201509 | 29.11 | 7 | 0.0013083 | 0.27 | 0.46 |
| 376300-Mains - Plastic | 900986 | 3303L | Repl w/ 2189F 2P Earthquake Zone 2A | 201509 | (33,510.61) | 7 | 0.0013083 | (306.89) | (526.10) |
| 376300-Mains - Plastic | 900986 | 3303L | Repl w/ 2189F 2P Earthquake Zone 2A | 201510 | (58.62) | 6 | 0.0013083 | (0.46) | (0.92) |
| 376300-Mains - Plastic | 900988 | 3303L | Repl w/ 3840F 2P Earthquake Zn Ph2B | 201509 | 130,921.07 | 7 | 0.0013083 | 1,198.99 | 2,055.41 |

| | | | | | | | | | |
|------------------------|--------|-------|-------------------------------------|--------|------------|---|-----------|--------|----------|
| 376300-Mains - Plastic | 900988 | 3303L | Repl w/ 3840F 2P Earthquake Zn Ph2B | 201510 | 207.36 | 6 | 0.0013083 | 1.63 | 3.26 |
| 376300-Mains - Plastic | 900988 | 3303L | Repl w/ 3840F 2P Earthquake Zn Ph2B | 201511 | (918.56) | 5 | 0.0013083 | (6.01) | (14.42) |
| 376300-Mains - Plastic | 900988 | 3303L | Repl w/ 3840F 2P Earthquake Zn Ph2B | 201512 | 18.09 | 4 | 0.0013083 | 0.09 | 0.28 |
| 376300-Mains - Plastic | 900993 | 3303L | Repl w/ 2220F 2P CentralWestEndPh1G | 201511 | 844.95 | 5 | 0.0013083 | 5.53 | 13.27 |
| 376300-Mains - Plastic | 901011 | 340RL | Rel w/ 450F 4P Sanford AOR | 201509 | 11,350.40 | 7 | 0.0013083 | 103.95 | 178.20 |
| 376300-Mains - Plastic | 901011 | 340RL | Rel w/ 450F 4P Sanford AOR | 201510 | (35.57) | 6 | 0.0013083 | (0.28) | (0.56) |
| 376300-Mains - Plastic | 901015 | 340RL | Rel w/ 35F 4P Elmbank & Taylor AOR | 201509 | (1,019.70) | 7 | 0.0013083 | (9.34) | (16.01) |
| 376100-Mains - Steel | 901019 | 3403L | Rel w/ 80F 6S Fee Fee | 201509 | (22.70) | 7 | 0.0012000 | (0.19) | (0.33) |
| 376100-Mains - Steel | 901019 | 3403L | Rel w/ 80F 6S Fee Fee | 201510 | (26.98) | 6 | 0.0012000 | (0.19) | (0.39) |
| 376300-Mains - Plastic | 901022 | 3403L | Rel w/ 427F 2P Valley Park SE | 201509 | (506.70) | 7 | 0.0013083 | (4.64) | (7.95) |
| 376300-Mains - Plastic | 901040 | 3303L | Repl w/ 315F 2P Amherst Ave | 201509 | (296.05) | 7 | 0.0013083 | (2.71) | (4.65) |
| 376300-Mains - Plastic | 901059 | 3303L | Repl w/ 680' 2P Gregg | 201509 | 36,205.77 | 7 | 0.0013083 | 331.58 | 568.42 |
| 376300-Mains - Plastic | 901059 | 3303L | Repl w/ 680' 2P Gregg | 201510 | 729.87 | 6 | 0.0013083 | 5.73 | 11.46 |
| 376300-Mains - Plastic | 901059 | 3303L | Repl w/ 680' 2P Gregg | 201511 | (495.83) | 5 | 0.0013083 | (3.24) | (7.78) |
| 376300-Mains - Plastic | 901059 | 3303L | Repl w/ 680' 2P Gregg | 201512 | 17.41 | 4 | 0.0013083 | 0.09 | 0.27 |
| 376300-Mains - Plastic | 901063 | 340RL | Rel w/ 1307F 4P Bessie AOR | 201509 | 86,750.41 | 7 | 0.0013083 | 794.47 | 1,361.95 |
| 376300-Mains - Plastic | 901063 | 340RL | Rel w/ 1307F 4P Bessie AOR | 201510 | 211.04 | 6 | 0.0013083 | 1.66 | 3.31 |
| 376300-Mains - Plastic | 901063 | 340RL | Rel w/ 1307F 4P Bessie AOR | 201511 | 4,342.54 | 5 | 0.0013083 | 28.41 | 68.18 |
| 376300-Mains - Plastic | 901063 | 340RL | Rel w/ 1307F 4P Bessie AOR | 201512 | 19.15 | 4 | 0.0013083 | 0.10 | 0.30 |
| 376300-Mains - Plastic | 901071 | 3403L | Rel w/ 285F 2P Froesel Ph2 | 201509 | (28.80) | 7 | 0.0013083 | (0.26) | (0.45) |
| 376300-Mains - Plastic | 901071 | 3403L | Rel w/ 285F 2P Froesel Ph2 | 201511 | 18.46 | 5 | 0.0013083 | 0.12 | 0.29 |
| 376300-Mains - Plastic | 901071 | 3403L | Rel w/ 285F 2P Froesel Ph2 | 201512 | (3.72) | 4 | 0.0013083 | (0.02) | (0.06) |
| 376300-Mains - Plastic | 901081 | 3403L | Rel w/ 970F 6P Pralle Lane | 201512 | 7,738.91 | 4 | 0.0013083 | 40.50 | 121.50 |
| 376300-Mains - Plastic | 901088 | 3303L | Repl w/ 4597F 2P U-City Ph1B | 201512 | 127,254.14 | 4 | 0.0013083 | 665.95 | 1,997.84 |
| 376300-Mains - Plastic | 901106 | 3403L | Rel w/ 38F 4P Compton AOR | 201509 | (53.56) | 7 | 0.0013083 | (0.49) | (0.84) |
| 376300-Mains - Plastic | 901106 | 3403L | Rel w/ 38F 4P Compton AOR | 201511 | 50.94 | 5 | 0.0013083 | 0.33 | 0.80 |
| 376300-Mains - Plastic | 901106 | 3403L | Rel w/ 38F 4P Compton AOR | 201512 | 59.77 | 4 | 0.0013083 | 0.31 | 0.94 |
| 376300-Mains - Plastic | 901107 | 3403L | Rel w/ 62F 4P Southwest AOR | 201509 | (112.98) | 7 | 0.0013083 | (1.03) | (1.77) |
| 376300-Mains - Plastic | 901107 | 3403L | Rel w/ 62F 4P Southwest AOR | 201511 | 74.23 | 5 | 0.0013083 | 0.49 | 1.17 |
| 376300-Mains - Plastic | 901107 | 3403L | Rel w/ 62F 4P Southwest AOR | 201512 | (57.92) | 4 | 0.0013083 | (0.30) | (0.91) |
| 376300-Mains - Plastic | 901111 | 3303L | Repl w/ 955F 2P Hickory | 201509 | 39,837.13 | 7 | 0.0013083 | 364.83 | 625.43 |
| 376300-Mains - Plastic | 901111 | 3303L | Repl w/ 955F 2P Hickory | 201510 | 2,993.07 | 6 | 0.0013083 | 23.50 | 46.99 |
| 376300-Mains - Plastic | 901111 | 3303L | Repl w/ 955F 2P Hickory | 201511 | (587.87) | 5 | 0.0013083 | (3.85) | (9.23) |
| 376300-Mains - Plastic | 901111 | 3303L | Repl w/ 955F 2P Hickory | 201512 | 57.72 | 4 | 0.0013083 | 0.30 | 0.91 |
| 376300-Mains - Plastic | 901114 | 3303L | Repl w/ 1630F 2P Maffitt | 201512 | 43,124.45 | 4 | 0.0013083 | 225.68 | 677.04 |
| 376300-Mains - Plastic | 901139 | 3303L | Repl w/ 901F 2P Suburban Ave | 201509 | 7,283.29 | 7 | 0.0013083 | 66.70 | 114.34 |
| 376300-Mains - Plastic | 901139 | 3303L | Repl w/ 901F 2P Suburban Ave | 201510 | 1,543.49 | 6 | 0.0013083 | 12.12 | 24.23 |
| 376300-Mains - Plastic | 901139 | 3303L | Repl w/ 901F 2P Suburban Ave | 201511 | (46.49) | 5 | 0.0013083 | (0.30) | (0.73) |
| 376300-Mains - Plastic | 901139 | 3303L | Repl w/ 901F 2P Suburban Ave | 201512 | (0.94) | 4 | 0.0013083 | - | (0.01) |
| 376300-Mains - Plastic | 901162 | 3303L | Repl w/ 210F 2P St. Leonard Ct. | 201512 | 18,186.66 | 4 | 0.0013083 | 95.17 | 285.52 |
| 376300-Mains - Plastic | 901173 | 3403L | Vandeventer - City of St. Louis MRE | 201509 | (26.91) | 7 | 0.0013083 | (0.25) | (0.42) |
| 376300-Mains - Plastic | 901173 | 3403L | Rel w/ 260F 6P Vandeventer | 201511 | (20.90) | 5 | 0.0013083 | (0.14) | (0.33) |
| 376300-Mains - Plastic | 901173 | 3403L | Rel w/ 260F 6P Vandeventer | 201512 | 0.52 | 4 | 0.0013083 | - | 0.01 |
| 376300-Mains - Plastic | 901178 | 3303L | Repl w/ 185F 2P Evans | 201509 | 4,324.10 | 7 | 0.0013083 | 39.60 | 67.89 |
| 376300-Mains - Plastic | 901178 | 3303L | Repl w/ 185F 2P Evans | 201510 | 333.31 | 6 | 0.0013083 | 2.62 | 5.23 |
| 376300-Mains - Plastic | 901178 | 3303L | Repl w/ 185F 2P Evans | 201511 | (0.34) | 5 | 0.0013083 | - | (0.01) |
| 376300-Mains - Plastic | 901178 | 3303L | Repl w/ 185F 2P Evans | 201512 | 12.67 | 4 | 0.0013083 | 0.07 | 0.20 |
| 376300-Mains - Plastic | | 3303L | SERVICE TRANSFER WORK ORDERS | 201601 | | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | | 3303L | SERVICE TRANSFER WORK ORDERS | 201602 | | 2 | 0.0013083 | - | - |

TOTAL 1,634,215.10 11,374.30 25,656.70

ACCOUNT 37620 MAINS CAST IRON LEAK CLAMPS

| PLANT ACCOUNT | WORK ORDER | BUDGET PROJECT | DESCRIPTION | IN SERVICE DATE | ADDITION AMOUNT | MONTHS | DEPR. MO. RATE | ACCUM. DEPR. | DEPR. EXPENSE |
|--------------------------|------------|----------------|--------------------------|-----------------|-------------------|--------|----------------|------------------|------------------|
| 376200-Mains - Cast Iron | 699010 | 3503L | 69901 MN LEAK CLAMPS CTY | 201509 | 134,905.03 | 7 | 0.0027583 | 2,604.76 | 4,465.30 |
| 376200-Mains - Cast Iron | 699010 | 3503L | 69901 MN LEAK CLAMPS CTY | 201510 | 162,185.59 | 6 | 0.0027583 | 2,684.14 | 5,368.28 |
| 376200-Mains - Cast Iron | 699010 | 3503L | 69901 MN LEAK CLAMPS CTY | 201511 | 136,594.06 | 5 | 0.0027583 | 1,883.84 | 4,521.21 |
| 376200-Mains - Cast Iron | 699010 | 3503L | 69901 MN LEAK CLAMPS CTY | 201512 | 169,339.75 | 4 | 0.0027583 | 1,868.36 | 5,605.08 |
| 376200-Mains - Cast Iron | 699510 | 3503L | 69951 MN LEAK CLAMPS CO | 201509 | 6,396.44 | 7 | 0.0027583 | 123.50 | 211.72 |
| 376200-Mains - Cast Iron | 699510 | 3503L | 69951 MN LEAK CLAMPS CO | 201510 | 4,785.10 | 6 | 0.0027583 | 79.19 | 158.38 |
| 376200-Mains - Cast Iron | 699510 | 3503L | 69951 MN LEAK CLAMPS CO | 201511 | 261.37 | 5 | 0.0027583 | 3.60 | 8.65 |
| 376200-Mains - Cast Iron | 699510 | 3503L | 69951 MN LEAK CLAMPS CO | 201512 | 51.71 | 4 | 0.0027583 | 0.57 | 1.71 |
| 376200-Mains - Cast Iron | | 3503L | Mains Clamping | 201601 | 170,000.00 | 3 | 0.0027583 | 1,406.73 | 5,626.93 |
| 376200-Mains - Cast Iron | | 3503L | Mains Clamping | 201602 | 170,000.00 | 2 | 0.0027583 | 937.82 | 5,626.93 |
| TOTAL | | | | | <u>954,519.05</u> | | | <u>11,592.51</u> | <u>31,594.19</u> |

ACCOUNT 37670 MAINS CATHODIC PROTECTION

| PLANT ACCOUNT | WORK ORDER | BUDGET PROJECT | DESCRIPTION | IN SERVICE DATE | ADDITION AMOUNT | MONTHS | DEPR. MO. RATE | ACCUM. DEPR. | DEPR. EXPENSE |
|----------------------|------------|----------------|--|-----------------|------------------|--------|----------------|---------------|---------------|
| 376100-Mains - Steel | 697390 | 3501M | 69739 CATHODIC PROT MAIN | 201509 | 4,902.32 | 7 | 0.0012000 | 41.18 | 70.59 |
| 376100-Mains - Steel | 697390 | 3501M | 69739 CATHODIC PROT MAIN | 201510 | 2,129.19 | 6 | 0.0012000 | 15.33 | 30.66 |
| 376100-Mains - Steel | 697390 | 3501M | 69739 CATHODIC PROT MAIN | 201511 | 2,667.94 | 5 | 0.0012000 | 16.01 | 38.42 |
| 376100-Mains - Steel | 697390 | 3501M | 69739 CATHODIC PROT MAIN | 201512 | 350.93 | 4 | 0.0012000 | 1.68 | 5.05 |
| 376100-Mains - Steel | | 3503L | ACCOUNT 37670 MAINS CATHODIC PROTECTIO | 201601 | 2,500.00 | 3 | 0.0027583 | 20.69 | 62.75 |
| 376100-Mains - Steel | | 3503L | ACCOUNT 37670 MAINS CATHODIC PROTECTIO | 201602 | 2,500.00 | 2 | 0.0027583 | 13.79 | 62.75 |
| TOTAL | | | | | <u>15,050.38</u> | | | <u>108.68</u> | <u>310.22</u> |

Total Main Replacements and Other Projects Extending Useful Life of Mains 19,933,736.40 105,765.27 329,555.09

SERVICE LINE REPLACEMENTS AND INSERTION PROJECTS - ADDITIONS

ACCOUNT 38010 SERVICES STEEL

| PLANT ACCOUNT | WORK ORDER | BUDGET PROJECT | DESCRIPTION | IN SERVICE DATE | ADDITION AMOUNT | MONTHS | DEPR. MO. RATE | ACCUM. DEPR. | DEPR. EXPENSE |
|-------------------------|------------|----------------|--------------------------|-----------------|-----------------|--------|----------------|--------------|---------------|
| 380100-Services - Steel | 695160 | | 69516 SVC RENEW STEEL SO | 201509 | 81,095.87 | 7 | 0.0043583 | 2,474.08 | 4,241.28 |
| 380100-Services - Steel | 695160 | | 69516 SVC RENEW STEEL SO | 201510 | 76,786.45 | 6 | 0.0043583 | 2,007.95 | 4,015.90 |
| 380100-Services - Steel | 695160 | | 69516 SVC RENEW STEEL SO | 201511 | 17,413.27 | 5 | 0.0043583 | 379.46 | 910.71 |
| 380100-Services - Steel | 695160 | | 69516 SVC RENEW STEEL SO | 201512 | 68,965.64 | 4 | 0.0043583 | 1,202.29 | 3,606.88 |
| 380100-Services - Steel | 695660 | | 69566 SVC RENEW STEEL NO | 201509 | (783.38) | 7 | 0.0043583 | (23.90) | (40.97) |
| 380100-Services - Steel | 696300 | | 69630 SVC RENEW STEEL MW | 201509 | (2,060.69) | 7 | 0.0043583 | (62.87) | (107.77) |
| 380100-Services - Steel | 697300 | | 69730 SVC RENEW STEEL MN | 201509 | 4,477.72 | 7 | 0.0043583 | 136.61 | 234.18 |
| 380100-Services - Steel | 697300 | | 69730 SVC RENEW STEEL MN | 201511 | 10,376.31 | 5 | 0.0043583 | 226.12 | 542.68 |
| 380100-Services - Steel | 697300 | | 69730 SVC RENEW STEEL MN | 201512 | (1,623.36) | 4 | 0.0043583 | (28.30) | (84.90) |
| 380100-Services - Steel | 698300 | | 69830 SVC RENEW STEEL SC | 201509 | 7,544.20 | 7 | 0.0043583 | 230.16 | 394.56 |
| 380100-Services - Steel | 698300 | | 69830 SVC RENEW STEEL SC | 201511 | (221.28) | 5 | 0.0043583 | (4.82) | (11.57) |

| | | | | | | | | | | |
|-------------------------|--------|--|-----------------------------------|--------------|-------------------|---|-----------|------------------|------------------|---|
| 380100-Services - Steel | 698300 | | 69830 SVC RENEW STEEL SC | 201512 | 3.19 | 4 | 0.0043583 | 0.06 | 0.17 | |
| 380100-Services - Steel | 699160 | | 69916 SVC RENEW STEEL C | 201509 | 73,559.19 | 7 | 0.0043583 | 2,244.15 | 3,847.12 | |
| 380100-Services - Steel | 699160 | | 69916 SVC RENEW STEEL C | 201510 | 64,801.56 | 6 | 0.0043583 | 1,694.55 | 3,389.10 | |
| 380100-Services - Steel | 699160 | | 69916 SVC RENEW STEEL C | 201511 | 32,210.34 | 5 | 0.0043583 | 701.91 | 1,684.59 | |
| 380100-Services - Steel | 699160 | | 69916 SVC RENEW STEEL C | 201512 | 30,000.85 | 4 | 0.0043583 | 523.01 | 1,569.03 | |
| 380100-Services - Steel | 900266 | | Inst 4640F 2P Baden Ph 5C | 201509 | (0.04) | 7 | 0.0043583 | - | - | |
| 380100-Services - Steel | 900266 | | Inst 4640F 2P Baden Ph 5C | 201510 | 0.16 | 6 | 0.0043583 | - | 0.01 | |
| 380100-Services - Steel | 900266 | | Inst 4640F 2P Baden Ph 5C | 201511 | (0.01) | 5 | 0.0043583 | - | - | |
| 380100-Services - Steel | 900266 | | Inst 4640F 2P Baden Ph 5C | 201512 | 0.79 | 4 | 0.0043583 | 0.01 | 0.04 | |
| 380100-Services - Steel | 900279 | | Repl w/ 3345F 2P Walnut Park Ph4D | 201509 | (33.39) | 7 | 0.0043583 | (1.02) | (1.75) | |
| 380100-Services - Steel | 900892 | | Rel w/ 180F 2S Elaine Drive | 201509 | (163.70) | 7 | 0.0043583 | (4.99) | (8.56) | |
| 380100-Services - Steel | 900900 | | Repl w/ 1075F 2P Washington | 201509 | 7,104.30 | 7 | 0.0043583 | 216.74 | 371.55 | |
| 380100-Services - Steel | 900900 | | Repl w/ 1075F 2P Washington | 201510 | 3.20 | 6 | 0.0043583 | 0.08 | 0.17 | |
| 380100-Services - Steel | 901011 | | Rel w/ 450F 4P Sanford AOR | 201509 | (15,149.95) | 7 | 0.0043583 | (462.20) | (792.34) | |
| 380100-Services - Steel | | | ACCOUNT 38010 SERVICES STEEL | 201601 | | | 3 | 0.0043583 | - | - |
| 380100-Services - Steel | | | ACCOUNT 38010 SERVICES STEEL | 201602 | | | 2 | 0.0043583 | - | - |
| | | | | TOTAL | 454,307.24 | | | 11,449.08 | 23,760.11 | |

ACCOUNT 38020 SERVICES PLASTIC & COPPER

| PLANT ACCOUNT | WORK ORDER | BUDGET PROJECT | DESCRIPTION | IN SERVICE DATE | ADDITION AMOUNT | MONTHS | DEPR. MO. RATE | ACCUM. DEPR. | DEPR. EXPENSE |
|------------------------------------|------------|----------------|------------------------------|-----------------|-----------------|--------|----------------|--------------|---------------|
| 380200-Services - Plastic & Copper | 694250 | | 69425 SVC RNW PLS 5/8IN | 201509 | 2,847.96 | 7 | 0.0031250 | 62.30 | 106.80 |
| 380200-Services - Plastic & Copper | 694370 | | 69437 SVCS RENEW PLS 5/4-2IN | 201509 | 38.10 | 7 | 0.0031250 | 0.83 | 1.43 |
| 380200-Services - Plastic & Copper | 695300 | | 69530 SVC REN 1/2 PL SO | 201509 | 1,015,583.28 | 7 | 0.0031250 | 22,215.88 | 38,084.37 |
| 380200-Services - Plastic & Copper | 695300 | | 69530 SVC REN 1/2 PL SO | 201510 | 819,355.35 | 6 | 0.0031250 | 15,362.91 | 30,725.83 |
| 380200-Services - Plastic & Copper | 695300 | | 69530 SVC REN 1/2 PL SO | 201511 | 699,429.55 | 5 | 0.0031250 | 10,928.59 | 26,228.61 |
| 380200-Services - Plastic & Copper | 695300 | | 69530 SVC REN 1/2 PL SO | 201512 | 778,786.74 | 4 | 0.0031250 | 9,734.83 | 29,204.50 |
| 380200-Services - Plastic & Copper | 695310 | | 69531 SV REN 1IN PL SO | 201509 | (8,796.56) | 7 | 0.0031250 | (192.42) | (329.87) |
| 380200-Services - Plastic & Copper | 695310 | | 69531 SV REN 1IN PL SO | 201510 | 64,389.29 | 6 | 0.0031250 | 1,207.30 | 2,414.60 |
| 380200-Services - Plastic & Copper | 695310 | | 69531 SV REN 1IN PL SO | 201511 | 25,419.91 | 5 | 0.0031250 | 397.19 | 953.25 |
| 380200-Services - Plastic & Copper | 695310 | | 69531 SV REN 1IN PL SO | 201512 | 49,459.64 | 4 | 0.0031250 | 618.25 | 1,854.74 |
| 380200-Services - Plastic & Copper | 695320 | | 69532 SV REN 1 1/4 PL SO | 201509 | (1,131.57) | 7 | 0.0031250 | (24.75) | (42.43) |
| 380200-Services - Plastic & Copper | 695320 | | 69532 SV REN 1 1/4 PL SO | 201510 | (6,258.83) | 6 | 0.0031250 | (117.35) | (234.71) |
| 380200-Services - Plastic & Copper | 695320 | | 69532 SV REN 1 1/4 PL SO | 201512 | 5,351.42 | 4 | 0.0031250 | 66.89 | 200.68 |
| 380200-Services - Plastic & Copper | 695330 | | 69533 SV REN 2&OVR PL SO | 201509 | (457.46) | 7 | 0.0031250 | (10.01) | (17.15) |
| 380200-Services - Plastic & Copper | 695330 | | 69533 SV REN 2&OVR PL SO | 201511 | (2,037.82) | 5 | 0.0031250 | (31.84) | (76.42) |
| 380200-Services - Plastic & Copper | 695330 | | 69533 SV REN 2&OVR PL SO | 201512 | 9.97 | 4 | 0.0031250 | 0.12 | 0.37 |
| 380200-Services - Plastic & Copper | 695800 | | 69580 SVC REN 1/2 PL NO | 201509 | 14,906.84 | 7 | 0.0031250 | 326.09 | 559.01 |
| 380200-Services - Plastic & Copper | 695800 | | 69580 SVC REN 1/2 PL NO | 201510 | 59,569.83 | 6 | 0.0031250 | 1,116.93 | 2,233.87 |
| 380200-Services - Plastic & Copper | 695800 | | 69580 SVC REN 1/2 PL NO | 201511 | 28,817.24 | 5 | 0.0031250 | 450.27 | 1,080.65 |
| 380200-Services - Plastic & Copper | 695800 | | 69580 SVC REN 1/2 PL NO | 201512 | 62,661.33 | 4 | 0.0031250 | 783.27 | 2,349.80 |
| 380200-Services - Plastic & Copper | 695810 | | 69581 SV REN 1IN PL NO | 201509 | (1,610.04) | 7 | 0.0031250 | (35.22) | (60.38) |
| 380200-Services - Plastic & Copper | 695810 | | 69581 SV REN 1IN PL NO | 201510 | 12,482.83 | 6 | 0.0031250 | 233.68 | 467.36 |
| 380200-Services - Plastic & Copper | 695810 | | 69581 SV REN 1IN PL NO | 201511 | 17,438.35 | 5 | 0.0031250 | 272.47 | 653.94 |
| 380200-Services - Plastic & Copper | 695810 | | 69581 SV REN 1IN PL NO | 201512 | 2,691.06 | 4 | 0.0031250 | 33.64 | 100.91 |
| 380200-Services - Plastic & Copper | 695820 | | 69582 SV REN 1 1/4 PL NO | 201509 | (5,057.09) | 7 | 0.0031250 | (110.62) | (189.64) |
| 380200-Services - Plastic & Copper | 695820 | | 69582 SV REN 1 1/4 PL NO | 201510 | 23,290.43 | 6 | 0.0031250 | 436.70 | 873.39 |
| 380200-Services - Plastic & Copper | 695820 | | 69582 SV REN 1 1/4 PL NO | 201511 | 765.11 | 5 | 0.0031250 | 11.95 | 28.69 |
| 380200-Services - Plastic & Copper | 695820 | | 69582 SV REN 1 1/4 PL NO | 201512 | 379.80 | 4 | 0.0031250 | 4.75 | 14.24 |
| 380200-Services - Plastic & Copper | 695830 | | 69583 SV REN 2&OVR PL NO | 201509 | (123.77) | 7 | 0.0031250 | (2.71) | (4.64) |
| 380200-Services - Plastic & Copper | 695830 | | 69583 SV REN 2&OVR PL NO | 201511 | (2,937.13) | 5 | 0.0031250 | (45.89) | (110.14) |
| 380200-Services - Plastic & Copper | 695830 | | 69583 SV REN 2&OVR PL NO | 201512 | 2,406.75 | 4 | 0.0031250 | 30.08 | 90.25 |
| 380200-Services - Plastic & Copper | 695840 | | 69584 RNW COPPER SVCS-NORTH | 201509 | (563.97) | 7 | 0.0031250 | (12.34) | (21.15) |

| | | | | | | | | |
|------------------------------------|--------|--------------------------------|--------|------------|---|-----------|----------|-----------|
| 380200-Services - Plastic & Copper | 696400 | 69640 SVC REN COR TRFR MIDW | 201509 | (10.30) | 7 | 0.0031250 | (0.23) | (0.39) |
| 380200-Services - Plastic & Copper | 696400 | 69640 SVC REN COR TRFR MIDW | 201510 | (154.25) | 6 | 0.0031250 | (2.89) | (5.78) |
| 380200-Services - Plastic & Copper | 696400 | 69640 SVC REN COR TRFR MIDW | 201511 | (4.88) | 5 | 0.0031250 | (0.08) | (0.18) |
| 380200-Services - Plastic & Copper | 696400 | 69640 SVC REN COR TRFR MIDW | 201512 | 0.90 | 4 | 0.0031250 | 0.01 | 0.03 |
| 380200-Services - Plastic & Copper | 696450 | 69645 SVC REN 1/2 PL MW | 201509 | (2,034.80) | 7 | 0.0031250 | (44.51) | (76.31) |
| 380200-Services - Plastic & Copper | 696450 | 69645 SVC REN 1/2 PL MW | 201510 | 6,942.87 | 6 | 0.0031250 | 130.18 | 260.36 |
| 380200-Services - Plastic & Copper | 696450 | 69645 SVC REN 1/2 PL MW | 201511 | 6,015.88 | 5 | 0.0031250 | 94.00 | 225.60 |
| 380200-Services - Plastic & Copper | 696450 | 69645 SVC REN 1/2 PL MW | 201512 | 12,028.49 | 4 | 0.0031250 | 150.36 | 451.07 |
| 380200-Services - Plastic & Copper | 696460 | 69646 SVC REN 1IN PL MW | 201509 | (51.38) | 7 | 0.0031250 | (1.12) | (1.93) |
| 380200-Services - Plastic & Copper | 696470 | 69647 SV REN 1-1/4 PL MW | 201509 | (94.23) | 7 | 0.0031250 | (2.06) | (3.53) |
| 380200-Services - Plastic & Copper | 696480 | 69648 SV REN 2&OVR PL MW | 201509 | 47,782.12 | 7 | 0.0031250 | 1,045.23 | 1,791.83 |
| 380200-Services - Plastic & Copper | 696480 | 69648 SV REN 2&OVR PL MW | 201510 | 2,539.45 | 6 | 0.0031250 | 47.61 | 95.23 |
| 380200-Services - Plastic & Copper | 696480 | 69648 SV REN 2&OVR PL MW | 201511 | (4.64) | 5 | 0.0031250 | (0.07) | (0.17) |
| 380200-Services - Plastic & Copper | 696480 | 69648 SV REN 2&OVR PL MW | 201512 | 2,432.22 | 4 | 0.0031250 | 30.40 | 91.21 |
| 380200-Services - Plastic & Copper | 697450 | 69745 SVC REN 1/2 PL MN | 201509 | 16,580.43 | 7 | 0.0031250 | 362.70 | 621.77 |
| 380200-Services - Plastic & Copper | 697450 | 69745 SVC REN 1/2 PL MN | 201510 | 33,691.07 | 6 | 0.0031250 | 631.71 | 1,263.42 |
| 380200-Services - Plastic & Copper | 697450 | 69745 SVC REN 1/2 PL MN | 201511 | 15,513.72 | 5 | 0.0031250 | 242.40 | 581.76 |
| 380200-Services - Plastic & Copper | 697450 | 69745 SVC REN 1/2 PL MN | 201512 | 43,142.55 | 4 | 0.0031250 | 539.28 | 1,617.85 |
| 380200-Services - Plastic & Copper | 697460 | 69746 SVC RNW 1IN PL MN | 201509 | (640.69) | 7 | 0.0031250 | (14.02) | (24.03) |
| 380200-Services - Plastic & Copper | 697460 | 69746 SVC RNW 1IN PL MN | 201510 | 50.25 | 6 | 0.0031250 | 0.94 | 1.88 |
| 380200-Services - Plastic & Copper | 697460 | 69746 SVC RNW 1IN PL MN | 201511 | (0.19) | 5 | 0.0031250 | - | (0.01) |
| 380200-Services - Plastic & Copper | 697460 | 69746 SVC RNW 1IN PL MN | 201512 | 1.76 | 4 | 0.0031250 | 0.02 | 0.07 |
| 380200-Services - Plastic & Copper | 697470 | 69747 SVC RNW 5/4 PL MN | 201509 | (1,192.78) | 7 | 0.0031250 | (26.09) | (44.73) |
| 380200-Services - Plastic & Copper | 697480 | 69748 SVC RNW 2" & OVR MN | 201509 | 587.15 | 7 | 0.0031250 | 12.84 | 22.02 |
| 380200-Services - Plastic & Copper | 697480 | 69748 SVC RNW 2" & OVR MN | 201510 | (1,537.00) | 6 | 0.0031250 | (28.82) | (57.64) |
| 380200-Services - Plastic & Copper | 697480 | 69748 SVC RNW 2" & OVR MN | 201511 | (1,979.00) | 5 | 0.0031250 | (30.92) | (74.21) |
| 380200-Services - Plastic & Copper | 697480 | 69748 SVC RNW 2" & OVR MN | 201512 | 447.00 | 4 | 0.0031250 | 5.59 | 16.76 |
| 380200-Services - Plastic & Copper | 698400 | 69840 SVC RNW COR TRFR STCH | 201509 | (1,067.24) | 7 | 0.0031250 | (23.35) | (40.02) |
| 380200-Services - Plastic & Copper | 698400 | 69840 SVC RNW COR TRFR STCH | 201510 | (7,713.26) | 6 | 0.0031250 | (144.62) | (289.25) |
| 380200-Services - Plastic & Copper | 698400 | 69840 SVC RNW COR TRFR STCH | 201511 | (6,755.26) | 5 | 0.0031250 | (105.55) | (253.32) |
| 380200-Services - Plastic & Copper | 698400 | 69840 SVC RNW COR TRFR STCH | 201512 | (3,236.25) | 4 | 0.0031250 | (40.45) | (121.36) |
| 380200-Services - Plastic & Copper | 698450 | 69845 SVC RNW 1/2 PL SC | 201509 | 87,612.81 | 7 | 0.0031250 | 1,916.53 | 3,285.48 |
| 380200-Services - Plastic & Copper | 698450 | 69845 SVC RNW 1/2 PL SC | 201510 | 57,300.46 | 6 | 0.0031250 | 1,074.38 | 2,148.77 |
| 380200-Services - Plastic & Copper | 698450 | 69845 SVC RNW 1/2 PL SC | 201511 | 61,747.62 | 5 | 0.0031250 | 964.81 | 2,315.54 |
| 380200-Services - Plastic & Copper | 698450 | 69845 SVC RNW 1/2 PL SC | 201512 | 62,357.71 | 4 | 0.0031250 | 779.47 | 2,338.41 |
| 380200-Services - Plastic & Copper | 698460 | 69846 SVC RNW 1IN PL SC | 201509 | (1,223.21) | 7 | 0.0031250 | (26.76) | (45.87) |
| 380200-Services - Plastic & Copper | 698460 | 69846 SVC RNW 1IN PL SC | 201510 | 3,336.74 | 6 | 0.0031250 | 62.56 | 125.13 |
| 380200-Services - Plastic & Copper | 698460 | 69846 SVC RNW 1IN PL SC | 201511 | (425.22) | 5 | 0.0031250 | (6.64) | (15.95) |
| 380200-Services - Plastic & Copper | 698460 | 69846 SVC RNW 1IN PL SC | 201512 | 34.08 | 4 | 0.0031250 | 0.43 | 1.28 |
| 380200-Services - Plastic & Copper | 698470 | 69847 SV RNW 1-1/4 PL SC | 201510 | (486.94) | 6 | 0.0031250 | (9.13) | (18.26) |
| 380200-Services - Plastic & Copper | 698480 | 69848 SV RNW 2&OVR PL SC | 201509 | 38,674.77 | 7 | 0.0031250 | 846.01 | 1,450.30 |
| 380200-Services - Plastic & Copper | 698480 | 69848 SV RNW 2&OVR PL SC | 201510 | 369.08 | 6 | 0.0031250 | 6.92 | 13.84 |
| 380200-Services - Plastic & Copper | 698480 | 69848 SV RNW 2&OVR PL SC | 201511 | (190.60) | 5 | 0.0031250 | (2.98) | (7.15) |
| 380200-Services - Plastic & Copper | 698480 | 69848 SV RNW 2&OVR PL SC | 201512 | 15.49 | 4 | 0.0031250 | 0.19 | 0.58 |
| 380200-Services - Plastic & Copper | 698500 | 69850 RELAY COPPER SVC- ST CHR | 201509 | (0.79) | 7 | 0.0031250 | (0.02) | (0.03) |
| 380200-Services - Plastic & Copper | 699300 | 69930 SVC REN 1/2 PL CTY | 201509 | 432,940.00 | 7 | 0.0031250 | 9,470.56 | 16,235.25 |
| 380200-Services - Plastic & Copper | 699300 | 69930 SVC REN 1/2 PL CTY | 201510 | 434,467.63 | 6 | 0.0031250 | 8,146.27 | 16,292.54 |
| 380200-Services - Plastic & Copper | 699300 | 69930 SVC REN 1/2 PL CTY | 201511 | 317,649.33 | 5 | 0.0031250 | 4,963.27 | 11,911.85 |
| 380200-Services - Plastic & Copper | 699300 | 69930 SVC REN 1/2 PL CTY | 201512 | 280,160.74 | 4 | 0.0031250 | 3,502.01 | 10,506.03 |
| 380200-Services - Plastic & Copper | 699310 | 69931 SVC REN 1IN PL CTY | 201509 | 53,316.64 | 7 | 0.0031250 | 1,166.30 | 1,999.37 |
| 380200-Services - Plastic & Copper | 699310 | 69931 SVC REN 1IN PL CTY | 201510 | 83,810.28 | 6 | 0.0031250 | 1,571.44 | 3,142.89 |
| 380200-Services - Plastic & Copper | 699310 | 69931 SVC REN 1IN PL CTY | 201511 | 100,483.86 | 5 | 0.0031250 | 1,570.06 | 3,768.14 |
| 380200-Services - Plastic & Copper | 699310 | 69931 SVC REN 1IN PL CTY | 201512 | 30,648.41 | 4 | 0.0031250 | 383.11 | 1,149.32 |
| 380200-Services - Plastic & Copper | 699320 | 69932 SVC REN 1 1/4 PL C | 201509 | 7,579.91 | 7 | 0.0031250 | 165.81 | 284.25 |
| 380200-Services - Plastic & Copper | 699320 | 69932 SVC REN 1 1/4 PL C | 201510 | 14,789.72 | 6 | 0.0031250 | 277.31 | 554.61 |

| | | | | | | | | |
|------------------------------------|--------|-------------------------------------|--------|--------------|---|-----------|------------|-------------|
| 380200-Services - Plastic & Copper | 699320 | 69932 SVC REN 1 1/4 PL C | 201511 | 2,409.88 | 5 | 0.0031250 | 37.65 | 90.37 |
| 380200-Services - Plastic & Copper | 699320 | 69932 SVC REN 1 1/4 PL C | 201512 | 302.09 | 4 | 0.0031250 | 3.78 | 11.33 |
| 380200-Services - Plastic & Copper | 699330 | 69933 SVC REN 2&OVR PL C | 201509 | 4,093.98 | 7 | 0.0031250 | 89.56 | 153.52 |
| 380200-Services - Plastic & Copper | 699330 | 69933 SVC REN 2&OVR PL C | 201510 | 1,614.47 | 6 | 0.0031250 | 30.27 | 60.54 |
| 380200-Services - Plastic & Copper | 699330 | 69933 SVC REN 2&OVR PL C | 201511 | (10,296.27) | 5 | 0.0031250 | (160.88) | (386.11) |
| 380200-Services - Plastic & Copper | 699330 | 69933 SVC REN 2&OVR PL C | 201512 | 22,892.86 | 4 | 0.0031250 | 286.16 | 858.48 |
| 380200-Services - Plastic & Copper | 699400 | 69940 SVC REN COR TRANSFER CI | 201509 | (7,535.83) | 7 | 0.0031250 | (164.85) | (282.59) |
| 380200-Services - Plastic & Copper | 699400 | 69940 SVC REN COR TRANSFER CI | 201510 | (11,724.15) | 6 | 0.0031250 | (219.83) | (439.66) |
| 380200-Services - Plastic & Copper | 699400 | 69940 SVC REN COR TRANSFER CI | 201511 | (24,352.04) | 5 | 0.0031250 | (380.50) | (913.20) |
| 380200-Services - Plastic & Copper | 699400 | 69940 SVC REN COR TRANSFER CI | 201512 | (5,167.23) | 4 | 0.0031250 | (64.59) | (193.77) |
| 380200-Services - Plastic & Copper | 699410 | 69941 SVC REN COR TRANSFER CO | 201509 | (15,484.93) | 7 | 0.0031250 | (338.73) | (580.68) |
| 380200-Services - Plastic & Copper | 699410 | 69941 SVC REN COR TRANSFER CO | 201510 | (54,764.14) | 6 | 0.0031250 | (1,026.83) | (2,053.66) |
| 380200-Services - Plastic & Copper | 699410 | 69941 SVC REN COR TRANSFER CO | 201511 | (23,011.87) | 5 | 0.0031250 | (359.56) | (862.95) |
| 380200-Services - Plastic & Copper | 699410 | 69941 SVC REN COR TRANSFER CO | 201512 | (11,885.14) | 4 | 0.0031250 | (148.56) | (445.69) |
| 380200-Services - Plastic & Copper | 900068 | Repl w/ 1750F 2P Jefferson Ph 2 | 201509 | (75.19) | 7 | 0.0031250 | (1.64) | (2.82) |
| 380200-Services - Plastic & Copper | 900069 | Inst 3539F 2P Jefferson Ph 3 | 201509 | 21,832.48 | 7 | 0.0031250 | 477.59 | 818.72 |
| 380200-Services - Plastic & Copper | 900069 | Inst 3539F 2P Jefferson Ph 3 | 201510 | 1,443.09 | 6 | 0.0031250 | 27.06 | 54.12 |
| 380200-Services - Plastic & Copper | 900069 | Inst 3539F 2P Jefferson Ph 3 | 201511 | (51.06) | 5 | 0.0031250 | (0.80) | (1.91) |
| 380200-Services - Plastic & Copper | 900069 | Inst 3539F 2P Jefferson Ph 3 | 201512 | 2,262.82 | 4 | 0.0031250 | 28.29 | 84.86 |
| 380200-Services - Plastic & Copper | 900071 | Repl w/ 4240F 2-4P Jefferson Ph5 | 201511 | 673,722.70 | 5 | 0.0031250 | 10,526.92 | 25,264.60 |
| 380200-Services - Plastic & Copper | 900071 | Repl w/ 4240F 2-4P Jefferson Ph5 | 201512 | 2,227.25 | 4 | 0.0031250 | 27.84 | 83.52 |
| 380200-Services - Plastic & Copper | 900072 | Repl w 688F 2P & 2527F 4P Lafayette | 201509 | (0.09) | 7 | 0.0031250 | - | - |
| 380200-Services - Plastic & Copper | 900073 | Repl w/ 2520F 2P Jefferson Ph 6 | 201509 | (299,740.25) | 7 | 0.0031250 | (6,556.82) | (11,240.26) |
| 380200-Services - Plastic & Copper | 900073 | Repl w/ 2520F 2P Jefferson Ph 6 | 201510 | 160.20 | 6 | 0.0031250 | 3.00 | 6.01 |
| 380200-Services - Plastic & Copper | 900093 | Repl w/ 184F 2P Cass | 201509 | 0.06 | 7 | 0.0031250 | - | - |
| 380200-Services - Plastic & Copper | 900099 | Rel 1830F 2P McKnight Rd | 201509 | (72.37) | 7 | 0.0031250 | (1.58) | (2.71) |
| 380200-Services - Plastic & Copper | 900283 | Rel w/ 1924F 6P Fee Fee Road | 201509 | (0.18) | 7 | 0.0031250 | - | (0.01) |
| 380200-Services - Plastic & Copper | 900264 | Int 3087F 4P 2P Baden Grid Ph 5A | 201509 | 26.72 | 7 | 0.0031250 | 0.58 | 1.00 |
| 380200-Services - Plastic & Copper | 900265 | Repl w/ 3337F 2P Baden Ph 5B | 201509 | 5.12 | 7 | 0.0031250 | 0.11 | 0.19 |
| 380200-Services - Plastic & Copper | 900266 | Inst 4640F 2P Baden Ph 5C | 201509 | (3.00) | 7 | 0.0031250 | (0.07) | (0.11) |
| 380200-Services - Plastic & Copper | 900266 | Inst 4640F 2P Baden Ph 5C | 201510 | 14.69 | 6 | 0.0031250 | 0.28 | 0.55 |
| 380200-Services - Plastic & Copper | 900266 | Inst 4640F 2P Baden Ph 5C | 201511 | (0.91) | 5 | 0.0031250 | (0.01) | (0.03) |
| 380200-Services - Plastic & Copper | 900266 | Inst 4640F 2P Baden Ph 5C | 201512 | 68.29 | 4 | 0.0031250 | 0.85 | 2.56 |
| 380200-Services - Plastic & Copper | 900267 | Repl w/ 4536F 2P Baden Ph5D | 201509 | 4.52 | 7 | 0.0031250 | 0.10 | 0.17 |
| 380200-Services - Plastic & Copper | 900268 | Inst 4411F 2P Baden Ph5E | 201509 | 2.58 | 7 | 0.0031250 | 0.06 | 0.10 |
| 380200-Services - Plastic & Copper | 900269 | Inst 1150F 4P Walnut Park Ph 5A | 201509 | (791.57) | 7 | 0.0031250 | (17.32) | (29.68) |
| 380200-Services - Plastic & Copper | 900270 | Inst 2942F 2P Walnut Park Ph5B | 201509 | (915.37) | 7 | 0.0031250 | (20.02) | (34.33) |
| 380200-Services - Plastic & Copper | 900270 | Inst 2942F 2P Walnut Park Ph5B | 201511 | 1,487.40 | 5 | 0.0031250 | 23.24 | 55.78 |
| 380200-Services - Plastic & Copper | 900271 | Inst 2646F 2P Walnut Park Ph5C | 201509 | (3,666.46) | 7 | 0.0031250 | (80.20) | (137.49) |
| 380200-Services - Plastic & Copper | 900271 | Inst 2646F 2P Walnut Park Ph5C | 201511 | 1,954.92 | 5 | 0.0031250 | 30.55 | 73.31 |
| 380200-Services - Plastic & Copper | 900272 | Inst 4170F 2P Walnut Park Ph 5D | 201509 | 358,981.28 | 7 | 0.0031250 | 7,852.72 | 13,461.80 |
| 380200-Services - Plastic & Copper | 900272 | Inst 4170F 2P Walnut Park Ph 5D | 201511 | (31.00) | 5 | 0.0031250 | (0.48) | (1.16) |
| 380200-Services - Plastic & Copper | 900272 | Inst 4170F 2P Walnut Park Ph 5D | 201512 | 0.42 | 4 | 0.0031250 | 0.01 | 0.02 |
| 380200-Services - Plastic & Copper | 900273 | Repl w/ 4565F 2P Walnut Park Ph5E | 201510 | 483,449.97 | 6 | 0.0031250 | 9,064.69 | 18,129.37 |
| 380200-Services - Plastic & Copper | 900273 | Repl w/ 4565F 2P Walnut Park Ph5E | 201511 | (383.16) | 5 | 0.0031250 | (5.99) | (14.37) |
| 380200-Services - Plastic & Copper | 900273 | Repl w/ 4565F 2P Walnut Park Ph5E | 201512 | 169.38 | 4 | 0.0031250 | 2.12 | 6.35 |
| 380200-Services - Plastic & Copper | 900274 | Repl w/ 3390F 2P Wellington Ph 4D | 201509 | (12,481.16) | 7 | 0.0031250 | (273.03) | (468.04) |
| 380200-Services - Plastic & Copper | 900274 | Repl w/ 3390F 2P Wellington Ph 4D | 201512 | (107,174.75) | 4 | 0.0031250 | (1,339.68) | (4,019.05) |
| 380200-Services - Plastic & Copper | 900275 | Repl w/ 4989F 2P Wellington Ph4E | 201509 | (2,849.40) | 7 | 0.0031250 | (62.33) | (106.85) |
| 380200-Services - Plastic & Copper | 900277 | Repl w/ 1725F 2P Walnut Park Ph4B | 201509 | (128.05) | 7 | 0.0031250 | (2.80) | (4.80) |
| 380200-Services - Plastic & Copper | 900278 | Repl w/ 3977F 2P Walnut Park Ph4C | 201509 | (141.25) | 7 | 0.0031250 | (3.09) | (5.30) |
| 380200-Services - Plastic & Copper | 900279 | Repl w/ 3345F 2P Walnut Park Ph4D | 201509 | (1,934.34) | 7 | 0.0031250 | (42.31) | (72.54) |
| 380200-Services - Plastic & Copper | 900281 | Inst 4984F 4P Wellston Phase 2B | 201509 | (0.84) | 7 | 0.0031250 | (0.02) | (0.03) |
| 380200-Services - Plastic & Copper | 900282 | Inst 4400F 2P Wellston 2C | 201509 | (2,841.81) | 7 | 0.0031250 | (62.16) | (106.57) |
| 380200-Services - Plastic & Copper | 900283 | Inst 5300F 2P Wellston Ph2D | 201509 | 1.78 | 7 | 0.0031250 | 0.04 | 0.07 |

| | | | | | | | | |
|------------------------------------|--------|-------------------------------------|--------|-------------|---|-----------|-----------|-----------|
| 380200-Services - Plastic & Copper | 900284 | Inst 5466F 2P Wellston Ph2E | 201509 | (1,608.98) | 7 | 0.0031250 | (35.20) | (60.34) |
| 380200-Services - Plastic & Copper | 900310 | Inst 2250F 2P Yale Ave Maplewood 1C | 201511 | 85.11 | 5 | 0.0031250 | 1.33 | 3.19 |
| 380200-Services - Plastic & Copper | 900313 | Inst 775F 2P Caulks Hill Rd CJ | 201510 | (297.22) | 6 | 0.0031250 | (5.57) | (11.15) |
| 380200-Services - Plastic & Copper | 900375 | Inst 1747F 6P Litzsinger | 201509 | 0.17 | 7 | 0.0031250 | - | 0.01 |
| 380200-Services - Plastic & Copper | 900377 | Repl w/ 978F 2-4P Big Bend | 201509 | (295.64) | 7 | 0.0031250 | (6.47) | (11.09) |
| 380200-Services - Plastic & Copper | 900379 | Inst 783F 4P & 529F 2POld Bonhomme | 201509 | (7.34) | 7 | 0.0031250 | (0.16) | (0.28) |
| 380200-Services - Plastic & Copper | 900388 | Repl w/ 332F 2P Tay Rd | 201509 | (2.61) | 7 | 0.0031250 | (0.06) | (0.10) |
| 380200-Services - Plastic & Copper | 900390 | Inst 205F 1 1/4P Gore | 201509 | (0.83) | 7 | 0.0031250 | (0.02) | (0.03) |
| 380200-Services - Plastic & Copper | 900392 | Inst 580F 4P & 255F 2P Ferguson | 201509 | (0.08) | 7 | 0.0031250 | - | - |
| 380200-Services - Plastic & Copper | 900393 | Inst 3745F 6P Clayton Ave | 201509 | (0.01) | 7 | 0.0031250 | - | - |
| 380200-Services - Plastic & Copper | 900395 | Repl w/ 525F 2P Clay St | 201509 | (0.89) | 7 | 0.0031250 | (0.02) | (0.03) |
| 380200-Services - Plastic & Copper | 900415 | Repl w/ 1093F 2P Princeton | 201509 | (1.63) | 7 | 0.0031250 | (0.04) | (0.06) |
| 380200-Services - Plastic & Copper | 900420 | Repl w/ 520F 2P Oregon | 201509 | (0.70) | 7 | 0.0031250 | (0.02) | (0.03) |
| 380200-Services - Plastic & Copper | 900421 | Repl w/ 970F 2P Winnebago | 201509 | (11.61) | 7 | 0.0031250 | (0.25) | (0.44) |
| 380200-Services - Plastic & Copper | 900422 | Repl w/ 780F 2P Taft | 201509 | (9.04) | 7 | 0.0031250 | (0.20) | (0.34) |
| 380200-Services - Plastic & Copper | 900423 | Repl w/ 1373F 2P Dr MLK | 201509 | (0.05) | 7 | 0.0031250 | - | - |
| 380200-Services - Plastic & Copper | 900424 | Repl w/ 520F 3P Red Bud | 201509 | 0.18 | 7 | 0.0031250 | - | 0.01 |
| 380200-Services - Plastic & Copper | 900430 | Repl w/ 654F 2P Maurice | 201509 | (1.82) | 7 | 0.0031250 | (0.04) | (0.07) |
| 380200-Services - Plastic & Copper | 900432 | Repl w/ 503F 2P Gravois | 201509 | (7.69) | 7 | 0.0031250 | (0.17) | (0.29) |
| 380200-Services - Plastic & Copper | 900433 | Repl w/ 570F 4P Chippewa | 201509 | (8.47) | 7 | 0.0031250 | (0.19) | (0.32) |
| 380200-Services - Plastic & Copper | 900439 | Repl w/ 269F 2P Ferguson | 201509 | (0.50) | 7 | 0.0031250 | (0.01) | (0.02) |
| 380200-Services - Plastic & Copper | 900456 | Inst 8175F 8P Jamieson McCausland | 201509 | 0.01 | 7 | 0.0031250 | - | - |
| 380200-Services - Plastic & Copper | 900457 | Inst 4546F 2P Baden Ph5F | 201509 | (3.18) | 7 | 0.0031250 | (0.07) | (0.12) |
| 380200-Services - Plastic & Copper | 900460 | Inst 3488F 2P Walnut Park Ph4E | 201509 | (2.51) | 7 | 0.0031250 | (0.05) | (0.09) |
| 380200-Services - Plastic & Copper | 900461 | Inst 893F 2P Walnut Park Ph4F | 201509 | (0.21) | 7 | 0.0031250 | - | (0.01) |
| 380200-Services - Plastic & Copper | 900462 | Repl w/ 2240F 2P Walnut Park Ph4G | 201509 | (1,049.00) | 7 | 0.0031250 | (22.95) | (39.34) |
| 380200-Services - Plastic & Copper | 900463 | Inst 4082F 2P Walnut Park Ph4H | 201509 | (17.65) | 7 | 0.0031250 | (0.39) | (0.66) |
| 380200-Services - Plastic & Copper | 900464 | Inst 4741F 2P Walnut Park Ph 4I | 201509 | (286.44) | 7 | 0.0031250 | (6.27) | (10.74) |
| 380200-Services - Plastic & Copper | 900487 | Repl w/ 2400F 2-4P Potomac AOR | 201509 | (0.41) | 7 | 0.0031250 | (0.01) | (0.02) |
| 380200-Services - Plastic & Copper | 900476 | Inst 3350F 6P Ivory | 201509 | (207.15) | 7 | 0.0031250 | (4.53) | (7.77) |
| 380200-Services - Plastic & Copper | 900476 | Inst 3350F 6P Ivory | 201511 | 106.46 | 5 | 0.0031250 | 1.66 | 3.99 |
| 380200-Services - Plastic & Copper | 900476 | Inst 3350F 6P Ivory | 201512 | 0.27 | 4 | 0.0031250 | - | 0.01 |
| 380200-Services - Plastic & Copper | 900485 | Inst 4236F 12P Alaska | 201509 | (0.07) | 7 | 0.0031250 | - | - |
| 380200-Services - Plastic & Copper | 900488 | Repl w/ 2873F 6P Hodiament | 201509 | 6.81 | 7 | 0.0031250 | 0.15 | 0.26 |
| 380200-Services - Plastic & Copper | 900523 | Repl w/ 5304F 2P Maplewood Ph1D | 201512 | 753,907.38 | 4 | 0.0031250 | 9,423.84 | 28,271.53 |
| 380200-Services - Plastic & Copper | 900536 | Aband 1681F 6C Walnut Park Ph4B | 201509 | (14.94) | 7 | 0.0031250 | (0.33) | (0.56) |
| 380200-Services - Plastic & Copper | 900538 | Aband 3381F 6C Walnut Park Ph4D | 201509 | (10.93) | 7 | 0.0031250 | (0.24) | (0.41) |
| 380200-Services - Plastic & Copper | 900540 | Aband var Walnut Park Ph4F | 201509 | (15.07) | 7 | 0.0031250 | (0.33) | (0.57) |
| 380200-Services - Plastic & Copper | 900546 | Inst 5691F 2P Wellston Ph2F | 201512 | 195,100.16 | 4 | 0.0031250 | 2,438.75 | 7,316.26 |
| 380200-Services - Plastic & Copper | 900548 | Inst 6712F 2P Wellston Ph2H | 201511 | 240,805.74 | 5 | 0.0031250 | 3,762.59 | 9,030.22 |
| 380200-Services - Plastic & Copper | 900548 | Inst 6712F 2P Wellston Ph2H | 201512 | 6,482.60 | 4 | 0.0031250 | 81.03 | 243.10 |
| 380200-Services - Plastic & Copper | 900556 | Inst 5130F 2P Walnut Park Ph 5F | 201509 | 458,541.15 | 7 | 0.0031250 | 10,030.59 | 17,195.29 |
| 380200-Services - Plastic & Copper | 900556 | Inst 5130F 2P Walnut Park Ph 5F | 201510 | (8,838.37) | 6 | 0.0031250 | (165.72) | (331.44) |
| 380200-Services - Plastic & Copper | 900556 | Inst 5130F 2P Walnut Park Ph 5F | 201511 | 1,271.13 | 5 | 0.0031250 | 19.86 | 47.67 |
| 380200-Services - Plastic & Copper | 900556 | Inst 5130F 2P Walnut Park Ph 5F | 201512 | 43.45 | 4 | 0.0031250 | 0.54 | 1.63 |
| 380200-Services - Plastic & Copper | 900557 | Inst 2123F 2P Walnut Park Ph6A | 201509 | (4,286.66) | 7 | 0.0031250 | (93.77) | (160.75) |
| 380200-Services - Plastic & Copper | 900558 | Inst 1859F 2P Walnut Park Ph6B | 201509 | (15,475.52) | 7 | 0.0031250 | (338.53) | (580.33) |
| 380200-Services - Plastic & Copper | 900558 | Inst 1859F 2P Walnut Park Ph6B | 201510 | 2,008.70 | 6 | 0.0031250 | 37.66 | 75.33 |
| 380200-Services - Plastic & Copper | 900558 | Inst 1859F 2P Walnut Park Ph6B | 201511 | 152.53 | 5 | 0.0031250 | 2.38 | 5.72 |
| 380200-Services - Plastic & Copper | 900558 | Inst 1859F 2P Walnut Park Ph6B | 201512 | 4.12 | 4 | 0.0031250 | 0.05 | 0.15 |
| 380200-Services - Plastic & Copper | 900559 | Inst 3875F 2P Walnut Park Ph6C | 201509 | (4,669.68) | 7 | 0.0031250 | (102.15) | (175.11) |
| 380200-Services - Plastic & Copper | 900559 | Inst 3875F 2P Walnut Park Ph6C | 201510 | (448.13) | 6 | 0.0031250 | (8.40) | (16.80) |
| 380200-Services - Plastic & Copper | 900559 | Inst 3875F 2P Walnut Park Ph6C | 201511 | 1,814.04 | 5 | 0.0031250 | 28.34 | 68.03 |
| 380200-Services - Plastic & Copper | 900559 | Inst 3875F 2P Walnut Park Ph6C | 201512 | 558.18 | 4 | 0.0031250 | 6.98 | 20.93 |
| 380200-Services - Plastic & Copper | 900560 | Inst 4705F 2P Walnut Park Ph6D | 201509 | 318,859.28 | 7 | 0.0031250 | 6,975.05 | 11,957.22 |

| | | | | | | | | |
|------------------------------------|--------|------------------------------------|--------|--------------|---|-----------|------------|------------|
| 380200-Services - Plastic & Copper | 900560 | Inst 4705F 2P Walnut Park Ph6D | 201511 | (739.17) | 5 | 0.0031250 | (11.55) | (27.72) |
| 380200-Services - Plastic & Copper | 900560 | Inst 4705F 2P Walnut Park Ph6D | 201512 | 596.54 | 4 | 0.0031250 | 7.46 | 22.37 |
| 380200-Services - Plastic & Copper | 900603 | Inst 4300F 2P Maplewood Ph2A | 201512 | 225,104.47 | 4 | 0.0031250 | 2,813.81 | 8,441.42 |
| 380200-Services - Plastic & Copper | 900605 | Inst 2020F 2P Maplewood Ph 2B | 201512 | 255,753.22 | 4 | 0.0031250 | 3,196.92 | 9,590.75 |
| 380200-Services - Plastic & Copper | 900607 | Inst 3183F 2P Maplewood Ph2C | 201509 | 169,510.47 | 7 | 0.0031250 | 3,708.04 | 6,356.64 |
| 380200-Services - Plastic & Copper | 900607 | Inst 3183F 2P Maplewood Ph2C | 201510 | 7,161.47 | 6 | 0.0031250 | 134.28 | 268.56 |
| 380200-Services - Plastic & Copper | 900607 | Inst 3183F 2P Maplewood Ph2C | 201511 | 14,694.72 | 5 | 0.0031250 | 229.61 | 551.05 |
| 380200-Services - Plastic & Copper | 900607 | Inst 3183F 2P Maplewood Ph2C | 201512 | 188.42 | 4 | 0.0031250 | 2.36 | 7.07 |
| 380200-Services - Plastic & Copper | 900623 | Repl w/ 2852' 2P Wydown Ph 6 | 201509 | (1,679.50) | 7 | 0.0031250 | (36.74) | (62.98) |
| 380200-Services - Plastic & Copper | 900633 | Rel w/ 321F 4S 2S Progress Parkway | 201509 | 2,965.86 | 7 | 0.0031250 | 64.88 | 111.22 |
| 380200-Services - Plastic & Copper | 900633 | Rel w/ 321F 4S 2S Progress Parkway | 201510 | (18.96) | 6 | 0.0031250 | (0.36) | (0.71) |
| 380200-Services - Plastic & Copper | 900643 | Inst 1801F 6P-12P Marmaduke/Hudler | 201509 | 4,484.71 | 7 | 0.0031250 | 98.10 | 168.18 |
| 380200-Services - Plastic & Copper | 900643 | Inst 1801F 6P-12P Marmaduke/Hudler | 201510 | 0.72 | 6 | 0.0031250 | 0.01 | 0.03 |
| 380200-Services - Plastic & Copper | 900650 | Inst 3290F 2P St Louis Hills Ph1A | 201509 | (17,932.32) | 7 | 0.0031250 | (392.27) | (672.46) |
| 380200-Services - Plastic & Copper | 900650 | Inst 3290F 2P St Louis Hills Ph1A | 201512 | (164,337.66) | 4 | 0.0031250 | (2,054.22) | (6,162.66) |
| 380200-Services - Plastic & Copper | 900652 | Inst 4435F 2P St Louis Hills Ph1B | 201509 | (3,999.18) | 7 | 0.0031250 | (87.48) | (149.97) |
| 380200-Services - Plastic & Copper | 900652 | Inst 4435F 2P St Louis Hills Ph1B | 201511 | 1,542.26 | 5 | 0.0031250 | 24.10 | 57.83 |
| 380200-Services - Plastic & Copper | 900653 | Inst 2636F 2P St Louis Hills Ph1C | 201509 | (1,685.99) | 7 | 0.0031250 | (36.88) | (63.22) |
| 380200-Services - Plastic & Copper | 900653 | Inst 2636F 2P St Louis Hills Ph1C | 201510 | 172.57 | 6 | 0.0031250 | 3.24 | 6.47 |
| 380200-Services - Plastic & Copper | 900653 | Inst 2636F 2P St Louis Hills Ph1C | 201511 | (2,800.41) | 5 | 0.0031250 | (43.76) | (105.02) |
| 380200-Services - Plastic & Copper | 900653 | Inst 2636F 2P St Louis Hills Ph1C | 201512 | 5.27 | 4 | 0.0031250 | 0.07 | 0.20 |
| 380200-Services - Plastic & Copper | 900670 | Rel w/ 400F 6P Vogel Rd | 201509 | 2,632.89 | 7 | 0.0031250 | 57.59 | 98.73 |
| 380200-Services - Plastic & Copper | 900670 | Rel w/ 400F 6P Vogel Rd | 201510 | 0.03 | 6 | 0.0031250 | - | - |
| 380200-Services - Plastic & Copper | 900677 | Repl w/ 1795F 2P Cole & 18th PhA | 201509 | 6,537.41 | 7 | 0.0031250 | 143.01 | 245.15 |
| 380200-Services - Plastic & Copper | 900679 | Inst 2312F 4P Cole & 18th PhB | 201509 | (628.69) | 7 | 0.0031250 | (13.75) | (23.58) |
| 380200-Services - Plastic & Copper | 900679 | Inst 2312F 4P Cole & 18th PhB | 201511 | (8,971.62) | 5 | 0.0031250 | (140.18) | (336.44) |
| 380200-Services - Plastic & Copper | 900681 | Inst 1637F 2P Cole & 18th Ph C | 201509 | (9,068.74) | 7 | 0.0031250 | (198.38) | (340.08) |
| 380200-Services - Plastic & Copper | 900683 | Inst 1864F 2P Cole & 18th Ph D | 201509 | (8,238.20) | 7 | 0.0031250 | (180.21) | (308.93) |
| 380200-Services - Plastic & Copper | 900683 | Inst 1864F 2P Cole & 18th Ph D | 201510 | 14.17 | 6 | 0.0031250 | 0.27 | 0.53 |
| 380200-Services - Plastic & Copper | 900683 | Inst 1864F 2P Cole & 18th Ph D | 201511 | (0.02) | 5 | 0.0031250 | - | - |
| 380200-Services - Plastic & Copper | 900683 | Inst 1864F 2P Cole & 18th Ph D | 201512 | 0.64 | 4 | 0.0031250 | 0.01 | 0.02 |
| 380200-Services - Plastic & Copper | 900685 | Inst 1550F 2P Cole & 18th PhE | 201509 | (6,238.78) | 7 | 0.0031250 | (136.47) | (233.95) |
| 380200-Services - Plastic & Copper | 900685 | Inst 1550F 2P Cole & 18th PhE | 201510 | 17.64 | 6 | 0.0031250 | 0.33 | 0.66 |
| 380200-Services - Plastic & Copper | 900685 | Inst 1550F 2P Cole & 18th PhE | 201511 | (0.04) | 5 | 0.0031250 | - | - |
| 380200-Services - Plastic & Copper | 900685 | Inst 1550F 2P Cole & 18th PhE | 201512 | 0.87 | 4 | 0.0031250 | 0.01 | 0.03 |
| 380200-Services - Plastic & Copper | 900687 | Inst 1096F 2P Cole & 18th PhF | 201509 | (4,235.08) | 7 | 0.0031250 | (92.64) | (158.82) |
| 380200-Services - Plastic & Copper | 900689 | Inst 2434F 2P Cole & 18th PhG | 201509 | (4,457.29) | 7 | 0.0031250 | (97.50) | (167.15) |
| 380200-Services - Plastic & Copper | 900689 | Inst 2434F 2P Cole & 18th PhG | 201510 | (35.11) | 6 | 0.0031250 | (0.66) | (1.32) |
| 380200-Services - Plastic & Copper | 900689 | Inst 2434F 2P Cole & 18th PhG | 201511 | 0.09 | 5 | 0.0031250 | - | - |
| 380200-Services - Plastic & Copper | 900689 | Inst 2434F 2P Cole & 18th PhG | 201512 | (9.03) | 4 | 0.0031250 | (0.11) | (0.34) |
| 380200-Services - Plastic & Copper | 900691 | Repl w/ 3458F 2P Cole & 18th Ph H | 201509 | 4,910.78 | 7 | 0.0031250 | 107.42 | 184.15 |
| 380200-Services - Plastic & Copper | 900691 | Repl w/ 3458F 2P Cole & 18th Ph H | 201510 | 1,575.17 | 6 | 0.0031250 | 29.53 | 59.07 |
| 380200-Services - Plastic & Copper | 900691 | Repl w/ 3458F 2P Cole & 18th Ph H | 201511 | (35.64) | 5 | 0.0031250 | (0.56) | (1.34) |
| 380200-Services - Plastic & Copper | 900691 | Repl w/ 3458F 2P Cole & 18th Ph H | 201512 | 4,511.38 | 4 | 0.0031250 | 56.39 | 169.18 |
| 380200-Services - Plastic & Copper | 900723 | Rel w/ 3350F 2P Valley Park | 201509 | 1.35 | 7 | 0.0031250 | 0.03 | 0.05 |
| 380200-Services - Plastic & Copper | 900730 | Rel w/ 310F 2P Bramblett | 201509 | (80.58) | 7 | 0.0031250 | (1.76) | (3.02) |
| 380200-Services - Plastic & Copper | 900730 | Rel w/ 310F 2P Bramblett | 201510 | (0.18) | 6 | 0.0031250 | - | (0.01) |
| 380200-Services - Plastic & Copper | 900734 | Repl w/ 1717F 2P Hurck | 201509 | (3,550.66) | 7 | 0.0031250 | (77.67) | (133.15) |
| 380200-Services - Plastic & Copper | 900734 | Repl w/ 1717F 2P Hurck | 201510 | 27.47 | 6 | 0.0031250 | 0.52 | 1.03 |
| 380200-Services - Plastic & Copper | 900734 | Repl w/ 1717F 2P Hurck | 201511 | 1,073.91 | 5 | 0.0031250 | 16.78 | 40.27 |
| 380200-Services - Plastic & Copper | 900734 | Repl w/ 1717F 2P Hurck | 201512 | 119.04 | 4 | 0.0031250 | 1.49 | 4.46 |
| 380200-Services - Plastic & Copper | 900738 | Repl w/ 780F 2P Kingsland MSD | 201509 | (1,862.01) | 7 | 0.0031250 | (40.73) | (69.83) |
| 380200-Services - Plastic & Copper | 900738 | Repl w/ 780F 2P Kingsland MSD | 201511 | 179.62 | 5 | 0.0031250 | 2.81 | 6.74 |
| 380200-Services - Plastic & Copper | 900738 | Repl w/ 780F 2P Kingsland MSD | 201512 | 25.45 | 4 | 0.0031250 | 0.32 | 0.95 |
| 380200-Services - Plastic & Copper | 900759 | Repl w/ 2836F 2P Hickory Dale | 201509 | 74,549.17 | 7 | 0.0031250 | 1,630.76 | 2,795.59 |

| | | | | | | | | |
|------------------------------------|--------|-------------------------------------|--------|--------------|---|-----------|------------|------------|
| 380200-Services - Plastic & Copper | 900759 | Repl w/ 2836F 2P Hickory Dale | 201510 | 15.62 | 6 | 0.0031250 | 0.29 | 0.59 |
| 380200-Services - Plastic & Copper | 900762 | Inst 2069F 2P Earthquake Zone Ph1A | 201509 | (2,102.42) | 7 | 0.0031250 | (45.99) | (78.84) |
| 380200-Services - Plastic & Copper | 900763 | Inst 3508F 2P Earthquake Zone Ph1B | 201509 | (186,673.29) | 7 | 0.0031250 | (4,083.48) | (7,000.25) |
| 380200-Services - Plastic & Copper | 900764 | Repl w/758F 2P Earthquake Zone Ph1C | 201509 | (37,485.34) | 7 | 0.0031250 | (819.99) | (1,405.70) |
| 380200-Services - Plastic & Copper | 900764 | Repl w/758F 2P Earthquake Zone Ph1C | 201510 | 6.19 | 6 | 0.0031250 | 0.12 | 0.23 |
| 380200-Services - Plastic & Copper | 900765 | Inst 1899F 4P Earthquake Zone Ph1D | 201509 | (18,209.01) | 7 | 0.0031250 | (398.32) | (682.84) |
| 380200-Services - Plastic & Copper | 900775 | Rel w/ 1535F 2P Page&Hodiamont AOR | 201509 | (304.95) | 7 | 0.0031250 | (6.67) | (11.44) |
| 380200-Services - Plastic & Copper | 900813 | Rel w/ 700F 2P Froesel | 201509 | 0.21 | 7 | 0.0031250 | - | 0.01 |
| 380200-Services - Plastic & Copper | 900822 | Rel w/ 130F 6S Price Road | 201509 | (676.15) | 7 | 0.0031250 | (14.79) | (25.36) |
| 380200-Services - Plastic & Copper | 900823 | Repl w/ 659F 2P Baden Ph6A | 201509 | (86.18) | 7 | 0.0031250 | (1.89) | (3.23) |
| 380200-Services - Plastic & Copper | 900848 | Rel w/ 810F 4P Bircher & Newstead | 201509 | (970.95) | 7 | 0.0031250 | (21.24) | (36.41) |
| 380200-Services - Plastic & Copper | 900859 | Repl w/ 290F 2P Cabanne | 201509 | (874.17) | 7 | 0.0031250 | (19.12) | (32.78) |
| 380200-Services - Plastic & Copper | 900859 | Repl w/ 290F 2P Cabanne | 201510 | 10.00 | 6 | 0.0031250 | 0.19 | 0.38 |
| 380200-Services - Plastic & Copper | 900861 | Repl w/ 105F 4P McLaran | 201509 | (21.21) | 7 | 0.0031250 | (0.46) | (0.80) |
| 380200-Services - Plastic & Copper | 900862 | Rep w/ 4552F 2P Broadway AOR | 201509 | 79,870.08 | 7 | 0.0031250 | 1,747.16 | 2,995.13 |
| 380200-Services - Plastic & Copper | 900862 | Rep w/ 4552F 2P Broadway AOR | 201510 | (9.18) | 6 | 0.0031250 | (0.17) | (0.34) |
| 380200-Services - Plastic & Copper | 900862 | Rep w/ 4552F 2P Broadway AOR | 201511 | 0.03 | 5 | 0.0031250 | - | - |
| 380200-Services - Plastic & Copper | 900862 | Repl w/ 4552F 2P Broadway AOR | 201512 | (1.48) | 4 | 0.0031250 | (0.02) | (0.06) |
| 380200-Services - Plastic & Copper | 900873 | Repl w/ 538F 2P Longacre | 201509 | (1,251.75) | 7 | 0.0031250 | (27.38) | (46.94) |
| 380200-Services - Plastic & Copper | 900873 | Repl w/ 538F 2P Longacre | 201510 | 12,610.44 | 6 | 0.0031250 | 236.45 | 472.89 |
| 380200-Services - Plastic & Copper | 900876 | Repl w/ 1060F 2P Rauschenbach PVC | 201509 | (572.76) | 7 | 0.0031250 | (12.53) | (21.48) |
| 380200-Services - Plastic & Copper | 900876 | Repl w/ 1060F 2P Rauschenbach PVC | 201510 | 393.26 | 6 | 0.0031250 | 7.37 | 14.75 |
| 380200-Services - Plastic & Copper | 900876 | Repl w/ 1060F 2P Rauschenbach PVC | 201511 | (0.30) | 5 | 0.0031250 | - | (0.01) |
| 380200-Services - Plastic & Copper | 900876 | Repl w/ 1060F 2P Rauschenbach PVC | 201512 | 10,636.09 | 4 | 0.0031250 | 132.98 | 398.93 |
| 380200-Services - Plastic & Copper | 900890 | Repl w/ 2218F 2P Russell & Flora | 201509 | 241,794.32 | 7 | 0.0031250 | 5,289.25 | 9,067.29 |
| 380200-Services - Plastic & Copper | 900890 | Repl w/ 2218F 2P Russell & Flora | 201510 | 76.12 | 6 | 0.0031250 | 1.43 | 2.85 |
| 380200-Services - Plastic & Copper | 900893 | Repl w/ 2486F 6P Arlington | 201509 | (750.29) | 7 | 0.0031250 | (16.41) | (28.14) |
| 380200-Services - Plastic & Copper | 900893 | Repl w/ 2486F 6P Arlington | 201511 | (494.70) | 5 | 0.0031250 | (7.73) | (18.55) |
| 380200-Services - Plastic & Copper | 900893 | Repl w/ 2486F 6P Arlington | 201512 | (178.20) | 4 | 0.0031250 | (2.23) | (6.68) |
| 380200-Services - Plastic & Copper | 900895 | Repl w/ 828F 2P Marquette | 201509 | 35,296.44 | 7 | 0.0031250 | 772.11 | 1,323.62 |
| 380200-Services - Plastic & Copper | 900895 | Repl w/ 828F 2P Marquette | 201510 | (371.52) | 6 | 0.0031250 | (6.97) | (13.93) |
| 380200-Services - Plastic & Copper | 900895 | Repl w/ 828F 2P Marquette | 201511 | 0.02 | 5 | 0.0031250 | - | - |
| 380200-Services - Plastic & Copper | 900895 | Repl w/ 828F 2P Marquette | 201512 | (31.73) | 4 | 0.0031250 | (0.40) | (1.19) |
| 380200-Services - Plastic & Copper | 900896 | Repl w/ 2990F 2P 4P Maple | 201509 | (1,984.53) | 7 | 0.0031250 | (43.41) | (74.42) |
| 380200-Services - Plastic & Copper | 900896 | Repl w/ 2990F 2P 4P Maple | 201510 | 221.79 | 6 | 0.0031250 | 4.16 | 8.32 |
| 380200-Services - Plastic & Copper | 900896 | Repl w/ 2990F 2P 4P Maple | 201511 | 988.51 | 5 | 0.0031250 | 15.45 | 37.07 |
| 380200-Services - Plastic & Copper | 900896 | Repl w/ 2990F 2P 4P Maple | 201512 | (219.47) | 4 | 0.0031250 | (2.74) | (8.23) |
| 380200-Services - Plastic & Copper | 900897 | Repl w/ 587F 2P Syracuse | 201509 | 2,145.12 | 7 | 0.0031250 | 46.92 | 80.44 |
| 380200-Services - Plastic & Copper | 900897 | Repl w/ 587F 2P Syracuse | 201511 | 475.01 | 5 | 0.0031250 | 7.42 | 17.81 |
| 380200-Services - Plastic & Copper | 900897 | Repl w/ 587F 2P Syracuse | 201512 | (245.75) | 4 | 0.0031250 | (3.07) | (9.22) |
| 380200-Services - Plastic & Copper | 900898 | Repl w/ 1220F 2P Ohio | 201509 | (11,927.76) | 7 | 0.0031250 | (260.92) | (447.29) |
| 380200-Services - Plastic & Copper | 900898 | Repl w/ 1220F 2P Ohio | 201510 | (4.28) | 6 | 0.0031250 | (0.08) | (0.16) |
| 380200-Services - Plastic & Copper | 900900 | Repl w/ 1075F 2P Washington | 201509 | (25,487.00) | 7 | 0.0031250 | (557.53) | (955.76) |
| 380200-Services - Plastic & Copper | 900900 | Repl w/ 1075F 2P Washington | 201510 | 21.38 | 6 | 0.0031250 | 0.40 | 0.80 |
| 380200-Services - Plastic & Copper | 900902 | Repl w/ 530' 2P Oakland | 201509 | 4,396.87 | 7 | 0.0031250 | 96.18 | 164.88 |
| 380200-Services - Plastic & Copper | 900902 | Repl w/ 530' 2P Oakland | 201510 | (48.29) | 6 | 0.0031250 | (0.91) | (1.81) |
| 380200-Services - Plastic & Copper | 900905 | Repl w/ 806F 2P Utah | 201509 | (1,847.00) | 7 | 0.0031250 | (40.40) | (69.26) |
| 380200-Services - Plastic & Copper | 900905 | Repl w/ 806F 2P Utah | 201510 | 11.84 | 6 | 0.0031250 | 0.22 | 0.44 |
| 380200-Services - Plastic & Copper | 900908 | Repl w/ 460F 2P California | 201509 | (125.54) | 7 | 0.0031250 | (2.75) | (4.71) |
| 380200-Services - Plastic & Copper | 900908 | Repl w/ 460F 2P California | 201510 | 1.69 | 6 | 0.0031250 | 0.03 | 0.06 |
| 380200-Services - Plastic & Copper | 900912 | Repl w/ 745F 2P Shaw | 201509 | (2,171.37) | 7 | 0.0031250 | (47.50) | (81.43) |
| 380200-Services - Plastic & Copper | 900912 | Repl w/ 745F 2P Shaw | 201510 | 49.81 | 6 | 0.0031250 | 0.93 | 1.87 |
| 380200-Services - Plastic & Copper | 900921 | Repl w/ 2457F 4P&2P Flad AOR | 201509 | (10,980.70) | 7 | 0.0031250 | (240.20) | (411.78) |
| 380200-Services - Plastic & Copper | 900921 | Repl w/ 2457F 4P&2P Flad AOR | 201510 | 10,731.29 | 6 | 0.0031250 | 201.21 | 402.42 |
| 380200-Services - Plastic & Copper | 900952 | Repl w/ 2606F 2P Clifton Heights-1B | 201512 | 129,483.46 | 4 | 0.0031250 | 1,618.54 | 4,855.63 |

| | | | | | | | | |
|---|--------|-------------------------------------|--------|--------------|---|-----------|-----------|------------|
| 380200-Services - Plastic & Copper | 900961 | Rel w/ 190F 2P Clay | 201509 | (30.19) | 7 | 0.0031250 | (0.66) | (1.13) |
| 380200-Services - Plastic & Copper | 900977 | Repl w/ 1291F 4P Boyle | 201509 | 64.81 | 7 | 0.0031250 | 1.42 | 2.43 |
| 380200-Services - Plastic & Copper | 900983 | Repl w/ 3143F 2P 4P Shaw AOR | 201512 | 477,073.00 | 4 | 0.0031250 | 5,963.41 | 17,890.24 |
| 380200-Services - Plastic & Copper | 900986 | Repl w/ 2189F 2P Earthquake Zone 2A | 201509 | (30,716.38) | 7 | 0.0031250 | (671.92) | (1,151.86) |
| 380200-Services - Plastic & Copper | 900986 | Repl w/ 2189F 2P Earthquake Zone 2A | 201510 | (94.41) | 6 | 0.0031250 | (1.77) | (3.54) |
| 380200-Services - Plastic & Copper | 900988 | Repl w/ 3840F 2P Earthquake Zn Ph2B | 201509 | 170,342.42 | 7 | 0.0031250 | 3,726.24 | 6,387.84 |
| 380200-Services - Plastic & Copper | 900988 | Repl w/ 3840F 2P Earthquake Zn Ph2B | 201510 | 269.79 | 6 | 0.0031250 | 5.06 | 10.12 |
| 380200-Services - Plastic & Copper | 900988 | Repl w/ 3840F 2P Earthquake Zn Ph2B | 201511 | (1,195.16) | 5 | 0.0031250 | (18.67) | (44.82) |
| 380200-Services - Plastic & Copper | 900988 | Repl w/ 3840F 2P Earthquake Zn Ph2B | 201512 | 23.54 | 4 | 0.0031250 | 0.29 | 0.88 |
| 380200-Services - Plastic & Copper | 900993 | Repl w/ 2220F 2P CentralWestEndPh1G | 201511 | 1,099.36 | 5 | 0.0031250 | 17.18 | 41.23 |
| 380200-Services - Plastic & Copper | 901011 | Rel w/ 450F 4P Sanford AOR | 201509 | 30,639.29 | 7 | 0.0031250 | 670.23 | 1,148.97 |
| 380200-Services - Plastic & Copper | 901011 | Rel w/ 450F 4P Sanford AOR | 201510 | (278.69) | 6 | 0.0031250 | (5.23) | (10.45) |
| 380200-Services - Plastic & Copper | 901013 | Rel w/ 1612F 4P Woodstock CJ | 201511 | (1,558.51) | 5 | 0.0031250 | (24.35) | (58.44) |
| 380200-Services - Plastic & Copper | 901013 | Rel w/ 1612F 4P Woodstock CJ | 201512 | 17.07 | 4 | 0.0031250 | 0.21 | 0.64 |
| 380200-Services - Plastic & Copper | 901019 | Rel w/ 80F 6S Fee Fee | 201509 | (67.05) | 7 | 0.0031250 | (1.47) | (2.51) |
| 380200-Services - Plastic & Copper | 901019 | Rel w/ 80F 6S Fee Fee | 201510 | (40.99) | 6 | 0.0031250 | (0.77) | (1.54) |
| 380200-Services - Plastic & Copper | 901040 | Repl w/ 315F 2P Amherst Ave | 201509 | (445.45) | 7 | 0.0031250 | (9.74) | (16.70) |
| 380200-Services - Plastic & Copper | 901059 | Repl w/ 680' 2P Gregg | 201509 | 47,107.63 | 7 | 0.0031250 | 1,030.48 | 1,766.54 |
| 380200-Services - Plastic & Copper | 901059 | Repl w/ 680' 2P Gregg | 201510 | 949.62 | 6 | 0.0031250 | 17.81 | 35.61 |
| 380200-Services - Plastic & Copper | 901059 | Repl w/ 680' 2P Gregg | 201511 | (645.11) | 5 | 0.0031250 | (10.08) | (24.19) |
| 380200-Services - Plastic & Copper | 901059 | Repl w/ 680' 2P Gregg | 201512 | 22.66 | 4 | 0.0031250 | 0.28 | 0.85 |
| 380200-Services - Plastic & Copper | 901063 | Rel w/ 1307F 4P Bessie AOR | 201509 | 112,871.64 | 7 | 0.0031250 | 2,469.07 | 4,232.69 |
| 380200-Services - Plastic & Copper | 901063 | Rel w/ 1307F 4P Bessie AOR | 201510 | 274.58 | 6 | 0.0031250 | 5.15 | 10.30 |
| 380200-Services - Plastic & Copper | 901063 | Rel w/ 1307F 4P Bessie AOR | 201511 | 5,650.11 | 5 | 0.0031250 | 88.28 | 211.88 |
| 380200-Services - Plastic & Copper | 901063 | Rel w/ 1307F 4P Bessie AOR | 201512 | 24.91 | 4 | 0.0031250 | 0.31 | 0.93 |
| 380200-Services - Plastic & Copper | 901071 | Rel w/ 285F 2P Froesel Ph2 | 201509 | (94.09) | 7 | 0.0031250 | (2.06) | (3.53) |
| 380200-Services - Plastic & Copper | 901071 | Rel w/ 285F 2P Froesel Ph2 | 201511 | 14.21 | 5 | 0.0031250 | 0.22 | 0.53 |
| 380200-Services - Plastic & Copper | 901071 | Rel w/ 285F 2P Froesel Ph2 | 201512 | (11.97) | 4 | 0.0031250 | (0.15) | (0.45) |
| 380200-Services - Plastic & Copper | 901081 | Rel w/ 970F 6P Pralle Lane | 201512 | 4,933.89 | 4 | 0.0031250 | 61.67 | 185.02 |
| 380200-Services - Plastic & Copper | 901088 | Repl w/ 4597F 2P U-City Ph1B | 201512 | 189,313.18 | 4 | 0.0031250 | 2,366.41 | 7,099.24 |
| 380200-Services - Plastic & Copper | 901107 | Rel w/ 62F 4P Southwest AOR | 201509 | (168.08) | 7 | 0.0031250 | (3.68) | (6.30) |
| 380200-Services - Plastic & Copper | 901107 | Rel w/ 62F 4P Southwest AOR | 201511 | 93.74 | 5 | 0.0031250 | 1.46 | 3.52 |
| 380200-Services - Plastic & Copper | 901107 | Rel w/ 62F 4P Southwest AOR | 201512 | (87.60) | 4 | 0.0031250 | (1.10) | (3.29) |
| 380200-Services - Plastic & Copper | 901111 | Repl w/ 955F 2P Hickory | 201509 | 10,116.14 | 7 | 0.0031250 | 221.29 | 379.36 |
| 380200-Services - Plastic & Copper | 901111 | Repl w/ 955F 2P Hickory | 201510 | 760.05 | 6 | 0.0031250 | 14.25 | 28.50 |
| 380200-Services - Plastic & Copper | 901111 | Repl w/ 955F 2P Hickory | 201511 | (149.28) | 5 | 0.0031250 | (2.33) | (5.60) |
| 380200-Services - Plastic & Copper | 901111 | Repl w/ 955F 2P Hickory | 201512 | 14.66 | 4 | 0.0031250 | 0.18 | 0.55 |
| 380200-Services - Plastic & Copper | 901114 | Repl w/ 1630F 2P Maffitt | 201512 | 64,156.59 | 4 | 0.0031250 | 801.96 | 2,405.87 |
| 380200-Services - Plastic & Copper | 901139 | Repl w/ 901F 2P Suburban Ave | 201509 | 10,836.52 | 7 | 0.0031250 | 237.05 | 406.37 |
| 380200-Services - Plastic & Copper | 901139 | Repl w/ 901F 2P Suburban Ave | 201510 | 2,296.49 | 6 | 0.0031250 | 43.06 | 86.12 |
| 380200-Services - Plastic & Copper | 901139 | Repl w/ 901F 2P Suburban Ave | 201511 | (69.17) | 5 | 0.0031250 | (1.08) | (2.59) |
| 380200-Services - Plastic & Copper | 901139 | Repl w/ 901F 2P Suburban Ave | 201512 | (1.39) | 4 | 0.0031250 | (0.02) | (0.05) |
| 380200-Services - Plastic & Copper | 901162 | Repl w/ 210F 2P St. Leonard Ct. | 201512 | 27,059.20 | 4 | 0.0031250 | 338.24 | 1,014.72 |
| 380200-Services - Plastic & Copper | 901173 | Vandeventer - City of St. Louis MRE | 201509 | (40.02) | 7 | 0.0031250 | (0.88) | (1.50) |
| 380200-Services - Plastic & Copper | 901173 | Rei w/ 260F 6P Vandeventer | 201511 | (42.95) | 5 | 0.0031250 | (0.67) | (1.61) |
| 380200-Services - Plastic & Copper | 901173 | Rei w/ 260F 6P Vandeventer | 201512 | 0.74 | 4 | 0.0031250 | 0.01 | 0.03 |
| 380200-Services - Plastic & Copper | 901178 | Repl w/ 185F 2P Evans | 201509 | 3,920.21 | 7 | 0.0031250 | 85.75 | 147.01 |
| 380200-Services - Plastic & Copper | 901178 | Repl w/ 185F 2P Evans | 201510 | 302.14 | 6 | 0.0031250 | 5.67 | 11.33 |
| 380200-Services - Plastic & Copper | 901178 | Repl w/ 185F 2P Evans | 201511 | (0.30) | 5 | 0.0031250 | - | (0.01) |
| 380200-Services - Plastic & Copper | 901178 | Repl w/ 185F 2P Evans | 201512 | 11.49 | 4 | 0.0031250 | 0.14 | 0.43 |
| 380200-Services - Plastic & Copper | 901308 | Rel w/ 400F 2P Bismark Ave | 201512 | 2,221.47 | 4 | 0.0031250 | 27.77 | 83.31 |
| ACCOUNT 38020 SERVICES PLASTIC & COPPER | | Renewed Services | 201601 | 1,407,500.00 | 3 | 0.0031250 | 13,195.31 | 52,781.25 |
| ACCOUNT 38020 SERVICES PLASTIC & COPPER | | Renewed Services | 201602 | 1,407,500.00 | 2 | 0.0031250 | 8,796.88 | 52,781.25 |

TOTAL 13,509,753.75

204,175.49 506,615.81

Total Service Line Replacements and Insertion Projects:

13,964,060.99

215,624.57

530,375.92

REGULATOR STATIONS - ADDITIONS

LACLEDE DIVISION

| PLANT ACCOUNT | WORK ORDER | BUDGET PROJECT | DESCRIPTION | IN SERVICE DATE | ADDITION AMOUNT | MONTHS | DEPR. MO. RATE | ACCUM. DEPR. | DEPR. EXPENSE |
|-------------------------------------|------------|----------------|------------------------------------|-----------------|-------------------|--------|----------------|----------------|-----------------|
| 375100-Struct & Impv - Meas & Reg S | 606330 | | 60633 Inst Reg Sta Jefferson-Rut | 201509 | (212.71) | 7 | 0.0025000 | (3.72) | (6.38) |
| | | | | | | | | | |
| 378000-Meas & Reg Station Equipment | 003304 | | Replace Osceola & Virginia Reg Sta | 201509 | 16.05 | 7 | 0.0030917 | 0.35 | 0.60 |
| 378000-Meas & Reg Station Equipment | 003305 | | Repl Euclid & Hooke Reg Station | 201509 | (2,329.20) | 7 | 0.0030917 | (50.41) | (86.41) |
| | | | | | | | | | |
| 378000-Meas & Reg Station Equipment | 606330 | | 60633 Inst Reg Sta Jefferson-Rut | 201509 | (271.75) | 7 | 0.0030917 | (5.88) | (10.08) |
| REGULATOR STATIONS - ADDITIONS | | | REGULATOR STATIONS - ADDITIONS | 201601 | | 3 | 0.0030917 | - | - |
| REGULATOR STATIONS - ADDITIONS | | | REGULATOR STATIONS - ADDITIONS | 201602 | | 2 | 0.0030917 | - | - |
| TOTAL | | | | | <u>(2,797.61)</u> | | | <u>(59.66)</u> | <u>(102.27)</u> |

ACCOUNT 379000 MEASURING & REGULATING STATION EQUIPMENT - CITY GATE

| PLANT ACCOUNT | WORK ORDER | BUDGET PROJECT | DESCRIPTION | IN SERVICE DATE | ADDITION AMOUNT | MONTHS | DEPR. MO. RATE | ACCUM. DEPR. | DEPR. EXPENSE |
|-------------------------------------|------------|----------------|------------------------------------|-----------------|------------------|--------|----------------|---------------|---------------|
| 379000-Meas & Reg Station Eqpt-City | 005045 | | Replace odorant tanks on MoNat Sys | 201509 | (1,783.17) | 7 | 0.0030917 | (38.59) | (66.16) |
| 379000-Meas & Reg Station Eqpt-City | 007132 | | Ph 2 - Replace Monat Odorant Tanks | 201509 | 16,664.12 | 7 | 0.0030917 | 360.64 | 618.25 |
| 379000-Meas & Reg Station Eqpt-City | 007132 | | Ph 2 - Replace Monat Odorant Tanks | 201511 | (189.34) | 5 | 0.0030917 | (2.93) | (7.02) |
| 379000-Meas & Reg Station Eqpt-City | 007132 | | Ph 2 - Replace Monat Odorant Tanks | 201512 | (51.76) | 4 | 0.0030917 | (0.64) | (1.92) |
| REGULATOR STATIONS - ADDITIONS | | | REGULATOR STATIONS - ADDITIONS | 201601 | | 3 | 0.0030917 | - | - |
| REGULATOR STATIONS - ADDITIONS | | | REGULATOR STATIONS - ADDITIONS | 201602 | | 2 | 0.0030917 | - | - |
| TOTAL | | | | | <u>14,839.85</u> | | | <u>318.48</u> | <u>543.15</u> |

Total Regulator Station Replacements

11,842.24

258.82

440.88

MAIN RELOCATIONS NET OF REIMBURSEMENTS - NET ADDITIONS

| PLANT ACCOUNT | WORK ORDER | BUDGET PROJECT | DESCRIPTION | IN SERVICE DATE | ADDITION AMOUNT | MONTHS | DEPR. MO. RATE | ACCUM. DEPR. | DEPR. EXPENSE |
|------------------------|------------|----------------|------------------------------------|-----------------|-----------------|--------|----------------|--------------|---------------|
| 376100-Mains - Steel | 900732 | 3403L | Rel w/ 120F 6S DeBailiviere Bridge | 201512 | (2,962.09) | 4 | 0.0012000 | (14.22) | (42.65) |
| 376300-Mains - Plastic | 001337 | 3403L | Inst 622F 4P Shenandoah | 201509 | 368,019.86 | 7 | 0.0013083 | 3,370.36 | 5,777.76 |
| 376300-Mains - Plastic | 001337 | 3403L | Inst 622F 4P Shenandoah CJ -Reimb | 201511 | (169,531.01) | 5 | 0.0013083 | (1,108.99) | (2,661.57) |
| 376300-Mains - Plastic | 001494 | 3403M | Relocate along Oak Grove (Phase 2) | 201509 | 1,251.18 | 7 | 0.0013083 | 11.46 | 19.64 |
| 376300-Mains - Plastic | 001878 | 3403M | Relocate main at Westwood and Katy | 201509 | 103,521.26 | 7 | 0.0013083 | 948.06 | 1,625.24 |
| 376100-Mains - Steel | 002882 | 3403M | FE - American Legion & S Mill St | 201509 | 4,780.64 | 7 | 0.0012000 | 40.16 | 68.84 |

| | | | | | | | | | |
|------------------------|--------|-------|-------------------------------------|--------|-------------|---|-----------|----------|------------|
| 376300-Mains - Plastic | 002862 | 3403M | FE - American Legion & S Mill St | 201509 | (408.90) | 7 | 0.0013083 | (3.74) | (6.42) |
| 376300-Mains - Plastic | 003763 | 3403M | Rel w/ 3200F 4P Oak Grove Rd-MN | 201509 | 51.41 | 7 | 0.0013083 | 0.47 | 0.81 |
| 376300-Mains - Plastic | 006238 | 3403M | Rel w/ 23F 2P Prairie Dell Rd | 201509 | 465.21 | 7 | 0.0013083 | 4.26 | 7.30 |
| 376300-Mains - Plastic | 009113 | 3403M | Rel w/ 210F 4P W Congress MN | 201512 | 16,260.54 | 4 | 0.0013083 | 85.09 | 255.28 |
| 376300-Mains - Plastic | 647910 | 3401L | 64791 225F 2P S MAIN ST | 201511 | (254.90) | 5 | 0.0013083 | (1.67) | (4.00) |
| 376300-Mains - Plastic | 698960 | 3401L | 69896 MAIN CONTR CONSTR ST CHS | 201509 | 22,488.59 | 7 | 0.0013083 | 205.95 | 353.06 |
| 376300-Mains - Plastic | 699260 | 3401L | 69926 CONTBTN CONST CITY | 201509 | (31,859.79) | 7 | 0.0013083 | (291.78) | (500.19) |
| 376300-Mains - Plastic | 699760 | 3401L | 69976 CONTBTN CONST CNTY | 201509 | (24,222.80) | 7 | 0.0013083 | (221.83) | (360.29) |
| 376300-Mains - Plastic | 900095 | 3403L | Rel w/ 350F 8P Mason Rd Bridge #211 | 201509 | (1,837.83) | 7 | 0.0013083 | (16.83) | (28.85) |
| 376300-Mains - Plastic | 900095 | 3403L | Rel w/ 350F 8P Mason Rd Bridge #211 | 201509 | (26.17) | 7 | 0.0013083 | (0.24) | (0.41) |
| 376300-Mains - Plastic | 900095 | 3403L | Rel w/ 350F 8P Mason Rd Bridge #211 | 201511 | (1,295.45) | 5 | 0.0013083 | (8.47) | (20.34) |
| 376300-Mains - Plastic | 900095 | 3403L | Rel w/ 350F 8P Mason Rd Bridge #211 | 201511 | 1,295.45 | 5 | 0.0013083 | 8.47 | 20.34 |
| 376300-Mains - Plastic | 900095 | 3403L | Rel w/ 350F 8P Mason Rd Bridge #211 | 201512 | 3.83 | 4 | 0.0013083 | 0.02 | 0.06 |
| 376300-Mains - Plastic | 900095 | 3403L | Rel w/ 350F 8P Mason Rd Bridge #211 | 201512 | 225.38 | 4 | 0.0013083 | 1.18 | 3.54 |
| 376100-Mains - Steel | 900099 | 3403L | Rel 1830F 2P McKnight Rd | 201509 | (59.16) | 7 | 0.0012000 | (0.50) | (0.85) |
| 376300-Mains - Plastic | 900099 | 3403L | Rel 1830F 2P McKnight Rd | 201509 | (628.21) | 7 | 0.0013083 | (5.75) | (9.86) |
| 376300-Mains - Plastic | 900099 | 3403L | Rel 1830F 2P McKnight Rd | 201509 | (8.99) | 7 | 0.0013083 | (0.08) | (0.14) |
| 376100-Mains - Steel | 900104 | 3403L | Rel w/ 3018F Var-Kingshighway Bridg | 201512 | 115,776.74 | 4 | 0.0012000 | 555.73 | 1,667.19 |
| 376300-Mains - Plastic | 900104 | 3403L | Rel w/ 3018F Var-Kingshighway Bridg | 201512 | 763,983.73 | 4 | 0.0013083 | 3,998.08 | 11,994.24 |
| 376100-Mains - Steel | 900147 | 3403L | Inst 2270F Route 364-Final Phase | 201509 | (7.05) | 7 | 0.0012000 | (0.06) | (0.10) |
| 376300-Mains - Plastic | 900147 | 3403L | Inst 2270F Route 364-Final Phase | 201509 | (4.26) | 7 | 0.0013083 | (0.04) | (0.07) |
| 376300-Mains - Plastic | 900233 | 3403L | Rel w/ 1924F 6P Fee Fee Road | 201509 | (2.25) | 7 | 0.0013083 | (0.02) | (0.04) |
| 376300-Mains - Plastic | 900233 | 3403L | Rel w/ 1924F 6P Fee Fee Road | 201509 | (0.03) | 7 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900313 | 3403L | Rel w/ 775F 2P Caulks Hill Rd CJ | 201510 | (3,280.19) | 6 | 0.0013083 | (25.75) | (51.50) |
| 376100-Mains - Steel | 900319 | 3403L | Repl w/ 50F 6S Old Halls Ferry/Vail | 201509 | (3,036.41) | 7 | 0.0012000 | (25.51) | (43.72) |
| 376100-Mains - Steel | 900319 | 3403L | Repl w/ 50F 6S Old Halls Ferry/Vail | 201509 | 2,242.63 | 7 | 0.0012000 | 18.84 | 32.29 |
| 376100-Mains - Steel | 900319 | 3403L | Repl w/ 50F 6S Old Halls Ferry/Vail | 201510 | (222.04) | 6 | 0.0012000 | (1.60) | (3.20) |
| 376100-Mains - Steel | 900319 | 3403L | Repl w/ 50F 6S Old Halls Ferry/Vail | 201510 | (12.33) | 6 | 0.0012000 | (0.09) | (0.18) |
| 376300-Mains - Plastic | 900444 | 3403L | Rel w/405F 4P Pitman Hill Phase3 CJ | 201510 | 18,042.49 | 6 | 0.0013083 | 141.63 | 283.26 |
| 376300-Mains - Plastic | 900454 | 3403L | Inst 229F 2P Pitman Hill Phase 3 CJ | 201510 | 10,728.15 | 6 | 0.0013083 | 84.21 | 168.43 |
| 376100-Mains - Steel | 900498 | 3403L | Rel w/ 1150F 6P Saline Road | 201512 | 948.63 | 4 | 0.0012000 | 4.55 | 13.66 |
| 376100-Mains - Steel | 900498 | 3403L | Rel w/ 1150F 6P Saline Road | 201512 | 54,156.39 | 4 | 0.0012000 | 259.95 | 779.85 |
| 376300-Mains - Plastic | 900498 | 3403L | Rel w/ 1150F 6P Saline Road | 201512 | 391,746.49 | 4 | 0.0013083 | 2,050.09 | 6,150.26 |
| 376300-Mains - Plastic | 900508 | 3403L | Rel w/ 127F 2P Dearborn | 201509 | (148.31) | 7 | 0.0013083 | (1.36) | (2.33) |
| 376100-Mains - Steel | 900602 | 3403L | Rel w/ 24F 8S Natural Bridge | 201509 | (900.47) | 7 | 0.0012000 | (7.56) | (12.97) |
| 376300-Mains - Plastic | 900602 | 3403L | Rel w/ 24F 8S Natural Bridge | 201509 | (93.46) | 7 | 0.0013083 | (0.86) | (1.47) |
| 376100-Mains - Steel | 900633 | 3403L | Rel w/ 321F 4S 2S Progress Parkway | 201509 | (1,441.95) | 7 | 0.0012000 | (12.11) | (20.76) |
| 376100-Mains - Steel | 900633 | 3403L | Rel w/ 321F 4S 2S Progress Parkway | 201509 | (4,493.62) | 7 | 0.0012000 | (37.75) | (64.71) |
| 376100-Mains - Steel | 900633 | 3403L | Rel w/ 321F 4S 2S Progress Parkway | 201510 | (826.28) | 6 | 0.0012000 | (5.95) | (11.90) |
| 376300-Mains - Plastic | 900670 | 3403L | Rel w/ 400F 6P Vogel Rd | 201509 | (1,327.26) | 7 | 0.0013083 | (12.16) | (20.84) |
| 376300-Mains - Plastic | 900670 | 3403L | Rel w/ 400F 6P Vogel Rd | 201510 | 1.45 | 6 | 0.0013083 | 0.01 | 0.02 |
| 376300-Mains - Plastic | 900693 | 3403L | Rel w/ 350F 4P Civic Center Dr | 201509 | (64,833.06) | 7 | 0.0013083 | (593.75) | (1,017.85) |
| 376300-Mains - Plastic | 900723 | 3403L | Rel w/ 3350F 2P Valley Park | 201509 | 3.72 | 7 | 0.0013083 | 0.03 | 0.06 |
| 376300-Mains - Plastic | 900723 | 3403L | Rel w/ 3350F 2P Valley Park | 201509 | 0.08 | 7 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900730 | 3403L | Rel w/ 310F 2P Bramblett | 201509 | (1,027.05) | 7 | 0.0013083 | (9.41) | (16.12) |
| 376300-Mains - Plastic | 900730 | 3403L | Rel w/ 310F 2P Bramblett | 201510 | (2.33) | 6 | 0.0013083 | (0.02) | (0.04) |
| 376100-Mains - Steel | 900732 | 3403L | Rel w/ 120F 6S DeBaliviere Bridge | 201509 | (1,797.38) | 7 | 0.0012000 | (15.10) | (25.88) |
| 376100-Mains - Steel | 900732 | 3403L | Rel w/ 120F 6S DeBaliviere Bridge | 201509 | (72.95) | 7 | 0.0012000 | (0.61) | (1.05) |
| 376300-Mains - Plastic | 900732 | 3403L | Rel w/ 120F 6S DeBaliviere Bridge | 201509 | (80.03) | 7 | 0.0013083 | (0.73) | (1.26) |
| 376100-Mains - Steel | 900732 | 3403L | Rel w/ 120F 6S DeBaliviere Bridge | 201510 | 15,688.62 | 6 | 0.0012000 | 112.96 | 225.92 |
| 376100-Mains - Steel | 900732 | 3403L | Rel w/ 120F 6S DeBaliviere Bridge | 201510 | 636.57 | 6 | 0.0012000 | 4.58 | 9.17 |
| 376300-Mains - Plastic | 900732 | 3403L | Rel w/ 120F 6S DeBaliviere Bridge | 201510 | 698.71 | 6 | 0.0013083 | 5.48 | 10.97 |

| | | | | | | | | | |
|------------------------|--------|-------|-------------------------------------|--------|-------------|---|-----------|----------|----------|
| 376100-Mains - Steel | 900732 | 3403L | Rel w/ 120F 6S DeBaliviere Bridge | 201511 | 0.08 | 5 | 0.0012000 | - | - |
| 376100-Mains - Steel | 900732 | 3403L | Rel w/ 120F 6S DeBaliviere Bridge | 201511 | (0.01) | 5 | 0.0012000 | - | - |
| 376300-Mains - Plastic | 900732 | 3403L | Rel w/ 120F 6S DeBaliviere Bridge | 201511 | 0.01 | 5 | 0.0013083 | - | - |
| 376100-Mains - Steel | 900732 | 3403L | Rel w/ 120F 6S DeBaliviere Bridge | 201512 | (49,447.88) | 4 | 0.0012000 | (237.35) | (712.05) |
| 376300-Mains - Plastic | 900732 | 3403L | Rel w/ 120F 6S DeBaliviere Bridge | 201512 | 3,094.70 | 4 | 0.0013083 | 16.20 | 48.59 |
| 376300-Mains - Plastic | 900732 | 3403L | Rel w/ 120F 6S DeBaliviere Bridge | 201512 | 49,312.87 | 4 | 0.0013083 | 258.06 | 774.19 |
| 376300-Mains - Plastic | 900775 | 3403L | Rel w/ 1535F 2P Page&Hodiament AOR | 201509 | (1,086.17) | 7 | 0.0013083 | (9.95) | (17.05) |
| 376300-Mains - Plastic | 900775 | 3403L | Rel w/ 1535F 2P Page&Hodiament AOR | 201509 | (55.80) | 7 | 0.0013083 | (0.51) | (0.88) |
| 376300-Mains - Plastic | 900813 | 3403L | Rel w/ 700F 2P Froesel | 201509 | 0.43 | 7 | 0.0013083 | - | 0.01 |
| 376100-Mains - Steel | 900817 | 3403L | Rel w/ 330F 6P St Cyr Rd Culvert | 201509 | 2,957.38 | 7 | 0.0012000 | 24.84 | 42.59 |
| 376300-Mains - Plastic | 900817 | 3403L | Rel w/ 330F 6P St Cyr Rd Culvert | 201509 | 4,180.64 | 7 | 0.0013083 | 38.29 | 65.63 |
| 376300-Mains - Plastic | 900817 | 3403L | Rel w/ 330F 6P St Cyr Rd Culvert | 201509 | 311.13 | 7 | 0.0013083 | 2.85 | 4.88 |
| 376100-Mains - Steel | 900817 | 3403L | Rel w/ 330F 6P St Cyr Rd Culvert | 201510 | (40.99) | 6 | 0.0012000 | (0.30) | (0.59) |
| 376300-Mains - Plastic | 900817 | 3403L | Rel w/ 330F 6P St Cyr Rd Culvert | 201510 | (132.44) | 6 | 0.0013083 | (1.04) | (2.08) |
| 376300-Mains - Plastic | 900817 | 3403L | Rel w/ 330F 6P St Cyr Rd Culvert | 201510 | (2.28) | 6 | 0.0013083 | (0.02) | (0.04) |
| 376100-Mains - Steel | 900819 | 3403L | Rel w/ 18F 6S Howdershell Rd | 201509 | (749.99) | 7 | 0.0012000 | (6.30) | (10.80) |
| 376100-Mains - Steel | 900819 | 3403L | Rel w/ 18F 6S Howdershell Rd | 201509 | (20.63) | 7 | 0.0012000 | (0.17) | (0.30) |
| 376300-Mains - Plastic | 900820 | 3403L | Rel w/ 410' 6P Willott Rd BridgeCJ | 201509 | 2,816.68 | 7 | 0.0013083 | 25.80 | 44.22 |
| 376300-Mains - Plastic | 900820 | 3403L | Rel w/ 410' 6P Willott Rd BridgeCJ | 201510 | 9.43 | 6 | 0.0013083 | 0.07 | 0.15 |
| 376100-Mains - Steel | 900822 | 3403L | Rel w/ 130F 6S Price Road | 201509 | (1,482.11) | 7 | 0.0012000 | (12.45) | (21.34) |
| 376100-Mains - Steel | 900822 | 3403L | Rel w/ 130F 6S Price Road | 201509 | (83.66) | 7 | 0.0012000 | (0.70) | (1.20) |
| 376300-Mains - Plastic | 900822 | 3403L | Rel w/ 130F 6S Price Road | 201509 | (4,644.81) | 7 | 0.0013083 | (42.54) | (72.92) |
| 376300-Mains - Plastic | 900822 | 3403L | Rel w/ 130F 6S Price Road | 201509 | (174.45) | 7 | 0.0013083 | (1.60) | (2.74) |
| 376100-Mains - Steel | 900837 | 3403L | Rel w/ 1736F 4P Champ Line | 201509 | (376.85) | 7 | 0.0012000 | (3.17) | (5.43) |
| 376300-Mains - Plastic | 900837 | 3403L | Rel w/ 1736F 4P Champ Line | 201509 | (2,601.92) | 7 | 0.0013083 | (23.83) | (40.85) |
| 376100-Mains - Steel | 900837 | 3403L | Rel w/ 1736F 4P Champ Line | 201511 | 191.30 | 5 | 0.0012000 | 1.15 | 2.75 |
| 376300-Mains - Plastic | 900837 | 3403L | Rel w/ 1736F 4P Champ Line | 201511 | (191.30) | 5 | 0.0013083 | (1.25) | (3.00) |
| 376300-Mains - Plastic | 900841 | 340RL | Rel w/ 57F 4P Ashland AOR | 201509 | (216.10) | 7 | 0.0013083 | (1.98) | (3.39) |
| 376300-Mains - Plastic | 900841 | 340RL | Rel w/ 57F 4P Ashland AOR | 201509 | (11.86) | 7 | 0.0013083 | (0.11) | (0.19) |
| 376300-Mains - Plastic | 900845 | 340RL | Rel w/ 85F 4P Russell & Thurman AOR | 201509 | (530.45) | 7 | 0.0013083 | (4.86) | (8.33) |
| 376300-Mains - Plastic | 900845 | 340RL | Rel w/ 85F 4P Russell & Thurman AOR | 201509 | (39.25) | 7 | 0.0013083 | (0.36) | (0.62) |
| 376300-Mains - Plastic | 900848 | 340RL | Rel w/ 810F 4P Bircher & Newstead | 201509 | (1,693.22) | 7 | 0.0013083 | (15.51) | (26.58) |
| 376300-Mains - Plastic | 900848 | 340RL | Rel w/ 810F 4P Bircher & Newstead | 201509 | (28.24) | 7 | 0.0013083 | (0.26) | (0.44) |
| 376100-Mains - Steel | 900852 | 3403L | Rel w/ 570' 8S Rte100 Great Streets | 201509 | (2,867.77) | 7 | 0.0012000 | (24.09) | (41.30) |
| 376300-Mains - Plastic | 900852 | 3403L | Rel w/ 570' 8S Rte100 Great Streets | 201509 | (130.71) | 7 | 0.0013083 | (1.20) | (2.05) |
| 376300-Mains - Plastic | 900858 | 3403L | Rel w/ 60F 3P Burning Leaf Bridge | 201509 | (59.68) | 7 | 0.0013083 | (0.55) | (0.94) |
| 376300-Mains - Plastic | 900858 | 3403L | Rel w/ 60F 3P Burning Leaf Bridge | 201510 | (62.79) | 6 | 0.0013083 | (0.49) | (0.99) |
| 376300-Mains - Plastic | 900864 | 3403L | Rel w/ 80F 4P St. Louis & Norwood | 201509 | (274.12) | 7 | 0.0013083 | (2.51) | (4.30) |
| 376300-Mains - Plastic | 900864 | 3403L | Rel w/ 80F 4P St. Louis & Norwood | 201509 | (21.05) | 7 | 0.0013083 | (0.19) | (0.33) |
| 376300-Mains - Plastic | 900864 | 3403L | Rel w/ 80F 4P St. Louis & Norwood | 201510 | (237.06) | 6 | 0.0013083 | (1.86) | (3.72) |
| 376300-Mains - Plastic | 900864 | 3403L | Rel w/ 80F 4P St. Louis & Norwood | 201510 | (18.93) | 6 | 0.0013083 | (0.15) | (0.30) |
| 376300-Mains - Plastic | 900866 | 3403L | Repl w/ 1480F 6P 4P-IKEA | 201509 | (5,654.04) | 7 | 0.0013083 | (51.78) | (88.77) |
| 376300-Mains - Plastic | 900866 | 3403L | Repl w/ 1480F 6P 4P-IKEA | 201509 | (840.88) | 7 | 0.0013083 | (7.70) | (13.20) |
| 376300-Mains - Plastic | 900868 | 3403L | Rel w/ 210F 2P Vance -Valley Park | 201510 | 8,598.23 | 6 | 0.0013083 | 67.49 | 134.99 |
| 376300-Mains - Plastic | 900868 | 3403L | Rel w/ 210F 2P Vance -Valley Park | 201510 | 248.91 | 6 | 0.0013083 | 1.95 | 3.91 |
| 376300-Mains - Plastic | 900868 | 3403L | Rel w/ 210F 2P Vance -Valley Park | 201511 | 479.91 | 5 | 0.0013083 | 3.14 | 7.53 |
| 376300-Mains - Plastic | 900868 | 3403L | Rel w/ 210F 2P Vance -Valley Park | 201511 | 13.90 | 5 | 0.0013083 | 0.09 | 0.22 |
| 376300-Mains - Plastic | 900868 | 3403L | Rel w/ 210F 2P Vance -Valley Park | 201512 | 2.98 | 4 | 0.0013083 | 0.02 | 0.05 |
| 376300-Mains - Plastic | 900868 | 3403L | Rel w/ 210F 2P Vance -Valley Park | 201512 | 102.76 | 4 | 0.0013083 | 0.54 | 1.61 |
| 376100-Mains - Steel | 900885 | 3403L | Rel w/ 293F 2S Spellman Ph2 | 201509 | (2,409.79) | 7 | 0.0012000 | (20.24) | (34.70) |
| 376100-Mains - Steel | 900885 | 3403L | Rel w/ 293F 2S Spellman Ph2 | 201509 | (48.32) | 7 | 0.0012000 | (0.41) | (0.70) |
| 376100-Mains - Steel | 900885 | 3403L | Rel w/ 293F 2S Spellman Ph2 | 201510 | (20,775.07) | 6 | 0.0012000 | (149.58) | (299.16) |

| | | | | | | | | | |
|------------------------|--------|-------|-------------------------------------|--------|------------|---|-----------|---------|---------|
| 376300-Mains - Plastic | 901106 | 3403L | Rel w/ 38F 4P Compton AOR | 201509 | (680.60) | 7 | 0.0013083 | (6.23) | (10.69) |
| 376300-Mains - Plastic | 901106 | 3403L | Rel w/ 38F 4P Compton AOR | 201509 | (41.30) | 7 | 0.0013083 | (0.38) | (0.65) |
| 376300-Mains - Plastic | 901106 | 3403L | Rel w/ 38F 4P Compton AOR | 201511 | 67.19 | 5 | 0.0013083 | 0.44 | 1.05 |
| 376300-Mains - Plastic | 901106 | 3403L | Rel w/ 38F 4P Compton AOR | 201511 | (118.13) | 5 | 0.0013083 | (0.77) | (1.85) |
| 376300-Mains - Plastic | 901106 | 3403L | Rel w/ 38F 4P Compton AOR | 201512 | 192.06 | 4 | 0.0013083 | 1.01 | 3.02 |
| 376300-Mains - Plastic | 901106 | 3403L | Rel w/ 38F 4P Compton AOR | 201512 | 1,058.81 | 4 | 0.0013083 | 5.54 | 16.62 |
| 376300-Mains - Plastic | 901107 | 3403L | Rel w/ 62F 4P Southwest AOR | 201509 | (556.72) | 7 | 0.0013083 | (5.10) | (8.74) |
| 376300-Mains - Plastic | 901107 | 3403L | Rel w/ 62F 4P Southwest AOR | 201509 | (12.25) | 7 | 0.0013083 | (0.11) | (0.19) |
| 376300-Mains - Plastic | 901107 | 3403L | Rel w/ 62F 4P Southwest AOR | 201511 | (182.80) | 5 | 0.0013083 | (1.20) | (2.87) |
| 376300-Mains - Plastic | 901107 | 3403L | Rel w/ 62F 4P Southwest AOR | 201511 | 14.83 | 5 | 0.0013083 | 0.10 | 0.23 |
| 376300-Mains - Plastic | 901107 | 3403L | Rel w/ 62F 4P Southwest AOR | 201512 | (263.72) | 4 | 0.0013083 | (1.38) | (4.14) |
| 376300-Mains - Plastic | 901107 | 3403L | Rel w/ 62F 4P Southwest AOR | 201512 | (2.09) | 4 | 0.0013083 | (0.01) | (0.03) |
| 376100-Mains - Steel | 901109 | 3403L | Rel w/ 18F 2S Madison | 201509 | 266.11 | 7 | 0.0012000 | 2.24 | 3.83 |
| 376100-Mains - Steel | 901173 | 3403L | Vandeventer - City of St. Louis MRE | 201509 | (129.71) | 7 | 0.0012000 | (1.09) | (1.87) |
| 376300-Mains - Plastic | 901173 | 3403L | Vandeventer - City of St. Louis MRE | 201509 | (1,499.83) | 7 | 0.0013083 | (13.74) | (23.55) |
| 376300-Mains - Plastic | 901173 | 3403L | Vandeventer - City of St. Louis MRE | 201509 | (200.08) | 7 | 0.0013083 | (1.83) | (3.14) |
| 376100-Mains - Steel | 901173 | 3403L | Rel w/ 260F 6P Vandeventer | 201511 | 39.73 | 5 | 0.0012000 | 0.24 | 0.57 |
| 376300-Mains - Plastic | 901173 | 3403L | Rel w/ 260F 6P Vandeventer | 201511 | (303.03) | 5 | 0.0013083 | (1.98) | (4.78) |
| 376300-Mains - Plastic | 901173 | 3403L | Rel w/ 260F 6P Vandeventer | 201511 | 327.15 | 5 | 0.0013083 | 2.14 | 5.14 |
| 376100-Mains - Steel | 901173 | 3403L | Rel w/ 260F 6P Vandeventer | 201512 | 3.58 | 4 | 0.0012000 | 0.02 | 0.05 |
| 376300-Mains - Plastic | 901173 | 3403L | Rel w/ 260F 6P Vandeventer | 201512 | 6.89 | 4 | 0.0013083 | 0.04 | 0.11 |
| 376300-Mains - Plastic | 901173 | 3403L | Rel w/ 260F 6P Vandeventer | 201512 | 37.90 | 4 | 0.0013083 | 0.20 | 0.60 |
| 376300-Mains - Plastic | 901248 | 3403M | Rel 29F 4PDenmarkFrkin CntySEENOTE | 201512 | 3,916.40 | 4 | 0.0013083 | 20.50 | 61.49 |
| 376300-Mains - Plastic | 901308 | 3403L | Rel w/ 400F 2P Bismark Ave | 201512 | 1,330.99 | 4 | 0.0013083 | 6.97 | 20.90 |
| 376300-Mains - Plastic | 901308 | 3403L | Rel w/ 400F 2P Bismark Ave | 201512 | 34,020.16 | 4 | 0.0013083 | 178.03 | 534.10 |
| 376300-Mains - Plastic | | 3403L | Relocation of Distribution System | 201507 | | 9 | 0.0013083 | - | - |
| 376300-Mains - Plastic | | 3403L | Relocation of Distribution System | 201508 | | 8 | 0.0013083 | - | - |

Total Main Relocations Net of Reimbursements

TOTAL 1,885,560.27 11,561.70 29,377.01

MAIN REINFORCEMENTS RELATED TO OTHER ISRS ELIGIBLE PROJECTS

ACCOUNT 376 PLASTIC MAINS REINFORCEMENT RELATED TO RELOCATION OF GAS MAIN

| PLANT ACCOUNT | WORK ORDER | BUDGET PROJECT | DESCRIPTION | IN SERVICE DATE | ADDITION AMOUNT | MONTHS | DEPR. MO. RATE | ACCUM. DEPR. | DEPR. EXPENSE |
|---------------|------------|----------------|-------------|-----------------|-----------------|--------|----------------|--------------|---------------|
|---------------|------------|----------------|-------------|-----------------|-----------------|--------|----------------|--------------|---------------|

TOTAL - - -

Total Main Reinforcements related to other ISRS-eligible projects

TOTAL - - -

Total ISRS-Eligible Additions

35,795,199.90 333,210.36 889,748.90

MAIN REPLACEMENTS - RETIREMENTS

MAINS - PLASTIC - RETIREMENTS - MAIN REPLACEMENTS

| PLANT ACCOUNT | WORK ORDER | BUDGET PROJECT | RELATED CWO | DESCRIPTION | RETIREMENT DATE | RETIREMENT AMOUNT | MONTHS | DEPR. MO. RATE | ACCUM. DEPR. | DEPR. EXPENSE |
|------------------------|------------|----------------|-------------|-------------------------------------|-----------------|-------------------|--------|----------------|--------------|---------------|
| 376300-Mains - Plastic | 002140 | 3303L | 002140 | Inst 6894F 2P Bertha-Wellston 1A | 201509 | (21,921.02) | 7 | 0.0013083 | (200.75) | (344.15) |
| 376300-Mains - Plastic | 699220 | 3301L | 699220 | 69922 MAIN PLS INST MTCE | 201509 | (1,343.72) | 7 | 0.0013083 | (12.31) | (21.10) |
| 376300-Mains - Plastic | 900274 | 3303L | 900274 | Repl w/ 3390F 2P Wellington Ph 4D | 201509 | (18,157.01) | 7 | 0.0013083 | (166.28) | (285.06) |
| 376300-Mains - Plastic | 900458 | 3303L | 900458 | Repl w/ 2796F 2P Wellington Grd Ph4 | 201511 | (2,847.93) | 5 | 0.0013083 | (18.63) | (44.71) |
| 376300-Mains - Plastic | 900558 | 3303L | 900558 | Inst 1859F 2P Walnut Park Ph6B | 201510 | (6,151.14) | 6 | 0.0013083 | (48.29) | (96.57) |
| 376300-Mains - Plastic | 900607 | 3303L | 900608 | Inst 3183F 2P Maplewood Ph2C | 201511 | (25,814.73) | 5 | 0.0013083 | (168.87) | (405.28) |
| 376300-Mains - Plastic | 900650 | 3303L | 900650 | Inst 3290F 2P St Louis Hills Ph1A | 201509 | (9,308.79) | 7 | 0.0013083 | (85.25) | (146.14) |
| 376300-Mains - Plastic | 900691 | 3303L | 900691 | Repl w/ 3458F 2P Cole & 18th Ph H | 201512 | (10,924.79) | 4 | 0.0013083 | (57.17) | (171.51) |
| 376300-Mains - Plastic | 900763 | 3303L | 900763 | Inst 3508F 2P Earthquake Zone Ph1B | 201509 | (11,093.01) | 7 | 0.0013083 | (101.59) | (174.16) |
| 376300-Mains - Plastic | 900873 | 3303L | 900873 | Repl w/ 538F 2P Longacre | 201510 | (786.62) | 6 | 0.0013083 | (6.17) | (12.35) |
| 376300-Mains - Plastic | 900876 | 3303L | 900876 | Repl w/ 1060F 2P Rauschenbach PVC | 201509 | (2,840.24) | 7 | 0.0013083 | (26.01) | (44.59) |
| 376300-Mains - Plastic | 901114 | 3303L | 901114 | Repl w/ 1630F 2P Maffitt | 201512 | (11,379.50) | 4 | 0.0013083 | (59.55) | (178.65) |
| 376300-Mains - Plastic | 901139 | 3303L | 901139 | Repl w/ 901F 2P Suburban Ave | 201510 | (2,078.03) | 6 | 0.0013083 | (16.31) | (32.62) |
| 376300-Mains - Plastic | 901220 | 3303L | 901220 | Aband 511F 4C Marcus AOR | 201512 | (10,663.71) | 4 | 0.0013083 | (55.81) | (167.42) |

TOTAL - MAINS - PLASTIC - RETIREMENTS - MAIN REPLACEMENTS

(135,310.24)

(1,022.99)

(2,124.31)

MAINS - CAST IRON - RETIREMENTS - MAIN REPLACEMENTS

| PLANT ACCOUNT | WORK ORDER | BUDGET PROJECT | RELATED CWO | DESCRIPTION | RETIREMENT DATE | RETIREMENT AMOUNT | MONTHS | DEPR. MO. RATE | ACCUM. DEPR. | DEPR. EXPENSE |
|--------------------------|------------|----------------|-------------|-------------------------------------|-----------------|-------------------|--------|----------------|--------------|---------------|
| 376200-Mains - Cast Iron | 002140 | 3303L | 002140 | Inst 6894F 2P Bertha-Wellston 1A | 201509 | (19,587.67) | 7 | 0.0027583 | (378.20) | (648.34) |
| 376200-Mains - Cast Iron | 699220 | 3301L | 699220 | 69922 MAIN PLS INST MTCE | 201510 | (1,493.11) | 6 | 0.0027583 | (24.71) | (49.42) |
| 376200-Mains - Cast Iron | 900274 | 3303L | 900274 | Repl w/ 3390F 2P Wellington Ph 4D | 201509 | (552.11) | 7 | 0.0027583 | (10.66) | (18.27) |
| 376200-Mains - Cast Iron | 900458 | 3303L | 900458 | Repl w/ 2796F 2P Wellington Grd Ph4 | 201511 | (127,878.66) | 5 | 0.0027583 | (1,763.64) | (4,232.73) |
| 376200-Mains - Cast Iron | 900558 | 3303L | 900558 | Inst 5130F 2P Walnut Park Ph 5F | 201510 | (10,540.87) | 6 | 0.0027583 | (174.45) | (348.90) |
| 376200-Mains - Cast Iron | 900558 | 3303L | 900568 | Inst 1859F 2P Walnut Park Ph6B | 201510 | (7,532.69) | 6 | 0.0027583 | (124.66) | (249.33) |
| 376200-Mains - Cast Iron | 900607 | 3303L | 900608 | Inst 3183F 2P Maplewood Ph2C | 201511 | (38,174.47) | 5 | 0.0027583 | (526.48) | (1,263.56) |
| 376200-Mains - Cast Iron | 900650 | 3303L | 900650 | Inst 3290F 2P St Louis Hills Ph1A | 201509 | (8,854.37) | 7 | 0.0027583 | (170.96) | (293.08) |
| 376200-Mains - Cast Iron | 900691 | 3303L | 900691 | Repl w/ 3458F 2P Cole & 18th Ph H | 201512 | (12,082.24) | 4 | 0.0027583 | (133.31) | (399.92) |
| 376200-Mains - Cast Iron | 900763 | 3303L | 900763 | Inst 3508F 2P Earthquake Zone Ph1B | 201509 | (20,208.83) | 7 | 0.0027583 | (390.19) | (868.90) |
| 376200-Mains - Cast Iron | 901114 | 3303L | 901114 | Repl w/ 1630F 2P Maffitt | 201512 | (1,366.11) | 4 | 0.0027583 | (15.07) | (45.22) |
| 376200-Mains - Cast Iron | 901139 | 3303L | 901139 | Repl w/ 901F 2P Suburban Ave | 201510 | (6,054.28) | 6 | 0.0027583 | (100.20) | (200.39) |
| 376200-Mains - Cast Iron | 901220 | 3303L | 901220 | Aband 511F 4C Marcus AOR | 201512 | (694.67) | 4 | 0.0027583 | (7.66) | (22.99) |

TOTAL - MAINS - CAST IRON - RETIREMENTS - MAIN REPLACEMENTS

(255,020.08)

(3,820.19)

(8,441.05)

MAINS - STEEL - RETIREMENTS - MAIN REPLACEMENTS

| PLANT ACCOUNT | WORK ORDER | BUDGET PROJECT | RELATED CWO | DESCRIPTION | RETIREMENT DATE | RETIREMENT AMOUNT | MONTHS | DEPR. MO. RATE | ACCUM. DEPR. | DEPR. EXPENSE |
|----------------------|------------|----------------|-------------|--------------------------------|-----------------|-------------------|--------|----------------|--------------|---------------|
| 376100-Mains - Steel | 002434 | 3303M | 002434 | Deer Run main replacement | 201509 | (2,715.33) | 7 | 0.0012000 | (22.81) | (39.10) |
| 376100-Mains - Steel | 005312 | 3602L | 005312 | Rtr Reg Stn - Rosalie & Shreve | 201511 | (1,431.37) | 5 | 0.0012000 | (8.59) | (20.61) |
| 376100-Mains - Steel | 699220 | 3301L | 699220 | 69922 MAIN PLS INST MTCE | 201509 | (1,777.44) | 7 | 0.0012000 | (14.93) | (25.60) |
| 376100-Mains - Steel | 699500 | 3301L | 699500 | 69950 MAIN STL INST MTCE | 201509 | (285.99) | 7 | 0.0012000 | (2.40) | (4.12) |
| 376100-Mains - Steel | 699720 | 3301L | 699720 | 69972 MAIN PLS INST MTCE | 201509 | (400.02) | 7 | 0.0012000 | (3.36) | (5.76) |
| 376100-Mains - Steel | 699720 | 3303L | 699720 | 69972 MAIN PLS INST MTCE | 201511 | (21.05) | 5 | 0.0012000 | (0.13) | (0.30) |

| | | | | | | | | | | |
|----------------------|--------|-------|--------|-------------------------------------|--------|-------------|---|-----------|----------|----------|
| 376100-Mains - Steel | 900458 | 3303L | 900458 | Repl w/ 2796F 2P Wellington Grd Ph4 | 201511 | (19,466.06) | 5 | 0.0012000 | (116.80) | (280.31) |
| 376100-Mains - Steel | 900558 | 3303L | 900568 | Inst 1859F 2P Walnut Park Ph6B | 201510 | (34.99) | 6 | 0.0012000 | (0.25) | (0.50) |
| 376100-Mains - Steel | 900607 | 3303L | 900608 | Inst 3183F 2P Maplewood Ph2C | 201511 | (19,757.82) | 5 | 0.0012000 | (118.55) | (264.51) |
| 376100-Mains - Steel | 900691 | 3303L | 900691 | Repl w/ 3458F 2P Cole & 18th Ph H | 201512 | (38,449.90) | 4 | 0.0012000 | (184.56) | (553.69) |
| 376100-Mains - Steel | 900763 | 3303L | 900763 | Inst 3508F 2P Earthquake Zone Ph1B | 201509 | (6,329.05) | 7 | 0.0012000 | (53.16) | (91.14) |
| 376100-Mains - Steel | 900873 | 3303L | 900873 | Repl w/ 538F 2P Longacre | 201510 | (225.58) | 6 | 0.0012000 | (1.62) | (3.25) |
| 376100-Mains - Steel | 900876 | 3303L | 900876 | Repl w/ 1060F 2P Rauschenbach PVC | 201509 | (210.66) | 7 | 0.0012000 | (1.77) | (3.04) |
| 376100-Mains - Steel | 901114 | 3303L | 901114 | Repl w/ 1630F 2P Maffitt | 201512 | (773.46) | 4 | 0.0012000 | (3.71) | (11.14) |
| 376100-Mains - Steel | 901139 | 3303L | 901139 | Repl w/ 901F 2P Suburban Ave | 201510 | (928.35) | 6 | 0.0012000 | (6.68) | (13.37) |
| 376100-Mains - Steel | 901178 | 3303L | 901178 | Repl w/ 185F 2P Evans | 201511 | (316.68) | 5 | 0.0012000 | (1.90) | (4.56) |

TOTAL MAINS - STEEL - RETIREMENTS - MAIN REPLACEMENTS

(93,123.95) (541.22) (1,340.99)

Distribution Plant - Mains - Replacement

| PLANT ACCOUNT | WORK ORDER | BUDGET PROJECT | DESCRIPTION | IN SERVICE DATE | ADDITION AMOUNT | MONTHS | DEPR. MO. RATE | ACCUM. DEPR. | DEPR. EXPENSE |
|---------------|------------|----------------|-------------|-----------------|-----------------|--------|----------------|--------------|---------------|
|---------------|------------|----------------|-------------|-----------------|-----------------|--------|----------------|--------------|---------------|

Total Distribution Plant - Mains - Replacement

- - -

TOTAL MAIN RETIREMENTS - MAIN REPLACEMENTS

(483,454.27) (5,384.40) (11,906.35)

RETIREMENT OF SERVICES

ACCOUNT 38010 SERVICES STEEL

| PLANT ACCOUNT | WORK ORDER | BUDGET PROJECT | DESCRIPTION | RETIREMENT DATE | RETIREMENT AMOUNT | MONTHS | DEPR. MO. RATE | ACCUM. DEPR. | DEPR. EXPENSE |
|-------------------------|------------|----------------|--------------------------|-----------------|-------------------|--------|----------------|--------------|---------------|
| 380100-Services - Steel | 597170 | | 59717 SVC RNW CP/PL MNAT | 201512 | (180.24) | 4 | 0.0043583 | (3.14) | (9.43) |
| 380100-Services - Steel | 695160 | | 69516 SVC RENEW STEEL SO | 201509 | (7,146.38) | 7 | 0.0043583 | (218.02) | (373.75) |
| 380100-Services - Steel | 695160 | | 69516 SVC RENEW STEEL SO | 201510 | (5,292.96) | 6 | 0.0043583 | (138.41) | (276.82) |
| 380100-Services - Steel | 695160 | | 69516 SVC RENEW STEEL SO | 201511 | (34.79) | 5 | 0.0043583 | (0.76) | (1.82) |
| 380100-Services - Steel | 695160 | | 69516 SVC RENEW STEEL SO | 201512 | (241.91) | 4 | 0.0043583 | (4.22) | (12.65) |
| 380100-Services - Steel | 695300 | | 69530 SVC REN 1/2 PL SO | 201509 | (1,152.63) | 7 | 0.0043583 | (35.16) | (60.28) |
| 380100-Services - Steel | 695300 | | 69530 SVC REN 1/2 PL SO | 201510 | (7,836.78) | 6 | 0.0043583 | (204.93) | (409.86) |
| 380100-Services - Steel | 695300 | | 69530 SVC REN 1/2 PL SO | 201511 | (5,549.88) | 5 | 0.0043583 | (120.94) | (290.26) |
| 380100-Services - Steel | 695300 | | 69530 SVC REN 1/2 PL SO | 201512 | (3,630.24) | 4 | 0.0043583 | (63.29) | (189.86) |
| 380100-Services - Steel | 695310 | | 69531 SV REN 1IN PL SO | 201509 | (839.20) | 7 | 0.0043583 | (25.60) | (43.89) |
| 380100-Services - Steel | 695310 | | 69531 SV REN 1IN PL SO | 201510 | (982.68) | 6 | 0.0043583 | (25.70) | (51.39) |
| 380100-Services - Steel | 695310 | | 69531 SV REN 1IN PL SO | 201511 | (1,295.47) | 5 | 0.0043583 | (28.23) | (67.75) |
| 380100-Services - Steel | 695310 | | 69531 SV REN 1IN PL SO | 201512 | (174.31) | 4 | 0.0043583 | (3.04) | (9.12) |
| 380100-Services - Steel | 695320 | | 69532 SV REN 1 1/4 PL SO | 201509 | (1,181.57) | 7 | 0.0043583 | (36.05) | (61.80) |
| 380100-Services - Steel | 695320 | | 69532 SV REN 1 1/4 PL SO | 201510 | (364.66) | 6 | 0.0043583 | (9.54) | (19.07) |
| 380100-Services - Steel | 695330 | | 69533 SV REN 2&OVR PL SO | 201510 | (134.12) | 6 | 0.0043583 | (3.51) | (7.01) |
| 380100-Services - Steel | 695800 | | 69580 SVC REN 1/2 PL NO | 201511 | (199.83) | 5 | 0.0043583 | (4.35) | (10.45) |
| 380100-Services - Steel | 695810 | | 69581 SV REN 1IN PL NO | 201510 | (123.83) | 6 | 0.0043583 | (3.24) | (6.48) |
| 380100-Services - Steel | 695810 | | 69581 SV REN 1IN PL NO | 201511 | (19.87) | 5 | 0.0043583 | (0.43) | (1.04) |
| 380100-Services - Steel | 695810 | | 69581 SV REN 1IN PL NO | 201512 | (156.90) | 4 | 0.0043583 | (2.74) | (8.21) |
| 380100-Services - Steel | 695820 | | 69582 SV REN 1 1/4 PL NO | 201510 | (1,852.38) | 6 | 0.0043583 | (48.44) | (96.88) |
| 380100-Services - Steel | 698300 | | 69830 SVC RENEW STEEL SC | 201510 | (5,558.46) | 6 | 0.0043583 | (145.35) | (290.71) |
| 380100-Services - Steel | 698450 | | 69845 SVC RNW 1/2 PL SC | 201509 | (64.55) | 7 | 0.0043583 | (1.97) | (3.38) |
| 380100-Services - Steel | 698450 | | 69845 SVC RNW 1/2 PL SC | 201510 | (349.68) | 6 | 0.0043583 | (9.14) | (18.29) |

| | | | | | | | | | |
|------------------------------------|--------|--|-------------------------------------|--------|--------------|---|-----------|------------|------------|
| 380200-Services - Plastic & Copper | 695810 | | 69581 SV REN 1IN PL NO | 201510 | (9,404.11) | 6 | 0.0031250 | (176.33) | (352.65) |
| 380200-Services - Plastic & Copper | 695810 | | 69581 SV REN 1IN PL NO | 201511 | (2,649.00) | 5 | 0.0031250 | (41.39) | (99.34) |
| 380200-Services - Plastic & Copper | 695810 | | 69581 SV REN 1IN PL NO | 201512 | (33.30) | 4 | 0.0031250 | (0.42) | (1.25) |
| 380200-Services - Plastic & Copper | 695820 | | 69582 SV REN 1 1/4 PL NO | 201509 | (8,978.06) | 7 | 0.0031250 | (196.40) | (336.68) |
| 380200-Services - Plastic & Copper | 695820 | | 69582 SV REN 1 1/4 PL NO | 201510 | (12,026.86) | 6 | 0.0031250 | (225.50) | (451.01) |
| 380200-Services - Plastic & Copper | 695830 | | 69583 SV REN 2&OVR PL NO | 201512 | (322.88) | 4 | 0.0031250 | (4.04) | (12.11) |
| 380200-Services - Plastic & Copper | 695840 | | 69584 RNW COPPER SVCS-NORTH | 201511 | (88.25) | 5 | 0.0031250 | (1.38) | (3.31) |
| 380200-Services - Plastic & Copper | 698450 | | 69845 SVC RNW 1/2 PL SC | 201509 | (744.99) | 7 | 0.0031250 | (16.30) | (27.94) |
| 380200-Services - Plastic & Copper | 698450 | | 69845 SVC RNW 1/2 PL SC | 201510 | (4,370.73) | 6 | 0.0031250 | (81.95) | (163.90) |
| 380200-Services - Plastic & Copper | 698450 | | 69845 SVC RNW 1/2 PL SC | 201511 | (3,994.72) | 5 | 0.0031250 | (62.42) | (149.80) |
| 380200-Services - Plastic & Copper | 698450 | | 69845 SVC RNW 1/2 PL SC | 201512 | (3,643.58) | 4 | 0.0031250 | (45.54) | (136.63) |
| 380200-Services - Plastic & Copper | 698460 | | 69846 SVC RNW 1IN PL SC | 201510 | (2,179.82) | 6 | 0.0031250 | (40.87) | (81.74) |
| 380200-Services - Plastic & Copper | 698460 | | 69846 SVC RNW 1IN PL SC | 201512 | (65.13) | 4 | 0.0031250 | (0.81) | (2.44) |
| 380200-Services - Plastic & Copper | 698470 | | 69847 SV RNW 1-1/4 PL SC | 201509 | (1,334.94) | 7 | 0.0031250 | (29.20) | (50.06) |
| 380200-Services - Plastic & Copper | 698470 | | 69847 SV RNW 1-1/4 PL SC | 201510 | (150.52) | 6 | 0.0031250 | (2.82) | (5.64) |
| 380200-Services - Plastic & Copper | 699160 | | 69916 SVC RENEW STEEL C | 201510 | (90.13) | 6 | 0.0031250 | (1.69) | (3.38) |
| 380200-Services - Plastic & Copper | 699160 | | 69916 SVC RENEW STEEL C | 201511 | (432.75) | 5 | 0.0031250 | (6.76) | (16.23) |
| 380200-Services - Plastic & Copper | 699160 | | 69916 SVC RENEW STEEL C | 201512 | (591.17) | 4 | 0.0031250 | (7.39) | (22.17) |
| 380200-Services - Plastic & Copper | 699300 | | 69930 SVC REN 1/2 PL CTY | 201509 | (8,996.86) | 7 | 0.0031250 | (196.81) | (337.38) |
| 380200-Services - Plastic & Copper | 699300 | | 69930 SVC REN 1/2 PL CTY | 201510 | (15,766.20) | 6 | 0.0031250 | (295.62) | (591.23) |
| 380200-Services - Plastic & Copper | 699300 | | 69930 SVC REN 1/2 PL CTY | 201511 | (26,940.39) | 5 | 0.0031250 | (420.94) | (1,010.26) |
| 380200-Services - Plastic & Copper | 699300 | | 69930 SVC REN 1/2 PL CTY | 201512 | (3,700.06) | 4 | 0.0031250 | (46.25) | (138.75) |
| 380200-Services - Plastic & Copper | 699310 | | 69931 SVC REN 1IN PL CTY | 201509 | (18,184.83) | 7 | 0.0031250 | (397.79) | (681.93) |
| 380200-Services - Plastic & Copper | 699310 | | 69931 SVC REN 1IN PL CTY | 201510 | (10,851.53) | 6 | 0.0031250 | (203.47) | (406.93) |
| 380200-Services - Plastic & Copper | 699310 | | 69931 SVC REN 1IN PL CTY | 201511 | (4,521.13) | 5 | 0.0031250 | (70.64) | (169.54) |
| 380200-Services - Plastic & Copper | 699310 | | 69931 SVC REN 1IN PL CTY | 201512 | (18,427.94) | 4 | 0.0031250 | (230.35) | (691.05) |
| 380200-Services - Plastic & Copper | 699320 | | 69932 SVC REN 1 1/4 PL C | 201509 | (678.74) | 7 | 0.0031250 | (14.85) | (25.45) |
| 380200-Services - Plastic & Copper | 699330 | | 69933 SVC REN 2&OVR PL C | 201509 | (10,364.67) | 7 | 0.0031250 | (226.73) | (388.68) |
| 380200-Services - Plastic & Copper | 699330 | | 69933 SVC REN 2&OVR PL C | 201512 | (760.55) | 4 | 0.0031250 | (9.51) | (28.52) |
| 380200-Services - Plastic & Copper | 900274 | | Repl w/ 3390F 2P Wellington Ph 4D | 201509 | (41,876.83) | 7 | 0.0031250 | (916.06) | (1,570.38) |
| 380200-Services - Plastic & Copper | 900458 | | Repl w/ 2796F 2P Wellington Grd Ph4 | 201511 | (60,832.08) | 5 | 0.0031250 | (950.50) | (2,281.20) |
| 380200-Services - Plastic & Copper | 900556 | | Inst 5130F 2P Walnut Park Ph 5F | 201510 | (190,662.15) | 6 | 0.0031250 | (3,574.92) | (7,149.83) |
| 380200-Services - Plastic & Copper | 900558 | | Inst 1859F 2P Walnut Park Ph6B | 201510 | (79,736.21) | 6 | 0.0031250 | (1,495.05) | (2,990.11) |
| 380200-Services - Plastic & Copper | 900607 | | Inst 3183F 2P Maplewood Ph2C | 201511 | (29,553.61) | 5 | 0.0031250 | (461.78) | (1,106.26) |
| 380200-Services - Plastic & Copper | 900650 | | Inst 3290F 2P St Louis Hills Ph1A | 201509 | (188,119.56) | 7 | 0.0031250 | (4,115.12) | (7,054.48) |
| 380200-Services - Plastic & Copper | 900691 | | Repl w/ 3458F 2P Cole & 18th Ph H | 201512 | (3,767.11) | 4 | 0.0031250 | (47.09) | (141.27) |
| 380200-Services - Plastic & Copper | 900763 | | Inst 3508F 2P Earthquake Zone Ph1B | 201509 | (49,511.81) | 7 | 0.0031250 | (1,083.07) | (1,856.69) |
| 380200-Services - Plastic & Copper | 900873 | | Repl w/ 538F 2P Longacre | 201510 | (1,296.03) | 6 | 0.0031250 | (24.30) | (48.60) |
| 380200-Services - Plastic & Copper | 900876 | | Repl w/ 1060F 2P Rauschenbach PVC | 201509 | (3,750.87) | 7 | 0.0031250 | (82.05) | (140.66) |
| 380200-Services - Plastic & Copper | 900885 | | Rel w/ 293F 2S Spellman Ph2 | 201510 | (377.59) | 6 | 0.0031250 | (7.08) | (14.16) |
| 380200-Services - Plastic & Copper | 900973 | | Rel w/ 28F 2S Terrie Ln | 201511 | (1,161.94) | 5 | 0.0031250 | (18.16) | (43.57) |
| 380200-Services - Plastic & Copper | 901063 | | Rel w/ 1307F 4P Bessie AOR | 201511 | (76,861.26) | 5 | 0.0031250 | (1,200.96) | (2,882.30) |
| 380200-Services - Plastic & Copper | 901114 | | Repl w/ 1630F 2P Maffitt | 201512 | (83,095.76) | 4 | 0.0031250 | (1,038.70) | (3,116.09) |
| 380200-Services - Plastic & Copper | 901139 | | Repl w/ 901F 2P Suburban Ave | 201510 | (5,515.45) | 6 | 0.0031250 | (103.41) | (206.83) |
| 380200-Services - Plastic & Copper | 901178 | | Repl w/ 185F 2P Evans | 201511 | (501.07) | 5 | 0.0031250 | (7.83) | (18.79) |
| 380200-Services - Plastic & Copper | 901220 | | Aband 511F 4C Marcus AOR | 201512 | (573.84) | 4 | 0.0031250 | (7.17) | (21.52) |

TOTAL (1,125,841.80) (20,595.36) (42,219.03)

Distribution Plant - Services - Renewed

| PLANT ACCOUNT | WORK ORDER | BUDGET PROJECT | RELATED WORK ORDER | IN SERVICE DATE | ADDITION AMOUNT | MONTHS | DEPR. MO. RATE | ACCUM. DEPR. | DEPR. EXPENSE |
|---------------|------------|----------------|--------------------|-----------------|-----------------|--------|----------------|--------------|---------------|
|---------------|------------|----------------|--------------------|-----------------|-----------------|--------|----------------|--------------|---------------|

| | | | | | | | | | | |
|--------------------------|--------|-------|--------|----------------------------|--------|------------|---|-----------|----------|----------|
| 376200-Mains - Cast Iron | 001337 | 3403L | 001337 | Inst 622F 2P Shenendoah | 201509 | (2,674.01) | 7 | 0.0027583 | (51.63) | (88.51) |
| 376200-Mains - Cast Iron | 901063 | 3403L | 901063 | Rel w/ 1307F 4P Bessie AOR | 201511 | (8,472.00) | 5 | 0.0027583 | (116.84) | (280.42) |
| | | | | | | | | | | |

TOTAL MAINS - CAST IRON - RETIREMENTS - MAIN RELOCATIONS

TOTAL (11,146.01) (168.47) (368.93)

MAINS - STEEL - RETIREMENTS - MAIN RELOCATIONS

| PLANT ACCOUNT | WORK ORDER | BUDGET PROJECT | RELATED CWO | DESCRIPTION | RETIREMENT DATE | RETIREMENT AMOUNT | MONTHS | DEPR. MO. RATE | ACCUM. DEPR. | DEPR. EXPENSE |
|----------------------|------------|----------------|-------------|------------------------------------|-----------------|-------------------|--------|----------------|--------------|---------------|
| 376100-Mains - Steel | 001494 | 3403M | 001494 | Relocate along Oak Grove (Phase 2) | 201509 | (8,037.51) | 7 | 0.0012000 | (67.52) | (115.74) |
| 376100-Mains - Steel | 002882 | 3403M | 002882 | FE - American Legion & S Mill St | 201509 | (18.60) | 7 | 0.0012000 | (0.16) | (0.27) |
| 376100-Mains - Steel | 900732 | 3403L | 900732 | Rel w/ 120F 6S DeBaliviere Bridge | 201509 | (60,239.36) | 7 | 0.0012000 | (506.01) | (867.45) |
| 376100-Mains - Steel | 900868 | 3403L | 900868 | Rel w/ 210F 2P Vance -Vailey Park | 201510 | (252.17) | 6 | 0.0012000 | (1.82) | (3.63) |
| 376100-Mains - Steel | 900885 | 3403L | 900885 | Rel w/ 293F 2S Spellman Ph2 | 201510 | (2,779.84) | 6 | 0.0012000 | (20.01) | (40.03) |
| 376100-Mains - Steel | 900967 | 3403L | 900967 | Rel w/ 200F 2P Fawnvalley Bridge | 201510 | (594.79) | 6 | 0.0012000 | (4.28) | (8.56) |
| 376100-Mains - Steel | 900973 | 3403L | 900973 | Rel w/ 28F 2S Terrie Ln | 201511 | (537.55) | 5 | 0.0012000 | (3.23) | (7.74) |

TOTAL MAINS - STEEL - RETIREMENTS - MAIN RELOCATIONS

TOTAL (72,459.82) (603.03) (1,043.42)

Distribution Plant - Mains - Relocation

| | | | | | | | | | | |
|--|--|------|--|---|--------|--|--|--|---|---|
| | | BP34 | | Distribution Plant - Mains - Relocation | 201407 | | | | - | - |
| | | BP34 | | Distribution Plant - Mains - Relocation | 201408 | | | | - | - |

Total Distribution Plant - Mains - Relocation

TOTAL - - -

TOTAL MAIN RETIREMENTS - MAIN RELOCATIONS

(113,769.71) (1,010.74) (1,885.91)

TOTAL RETIREMENTS - ISRS ELIGIBLE PROPERTY

(1,940,989.35) (31,394.34) (65,830.42)

MAIN REPLACEMENTS - ADDITIONS

| PLANT ACCOUNT | WORK ORDER | BUDGET PROJECT | DESCRIPTION | IN SERVICE DATE | ADDITION AMOUNT | ISRS STATUTE | STATE OR FEDERAL SAFETY REQUIREMENT |
|------------------------|------------|----------------|------------------------------------|-----------------|-----------------|--------------|-------------------------------------|
| 376300-Mains - Plastic | 000569 | 3304L | 4015F 6P 2P Lemay Ferry | 201509 | (1.41) | a | A, B, C, K |
| 376300-Mains - Plastic | 001040 | 3303L | Install 46F 4P Nashville | 201509 | 0.24 | a | A, B, C, K |
| 376300-Mains - Plastic | 001330 | 3303L | Inst 9084F 2P Aberdeen PI | 201509 | (2,560.98) | a | A, B, C, K |
| 376300-Mains - Plastic | 001535 | 3303L | Repl w/ 9098F 2P Arlington | 201509 | (64.85) | a | A, B, C, K |
| 376300-Mains - Plastic | 001711 | 3303L | Inst 7023F 2P Northmoor Wydown Ph5 | 201509 | (3.95) | a | A, B, C, K |
| 376300-Mains - Plastic | 001712 | 3303L | Inst 16489F 2P Cote Brilliante | 201509 | 9,221.71 | a | A, B, C, K |
| 376300-Mains - Plastic | 001712 | 3303L | Inst 16489F 2P Cote Brilliante | 201510 | (31.23) | a | A, B, C, K |
| 376300-Mains - Plastic | 002137 | 3303L | Repl w/ 5955F 2P Boneta | 201509 | (945.64) | a | A, B, C, K |
| 376300-Mains - Plastic | 002138 | 3303L | Repl w/ 10203F 2P Manchester | 201509 | (2,642.34) | a | A, B, C, K |
| 376300-Mains - Plastic | 002139 | 3303L | Inst 3278F 2P MLK -Wellston 1B | 201509 | (5,826.13) | a | A, B, C, K |
| 376300-Mains - Plastic | 002139 | 3303L | Inst 3278F 2P MLK -Wellston 1B | 201510 | 904.98 | a | A, B, C, K |
| 376300-Mains - Plastic | 002139 | 3303L | Inst 3278F 2P MLK -Wellston 1B | 201511 | 1,800.80 | a | A, B, C, K |
| 376300-Mains - Plastic | 002139 | 3303L | Inst 3278F 2P MLK -Wellston 1B | 201512 | 259.07 | a | A, B, C, K |
| 376300-Mains - Plastic | 002140 | 3303L | Inst 6894F 2P Bertha-Wellston 1A | 201509 | (3,734.71) | a | A, B, C, K |
| 376300-Mains - Plastic | 002140 | 3303L | Inst 6894F 2P Bertha-Wellston 1A | 201510 | 3,703.14 | a | A, B, C, K |
| 376300-Mains - Plastic | 002141 | 3303L | Inst 6161F 2P Marshall-Well, Ph4C | 201509 | (0.90) | a | A, B, C, K |
| 376300-Mains - Plastic | 002434 | 3303M | Deer Run main replacement | 201509 | 1,157.63 | a | A, B, C, K |
| 376300-Mains - Plastic | 672850 | 3301L | 67285 590F 4P JAMES & SUTTON | 201509 | 21,540.46 | a | A, B, C, K |
| 376300-Mains - Plastic | 696000 | 3301M | 69600 MAIN VAR INST MTCE | 201509 | (1,040.93) | a | A, B, C, D, E, K |
| 376300-Mains - Plastic | 698000 | 3301L | 69800 MAIN VAR INST MTCE | 201509 | 1,345.76 | a | A, B, C, D, E, K |
| 376300-Mains - Plastic | 698000 | 3301L | 69800 MAIN VAR INST MTCE | 201510 | 1,852.53 | a | A, B, C, D, E, K |
| 376300-Mains - Plastic | 698000 | 3301L | 69800 MAIN VAR INST MTCE | 201511 | 100.79 | a | A, B, C, D, E, K |
| 376300-Mains - Plastic | 698000 | 3301L | 69800 MAIN VAR INST MTCE | 201512 | 1,954.95 | a | A, B, C, D, E, K |
| 376100-Mains - Steel | 699000 | 3301L | 69900 MAIN STL INST MTCE | 201509 | (32.75) | a | A, B, C, D, E, K |
| 376300-Mains - Plastic | 699220 | 3301L | 69922 MAIN PLS INST MTCE | 201509 | 111,071.44 | a | A, B, C, D, E, K |
| 376300-Mains - Plastic | 699220 | 3301L | 69922 MAIN PLS INST MTCE | 201510 | 46,027.60 | a | A, B, C, D, E, K |
| 376300-Mains - Plastic | 699220 | 3301L | 69922 MAIN PLS INST MTCE | 201511 | 10,719.41 | a | A, B, C, D, E, K |
| 376300-Mains - Plastic | 699220 | 3301L | 69922 MAIN PLS INST MTCE | 201512 | 7,439.66 | a | A, B, C, D, E, K |
| 376100-Mains - Steel | 699500 | 3301L | 69950 MAIN STL INST MTCE | 201509 | 2,081.35 | a | A, B, C, D, E, K |
| 376100-Mains - Steel | 699500 | 3301L | 69950 MAIN STL INST MTCE | 201510 | 1,475.86 | a | A, B, C, D, E, K |
| 376100-Mains - Steel | 699500 | 3301L | 69950 MAIN STL INST MTCE | 201511 | 39,587.15 | a | A, B, C, D, E, K |
| 376100-Mains - Steel | 699500 | 3301L | 69950 MAIN STL INST MTCE | 201512 | (721.14) | a | A, B, C, D, E, K |
| 376300-Mains - Plastic | 699720 | 3301L | 69972 MAIN PLS INST MTCE | 201509 | 12,161.30 | a | A, B, C, D, E, K |
| 376300-Mains - Plastic | 699720 | 3301L | 69972 MAIN PLS INST MTCE | 201510 | 95,590.12 | a | A, B, C, D, E, K |
| 376300-Mains - Plastic | 699720 | 3301L | 69972 MAIN PLS INST MTCE | 201511 | 43,287.57 | a | A, B, C, D, E, K |
| 376300-Mains - Plastic | 699720 | 3301L | 69972 MAIN PLS INST MTCE | 201512 | 100,205.95 | a | A, B, C, D, E, K |
| 376300-Mains - Plastic | 900068 | 3303L | Repl w/ 1750F 2P Jefferson Ph 2 | 201509 | (4,343.07) | a | A, B, C, K |
| 376300-Mains - Plastic | 900068 | 3303L | Repl w/ 1750F 2P Jefferson Ph 2 | 201509 | (102.69) | a | A, B, C, K |
| 376300-Mains - Plastic | 900069 | 3303L | Inst 3539F 2P Jefferson Ph 3 | 201509 | 17,838.94 | a | A, B, C, K |
| 376300-Mains - Plastic | 900069 | 3303L | Inst 3539F 2P Jefferson Ph 3 | 201509 | 575.06 | a | A, B, C, K |
| 376300-Mains - Plastic | 900069 | 3303L | Inst 3539F 2P Jefferson Ph 3 | 201510 | 1,179.13 | a | A, B, C, K |
| 376300-Mains - Plastic | 900069 | 3303L | Inst 3539F 2P Jefferson Ph 3 | 201510 | 38.01 | a | A, B, C, K |
| 376300-Mains - Plastic | 900069 | 3303L | Inst 3539F 2P Jefferson Ph 3 | 201511 | (41.72) | a | A, B, C, K |
| 376300-Mains - Plastic | 900069 | 3303L | Inst 3539F 2P Jefferson Ph 3 | 201511 | (1.34) | a | A, B, C, K |
| 376300-Mains - Plastic | 900069 | 3303L | Inst 3539F 2P Jefferson Ph 3 | 201512 | 59.61 | a | A, B, C, K |
| 376300-Mains - Plastic | 900069 | 3303L | Inst 3539F 2P Jefferson Ph 3 | 201512 | 1,848.91 | a | A, B, C, K |

| | | | | | | | |
|------------------------|--------|-------|-------------------------------------|--------|-------------|---|------------|
| 376100-Mains - Steel | 900071 | 3303L | Repl w/ 4240F 2-4P Jefferson Ph5 | 201511 | 13,103.35 | a | A, B, C, K |
| 376300-Mains - Plastic | 900071 | 3303L | Repl w/ 4240F 2-4P Jefferson Ph5 | 201511 | 900,252.52 | a | A, B, C, K |
| 376300-Mains - Plastic | 900071 | 3303L | Repl w/ 4240F 2-4P Jefferson Ph5 | 201511 | 62,981.36 | a | A, B, C, K |
| 376100-Mains - Steel | 900071 | 3303L | Repl w/ 4240F 2-4P Jefferson Ph5 | 201512 | 43.32 | a | A, B, C, K |
| 376300-Mains - Plastic | 900071 | 3303L | Repl w/ 4240F 2-4P Jefferson Ph5 | 201512 | 208.22 | a | A, B, C, K |
| 376300-Mains - Plastic | 900071 | 3303L | Repl w/ 4240F 2-4P Jefferson Ph5 | 201512 | 2,976.14 | a | A, B, C, K |
| 376300-Mains - Plastic | 900072 | 3303L | Repl w 688F 2P & 2527F 4P Lafayette | 201509 | (0.71) | a | A, B, C, K |
| 376300-Mains - Plastic | 900072 | 3303L | Repl w 688F 2P & 2527F 4P Lafayette | 201509 | (0.07) | a | A, B, C, K |
| 376300-Mains - Plastic | 900073 | 3303L | Repl w/ 2520F 2P Jefferson Ph 6 | 201509 | (13,672.40) | a | A, B, C, K |
| 376300-Mains - Plastic | 900073 | 3303L | Repl w/ 2520F 2P Jefferson Ph 6 | 201509 | 85,369.76 | a | A, B, C, K |
| 376300-Mains - Plastic | 900073 | 3303L | Repl w/ 2520F 2P Jefferson Ph 6 | 201509 | 1,089.22 | a | A, B, C, K |
| 376300-Mains - Plastic | 900073 | 3303L | Repl w/ 2520F 2P Jefferson Ph 6 | 201510 | 577.21 | a | A, B, C, K |
| 376300-Mains - Plastic | 900073 | 3303L | Repl w/ 2520F 2P Jefferson Ph 6 | 201510 | 19.92 | a | A, B, C, K |
| 376300-Mains - Plastic | 900093 | 3303L | Repl w/ 184F 2P Cass | 201509 | 0.09 | a | A, B, C, K |
| 376300-Mains - Plastic | 900093 | 3303L | Repl w/ 184F 2P Cass | 201509 | 0.01 | a | A, B, C, K |
| 376300-Mains - Plastic | 900169 | 3304L | Inst 6228F 8P Loughborough | 201509 | (0.58) | a | A, B, C, K |
| 376300-Mains - Plastic | 900169 | 3304L | Inst 6228F 8P Loughborough | 201509 | (0.01) | a | A, B, C, K |
| 376300-Mains - Plastic | 900170 | 3304L | Inst 3526F 6P Field & Koeln | 201509 | 0.24 | a | A, B, C, K |
| 376300-Mains - Plastic | 900170 | 3304L | Inst 3526F 6P Field & Koeln | 201509 | 0.01 | a | A, B, C, K |
| 376300-Mains - Plastic | 900262 | 3304L | Inst 7615F 12P Clifton Hill-Columbi | 201509 | (5,684.03) | a | A, B, C, K |
| 376300-Mains - Plastic | 900262 | 3304L | Inst 7615F 12P Clifton Hill-Columbi | 201509 | (659.50) | a | A, B, C, K |
| 376300-Mains - Plastic | 900264 | 3303L | Int 3087F 4P 2P Baden Grid Ph 5A | 201509 | 69.14 | a | A, B, C, K |
| 376300-Mains - Plastic | 900264 | 3303L | Int 3087F 4P 2P Baden Grid Ph 5A | 201509 | 4.36 | a | A, B, C, K |
| 376300-Mains - Plastic | 900265 | 3303L | Repl w/ 3337F 2P Baden Ph 5B | 201509 | 2.35 | a | A, B, C, K |
| 376300-Mains - Plastic | 900265 | 3303L | Repl w/ 3337F 2P Baden Ph 5B | 201509 | 0.11 | a | A, B, C, K |
| 376300-Mains - Plastic | 900266 | 3303L | Inst 4640F 2P Baden Ph 5C | 201509 | (1.37) | a | A, B, C, K |
| 376300-Mains - Plastic | 900266 | 3303L | Inst 4640F 2P Baden Ph 5C | 201509 | (0.01) | a | A, B, C, K |
| 376300-Mains - Plastic | 900266 | 3303L | Inst 4640F 2P Baden Ph 5C | 201510 | 6.69 | a | A, B, C, K |
| 376300-Mains - Plastic | 900266 | 3303L | Inst 4640F 2P Baden Ph 5C | 201510 | 0.16 | a | A, B, C, K |
| 376300-Mains - Plastic | 900266 | 3303L | Inst 4640F 2P Baden Ph 5C | 201511 | (0.43) | a | A, B, C, K |
| 376300-Mains - Plastic | 900266 | 3303L | Inst 4640F 2P Baden Ph 5C | 201511 | (0.01) | a | A, B, C, K |
| 376300-Mains - Plastic | 900266 | 3303L | Inst 4640F 2P Baden Ph 5C | 201512 | 0.83 | a | A, B, C, K |
| 376300-Mains - Plastic | 900266 | 3303L | Inst 4640F 2P Baden Ph 5C | 201512 | 31.28 | a | A, B, C, K |
| 376300-Mains - Plastic | 900267 | 3303L | Repl w/ 4536F 2P Baden Ph5D | 201509 | 3.79 | a | A, B, C, K |
| 376300-Mains - Plastic | 900267 | 3303L | Repl w/ 4536F 2P Baden Ph5D | 201509 | 0.18 | a | A, B, C, K |
| 376300-Mains - Plastic | 900268 | 3303L | Inst 4411F 2P Baden Ph5E | 201509 | 1.80 | a | A, B, C, K |
| 376300-Mains - Plastic | 900268 | 3303L | Inst 4411F 2P Baden Ph5E | 201509 | 0.17 | a | A, B, C, K |
| 376300-Mains - Plastic | 900269 | 3303L | Inst 1150F 4P Walnut Park Ph 5A | 201509 | (934.60) | a | A, B, C, K |
| 376300-Mains - Plastic | 900270 | 3303L | Inst 2942F 2P Walnut Park Ph5B | 201509 | (1,257.45) | a | A, B, C, K |
| 376300-Mains - Plastic | 900270 | 3303L | Inst 2942F 2P Walnut Park Ph5B | 201509 | (6.08) | a | A, B, C, K |
| 376300-Mains - Plastic | 900270 | 3303L | Inst 2942F 2P Walnut Park Ph5B | 201511 | (3,525.80) | a | A, B, C, K |
| 376300-Mains - Plastic | 900270 | 3303L | Inst 2942F 2P Walnut Park Ph5B | 201511 | 182.10 | a | A, B, C, K |
| 376300-Mains - Plastic | 900271 | 3303L | Inst 2646F 2P Walnut Park Ph5C | 201509 | (4,190.49) | a | A, B, C, K |
| 376300-Mains - Plastic | 900271 | 3303L | Inst 2646F 2P Walnut Park Ph5C | 201509 | (175.33) | a | A, B, C, K |
| 376300-Mains - Plastic | 900271 | 3303L | Inst 2646F 2P Walnut Park Ph5C | 201511 | (1,893.59) | a | A, B, C, K |
| 376300-Mains - Plastic | 900271 | 3303L | Inst 2646F 2P Walnut Park Ph5C | 201511 | (61.33) | a | A, B, C, K |
| 376300-Mains - Plastic | 900272 | 3303L | Inst 4170F 2P Walnut Park Ph 5D | 201509 | 220,111.88 | a | A, B, C, K |
| 376300-Mains - Plastic | 900272 | 3303L | Inst 4170F 2P Walnut Park Ph 5D | 201509 | 13,967.23 | a | A, B, C, K |
| 376300-Mains - Plastic | 900272 | 3303L | Inst 4170F 2P Walnut Park Ph 5D | 201511 | (19.02) | a | A, B, C, K |
| 376300-Mains - Plastic | 900272 | 3303L | Inst 4170F 2P Walnut Park Ph 5D | 201511 | (1.21) | a | A, B, C, K |
| 376300-Mains - Plastic | 900272 | 3303L | Inst 4170F 2P Walnut Park Ph 5D | 201512 | 0.01 | a | A, B, C, K |

| | | | | | | | |
|------------------------|--------|-------|-------------------------------------|--------|------------|---|------------|
| 376300-Mains - Plastic | 900272 | 3303L | Inst 4170F 2P Walnut Park Ph 5D | 201512 | 0.26 | a | A, B, C, K |
| 376300-Mains - Plastic | 900273 | 3303L | Repl w/ 4565F 2P Walnut Park Ph5E | 201510 | 179,255.41 | a | A, B, C, K |
| 376300-Mains - Plastic | 900273 | 3303L | Repl w/ 4565F 2P Walnut Park Ph5E | 201510 | 11,376.57 | a | A, B, C, K |
| 376300-Mains - Plastic | 900273 | 3303L | Repl w/ 4565F 2P Walnut Park Ph5E | 201511 | (142.08) | a | A, B, C, K |
| 376300-Mains - Plastic | 900273 | 3303L | Repl w/ 4565F 2P Walnut Park Ph5E | 201511 | (9.03) | a | A, B, C, K |
| 376300-Mains - Plastic | 900273 | 3303L | Repl w/ 4565F 2P Walnut Park Ph5E | 201512 | 3.98 | a | A, B, C, K |
| 376300-Mains - Plastic | 900273 | 3303L | Repl w/ 4565F 2P Walnut Park Ph5E | 201512 | 62.81 | a | A, B, C, K |
| 376300-Mains - Plastic | 900274 | 3303L | Repl w/ 3390F 2P Wellington Ph 4D | 201509 | (8,673.73) | a | A, B, C, K |
| 376300-Mains - Plastic | 900274 | 3303L | Repl w/ 3390F 2P Wellington Ph 4D | 201509 | (461.00) | a | A, B, C, K |
| 376300-Mains - Plastic | 900274 | 3303L | Repl w/ 3390F 2P Wellington Ph 4D | 201512 | (7,614.83) | a | A, B, C, K |
| 376300-Mains - Plastic | 900274 | 3303L | Repl w/ 3390F 2P Wellington Ph 4D | 201512 | (1,051.67) | a | A, B, C, K |
| 376300-Mains - Plastic | 900275 | 3303L | Repl w/ 4989F 2P Wellington Ph4E | 201509 | (5,743.64) | a | A, B, C, K |
| 376300-Mains - Plastic | 900275 | 3303L | Repl w/ 4989F 2P Wellington Ph4E | 201509 | (25.04) | a | A, B, C, K |
| 376300-Mains - Plastic | 900277 | 3303L | Repl w/ 1725F 2P Walnut Park Ph4B | 201509 | (43.04) | a | A, B, C, K |
| 376300-Mains - Plastic | 900277 | 3303L | Repl w/ 1725F 2P Walnut Park Ph4B | 201509 | (2.12) | a | A, B, C, K |
| 376300-Mains - Plastic | 900278 | 3303L | Repl w/ 3977F 2P Walnut Park Ph4C | 201509 | (77.43) | a | A, B, C, K |
| 376300-Mains - Plastic | 900278 | 3303L | Repl w/ 3977F 2P Walnut Park Ph4C | 201509 | (1.70) | a | A, B, C, K |
| 376300-Mains - Plastic | 900279 | 3303L | Repl w/ 3345F 2P Walnut Park Ph4D | 201509 | (1,520.17) | a | A, B, C, K |
| 376300-Mains - Plastic | 900279 | 3303L | Repl w/ 3345F 2P Walnut Park Ph4D | 201509 | (2.37) | a | A, B, C, K |
| 376300-Mains - Plastic | 900281 | 3303L | Inst 4984F 4PWellston Phase 2B | 201509 | (5.95) | a | A, B, C, K |
| 376300-Mains - Plastic | 900281 | 3303L | Inst 4984F 4PWellston Phase 2B | 201509 | (0.08) | a | A, B, C, K |
| 376300-Mains - Plastic | 900282 | 3303L | Inst 4400F 2P Wellston 2C | 201509 | (2,206.46) | a | A, B, C, K |
| 376300-Mains - Plastic | 900282 | 3303L | Inst 4400F 2P Wellston 2C | 201509 | (15.44) | a | A, B, C, K |
| 376300-Mains - Plastic | 900283 | 3303L | Inst 5300F 2P Wellston Ph2D | 201509 | 1.96 | a | A, B, C, K |
| 376300-Mains - Plastic | 900283 | 3303L | Inst 5300F 2P Wellston Ph2D | 201509 | 0.12 | a | A, B, C, K |
| 376300-Mains - Plastic | 900284 | 3303L | Inst 5466F 2P Wellston Ph2E | 201509 | (1,985.71) | a | A, B, C, K |
| 376300-Mains - Plastic | 900284 | 3303L | Inst 5466F 2P Wellston Ph2E | 201509 | (38.81) | a | A, B, C, K |
| 376300-Mains - Plastic | 900310 | 3303L | Inst 2250F 2P Yale Ave Maplewood 1C | 201511 | (85.11) | a | A, B, C, K |
| 376300-Mains - Plastic | 900375 | 3303L | Inst 1747F 6P Litzsinger | 201509 | 5.18 | a | A, B, C, K |
| 376300-Mains - Plastic | 900375 | 3303L | Inst 1747F 6P Litzsinger | 201509 | 0.06 | a | A, B, C, K |
| 376300-Mains - Plastic | 900377 | 3303L | Repl w/ 978F 2-4P Big Bend | 201509 | (780.84) | a | A, B, C, K |
| 376300-Mains - Plastic | 900377 | 3303L | Repl w/ 978F 2-4P Big Bend | 201509 | (9.65) | a | A, B, C, K |
| 376100-Mains - Steel | 900379 | 3303L | Inst 783F 4P & 529F 2POld Bonhomme | 201509 | (4.39) | a | A, B, C, K |
| 376300-Mains - Plastic | 900379 | 3303L | Inst 783F 4P & 529F 2POld Bonhomme | 201509 | (34.34) | a | A, B, C, K |
| 376300-Mains - Plastic | 900379 | 3303L | Inst 783F 4P & 529F 2POld Bonhomme | 201509 | (0.70) | a | A, B, C, K |
| 376300-Mains - Plastic | 900388 | 3303L | Repl w/ 332F 2P Tay Rd | 201509 | (5.15) | a | A, B, C, K |
| 376300-Mains - Plastic | 900390 | 3303L | Inst 205F 1 1/4P Gore | 201509 | (4.45) | a | A, B, C, K |
| 376300-Mains - Plastic | 900390 | 3303L | Inst 205F 1 1/4P Gore | 201509 | (0.08) | a | A, B, C, K |
| 376300-Mains - Plastic | 900392 | 3303L | Inst 580F 4P & 255F 2P Ferguson | 201509 | (2.54) | a | A, B, C, K |
| 376300-Mains - Plastic | 900392 | 3303L | Inst 580F 4P & 255F 2P Ferguson | 201509 | (0.05) | a | A, B, C, K |
| 376300-Mains - Plastic | 900393 | 3304L | Inst 3745F 8P Clayton Ave | 201509 | (1.72) | a | A, B, C, K |
| 376300-Mains - Plastic | 900393 | 3304L | Inst 3745F 8P Clayton Ave | 201509 | (0.09) | a | A, B, C, K |
| 376300-Mains - Plastic | 900395 | 3303L | Repl w/ 525F 2P Clay St | 201509 | (1.30) | a | A, B, C, K |
| 376300-Mains - Plastic | 900412 | 3303L | Repl w/ 412F 6P Holly Hills | 201509 | (123.62) | a | A, B, C, K |
| 376300-Mains - Plastic | 900412 | 3303L | Repl w/ 412F 6P Holly Hills | 201509 | (5.62) | a | A, B, C, K |
| 376300-Mains - Plastic | 900415 | 3303L | Repl w/ 1093F 2P Princeton | 201509 | (3.64) | a | A, B, C, K |
| 376300-Mains - Plastic | 900415 | 3303L | Repl w/ 1093F 2P Princeton | 201509 | (0.08) | a | A, B, C, K |
| 376300-Mains - Plastic | 900420 | 3303L | Repl w/ 520F 2P Oregon | 201509 | (7.28) | a | A, B, C, K |
| 376300-Mains - Plastic | 900420 | 3303L | Repl w/ 520F 2P Oregon | 201509 | (0.49) | a | A, B, C, K |
| 376300-Mains - Plastic | 900421 | 3303L | Repl w/ 970F 2P Winnebago | 201509 | (9.06) | a | A, B, C, K |
| 376300-Mains - Plastic | 900422 | 3303L | Repl w/ 780F 2P Taft | 201509 | (6.12) | a | A, B, C, K |
| 376300-Mains - Plastic | 900422 | 3303L | Repl w/ 780F 2P Taft | 201509 | (0.24) | a | A, B, C, K |
| 376300-Mains - Plastic | 900423 | 3303L | Repl w/ 1373F 2P Dr MLK | 201509 | (0.19) | a | A, B, C, K |

| | | | | | | | |
|------------------------|--------|-------|-------------------------------------|--------|-------------|---|------------|
| 376300-Mains - Plastic | 900423 | 3303L | Repl w/ 1373F 2P Dr MLK | 201509 | (0.02) | a | A, B, C, K |
| 376300-Mains - Plastic | 900424 | 3303L | Repl w/ 520F 3P Red Bud | 201509 | 4.52 | a | A, B, C, K |
| 376300-Mains - Plastic | 900424 | 3303L | Repl w/ 520F 3P Red Bud | 201509 | 0.72 | a | A, B, C, K |
| 376300-Mains - Plastic | 900430 | 3303L | Repl w/ 654F 2P Maurice | 201509 | (5.48) | a | A, B, C, K |
| 376300-Mains - Plastic | 900430 | 3303L | Repl w/ 654F 2P Maurice | 201509 | (0.41) | a | A, B, C, K |
| 376300-Mains - Plastic | 900432 | 3303L | Repl w/ 503F 2P Gravois | 201509 | (7.24) | a | A, B, C, K |
| 376300-Mains - Plastic | 900432 | 3303L | Repl w/ 503F 2P Gravois | 201509 | (0.17) | a | A, B, C, K |
| 376300-Mains - Plastic | 900433 | 3303L | Repl w/ 570F 4P Chippewa | 201509 | (9.50) | a | A, B, C, K |
| 376300-Mains - Plastic | 900433 | 3303L | Repl w/ 570F 4P Chippewa | 201509 | (0.47) | a | A, B, C, K |
| 376300-Mains - Plastic | 900439 | 3303L | Repl w/ 269F 2P Ferguson | 201509 | (3.99) | a | A, B, C, K |
| 376300-Mains - Plastic | 900439 | 3303L | Repl w/ 269F 2P Ferguson | 201509 | (0.13) | a | A, B, C, K |
| 376300-Mains - Plastic | 900456 | 3304L | Inst 8175F 8P Jamieson McCausland | 201509 | 2.80 | a | A, B, C, K |
| 376300-Mains - Plastic | 900456 | 3304L | Inst 8175F 8P Jamieson McCausland | 201509 | 0.13 | a | A, B, C, K |
| 376300-Mains - Plastic | 900457 | 3303L | Inst 4546F 2P Baden Ph5F | 201509 | (1.87) | a | A, B, C, K |
| 376300-Mains - Plastic | 900457 | 3303L | Inst 4546F 2P Baden Ph5F | 201509 | (0.09) | a | A, B, C, K |
| 376300-Mains - Plastic | 900458 | 3303L | Repl w/ 2796F 2P Wellington Grd Ph4 | 201509 | (58,082.40) | a | A, B, C, K |
| 376300-Mains - Plastic | 900458 | 3303L | Repl w/ 2796F 2P Wellington Grd Ph4 | 201509 | (571.95) | a | A, B, C, K |
| 376300-Mains - Plastic | 900458 | 3303L | Repl w/ 2796F 2P Wellington Grd Ph4 | 201511 | (3,690.24) | a | A, B, C, K |
| 376300-Mains - Plastic | 900458 | 3303L | Repl w/ 2796F 2P Wellington Grd Ph4 | 201511 | (36.33) | a | A, B, C, K |
| 376300-Mains - Plastic | 900460 | 3303L | Inst 3488F 2P Walnut Park Ph4E | 201509 | (4.12) | a | A, B, C, K |
| 376300-Mains - Plastic | 900460 | 3303L | Inst 3488F 2P Walnut Park Ph4E | 201509 | (0.23) | a | A, B, C, K |
| 376300-Mains - Plastic | 900461 | 3303L | Inst 893F 2P Walnut Park Ph4F | 201509 | (0.36) | a | A, B, C, K |
| 376300-Mains - Plastic | 900462 | 3303L | Repl w/ 2240F 2P Walnut Park Ph4G | 201509 | (509.22) | a | A, B, C, K |
| 376300-Mains - Plastic | 900462 | 3303L | Repl w/ 2240F 2P Walnut Park Ph4G | 201509 | (12.42) | a | A, B, C, K |
| 376300-Mains - Plastic | 900463 | 3303L | Inst 4082F 2P Walnut Park Ph4H | 201509 | (22.15) | a | A, B, C, K |
| 376300-Mains - Plastic | 900463 | 3303L | Inst 4082F 2P Walnut Park Ph4H | 201509 | (1.28) | a | A, B, C, K |
| 376300-Mains - Plastic | 900464 | 3303L | Inst 4741F 2P Walnut Park Ph 4I | 201509 | (447.33) | a | A, B, C, K |
| 376300-Mains - Plastic | 900464 | 3303L | Inst 4741F 2P Walnut Park Ph 4I | 201509 | (7.52) | a | A, B, C, K |
| 376300-Mains - Plastic | 900467 | 3303L | Repl w/ 2400F 2-4P Potomac AOR | 201509 | (0.22) | a | A, B, C, K |
| 376300-Mains - Plastic | 900467 | 3303L | Repl w/ 2400F 2-4P Potomac AOR | 201509 | (0.01) | a | A, B, C, K |
| 376100-Mains - Steel | 900474 | 3304L | Repl w/ 3774F 8P 8S Mullanphy | 201509 | 10.38 | a | A, B, C, K |
| 376300-Mains - Plastic | 900474 | 3304L | Repl w/ 3774F 8P 8S Mullanphy | 201509 | 31.57 | a | A, B, C, K |
| 376300-Mains - Plastic | 900474 | 3304L | Repl w/ 3774F 8P 8S Mullanphy | 201509 | 1.31 | a | A, B, C, K |
| 376300-Mains - Plastic | 900475 | 3304L | Inst 1895F 6P Koeln | 201509 | (10,229.73) | a | A, B, C, K |
| 376300-Mains - Plastic | 900475 | 3304L | Inst 1895F 6P Koeln | 201509 | (386.96) | a | A, B, C, K |
| 376300-Mains - Plastic | 900476 | 3304L | Inst 3350F 6P Ivory | 201509 | (11,473.52) | a | A, B, C, K |
| 376300-Mains - Plastic | 900476 | 3304L | Inst 3350F 6P Ivory | 201509 | (1,118.62) | a | A, B, C, K |
| 376300-Mains - Plastic | 900476 | 3304L | Inst 3350F 6P Ivory | 201511 | 480.45 | a | A, B, C, K |
| 376300-Mains - Plastic | 900476 | 3304L | Inst 3350F 6P Ivory | 201511 | (586.91) | a | A, B, C, K |
| 376300-Mains - Plastic | 900476 | 3304L | Inst 3350F 6P Ivory | 201512 | (18.06) | a | A, B, C, K |
| 376300-Mains - Plastic | 900476 | 3304L | Inst 3350F 6P Ivory | 201512 | (3.62) | a | A, B, C, K |
| 376100-Mains - Steel | 900479 | 3304L | Inst 3525F 8P Union | 201509 | (239.24) | a | A, B, C, K |
| 376300-Mains - Plastic | 900479 | 3304L | Inst 3525F 8P Union | 201509 | (8,296.61) | a | A, B, C, K |
| 376300-Mains - Plastic | 900479 | 3304L | Inst 3525F 8P Union | 201509 | (532.73) | a | A, B, C, K |
| 376100-Mains - Steel | 900479 | 3304L | Inst 3525F 8P Union | 201511 | (14,911.61) | a | A, B, C, K |
| 376300-Mains - Plastic | 900479 | 3304L | Inst 3525F 8P Union | 201511 | 27,392.31 | a | A, B, C, K |
| 376300-Mains - Plastic | 900479 | 3304L | Inst 3525F 8P Union | 201511 | (12,480.70) | a | A, B, C, K |
| 376300-Mains - Plastic | 900480 | 3304L | Inst 4528 8P Minerva | 201509 | (38.45) | a | A, B, C, K |
| 376300-Mains - Plastic | 900480 | 3304L | Inst 4528 8P Minerva | 201509 | (1.05) | a | A, B, C, K |
| 376300-Mains - Plastic | 900481 | 3304L | Inst 3125F 8P Union | 201509 | (9.78) | a | A, B, C, K |
| 376300-Mains - Plastic | 900481 | 3304L | Inst 3125F 8P Union | 201509 | (0.69) | a | A, B, C, K |
| 376300-Mains - Plastic | 900484 | 3304L | Inst 5203F 12P Ivanhoe | 201509 | (4,301.07) | a | A, B, C, K |
| 376300-Mains - Plastic | 900484 | 3304L | Inst 5203F 12P Ivanhoe | 201509 | (678.02) | a | A, B, C, K |
| 376100-Mains - Steel | 900485 | 3304L | Inst 4236F 12P Alaska | 201509 | (0.24) | a | A, B, C, K |

| | | | | | | | |
|------------------------|--------|-------|---------------------------------|--------|-------------|---|------------|
| 376300-Mains - Plastic | 900485 | 3304L | Inst 4236F 12P Alaska | 201509 | (34.47) | a | A, B, C, K |
| 376300-Mains - Plastic | 900485 | 3304L | Inst 4236F 12P Alaska | 201509 | (0.61) | a | A, B, C, K |
| 376300-Mains - Plastic | 900486 | 3304L | Inst 6210F 8P Jamieson | 201509 | (0.56) | a | A, B, C, K |
| 376300-Mains - Plastic | 900486 | 3304L | Inst 6210F 8P Jamieson | 201509 | (0.03) | a | A, B, C, K |
| 376300-Mains - Plastic | 900487 | 3304L | Inst 4845F 8P Loughborough | 201509 | (11,894.55) | a | A, B, C, K |
| 376300-Mains - Plastic | 900487 | 3304L | Inst 4845F 8P Loughborough | 201509 | 9,963.32 | a | A, B, C, K |
| 376300-Mains - Plastic | 900488 | 3304L | Repl w/ 2873F 6P Hodiament | 201509 | 93.52 | a | A, B, C, K |
| 376300-Mains - Plastic | 900488 | 3304L | Repl w/ 2873F 6P Hodiament | 201509 | 7.93 | a | A, B, C, K |
| 376300-Mains - Plastic | 900520 | 3303L | Repl w/ 6590F 2P Maplewood Ph1C | 201509 | 56,967.70 | a | A, B, C, K |
| 376300-Mains - Plastic | 900520 | 3303L | Repl w/ 6590F 2P Maplewood Ph1C | 201509 | 1,032.48 | a | A, B, C, K |
| 376300-Mains - Plastic | 900520 | 3303L | Repl w/ 6590F 2P Maplewood Ph1C | 201510 | 496.20 | a | A, B, C, K |
| 376300-Mains - Plastic | 900520 | 3303L | Repl w/ 6590F 2P Maplewood Ph1C | 201510 | 9.01 | a | A, B, C, K |
| 376300-Mains - Plastic | 900520 | 3303L | Repl w/ 6590F 2P Maplewood Ph1C | 201511 | (1,103.95) | a | A, B, C, K |
| 376300-Mains - Plastic | 900520 | 3303L | Repl w/ 6590F 2P Maplewood Ph1C | 201511 | (20.00) | a | A, B, C, K |
| 376300-Mains - Plastic | 900520 | 3303L | Repl w/ 6590F 2P Maplewood Ph1C | 201512 | 55.91 | a | A, B, C, K |
| 376300-Mains - Plastic | 900520 | 3303L | Repl w/ 6590F 2P Maplewood Ph1C | 201512 | 3,084.21 | a | A, B, C, K |
| 376300-Mains - Plastic | 900523 | 3303L | Repl w/ 5304F 2P Maplewood Ph1D | 201512 | 5,348.03 | a | A, B, C, K |
| 376300-Mains - Plastic | 900523 | 3303L | Repl w/ 5304F 2P Maplewood Ph1D | 201512 | 510,114.64 | a | A, B, C, K |
| 376300-Mains - Plastic | 900546 | 3303L | Inst 5691F 2P Wellston Ph2F | 201512 | 24,704.27 | a | A, B, C, K |
| 376300-Mains - Plastic | 900546 | 3303L | Inst 5691F 2P Wellston Ph2F | 201512 | 331,690.96 | a | A, B, C, K |
| 376300-Mains - Plastic | 900548 | 3303L | Inst 6712F 2P Wellston Ph2H | 201511 | 311,357.07 | a | A, B, C, K |
| 376300-Mains - Plastic | 900548 | 3303L | Inst 6712F 2P Wellston Ph2H | 201511 | 7,800.93 | a | A, B, C, K |
| 376300-Mains - Plastic | 900548 | 3303L | Inst 6712F 2P Wellston Ph2H | 201512 | 210.01 | a | A, B, C, K |
| 376300-Mains - Plastic | 900548 | 3303L | Inst 6712F 2P Wellston Ph2H | 201512 | 8,381.89 | a | A, B, C, K |
| 376300-Mains - Plastic | 900556 | 3303L | Inst 5130F 2P Walnut Park Ph 5F | 201509 | 202,666.25 | a | A, B, C, K |
| 376300-Mains - Plastic | 900556 | 3303L | Inst 5130F 2P Walnut Park Ph 5F | 201509 | 15,492.14 | a | A, B, C, K |
| 376300-Mains - Plastic | 900556 | 3303L | Inst 5130F 2P Walnut Park Ph 5F | 201510 | (3,906.39) | a | A, B, C, K |
| 376300-Mains - Plastic | 900556 | 3303L | Inst 5130F 2P Walnut Park Ph 5F | 201510 | (298.60) | a | A, B, C, K |
| 376300-Mains - Plastic | 900556 | 3303L | Inst 5130F 2P Walnut Park Ph 5F | 201511 | 561.81 | a | A, B, C, K |
| 376300-Mains - Plastic | 900556 | 3303L | Inst 5130F 2P Walnut Park Ph 5F | 201511 | 42.94 | a | A, B, C, K |
| 376300-Mains - Plastic | 900556 | 3303L | Inst 5130F 2P Walnut Park Ph 5F | 201512 | 1.47 | a | A, B, C, K |
| 376300-Mains - Plastic | 900556 | 3303L | Inst 5130F 2P Walnut Park Ph 5F | 201512 | 19.21 | a | A, B, C, K |
| 376300-Mains - Plastic | 900557 | 3303L | Inst 2123F 2P Walnut Park Ph6A | 201509 | (5,622.87) | a | A, B, C, K |
| 376300-Mains - Plastic | 900557 | 3303L | Inst 2123F 2P Walnut Park Ph6A | 201509 | (106.47) | a | A, B, C, K |
| 376300-Mains - Plastic | 900558 | 3303L | Inst 1859F 2P Walnut Park Ph6B | 201509 | (14,863.41) | a | A, B, C, K |
| 376300-Mains - Plastic | 900558 | 3303L | Inst 1859F 2P Walnut Park Ph6B | 201509 | (831.46) | a | A, B, C, K |
| 376300-Mains - Plastic | 900558 | 3303L | Inst 1859F 2P Walnut Park Ph6B | 201510 | 1,929.26 | a | A, B, C, K |
| 376300-Mains - Plastic | 900558 | 3303L | Inst 1859F 2P Walnut Park Ph6B | 201510 | 107.92 | a | A, B, C, K |
| 376300-Mains - Plastic | 900558 | 3303L | Inst 1859F 2P Walnut Park Ph6B | 201511 | 146.48 | a | A, B, C, K |
| 376300-Mains - Plastic | 900558 | 3303L | Inst 1859F 2P Walnut Park Ph6B | 201511 | 8.19 | a | A, B, C, K |
| 376300-Mains - Plastic | 900558 | 3303L | Inst 1859F 2P Walnut Park Ph6B | 201512 | 0.21 | a | A, B, C, K |
| 376300-Mains - Plastic | 900558 | 3303L | Inst 1859F 2P Walnut Park Ph6B | 201512 | 3.97 | a | A, B, C, K |
| 376300-Mains - Plastic | 900559 | 3303L | Inst 3875F 2P Walnut Park Ph6C | 201509 | (4,396.29) | a | A, B, C, K |
| 376300-Mains - Plastic | 900559 | 3303L | Inst 3875F 2P Walnut Park Ph6C | 201509 | (83.21) | a | A, B, C, K |
| 376300-Mains - Plastic | 900559 | 3303L | Inst 3875F 2P Walnut Park Ph6C | 201510 | (421.90) | a | A, B, C, K |
| 376300-Mains - Plastic | 900559 | 3303L | Inst 3875F 2P Walnut Park Ph6C | 201510 | (7.98) | a | A, B, C, K |
| 376300-Mains - Plastic | 900559 | 3303L | Inst 3875F 2P Walnut Park Ph6C | 201511 | (4,760.06) | a | A, B, C, K |
| 376300-Mains - Plastic | 900559 | 3303L | Inst 3875F 2P Walnut Park Ph6C | 201511 | 327.17 | a | A, B, C, K |
| 376300-Mains - Plastic | 900559 | 3303L | Inst 3875F 2P Walnut Park Ph6C | 201512 | 52.00 | a | A, B, C, K |
| 376300-Mains - Plastic | 900559 | 3303L | Inst 3875F 2P Walnut Park Ph6C | 201512 | 429.47 | a | A, B, C, K |

| | | | | | | | |
|------------------------|--------|-------|------------------------------------|--------|-------------|---|------------|
| 376300-Mains - Plastic | 900560 | 3303L | Inst 4705F 2P Walnut Park Ph6D | 201509 | 139,228.54 | a | A, B, C, K |
| 376300-Mains - Plastic | 900560 | 3303L | Inst 4705F 2P Walnut Park Ph6D | 201509 | 7,455.22 | a | A, B, C, K |
| 376300-Mains - Plastic | 900560 | 3303L | Inst 4705F 2P Walnut Park Ph6D | 201511 | (322.76) | a | A, B, C, K |
| 376300-Mains - Plastic | 900560 | 3303L | Inst 4705F 2P Walnut Park Ph6D | 201511 | (17.27) | a | A, B, C, K |
| 376300-Mains - Plastic | 900560 | 3303L | Inst 4705F 2P Walnut Park Ph6D | 201512 | 13.93 | a | A, B, C, K |
| 376300-Mains - Plastic | 900560 | 3303L | Inst 4705F 2P Walnut Park Ph6D | 201512 | 260.48 | a | A, B, C, K |
| 376300-Mains - Plastic | 900561 | 3303L | Repl w/ 6270F 2P Walnut Park Ph6E | 201511 | 564,972.10 | a | A, B, C, K |
| 376300-Mains - Plastic | 900561 | 3303L | Repl w/ 6270F 2P Walnut Park Ph6E | 201511 | 6,448.21 | a | A, B, C, K |
| 376300-Mains - Plastic | 900561 | 3303L | Repl w/ 6270F 2P Walnut Park Ph6E | 201512 | 0.54 | a | A, B, C, K |
| 376300-Mains - Plastic | 900561 | 3303L | Repl w/ 6270F 2P Walnut Park Ph6E | 201512 | 48.37 | a | A, B, C, K |
| 376300-Mains - Plastic | 900585 | 3304L | Inst 8458F 8P 8S Lindell | 201509 | (8,875.68) | a | A, B, C, K |
| 376300-Mains - Plastic | 900585 | 3304L | Inst 8458F 8P 8S Lindell | 201509 | (172.61) | a | A, B, C, K |
| 376300-Mains - Plastic | 900595 | 3304L | Inst 4616F 8P Alaska | 201509 | (115.42) | a | A, B, C, K |
| 376300-Mains - Plastic | 900595 | 3304L | Inst 4616F 8P Alaska | 201509 | (2.74) | a | A, B, C, K |
| 376100-Mains - Steel | 900596 | 3304L | Inst 3200F 8P Holly Hills | 201509 | (409.17) | a | A, B, C, K |
| 376300-Mains - Plastic | 900596 | 3304L | Inst 3200F 8P Holly Hills | 201509 | (4,915.70) | a | A, B, C, K |
| 376300-Mains - Plastic | 900596 | 3304L | Inst 3200F 8P Holly Hills | 201509 | (89.34) | a | A, B, C, K |
| 376100-Mains - Steel | 900597 | 3304L | Inst 5626F 12P Lindell | 201509 | (37,594.23) | a | A, B, C, K |
| 376300-Mains - Plastic | 900597 | 3304L | Inst 5626F 12P Lindell | 201509 | 25,745.08 | a | A, B, C, K |
| 376300-Mains - Plastic | 900597 | 3304L | Inst 5626F 12P Lindell | 201509 | (4,580.55) | a | A, B, C, K |
| 376300-Mains - Plastic | 900598 | 3304L | Inst 5746F 8P Winnebago-Gravois | 201509 | (11,230.96) | a | A, B, C, K |
| 376300-Mains - Plastic | 900598 | 3304L | Inst 5746F 8P Winnebago-Gravois | 201509 | 151.18 | a | A, B, C, K |
| 376300-Mains - Plastic | 900603 | 3303L | Inst 4300F 2P Maplewood Ph2A | 201512 | 8,066.95 | a | A, B, C, K |
| 376300-Mains - Plastic | 900603 | 3303L | Inst 4300F 2P Maplewood Ph2A | 201512 | 121,862.63 | a | A, B, C, K |
| 376300-Mains - Plastic | 900605 | 3303L | Inst 2020F 2P Maplewood Ph 2B | 201512 | 15,771.30 | a | A, B, C, K |
| 376300-Mains - Plastic | 900605 | 3303L | Inst 2020F 2P Maplewood Ph 2B | 201512 | 216,813.61 | a | A, B, C, K |
| 376300-Mains - Plastic | 900607 | 3303L | Inst 3183F 2P Maplewood Ph2C | 201509 | 181,653.32 | a | A, B, C, K |
| 376300-Mains - Plastic | 900607 | 3303L | Inst 3183F 2P Maplewood Ph2C | 201509 | 7,357.65 | a | A, B, C, K |
| 376300-Mains - Plastic | 900607 | 3303L | Inst 3183F 2P Maplewood Ph2C | 201510 | 7,674.49 | a | A, B, C, K |
| 376300-Mains - Plastic | 900607 | 3303L | Inst 3183F 2P Maplewood Ph2C | 201510 | 310.84 | a | A, B, C, K |
| 376300-Mains - Plastic | 900607 | 3303L | Inst 3183F 2P Maplewood Ph2C | 201511 | 15,747.37 | a | A, B, C, K |
| 376300-Mains - Plastic | 900607 | 3303L | Inst 3183F 2P Maplewood Ph2C | 201511 | 637.81 | a | A, B, C, K |
| 376300-Mains - Plastic | 900607 | 3303L | Inst 3183F 2P Maplewood Ph2C | 201512 | 8.19 | a | A, B, C, K |
| 376300-Mains - Plastic | 900607 | 3303L | Inst 3183F 2P Maplewood Ph2C | 201512 | 201.92 | a | A, B, C, K |
| 376300-Mains - Plastic | 900623 | 3303L | Repl w/ 2852' 2P Wydown Ph 6 | 201509 | (9,527.55) | a | A, B, C, K |
| 376300-Mains - Plastic | 900623 | 3303L | Repl w/ 2852' 2P Wydown Ph 6 | 201509 | 1,399.22 | a | A, B, C, K |
| 376300-Mains - Plastic | 900625 | 3304L | Inst 4530F 8P Newstead | 201509 | (18,244.96) | a | A, B, C, K |
| 376300-Mains - Plastic | 900625 | 3304L | Inst 4530F 8P Newstead | 201509 | (1,083.94) | a | A, B, C, K |
| 376300-Mains - Plastic | 900625 | 3304L | Inst 4530F 8P Newstead | 201511 | 14,618.22 | a | A, B, C, K |
| 376300-Mains - Plastic | 900625 | 3304L | Inst 4530F 8P Newstead | 201511 | 868.48 | a | A, B, C, K |
| 376300-Mains - Plastic | 900625 | 3304L | Inst 4530F 8P Newstead | 201512 | 4,904.39 | a | A, B, C, K |
| 376300-Mains - Plastic | 900625 | 3304L | Inst 4530F 8P Newstead | 201512 | 82,551.32 | a | A, B, C, K |
| 376100-Mains - Steel | 900629 | 3304L | Inst 4820F 8P Kingshighway & McRee | 201509 | (1,976.91) | a | A, B, C, K |
| 376300-Mains - Plastic | 900629 | 3304L | Inst 4820F 8P Kingshighway & McRee | 201509 | (6,157.45) | a | A, B, C, K |
| 376300-Mains - Plastic | 900629 | 3304L | Inst 4820F 8P Kingshighway & McRee | 201509 | (2,161.37) | a | A, B, C, K |
| 376300-Mains - Plastic | 900635 | 3304L | Inst 1228F 8P Manchester | 201509 | (5.48) | a | A, B, C, K |
| 376300-Mains - Plastic | 900635 | 3304L | Inst 1228F 8P Manchester | 201509 | (0.04) | a | A, B, C, K |
| 376100-Mains - Steel | 900643 | 3304L | Inst 1801F 6P-12P Marmaduke/Hudler | 201509 | 191.63 | a | A, B, C, K |
| 376300-Mains - Plastic | 900643 | 3304L | Inst 1801F 6P-12P Marmaduke/Hudler | 201509 | (13,791.93) | a | A, B, C, K |
| 376300-Mains - Plastic | 900643 | 3304L | Inst 1801F 6P-12P Marmaduke/Hudler | 201509 | (7,187.64) | a | A, B, C, K |
| 376100-Mains - Steel | 900643 | 3304L | Inst 1801F 6P-12P Marmaduke/Hudler | 201510 | 0.03 | a | A, B, C, K |

| | | | | | | | |
|------------------------|--------|-------|------------------------------------|--------|-------------|---|------------|
| 376300-Mains - Plastic | 900643 | 3304L | Inst 1801F 6P-12P Marmaduke/Hudler | 201510 | 84.18 | a | A, B, C, K |
| 376300-Mains - Plastic | 900643 | 3304L | Inst 1801F 6P-12P Marmaduke/Hudler | 201510 | 3.63 | a | A, B, C, K |
| 376300-Mains - Plastic | 900644 | 3304L | Inst 4190F 8P Evans | 201509 | (1,001.18) | a | A, B, C, K |
| 376300-Mains - Plastic | 900644 | 3304L | Inst 4190F 8P Evans | 201509 | (24.86) | a | A, B, C, K |
| 376300-Mains - Plastic | 900645 | 3304L | Inst 4690F 8P Vandeventer | 201509 | (4,535.80) | a | A, B, C, K |
| 376300-Mains - Plastic | 900645 | 3304L | Inst 4690F 8P Vandeventer | 201509 | (135.37) | a | A, B, C, K |
| 376300-Mains - Plastic | 900649 | 3304L | Inst 5308F 8P Manchester Header | 201512 | 44,154.33 | a | A, B, C, K |
| 376100-Mains - Steel | 900649 | 3304L | Inst 5308F 8P Manchester Header | 201512 | 75,025.50 | a | A, B, C, K |
| 376300-Mains - Plastic | 900649 | 3304L | Inst 5308F 8P Manchester Header | 201512 | 641,406.15 | a | A, B, C, K |
| 376300-Mains - Plastic | 900650 | 3303L | Inst 3290F 2P St Louis Hills Ph1A | 201509 | (9,128.55) | a | A, B, C, K |
| 376300-Mains - Plastic | 900650 | 3303L | Inst 3290F 2P St Louis Hills Ph1A | 201509 | (388.50) | a | A, B, C, K |
| 376300-Mains - Plastic | 900650 | 3303L | Inst 3290F 2P St Louis Hills Ph1A | 201512 | (4,310.42) | a | A, B, C, K |
| 376300-Mains - Plastic | 900650 | 3303L | Inst 3290F 2P St Louis Hills Ph1A | 201512 | 5,479.81 | a | A, B, C, K |
| 376300-Mains - Plastic | 900652 | 3303L | Inst 4435F 2P St Louis Hills Ph1B | 201509 | (3,756.04) | a | A, B, C, K |
| 376300-Mains - Plastic | 900652 | 3303L | Inst 4435F 2P St Louis Hills Ph1B | 201509 | (147.45) | a | A, B, C, K |
| 376300-Mains - Plastic | 900652 | 3303L | Inst 4435F 2P St Louis Hills Ph1B | 201511 | (5,589.37) | a | A, B, C, K |
| 376300-Mains - Plastic | 900652 | 3303L | Inst 4435F 2P St Louis Hills Ph1B | 201511 | 1,596.32 | a | A, B, C, K |
| 376300-Mains - Plastic | 900653 | 3303L | Inst 2636F 2P St Louis Hills Ph1C | 201509 | (1,252.76) | a | A, B, C, K |
| 376300-Mains - Plastic | 900653 | 3303L | Inst 2636F 2P St Louis Hills Ph1C | 201509 | (12.78) | a | A, B, C, K |
| 376300-Mains - Plastic | 900653 | 3303L | Inst 2636F 2P St Louis Hills Ph1C | 201510 | 128.23 | a | A, B, C, K |
| 376300-Mains - Plastic | 900653 | 3303L | Inst 2636F 2P St Louis Hills Ph1C | 201510 | 1.31 | a | A, B, C, K |
| 376300-Mains - Plastic | 900653 | 3303L | Inst 2636F 2P St Louis Hills Ph1C | 201511 | (3,418.85) | a | A, B, C, K |
| 376300-Mains - Plastic | 900653 | 3303L | Inst 2636F 2P St Louis Hills Ph1C | 201511 | 790.06 | a | A, B, C, K |
| 376300-Mains - Plastic | 900653 | 3303L | Inst 2636F 2P St Louis Hills Ph1C | 201512 | 0.05 | a | A, B, C, K |
| 376300-Mains - Plastic | 900653 | 3303L | Inst 2636F 2P St Louis Hills Ph1C | 201512 | 3.90 | a | A, B, C, K |
| 376300-Mains - Plastic | 900668 | 3304L | Inst 5690F 8P Cora | 201509 | (19.02) | a | A, B, C, K |
| 376300-Mains - Plastic | 900668 | 3304L | Inst 5690F 8P Cora | 201509 | (0.93) | a | A, B, C, K |
| 376300-Mains - Plastic | 900669 | 3304L | Inst 4565F 8P Page & Evans | 201509 | (7.87) | a | A, B, C, K |
| 376300-Mains - Plastic | 900669 | 3304L | Inst 4565F 8P Page & Evans | 201509 | (0.31) | a | A, B, C, K |
| 376100-Mains - Steel | 900677 | 3303L | Repl w/ 1795F 2P Cole & 18th PhA | 201509 | (14,440.02) | a | A, B, C, K |
| 376300-Mains - Plastic | 900677 | 3303L | Repl w/ 1795F 2P Cole & 18th PhA | 201509 | 5,824.99 | a | A, B, C, K |
| 376300-Mains - Plastic | 900677 | 3303L | Repl w/ 1795F 2P Cole & 18th PhA | 201509 | (3,214.96) | a | A, B, C, K |
| 376300-Mains - Plastic | 900679 | 3303L | Inst 2312F 4P Cole & 18th PhB | 201509 | (6,760.02) | a | A, B, C, K |
| 376300-Mains - Plastic | 900679 | 3303L | Inst 2312F 4P Cole & 18th PhB | 201509 | (414.06) | a | A, B, C, K |
| 376300-Mains - Plastic | 900679 | 3303L | Inst 2312F 4P Cole & 18th PhB | 201511 | (26,817.23) | a | A, B, C, K |
| 376300-Mains - Plastic | 900679 | 3303L | Inst 2312F 4P Cole & 18th PhB | 201511 | 22,892.15 | a | A, B, C, K |
| 376300-Mains - Plastic | 900681 | 3303L | Inst 1637F 2P Cole & 18th Ph C | 201509 | (15,290.97) | a | A, B, C, K |
| 376300-Mains - Plastic | 900681 | 3303L | Inst 1637F 2P Cole & 18th Ph C | 201509 | (899.28) | a | A, B, C, K |
| 376300-Mains - Plastic | 900683 | 3303L | Inst 1864F 2P Cole & 18th Ph D | 201509 | (27,232.88) | a | A, B, C, K |
| 376300-Mains - Plastic | 900683 | 3303L | Inst 1864F 2P Cole & 18th Ph D | 201509 | (2,098.47) | a | A, B, C, K |
| 376300-Mains - Plastic | 900683 | 3303L | Inst 1864F 2P Cole & 18th Ph D | 201510 | 67.70 | a | A, B, C, K |
| 376300-Mains - Plastic | 900683 | 3303L | Inst 1864F 2P Cole & 18th Ph D | 201510 | 32.24 | a | A, B, C, K |
| 376300-Mains - Plastic | 900683 | 3303L | Inst 1864F 2P Cole & 18th Ph D | 201511 | (0.14) | a | A, B, C, K |
| 376300-Mains - Plastic | 900683 | 3303L | Inst 1864F 2P Cole & 18th Ph D | 201511 | (0.01) | a | A, B, C, K |
| 376300-Mains - Plastic | 900683 | 3303L | Inst 1864F 2P Cole & 18th Ph D | 201512 | 0.20 | a | A, B, C, K |
| 376300-Mains - Plastic | 900683 | 3303L | Inst 1864F 2P Cole & 18th Ph D | 201512 | 3.32 | a | A, B, C, K |
| 376300-Mains - Plastic | 900685 | 3303L | Inst 1550F 2P Cole & 18th PhE | 201509 | (2,690.67) | a | A, B, C, K |
| 376300-Mains - Plastic | 900685 | 3303L | Inst 1550F 2P Cole & 18th PhE | 201509 | (6,784.32) | a | A, B, C, K |
| 376300-Mains - Plastic | 900685 | 3303L | Inst 1550F 2P Cole & 18th PhE | 201510 | 177.37 | a | A, B, C, K |
| 376300-Mains - Plastic | 900685 | 3303L | Inst 1550F 2P Cole & 18th PhE | 201510 | 57.77 | a | A, B, C, K |
| 376300-Mains - Plastic | 900685 | 3303L | Inst 1550F 2P Cole & 18th PhE | 201511 | (0.25) | a | A, B, C, K |

| | | | | | | | |
|------------------------|--------|-------|------------------------------------|--------|-------------|---|------------|
| 376300-Mains - Plastic | 900685 | 3303L | Inst 1550F 2P Cole & 18th PhE | 201511 | (0.02) | a | A, B, C, K |
| 376300-Mains - Plastic | 900685 | 3303L | Inst 1550F 2P Cole & 18th PhE | 201512 | 0.22 | a | A, B, C, K |
| 376300-Mains - Plastic | 900685 | 3303L | Inst 1550F 2P Cole & 18th PhE | 201512 | 6.93 | a | A, B, C, K |
| 376300-Mains - Plastic | 900687 | 3303L | Inst 1096F 2P Cole & 18th PhF | 201509 | (16,803.86) | a | A, B, C, K |
| 376300-Mains - Plastic | 900687 | 3303L | Inst 1096F 2P Cole & 18th PhF | 201509 | 6,235.82 | a | A, B, C, K |
| 376300-Mains - Plastic | 900689 | 3303L | Inst 2434F 2P Cole & 18th PhG | 201509 | (27,702.44) | a | A, B, C, K |
| 376300-Mains - Plastic | 900689 | 3303L | Inst 2434F 2P Cole & 18th PhG | 201509 | 2,269.38 | a | A, B, C, K |
| 376300-Mains - Plastic | 900689 | 3303L | Inst 2434F 2P Cole & 18th PhG | 201510 | (184.17) | a | A, B, C, K |
| 376300-Mains - Plastic | 900689 | 3303L | Inst 2434F 2P Cole & 18th PhG | 201510 | (132.64) | a | A, B, C, K |
| 376300-Mains - Plastic | 900689 | 3303L | Inst 2434F 2P Cole & 18th PhG | 201511 | 0.43 | a | A, B, C, K |
| 376300-Mains - Plastic | 900689 | 3303L | Inst 2434F 2P Cole & 18th PhG | 201511 | 0.06 | a | A, B, C, K |
| 376300-Mains - Plastic | 900689 | 3303L | Inst 2434F 2P Cole & 18th PhG | 201512 | (48.36) | a | A, B, C, K |
| 376300-Mains - Plastic | 900689 | 3303L | Inst 2434F 2P Cole & 18th PhG | 201512 | (27.20) | a | A, B, C, K |
| 376300-Mains - Plastic | 900691 | 3303L | Repl w/ 3458F 2P Cole & 18th Ph H | 201509 | 768.31 | a | A, B, C, K |
| 376300-Mains - Plastic | 900691 | 3303L | Repl w/ 3458F 2P Cole & 18th Ph H | 201509 | 1,084.60 | a | A, B, C, K |
| 376300-Mains - Plastic | 900691 | 3303L | Repl w/ 3458F 2P Cole & 18th Ph H | 201510 | 2,874.34 | a | A, B, C, K |
| 376300-Mains - Plastic | 900691 | 3303L | Repl w/ 3458F 2P Cole & 18th Ph H | 201510 | 1,551.80 | a | A, B, C, K |
| 376300-Mains - Plastic | 900691 | 3303L | Repl w/ 3458F 2P Cole & 18th Ph H | 201511 | (79.98) | a | A, B, C, K |
| 376300-Mains - Plastic | 900691 | 3303L | Repl w/ 3458F 2P Cole & 18th Ph H | 201511 | (2.11) | a | A, B, C, K |
| 376300-Mains - Plastic | 900691 | 3303L | Repl w/ 3458F 2P Cole & 18th Ph H | 201512 | 1,591.73 | a | A, B, C, K |
| 376300-Mains - Plastic | 900691 | 3303L | Repl w/ 3458F 2P Cole & 18th Ph H | 201512 | 9,523.08 | a | A, B, C, K |
| 376300-Mains - Plastic | 900692 | 3304L | Inst 3834F 8P Lindell | 201509 | (167.06) | a | A, B, C, K |
| 376300-Mains - Plastic | 900692 | 3304L | Inst 3834F 8P Lindell | 201509 | (23.89) | a | A, B, C, K |
| 376100-Mains - Steel | 900709 | 3304L | Repl w/ 2662F 8P Natural Bridge | 201509 | (617.58) | a | A, B, C, K |
| 376300-Mains - Plastic | 900709 | 3304L | Repl w/ 2662F 8P Natural Bridge | 201509 | (9,906.95) | a | A, B, C, K |
| 376300-Mains - Plastic | 900709 | 3304L | Repl w/ 2662F 8P Natural Bridge | 201509 | 2,196.70 | a | A, B, C, K |
| 376100-Mains - Steel | 900709 | 3304L | Repl w/ 2662F 8P Natural Bridge | 201510 | (14.12) | a | A, B, C, K |
| 376300-Mains - Plastic | 900709 | 3304L | Repl w/ 2662F 8P Natural Bridge | 201510 | (333.38) | a | A, B, C, K |
| 376300-Mains - Plastic | 900709 | 3304L | Repl w/ 2662F 8P Natural Bridge | 201510 | (6.63) | a | A, B, C, K |
| 376300-Mains - Plastic | 900711 | 3304L | Inst 4010F 8P Natural Bridge | 201509 | (36,871.02) | a | A, B, C, K |
| 376300-Mains - Plastic | 900711 | 3304L | Inst 4010F 8P Natural Bridge | 201509 | 19,345.99 | a | A, B, C, K |
| 376300-Mains - Plastic | 900713 | 3304L | Inst 4816F 8P Penrod & Sulphur | 201509 | (5,881.60) | a | A, B, C, K |
| 376300-Mains - Plastic | 900713 | 3304L | Inst 4816F 8P Penrod & Sulphur | 201509 | (207.96) | a | A, B, C, K |
| 376300-Mains - Plastic | 900734 | 3303L | Repl w/ 1717F 2P Hurck | 201509 | (4,653.97) | a | A, B, C, K |
| 376300-Mains - Plastic | 900734 | 3303L | Repl w/ 1717F 2P Hurck | 201509 | (251.65) | a | A, B, C, K |
| 376300-Mains - Plastic | 900734 | 3303L | Repl w/ 1717F 2P Hurck | 201510 | 35.99 | a | A, B, C, K |
| 376300-Mains - Plastic | 900734 | 3303L | Repl w/ 1717F 2P Hurck | 201510 | 1.94 | a | A, B, C, K |
| 376300-Mains - Plastic | 900734 | 3303L | Repl w/ 1717F 2P Hurck | 201511 | (2,398.57) | a | A, B, C, K |
| 376300-Mains - Plastic | 900734 | 3303L | Repl w/ 1717F 2P Hurck | 201511 | 405.71 | a | A, B, C, K |
| 376300-Mains - Plastic | 900734 | 3303L | Repl w/ 1717F 2P Hurck | 201512 | 31.18 | a | A, B, C, K |
| 376300-Mains - Plastic | 900734 | 3303L | Repl w/ 1717F 2P Hurck | 201512 | 152.43 | a | A, B, C, K |
| 376300-Mains - Plastic | 900738 | 3303L | Repl w/ 780F 2P Kingsland MSD | 201509 | (1,359.61) | a | A, B, C, K |
| 376300-Mains - Plastic | 900738 | 3303L | Repl w/ 780F 2P Kingsland MSD | 201509 | (113.02) | a | A, B, C, K |
| 376300-Mains - Plastic | 900738 | 3303L | Repl w/ 780F 2P Kingsland MSD | 201511 | (392.60) | a | A, B, C, K |
| 376300-Mains - Plastic | 900738 | 3303L | Repl w/ 780F 2P Kingsland MSD | 201511 | 18.62 | a | A, B, C, K |
| 376300-Mains - Plastic | 900738 | 3303L | Repl w/ 780F 2P Kingsland MSD | 201512 | 1.52 | a | A, B, C, K |
| 376300-Mains - Plastic | 900738 | 3303L | Repl w/ 780F 2P Kingsland MSD | 201512 | 18.40 | a | A, B, C, K |
| 376300-Mains - Plastic | 900759 | 3303L | Repl w/ 2836F 2P Hickory Dale | 201509 | (17,053.03) | a | A, B, C, K |
| 376300-Mains - Plastic | 900759 | 3303L | Repl w/ 2836F 2P Hickory Dale | 201510 | 30.74 | a | A, B, C, K |
| 376300-Mains - Plastic | 900762 | 3303L | Inst 2069F 2P Earthquake Zone Ph1A | 201509 | (3,072.69) | a | A, B, C, K |

| | | | | | | | |
|------------------------|--------|-------|-------------------------------------|--------|-------------|---|---------------|
| 376300-Mains - Plastic | 900762 | 3303L | Inst 2069F 2P Earthquake Zone Ph1A | 201509 | (102.65) | a | A, B, C, K |
| 376300-Mains - Plastic | 900763 | 3303L | Inst 3508F 2P Earthquake Zone Ph1B | 201509 | 20,488.93 | a | A, B, C, K |
| 376300-Mains - Plastic | 900763 | 3303L | Inst 3508F 2P Earthquake Zone Ph1B | 201509 | (14,166.62) | a | A, B, C, K |
| 376300-Mains - Plastic | 900764 | 3303L | Repl w/758F 2P Earthquake Zone Ph1C | 201509 | 22,173.79 | a | A, B, C, K |
| 376300-Mains - Plastic | 900764 | 3303L | Repl w/758F 2P Earthquake Zone Ph1C | 201509 | 1,617.46 | a | A, B, C, K |
| 376300-Mains - Plastic | 900764 | 3303L | Repl w/758F 2P Earthquake Zone Ph1C | 201510 | 23.44 | a | A, B, C, K |
| 376300-Mains - Plastic | 900764 | 3303L | Repl w/758F 2P Earthquake Zone Ph1C | 201510 | 2.06 | a | A, B, C, K |
| 376300-Mains - Plastic | 900765 | 3303L | Inst 1899F 4P Earthquake Zone Ph1D | 201509 | (27,340.10) | a | A, B, C, K |
| 376300-Mains - Plastic | 900765 | 3303L | Inst 1899F 4P Earthquake Zone Ph1D | 201509 | (713.99) | a | A, B, C, K |
| 376300-Mains - Plastic | 900780 | 3304L | Inst 2180F 6P Union Header Main | 201509 | (4,941.69) | a | A, B, C, K |
| 376300-Mains - Plastic | 900780 | 3304L | Inst 2180F 6P Union Header Main | 201509 | (282.64) | a | A, B, C, K |
| 376300-Mains - Plastic | 900780 | 3304L | Inst 2180F 6P Union Header Main | 201511 | (68.45) | a | A, B, C, K |
| 376300-Mains - Plastic | 900780 | 3304L | Inst 2180F 6P Union Header Main | 201511 | 68.45 | a | A, B, C, K |
| 376300-Mains - Plastic | 900786 | 3304L | Inst 6713F 8P Chippewa & Tholozan | 201509 | (18,763.45) | a | A, B, C, K |
| 376300-Mains - Plastic | 900786 | 3304L | Inst 6713F 8P Chippewa & Tholozan | 201509 | (210.67) | a | A, B, C, K |
| 376300-Mains - Plastic | 900787 | 3304L | Inst 4235F 8P Beck Ave | 201509 | (19,996.85) | a | A, B, C, K |
| 376300-Mains - Plastic | 900787 | 3304L | Inst 4235F 8P Beck Ave | 201509 | 6,066.68 | a | A, B, C, K |
| 376300-Mains - Plastic | 900789 | 3304L | Inst 3104F 8P Hampton Header | 201509 | (9,094.42) | a | A, B, C, K |
| 376300-Mains - Plastic | 900789 | 3304L | Inst 3104F 8P Hampton Header | 201509 | (271.71) | a | A, B, C, K |
| 376300-Mains - Plastic | 900789 | 3304L | Inst 3104F 8P Hampton Header | 201510 | 896.19 | a | A, B, C, K |
| 376300-Mains - Plastic | 900789 | 3304L | Inst 3104F 8P Hampton Header | 201510 | 26.76 | a | A, B, C, K |
| 376300-Mains - Plastic | 900789 | 3304L | Inst 3104F 8P Hampton Header | 201511 | 476.73 | a | A, B, C, K |
| 376300-Mains - Plastic | 900789 | 3304L | Inst 3104F 8P Hampton Header | 201511 | (480.00) | a | A, B, C, K |
| 376300-Mains - Plastic | 900789 | 3304L | Inst 3104F 8P Hampton Header | 201512 | 0.97 | a | A, B, C, K |
| 376300-Mains - Plastic | 900789 | 3304L | Inst 3104F 8P Hampton Header | 201512 | 29.72 | a | A, B, C, K |
| 376300-Mains - Plastic | 900823 | 3303L | Repl w/ 659F 2P Baden Ph6A | 201509 | (805.24) | a | A, B, C, K |
| 376300-Mains - Plastic | 900823 | 3303L | Repl w/ 659F 2P Baden Ph6A | 201509 | (112.58) | a | A, B, C, K |
| 376300-Mains - Plastic | 900830 | 3303L | Repl w/ 5F 8P Florissant | 201509 | (12.65) | a | A, B, C, K |
| 376300-Mains - Plastic | 900830 | 3303L | Repl w/ 5F 8P Florissant | 201509 | (1.28) | a | A, B, C, K |
| 376300-Mains - Plastic | 900849 | 3304L | Inst 850F 12P Whittier Header | 201509 | (3,389.13) | a | A, B, C, K |
| 376300-Mains - Plastic | 900849 | 3304L | Inst 850F 12P Whittier Header | 201509 | (898.89) | a | A, B, C, K |
| 376300-Mains - Plastic | 900859 | 3303L | Repl w/ 290F 2P Cabanne | 201509 | (1,062.84) | a | A, B, C, K |
| 376300-Mains - Plastic | 900859 | 3303L | Repl w/ 290F 2P Cabanne | 201509 | (44.62) | a | A, B, C, K |
| 376300-Mains - Plastic | 900859 | 3303L | Repl w/ 290F 2P Cabanne | 201510 | 12.05 | a | A, B, C, K |
| 376300-Mains - Plastic | 900859 | 3303L | Repl w/ 290F 2P Cabanne | 201510 | 1.70 | a | A, B, C, K |
| 376300-Mains - Plastic | 900861 | 3303L | Repl w/ 105F 4P McLaran | 201509 | (165.10) | a | A, B, C, K |
| 376300-Mains - Plastic | 900861 | 3303L | Repl w/ 105F 4P McLaran | 201509 | (5.54) | a | A, B, C, K |
| 376300-Mains - Plastic | 900862 | 3303L | Rep w/ 4552F 2P Broadway AOR | 201509 | (77,130.19) | a | A, B, C, F, K |
| 376300-Mains - Plastic | 900862 | 3303L | Rep w/ 4552F 2P Broadway AOR | 201509 | 15,147.92 | a | A, B, C, F, K |
| 376300-Mains - Plastic | 900862 | 3303L | Repl w/ 4552F 2P Broadway AOR | 201510 | (8.69) | a | A, B, C, F, K |
| 376300-Mains - Plastic | 900862 | 3303L | Repl w/ 4552F 2P Broadway AOR | 201510 | (114.20) | a | A, B, C, F, K |
| 376300-Mains - Plastic | 900862 | 3303L | Repl w/ 4552F 2P Broadway AOR | 201511 | 0.15 | a | A, B, C, F, K |
| 376300-Mains - Plastic | 900862 | 3303L | Repl w/ 4552F 2P Broadway AOR | 201511 | (0.02) | a | A, B, C, F, K |
| 376300-Mains - Plastic | 900862 | 3303L | Repl w/ 4552F 2P Broadway AOR | 201512 | (7.27) | a | A, B, C, F, K |
| 376300-Mains - Plastic | 900862 | 3303L | Repl w/ 4552F 2P Broadway AOR | 201512 | (1.00) | a | A, B, C, F, K |
| 376300-Mains - Plastic | 900871 | 3303L | Repl w/ 3201F 2P Baden Ph6F | 201512 | 3,992.84 | a | A, B, C, K |
| 376300-Mains - Plastic | 900871 | 3303L | Repl w/ 3201F 2P Baden Ph6F | 201512 | 248,451.55 | a | A, B, C, K |
| 376300-Mains - Plastic | 900873 | 3303L | Repl w/ 538F 2P Longacre | 201509 | (1,321.76) | a | A, B, C, K |
| 376300-Mains - Plastic | 900873 | 3303L | Repl w/ 538F 2P Longacre | 201509 | (78.05) | a | A, B, C, K |
| 376300-Mains - Plastic | 900873 | 3303L | Repl w/ 538F 2P Longacre | 201510 | 13,315.54 | a | A, B, C, K |
| 376300-Mains - Plastic | 900873 | 3303L | Repl w/ 538F 2P Longacre | 201510 | 786.24 | a | A, B, C, K |

| | | | | | | | |
|------------------------|--------|-------|-----------------------------------|--------|--------------|---|------------|
| 376300-Mains - Plastic | 900876 | 3303L | Repl w/ 1060F 2P Rauschenbach PVC | 201509 | (1,774.32) | a | A, B, C, K |
| 376300-Mains - Plastic | 900876 | 3303L | Repl w/ 1060F 2P Rauschenbach PVC | 201509 | (27.80) | a | A, B, C, K |
| 376300-Mains - Plastic | 900876 | 3303L | Repl w/ 1060F 2P Rauschenbach PVC | 201510 | 1,218.32 | a | A, B, C, K |
| 376300-Mains - Plastic | 900876 | 3303L | Repl w/ 1060F 2P Rauschenbach PVC | 201510 | 19.09 | a | A, B, C, K |
| 376300-Mains - Plastic | 900876 | 3303L | Repl w/ 1060F 2P Rauschenbach PVC | 201511 | (0.93) | a | A, B, C, K |
| 376300-Mains - Plastic | 900876 | 3303L | Repl w/ 1060F 2P Rauschenbach PVC | 201511 | (0.02) | a | A, B, C, K |
| 376300-Mains - Plastic | 900876 | 3303L | Repl w/ 1060F 2P Rauschenbach PVC | 201512 | (6,247.79) | a | A, B, C, K |
| 376300-Mains - Plastic | 900876 | 3303L | Repl w/ 1060F 2P Rauschenbach PVC | 201512 | 29.98 | a | A, B, C, K |
| 376300-Mains - Plastic | 900890 | 3303L | Repl w/ 2218F 2P Russell & Flora | 201509 | (153,825.96) | a | A, B, C, K |
| 376300-Mains - Plastic | 900890 | 3303L | Repl w/ 2218F 2P Russell & Flora | 201509 | (1,147.20) | a | A, B, C, K |
| 376300-Mains - Plastic | 900890 | 3303L | Repl w/ 2218F 2P Russell & Flora | 201510 | 61.50 | a | A, B, C, K |
| 376300-Mains - Plastic | 900890 | 3303L | Repl w/ 2218F 2P Russell & Flora | 201510 | 1.83 | a | A, B, C, K |
| 376300-Mains - Plastic | 900893 | 3303L | Repl w/ 2486F 6P Arlington | 201509 | (4,442.05) | a | A, B, C, K |
| 376300-Mains - Plastic | 900893 | 3303L | Repl w/ 2486F 6P Arlington | 201509 | (319.29) | a | A, B, C, K |
| 376300-Mains - Plastic | 900893 | 3303L | Repl w/ 2486F 6P Arlington | 201511 | (4,163.64) | a | A, B, C, K |
| 376300-Mains - Plastic | 900893 | 3303L | Repl w/ 2486F 6P Arlington | 201511 | 4,734.79 | a | A, B, C, K |
| 376300-Mains - Plastic | 900893 | 3303L | Repl w/ 2486F 6P Arlington | 201512 | (1,007.99) | a | A, B, C, K |
| 376300-Mains - Plastic | 900893 | 3303L | Repl w/ 2486F 6P Arlington | 201512 | (21.91) | a | A, B, C, K |
| 376300-Mains - Plastic | 900895 | 3303L | Repl w/ 828F 2P Marquette | 201509 | 22,993.48 | a | A, B, C, K |
| 376300-Mains - Plastic | 900895 | 3303L | Repl w/ 828F 2P Marquette | 201509 | 2,458.35 | a | A, B, C, K |
| 376300-Mains - Plastic | 900895 | 3303L | Repl w/ 828F 2P Marquette | 201510 | (232.20) | a | A, B, C, K |
| 376300-Mains - Plastic | 900895 | 3303L | Repl w/ 828F 2P Marquette | 201510 | 5.79 | a | A, B, C, K |
| 376300-Mains - Plastic | 900895 | 3303L | Repl w/ 828F 2P Marquette | 201512 | (15.88) | a | A, B, C, K |
| 376300-Mains - Plastic | 900895 | 3303L | Repl w/ 828F 2P Marquette | 201512 | (10.68) | a | A, B, C, K |
| 376300-Mains - Plastic | 900896 | 3303L | Repl w/ 2990F 2P 4P Maple | 201509 | (3,391.46) | a | A, B, C, K |
| 376300-Mains - Plastic | 900896 | 3303L | Repl w/ 2990F 2P 4P Maple | 201509 | (160.01) | a | A, B, C, K |
| 376300-Mains - Plastic | 900896 | 3303L | Repl w/ 2990F 2P 4P Maple | 201510 | 379.02 | a | A, B, C, K |
| 376300-Mains - Plastic | 900896 | 3303L | Repl w/ 2990F 2P 4P Maple | 201510 | 17.90 | a | A, B, C, K |
| 376300-Mains - Plastic | 900896 | 3303L | Repl w/ 2990F 2P 4P Maple | 201511 | (2,811.35) | a | A, B, C, K |
| 376300-Mains - Plastic | 900896 | 3303L | Repl w/ 2990F 2P 4P Maple | 201511 | 789.25 | a | A, B, C, K |
| 376300-Mains - Plastic | 900896 | 3303L | Repl w/ 2990F 2P 4P Maple | 201512 | (369.18) | a | A, B, C, K |
| 376300-Mains - Plastic | 900896 | 3303L | Repl w/ 2990F 2P 4P Maple | 201512 | (9.99) | a | A, B, C, K |
| 376300-Mains - Plastic | 900897 | 3303L | Repl w/ 587F 2P Syracuse | 201509 | 2,783.36 | a | A, B, C, K |
| 376300-Mains - Plastic | 900897 | 3303L | Repl w/ 587F 2P Syracuse | 201511 | (1,132.63) | a | A, B, C, K |
| 376300-Mains - Plastic | 900897 | 3303L | Repl w/ 587F 2P Syracuse | 201512 | (315.11) | a | A, B, C, K |
| 376300-Mains - Plastic | 900898 | 3303L | Repl w/ 1220F 2P Ohio | 201509 | 19,719.80 | a | A, B, C, K |
| 376300-Mains - Plastic | 900898 | 3303L | Repl w/ 1220F 2P Ohio | 201509 | 2,579.92 | a | A, B, C, K |
| 376300-Mains - Plastic | 900898 | 3303L | Repl w/ 1220F 2P Ohio | 201510 | (13.58) | a | A, B, C, K |
| 376300-Mains - Plastic | 900898 | 3303L | Repl w/ 1220F 2P Ohio | 201510 | 1.62 | a | A, B, C, K |
| 376300-Mains - Plastic | 900900 | 3303L | Repl w/ 1075F 2P Washington | 201509 | 1,690.84 | a | A, B, C, K |
| 376300-Mains - Plastic | 900900 | 3303L | Repl w/ 1075F 2P Washington | 201509 | 7,070.73 | a | A, B, C, K |
| 376300-Mains - Plastic | 900900 | 3303L | Repl w/ 1075F 2P Washington | 201510 | 53.62 | a | A, B, C, K |
| 376300-Mains - Plastic | 900900 | 3303L | Repl w/ 1075F 2P Washington | 201510 | 7.67 | a | A, B, C, K |
| 376300-Mains - Plastic | 900902 | 3303L | Repl w/ 530' 2P Oakland | 201509 | (1,569.92) | a | A, B, C, K |
| 376300-Mains - Plastic | 900902 | 3303L | Repl w/ 530' 2P Oakland | 201509 | (3,524.82) | a | A, B, C, K |
| 376300-Mains - Plastic | 900902 | 3303L | Repl w/ 530' 2P Oakland | 201510 | (466.36) | a | A, B, C, K |
| 376300-Mains - Plastic | 900902 | 3303L | Repl w/ 530' 2P Oakland | 201510 | (4.12) | a | A, B, C, K |
| 376300-Mains - Plastic | 900905 | 3303L | Repl w/ 806F 2P Utah | 201509 | 5,653.63 | a | A, B, C, K |
| 376300-Mains - Plastic | 900905 | 3303L | Repl w/ 806F 2P Utah | 201509 | (1,503.84) | a | A, B, C, K |
| 376300-Mains - Plastic | 900905 | 3303L | Repl w/ 806F 2P Utah | 201510 | 11.12 | a | A, B, C, K |

| | | | | | | | |
|------------------------|--------|-------|-------------------------------------|--------|-------------|---|---------------|
| 376300-Mains - Plastic | 900905 | 3303L | Repl w/ 806F 2P Utah | 201510 | 0.05 | a | A, B, C, K |
| 376300-Mains - Plastic | 900908 | 3303L | Repl w/ 460F 2P California | 201509 | (541.99) | a | A, B, C, K |
| 376300-Mains - Plastic | 900908 | 3303L | Repl w/ 460F 2P California | 201509 | (20.72) | a | A, B, C, K |
| 376300-Mains - Plastic | 900908 | 3303L | Repl w/ 460F 2P California | 201510 | 7.16 | a | A, B, C, K |
| 376300-Mains - Plastic | 900908 | 3303L | Repl w/ 460F 2P California | 201510 | 0.78 | a | A, B, C, K |
| 376300-Mains - Plastic | 900912 | 3303L | Repl w/ 745F 2P Shaw | 201509 | (2,144.45) | a | A, B, C, K |
| 376300-Mains - Plastic | 900912 | 3303L | Repl w/ 745F 2P Shaw | 201509 | (81.48) | a | A, B, C, K |
| 376300-Mains - Plastic | 900912 | 3303L | Repl w/ 745F 2P Shaw | 201510 | 32.31 | a | A, B, C, K |
| 376300-Mains - Plastic | 900912 | 3303L | Repl w/ 745F 2P Shaw | 201510 | 0.84 | a | A, B, C, K |
| 376300-Mains - Plastic | 900921 | 3303L | Repl w/ 2457F 4P&2P Flad AOR | 201509 | (5,504.14) | a | A, B, C, F, K |
| 376300-Mains - Plastic | 900921 | 3303L | Repl w/ 2457F 4P&2P Flad AOR | 201509 | 178.37 | a | A, B, C, F, K |
| 376300-Mains - Plastic | 900921 | 3303L | Repl w/ 2457F 4P&2P Flad AOR | 201510 | 4,089.37 | a | A, B, C, F, K |
| 376300-Mains - Plastic | 900921 | 3303L | Repl w/ 2457F 4P&2P Flad AOR | 201510 | 195.60 | a | A, B, C, F, K |
| 376300-Mains - Plastic | 900923 | 3303L | Repl w/ 54F 6P West Florissant | 201511 | 58,748.33 | a | A, B, C, K |
| 376300-Mains - Plastic | 900923 | 3303L | Repl w/ 54F 6P West Florissant | 201511 | 4,888.86 | a | A, B, C, K |
| 376300-Mains - Plastic | 900923 | 3303L | Repl w/ 54F 6P West Florissant | 201512 | 2.23 | a | A, B, C, K |
| 376300-Mains - Plastic | 900923 | 3303L | Repl w/ 54F 6P West Florissant | 201512 | 26.65 | a | A, B, C, K |
| 376300-Mains - Plastic | 900932 | 3303L | Repl w/ 160F 2P Cler Ave | 201509 | (144.18) | a | A, B, C, K |
| 376300-Mains - Plastic | 900932 | 3303L | Repl w/ 160F 2P Cler Ave | 201509 | (2.66) | a | A, B, C, K |
| 376300-Mains - Plastic | 900945 | 3304L | Inst 3920F 8P Hampton&Sulpher Headr | 201509 | (10,876.19) | a | A, B, C, K |
| 376300-Mains - Plastic | 900945 | 3304L | Inst 3920F 8P Hampton&Sulpher Headr | 201509 | (840.11) | a | A, B, C, K |
| 376300-Mains - Plastic | 900945 | 3304L | Inst 3920F 8P Hampton&Sulpher Headr | 201510 | 404.39 | a | A, B, C, K |
| 376300-Mains - Plastic | 900945 | 3304L | Inst 3920F 8P Hampton&Sulpher Headr | 201510 | 31.23 | a | A, B, C, K |
| 376300-Mains - Plastic | 900945 | 3304L | Inst 3920F 8P Hampton&Sulpher Headr | 201511 | (2,800.39) | a | A, B, C, K |
| 376300-Mains - Plastic | 900945 | 3304L | Inst 3920F 8P Hampton&Sulpher Headr | 201511 | 2,799.80 | a | A, B, C, K |
| 376300-Mains - Plastic | 900945 | 3304L | Inst 3920F 8P Hampton&Sulpher Headr | 201512 | 1.14 | a | A, B, C, K |
| 376300-Mains - Plastic | 900945 | 3304L | Inst 3920F 8P Hampton&Sulpher Headr | 201512 | 13.32 | a | A, B, C, K |
| 376300-Mains - Plastic | 900948 | 3303L | Repl w/ 132F 2P Southcote | 201509 | (960.68) | a | A, B, C, K |
| 376300-Mains - Plastic | 900948 | 3303L | Repl w/ 132F 2P Southcote | 201510 | 3.58 | a | A, B, C, K |
| 376300-Mains - Plastic | 900952 | 3303L | Repl w/ 2606F 2P Clifton Heights-1B | 201512 | 14,963.94 | a | A, B, C, K |
| 376300-Mains - Plastic | 900952 | 3303L | Repl w/ 2606F 2P Clifton Heights-1B | 201512 | 295,611.05 | a | A, B, C, K |
| 376300-Mains - Plastic | 900962 | 3304L | Inst 5842F 6P 4P Newstead -Header | 201509 | (9,276.64) | a | A, B, C, K |
| 376300-Mains - Plastic | 900962 | 3304L | Inst 5842F 6P 4P Newstead -Header | 201509 | (2,837.00) | a | A, B, C, K |
| 376300-Mains - Plastic | 900962 | 3304L | Inst 5842F 6P 4P Newstead -Header | 201511 | (8,923.52) | a | A, B, C, K |
| 376300-Mains - Plastic | 900962 | 3304L | Inst 5842F 6P 4P Newstead -Header | 201511 | 8,923.52 | a | A, B, C, K |
| 376300-Mains - Plastic | 900977 | 3303L | Repl w/ 1291F 4P Boyle | 201509 | 454.79 | a | A, B, C, K |
| 376300-Mains - Plastic | 900977 | 3303L | Repl w/ 1291F 4P Boyle | 201509 | 39.00 | a | A, B, C, K |
| 376300-Mains - Plastic | 900978 | 3304L | Inst 3875F 8P Brannon Ave-Header | 201509 | 18,953.48 | a | A, B, C, K |
| 376300-Mains - Plastic | 900978 | 3304L | Inst 3875F 8P Brannon Ave-Header | 201509 | 1,380.98 | a | A, B, C, K |
| 376300-Mains - Plastic | 900978 | 3304L | Inst 3875F 8P Brannon Ave-Header | 201510 | 556.72 | a | A, B, C, K |
| 376300-Mains - Plastic | 900978 | 3304L | Inst 3875F 8P Brannon Ave-Header | 201510 | 40.56 | a | A, B, C, K |
| 376300-Mains - Plastic | 900978 | 3304L | Inst 3875F 8P Brannon Ave-Header | 201511 | (0.77) | a | A, B, C, K |
| 376300-Mains - Plastic | 900978 | 3304L | Inst 3875F 8P Brannon Ave-Header | 201511 | (0.06) | a | A, B, C, K |
| 376300-Mains - Plastic | 900978 | 3304L | Inst 3875F 8P Brannon Ave-Header | 201512 | (84,254.24) | a | A, B, C, K |
| 376300-Mains - Plastic | 900978 | 3304L | Inst 3875F 8P Brannon Ave-Header | 201512 | 84,274.07 | a | A, B, C, K |
| 376300-Mains - Plastic | 900979 | 3304L | Inst 2254F 8P Brannon | 201509 | 305,891.76 | a | A, B, C, K |
| 376300-Mains - Plastic | 900979 | 3304L | Inst 2254F 8P Brannon | 201509 | 18,214.16 | a | A, B, C, K |
| 376300-Mains - Plastic | 900979 | 3304L | Inst 2254F 8P Brannon | 201510 | 710.09 | a | A, B, C, K |
| 376300-Mains - Plastic | 900979 | 3304L | Inst 2254F 8P Brannon | 201510 | 42.29 | a | A, B, C, K |
| 376300-Mains - Plastic | 900979 | 3304L | Inst 2254F 8P Brannon | 201511 | (5,949.46) | a | A, B, C, K |

| | | | | | | | |
|------------------------|--------|-------|-------------------------------------|--------|-------------|---|---------------|
| 376300-Mains - Plastic | 900979 | 3304L | Inst 2254F 8P Brannon | 201511 | (354.26) | a | A, B, C, K |
| 376300-Mains - Plastic | 900979 | 3304L | Inst 2254F 8P Brannon | 201512 | 4.88 | a | A, B, C, K |
| 376300-Mains - Plastic | 900979 | 3304L | Inst 2254F 8P Brannon | 201512 | 81.93 | a | A, B, C, K |
| 376300-Mains - Plastic | 900983 | 3303L | Repl w/ 3143F 2P 4P Shaw AOR | 201512 | 9,922.30 | a | A, B, C, F, K |
| 376300-Mains - Plastic | 900983 | 3303L | Repl w/ 3143F 2P 4P Shaw AOR | 201512 | 400,436.29 | a | A, B, C, F, K |
| 376300-Mains - Plastic | 900986 | 3303L | Repl w/ 2189F 2P Earthquake Zone 2A | 201509 | 44,753.62 | a | A, B, C, K |
| 376300-Mains - Plastic | 900986 | 3303L | Repl w/ 2189F 2P Earthquake Zone 2A | 201509 | 11,424.95 | a | A, B, C, K |
| 376300-Mains - Plastic | 900986 | 3303L | Repl w/ 2189F 2P Earthquake Zone 2A | 201510 | (258.39) | a | A, B, C, K |
| 376300-Mains - Plastic | 900986 | 3303L | Repl w/ 2189F 2P Earthquake Zone 2A | 201510 | (15.52) | a | A, B, C, K |
| 376300-Mains - Plastic | 900988 | 3303L | Repl w/ 3840F 2P Earthquake Zn Ph2B | 201509 | 207,224.86 | a | A, B, C, K |
| 376300-Mains - Plastic | 900988 | 3303L | Repl w/ 3840F 2P Earthquake Zn Ph2B | 201509 | 5,106.34 | a | A, B, C, K |
| 376300-Mains - Plastic | 900988 | 3303L | Repl w/ 3840F 2P Earthquake Zn Ph2B | 201510 | 328.21 | a | A, B, C, K |
| 376300-Mains - Plastic | 900988 | 3303L | Repl w/ 3840F 2P Earthquake Zn Ph2B | 201510 | 8.10 | a | A, B, C, K |
| 376300-Mains - Plastic | 900988 | 3303L | Repl w/ 3840F 2P Earthquake Zn Ph2B | 201511 | (1,453.94) | a | A, B, C, K |
| 376300-Mains - Plastic | 900988 | 3303L | Repl w/ 3840F 2P Earthquake Zn Ph2B | 201511 | (35.83) | a | A, B, C, K |
| 376300-Mains - Plastic | 900988 | 3303L | Repl w/ 3840F 2P Earthquake Zn Ph2B | 201512 | 0.71 | a | A, B, C, K |
| 376300-Mains - Plastic | 900988 | 3303L | Repl w/ 3840F 2P Earthquake Zn Ph2B | 201512 | 28.63 | a | A, B, C, K |
| 376300-Mains - Plastic | 900993 | 3303L | Repl w/ 2220F 2P CentralWestEndPh1G | 201511 | 1,596.26 | a | A, B, C, K |
| 376300-Mains - Plastic | 900993 | 3303L | Repl w/ 2220F 2P CentralWestEndPh1G | 201511 | 66.59 | a | A, B, C, K |
| 376300-Mains - Plastic | 901025 | 3303L | Repl w/ 85F 2P Walnut Park | 201509 | (1,193.73) | a | A, B, C, K |
| 376300-Mains - Plastic | 901025 | 3303L | Repl w/ 85F 2P Walnut Park | 201509 | (109.02) | a | A, B, C, K |
| 376300-Mains - Plastic | 901025 | 3303L | Repl w/ 85F 2P Walnut Park | 201510 | 52.48 | a | A, B, C, K |
| 376300-Mains - Plastic | 901025 | 3303L | Repl w/ 85F 2P Walnut Park | 201510 | 4.80 | a | A, B, C, K |
| 376300-Mains - Plastic | 901025 | 3303L | Repl w/ 85F 2P Walnut Park | 201511 | (4.56) | a | A, B, C, K |
| 376300-Mains - Plastic | 901025 | 3303L | Repl w/ 85F 2P Walnut Park | 201511 | 4.49 | a | A, B, C, K |
| 376300-Mains - Plastic | 901025 | 3303L | Repl w/ 85F 2P Walnut Park | 201512 | 1.07 | a | A, B, C, K |
| 376300-Mains - Plastic | 901025 | 3303L | Repl w/ 85F 2P Walnut Park | 201512 | 9.66 | a | A, B, C, K |
| 376300-Mains - Plastic | 901040 | 3303L | Repl w/ 315F 2P Amherst Ave | 201509 | (754.32) | a | A, B, C, K |
| 376300-Mains - Plastic | 901040 | 3303L | Repl w/ 315F 2P Amherst Ave | 201509 | (17.72) | a | A, B, C, K |
| 376300-Mains - Plastic | 901059 | 3303L | Repl w/ 680' 2P Gregg | 201509 | 32,723.70 | a | A, B, C, K |
| 376300-Mains - Plastic | 901059 | 3303L | Repl w/ 680' 2P Gregg | 201509 | 1,565.71 | a | A, B, C, K |
| 376300-Mains - Plastic | 901059 | 3303L | Repl w/ 680' 2P Gregg | 201510 | 659.67 | a | A, B, C, K |
| 376300-Mains - Plastic | 901059 | 3303L | Repl w/ 680' 2P Gregg | 201510 | 31.55 | a | A, B, C, K |
| 376300-Mains - Plastic | 901059 | 3303L | Repl w/ 680' 2P Gregg | 201511 | (448.14) | a | A, B, C, K |
| 376300-Mains - Plastic | 901059 | 3303L | Repl w/ 680' 2P Gregg | 201511 | (21.44) | a | A, B, C, K |
| 376300-Mains - Plastic | 901059 | 3303L | Repl w/ 680' 2P Gregg | 201512 | 0.74 | a | A, B, C, K |
| 376300-Mains - Plastic | 901059 | 3303L | Repl w/ 680' 2P Gregg | 201512 | 15.74 | a | A, B, C, K |
| 376300-Mains - Plastic | 901070 | 3304L | Repl w/ 4194F 6P Eichelberger heade | 201512 | 39,428.37 | a | A, B, C, K |
| 376300-Mains - Plastic | 901070 | 3304L | Repl w/ 4194F 6P Eichelberger heade | 201512 | 476,956.19 | a | A, B, C, K |
| 376100-Mains - Steel | 901084 | 3304L | Inst 4297F 8P Fair Ave header | 201509 | 6,650.31 | a | A, B, C, K |
| 376300-Mains - Plastic | 901084 | 3304L | Inst 4297F 8P Fair Ave header | 201509 | 341,419.16 | a | A, B, C, K |
| 376300-Mains - Plastic | 901084 | 3304L | Inst 4297F 8P Fair Ave header | 201509 | 71,756.88 | a | A, B, C, K |
| 376100-Mains - Steel | 901084 | 3304L | Inst 4297F 8P Fair Ave header | 201510 | (198.44) | a | A, B, C, K |
| 376300-Mains - Plastic | 901084 | 3304L | Inst 4297F 8P Fair Ave header | 201510 | (10,188.42) | a | A, B, C, K |
| 376300-Mains - Plastic | 901084 | 3304L | Inst 4297F 8P Fair Ave header | 201510 | (2,141.33) | a | A, B, C, K |
| 376100-Mains - Steel | 901084 | 3304L | Inst 4297F 8P Fair Ave header | 201511 | (50.64) | a | A, B, C, K |
| 376300-Mains - Plastic | 901084 | 3304L | Inst 4297F 8P Fair Ave header | 201511 | (2,500.88) | a | A, B, C, K |
| 376300-Mains - Plastic | 901084 | 3304L | Inst 4297F 8P Fair Ave header | 201511 | (546.64) | a | A, B, C, K |
| 376300-Mains - Plastic | 901084 | 3304L | Inst 4297F 8P Fair Ave header | 201512 | (297.42) | a | A, B, C, K |

| | | | | | | | |
|------------------------|--------|-------|---------------------------------|--------|--------------|---|---------------|
| 376300-Mains - Plastic | 901084 | 3304L | Inst 4297F 8P Fair Ave header | 201512 | (62.51) | a | A, B, C, K |
| 376100-Mains - Steel | 901084 | 3304L | Inst 4297F 8P Fair Ave header | 201512 | (5.79) | a | A, B, C, K |
| 376300-Mains - Plastic | 901088 | 3303L | Repl w/ 4597F 2P U-City Ph1B | 201512 | 7,810.51 | a | A, B, C, K |
| 376300-Mains - Plastic | 901088 | 3303L | Repl w/ 4597F 2P U-City Ph1B | 201512 | 204,650.36 | a | A, B, C, K |
| 376300-Mains - Plastic | 901111 | 3303L | Repl w/ 955F 2P Hickory | 201509 | 79,845.33 | a | A, B, C, K |
| 376300-Mains - Plastic | 901111 | 3303L | Repl w/ 955F 2P Hickory | 201509 | 3,741.97 | a | A, B, C, K |
| 376300-Mains - Plastic | 901111 | 3303L | Repl w/ 955F 2P Hickory | 201510 | 5,998.99 | a | A, B, C, K |
| 376300-Mains - Plastic | 901111 | 3303L | Repl w/ 955F 2P Hickory | 201510 | 281.15 | a | A, B, C, K |
| 376300-Mains - Plastic | 901111 | 3303L | Repl w/ 955F 2P Hickory | 201511 | (1,178.26) | a | A, B, C, K |
| 376300-Mains - Plastic | 901111 | 3303L | Repl w/ 955F 2P Hickory | 201511 | (55.23) | a | A, B, C, K |
| 376300-Mains - Plastic | 901111 | 3303L | Repl w/ 955F 2P Hickory | 201512 | 5.43 | a | A, B, C, K |
| 376300-Mains - Plastic | 901111 | 3303L | Repl w/ 955F 2P Hickory | 201512 | 115.70 | a | A, B, C, K |
| 376100-Mains - Steel | 901112 | 3303L | UGS Gathering Line Replacement | 201509 | (5,629.12) | a | A, B, C, K |
| 376100-Mains - Steel | 901112 | 3303L | UGS Gathering Line Replacement | 201512 | (216.99) | a | A, B, C, K |
| 376300-Mains - Plastic | 901114 | 3303L | Repl w/ 1630F 2P Maffitt | 201512 | 6,323.75 | a | A, B, C, K |
| 376300-Mains - Plastic | 901114 | 3303L | Repl w/ 1630F 2P Maffitt | 201512 | 154,355.11 | a | A, B, C, K |
| 376300-Mains - Plastic | 901139 | 3303L | Repl w/ 901F 2P Suburban Ave | 201509 | 40,932.69 | a | A, B, C, K |
| 376300-Mains - Plastic | 901139 | 3303L | Repl w/ 901F 2P Suburban Ave | 201509 | 2,690.78 | a | A, B, C, K |
| 376300-Mains - Plastic | 901139 | 3303L | Repl w/ 901F 2P Suburban Ave | 201510 | 8,674.51 | a | A, B, C, K |
| 376300-Mains - Plastic | 901139 | 3303L | Repl w/ 901F 2P Suburban Ave | 201510 | 570.23 | a | A, B, C, K |
| 376300-Mains - Plastic | 901139 | 3303L | Repl w/ 901F 2P Suburban Ave | 201511 | (261.30) | a | A, B, C, K |
| 376300-Mains - Plastic | 901139 | 3303L | Repl w/ 901F 2P Suburban Ave | 201511 | (17.19) | a | A, B, C, K |
| 376300-Mains - Plastic | 901139 | 3303L | Repl w/ 901F 2P Suburban Ave | 201512 | (5.29) | a | A, B, C, K |
| 376300-Mains - Plastic | 901139 | 3303L | Repl w/ 901F 2P Suburban Ave | 201512 | (0.37) | a | A, B, C, K |
| 376300-Mains - Plastic | 901161 | 3303L | Repl w/ 535F 2P Grantsview | 201512 | 869.82 | a | A, B, C, K |
| 376300-Mains - Plastic | 901161 | 3303L | Repl w/ 535F 2P Grantsview | 201512 | 41,404.01 | a | A, B, C, K |
| 376300-Mains - Plastic | 901162 | 3303L | Repl w/ 210F 2P St. Leonard Ct. | 201512 | 1,388.83 | a | A, B, C, K |
| 376300-Mains - Plastic | 901162 | 3303L | Repl w/ 210F 2P St. Leonard Ct. | 201512 | 32,114.37 | a | A, B, C, K |
| 376300-Mains - Plastic | 901178 | 3303L | Repl w/ 185F 2P Evans | 201509 | 7,839.50 | a | A, B, C, K |
| 376300-Mains - Plastic | 901178 | 3303L | Repl w/ 185F 2P Evans | 201510 | 604.27 | a | A, B, C, K |
| 376300-Mains - Plastic | 901178 | 3303L | Repl w/ 185F 2P Evans | 201511 | (0.60) | a | A, B, C, K |
| 376300-Mains - Plastic | 901178 | 3303L | Repl w/ 185F 2P Evans | 201512 | 22.98 | a | A, B, C, K |
| 376300-Mains - Plastic | 901220 | 3303L | Aband 511F 4C Marcus AOR | 201512 | 606.37 | a | A, B, C, F, K |
| 376300-Mains - Plastic | 901220 | 3303L | Aband 511F 4C Marcus AOR | 201512 | 5,399.81 | a | A, B, C, F, K |
| 376300-Mains - Plastic | | 3303L | MAIN REPLACEMENTS - ADDITIONS | 201601 | 4,856,000.00 | a | A, B, C, K |
| 376300-Mains - Plastic | | 3303L | MAIN REPLACEMENTS - ADDITIONS | 201602 | 3,362,000.00 | a | A, B, C, K |

16,329,951.87

SERVICE TRANSFER WORK ORDERS

| PLANT ACCOUNT | WORK ORDER | BUDGET PROJECT | DESCRIPTION | IN SERVICE DATE | ADDITION AMOUNT | | |
|------------------------|------------|----------------|------------------------------------|-----------------|-----------------|---|------------|
| 376300-Mains - Plastic | 000569 | 3304L | 4015F 6P 2P Lemay Ferry | 201509 | (0.01) | a | A, B, C, K |
| 376300-Mains - Plastic | 001040 | 3303L | Install 46F 4P Nashville | 201509 | 0.30 | a | A, B, C, K |
| 376300-Mains - Plastic | 001330 | 3303L | Inst 9084F 2P Aberdeen PI | 201509 | (2,758.95) | a | A, B, C, K |
| 376300-Mains - Plastic | 001337 | 3403L | Inst 622F 4P Shenandoah | 201509 | 110,930.59 | a | A, B, C, K |
| 376300-Mains - Plastic | 001337 | 3403L | Inst 622F 4P Shenandoah CJ - Reimb | 201511 | (51,100.99) | a | A, B, C, K |
| 376300-Mains - Plastic | 001535 | 3303L | Repl w/ 9098F 2P Arlington | 201509 | (74.71) | a | A, B, C, K |
| 376300-Mains - Plastic | 001582 | 3303L | Inst 2986F 2P Elendale-Well Ph 4A | 201509 | (0.01) | a | A, B, C, K |

| | | | | | | | |
|------------------------|--------|-------|-------------------------------------|--------|------------|---|------------|
| 376300-Mains - Plastic | 001711 | 3303L | Inst 7023F 2P Northmoor Wydown Ph5 | 201509 | (2.81) | a | A, B, C, K |
| 376300-Mains - Plastic | 001712 | 3303L | Inst 16489F 2P Cote Brillante | 201509 | 6,666.83 | a | A, B, C, K |
| 376300-Mains - Plastic | 001712 | 3303L | Inst 16489F 2P Cote Brillante | 201510 | (22.96) | a | A, B, C, K |
| 376300-Mains - Plastic | 002137 | 3303L | Repl w/ 5955F 2P Boneta | 201509 | (1,621.71) | a | A, B, C, K |
| 376300-Mains - Plastic | 002138 | 3303L | Repl w/ 10203F 2P Manchester | 201509 | (2,490.75) | a | A, B, C, K |
| 376300-Mains - Plastic | 002139 | 3303L | Inst 3278F 2P MLK -Wellston 1B | 201509 | (8,638.24) | a | A, B, C, K |
| 376300-Mains - Plastic | 002139 | 3303L | Inst 3278F 2P MLK -Wellston 1B | 201510 | 1,725.33 | a | A, B, C, K |
| 376300-Mains - Plastic | 002139 | 3303L | Inst 3278F 2P MLK -Wellston 1B | 201511 | 2,708.85 | a | A, B, C, K |
| 376300-Mains - Plastic | 002139 | 3303L | Inst 3278F 2P MLK -Wellston 1B | 201512 | 387.47 | a | A, B, C, K |
| 376300-Mains - Plastic | 002140 | 3303L | Inst 6894F 2P Bertha-Wellston 1A | 201509 | (2,470.33) | a | A, B, C, K |
| 376300-Mains - Plastic | 002140 | 3303L | Inst 6894F 2P Bertha-Wellston 1A | 201510 | (3,703.14) | a | A, B, C, K |
| 376300-Mains - Plastic | 002141 | 3303L | Inst 6161F 2P Marshall-Well. Ph4C | 201509 | (0.56) | a | A, B, C, K |
| 376300-Mains - Plastic | 003763 | 3403M | Rel w/ 3200F 4P Oak Grove Rd-MN | 201509 | 289.62 | a | A, B, C, K |
| 376300-Mains - Plastic | 009113 | 3403M | Rel w/ 210F 4P W Congress MN | 201512 | 2,025.67 | a | A, B, C, K |
| 376300-Mains - Plastic | 672860 | 3504L | 67286 SVC TRF 67285 | 201510 | 4,021.28 | a | A, B, C, K |
| 376300-Mains - Plastic | 900068 | 3303L | Repl w/ 1750F 2P Jefferson Ph 2 | 201509 | (111.72) | a | A, B, C, K |
| 376300-Mains - Plastic | 900071 | 3303L | Repl w/ 4240F 2-4P Jefferson Ph5 | 201511 | 180,314.01 | a | A, B, C, K |
| 376300-Mains - Plastic | 900071 | 3303L | Repl w/ 4240F 2-4P Jefferson Ph5 | 201512 | 596.10 | a | A, B, C, K |
| 376300-Mains - Plastic | 900073 | 3303L | Repl w/ 2520F 2P Jefferson Ph 6 | 201509 | 217,169.41 | a | A, B, C, K |
| 376300-Mains - Plastic | 900073 | 3303L | Repl w/ 2520F 2P Jefferson Ph 6 | 201510 | 285.49 | a | A, B, C, K |
| 376300-Mains - Plastic | 900093 | 3303L | Repl w/ 184F 2P Cass | 201509 | 0.04 | a | A, B, C, K |
| 376300-Mains - Plastic | 900099 | 3403L | Rel 1830F 2P McKnight Rd | 201509 | (60.36) | a | A, B, C, K |
| 376300-Mains - Plastic | 900104 | 3403L | Rel w/ 3018F Var-Kingshighway Bridg | 201512 | 46,034.50 | a | A, B, C, K |
| 376300-Mains - Plastic | 900265 | 3303L | Repl w/ 3337F 2P Baden Ph 5B | 201509 | 0.04 | a | A, B, C, K |
| 376300-Mains - Plastic | 900266 | 3303L | Inst 4640F 2P Baden Ph 5C | 201509 | (0.04) | a | A, B, C, K |
| 376300-Mains - Plastic | 900266 | 3303L | Inst 4640F 2P Baden Ph 5C | 201510 | 0.14 | a | A, B, C, K |
| 376300-Mains - Plastic | 900266 | 3303L | Inst 4640F 2P Baden Ph 5C | 201511 | (0.01) | a | A, B, C, K |
| 376300-Mains - Plastic | 900266 | 3303L | Inst 4640F 2P Baden Ph 5C | 201512 | 0.69 | a | A, B, C, K |
| 376300-Mains - Plastic | 900269 | 3303L | Inst 1150F 4P Walnut Park Ph 5A | 201509 | (613.90) | a | A, B, C, K |
| 376300-Mains - Plastic | 900270 | 3303L | Inst 2942F 2P Walnut Park Ph5B | 201509 | (615.30) | a | A, B, C, K |
| 376300-Mains - Plastic | 900270 | 3303L | Inst 2942F 2P Walnut Park Ph5B | 201511 | 1,856.30 | a | A, B, C, K |
| 376300-Mains - Plastic | 900274 | 3303L | Repl w/ 3390F 2P Wellington Ph 4D | 201512 | 115,841.25 | a | A, B, C, K |
| 376300-Mains - Plastic | 900275 | 3303L | Repl w/ 4989F 2P Wellington Ph4E | 201509 | (1,631.25) | a | A, B, C, K |
| 376300-Mains - Plastic | 900278 | 3303L | Repl w/ 3977F 2P Walnut Park Ph4C | 201509 | (1.42) | a | A, B, C, K |
| 376300-Mains - Plastic | 900279 | 3303L | Repl w/ 3345F 2P Walnut Park Ph4D | 201509 | (528.38) | a | A, B, C, K |
| 376300-Mains - Plastic | 900282 | 3303L | Inst 4400F 2P Wellston 2C | 201509 | (773.04) | a | A, B, C, K |
| 376300-Mains - Plastic | 900284 | 3303L | Inst 5466F 2P Wellston Ph2E | 201509 | (22.33) | a | A, B, C, K |
| 376300-Mains - Plastic | 900313 | 3403L | Rel w/ 775F 2P Caulks Hill Rd CJ | 201510 | (232.81) | a | A, B, C, K |
| 376300-Mains - Plastic | 900375 | 3303L | Inst 1747F 6P Litzinger | 201509 | 0.22 | a | A, B, C, K |
| 376300-Mains - Plastic | 900377 | 3303L | Repl w/ 978F 2-4P Big Bend | 201509 | (250.19) | a | A, B, C, K |
| 376300-Mains - Plastic | 900379 | 3303L | Inst 783F 4P & 529F 2POld Bonhomme | 201509 | (10.51) | a | A, B, C, K |
| 376300-Mains - Plastic | 900388 | 3303L | Repl w/ 332F 2P Tay Rd | 201509 | (8.12) | a | A, B, C, K |
| 376300-Mains - Plastic | 900390 | 3303L | Inst 205F 1 1/4P Gore | 201509 | (0.47) | a | A, B, C, K |
| 376300-Mains - Plastic | 900392 | 3303L | Inst 580F 4P & 255F 2P Ferguson | 201509 | (0.09) | a | A, B, C, K |
| 376300-Mains - Plastic | 900415 | 3303L | Repl w/ 1093F 2P Princeton | 201509 | (4.11) | a | A, B, C, K |
| 376300-Mains - Plastic | 900420 | 3303L | Repl w/ 520F 2P Oregon | 201509 | (14.76) | a | A, B, C, K |
| 376300-Mains - Plastic | 900423 | 3303L | Repl w/ 1373F 2P Dr MLK | 201509 | (0.04) | a | A, B, C, K |
| 376300-Mains - Plastic | 900430 | 3303L | Repl w/ 654F 2P Maurice | 201509 | (1.31) | a | A, B, C, K |
| 376300-Mains - Plastic | 900432 | 3303L | Repl w/ 503F 2P Gravois | 201509 | (6.62) | a | A, B, C, K |
| 376300-Mains - Plastic | 900462 | 3303L | Repl w/ 2240F 2P Walnut Park Ph4G | 201509 | (448.53) | a | A, B, C, K |
| 376300-Mains - Plastic | 900463 | 3303L | Inst 4082F 2P Walnut Park Ph4H | 201509 | (1.93) | a | A, B, C, K |
| 376300-Mains - Plastic | 900464 | 3303L | Inst 4741F 2PWalnut Park Ph 4I | 201509 | (210.42) | a | A, B, C, K |

| | | | | | | | |
|------------------------|--------|-------|-------------------------------------|--------|-------------|---|------------|
| 376300-Mains - Plastic | 900557 | 3303L | Inst 2123F 2P Walnut Park Ph6A | 201509 | (3,228.70) | a | A, B, C, K |
| 376300-Mains - Plastic | 900559 | 3303L | Inst 3875F 2P Walnut Park Ph6C | 201509 | (3,138.92) | a | A, B, C, K |
| 376300-Mains - Plastic | 900559 | 3303L | Inst 3875F 2P Walnut Park Ph6C | 201510 | (301.23) | a | A, B, C, K |
| 376300-Mains - Plastic | 900559 | 3303L | Inst 3875F 2P Walnut Park Ph6C | 201511 | 2,620.23 | a | A, B, C, K |
| 376300-Mains - Plastic | 900559 | 3303L | Inst 3875F 2P Walnut Park Ph6C | 201512 | 524.81 | a | A, B, C, K |
| 376300-Mains - Plastic | 900581 | 3303L | Repl w/ 6270F 2P Walnut Park Ph6E | 201511 | 235,678.12 | a | A, B, C, K |
| 376300-Mains - Plastic | 900581 | 3303L | Repl w/ 6270F 2P Walnut Park Ph6E | 201512 | 20.18 | a | A, B, C, K |
| 376300-Mains - Plastic | 900623 | 3303L | Repl w/ 2852' 2P Wydown Ph 6 | 201509 | 347.05 | a | A, B, C, K |
| 376100-Mains - Steel | 900633 | 3403L | Rel w/ 321F 4S 2S Progress Parkway | 201509 | 69.23 | a | A, B, C, K |
| 376100-Mains - Steel | 900633 | 3403L | Rel w/ 321F 4S 2S Progress Parkway | 201510 | (21.24) | a | A, B, C, K |
| 376300-Mains - Plastic | 900643 | 3304L | Inst 1801F 6P-12P Marmaduke/Hudler | 201509 | 3,004.32 | a | A, B, C, K |
| 376300-Mains - Plastic | 900643 | 3304L | Inst 1801F 6P-12P Marmaduke/Hudler | 201510 | 0.46 | a | A, B, C, K |
| 376300-Mains - Plastic | 900650 | 3303L | Inst 3290F 2P St Louis Hills Ph1A | 201512 | 163,168.27 | a | A, B, C, K |
| 376300-Mains - Plastic | 900652 | 3303L | Inst 4435F 2P St Louis Hills Ph1B | 201509 | (2,688.21) | a | A, B, C, K |
| 376300-Mains - Plastic | 900652 | 3303L | Inst 4435F 2P St Louis Hills Ph1B | 201511 | 2,450.79 | a | A, B, C, K |
| 376300-Mains - Plastic | 900653 | 3303L | Inst 2636F 2P St Louis Hills Ph1C | 201509 | (1,110.82) | a | A, B, C, K |
| 376300-Mains - Plastic | 900653 | 3303L | Inst 2636F 2P St Louis Hills Ph1C | 201510 | 113.69 | a | A, B, C, K |
| 376300-Mains - Plastic | 900653 | 3303L | Inst 2636F 2P St Louis Hills Ph1C | 201511 | 5,428.80 | a | A, B, C, K |
| 376300-Mains - Plastic | 900653 | 3303L | Inst 2636F 2P St Louis Hills Ph1C | 201512 | 3.58 | a | A, B, C, K |
| 376300-Mains - Plastic | 900670 | 3403L | Rel w/ 400F 6P Vogel Rd | 201509 | (3,400.72) | a | A, B, C, K |
| 376300-Mains - Plastic | 900679 | 3303L | Inst 2312F 4P Cole & 18th PhB | 201511 | 12,896.70 | a | A, B, C, K |
| 376300-Mains - Plastic | 900681 | 3303L | Inst 1637F 2P Cole & 18th Ph C | 201509 | 20,971.99 | a | A, B, C, K |
| 376300-Mains - Plastic | 900683 | 3303L | Inst 1864F 2P Cole & 18th Ph D | 201509 | 30,596.05 | a | A, B, C, K |
| 376300-Mains - Plastic | 900683 | 3303L | Inst 1864F 2P Cole & 18th Ph D | 201510 | 14.69 | a | A, B, C, K |
| 376300-Mains - Plastic | 900683 | 3303L | Inst 1864F 2P Cole & 18th Ph D | 201511 | (0.01) | a | A, B, C, K |
| 376300-Mains - Plastic | 900683 | 3303L | Inst 1864F 2P Cole & 18th Ph D | 201512 | 0.48 | a | A, B, C, K |
| 376300-Mains - Plastic | 900685 | 3303L | Inst 1550F 2P Cole & 18th PhE | 201509 | 11,433.79 | a | A, B, C, K |
| 376300-Mains - Plastic | 900685 | 3303L | Inst 1550F 2P Cole & 18th PhE | 201510 | 15.45 | a | A, B, C, K |
| 376300-Mains - Plastic | 900685 | 3303L | Inst 1550F 2P Cole & 18th PhE | 201511 | (0.02) | a | A, B, C, K |
| 376300-Mains - Plastic | 900685 | 3303L | Inst 1550F 2P Cole & 18th PhE | 201512 | 0.52 | a | A, B, C, K |
| 376300-Mains - Plastic | 900687 | 3303L | Inst 1096F 2P Cole & 18th PhF | 201509 | 9,530.10 | a | A, B, C, K |
| 376300-Mains - Plastic | 900689 | 3303L | Inst 2434F 2P Cole & 18th PhG | 201509 | 15,057.72 | a | A, B, C, K |
| 376300-Mains - Plastic | 900689 | 3303L | Inst 2434F 2P Cole & 18th PhG | 201510 | (32.36) | a | A, B, C, K |
| 376300-Mains - Plastic | 900689 | 3303L | Inst 2434F 2P Cole & 18th PhG | 201511 | 0.06 | a | A, B, C, K |
| 376300-Mains - Plastic | 900689 | 3303L | Inst 2434F 2P Cole & 18th PhG | 201512 | (7.82) | a | A, B, C, K |
| 376300-Mains - Plastic | 900723 | 3403L | Rel w/ 3350F 2P Valley Park | 201509 | 1.37 | a | A, B, C, K |
| 376300-Mains - Plastic | 900730 | 3403L | Rel w/ 310F 2P Bramblett | 201509 | (167.78) | a | A, B, C, K |
| 376300-Mains - Plastic | 900730 | 3403L | Rel w/ 310F 2P Bramblett | 201510 | (0.39) | a | A, B, C, K |
| 376300-Mains - Plastic | 900734 | 3303L | Repl w/ 1717F 2P Hurck | 201509 | (2,232.41) | a | A, B, C, K |
| 376300-Mains - Plastic | 900734 | 3303L | Repl w/ 1717F 2P Hurck | 201510 | 17.27 | a | A, B, C, K |
| 376300-Mains - Plastic | 900734 | 3303L | Repl w/ 1717F 2P Hurck | 201511 | 994.93 | a | A, B, C, K |
| 376300-Mains - Plastic | 900734 | 3303L | Repl w/ 1717F 2P Hurck | 201512 | 83.23 | a | A, B, C, K |
| 376300-Mains - Plastic | 900738 | 3303L | Repl w/ 780F 2P Kingsland MSD | 201509 | (1,251.62) | a | A, B, C, K |
| 376300-Mains - Plastic | 900738 | 3303L | Repl w/ 780F 2P Kingsland MSD | 201511 | 194.36 | a | A, B, C, K |
| 376300-Mains - Plastic | 900738 | 3303L | Repl w/ 780F 2P Kingsland MSD | 201512 | 17.14 | a | A, B, C, K |
| 376300-Mains - Plastic | 900759 | 3303L | Repl w/ 2836F 2P Hickory Dale | 201509 | (64,448.48) | a | A, B, C, K |
| 376300-Mains - Plastic | 900759 | 3303L | Repl w/ 2836F 2P Hickory Dale | 201510 | 11.48 | a | A, B, C, K |
| 376300-Mains - Plastic | 900762 | 3303L | Inst 2069F 2P Earthquake Zone Ph1A | 201509 | (90.58) | a | A, B, C, K |
| 376300-Mains - Plastic | 900763 | 3303L | Inst 3508F 2P Earthquake Zone Ph1B | 201509 | 143,475.06 | a | A, B, C, K |
| 376300-Mains - Plastic | 900764 | 3303L | Repl w/758F 2P Earthquake Zone Ph1C | 201509 | 11,272.00 | a | A, B, C, K |

| | | | | | | | |
|------------------------|--------|-------|-------------------------------------|--------|--------------|---|---------------|
| 376300-Mains - Plastic | 900764 | 3303L | Repl w/758F 2P Earthquake Zone Ph1C | 201510 | 4.15 | a | A, B, C, K |
| 376300-Mains - Plastic | 900765 | 3303L | Inst 1899F 4P Earthquake Zone Ph1D | 201509 | 40,343.95 | a | A, B, C, K |
| 376300-Mains - Plastic | 900775 | 3403L | Rel w/ 1535F 2P Page&Hodiamont AOR | 201509 | (567.54) | a | A, B, C, K |
| 376300-Mains - Plastic | 900822 | 3403L | Rel w/ 130F 6S Price Road | 201509 | (726.74) | a | A, B, C, K |
| 376300-Mains - Plastic | 900841 | 340RL | Rel w/ 57F 4P Ashland AOR | 201509 | (85.78) | a | A, B, C, F, K |
| 376300-Mains - Plastic | 900848 | 340RL | Rel w/ 810F 4P Bircher & Newstead | 201509 | (880.86) | a | A, B, C, K |
| 376300-Mains - Plastic | 900859 | 3303L | Repl w/ 290F 2P Cabanne | 201509 | (577.52) | a | A, B, C, K |
| 376300-Mains - Plastic | 900859 | 3303L | Repl w/ 290F 2P Cabanne | 201510 | 6.99 | a | A, B, C, K |
| 376300-Mains - Plastic | 900861 | 3303L | Repl w/ 105F 4P McLaran | 201509 | (32.91) | a | A, B, C, K |
| 376300-Mains - Plastic | 900862 | 3303L | Rep w/ 4552F 2P Broadway AOR | 201509 | (32,613.27) | a | A, B, C, F, K |
| 376300-Mains - Plastic | 900862 | 3303L | Repl w/ 4552F 2P Broadway AOR | 201510 | (14.29) | a | A, B, C, F, K |
| 376300-Mains - Plastic | 900862 | 3303L | Repl w/ 4552F 2P Broadway AOR | 201511 | 0.02 | a | A, B, C, F, K |
| 376300-Mains - Plastic | 900862 | 3303L | Repl w/ 4552F 2P Broadway AOR | 201512 | (0.97) | a | A, B, C, F, K |
| 376300-Mains - Plastic | 900871 | 3303L | Repl w/ 3201F 2P Baden Ph6F | 201512 | 123,314.47 | a | A, B, C, K |
| 376300-Mains - Plastic | 900876 | 3303L | Repl w/ 1060F 2P Rauschenbach PVC | 201509 | (660.31) | a | A, B, C, K |
| 376300-Mains - Plastic | 900876 | 3303L | Repl w/ 1060F 2P Rauschenbach PVC | 201510 | 453.39 | a | A, B, C, K |
| 376300-Mains - Plastic | 900876 | 3303L | Repl w/ 1060F 2P Rauschenbach PVC | 201511 | (0.34) | a | A, B, C, K |
| 376300-Mains - Plastic | 900876 | 3303L | Repl w/ 1060F 2P Rauschenbach PVC | 201512 | (4,356.04) | a | A, B, C, K |
| 376300-Mains - Plastic | 900890 | 3303L | Repl w/ 2218F 2P Russell & Flora | 201509 | (102,284.82) | a | A, B, C, K |
| 376300-Mains - Plastic | 900890 | 3303L | Repl w/ 2218F 2P Russell & Flora | 201510 | 53.95 | a | A, B, C, K |
| 376100-Mains - Steel | 900892 | 3403L | Rel w/ 180F 2S Elaine Drive | 201509 | (100.57) | a | A, B, C, K |
| 376300-Mains - Plastic | 900893 | 3303L | Repl w/ 2486F 6P Arlington | 201509 | (469.56) | a | A, B, C, K |
| 376300-Mains - Plastic | 900893 | 3303L | Repl w/ 2486F 6P Arlington | 201511 | (76.45) | a | A, B, C, K |
| 376300-Mains - Plastic | 900893 | 3303L | Repl w/ 2486F 6P Arlington | 201512 | (109.51) | a | A, B, C, K |
| 376300-Mains - Plastic | 900895 | 3303L | Repl w/ 828F 2P Marquette | 201509 | (64,879.04) | a | A, B, C, K |
| 376300-Mains - Plastic | 900895 | 3303L | Repl w/ 828F 2P Marquette | 201510 | (6.31) | a | A, B, C, K |
| 376300-Mains - Plastic | 900895 | 3303L | Repl w/ 828F 2P Marquette | 201512 | (0.82) | a | A, B, C, K |
| 376300-Mains - Plastic | 900896 | 3303L | Repl w/ 2990F 2P 4P Maple | 201509 | (1,333.98) | a | A, B, C, K |
| 376300-Mains - Plastic | 900896 | 3303L | Repl w/ 2990F 2P 4P Maple | 201510 | 149.08 | a | A, B, C, K |
| 376300-Mains - Plastic | 900896 | 3303L | Repl w/ 2990F 2P 4P Maple | 201511 | 1,032.84 | a | A, B, C, K |
| 376300-Mains - Plastic | 900896 | 3303L | Repl w/ 2990F 2P 4P Maple | 201512 | (144.91) | a | A, B, C, K |
| 376300-Mains - Plastic | 900897 | 3303L | Repl w/ 587F 2P Syracuse | 201509 | 1,441.88 | a | A, B, C, K |
| 376300-Mains - Plastic | 900897 | 3303L | Repl w/ 587F 2P Syracuse | 201511 | 657.62 | a | A, B, C, K |
| 376300-Mains - Plastic | 900897 | 3303L | Repl w/ 587F 2P Syracuse | 201512 | (162.03) | a | A, B, C, K |
| 376300-Mains - Plastic | 900898 | 3303L | Repl w/ 1220F 2P Ohio | 201509 | (13,628.71) | a | A, B, C, K |
| 376300-Mains - Plastic | 900898 | 3303L | Repl w/ 1220F 2P Ohio | 201510 | (2.13) | a | A, B, C, K |
| 376300-Mains - Plastic | 900900 | 3303L | Repl w/ 1075F 2P Washington | 201509 | 3,602.99 | a | A, B, C, K |
| 376300-Mains - Plastic | 900900 | 3303L | Repl w/ 1075F 2P Washington | 201510 | 26.89 | a | A, B, C, K |
| 376300-Mains - Plastic | 900902 | 3303L | Repl w/ 530' 2P Oakland | 201509 | (234.17) | a | A, B, C, K |
| 376300-Mains - Plastic | 900902 | 3303L | Repl w/ 530' 2P Oakland | 201510 | (63.69) | a | A, B, C, K |
| 376300-Mains - Plastic | 900905 | 3303L | Repl w/ 806F 2P Utah | 201509 | (4,938.82) | a | A, B, C, K |
| 376300-Mains - Plastic | 900905 | 3303L | Repl w/ 806F 2P Utah | 201510 | 7.97 | a | A, B, C, K |
| 376300-Mains - Plastic | 900908 | 3303L | Repl w/ 460F 2P California | 201509 | (455.99) | a | A, B, C, K |
| 376300-Mains - Plastic | 900908 | 3303L | Repl w/ 460F 2P California | 201510 | 6.41 | a | A, B, C, K |
| 376300-Mains - Plastic | 900911 | 3403L | Rel w/ 300F 2P Edgewood | 201509 | 0.10 | a | A, B, C, K |
| 376300-Mains - Plastic | 900912 | 3303L | Repl w/ 745F 2P Shaw | 201509 | (1,496.97) | a | A, B, C, K |
| 376300-Mains - Plastic | 900912 | 3303L | Repl w/ 745F 2P Shaw | 201510 | 34.85 | a | A, B, C, K |
| 376300-Mains - Plastic | 900921 | 3303L | Repl w/ 2457F 4P&2P Flad AOR | 201509 | (2,176.86) | a | A, B, C, F, K |
| 376300-Mains - Plastic | 900921 | 3303L | Repl w/ 2457F 4P&2P Flad AOR | 201510 | 8,340.17 | a | A, B, C, F, K |
| 376300-Mains - Plastic | 900948 | 3303L | Repl w/ 132F 2P Southcote | 201509 | 822.96 | a | A, B, C, K |
| 376300-Mains - Plastic | 900948 | 3303L | Repl w/ 132F 2P Southcote | 201510 | 0.60 | a | A, B, C, K |

| | | | | | | | |
|------------------------|--------|-------|-------------------------------------|--------|-------------|---|---------------|
| 376300-Mains - Plastic | 900961 | 3403L | Rel w/ 190F 2P Clay | 201509 | (26.46) | a | A, B, C, K |
| 376300-Mains - Plastic | 900977 | 3303L | Repl w/ 1291F 4P Boyle | 201509 | 29.11 | a | A, B, C, K |
| 376300-Mains - Plastic | 900986 | 3303L | Repl w/ 2189F 2P Earthquake Zone 2A | 201509 | (33,510.61) | a | A, B, C, K |
| 376300-Mains - Plastic | 900986 | 3303L | Repl w/ 2189F 2P Earthquake Zone 2A | 201510 | (58.62) | a | A, B, C, K |
| 376300-Mains - Plastic | 900988 | 3303L | Repl w/ 3840F 2P Earthquake Zn Ph2B | 201509 | 130,921.07 | a | A, B, C, K |
| 376300-Mains - Plastic | 900988 | 3303L | Repl w/ 3840F 2P Earthquake Zn Ph2B | 201510 | 207.36 | a | A, B, C, K |
| 376300-Mains - Plastic | 900988 | 3303L | Repl w/ 3840F 2P Earthquake Zn Ph2B | 201511 | (918.56) | a | A, B, C, K |
| 376300-Mains - Plastic | 900988 | 3303L | Repl w/ 3840F 2P Earthquake Zn Ph2B | 201512 | 18.09 | a | A, B, C, K |
| 376300-Mains - Plastic | 900993 | 3303L | Repl w/ 2220F 2P CentralWestEndPh1G | 201511 | 844.95 | a | A, B, C, K |
| 376300-Mains - Plastic | 901011 | 340RL | Rel w/ 450F 4P Sanford AOR | 201509 | 11,350.40 | a | A, B, C, F, K |
| 376300-Mains - Plastic | 901011 | 340RL | Rel w/ 450F 4P Sanford AOR | 201510 | (35.57) | a | A, B, C, F, K |
| 376300-Mains - Plastic | 901015 | 340RL | Rel w/ 35F 4P Eimbank & Taylor AOR | 201509 | (1,019.70) | a | A, B, C, F, K |
| 376100-Mains - Steel | 901019 | 3403L | Rel w/ 80F 6S Fee Fee | 201509 | (22.70) | a | A, B, C, K |
| 376100-Mains - Steel | 901019 | 3403L | Rel w/ 80F 6S Fee Fee | 201510 | (26.98) | a | A, B, C, K |
| 376300-Mains - Plastic | 901022 | 3403L | Rel w/ 427F 2P Valley Park SE | 201509 | (506.70) | a | A, B, C, K |
| 376300-Mains - Plastic | 901040 | 3303L | Repl w/ 315F 2P Amherst Ave | 201509 | (296.05) | a | A, B, C, K |
| 376300-Mains - Plastic | 901059 | 3303L | Repl w/ 680' 2P Gregg | 201509 | 36,205.77 | a | A, B, C, K |
| 376300-Mains - Plastic | 901059 | 3303L | Repl w/ 680' 2P Gregg | 201510 | 729.87 | a | A, B, C, K |
| 376300-Mains - Plastic | 901059 | 3303L | Repl w/ 680' 2P Gregg | 201511 | (495.83) | a | A, B, C, K |
| 376300-Mains - Plastic | 901059 | 3303L | Repl w/ 680' 2P Gregg | 201512 | 17.41 | a | A, B, C, K |
| 376300-Mains - Plastic | 901063 | 340RL | Rel w/ 1307F 4P Bessie AOR | 201509 | 86,750.41 | a | A, B, C, F, K |
| 376300-Mains - Plastic | 901063 | 340RL | Rel w/ 1307F 4P Bessie AOR | 201510 | 211.04 | a | A, B, C, F, K |
| 376300-Mains - Plastic | 901063 | 340RL | Rel w/ 1307F 4P Bessie AOR | 201511 | 4,342.54 | a | A, B, C, F, K |
| 376300-Mains - Plastic | 901063 | 340RL | Rel w/ 1307F 4P Bessie AOR | 201512 | 19.15 | a | A, B, C, F, K |
| 376300-Mains - Plastic | 901071 | 3403L | Rel w/ 285F 2P Froesel Ph2 | 201509 | (28.80) | a | A, B, C, K |
| 376300-Mains - Plastic | 901071 | 3403L | Rel w/ 285F 2P Froesel Ph2 | 201511 | 18.46 | a | A, B, C, K |
| 376300-Mains - Plastic | 901071 | 3403L | Rel w/ 285F 2P Froesel Ph2 | 201512 | (3.72) | a | A, B, C, K |
| 376300-Mains - Plastic | 901081 | 3403L | Rel w/ 970F 6P Pralle Lane | 201512 | 7,738.91 | a | A, B, C, K |
| 376300-Mains - Plastic | 901088 | 3303L | Repl w/ 4597F 2P U-City Ph1B | 201512 | 127,254.14 | a | A, B, C, K |
| 376300-Mains - Plastic | 901106 | 3403L | Rel w/ 38F 4P Compton AOR | 201509 | (53.56) | a | A, B, C, F, K |
| 376300-Mains - Plastic | 901106 | 3403L | Rel w/ 38F 4P Compton AOR | 201511 | 50.94 | a | A, B, C, F, K |
| 376300-Mains - Plastic | 901106 | 3403L | Rel w/ 38F 4P Compton AOR | 201512 | 59.77 | a | A, B, C, F, K |
| 376300-Mains - Plastic | 901107 | 3403L | Rel w/ 62F 4P Southwest AOR | 201509 | (112.98) | a | A, B, C, F, K |
| 376300-Mains - Plastic | 901107 | 3403L | Rel w/ 62F 4P Southwest AOR | 201511 | 74.23 | a | A, B, C, F, K |
| 376300-Mains - Plastic | 901107 | 3403L | Rel w/ 62F 4P Southwest AOR | 201512 | (57.92) | a | A, B, C, F, K |
| 376300-Mains - Plastic | 901111 | 3303L | Repl w/ 955F 2P Hickory | 201509 | 39,837.13 | a | A, B, C, K |
| 376300-Mains - Plastic | 901111 | 3303L | Repl w/ 955F 2P Hickory | 201510 | 2,993.07 | a | A, B, C, K |
| 376300-Mains - Plastic | 901111 | 3303L | Repl w/ 955F 2P Hickory | 201511 | (587.87) | a | A, B, C, K |
| 376300-Mains - Plastic | 901111 | 3303L | Repl w/ 955F 2P Hickory | 201512 | 57.72 | a | A, B, C, K |
| 376300-Mains - Plastic | 901114 | 3303L | Repl w/ 1630F 2P Maffitt | 201512 | 43,124.45 | a | A, B, C, K |
| 376300-Mains - Plastic | 901139 | 3303L | Repl w/ 901F 2P Suburban Ave | 201509 | 7,283.29 | a | A, B, C, K |
| 376300-Mains - Plastic | 901139 | 3303L | Repl w/ 901F 2P Suburban Ave | 201510 | 1,543.49 | a | A, B, C, K |
| 376300-Mains - Plastic | 901139 | 3303L | Repl w/ 901F 2P Suburban Ave | 201511 | (46.49) | a | A, B, C, K |
| 376300-Mains - Plastic | 901139 | 3303L | Repl w/ 901F 2P Suburban Ave | 201512 | (0.94) | a | A, B, C, K |
| 376300-Mains - Plastic | 901162 | 3303L | Repl w/ 210F 2P St. Leonard Ct. | 201512 | 18,186.66 | a | A, B, C, K |
| 376300-Mains - Plastic | 901173 | 3403L | Vandeventer - City of St. Louis MRE | 201509 | (26.91) | a | A, B, C, K |
| 376300-Mains - Plastic | 901173 | 3403L | Rel w/ 260F 6P Vandeventer | 201511 | (20.90) | a | A, B, C, K |
| 376300-Mains - Plastic | 901173 | 3403L | Rel w/ 260F 6P Vandeventer | 201512 | 0.52 | a | A, B, C, K |
| 376300-Mains - Plastic | 901178 | 3303L | Repl w/ 185F 2P Evans | 201509 | 4,324.10 | a | A, B, C, K |
| 376300-Mains - Plastic | 901178 | 3303L | Repl w/ 185F 2P Evans | 201510 | 333.31 | a | A, B, C, K |

| | | | | | | | |
|------------------------|--------|-------|------------------------------|--------|--------|---|---------------|
| 376300-Mains - Plastic | 901178 | 3303L | Repl w/ 185F 2P Evans | 201511 | (0.34) | a | A, B, C, K |
| 376300-Mains - Plastic | 901178 | 3303L | Repl w/ 185F 2P Evans | 201512 | 12.67 | a | A, B, C, K |
| 376300-Mains - Plastic | | 3303L | SERVICE TRANSFER WORK ORDERS | 201601 | | a | A, B, C, K |
| 376300-Mains - Plastic | | 3303L | SERVICE TRANSFER WORK ORDERS | 201602 | | a | A, B, C, F, K |

TOTAL 1,634,215.10

ACCOUNT 37620 MAINS CAST IRON LEAK CLAMPS

| PLANT ACCOUNT | WORK ORDER | BUDGET PROJECT | DESCRIPTION | IN SERVICE DATE | ADDITION AMOUNT | | |
|--------------------------|------------|----------------|--------------------------|-----------------|-----------------|---|------------|
| 376200-Mains - Cast Iron | 699010 | 3503L | 69901 MN LEAK CLAMPS CTY | 201509 | 134,905.03 | b | A, B, I, K |
| 376200-Mains - Cast Iron | 699010 | 3503L | 69901 MN LEAK CLAMPS CTY | 201510 | 162,185.59 | b | A, B, I, K |
| 376200-Mains - Cast Iron | 699010 | 3503L | 69901 MN LEAK CLAMPS CTY | 201511 | 136,594.06 | b | A, B, I, K |
| 376200-Mains - Cast Iron | 699010 | 3503L | 69901 MN LEAK CLAMPS CTY | 201512 | 169,339.75 | b | A, B, I, K |
| 376200-Mains - Cast Iron | 699510 | 3503L | 69951 MN LEAK CLAMPS CO | 201509 | 6,396.44 | b | A, B, I, K |
| 376200-Mains - Cast Iron | 699510 | 3503L | 69951 MN LEAK CLAMPS CO | 201510 | 4,785.10 | b | A, B, I, K |
| 376200-Mains - Cast Iron | 699510 | 3503L | 69951 MN LEAK CLAMPS CO | 201511 | 261.37 | b | A, B, I, K |
| 376200-Mains - Cast Iron | 699510 | 3503L | 69951 MN LEAK CLAMPS CO | 201512 | 51.71 | b | A, B, I, K |
| 376200-Mains - Cast Iron | | 3503L | Mains Clamping | 201601 | 170,000.00 | b | A, B, I, K |
| 376200-Mains - Cast Iron | | 3503L | Mains Clamping | 201602 | 170,000.00 | b | A, B, I, K |

TOTAL 954,519.05

ACCOUNT 37670 MAINS CATHODIC PROTECTION

| PLANT ACCOUNT | WORK ORDER | BUDGET PROJECT | DESCRIPTION | IN SERVICE DATE | ADDITION AMOUNT | | |
|----------------------|------------|----------------|--|-----------------|-----------------|---|---------|
| 376100-Mains - Steel | 697390 | 3501M | 69739 CATHODIC PROT MAIN | 201509 | 4,902.32 | b | A, B, K |
| 376100-Mains - Steel | 697390 | 3501M | 69739 CATHODIC PROT MAIN | 201510 | 2,129.19 | b | A, B, K |
| 376100-Mains - Steel | 697390 | 3501M | 69739 CATHODIC PROT MAIN | 201511 | 2,667.94 | b | A, B, K |
| 376100-Mains - Steel | 697390 | 3501M | 69739 CATHODIC PROT MAIN | 201512 | 350.93 | b | A, B, K |
| 376100-Mains - Steel | | 3503L | ACCOUNT 37670 MAINS CATHODIC PROTECTIO | 201601 | 2,500.00 | b | A, B, K |
| 376100-Mains - Steel | | 3503L | ACCOUNT 37670 MAINS CATHODIC PROTECTIO | 201602 | 2,500.00 | b | A, B, K |

TOTAL 15,050.38

Total Main Replacements and Other Projects Extending Useful Life of Mains

18,933,736.40

SERVICE LINE REPLACEMENTS AND INSERTION PROJECTS - ADDITIONS

ACCOUNT 38010 SERVICES STEEL

| PLANT ACCOUNT | WORK ORDER | BUDGET PROJECT | DESCRIPTION | IN SERVICE DATE | ADDITION AMOUNT | | |
|-------------------------|------------|----------------|--------------------------|-----------------|-----------------|---|------------|
| 380100-Services - Steel | 695160 | | 69516 SVC RENEW STEEL SO | 201509 | 81,095.87 | a | A, B, C, K |
| 380100-Services - Steel | 695160 | | 69516 SVC RENEW STEEL SO | 201510 | 76,786.45 | a | A, B, C, K |
| 380100-Services - Steel | 695160 | | 69516 SVC RENEW STEEL SO | 201511 | 17,413.27 | a | A, B, C, K |
| 380100-Services - Steel | 695160 | | 69516 SVC RENEW STEEL SO | 201512 | 68,965.64 | a | A, B, C, K |
| 380100-Services - Steel | 695660 | | 69566 SVC RENEW STEEL NO | 201509 | (783.38) | a | A, B, C, K |
| 380100-Services - Steel | 696300 | | 69630 SVC RENEW STEEL MW | 201509 | (2,060.69) | a | A, B, C, K |

| | | | | | | | |
|-------------------------|--------|--|-----------------------------------|--------|-------------|---|---------------|
| 380100-Services - Steel | 697300 | | 69730 SVC RENEW STEEL MN | 201509 | 4,477.72 | a | A, B, C, K |
| 380100-Services - Steel | 697300 | | 69730 SVC RENEW STEEL MN | 201511 | 10,376.31 | a | A, B, C, K |
| 380100-Services - Steel | 697300 | | 69730 SVC RENEW STEEL MN | 201512 | (1,623.36) | a | A, B, C, K |
| 380100-Services - Steel | 698300 | | 69830 SVC RENEW STEEL SC | 201509 | 7,544.20 | a | A, B, C, K |
| 380100-Services - Steel | 698300 | | 69830 SVC RENEW STEEL SC | 201511 | (221.28) | a | A, B, C, K |
| 380100-Services - Steel | 698300 | | 69830 SVC RENEW STEEL SC | 201512 | 3.19 | a | A, B, C, K |
| 380100-Services - Steel | 699160 | | 69916 SVC RENEW STEEL C | 201509 | 73,559.19 | a | A, B, C, K |
| 380100-Services - Steel | 699160 | | 69916 SVC RENEW STEEL C | 201510 | 64,801.56 | a | A, B, C, K |
| 380100-Services - Steel | 699160 | | 69916 SVC RENEW STEEL C | 201511 | 32,210.34 | a | A, B, C, K |
| 380100-Services - Steel | 699160 | | 69916 SVC RENEW STEEL C | 201512 | 30,000.85 | a | A, B, C, K |
| 380100-Services - Steel | 900266 | | Inst 4640F 2P Baden Ph 5C | 201509 | (0.04) | a | A, B, C, K |
| 380100-Services - Steel | 900266 | | Inst 4640F 2P Baden Ph 5C | 201510 | 0.16 | a | A, B, C, K |
| 380100-Services - Steel | 900266 | | Inst 4640F 2P Baden Ph 5C | 201511 | (0.01) | a | A, B, C, K |
| 380100-Services - Steel | 900266 | | Inst 4640F 2P Baden Ph 5C | 201512 | 0.79 | a | A, B, C, K |
| 380100-Services - Steel | 900279 | | Repl w/ 3345F 2P Walnut Park Ph4D | 201509 | (33.39) | a | A, B, C, K |
| 380100-Services - Steel | 900892 | | Rel w/ 180F 2S Elaine Drive | 201509 | (163.70) | a | A, B, C, K |
| 380100-Services - Steel | 900900 | | Repl w/ 1075F 2P Washington | 201509 | 7,104.30 | a | A, B, C, K |
| 380100-Services - Steel | 900900 | | Repl w/ 1075F 2P Washington | 201510 | 3.20 | a | A, B, C, K |
| 380100-Services - Steel | 901011 | | Rel w/ 450F 4P Sanford AOR | 201509 | (15,149.95) | a | A, B, C, F, K |
| 380100-Services - Steel | | | ACCOUNT:38010 SERVICES STEEL | 201601 | | a | A, B, C, K |
| 380100-Services - Steel | | | ACCOUNT:38010 SERVICES STEEL | 201602 | | a | A, B, C, K |

TOTAL 454,307.24

ACCOUNT 38020 SERVICES PLASTIC & COPPER

| PLANT ACCOUNT | WORK ORDER | BUDGET PROJECT | DESCRIPTION | IN SERVICE DATE | ADDITION AMOUNT | | |
|------------------------------------|------------|----------------|------------------------------|-----------------|-----------------|---|------------|
| 380200-Services - Plastic & Copper | 694250 | | 69425 SVC RNW PLS 5/8IN | 201509 | 2,847.96 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 694370 | | 69437 SVCS RENEW PLS 5/4-2IN | 201509 | 38.10 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 695300 | | 69530 SVC REN 1/2 PL SO | 201509 | 1,015,583.28 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 695300 | | 69530 SVC REN 1/2 PL SO | 201510 | 819,355.35 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 695300 | | 69530 SVC REN 1/2 PL SO | 201511 | 699,429.55 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 695300 | | 69530 SVC REN 1/2 PL SO | 201512 | 778,786.74 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 695310 | | 69531 SV REN 1IN PL SO | 201509 | (8,796.56) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 695310 | | 69531 SV REN 1IN PL SO | 201510 | 64,389.29 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 695310 | | 69531 SV REN 1IN PL SO | 201511 | 25,419.91 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 695310 | | 69531 SV REN 1IN PL SO | 201512 | 49,459.64 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 695320 | | 69532 SV REN 1 1/4 PL SO | 201509 | (1,131.57) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 695320 | | 69532 SV REN 1 1/4 PL SO | 201510 | (6,258.83) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 695320 | | 69532 SV REN 1 1/4 PL SO | 201512 | 5,351.42 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 695330 | | 69533 SV REN 2&OVR PL SO | 201509 | (457.46) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 695330 | | 69533 SV REN 2&OVR PL SO | 201511 | (2,037.82) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 695330 | | 69533 SV REN 2&OVR PL SO | 201512 | 9.97 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 695800 | | 69580 SVC REN 1/2 PL NO | 201509 | 14,906.84 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 695800 | | 69580 SVC REN 1/2 PL NO | 201510 | 59,569.83 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 695800 | | 69580 SVC REN 1/2 PL NO | 201511 | 28,817.24 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 695800 | | 69580 SVC REN 1/2 PL NO | 201512 | 62,661.33 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 695810 | | 69581 SV REN 1IN PL NO | 201509 | (1,610.04) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 695810 | | 69581 SV REN 1IN PL NO | 201510 | 12,462.83 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 695810 | | 69581 SV REN 1IN PL NO | 201511 | 17,438.35 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 695810 | | 69581 SV REN 1IN PL NO | 201512 | 2,691.06 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 695820 | | 69582 SV REN 1 1/4 PL NO | 201509 | (5,057.09) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 695820 | | 69582 SV REN 1 1/4 PL NO | 201510 | 23,290.43 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 695820 | | 69582 SV REN 1 1/4 PL NO | 201511 | 765.11 | a | A, B, C, K |

| | | | | | | |
|------------------------------------|--------|--------------------------------|--------|------------|---|------------|
| 380200-Services - Plastic & Copper | 695820 | 69582 SV REN 1 1/4 PL NO | 201512 | 379.80 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 695830 | 69583 SV REN 2&OVR PL NO | 201509 | (123.77) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 695830 | 69583 SV REN 2&OVR PL NO | 201511 | (2,937.13) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 695830 | 69583 SV REN 2&OVR PL NO | 201512 | 2,406.75 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 695840 | 69584 RNW COPPER SVCS-NORTH | 201509 | (563.97) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 696400 | 69640 SVC REN COR TRFR MIDW | 201509 | (10.30) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 696400 | 69640 SVC REN COR TRFR MIDW | 201510 | (154.25) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 696400 | 69640 SVC REN COR TRFR MIDW | 201511 | (4.88) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 696400 | 69640 SVC REN COR TRFR MIDW | 201512 | 0.90 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 696450 | 69645 SVC REN 1/2 PL MW | 201509 | (2,034.80) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 696450 | 69645 SVC REN 1/2 PL MW | 201510 | 6,942.87 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 696450 | 69645 SVC REN 1/2 PL MW | 201511 | 6,015.88 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 696450 | 69645 SVC REN 1/2 PL MW | 201512 | 12,028.49 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 696460 | 69646 SVC REN 1IN PL MW | 201509 | (51.38) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 696470 | 69647 SV REN 1-1/4 PL MW | 201509 | (94.23) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 696480 | 69648 SV REN 2&OVR PL MW | 201509 | 47,782.12 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 696480 | 69648 SV REN 2&OVR PL MW | 201510 | 2,539.45 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 696480 | 69648 SV REN 2&OVR PL MW | 201511 | (4.64) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 696480 | 69648 SV REN 2&OVR PL MW | 201512 | 2,432.22 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 697450 | 69745 SVC REN 1/2 PL MN | 201509 | 16,580.43 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 697450 | 69745 SVC REN 1/2 PL MN | 201510 | 33,691.07 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 697450 | 69745 SVC REN 1/2 PL MN | 201511 | 15,513.72 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 697450 | 69745 SVC REN 1/2 PL MN | 201512 | 43,142.55 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 697460 | 69746 SVC RNW 1IN PL MN | 201509 | (640.69) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 697460 | 69746 SVC RNW 1IN PL MN | 201510 | 50.25 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 697460 | 69746 SVC RNW 1IN PL MN | 201511 | (0.19) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 697460 | 69746 SVC RNW 1IN PL MN | 201512 | 1.76 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 697470 | 69747 SVC RNW 5/4 PL MN | 201509 | (1,192.78) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 697480 | 69748 SVC RNW 2" & OVR MN | 201509 | 587.15 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 697480 | 69748 SVC RNW 2" & OVR MN | 201510 | (1,537.00) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 697480 | 69748 SVC RNW 2" & OVR MN | 201511 | (1,979.00) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 697480 | 69748 SVC RNW 2" & OVR MN | 201512 | 447.00 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 698400 | 69840 SVC RNW COR TRFR STCH | 201509 | (1,067.24) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 698400 | 69840 SVC RNW COR TRFR STCH | 201510 | (7,713.26) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 698400 | 69840 SVC RNW COR TRFR STCH | 201511 | (6,755.26) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 698400 | 69840 SVC RNW COR TRFR STCH | 201512 | (3,236.25) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 698450 | 69845 SVC RNW 1/2 PL SC | 201509 | 87,612.81 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 698450 | 69845 SVC RNW 1/2 PL SC | 201510 | 57,300.46 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 698450 | 69845 SVC RNW 1/2 PL SC | 201511 | 61,747.62 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 698450 | 69845 SVC RNW 1/2 PL SC | 201512 | 62,357.71 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 698460 | 69846 SVC RNW 1IN PL SC | 201509 | (1,223.21) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 698460 | 69846 SVC RNW 1IN PL SC | 201510 | 3,336.74 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 698460 | 69846 SVC RNW 1IN PL SC | 201511 | (425.22) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 698460 | 69846 SVC RNW 1IN PL SC | 201512 | 34.08 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 698470 | 69847 SV RNW 1-1/4 PL SC | 201510 | (486.94) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 698480 | 69848 SV RNW 2&OVR PL SC | 201509 | 38,674.77 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 698480 | 69848 SV RNW 2&OVR PL SC | 201510 | 369.08 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 698480 | 69848 SV RNW 2&OVR PL SC | 201511 | (190.60) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 698480 | 69848 SV RNW 2&OVR PL SC | 201512 | 15.49 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 698500 | 69850 RELAY COPPER SVC- ST CHR | 201509 | (0.79) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 699300 | 69930 SVC REN 1/2 PL CTY | 201509 | 432,940.00 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 699300 | 69930 SVC REN 1/2 PL CTY | 201510 | 434,467.63 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 699300 | 69930 SVC REN 1/2 PL CTY | 201511 | 317,649.33 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 699300 | 69930 SVC REN 1/2 PL CTY | 201512 | 280,160.74 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 699310 | 69931 SVC REN 1IN PL CTY | 201509 | 53,316.64 | a | A, B, C, K |

| | | | | | | |
|------------------------------------|--------|-------------------------------------|--------|--------------|---|------------|
| 380200-Services - Plastic & Copper | 699310 | 69931 SVC REN 1IN PL CTY | 201510 | 83,810.28 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 699310 | 69931 SVC REN 1IN PL CTY | 201511 | 100,483.86 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 699310 | 69931 SVC REN 1IN PL CTY | 201512 | 30,648.41 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 699320 | 69932 SVC REN 1 1/4 PL C | 201509 | 7,579.91 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 699320 | 69932 SVC REN 1 1/4 PL C | 201510 | 14,789.72 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 699320 | 69932 SVC REN 1 1/4 PL C | 201511 | 2,409.88 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 699320 | 69932 SVC REN 1 1/4 PL C | 201512 | 302.09 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 699330 | 69933 SVC REN 2&OVR PL C | 201509 | 4,093.98 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 699330 | 69933 SVC REN 2&OVR PL C | 201510 | 1,614.47 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 699330 | 69933 SVC REN 2&OVR PL C | 201511 | (10,296.27) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 699330 | 69933 SVC REN 2&OVR PL C | 201512 | 22,892.86 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 699400 | 69940 SVC REN COR TRANSFER CI | 201509 | (7,595.83) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 699400 | 69940 SVC REN COR TRANSFER CI | 201510 | (11,724.15) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 699400 | 69940 SVC REN COR TRANSFER CI | 201511 | (24,352.04) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 699400 | 69940 SVC REN COR TRANSFER CI | 201512 | (5,167.23) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 699410 | 69941 SVC REN COR TRANSFER CO | 201509 | (15,484.93) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 699410 | 69941 SVC REN COR TRANSFER CO | 201510 | (54,764.14) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 699410 | 69941 SVC REN COR TRANSFER CO | 201511 | (23,011.87) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 699410 | 69941 SVC REN COR TRANSFER CO | 201512 | (11,885.14) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900068 | Repl w/ 1750F 2P Jefferson Ph 2 | 201509 | (75.19) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900069 | Inst 3539F 2P Jefferson Ph 3 | 201509 | 21,832.48 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900069 | Inst 3539F 2P Jefferson Ph 3 | 201510 | 1,443.09 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900069 | Inst 3539F 2P Jefferson Ph 3 | 201511 | (51.06) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900069 | Inst 3539F 2P Jefferson Ph 3 | 201512 | 2,262.82 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900071 | Repl w/ 4240F 2-4P Jefferson Ph5 | 201511 | 673,722.70 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900071 | Repl w/ 4240F 2-4P Jefferson Ph5 | 201512 | 2,227.25 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900072 | Repl w 688F 2P & 2527F 4P Lafayette | 201509 | (0.09) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900073 | Repl w/ 2520F 2P Jefferson Ph 6 | 201509 | (299,740.25) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900073 | Repl w/ 2520F 2P Jefferson Ph 6 | 201510 | 160.20 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900093 | Repl w/ 184F 2P Cass | 201509 | 0.06 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900099 | Rel 1830F 2P McKnight Rd | 201509 | (72.37) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900233 | Rel w/ 1924F 6P Fee Fee Road | 201509 | (0.18) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900264 | Int 3087F 4P 2P Baden Grid Ph 5A | 201509 | 26.72 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900265 | Repl w/ 3337F 2P Baden Ph 5B | 201509 | 5.12 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900266 | Inst 4640F 2P Baden Ph 5C | 201509 | (3.00) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900266 | Inst 4640F 2P Baden Ph 5C | 201510 | 14.69 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900266 | Inst 4640F 2P Baden Ph 5C | 201511 | (0.91) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900266 | Inst 4640F 2P Baden Ph 5C | 201512 | 68.29 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900267 | Repl w/ 4536F 2P Baden Ph5D | 201509 | 4.52 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900268 | Inst 4411F 2P Baden Ph5E | 201509 | 2.58 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900269 | Inst 1150F 4P Walnut Park Ph 5A | 201509 | (791.57) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900270 | Inst 2942F 2P Walnut Park Ph5B | 201509 | (915.37) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900270 | Inst 2942F 2P Walnut Park Ph5B | 201511 | 1,487.40 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900271 | Inst 2646F 2P Walnut Park Ph5C | 201509 | (3,666.46) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900271 | Inst 2646F 2P Walnut Park Ph5C | 201511 | 1,954.92 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900272 | Inst 4170F 2P Walnut Park Ph 5D | 201509 | 358,981.28 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900272 | Inst 4170F 2P Walnut Park Ph 5D | 201511 | (31.00) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900272 | Inst 4170F 2P Walnut Park Ph 5D | 201512 | 0.42 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900273 | Repl w/ 4565F 2P Walnut Park Ph5E | 201510 | 483,449.97 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900273 | Repl w/ 4565F 2P Walnut Park Ph5E | 201511 | (383.16) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900273 | Repl w/ 4565F 2P Walnut Park Ph5E | 201512 | 169.38 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900274 | Repl w/ 3390F 2P Wellington Ph 4D | 201509 | (12,481.16) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900274 | Repl w/ 3390F 2P Wellington Ph 4D | 201512 | (107,174.75) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900275 | Repl w/ 4989F 2P Wellington Ph4E | 201509 | (2,849.40) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900277 | Repl w/ 1725F 2P Walnut Park Ph4B | 201509 | (128.05) | a | A, B, C, K |

| | | | | | | |
|------------------------------------|--------|-------------------------------------|--------|-------------|---|---------------|
| 380200-Services - Plastic & Copper | 900278 | Repl w/ 3977F 2P Walnut Park Ph4C | 201509 | (141.25) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900279 | Repl w/ 3345F 2P Walnut Park Ph4D | 201509 | (1,934.34) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900281 | Inst 4984F 4PWellston Phase 2B | 201509 | (0.84) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900282 | Inst 4400F 2P Wellston 2C | 201509 | (2,841.81) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900283 | Inst 5300F 2P Wellston Ph2D | 201509 | 1.78 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900284 | Inst 5466F 2P Wellston Ph2E | 201509 | (1,608.98) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900310 | Inst 2250F 2P Yale Ave Maplewood 1C | 201511 | 85.11 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900313 | Inst 775F 2P Cauliks Hill Rd CJ | 201510 | (297.22) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900375 | Inst 1747F 6P Litzsinger | 201509 | 0.17 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900377 | Repl w/ 978F 2-4P Big Bend | 201509 | (295.64) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900379 | Inst 783F 4P & 529F 2POld Bonhomme | 201509 | (7.34) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900388 | Repl w/ 332F 2P Tay Rd | 201509 | (2.61) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900390 | Inst 205F 1 1/4P Gore | 201509 | (0.83) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900392 | Inst 580F 4P & 255F 2P Ferguson | 201509 | (0.08) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900393 | Inst 3745F 8P Clayton Ave | 201509 | (0.01) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900395 | Repl w/ 525F 2P Clay St | 201509 | (0.89) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900415 | Repl w/ 1093F 2P Princeton | 201509 | (1.63) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900420 | Repl w/ 520F 2P Oregon | 201509 | (0.70) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900421 | Repl w/ 970F 2P Winnebago | 201509 | (11.61) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900422 | Repl w/ 780F 2P Taft | 201509 | (9.04) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900423 | Repl w/ 1373F 2P Dr MLK | 201509 | (0.05) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900424 | Repl w/ 520F 3P Red Bud | 201509 | 0.18 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900430 | Repl w/ 654F 2P Maurice | 201509 | (1.82) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900432 | Repl w/ 503F 2P Gravois | 201509 | (7.69) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900433 | Repl w/ 570F 4P Chippewa | 201509 | (8.47) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900439 | Repl w/ 269F 2P Ferguson | 201509 | (0.50) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900456 | Inst 8175F 8P Jamieson McCausland | 201509 | 0.01 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900457 | Inst 4546F 2P Baden Ph5F | 201509 | (3.18) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900460 | Inst 3488F 2P Walnut Park Ph4E | 201509 | (2.51) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900461 | Inst 893F 2P Walnut Park Ph4F | 201509 | (0.21) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900462 | Repl w/ 2240F 2P Walnut Park Ph4G | 201509 | (1,049.00) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900463 | Inst 4082F 2P Walnut Park Ph4H | 201509 | (17.65) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900464 | Inst 4741F 2PWalnut Park Ph 4I | 201509 | (286.44) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900467 | Repl w/ 2400F 2-4P Potomac AOR | 201509 | (0.41) | a | A, B, C, F, K |
| 380200-Services - Plastic & Copper | 900476 | Inst 3350F 6P Ivory | 201509 | (207.15) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900476 | Inst 3350F 6P Ivory | 201511 | 106.46 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900476 | Inst 3350F 6P Ivory | 201512 | 0.27 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900485 | Inst 4236F 12P Alaska | 201509 | (0.07) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900488 | Repl w/ 2873F 6P Hodiamont | 201509 | 6.81 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900523 | Repl w/ 5304F 2P Maplewood Ph1D | 201512 | 753,907.38 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900536 | Aband 1681F 6CWalnut Park Ph4B | 201509 | (14.94) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900538 | Aband 3381F 6C Walnut Park Ph4D | 201509 | (10.93) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900540 | Aband var Walnut Park Ph4F | 201509 | (15.07) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900546 | Inst 5691F 2P Wellston Ph2F | 201512 | 195,100.16 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900548 | Inst 6712F 2P Wellston Ph2H | 201511 | 240,805.74 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900548 | Inst 6712F 2P Wellston Ph2H | 201512 | 6,482.60 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900556 | Inst 5130F 2P Walnut Park Ph 5F | 201509 | 458,541.15 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900556 | Inst 5130F 2P Walnut Park Ph 5F | 201510 | (8,838.37) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900556 | Inst 5130F 2P Walnut Park Ph 5F | 201511 | 1,271.13 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900556 | Inst 5130F 2P Walnut Park Ph 5F | 201512 | 43.45 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900557 | Inst 2123F 2P Walnut Park Ph6A | 201509 | (4,286.66) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900558 | Inst 1859F 2P Walnut Park Ph6B | 201509 | (15,475.52) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900558 | Inst 1859F 2P Walnut Park Ph6B | 201510 | 2,008.70 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900558 | Inst 1859F 2P Walnut Park Ph6B | 201511 | 152.53 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900558 | Inst 1859F 2P Walnut Park Ph6B | 201512 | 4.12 | a | A, B, C, K |

| | | | | | | |
|------------------------------------|--------|------------------------------------|--------|--------------|---|------------|
| 380200-Services - Plastic & Copper | 900559 | Inst 3875F 2P Walnut Park Ph6C | 201509 | (4,669.68) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900559 | Inst 3875F 2P Walnut Park Ph6C | 201510 | (448.13) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900559 | Inst 3875F 2P Walnut Park Ph6C | 201511 | 1,814.04 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900559 | Inst 3875F 2P Walnut Park Ph6C | 201512 | 558.18 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900560 | Inst 4705F 2P Walnut Park Ph6D | 201509 | 318,859.28 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900560 | Inst 4705F 2P Walnut Park Ph6D | 201511 | (739.17) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900560 | Inst 4705F 2P Walnut Park Ph6D | 201512 | 596.54 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900603 | Inst 4300F 2P Maplewood Ph2A | 201512 | 225,104.47 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900605 | Inst 2020F 2P Maplewood Ph 2B | 201512 | 255,753.22 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900607 | Inst 3183F 2P Maplewood Ph2C | 201509 | 169,510.47 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900607 | Inst 3183F 2P Maplewood Ph2C | 201510 | 7,161.47 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900607 | Inst 3183F 2P Maplewood Ph2C | 201511 | 14,694.72 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900607 | Inst 3183F 2P Maplewood Ph2C | 201512 | 188.42 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900623 | Repl w/ 2852' 2P Wydown Ph 6 | 201509 | (1,679.50) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900633 | Rel w/ 321F 4S 2S Progress Parkway | 201509 | 2,965.86 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900633 | Rel w/ 321F 4S 2S Progress Parkway | 201510 | (18.96) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900643 | Inst 1801F 6P-12P Marmaduke/Hudler | 201509 | 4,484.71 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900643 | Inst 1801F 6P-12P Marmaduke/Hudler | 201510 | 0.72 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900650 | Inst 3290F 2P St Louis Hills Ph1A | 201509 | (17,932.32) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900650 | Inst 3290F 2P St Louis Hills Ph1A | 201512 | (164,337.66) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900652 | Inst 4435F 2P St Louis Hills Ph1B | 201509 | (3,999.18) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900652 | Inst 4435F 2P St Louis Hills Ph1B | 201511 | 1,542.26 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900653 | Inst 2636F 2P St Louis Hills Ph1C | 201509 | (1,685.99) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900653 | Inst 2636F 2P St Louis Hills Ph1C | 201510 | 172.57 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900653 | Inst 2636F 2P St Louis Hills Ph1C | 201511 | (2,800.41) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900653 | Inst 2636F 2P St Louis Hills Ph1C | 201512 | 5.27 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900670 | Rel w/ 400F 6P Vogel Rd | 201509 | 2,632.89 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900670 | Rel w/ 400F 6P Vogel Rd | 201510 | 0.03 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900677 | Repl w/ 1795F 2P Cole & 18th PhA | 201509 | 6,537.41 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900679 | Inst 2312F 4P Cole & 18th PhB | 201509 | (628.69) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900679 | Inst 2312F 4P Cole & 18th PhB | 201511 | (8,971.62) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900681 | Inst 1637F 2P Cole & 18th Ph C | 201509 | (9,068.74) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900683 | Inst 1864F 2P Cole & 18th Ph D | 201509 | (8,238.20) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900683 | Inst 1864F 2P Cole & 18th Ph D | 201510 | 14.17 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900683 | Inst 1864F 2P Cole & 18th Ph D | 201511 | (0.02) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900683 | Inst 1864F 2P Cole & 18th Ph D | 201512 | 0.64 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900685 | Inst 1550F 2P Cole & 18th PhE | 201509 | (6,238.78) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900685 | Inst 1550F 2P Cole & 18th PhE | 201510 | 17.64 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900685 | Inst 1550F 2P Cole & 18th PhE | 201511 | (0.04) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900685 | Inst 1550F 2P Cole & 18th PhE | 201512 | 0.87 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900687 | Inst 1096F 2P Cole & 18th PhF | 201509 | (4,235.08) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900689 | Inst 2434F 2P Cole & 18th PhG | 201509 | (4,457.29) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900689 | Inst 2434F 2P Cole & 18th PhG | 201510 | (35.11) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900689 | Inst 2434F 2P Cole & 18th PhG | 201511 | 0.09 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900689 | Inst 2434F 2P Cole & 18th PhG | 201512 | (9.03) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900691 | Repl w/ 3458F 2P Cole & 18th Ph H | 201509 | 4,910.78 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900691 | Repl w/ 3458F 2P Cole & 18th Ph H | 201510 | 1,575.17 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900691 | Repl w/ 3458F 2P Cole & 18th Ph H | 201511 | (35.64) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900691 | Repl w/ 3458F 2P Cole & 18th Ph H | 201512 | 4,511.38 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900723 | Rel w/ 3350F 2P Valley Park | 201509 | 1.35 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900730 | Rel w/ 310F 2P Bramblett | 201509 | (80.58) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900730 | Rel w/ 310F 2P Bramblett | 201510 | (0.18) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900734 | Repl w/ 1717F 2P Hurck | 201509 | (3,550.66) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900734 | Repl w/ 1717F 2P Hurck | 201510 | 27.47 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900734 | Repl w/ 1717F 2P Hurck | 201511 | 1,073.91 | a | A, B, C, K |

| | | | | | | |
|------------------------------------|--------|-------------------------------------|--------|--------------|---|---------------|
| 380200-Services - Plastic & Copper | 900734 | Repl w/ 1717F 2P Hurck | 201512 | 119.04 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900738 | Repl w/ 780F 2P Kingsland MSD | 201509 | (1,862.01) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900738 | Repl w/ 780F 2P Kingsland MSD | 201511 | 179.62 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900738 | Repl w/ 780F 2P Kingsland MSD | 201512 | 25.45 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900759 | Repl w/ 2836F 2P Hickory Dale | 201509 | 74,549.17 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900759 | Repl w/ 2836F 2P Hickory Dale | 201510 | 15.62 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900762 | Inst 2069F 2P Earthquake Zone Ph1A | 201509 | (2,102.42) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900763 | Inst 3508F 2P Earthquake Zone Ph1B | 201509 | (186,673.29) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900764 | Repl w/758F 2P Earthquake Zone Ph1C | 201509 | (37,485.34) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900764 | Repl w/758F 2P Earthquake Zone Ph1C | 201510 | 6.19 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900765 | Inst 1899F 4P Earthquake Zone Ph1D | 201509 | (18,209.01) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900775 | Rel w/ 1535F 2P Page&Hodiamont AOR | 201509 | (304.95) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900813 | Rel w/ 700F 2P Froesel | 201509 | 0.21 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900822 | Rel w/ 130F 6S Price Road | 201509 | (676.15) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900823 | Repl w/ 659F 2P Baden Ph6A | 201509 | (86.18) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900848 | Rel w/ 810F 4P Bircher & Newstead | 201509 | (970.95) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900859 | Repl w/ 290F 2P Cabanne | 201509 | (874.17) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900859 | Repl w/ 290F 2P Cabanne | 201510 | 10.00 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900861 | Repl w/ 105F 4P McLaran | 201509 | (21.21) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900862 | Rep w/ 4552F 2P Broadway AOR | 201509 | 79,870.08 | a | A, B, C, F, K |
| 380200-Services - Plastic & Copper | 900862 | Rep w/ 4552F 2P Broadway AOR | 201510 | (9.18) | a | A, B, C, F, K |
| 380200-Services - Plastic & Copper | 900862 | Rep w/ 4552F 2P Broadway AOR | 201511 | 0.03 | a | A, B, C, F, K |
| 380200-Services - Plastic & Copper | 900862 | Repl w/ 4552F 2P Broadway AOR | 201512 | (1.48) | a | A, B, C, F, K |
| 380200-Services - Plastic & Copper | 900873 | Repl w/ 538F 2P Longacre | 201509 | (1,251.75) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900873 | Repl w/ 538F 2P Longacre | 201510 | 12,610.44 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900876 | Repl w/ 1060F 2P Rauschenbach PVC | 201509 | (572.76) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900876 | Repl w/ 1060F 2P Rauschenbach PVC | 201510 | 393.26 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900876 | Repl w/ 1060F 2P Rauschenbach PVC | 201511 | (0.30) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900876 | Repl w/ 1060F 2P Rauschenbach PVC | 201512 | 10,638.09 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900890 | Repl w/ 2218F 2P Russell & Flora | 201509 | 241,794.32 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900890 | Repl w/ 2218F 2P Russell & Flora | 201510 | 76.12 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900893 | Repl w/ 2486F 6P Arlington | 201509 | (750.29) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900893 | Repl w/ 2486F 6P Arlington | 201511 | (494.70) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900893 | Repl w/ 2486F 6P Arlington | 201512 | (178.20) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900895 | Repl w/ 828F 2P Marquette | 201509 | 35,296.44 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900895 | Repl w/ 828F 2P Marquette | 201510 | (371.52) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900895 | Repl w/ 828F 2P Marquette | 201511 | 0.02 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900895 | Repl w/ 828F 2P Marquette | 201512 | (31.73) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900896 | Repl w/ 2990F 2P 4P Maple | 201509 | (1,984.53) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900896 | Repl w/ 2990F 2P 4P Maple | 201510 | 221.79 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900896 | Repl w/ 2990F 2P 4P Maple | 201511 | 988.51 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900896 | Repl w/ 2990F 2P 4P Maple | 201512 | (219.47) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900897 | Repl w/ 587F 2P Syracuse | 201509 | 2,145.12 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900897 | Repl w/ 587F 2P Syracuse | 201511 | 475.01 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900897 | Repl w/ 587F 2P Syracuse | 201512 | (245.75) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900898 | Repl w/ 1220F 2P Ohio | 201509 | (11,927.76) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900898 | Repl w/ 1220F 2P Ohio | 201510 | (4.28) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900900 | Repl w/ 1075F 2P Washington | 201509 | (25,487.00) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900900 | Repl w/ 1075F 2P Washington | 201510 | 21.38 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900902 | Repl w/ 530' 2P Oakland | 201509 | 4,396.87 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900902 | Repl w/ 530' 2P Oakland | 201510 | (48.29) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900905 | Repl w/ 806F 2P Utah | 201509 | (1,847.00) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900905 | Repl w/ 806F 2P Utah | 201510 | 11.64 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900908 | Repl w/ 460F 2P California | 201509 | (125.54) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900908 | Repl w/ 460F 2P California | 201510 | 1.69 | a | A, B, C, K |

| | | | | | | |
|------------------------------------|--------|-------------------------------------|--------|-------------|---|---------------|
| 380200-Services - Plastic & Copper | 900912 | Repl w/ 745F 2P Shaw | 201509 | (2,171.37) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900912 | Repl w/ 745F 2P Shaw | 201510 | 49.81 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900921 | Repl w/ 2457F 4P&2P Flad AOR | 201509 | (10,980.70) | a | A, B, C, F, K |
| 380200-Services - Plastic & Copper | 900921 | Repl w/ 2457F 4P&2P Flad AOR | 201510 | 10,731.29 | a | A, B, C, F, K |
| 380200-Services - Plastic & Copper | 900952 | Repl w/ 2806F 2P Clifton Heights-1B | 201512 | 129,483.46 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900961 | Rel w/ 190F 2P Clay | 201509 | (30.19) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900977 | Repl w/ 1291F 4P Boyle | 201509 | 64.81 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900983 | Repl w/ 3143F 2P 4P Shaw AOR | 201512 | 477,073.00 | a | A, B, C, F, K |
| 380200-Services - Plastic & Copper | 900986 | Repl w/ 2189F 2P Earthquake Zone 2A | 201509 | (30,716.38) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900986 | Repl w/ 2189F 2P Earthquake Zone 2A | 201510 | (94.41) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900988 | Repl w/ 3840F 2P Earthquake Zn Ph2B | 201509 | 170,342.42 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900988 | Repl w/ 3840F 2P Earthquake Zn Ph2B | 201510 | 269.79 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900988 | Repl w/ 3840F 2P Earthquake Zn Ph2B | 201511 | (1,195.16) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900988 | Repl w/ 3840F 2P Earthquake Zn Ph2B | 201512 | 23.54 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 900993 | Repl w/ 2220F 2P CentralWestEndPh1G | 201511 | 1,099.36 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 901011 | Rel w/ 450F 4P Sanford AOR | 201509 | 30,639.29 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 901011 | Rel w/ 450F 4P Sanford AOR | 201510 | (278.69) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 901013 | Rel w/ 1612F 4P Woodstock CJ | 201511 | (1,558.51) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 901013 | Rel w/ 1612F 4P Woodstock CJ | 201512 | 17.07 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 901019 | Rel w/ 80F 6S Fee Fee | 201509 | (67.05) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 901019 | Rel w/ 80F 6S Fee Fee | 201510 | (40.99) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 901040 | Repl w/ 315F 2P Amherst Ave | 201509 | (445.45) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 901059 | Repl w/ 680' 2P Gregg | 201509 | 47,107.63 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 901059 | Repl w/ 680' 2P Gregg | 201510 | 949.62 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 901059 | Repl w/ 680' 2P Gregg | 201511 | (645.11) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 901059 | Repl w/ 680' 2P Gregg | 201512 | 22.66 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 901063 | Rel w/ 1307F 4P Bessie AOR | 201509 | 112,871.64 | a | A, B, C, F, K |
| 380200-Services - Plastic & Copper | 901063 | Rel w/ 1307F 4P Bessie AOR | 201510 | 274.58 | a | A, B, C, F, K |
| 380200-Services - Plastic & Copper | 901063 | Rel w/ 1307F 4P Bessie AOR | 201511 | 5,650.11 | a | A, B, C, F, K |
| 380200-Services - Plastic & Copper | 901063 | Rel w/ 1307F 4P Bessie AOR | 201512 | 24.91 | a | A, B, C, F, K |
| 380200-Services - Plastic & Copper | 901071 | Rel w/ 285F 2P Froesel Ph2 | 201509 | (94.09) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 901071 | Rel w/ 285F 2P Froesel Ph2 | 201511 | 14.21 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 901071 | Rel w/ 285F 2P Froesel Ph2 | 201512 | (11.97) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 901081 | Rel w/ 970F 6P Pralle Lane | 201512 | 4,933.89 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 901088 | Repl w/ 4597F 2P U-City Ph1B | 201512 | 189,313.18 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 901107 | Rel w/ 62F 4P Southwest AOR | 201509 | (168.08) | a | A, B, C, F, K |
| 380200-Services - Plastic & Copper | 901107 | Rel w/ 62F 4P Southwest AOR | 201511 | 93.74 | a | A, B, C, F, K |
| 380200-Services - Plastic & Copper | 901107 | Rel w/ 62F 4P Southwest AOR | 201512 | (87.60) | a | A, B, C, F, K |
| 380200-Services - Plastic & Copper | 901111 | Repl w/ 955F 2P Hickory | 201509 | 10,116.14 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 901111 | Repl w/ 955F 2P Hickory | 201510 | 760.05 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 901111 | Repl w/ 955F 2P Hickory | 201511 | (149.28) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 901111 | Repl w/ 955F 2P Hickory | 201512 | 14.66 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 901114 | Repl w/ 1630F 2P Maffitt | 201512 | 64,156.59 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 901139 | Repl w/ 901F 2P Suburban Ave | 201509 | 10,836.52 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 901139 | Repl w/ 901F 2P Suburban Ave | 201510 | 2,296.49 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 901139 | Repl w/ 901F 2P Suburban Ave | 201511 | (69.17) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 901139 | Repl w/ 901F 2P Suburban Ave | 201512 | (1.39) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 901162 | Repl w/ 210F 2P St. Leonard Ct. | 201512 | 27,059.20 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 901173 | Vandeventer - City of St. Louis MRE | 201509 | (40.02) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 901173 | Rel w/ 260F 6P Vandeventer | 201511 | (42.95) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 901173 | Rel w/ 260F 6P Vandeventer | 201512 | 0.74 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 901178 | Repl w/ 185F 2P Evans | 201509 | 3,920.21 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 901178 | Repl w/ 185F 2P Evans | 201510 | 302.14 | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 901178 | Repl w/ 185F 2P Evans | 201511 | (0.30) | a | A, B, C, K |
| 380200-Services - Plastic & Copper | 901178 | Repl w/ 185F 2P Evans | 201512 | 11.49 | a | A, B, C, K |

| | | | | | | | |
|---|--------|--|----------------------------|--------|--------------|---|------------|
| 380200-Services - Plastic & Copper | 901308 | | Rel w/ 400F 2P Bismark Ave | 201512 | 2,221.47 | a | A, B, C, K |
| ACCOUNT 38020 SERVICES PLASTIC & COPPER | | | Renewed Services | 201601 | 1,407,500.00 | a | A, B, C, K |
| ACCOUNT 38020 SERVICES PLASTIC & COPPER | | | Renewed Services | 201602 | 1,407,500.00 | a | A, B, C, K |

TOTAL 13,509,753.75

Total Service Line Replacements and Insertion Projects:

13,964,060.99

REGULATOR STATIONS - ADDITIONS

LACLEDE DIVISION

| PLANT ACCOUNT | WORK ORDER | BUDGET PROJECT | DESCRIPTION | IN SERVICE DATE | ADDITION AMOUNT | | |
|-------------------------------------|------------|----------------|------------------------------------|-----------------|-----------------|---|------------|
| 375100-Struct & Impv - Meas & Reg S | 606330 | | 60633 Inst Reg Sta Jefferson-Rut | 201509 | (212.71) | a | A, B, C, K |
| 378000-Meas & Reg Station Equipment | 003304 | | Replace Osceola & Virginia Reg Sta | 201509 | 16.05 | a | A, B, C, K |
| 378000-Meas & Reg Station Equipment | 003305 | | Repl Euclid & Hooke Reg Station | 201509 | (2,329.20) | a | A, B, C, K |
| 378000-Meas & Reg Station Equipment | 606330 | | 60633 Inst Reg Sta Jefferson-Rut | 201509 | (271.75) | a | A, B, C, K |
| REGULATOR STATIONS - ADDITIONS | | | REGULATOR STATIONS - ADDITIONS | 201601 | | a | A, B, C, K |
| REGULATOR STATIONS - ADDITIONS | | | REGULATOR STATIONS - ADDITIONS | 201602 | | a | A, B, C, K |

TOTAL (2,797.61)

ACCOUNT 379000 MEASURING & REGULATING STATION EQUIPMENT - CITY GATE

| PLANT ACCOUNT | WORK ORDER | BUDGET PROJECT | DESCRIPTION | IN SERVICE DATE | ADDITION AMOUNT | | |
|-------------------------------------|------------|----------------|------------------------------------|-----------------|-----------------|---|------------|
| 379000-Meas & Reg Station Eqpt-City | 005045 | | Replace odorant tanks on MoNat Sys | 201509 | (1,783.17) | a | A, B, K, M |
| 379000-Meas & Reg Station Eqpt-City | 007132 | | Ph 2 - Replace Monat Odorant Tanks | 201509 | 16,664.12 | a | A, B, K, M |
| 379000-Meas & Reg Station Eqpt-City | 007132 | | Ph 2 - Replace Monat Odorant Tanks | 201511 | (189.34) | a | A, B, K, M |
| 379000-Meas & Reg Station Eqpt-City | 007132 | | Ph 2 - Replace Monat Odorant Tanks | 201512 | (51.76) | a | A, B, K, M |
| REGULATOR STATIONS - ADDITIONS | | | REGULATOR STATIONS - ADDITIONS | 201601 | | a | A, B, K, M |
| REGULATOR STATIONS - ADDITIONS | | | REGULATOR STATIONS - ADDITIONS | 201602 | | a | A, B, K, M |

TOTAL 14,639.85

Total Regulator Station Replacements

11,842.24

MAIN RELOCATIONS NET OF REIMBURSEMENTS - NET ADDITIONS

| PLANT ACCOUNT | WORK ORDER | BUDGET PROJECT | DESCRIPTION | IN SERVICE DATE | ADDITION AMOUNT | | |
|------------------------|------------|----------------|------------------------------------|-----------------|-----------------|---|----|
| 376100-Mains - Steel | 900732 | 3403L | Rel w/ 120F 6S DeBaliviere Bridge | 201512 | (2,962.09) | c | na |
| 376300-Mains - Plastic | 001337 | 3403L | Inst 622F 4P Shenandoah | 201509 | 368,019.86 | c | na |
| 376300-Mains - Plastic | 001337 | 3403L | Inst 622F 4P Shenandoah CJ -Reimb | 201511 | (169,531.01) | c | na |
| 376300-Mains - Plastic | 001494 | 3403M | Relocate along Oak Grove (Phase 2) | 201509 | 1,251.18 | c | na |

| | | | | | | | |
|------------------------|--------|-------|-------------------------------------|--------|-------------|---|----|
| 376300-Mains - Plastic | 001878 | 3403M | Relocate main at Westwood and Katy | 201509 | 103,521.26 | c | na |
| 376100-Mains - Steel | 002882 | 3403M | FE - American Legion & S Mill St | 201509 | 4,780.64 | c | na |
| 376300-Mains - Plastic | 002882 | 3403M | FE - American Legion & S Mill St | 201509 | (408.90) | c | na |
| 376300-Mains - Plastic | 003763 | 3403M | Rel w/ 3200F 4P Oak Grove Rd-MN | 201509 | 51.41 | c | na |
| 376300-Mains - Plastic | 006238 | 3403M | Rel w/ 23F 2P Prairie Dell Rd | 201509 | 465.21 | c | na |
| 376300-Mains - Plastic | 009113 | 3403M | Rel w/ 210F 4P W Congress MN | 201512 | 16,260.54 | c | na |
| 376300-Mains - Plastic | 647910 | 3401L | 64791 225F 2P S MAIN ST | 201511 | (254.90) | c | na |
| 376300-Mains - Plastic | 698960 | 3401L | 69896 MAIN CONTR CONSTR ST CHS | 201509 | 22,488.59 | c | na |
| 376300-Mains - Plastic | 699260 | 3401L | 69926 CONTBTN CONST CITY | 201509 | (31,859.79) | c | na |
| 376300-Mains - Plastic | 699760 | 3401L | 69976 CONTBTN CONST CNTY | 201509 | (24,222.80) | c | na |
| 376300-Mains - Plastic | 900095 | 3403L | Rel w/ 350F 8P Mason Rd Bridge #211 | 201509 | (1,837.83) | c | na |
| 376300-Mains - Plastic | 900095 | 3403L | Rel w/ 350F 8P Mason Rd Bridge #211 | 201509 | (26.17) | c | na |
| 376300-Mains - Plastic | 900095 | 3403L | Rel w/ 350F 8P Mason Rd Bridge #211 | 201511 | (1,295.45) | c | na |
| 376300-Mains - Plastic | 900095 | 3403L | Rel w/ 350F 8P Mason Rd Bridge #211 | 201511 | 1,295.45 | c | na |
| 376300-Mains - Plastic | 900095 | 3403L | Rel w/ 350F 8P Mason Rd Bridge #211 | 201512 | 3.83 | c | na |
| 376300-Mains - Plastic | 900095 | 3403L | Rel w/ 350F 8P Mason Rd Bridge #211 | 201512 | 225.38 | c | na |
| 376100-Mains - Steel | 900099 | 3403L | Rel 1830F 2P McKnight Rd | 201509 | (59.16) | c | na |
| 376300-Mains - Plastic | 900099 | 3403L | Rel 1830F 2P McKnight Rd | 201509 | (628.21) | c | na |
| 376300-Mains - Plastic | 900099 | 3403L | Rel 1830F 2P McKnight Rd | 201509 | (8.99) | c | na |
| 376100-Mains - Steel | 900104 | 3403L | Rel w/ 3018F Var-Kingshighway Bridg | 201512 | 115,776.74 | c | na |
| 376300-Mains - Plastic | 900104 | 3403L | Rel w/ 3018F Var-Kingshighway Bridg | 201512 | 763,983.73 | c | na |
| 376100-Mains - Steel | 900147 | 3403L | Inst 2270F Route 364-Final Phase | 201509 | (7.05) | c | na |
| 376300-Mains - Plastic | 900147 | 3403L | Inst 2270F Route 364-Final Phase | 201509 | (4.26) | c | na |
| 376300-Mains - Plastic | 900233 | 3403L | Rel w/ 1924F 6P Fee Fee Road | 201509 | (2.25) | c | na |
| 376300-Mains - Plastic | 900233 | 3403L | Rel w/ 1924F 6P Fee Fee Road | 201509 | (0.03) | c | na |
| 376300-Mains - Plastic | 900313 | 3403L | Rel w/ 775F 2P Caulks Hill Rd CJ | 201510 | (3,280.19) | c | na |
| 376100-Mains - Steel | 900319 | 3403L | Repl w/ 50F 6S Old Halls Ferry/Vail | 201509 | (3,036.41) | c | na |
| 376100-Mains - Steel | 900319 | 3403L | Repl w/ 50F 6S Old Halls Ferry/Vail | 201509 | 2,242.63 | c | na |
| 376100-Mains - Steel | 900319 | 3403L | Repl w/ 50F 6S Old Halls Ferry/Vail | 201510 | (222.04) | c | na |
| 376100-Mains - Steel | 900319 | 3403L | Repl w/ 50F 6S Old Halls Ferry/Vail | 201510 | (12.33) | c | na |
| 376300-Mains - Plastic | 900444 | 3403L | Rel w/405F 4P Pitman Hill Phase3 CJ | 201510 | 18,042.49 | c | na |
| 376300-Mains - Plastic | 900454 | 3403L | Inst 229F 2P Pitman Hill Phase 3 CJ | 201510 | 10,728.15 | c | na |
| 376100-Mains - Steel | 900498 | 3403L | Rel w/ 1150F 6P Saline Road | 201512 | 948.63 | c | na |
| 376100-Mains - Steel | 900498 | 3403L | Rel w/ 1150F 6P Saline Road | 201512 | 54,156.39 | c | na |
| 376300-Mains - Plastic | 900498 | 3403L | Rel w/ 1150F 6P Saline Road | 201512 | 391,746.49 | c | na |
| 376300-Mains - Plastic | 900508 | 3403L | Rel w/ 127F 2P Dearborn | 201509 | (148.31) | c | na |
| 376100-Mains - Steel | 900602 | 3403L | Rel w/ 24F 8S Natural Bridge | 201509 | (900.47) | c | na |
| 376300-Mains - Plastic | 900602 | 3403L | Rel w/ 24F 8S Natural Bridge | 201509 | (93.46) | c | na |
| 376100-Mains - Steel | 900633 | 3403L | Rel w/ 321F 4S 2S Progress Parkway | 201509 | (1,441.95) | c | na |
| 376100-Mains - Steel | 900633 | 3403L | Rel w/ 321F 4S 2S Progress Parkway | 201509 | (4,493.62) | c | na |
| 376100-Mains - Steel | 900633 | 3403L | Rel w/ 321F 4S 2S Progress Parkway | 201510 | (826.28) | c | na |
| 376300-Mains - Plastic | 900670 | 3403L | Rel w/ 400F 6P Vogel Rd | 201509 | (1,327.26) | c | na |
| 376300-Mains - Plastic | 900670 | 3403L | Rel w/ 400F 6P Vogel Rd | 201510 | 1.45 | c | na |
| 376300-Mains - Plastic | 900693 | 3403L | Rel w/ 350F 4P Civic Center Dr | 201509 | (64,833.06) | c | na |
| 376300-Mains - Plastic | 900723 | 3403L | Rel w/ 3350F 2P Valley Park | 201509 | 3.72 | c | na |
| 376300-Mains - Plastic | 900723 | 3403L | Rel w/ 3350F 2P Valley Park | 201509 | 0.08 | c | na |
| 376300-Mains - Plastic | 900730 | 3403L | Rel w/ 310F 2P Bramblett | 201509 | (1,027.05) | c | na |
| 376300-Mains - Plastic | 900730 | 3403L | Rel w/ 310F 2P Bramblett | 201510 | (2.33) | c | na |
| 376100-Mains - Steel | 900732 | 3403L | Rel w/ 120F 6S DeBaliviere Bridge | 201509 | (1,797.38) | c | na |
| 376100-Mains - Steel | 900732 | 3403L | Rel w/ 120F 6S DeBaliviere Bridge | 201509 | (72.95) | c | na |
| 376300-Mains - Plastic | 900732 | 3403L | Rel w/ 120F 6S DeBaliviere Bridge | 201509 | (80.03) | c | na |
| 376100-Mains - Steel | 900732 | 3403L | Rel w/ 120F 6S DeBaliviere Bridge | 201510 | 15,688.62 | c | na |

| | | | | | | | |
|------------------------|--------|-------|-------------------------------------|--------|-------------|------|------------|
| 376100-Mains - Steel | 900732 | 3403L | Rel w/ 120F 6S DeBaliviere Bridge | 201510 | 636.57 | c | na |
| 376300-Mains - Plastic | 900732 | 3403L | Rel w/ 120F 6S DeBaliviere Bridge | 201510 | 698.71 | c | na |
| 376100-Mains - Steel | 900732 | 3403L | Rel w/ 120F 6S DeBaliviere Bridge | 201511 | 0.08 | c | na |
| 376100-Mains - Steel | 900732 | 3403L | Rel w/ 120F 6S DeBaliviere Bridge | 201511 | (0.01) | c | na |
| 376300-Mains - Plastic | 900732 | 3403L | Rel w/ 120F 6S DeBaliviere Bridge | 201511 | 0.01 | c | na |
| 376100-Mains - Steel | 900732 | 3403L | Rel w/ 120F 6S DeBaliviere Bridge | 201512 | (49,447.88) | c | na |
| 376300-Mains - Plastic | 900732 | 3403L | Rel w/ 120F 6S DeBaliviere Bridge | 201512 | 3,094.70 | c | na |
| 376300-Mains - Plastic | 900732 | 3403L | Rel w/ 120F 6S DeBaliviere Bridge | 201512 | 49,312.87 | c | na |
| 376300-Mains - Plastic | 900775 | 3403L | Rel w/ 1535F 2P Page&Hodiamont AOR | 201509 | (1,086.17) | a, c | A, B, C, F |
| 376300-Mains - Plastic | 900775 | 3403L | Rel w/ 1535F 2P Page&Hodiamont AOR | 201509 | (55.80) | a, c | A, B, C, F |
| 376300-Mains - Plastic | 900813 | 3403L | Rel w/ 700F 2P Froesel | 201509 | 0.43 | c | na |
| 376100-Mains - Steel | 900817 | 3403L | Rel w/ 330F 6P St Cyr Rd Culvert | 201509 | 2,957.38 | c | na |
| 376300-Mains - Plastic | 900817 | 3403L | Rel w/ 330F 6P St Cyr Rd Culvert | 201509 | 4,180.64 | c | na |
| 376300-Mains - Plastic | 900817 | 3403L | Rel w/ 330F 6P St Cyr Rd Culvert | 201509 | 311.13 | c | na |
| 376100-Mains - Steel | 900817 | 3403L | Rel w/ 330F 6P St Cyr Rd Culvert | 201510 | (40.99) | c | na |
| 376300-Mains - Plastic | 900817 | 3403L | Rel w/ 330F 6P St Cyr Rd Culvert | 201510 | (132.44) | c | na |
| 376300-Mains - Plastic | 900817 | 3403L | Rel w/ 330F 6P St Cyr Rd Culvert | 201510 | (2.28) | c | na |
| 376100-Mains - Steel | 900819 | 3403L | Rel w/ 18F 6S Howdershell Rd | 201509 | (749.99) | c | na |
| 376100-Mains - Steel | 900819 | 3403L | Rel w/ 18F 6S Howdershell Rd | 201509 | (20.63) | c | na |
| 376300-Mains - Plastic | 900820 | 3403L | Rel w/ 410' 6P Willott Rd BridgeCJ | 201509 | 2,816.68 | c | na |
| 376300-Mains - Plastic | 900820 | 3403L | Rel w/ 410' 6P Willott Rd BridgeCJ | 201510 | 9.43 | c | na |
| 376100-Mains - Steel | 900822 | 3403L | Rel w/ 130F 6S Price Road | 201509 | (1,482.11) | c | na |
| 376100-Mains - Steel | 900822 | 3403L | Rel w/ 130F 6S Price Road | 201509 | (83.66) | c | na |
| 376300-Mains - Plastic | 900822 | 3403L | Rel w/ 130F 6S Price Road | 201509 | (4,644.81) | c | na |
| 376300-Mains - Plastic | 900822 | 3403L | Rel w/ 130F 6S Price Road | 201509 | (174.45) | c | na |
| 376100-Mains - Steel | 900837 | 3403L | Rel w/ 1736F 4P Champ Line | 201509 | (376.85) | c | na |
| 376300-Mains - Plastic | 900837 | 3403L | Rel w/ 1736F 4P Champ Line | 201509 | (2,601.92) | c | na |
| 376100-Mains - Steel | 900837 | 3403L | Rel w/ 1736F 4P Champ Line | 201511 | 191.30 | c | na |
| 376300-Mains - Plastic | 900837 | 3403L | Rel w/ 1736F 4P Champ Line | 201511 | (191.30) | c | na |
| 376300-Mains - Plastic | 900841 | 340RL | Rel w/ 57F 4P Ashland AOR | 201509 | (216.10) | c | na |
| 376300-Mains - Plastic | 900841 | 340RL | Rel w/ 57F 4P Ashland AOR | 201509 | (11.86) | c | na |
| 376300-Mains - Plastic | 900845 | 340RL | Rel w/ 85F 4P Russell & Thurman AOR | 201509 | (530.45) | a, c | A, B, C, F |
| 376300-Mains - Plastic | 900845 | 340RL | Rel w/ 85F 4P Russell & Thurman AOR | 201509 | (39.25) | a, c | A, B, C, F |
| 376300-Mains - Plastic | 900848 | 340RL | Rel w/ 810F 4P Bircher & Newstead | 201509 | (1,693.22) | c | na |
| 376300-Mains - Plastic | 900848 | 340RL | Rel w/ 810F 4P Bircher & Newstead | 201509 | (28.24) | c | na |
| 376100-Mains - Steel | 900852 | 3403L | Rel w/ 570' 8S Rte100 Great Streets | 201509 | (2,867.77) | c | na |
| 376300-Mains - Plastic | 900852 | 3403L | Rel w/ 570' 8S Rte100 Great Streets | 201509 | (130.71) | c | na |
| 376300-Mains - Plastic | 900858 | 3403L | Rel w/ 60F 3P Burning Leaf Bridge | 201509 | (59.68) | c | na |
| 376300-Mains - Plastic | 900858 | 3403L | Rel w/ 60F 3P Burning Leaf Bridge | 201510 | (62.79) | c | na |
| 376300-Mains - Plastic | 900864 | 3403L | Rel w/ 80F 4P St. Louis & Norwood | 201509 | (274.12) | c | na |
| 376300-Mains - Plastic | 900864 | 3403L | Rel w/ 80F 4P St. Louis & Norwood | 201509 | (21.05) | c | na |
| 376300-Mains - Plastic | 900864 | 3403L | Rel w/ 80F 4P St. Louis & Norwood | 201510 | (237.06) | c | na |
| 376300-Mains - Plastic | 900864 | 3403L | Rel w/ 80F 4P St. Louis & Norwood | 201510 | (18.93) | c | na |
| 376300-Mains - Plastic | 900866 | 3403L | Repl w/ 1480F 6P 4P-IKEA | 201509 | (5,654.04) | c | na |
| 376300-Mains - Plastic | 900866 | 3403L | Repl w/ 1480F 6P 4P-IKEA | 201509 | (840.88) | c | na |
| 376300-Mains - Plastic | 900868 | 3403L | Rel w/ 210F 2P Vance -Valley Park | 201510 | 8,598.23 | c | na |
| 376300-Mains - Plastic | 900868 | 3403L | Rel w/ 210F 2P Vance -Valley Park | 201510 | 248.91 | c | na |
| 376300-Mains - Plastic | 900868 | 3403L | Rel w/ 210F 2P Vance -Valley Park | 201511 | 479.91 | c | na |
| 376300-Mains - Plastic | 900868 | 3403L | Rel w/ 210F 2P Vance -Valley Park | 201511 | 13.90 | c | na |
| 376300-Mains - Plastic | 900868 | 3403L | Rel w/ 210F 2P Vance -Valley Park | 201512 | 2.98 | c | na |
| 376300-Mains - Plastic | 900868 | 3403L | Rel w/ 210F 2P Vance -Valley Park | 201512 | 102.76 | c | na |

| | | | | | | | |
|------------------------|--------|-------|------------------------------------|--------|-------------|------|------------|
| 376100-Mains - Steel | 900885 | 3403L | Rel w/ 293F 2S Spellman Ph2 | 201509 | (2,409.79) | c | na |
| 376100-Mains - Steel | 900885 | 3403L | Rel w/ 293F 2S Spellman Ph2 | 201509 | (48.32) | c | na |
| 376100-Mains - Steel | 900885 | 3403L | Rel w/ 293F 2S Spellman Ph2 | 201510 | (20,775.07) | c | na |
| 376100-Mains - Steel | 900885 | 3403L | Rel w/ 293F 2S Spellman Ph2 | 201510 | (416.57) | c | na |
| 376100-Mains - Steel | 900892 | 3403L | Rel w/ 180F 2S Elaine Drive | 201509 | (950.63) | c | na |
| 376300-Mains - Plastic | 900911 | 3403L | Rel w/ 300F 2P Edgewood | 201509 | 0.60 | c | na |
| 376300-Mains - Plastic | 900941 | 340RL | Rel w/ 26F 4P Chippewa & Macklind | 201509 | (320.49) | c | na |
| 376300-Mains - Plastic | 900941 | 340RL | Rel w/ 26F 4P Chippewa & Macklind | 201509 | (12.89) | c | na |
| 376300-Mains - Plastic | 900961 | 3403L | Rel w/ 190F 2P Clay | 201509 | (283.59) | c | na |
| 376300-Mains - Plastic | 900967 | 3403L | Rel w/ 200F 2P Fawnvalley Bridge | 201509 | 23,625.40 | c | na |
| 376300-Mains - Plastic | 900967 | 3403L | Rel w/ 200F 2P Fawnvalley Bridge | 201510 | 2,625.82 | c | na |
| 376300-Mains - Plastic | 900967 | 3403L | Rel w/ 200F 2P Fawnvalley Bridge | 201511 | 473.53 | c | na |
| 376300-Mains - Plastic | 900967 | 3403L | Rel w/ 200F 2P Fawnvalley Bridge | 201512 | 17.42 | c | na |
| 376100-Mains - Steel | 900973 | 3403L | Rel w/ 28F 2S Terrie Ln | 201509 | 12,921.93 | c | na |
| 376100-Mains - Steel | 900973 | 3403L | Rel w/ 28F 2S Terrie Ln | 201509 | 626.03 | c | na |
| 376100-Mains - Steel | 900973 | 3403L | Rel w/ 28F 2S Terrie Ln | 201510 | 300.47 | c | na |
| 376100-Mains - Steel | 900973 | 3403L | Rel w/ 28F 2S Terrie Ln | 201510 | 14.56 | c | na |
| 376100-Mains - Steel | 900973 | 3403L | Rel w/ 28F 2S Terrie Ln | 201511 | (2.21) | c | na |
| 376100-Mains - Steel | 900973 | 3403L | Rel w/ 28F 2S Terrie Ln | 201511 | (0.11) | c | na |
| 376100-Mains - Steel | 900973 | 3403L | Rel w/ 28F 2S Terrie Ln | 201512 | 132.71 | c | na |
| 376100-Mains - Steel | 900973 | 3403L | Rel w/ 28F 2S Terrie Ln | 201512 | 2,739.51 | c | na |
| 376100-Mains - Steel | 901007 | 3403L | Rel w/ 24F 6S Strecker | 201509 | (604.93) | c | na |
| 376300-Mains - Plastic | 901011 | 340RL | Rel w/ 450F 4P Sanford AOR | 201509 | (25,416.73) | a, c | A, B, C, F |
| 376300-Mains - Plastic | 901011 | 340RL | Rel w/ 450F 4P Sanford AOR | 201509 | (5,095.22) | a, c | A, B, C, F |
| 376300-Mains - Plastic | 901011 | 340RL | Rel w/ 450F 4P Sanford AOR | 201510 | (246.23) | a, c | A, B, C, F |
| 376300-Mains - Plastic | 901011 | 340RL | Rel w/ 450F 4P Sanford AOR | 201510 | (3.14) | a, c | A, B, C, F |
| 376300-Mains - Plastic | 901015 | 340RL | Rel w/ 35F 4P Elmbank & Taylor AOR | 201509 | (2,161.42) | a, c | A, B, C, F |
| 376300-Mains - Plastic | 901015 | 340RL | Rel w/ 35F 4P Elmbank & Taylor AOR | 201509 | (21.70) | a, c | A, B, C, F |
| 376100-Mains - Steel | 901019 | 3403L | Rel w/ 80F 6S Fee Fee | 201509 | (1,403.30) | c | na |
| 376100-Mains - Steel | 901019 | 3403L | Rel w/ 80F 6S Fee Fee | 201509 | 168.71 | c | na |
| 376100-Mains - Steel | 901019 | 3403L | Rel w/ 80F 6S Fee Fee | 201510 | (1,012.81) | c | na |
| 376100-Mains - Steel | 901019 | 3403L | Rel w/ 80F 6S Fee Fee | 201510 | (13.83) | c | na |
| 376300-Mains - Plastic | 901022 | 3403L | Rel w/ 427F 2P Valley Park SE | 201509 | (1,055.21) | c | na |
| 376300-Mains - Plastic | 901063 | 340RL | Rel w/ 1307F 4P Bessie AOR | 201509 | 131,541.58 | a, c | A, B, C, F |
| 376300-Mains - Plastic | 901063 | 340RL | Rel w/ 1307F 4P Bessie AOR | 201509 | 7,352.00 | a, c | A, B, C, F |
| 376300-Mains - Plastic | 901063 | 340RL | Rel w/ 1307F 4P Bessie AOR | 201510 | 320.00 | a, c | A, B, C, F |
| 376300-Mains - Plastic | 901063 | 340RL | Rel w/ 1307F 4P Bessie AOR | 201510 | 17.88 | a, c | A, B, C, F |
| 376300-Mains - Plastic | 901063 | 340RL | Rel w/ 1307F 4P Bessie AOR | 201511 | 6,584.69 | a, c | A, B, C, F |
| 376300-Mains - Plastic | 901063 | 340RL | Rel w/ 1307F 4P Bessie AOR | 201511 | 368.05 | a, c | A, B, C, F |
| 376300-Mains - Plastic | 901063 | 340RL | Rel w/ 1307F 4P Bessie AOR | 201512 | 1.64 | a, c | A, B, C, F |
| 376300-Mains - Plastic | 901063 | 340RL | Rel w/ 1307F 4P Bessie AOR | 201512 | 29.04 | a, c | A, B, C, F |
| 376300-Mains - Plastic | 901071 | 3403L | Rel w/ 285F 2P Froesel Ph2 | 201509 | (590.08) | c | na |
| 376300-Mains - Plastic | 901071 | 3403L | Rel w/ 285F 2P Froesel Ph2 | 201511 | (32.67) | c | na |
| 376300-Mains - Plastic | 901071 | 3403L | Rel w/ 285F 2P Froesel Ph2 | 201512 | (75.92) | c | na |
| 376100-Mains - Steel | 901081 | 3403L | Rel w/ 970F 6P Pralle Lane | 201512 | 57,603.32 | c | na |
| 376300-Mains - Plastic | 901081 | 3403L | Rel w/ 970F 6P Pralle Lane | 201512 | 1,947.67 | c | na |
| 376300-Mains - Plastic | 901081 | 3403L | Rel w/ 970F 6P Pralle Lane | 201512 | 86,951.39 | c | na |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |

Legend for State or Federal Safety Requirements

| | | Regulatory Section Description | Description of Capital Expenditure Rehabilitation or Replacement |
|----------|--------------------------------|---|--|
| A | 393.130 RSMo | Safe and Adequate Service | Replace, repair or remove unsafe pipeline segments |
| B | 4 CSR 240-40.030(13)(B) | General Requirements for Maintenance | Replace, repair or remove unsafe pipeline segments |
| C | 4 CSR 240-40.030(15) | Replacement Programs | Replacement program requirements for certain pipelines |
| D | 4 CSR 240-40.030(14) | Gas Leaks | Repair of system leaks through pipeline rehabilitation and replacements |
| E | 4 CSR 240-40.030(9)(T) and (U) | Corrosion Control | Remedial action in response to graphitization and corrosion through pipeline rehabilitation and replacements |
| F | 4 CSR 240-40.030(13)(Z) | Protecting or Replacing Disturbed Cast Iron Pipelines | Replacement of cast iron pipelines where support has been disturbed |
| G | 4 CSR 240-40.030(7) | Construction requirements | Construction expense associated with relocating and replacing pipelines |
| H | 4 CSR 240-40.030(10) | Testing Requirements | Testing expense associated with relocating and replacing pipelines |
| I | 4 CSR 240-40.030(13)(Y) | Maintenance - Caulked Bell and Spigot Joints | Install clamps and other sealing on exposed cast iron joints |
| J | 4 CSR 240-40.030(16) | Gas Transmission Pipeline Integrity Management | Replace, repair or remove unsafe transmission pipeline segments |
| K | 4 CSR 240-40.030(17) | Gas Distribution Pipeline Integrity Management | Replace, repair or remove unsafe distribution pipeline segments |
| L | 4 CSR 240-40.030(13)(S)(1) | Telemetry Requirement | Replace Worn or Deteriorated Telemetry/SCADA Equipment |
| M | 4 CSR 240-40.030(12)(P)(1) | Requirements for Odorization of Gas | Replace Worn or Deteriorated Odorization Equipment |

ISRS Statute 393.1009(5):

- (a) Mains, valves, service lines, regulator stations, vaults and other pipeline system components installed to comply with state or federal safety requirements as replacements for existing facilities that have worn out or are in deteriorated condition;
- (b) Main relining projects, service line insertion projects, joint encapsulation projects, and other similar projects extending the useful life or enhancing the integrity of pipeline system components undertaken to comply with state or federal safety requirements;
- (c) Facilities relocations required due to construction or improvement of a highway, road, street, public way, or other public work;

**P.S.C. MO. No. 5 Consolidated, Twenty-Sixth Revised Sheet No. 12
 CANCELLING P.S.C. MO. No. 5 Consolidated, Twenty-Fifth Revised Sheet No. 12**

Laclede Gas Company For Refer to Sheet No. 1
 Name of Issuing Corporation or Municipality Community, Town or City

SCHEDULE OF RATES

INFRASTRUCTURE SYSTEM REPLACEMENT SURCHARGE ("ISRS")

Description: The ISRS is designed to recover the costs associated with the Company's eligible infrastructure replacements in accordance with the provisions of Sections 393.1009 to 393.1015, RSMo.

Applicability: In addition to the other charges provided for in the Company's tariff, a monthly ISRS shall be added to each customer's bill for service rendered on and after the effective date of the ISRS.

Schedule of Surcharges: The amount of the ISRS by rate schedule is as follows:

| | |
|--|-----------|
| Residential General Service (RG) | \$ 2.98 |
| Residential Seasonal Air Conditioning Service (RA) | \$ 2.98 |
| Commercial & Industrial General Service-Class I (C1) | \$ 3.90 |
| Commercial & Industrial General Service-Class II (C2) | \$ 6.77 |
| Commercial & Industrial General Service-Class III (C3) | \$ 13.54 |
| Commercial & Industrial Seasonal Service-Class I | \$ 3.90 |
| Commercial & Industrial Seasonal Service-Class II | \$ 6.77 |
| Commercial & Industrial Seasonal Service-Class III | \$ 13.54 |
| Large Volume Service (LV) | \$ 133.77 |
| Interruptible Service (IN) | \$ 118.72 |
| General L.P. Gas Service (LP) | \$ 2.60 |
| Unmetered Gas Light Service (SL) | \$.87 |
| Vehicular Fuel Rate (VF) | \$ 3.38 |
| Large Volume Transportation and Sales Service (LVTSS) | \$ 316.53 |

DATE OF ISSUE February 1, 2016 DATE EFFECTIVE March 2, 2016
 Month Day Year Month Day Year

ISSUED BY L. Craig Dowdy, Sr. VP, Ext. Affairs, Market. & Comm., 700 Market St., St. Louis, MO 63101
 Name of Officer Title Address

**Laclede Gas Company
ISRS Revenue Requirement Calculation**

ISRS Activity:

Gas Utility Plant Projects - Main Replacements and Other Projects Extending Useful Life of Mains:

| | |
|--------------------------------------|------------------|
| <u>Work Orders Placed in Service</u> | |
| Gross Additions | 19,933,736 |
| Deferred Taxes | (3,781,676) |
| Accumulated Depreciation | <u>(105,765)</u> |

Total Net 16,046,295

Gas Utility Plant Projects - Service Line Replacements and Insertion Projects:

| | |
|--------------------------------------|------------------|
| <u>Work Orders Placed in Service</u> | |
| Gross Additions | 13,964,061 |
| Deferred Taxes | (2,856,341) |
| Accumulated Depreciation | <u>(215,625)</u> |

Total Net 10,892,095

Gas Utility Plant Projects - Regulator Stations:

| | |
|--------------------------------------|--------------|
| <u>Work Orders Placed in Service</u> | |
| Gross Additions | 11,842 |
| Deferred Taxes | (2,517) |
| Accumulated Depreciation | <u>(259)</u> |

Total Net 9,066

Gas Utility Plant Projects - Main Relocations net of Reimbursements:

| | |
|--------------------------------------|-----------------|
| <u>Work Orders Placed in Service</u> | |
| Gross Additions | 1,885,560 |
| Deferred Taxes | (393,056) |
| Accumulated Depreciation | <u>(11,562)</u> |

Total Net 1,480,942

Gas Utility Plant Projects - Main Reinforcements Related to Other ISRS Eligible Projects:

| | |
|--------------------------------------|----------|
| <u>Work Orders Placed in Service</u> | |
| Gross Additions | - |
| Deferred Taxes | - |
| Accumulated Depreciation | <u>-</u> |

Total Net -

**Increase in Accumulated Deferred Income Taxes and Accumulated Depreciation
Associated with Eligible Infrastructure System Replacements which are included in a
Currently Effective ISRS**

| | |
|--|--------------|
| Total Incremental Accumulated Depreciation | (1,719,789) |
| Total Incremental Accumulated Deferred Taxes | (10,753,193) |

| | |
|---|------------------|
| Total ISRS Rate Base | 15,955,415 |
| Overall Rate of Return per GR-2010-0171 | 7.1855% |
| UOI Required | 1,146,476 |
| Income Tax Conversion Factor | 1.62674 |
| Revenue Requirement Before Interest Deductibility | <u>1,865,015</u> |

| | |
|--|----------------|
| Total ISRS Rate Base | 15,955,415 |
| Weighted Cost of Debt per GR-2010-0171 | 2.0445% |
| Interest Deduction | 326,208 |
| Marginal Income Tax Rate | 38.5272% |
| Income Tax Reduction due to Interest | 125,679 |
| Income Tax Conversion Factor | 1.62674 |
| Revenue Requirement Impact of Interest Deductibility | <u>204,447</u> |

| | |
|---|----------------|
| Total Revenue Requirement on Capital | 1,660,568 |
| Depreciation Expense | 823,918 |
| Net Property Taxes | 2,081,864 |
| ISRS Revenue Undercollection January 2014 through December 2015 | <u>729,715</u> |

Total Company ISRS Revenues 5,296,064

Total Staff Expected ISRS Revenues 4,781,972

Average of Company and Staff Recommendations 5,039,018

**Laclede Gas Company
ISRS Depreciation Expense**

| | Additions <u>Annual Depreciation</u> | Retirements <u>Annual Depreciation</u> |
|--|---|---|
| Main Replacements | 329,555.09 | (11,906.35) |
| Service Line Replacements and Insertion Projects | 530,375.92 | (48,185.83) |
| Regulator Stations | 440.88 | (3,852.33) |
| Main Relocations net of Reimbursements | 29,377.01 | (1,885.91) |
| Main Reinforcements | - | - |
| | | |
| Total | <u>889,748.90</u> | <u>(65,830.42)</u> |
| | | |
| Total Net Increase in Depreciation Expense | <u><u>823,918.48</u></u> | |

Laclede Gas Company
ISRS Filing
Incremental Accumulated Deferred Income Taxes and Accumulated Depreciation

| <u>ISRS Activity:</u> | <u>Accumulated Depreciation</u> | <u>Accumulated Deferred Income Taxes</u> |
|--|-------------------------------------|--|
| <u>Main Replacements, etc.</u> | | |
| At October 15, 2015 | 2,109,931.87 | 10,182,356.73 |
| At April 15, 2016 | <u>2,829,956.65</u> | <u>16,802,030.99</u> |
| Incremental Change | <u><u>720,024.79</u></u> | <u><u>6,619,674.26</u></u> |
| <u>Services</u> | | |
| At October 15, 2015 | 3,176,241.47 | 8,115,843.39 |
| At April 15, 2016 | <u>4,081,024.82</u> | <u>11,549,662.94</u> |
| Incremental Change | <u><u>904,783.36</u></u> | <u><u>3,433,819.55</u></u> |
| <u>Regulator Stations</u> | | |
| At October 15, 2015 | 118,270.18 | 321,715.27 |
| At April 15, 2016 | <u>160,671.31</u> | <u>483,752.83</u> |
| Incremental Change | <u><u>42,401.13</u></u> | <u><u>162,037.56</u></u> |
| <u>Main Relocations</u> | | |
| At October 15, 2015 | 155,980.17 | 1,109,046.32 |
| At April 15, 2016 | <u>208,560.20</u> | <u>1,646,708.31</u> |
| Incremental Change | <u><u>52,580.03</u></u> | <u><u>537,661.99</u></u> |
| <u>Main Reinforcements</u> | | |
| At October 15, 2015 | 0.00 | 0.00 |
| At April 15, 2016 | <u>0.00</u> | <u>0.00</u> |
| Incremental Change | <u><u>0.00</u></u> | <u><u>0.00</u></u> |
| TOTAL INCREMENTAL CHANGE | <u><u>1,719,789.31</u></u> | <u><u>10,753,193.36</u></u> |
| 2013 ISRS Property Taxes as Updated - GO-2015-0259 | | 1,146,523.40 |
| 2013 ISRS Property Taxes as Updated | | 1,119,969.39 |
| 2014 ISRS Property Taxes As Filed - GO-2015-0259 | | 1,401,667.69 |
| 2014 ISRS Property Taxes as Updated | | <u>1,397,648.39</u> |
| Incremental Change | | <u><u>(30,573.31)</u></u> |

Laclede Gas Company
ISRS Calculation of Property Taxes

DISTRIBUTION REAL ESTATE

| <u>Service Additions</u> | <u>CY 2015</u> |
|--------------------------|-----------------------|
| Total Service Additions | 29,995,652.19 |
| | |
| Specific Real Additions | |
| 376.10 | 93,835.01 |
| Mains - 376s | <u>46,265,350.02</u> |
| Total Specific Additions | <u>46,359,185.03</u> |
| | |
| Retirements | |
| Services | (4,563,158.32) |
| Mains - Cast Iron | (929,785.81) |
| Mains - Steel | (425,073.28) |
| Mains - Plastic | <u>(866,481.43)</u> |
| | <u>(6,784,498.84)</u> |
| | |
| Net Real Estate | 69,570,338.38 |
| Assessment Rate | <u>32%</u> |
| Assessed Value | 22,262,508.28 |
| Real Estate Rate/\$100 | <u>9.4001</u> |
| Real Estate Taxes | <u>2,092,698.04</u> |

DISTRIBUTION PERSONAL PROPERTY

| | <u>CY 2015</u> |
|-------------------------------|----------------------------|
| 378.00 | 1,143,338.11 |
| 379.00 | <u>198,189.14</u> |
| Total Specific Personal | <u>1,341,527.25</u> |
| | |
| Specific Personal Retirements | |
| 378.00 | (609,700.59) |
| 379.00 | <u>-</u> |
| Total Specific Personal | <u>(609,700.59)</u> |
| | |
| Net Personal Property | 731,826.66 |
| Assessment Rate | <u>33.33%</u> |
| Assessed Value | 243,917.83 |
| Personal Prop. Rate/\$100 | <u>8.0924</u> |
| Personal Property Taxes | <u>19,738.81</u> |
| | |
| Total Property Taxes | <u><u>2,112,436.85</u></u> |

Laclede Gas Company
ISRS Calculation of Property Taxes

DISTRIBUTION REAL ESTATE

| <u>Service Additions</u> | <u>CY 2014</u> |
|--------------------------|----------------------|
| Total Service Additions | 20,487,474.86 |
| | |
| Specific Real Additions | |
| 376.10 | 146,354.35 |
| Mains - 376s | <u>27,961,113.68</u> |
| Total Specific Additions | <u>28,107,468.03</u> |
| | |
| Retirements | |
| Services | (2,233,590.68) |
| Mains - Cast Iron | (170,179.22) |
| Mains - Steel | (263,390.25) |
| Mains - Plastic | <u>(400,310.11)</u> |
| | (3,067,470.26) |
| | |
| Net Real Estate | 45,527,472.63 |
| Additional Depreciation | <u>(910,549.50)</u> |
| Net Real Estate | 44,616,923.13 |
| Assessment Rate | <u>32%</u> |
| Assessed Value | 14,568,791.24 |
| Real Estate Rate/\$100 | <u>9.4001</u> |
| Real Estate Taxes | <u>1,369,480.95</u> |

DISTRIBUTION PERSONAL PROPERTY

| | <u>CY 2014</u> |
|-------------------------------|----------------------------|
| 378.00 | 1,085,144.04 |
| 379.00 | <u>31,897.86</u> |
| Total Specific Personal | <u>1,117,041.90</u> |
| | |
| Specific Personal Retirements | |
| 378.00 | (52,139.21) |
| 379.00 | <u>(20,579.81)</u> |
| Total Specific Personal | <u>(72,719.02)</u> |
| | |
| Net Personal Property | 1,044,322.88 |
| Additional Depreciation | <u>(20,886.46)</u> |
| Net Personal Property | 1,023,436.42 |
| Assessment Rate | <u>33.33%</u> |
| Assessed Value | 348,072.82 |
| Personal Prop. Rate/\$100 | <u>8.0924</u> |
| Personal Property Taxes | <u>28,167.44</u> |
| | |
| Total Property Taxes | <u><u>1,397,648.39</u></u> |

**Laclede Gas Company
ISRS Calculation of Property Taxes**

DISTRIBUTION REAL ESTATE

| <u>Service Additions</u> | <u>CY 2013</u> |
|--------------------------|-----------------------|
| Total Service Additions | 20,603,856.57 |
| | |
| Specific Real Additions | |
| 376.10 | 94,489.81 |
| Mains - 376s | <u>21,854,496.43</u> |
| Total Specific Additions | <u>21,948,986.24</u> |
| | |
| Retirements | |
| Services | (2,719,397.88) |
| Mains - Cast Iron | (365,375.12) |
| Mains - Steel | (245,241.13) |
| Mains - Plastic | <u>(761,767.28)</u> |
| | (4,091,781.41) |
| | |
| Net Real Estate | 38,461,061.40 |
| Additional Depreciation | <u>(1,538,442.50)</u> |
| Net Real Estate | 36,922,618.90 |
| Assessment Rate | <u>32%</u> |
| Assessed Value | 11,815,238.05 |
| Real Estate Rate/\$100 | <u>9.4001</u> |
| Real Estate Taxes | <u>1,110,644.19</u> |

DISTRIBUTION PERSONAL PROPERTY

| | <u>CY 2013</u> |
|-------------------------------|----------------------------|
| 378.00 | 152,506.79 |
| 379.00 | <u>268,045.59</u> |
| Total Specific Personal | 420,552.38 |
| | |
| Specific Personal Retirements | |
| 378.00 | (60,411.02) |
| 379.00 | <u>1.00</u> |
| Total Specific Personal | (60,410.02) |
| | |
| Net Personal Property | 360,142.36 |
| Additional Depreciation | <u>(14,405.69)</u> |
| Net Personal Property | 345,736.67 |
| Assessment Rate | <u>33.33%</u> |
| Assessed Value | 115,234.03 |
| Personal Prop. Rate/\$100 | <u>8.0924</u> |
| Personal Property Taxes | <u>9,325.20</u> |
| | |
| Total Property Taxes | <u><u>1,119,969.39</u></u> |

Laclede Gas Company
ISRS Deferred Taxes — Rate Base Reduction

| Depreciation for the period for Plant in Service | Sept 1 - April 15 2015 - 2016 | | Sept 1 - April 15 2015 - 2016 | | Total | |
|---|----------------------------------|-------------------------------|----------------------------------|-------------------------------|-------|---------------|
| | Sept 2015 | | Oct - Feb 2015 - 2016 | | | |
| | B 20 Year Life 50% Bonus | C 20 Year Life 0% Bonus | B 20 Year Life 50% Bonus | C 20 Year Life 0% Bonus | | |
| <u>Main Replacements, etc.</u> Additions | 1,713,143.91 | - | - | 16,586,377.39 | - | 18,299,521.30 |
| Bonus Depreciation | 856,571.96 | - | - | 8,293,188.70 | - | 9,149,760.66 |
| Adjusted Tax Basis on Additions | 856,571.95 | - | - | 8,293,188.69 | - | 9,149,760.64 |
| Bonus Depreciation for Period | | | | | | |
| Sept 1 - Sept 30, 2014 | 856,571.96 | - | - | - | - | 856,571.96 |
| Oct 1, 2014 - Feb 28, 2015 | - | - | - | 8,293,188.70 | - | 8,293,188.70 |
| Tax Depreciation On Adj. Basis | | | | | | |
| Fiscal Year 2014 (Sep 1 - Sep 30) | 32,121.45 | - | - | - | - | 32,121.45 |
| Fiscal Year 2015 (Oct 1 - May 15)) | 61,835.93 | - | - | 310,994.58 | - | 372,830.51 |
| | 30,979.71 | - | - | 324,287.87 | - | 355,267.58 |
| Total Tax Depreciation | 981,509.05 | - | - | 8,928,471.15 | - | 9,909,980.20 |
| Total Book Depreciation | | | | | | 94,390.97 |
| Difference Between Book and Tax Depreciation | | | | | | 9,815,589.23 |
| Deferred Income Taxes (@38.5272%) | | | | | | 3,781,676.42 |

Laclede Gas Company
ISRS Deferred Taxes — Rate Base Reduction

| Depreciation for the period for Plant in Service | Sept 1 - April 15 2015 - 2016 | | | Sept 1 - April 15 2015 - 2016 | | | Total |
|---|----------------------------------|-------------------------------|---------------------------|----------------------------------|-------------------------------|-------|---------------|
| | Sept 2015 | | 15 Year Life 50% Bonus | Oct - Feb 2015 - 2016 | | Total | |
| | B 20 Year Life 50% Bonus | C 20 Year Life 0% Bonus | | B 20 Year Life 50% Bonus | C 20 Year Life 0% Bonus | | |
| <u>Services</u> | | | | | | | |
| Additions | 3,250,954.67 | - | - | - | 10,713,106.32 | - | 13,964,060.99 |
| Bonus Depreciation | 1,625,477.34 | - | - | - | 5,356,553.16 | - | 6,982,030.50 |
| Adjusted Tax Basis on Additions | 1,625,477.33 | - | - | - | 5,356,553.16 | - | 6,982,030.49 |
| Bonus Depreciation for Period | | | | | | | |
| Sept 1 - Sept 30, 2014 | 1,625,477.34 | - | - | - | - | - | 1,625,477.34 |
| Oct 1, 2014 - Feb 28, 2015 | - | - | - | - | 5,356,553.16 | - | 5,356,553.16 |
| Tax Depreciation On Adj. Basis | | | | | | | |
| Fiscal Year 2014 (Sep 1 - Sep 30) | 60,955.40 | - | - | - | - | - | 60,955.40 |
| Fiscal Year 2015 (Oct 1 - May 15)) | 117,343.21 | - | - | - | 200,870.74 | - | 318,213.95 |
| | 58,788.77 | - | - | - | 209,456.85 | - | 268,245.62 |
| Total Tax Depreciation | 1,862,564.72 | - | - | - | 5,766,880.75 | - | 7,629,445.47 |
| Total Book Depreciation | | | | | | | 215,624.57 |
| Difference Between Book and Tax Depreciation | | | | | | | 7,413,820.90 |
| Deferred Income Taxes (@38.5272%) | | | | | | | 2,856,341.17 |

Laclede Gas Company
ISRS Deferred Taxes — Rate Base Reduction

| Depreciation for the period for Plant in Service | FY 2013 Telemetry | Sept 1 - April 15 2015 - 2016 Sept 2015 | | | Sept 1 - April 15 2015 - 2016 Oct - Feb 2015 - 2016 | | | Total |
|---|---------------------------|--|--------------------------|---------------------------|--|---------------------------|--------------------------|-----------|
| | 20 Year Life 50% Bonus | 20 Year Life 50% Bonus | 20 Year Life 0% Bonus | 15 Year Life 50% Bonus | 20 Year Life 100% Bonus | 20 Year Life 50% Bonus | 20 Year Life 0% Bonus | |
| <u>Regulator Stations</u> | | | | | | | | |
| Additions | - | 12,083.34 | - | | - | (241.10) | - | 11,842.24 |
| Bonus Depreciation | - | 6,041.67 | - | - | - | (120.55) | - | 5,921.12 |
| Adjusted Tax Basis on Additions | - | 6,041.67 | - | - | - | (120.55) | - | 5,921.12 |
| Bonus Depreciation for Period | | | | | | | | |
| FY 2013 | - | | | | | | | |
| Sept 1 - Sept 30, 2014 | - | 6,041.67 | - | - | - | - | - | 6,041.67 |
| Oct 1, 2014 - Feb 28, 2015 | - | - | - | - | - | (120.55) | - | (120.55) |
| Tax Depreciation On Adj. Basis | | | | | | | | |
| Fiscal Year 2013 (Sept 1 - Sept 30) | - | | | | | | | |
| Fiscal Year 2014 (Sep 1 - Sep 30) | - | 226.56 | - | - | - | - | - | 226.56 |
| Fiscal Year 2015 (Oct 1 - May 15) | - | 436.15 | - | - | - | (4.52) | - | 431.63 |
| | - | 218.51 | - | - | - | (4.71) | - | 213.80 |
| Total Tax Depreciation | - | 6,922.89 | - | - | - | (129.78) | - | 6,793.11 |
| Total Book Depreciation | | | | | | | | 258.82 |
| Difference Between Book and Tax Depreciation | | | | | | | | 6,534.29 |
| Deferred Income Taxes (@38.5272%) | | | | | | | | 2,517.48 |

Laclede Gas Company
ISRS Deferred Taxes — Rate Base Reduction

| Depreciation for the period for Plant in Service | Sept 1 - April 15 2015 - 2016 | | | Sept 1 - April 15 2015 - 2016 | | | Total |
|---|----------------------------------|---------------------------|--------------------------|----------------------------------|--------------------------------|-------------------------------|--------------|
| | Sept 2015 | | | Oct - Feb 2015 - 2016 | | | |
| | 20 Year Life 100% Bonus | 20 Year Life 50% Bonus | 20 Year Life 0% Bonus | 0 20 Year Life 100% Bonus | B 20 Year Life 50% Bonus | C 20 Year Life 0% Bonus | |
| <u>Main Relocations</u> | | | | | | | |
| Additions | - | 484,137.26 | - | - | 1,401,423.01 | - | 1,885,560.27 |
| Bonus Depreciation | - | 242,068.63 | - | - | 700,711.51 | - | 942,780.14 |
| Adjusted Tax Basis on Additions | - | 242,068.63 | - | - | 700,711.50 | - | 942,780.13 |
| Bonus Depreciation for Period | | | | | | | |
| Sept 1 - Sept 30, 2014 | - | 242,068.63 | - | - | - | - | 242,068.63 |
| Oct 1, 2014 - Feb 28, 2015 | - | - | - | - | 700,711.51 | - | 700,711.51 |
| Tax Depreciation On Adj. Basis | | | | | | | |
| Fiscal Year 2014 (Sep 1 - Sep 30) | - | 9,077.57 | - | - | - | - | 9,077.57 |
| Fiscal Year 2015 (Oct 1 - May 15)) | - | 17,474.93 | - | - | 26,276.68 | - | 43,751.61 |
| | - | 8,754.92 | - | - | 27,399.86 | - | 36,154.78 |
| Total Tax Depreciation | - | 277,376.05 | - | - | 754,388.05 | - | 1,031,764.10 |
| Total Book Depreciation | | | | | | | 11,561.70 |
| Difference Between Book and Tax Depreciation | | | | | | | 1,020,202.40 |
| Deferred Income Taxes (@38.5272%) | | | | | | | 393,055.91 |

Laclede Gas Company
Capital Structure/Rate of Return for ISRS
Case GR-2013-0171

| | % of Cap Structure | Embedded Cost | Weighted Cost |
|---------------------------------|--------------------|---------------|----------------|
| LTD | 47.00% | 4.35% | 2.0445% |
| Preferred Stock | 0.00% | 0.00% | 0.0000% |
| Common Equity | 53.00% | 9.70% | 5.1410% |
| Total Capital * | | | <u>7.1855%</u> |
| | | | |
| Tax Multiplier | | | 1.626737 |
| | | | |
| Composite Weighted Cost of Debt | | | 2.0445% |

* Reflects Stipulation and Agreement in GR-2013-0171, Late Filed Exhibit 1

**Laclede Gas Company
ISRS Rate Design**

Total ISRS Revenues 5,039,018

| <u>Customer Rate Class</u> | <u>Number of Customers*</u> | <u>Customer Charge</u> | <u>Ratio to Residential Customer Charge</u> | <u>Weighted Customer Nos.</u> | <u>Customer Percentage</u> | <u>Current ISRS Charge</u> | <u>Current ISRS Revenues</u> |
|----------------------------|-----------------------------|------------------------|---|-------------------------------|----------------------------|----------------------------|------------------------------|
| Residential | 606,244 | 19.50 | 1.0000 | 606,244 | 87.9253% | 0.61 | 4,430,572 |
| C&I 1 | 30,943 | 25.50 | 1.3077 | 40,464 | 5.8686% | 0.80 | 295,720 |
| C&I 2 | 8,961 | 44.29 | 2.2713 | 20,352 | 2.9517% | 1.38 | 148,736 |
| C&I 3 | 600 | 88.57 | 4.5421 | 2,726 | 0.3954% | 2.77 | 19,922 |
| LV | 72 | 874.78 | 44.8605 | 3,245 | 0.4706% | 27.32 | 23,715 |
| Interruptible | 18 | 776.36 | 39.8133 | 720 | 0.1044% | 24.25 | 5,262 |
| Transportation | 148 | 2,069.94 | 106.1508 | 15,675 | 2.2734% | 64.65 | 114,556 |
| Transportation - Other** | 0 | 1,707.94 | 87.5867 | 0 | 0.0000% | 0.00 | 0 |
| Gas Light | 87 | 5.69 | 0.2918 | 26 | 0.0037% | 0.18 | 186 |
| Vehicular Fuel | 9 | 22.09 | 1.1328 | 10 | 0.0014% | 0.69 | 72 |
| Liquid Propane | 44 | 17.00 | 0.8718 | 38 | 0.0055% | 0.53 | 279 |
| Total | 647,126 | | | | 100.0000% | | 5,039,018 |

*Average customers - FY 2014

**Single customers with multiple accounts located on contiguous property.

Laclede Gas Company
ISRS Rate Design

Total ISRS Revenues 24,671,884

| <u>Customer Rate Class</u> | <u>Number of Customers*</u> | <u>Customer Charge</u> | <u>Ratio to Residential Customer Charge</u> | <u>Weighted Customer Nos.</u> | <u>Customer Percentage</u> | <u>Current ISRS Charge</u> | <u>Current ISRS Revenues</u> |
|----------------------------|-----------------------------|------------------------|---|-------------------------------|----------------------------|----------------------------|------------------------------|
| Residential | 606,244 | 19.50 | 1.0000 | 606,244 | 87.9253% | 2.98 | 21,692,828 |
| C&I 1 | 30,943 | 25.50 | 1.3077 | 40,464 | 5.8686% | 3.90 | 1,447,893 |
| C&I 2 | 8,961 | 44.29 | 2.2713 | 20,352 | 2.9517% | 6.77 | 728,235 |
| C&I 3 | 600 | 88.57 | 4.5421 | 2,726 | 0.3954% | 13.54 | 97,542 |
| LV | 72 | 874.78 | 44.8605 | 3,245 | 0.4706% | 133.77 | 116,110 |
| Interruptible | 18 | 776.36 | 39.8133 | 720 | 0.1044% | 118.72 | 25,762 |
| Transportation | 148 | 2,069.94 | 106.1508 | 15,675 | 2.2734% | 316.53 | 560,885 |
| Transportation - Other** | 0 | 1,707.94 | 87.5867 | 0 | 0.0000% | 0.00 | 0 |
| Gas Light | 87 | 5.69 | 0.2918 | 26 | 0.0037% | 0.87 | 913 |
| Vehicular Fuel | 9 | 22.09 | 1.1328 | 10 | 0.0014% | 3.38 | 351 |
| Liquid Propane | 44 | 17.00 | 0.8718 | 38 | 0.0055% | 2.60 | 1,365 |
| Total | 647,126 | | | | 100.0000% | | 24,671,884 |

*Average customers - FY 2014

**Single customers with multiple accounts located on contiguous property.

CALL CENTER INSTRUCTIONS ON ISRS

Revised January 2016

TO: All Customer Relations Employees
RE: Infrastructure System Replacement Surcharge ("ISRS")

WHAT IS AN ISRS?

The ISRS is a charge that covers a portion of the expenses that the Company must incur to maintain and upgrade its system to comply with safety requirements and to relocate facilities in connection with local, state, and federal public improvement projects.

The ISRS covers the costs for:

- Replacing worn or deteriorated pipes or other parts of our pipeline system to comply with federal or state safety requirements.
 - Examples: (i) Installing plastic mains as replacements for cast iron mains in connection with our cast iron main replacement program; (ii) Replacing a main or service line that has become unsafe due to leaks or corrosion.
- Projects that extend the useful life or enhance the integrity of pipeline components.
 - Example: Installing clamps to seal cast iron joints.
- Relocating facilities required by governmental entities in connection with public improvement projects such as a street or highway widening.
 - An example would be the Page Avenue extension that connected I-270 with Highway 94 in St. Charles.

The ISRS does NOT apply to:

- Costs for privately funded projects where Laclede receives reimbursement for its expenses. An example is Busch Stadium III, where Laclede was reimbursed by the Cardinals for work done.
- Costs incurred to build infrastructure that directly connects to new customers who will be billed for service.

HOW HAS THE ISRS BEEN CHARGED?

The ISRS has been charged as a flat fee per month. ISRS rates always start at -0- when Laclede finishes a rate case. So upon resolution of the Company's rate case in July 2013, the monthly ISRS was reset to \$-0- and costs for the facilities that were part of the previous ISRS were incorporated into the Company's overall rates. This included costs for plant in service as of January 31, 2013.

Between July 2013 and April 2014, there were no ISRS charges on customer bills. In April 2014, Laclede Gas re-established an ISRS with the approval of the Missouri Public Service Commission (MoPSC). After an ISRS is re-established, the Company may change the ISRS, again with MoPSC approval, up to two times per year.

As of December 1, 2015, the ISRS charge for Residential customers is \$2.37 per month. Commercial customers pay more per month than Residential Customers.

HOW IS THE ISRS BILLED?

When a new ISRS is established, the first ISRS bill for each customer will contain a bill message on the front of the bill known as the Initial Notice. Such a bill message does not appear when the ISRS amount merely changes. However, please note that an abbreviated version of this message is also permanently on the back of the bill under Definitions. Once each year, bills will also contain an Annual ISRS Notice. (Please see Attachment 1 for the Initial Notice and the Annual Notice).

Customers who call with ISRS questions during the first month that ISRS bills are rendered may be directed to the bill message on the front of the bill. After the first month, the ISRS is still defined on the back of the bill.

SUMMARY

If customers seek to discuss the ISRS charge in greater detail, please emphasize the following:

- The ISRS covers a portion of the expenses that the Company must incur to maintain and upgrade its system to comply with safety requirements, and to relocate facilities in connection with local, state, and federal public improvement projects.
- ISRS is authorized by Missouri law, which allows gas utilities like Laclede to adjust their rates up to two times per year to recover these mandated costs.
- None of the mandated costs and projects covered by ISRS produce any new revenue for the Company. Any projects for which Laclede is separately reimbursed are not included in the ISRS.
- The financial impact of the ISRS is very modest. It is less for residential customers than for larger commercial and industrial customers. Since Laclede first established an ISRS in 2004, the residential ISRS has always been less than \$3 per month.

ATTACHMENT I

INITIAL NOTICE

ISRS

Each year, Laclede spends tens of millions of dollars on its more than 16,000 miles of pipeline facilities used to deliver gas to its customers. The infrastructure system replacement surcharge (ISRS) covers only a part of the expenses that the Company must incur to maintain and upgrade its system and to relocate facilities in connection with local, state and federal public improvement projects and safety requirements. In general, the ISRS charge to cover these costs is smaller for residential customers, while larger users in other customer classes are charged a greater amount. The amount of the charge may be adjusted periodically, and is being implemented in accordance with Sections 393.1009, 393.1012 and 393.1015 of the Revised Statutes of Missouri.

ANNUAL NOTICE

ISRS

Each year, Laclede spends tens of millions of dollars on its more than 16,000 miles of pipeline facilities used to deliver gas to its customers. The infrastructure system replacement surcharge (ISRS) covers only a part of the expenses that the Company must incur to maintain and upgrade its system and to relocate facilities in connection with local, state and federal public improvement projects and safety requirements. In general, the ISRS charge to cover these costs is smaller for residential customers, while larger users in other customer classes are charged a greater amount. The amount of the charge, which is reflected on the front of your bill, may be adjusted periodically, and has been implemented in accordance with Sections 393.1009, 393.1012 and 393.1015 of the Revised Statutes of Missouri.



- » ABOUT LACLEDE GAS
- » COMMUNITY SERVICE
- » RATES & REGULATIONS
- » CAREERS

✓ I AM LOOKING FOR...

RATES & REGULATIONS

[Home](#) / [Rates & Regulations](#)

» RESIDENTIAL RATE SUMMARY

» PGA EXPLANATION

» ISRS

» RATE SCHEDULES & CLAUSES

» RULES & REGULATIONS

» GAS SUPPLY RFP POSTINGS

ISRS

Each year Laclede spends tens of millions of dollars on its more than 16,000 miles of pipeline facilities used to deliver gas to its customers. The infrastructure system replacement surcharge (ISRS) covers only a part of the expenses that the Company must incur to maintain and upgrade its system and to relocate facilities in connection with local, state and federal public improvement projects and safety requirements. In general, the ISRS charge to cover these costs is smaller for residential customers, while larger users in other customer classes are charged a greater amount. The amount of the charge may be adjusted periodically, and is being implemented in accordance with a new law contained in Sections 393.1009, 393.1012 and 393.1015 of the Revised Statutes of Missouri.

To view the tariff sheet detailing the order and schedule of rates click [here](#).

MAIN REPLACEMENTS - ADDITIONS

| PLANT ACCOUNT | WORK ORDER | BUDGET PROJECT | DESCRIPTION | IN SERVICE DATE | ADDITION AMOUNT | MONTHS | DEPR. MO. RATE | ACCUM. DEPR. | DEPR. EXPENSE |
|------------------------|------------|----------------|-------------------------------------|-----------------|-----------------|--------|----------------|--------------|---------------|
| 376100-Mains - Steel | 699000 | 3301L | 69900 MAIN STL INST MTCE | 201507 | (4.85) | 3 | 0.0012000 | (0.02) | (0.07) |
| 376100-Mains - Steel | 699500 | 3301L | 69950 MAIN STL INST MTCE | 201507 | 1,723.26 | 3 | 0.0012000 | 6.20 | 24.81 |
| 376100-Mains - Steel | 900379 | 3303L | Inst 783F 4P & 529F 2P Old Bonhomme | 201507 | 0.31 | 3 | 0.0012000 | - | - |
| 376100-Mains - Steel | 900677 | 3303L | Inst 1795F 2P Cole & 18th PhA | 201507 | (118.33) | 3 | 0.0012000 | (0.43) | (1.70) |
| 376100-Mains - Steel | 901112 | 3303L | UGS Gathering Line Replacement | 201507 | 3,659.54 | 3 | 0.0012000 | 13.17 | 52.70 |
| 376100-Mains - Steel | 900474 | 3304L | Repl w/ 3774F 8P 8S Mullianphy | 201507 | (6.32) | 3 | 0.0012000 | (0.02) | (0.09) |
| 376100-Mains - Steel | 900479 | 3304L | Inst 3525F 8P Union | 201507 | (143.21) | 3 | 0.0012000 | (0.52) | (2.06) |
| 376100-Mains - Steel | 900485 | 3304L | Inst 4236F 12P Alaska | 201507 | (0.05) | 3 | 0.0012000 | - | - |
| 376100-Mains - Steel | 900596 | 3304L | Inst 3200F 8P Holly Hills | 201507 | (135.31) | 3 | 0.0012000 | (0.49) | (1.95) |
| 376100-Mains - Steel | 900597 | 3304L | Inst 5626F 12P Lindell | 201507 | (481.84) | 3 | 0.0012000 | (1.73) | (6.94) |
| 376100-Mains - Steel | 900629 | 3304L | Inst 4820F 8P Kingshighway & McRee | 201507 | (1,360.72) | 3 | 0.0012000 | (4.90) | (19.59) |
| 376100-Mains - Steel | 900709 | 3304L | Repl w/ 2662F 8P Natural Bridge | 201507 | (49.24) | 3 | 0.0012000 | (0.18) | (0.71) |
| 376300-Mains - Plastic | 698000 | 3301L | 69800 MAIN VAR INST MTCE | 201507 | 8,926.56 | 3 | 0.0013083 | 35.04 | 140.14 |
| 376300-Mains - Plastic | 699220 | 3301L | 69922 MAIN PLS INST MTCE | 201507 | 13,510.08 | 3 | 0.0013083 | 53.03 | 212.10 |
| 376300-Mains - Plastic | 699720 | 3301L | 69972 MAIN PLS INST MTCE | 201507 | 37,551.75 | 3 | 0.0013083 | 147.39 | 589.55 |
| 376300-Mains - Plastic | 698000 | 3301M | 69800 MAIN VAR INST MTCE | 201507 | (137.01) | 3 | 0.0013083 | (0.54) | (2.15) |
| 376300-Mains - Plastic | 001040 | 3303L | Install 46F 4P Nashville | 201507 | (0.18) | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 001330 | 3303L | Inst 9084F 2P Aberdeen PI | 201507 | (878.90) | 3 | 0.0013083 | (3.45) | (13.80) |
| 376300-Mains - Plastic | 001535 | 3303L | Repl w/ 9098F 2P Arlington | 201507 | (21.01) | 3 | 0.0013083 | (0.08) | (0.33) |
| 376300-Mains - Plastic | 001711 | 3303L | Inst 7023F 2P Northmoor Wydown Ph5 | 201507 | 2.12 | 3 | 0.0013083 | 0.01 | 0.03 |
| 376300-Mains - Plastic | 001712 | 3303L | Inst 16489F 2P Cote Brilliante | 201507 | 83,490.16 | 3 | 0.0013083 | 327.69 | 1,310.76 |
| 376300-Mains - Plastic | 002137 | 3303L | Repl w/ 5955F 2P Boneta | 201507 | 21.63 | 3 | 0.0013083 | 0.08 | 0.34 |
| 376300-Mains - Plastic | 002138 | 3303L | Repl w/ 10203F 2P Manchester | 201507 | (729.59) | 3 | 0.0013083 | (2.86) | (11.45) |
| 376300-Mains - Plastic | 002141 | 3303L | Inst 6161F 2P Marshall-Well. Ph4C | 201507 | 0.50 | 3 | 0.0013083 | - | 0.01 |
| 376300-Mains - Plastic | 900068 | 3303L | Repl w/ 1750F 2P Jefferson Ph 2 | 201507 | (842.73) | 3 | 0.0013083 | (3.31) | (13.23) |
| 376300-Mains - Plastic | 900072 | 3303L | Repl w 688F 2P & 2527F 4P Lafayette | 201507 | 0.49 | 3 | 0.0013083 | - | 0.01 |
| 376300-Mains - Plastic | 900073 | 3303L | Repl w/ 2520F 2P Jefferson Ph 6 | 201507 | (980.12) | 3 | 0.0013083 | (3.85) | (15.39) |
| 376300-Mains - Plastic | 900073 | 3303L | Repl w/ 2520F 2P Jefferson Ph 6 | 201507 | (40.41) | 3 | 0.0013083 | (0.16) | (0.63) |
| 376300-Mains - Plastic | 900093 | 3303L | Repl w/ 184F 2P Cass | 201507 | (0.08) | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900264 | 3303L | Int 3087F 4P 2P Baden Grid Ph 5A | 201507 | (41.29) | 3 | 0.0013083 | (0.16) | (0.65) |
| 376300-Mains - Plastic | 900265 | 3303L | Repl w/ 3337F 2P Baden Ph 5B | 201507 | (1.53) | 3 | 0.0013083 | (0.01) | (0.02) |
| 376300-Mains - Plastic | 900266 | 3303L | Inst 4840F 2P Baden Ph 5C | 201507 | (1.73) | 3 | 0.0013083 | (0.01) | (0.03) |
| 376300-Mains - Plastic | 900267 | 3303L | Repl w/ 4536F 2P Baden Ph5D | 201507 | (2.49) | 3 | 0.0013083 | (0.01) | (0.04) |
| 376300-Mains - Plastic | 900268 | 3303L | Inst 4411F 2P Baden Ph5E | 201507 | (2.45) | 3 | 0.0013083 | (0.01) | (0.04) |
| 376300-Mains - Plastic | 900269 | 3303L | Inst 1150F 4P Walnut Park Ph 5A | 201507 | (243.94) | 3 | 0.0013083 | (0.96) | (3.83) |
| 376300-Mains - Plastic | 900275 | 3303L | Repl w/ 4989F 2P Wellington Ph4E | 201507 | 159.78 | 3 | 0.0013083 | 0.63 | 2.51 |
| 376300-Mains - Plastic | 900277 | 3303L | Repl w/ 1725F 2P Walnut Park Ph4B | 201507 | (9.13) | 3 | 0.0013083 | (0.04) | (0.14) |
| 376300-Mains - Plastic | 900278 | 3303L | Repl w/ 3977F 2P Walnut Park Ph4C | 201507 | (20.78) | 3 | 0.0013083 | (0.08) | (0.33) |
| 376300-Mains - Plastic | 900279 | 3303L | Repl w/ 3345F 2P Walnut Park Ph4D | 201507 | (611.65) | 3 | 0.0013083 | (2.40) | (9.60) |
| 376300-Mains - Plastic | 900281 | 3303L | Inst 4964F 4P Wellston Phase 2B | 201507 | 3.90 | 3 | 0.0013083 | 0.02 | 0.06 |
| 376300-Mains - Plastic | 900282 | 3303L | Inst 4400F 2P Wellston 2C | 201507 | (70.49) | 3 | 0.0013083 | (0.28) | (1.11) |
| 376300-Mains - Plastic | 900283 | 3303L | Inst 5300F 2P Wellston Ph2D | 201507 | (1.28) | 3 | 0.0013083 | (0.01) | (0.02) |
| 376300-Mains - Plastic | 900284 | 3303L | Inst 5466F 2P Wellston Ph2E | 201507 | (552.79) | 3 | 0.0013083 | (2.17) | (8.68) |
| 376300-Mains - Plastic | 900375 | 3303L | Inst 1747F 6P Litzinger | 201507 | (3.39) | 3 | 0.0013083 | (0.01) | (0.05) |
| 376300-Mains - Plastic | 900377 | 3303L | Repl w/ 978F 2-4P Big Bend | 201507 | (175.20) | 3 | 0.0013083 | (0.69) | (2.75) |
| 376300-Mains - Plastic | 900379 | 3303L | Inst 783F 4P & 529F 2P Old Bonhomme | 201507 | 2.39 | 3 | 0.0013083 | 0.01 | 0.04 |
| 376300-Mains - Plastic | 900388 | 3303L | Repl w/ 332F 2P Tay Rd | 201507 | 2.90 | 3 | 0.0013083 | 0.01 | 0.05 |
| 376300-Mains - Plastic | 900390 | 3303L | Inst 205F 1 1/4P Gore | 201507 | 2.16 | 3 | 0.0013083 | 0.01 | 0.03 |
| 376300-Mains - Plastic | 900392 | 3303L | Inst 580F 4P & 255F 2P Ferguson | 201507 | (1.32) | 3 | 0.0013083 | (0.01) | (0.02) |
| 376300-Mains - Plastic | 900395 | 3303L | Repl w/ 525F 2P Clay St | 201507 | 0.74 | 3 | 0.0013083 | - | 0.01 |
| 376300-Mains - Plastic | 900412 | 3303L | Repl w/ 412F 6P Holly Hills | 201507 | (11.70) | 3 | 0.0013083 | (0.05) | (0.18) |

| | | | | | | | | | |
|------------------------|--------|-------|-------------------------------------|--------|------------|---|-----------|---------|----------|
| 376300-Mains - Plastic | 900415 | 3303L | Repl w/ 1093F 2P Princeton | 201507 | 2.05 | 3 | 0.0013083 | 0.01 | 0.03 |
| 376300-Mains - Plastic | 900420 | 3303L | Repl w/ 520F 2P Oregon | 201507 | 4.09 | 3 | 0.0013083 | 0.02 | 0.06 |
| 376300-Mains - Plastic | 900421 | 3303L | Repl w/ 970F 2P Winnebago | 201507 | 5.10 | 3 | 0.0013083 | 0.02 | 0.08 |
| 376300-Mains - Plastic | 900422 | 3303L | Repl w/ 780F 2P Taft | 201507 | 2.00 | 3 | 0.0013083 | 0.01 | 0.03 |
| 376300-Mains - Plastic | 900423 | 3303L | Repl w/ 1373F 2P Dr MLK | 201507 | 0.15 | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900424 | 3303L | Repl w/ 520F 3P Red Bud | 201507 | (5.42) | 3 | 0.0013083 | (0.02) | (0.09) |
| 376300-Mains - Plastic | 900430 | 3303L | Repl w/ 654F 2P Maurice | 201507 | 3.09 | 3 | 0.0013083 | 0.01 | 0.05 |
| 376300-Mains - Plastic | 900432 | 3303L | Repl w/ 503F 2P Gravois | 201507 | (0.78) | 3 | 0.0013083 | - | (0.01) |
| 376300-Mains - Plastic | 900433 | 3303L | Repl w/ 570F 4P Chippewa | 201507 | 5.28 | 3 | 0.0013083 | 0.02 | 0.08 |
| 376300-Mains - Plastic | 900439 | 3303L | Repl w/ 269F 2P Ferguson | 201507 | 2.27 | 3 | 0.0013083 | 0.01 | 0.04 |
| 376300-Mains - Plastic | 900457 | 3303L | Inst 4546F 2P Baden Ph5F | 201507 | 1.13 | 3 | 0.0013083 | - | 0.02 |
| 376300-Mains - Plastic | 900460 | 3303L | Inst 3488F 2P Walnut Park Ph4E | 201507 | 2.71 | 3 | 0.0013083 | 0.01 | 0.04 |
| 376300-Mains - Plastic | 900461 | 3303L | Inst 893F 2P Walnut Park Ph4F | 201507 | 0.05 | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900462 | 3303L | Repl w/ 2240F 2P Walnut Park Ph4G | 201507 | (37.18) | 3 | 0.0013083 | (0.15) | (0.58) |
| 376300-Mains - Plastic | 900463 | 3303L | Inst 4082F 2P Walnut Park Ph4H | 201507 | 485.43 | 3 | 0.0013083 | 1.91 | 7.62 |
| 376300-Mains - Plastic | 900464 | 3303L | Inst 4741F 2P Walnut Park Ph 4I | 201507 | (190.63) | 3 | 0.0013083 | (0.75) | (2.99) |
| 376300-Mains - Plastic | 900467 | 3303L | Repl w/ 2400F 2-4P Potomac AOR | 201507 | 0.16 | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900557 | 3303L | Inst 2123F 2P Walnut Park Ph6A | 201507 | (900.04) | 3 | 0.0013083 | (3.53) | (14.13) |
| 376300-Mains - Plastic | 900623 | 3303L | Repl w/ 2852' 2P Wydown Ph 6 | 201507 | (5,439.37) | 3 | 0.0013083 | (21.35) | (85.40) |
| 376300-Mains - Plastic | 900677 | 3303L | Inst 1795F 2P Cole & 18th PhA | 201507 | (1,228.89) | 3 | 0.0013083 | (4.82) | (19.29) |
| 376300-Mains - Plastic | 900679 | 3303L | Inst 2312F 4P Cole & 18th PhB | 201507 | (2,150.89) | 3 | 0.0013083 | (8.44) | (33.77) |
| 376300-Mains - Plastic | 900681 | 3303L | Inst 1637F 2P Cole & 18th Ph C | 201507 | (4,353.82) | 3 | 0.0013083 | (17.09) | (68.35) |
| 376300-Mains - Plastic | 900683 | 3303L | Inst 1864F 2P Cole & 18th Ph D | 201507 | (323.29) | 3 | 0.0013083 | (1.27) | (5.08) |
| 376300-Mains - Plastic | 900685 | 3303L | Inst 1550F 2P Cole & 18th PhE | 201507 | 3,461.98 | 3 | 0.0013083 | 13.59 | 54.35 |
| 376300-Mains - Plastic | 900687 | 3303L | Inst 1096F 2P Cole & 18th PhF | 201507 | 8,576.50 | 3 | 0.0013083 | 33.66 | 134.65 |
| 376300-Mains - Plastic | 900689 | 3303L | Inst 2434F 2P Cole & 18th PhG | 201507 | 19,396.78 | 3 | 0.0013083 | 76.13 | 304.52 |
| 376300-Mains - Plastic | 900691 | 3303L | Repl w/ 3458F 2P Cole & 18th Ph H | 201507 | 99,392.77 | 3 | 0.0013083 | 390.11 | 1,560.43 |
| 376300-Mains - Plastic | 900759 | 3303L | Repl w/ 2836F 2P Hickory Dale | 201507 | 853.42 | 3 | 0.0013083 | 3.35 | 13.40 |
| 376300-Mains - Plastic | 900762 | 3303L | Inst 2069F 2P Earthquake Zone Ph1A | 201507 | (347.03) | 3 | 0.0013083 | (1.36) | (5.45) |
| 376300-Mains - Plastic | 900763 | 3303L | Inst 3508F 2P Earthquake Zone Ph1B | 201507 | (1,878.80) | 3 | 0.0013083 | (7.37) | (29.50) |
| 376300-Mains - Plastic | 900764 | 3303L | Repl w/758F 2P Earthquake Zone Ph1C | 201507 | (262.72) | 3 | 0.0013083 | (1.03) | (4.12) |
| 376300-Mains - Plastic | 900765 | 3303L | Inst 1899F 4P Earthquake Zone Ph1D | 201507 | (1,611.34) | 3 | 0.0013083 | (6.32) | (25.30) |
| 376300-Mains - Plastic | 900859 | 3303L | Repl w/ 290F 2P Cabanne | 201507 | (261.36) | 3 | 0.0013083 | (1.03) | (4.10) |
| 376300-Mains - Plastic | 900861 | 3303L | Repl w/ 105F 4P McLaran | 201507 | (50.26) | 3 | 0.0013083 | (0.20) | (0.79) |
| 376300-Mains - Plastic | 900862 | 3303L | Rep w/ 4552F 2P Broadway AOR | 201507 | 79,139.14 | 3 | 0.0013083 | 310.61 | 1,242.45 |
| 376300-Mains - Plastic | 900890 | 3303L | Repl w/ 2218F 2P Russell & Flora | 201507 | (2,081.66) | 3 | 0.0013083 | (8.17) | (32.68) |
| 376300-Mains - Plastic | 900895 | 3303L | Repl w/ 828F 2P Marquette | 201507 | (211.58) | 3 | 0.0013083 | (0.83) | (3.32) |
| 376300-Mains - Plastic | 900898 | 3303L | Repl w/ 1220F 2P Ohio | 201507 | (4,849.47) | 3 | 0.0013083 | (19.03) | (76.13) |
| 376300-Mains - Plastic | 900900 | 3303L | Repl w/ 1075F 2P Washington | 201507 | (649.87) | 3 | 0.0013083 | (2.55) | (10.20) |
| 376300-Mains - Plastic | 900902 | 3303L | Repl w/ 530' 2P Oakland | 201507 | 11,116.24 | 3 | 0.0013083 | 43.63 | 174.52 |
| 376300-Mains - Plastic | 900905 | 3303L | Repl w/ 806F 2P Utah | 201507 | (156.82) | 3 | 0.0013083 | (0.62) | (2.46) |
| 376300-Mains - Plastic | 900908 | 3303L | Repl w/ 460F 2P California | 201507 | (141.93) | 3 | 0.0013083 | (0.56) | (2.23) |
| 376300-Mains - Plastic | 900912 | 3303L | Repl w/ 745F 2P Shaw | 201507 | 2,062.64 | 3 | 0.0013083 | 8.10 | 32.38 |
| 376300-Mains - Plastic | 900921 | 3303L | Repl w/ 2457F 4P&2P Flad AOR | 201507 | (450.52) | 3 | 0.0013083 | (1.77) | (7.07) |
| 376300-Mains - Plastic | 900932 | 3303L | Repl w/ 160F 2P Cler Ave | 201507 | (39.26) | 3 | 0.0013083 | (0.15) | (0.62) |
| 376300-Mains - Plastic | 900948 | 3303L | Repl w/ 132F 2P Southcote | 201507 | (184.87) | 3 | 0.0013083 | (0.73) | (2.90) |
| 376300-Mains - Plastic | 900977 | 3303L | Repl w/ 1291F 4P Boyle | 201507 | (252.98) | 3 | 0.0013083 | (0.99) | (3.97) |
| 376300-Mains - Plastic | 900986 | 3303L | Repl w/ 2189F 2P Earthquake Zone 2A | 201507 | (7,278.33) | 3 | 0.0013083 | (28.57) | (114.27) |
| 376300-Mains - Plastic | 002434 | 3303M | Deer Run main replacement | 201507 | 18,980.50 | 3 | 0.0013083 | 74.50 | 297.99 |
| 376300-Mains - Plastic | 000569 | 3304L | 4015F 6P 2P Lemay Ferry | 201507 | 0.92 | 3 | 0.0013083 | - | 0.01 |
| 376300-Mains - Plastic | 900169 | 3304L | Inst 6228F 8P Loughborough | 201507 | 0.38 | 3 | 0.0013083 | - | 0.01 |
| 376300-Mains - Plastic | 900170 | 3304L | Inst 3526F 6P Field & Koeln | 201507 | (0.20) | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900262 | 3304L | Inst 7615F 12P Clifton Hill-Columbi | 201507 | (1,592.92) | 3 | 0.0013083 | (6.25) | (25.01) |
| 376300-Mains - Plastic | 900393 | 3304L | Inst 3745F 8P Clayton Ave | 201507 | 1.12 | 3 | 0.0013083 | - | 0.02 |
| 376300-Mains - Plastic | 900456 | 3304L | Inst 8175F 8P Jamieson McCausland | 201507 | (1.90) | 3 | 0.0013083 | (0.01) | (0.03) |

| | | | | | | | | | |
|------------------------|--------|-------|-------------------------------------|--------|------------|---|-----------|---------|----------|
| 376300-Mains - Plastic | 900474 | 3304L | Repl w/ 3774F 8P 8S Mullanphy | 201507 | (21.19) | 3 | 0.0013083 | (0.08) | (0.33) |
| 376300-Mains - Plastic | 900475 | 3304L | Inst 1895F 6P Koeln | 201507 | (2,699.12) | 3 | 0.0013083 | (10.59) | (42.38) |
| 376300-Mains - Plastic | 900479 | 3304L | Inst 3525F 8P Union | 201507 | (4,966.61) | 3 | 0.0013083 | (19.49) | (77.97) |
| 376300-Mains - Plastic | 900480 | 3304L | Inst 4528 8P Minerva | 201507 | (8.05) | 3 | 0.0013083 | (0.03) | (0.13) |
| 376300-Mains - Plastic | 900481 | 3304L | Inst 3125F 8P Union | 201507 | 5.52 | 3 | 0.0013083 | 0.02 | 0.09 |
| 376300-Mains - Plastic | 900484 | 3304L | Inst 5203F 12P Ivanhoe | 201507 | (1,342.54) | 3 | 0.0013083 | (5.27) | (21.08) |
| 376300-Mains - Plastic | 900485 | 3304L | Inst 4236F 12P Alaska | 201507 | (7.83) | 3 | 0.0013083 | (0.03) | (0.12) |
| 376300-Mains - Plastic | 900486 | 3304L | Inst 6210F 8P Jamieson | 201507 | 0.36 | 3 | 0.0013083 | - | 0.01 |
| 376300-Mains - Plastic | 900487 | 3304L | Inst 4845F 8P Loughborough | 201507 | (616.96) | 3 | 0.0013083 | (2.42) | (9.69) |
| 376300-Mains - Plastic | 900488 | 3304L | Repl w/ 2873F 6P Hociamont | 201507 | (2.51) | 3 | 0.0013083 | (0.01) | (0.04) |
| 376300-Mains - Plastic | 900585 | 3304L | Inst 8458F 8P 8S Lindell | 201507 | (3,207.45) | 3 | 0.0013083 | (12.59) | (50.36) |
| 376300-Mains - Plastic | 900595 | 3304L | Inst 4616F 8P Alaska | 201507 | (8.77) | 3 | 0.0013083 | (0.03) | (0.14) |
| 376300-Mains - Plastic | 900596 | 3304L | Inst 3200F 8P Holly Hills | 201507 | (1,618.88) | 3 | 0.0013083 | (6.35) | (25.42) |
| 376300-Mains - Plastic | 900597 | 3304L | Inst 5626F 12P Lindell | 201507 | (5,027.19) | 3 | 0.0013083 | (19.73) | (78.92) |
| 376300-Mains - Plastic | 900598 | 3304L | Inst 5746F 8P Winnebago-Gravois | 201507 | (9,616.82) | 3 | 0.0013083 | (37.75) | (150.98) |
| 376300-Mains - Plastic | 900629 | 3304L | Inst 4820F 8P Kingshighway & McRee | 201507 | (5,956.40) | 3 | 0.0013083 | (23.38) | (93.51) |
| 376300-Mains - Plastic | 900635 | 3304L | Inst 1228F 8P Manchester | 201507 | 3.10 | 3 | 0.0013083 | 0.01 | 0.05 |
| 376300-Mains - Plastic | 900643 | 3304L | Inst 1801F 6P-12P Marmaduke/Hudler | 201507 | (4,245.88) | 3 | 0.0013083 | (16.66) | (66.66) |
| 376300-Mains - Plastic | 900644 | 3304L | Inst 4190F 8P Evans | 201507 | (235.25) | 3 | 0.0013083 | (0.92) | (3.69) |
| 376300-Mains - Plastic | 900645 | 3304L | Inst 4690F 8P Vandeventer | 201507 | (1,620.32) | 3 | 0.0013083 | (6.36) | (25.44) |
| 376300-Mains - Plastic | 900668 | 3304L | Inst 5690F 8P Cora | 201507 | 11.06 | 3 | 0.0013083 | 0.04 | 0.17 |
| 376300-Mains - Plastic | 900669 | 3304L | Inst 4565F 8P Page & Evans | 201507 | (0.24) | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900692 | 3304L | Inst 3834F 8P Lindell | 201507 | (22.58) | 3 | 0.0013083 | (0.09) | (0.35) |
| 376300-Mains - Plastic | 900709 | 3304L | Repl w/ 2662F 8P Natural Bridge | 201507 | (1,190.77) | 3 | 0.0013083 | (4.67) | (18.89) |
| 376300-Mains - Plastic | 900711 | 3304L | Inst 4010F 8P Natural Bridge | 201507 | (3,510.43) | 3 | 0.0013083 | (13.78) | (55.11) |
| 376300-Mains - Plastic | 900713 | 3304L | Inst 4816F 8P Penrod & Sulphur | 201507 | (1,717.94) | 3 | 0.0013083 | (6.74) | (26.97) |
| 376300-Mains - Plastic | 900786 | 3304L | Inst 6713F 8P Chippewa & Tholozan | 201507 | (7,390.84) | 3 | 0.0013083 | (29.01) | (116.03) |
| 376300-Mains - Plastic | 900787 | 3304L | Inst 4235F 8P Beck Ave | 201507 | (4,563.25) | 3 | 0.0013083 | (17.91) | (71.64) |
| 376300-Mains - Plastic | 900849 | 3304L | Inst 850F 12P Whittier Header | 201507 | (1,051.99) | 3 | 0.0013083 | (4.13) | (16.52) |
| 376300-Mains - Plastic | 900068 | 3303L | Repl w/ 1750F 2P Jefferson Ph 2 | 201507 | (11.26) | 3 | 0.0013083 | (0.04) | (0.18) |
| 376300-Mains - Plastic | 900072 | 3303L | Repl w 688F 2P & 2527F 4P Lafayette | 201507 | 0.03 | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900073 | 3303L | Repl w/ 2520F 2P Jefferson Ph 6 | 201507 | (75.36) | 3 | 0.0013083 | (0.30) | (1.18) |
| 376300-Mains - Plastic | 900264 | 3303L | Int 3087F 4P 2P Baden Grid Ph 5A | 201507 | (1.57) | 3 | 0.0013083 | (0.01) | (0.02) |
| 376300-Mains - Plastic | 900265 | 3303L | Repl w/ 3337F 2P Baden Ph 5B | 201507 | (0.05) | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900266 | 3303L | Inst 4640F 2P Baden Ph 5C | 201507 | (0.05) | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900267 | 3303L | Repl w/ 4536F 2P Baden Ph5D | 201507 | (0.07) | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900268 | 3303L | Inst 4411F 2P Baden Ph5E | 201507 | (0.10) | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900275 | 3303L | Repl w/ 4989F 2P Wellington Ph4E | 201507 | 0.29 | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900277 | 3303L | Repl w/ 1725F 2P Walnut Park Ph4B | 201507 | (0.52) | 3 | 0.0013083 | - | (0.01) |
| 376300-Mains - Plastic | 900278 | 3303L | Repl w/ 3977F 2P Walnut Park Ph4C | 201507 | (0.56) | 3 | 0.0013083 | - | (0.01) |
| 376300-Mains - Plastic | 900279 | 3303L | Repl w/ 3345F 2P Walnut Park Ph4D | 201507 | (2.94) | 3 | 0.0013083 | (0.01) | (0.05) |
| 376300-Mains - Plastic | 900281 | 3303L | Inst 4984F 4PWWellston Phase 2B | 201507 | 0.05 | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900282 | 3303L | Inst 4400F 2P Wellston 2C | 201507 | (0.87) | 3 | 0.0013083 | - | (0.01) |
| 376300-Mains - Plastic | 900283 | 3303L | Inst 5300F 2P Wellston Ph2D | 201507 | (0.05) | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900284 | 3303L | Inst 5466F 2P Wellston Ph2E | 201507 | (12.59) | 3 | 0.0013083 | (0.05) | (0.20) |
| 376300-Mains - Plastic | 900375 | 3303L | Inst 1747F 6P Litzinger | 201507 | (0.03) | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900377 | 3303L | Repl w/ 978F 2-4P Big Bend | 201507 | (2.32) | 3 | 0.0013083 | (0.01) | (0.04) |
| 376300-Mains - Plastic | 900379 | 3303L | Inst 783F 4P & 529F 2POld Bonhomme | 201507 | 0.06 | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900390 | 3303L | Inst 205F 1 1/4P Gore | 201507 | 0.04 | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900392 | 3303L | Inst 580F 4P & 255F 2P Ferguson | 201507 | (0.03) | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900412 | 3303L | Repl w/ 412F 6P Holly Hills | 201507 | (0.53) | 3 | 0.0013083 | - | (0.01) |
| 376300-Mains - Plastic | 900415 | 3303L | Repl w/ 1093F 2P Princeton | 201507 | 0.04 | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900420 | 3303L | Repl w/ 520F 2P Oregon | 201507 | 0.21 | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900422 | 3303L | Repl w/ 780F 2P Taft | 201507 | 0.08 | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900423 | 3303L | Repl w/ 1373F 2P Dr MLK | 201507 | 0.01 | 3 | 0.0013083 | - | - |

| | | | | | | | | | |
|------------------------|--------|-------|-------------------------------------|--------|----------|---|-----------|--------|--------|
| 376300-Mains - Plastic | 900424 | 3303L | Repl w/ 520F 3P Red Bud | 201507 | (0.36) | 3 | 0.0013083 | - | (0.01) |
| 376300-Mains - Plastic | 900430 | 3303L | Repl w/ 654F 2P Maurice | 201507 | 0.19 | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900432 | 3303L | Repl w/ 503F 2P Gravois | 201507 | (0.03) | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900433 | 3303L | Repl w/ 570F 4P Chippewa | 201507 | 0.24 | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900439 | 3303L | Repl w/ 269F 2P Ferguson | 201507 | 0.06 | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900457 | 3303L | Inst 4546F 2P Baden Ph5F | 201507 | 0.03 | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900460 | 3303L | Inst 3489F 2P Walnut Park Ph4E | 201507 | 0.09 | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900462 | 3303L | Repl w/ 2240F 2P Walnut Park Ph4G | 201507 | (1.27) | 3 | 0.0013083 | - | (0.02) |
| 376300-Mains - Plastic | 900463 | 3303L | Inst 4082F 2P Walnut Park Ph4H | 201507 | 7.84 | 3 | 0.0013083 | 0.03 | 0.12 |
| 376300-Mains - Plastic | 900464 | 3303L | Inst 4741F 2P Walnut Park Ph 4I | 201507 | (3.65) | 3 | 0.0013083 | (0.01) | (0.06) |
| 376300-Mains - Plastic | 900557 | 3303L | Inst 2123F 2P Walnut Park Ph6A | 201507 | (21.65) | 3 | 0.0013083 | (0.08) | (0.34) |
| 376300-Mains - Plastic | 900623 | 3303L | Repl w/ 2852' 2P Wydown Ph 6 | 201507 | (143.00) | 3 | 0.0013083 | (0.56) | (2.25) |
| 376300-Mains - Plastic | 900677 | 3303L | Inst 1795F 2P Cole & 18th PhA | 201507 | (78.98) | 3 | 0.0013083 | (0.31) | (1.24) |
| 376300-Mains - Plastic | 900679 | 3303L | Inst 2312F 4P Cole & 18th PhB | 201507 | (131.76) | 3 | 0.0013083 | (0.52) | (2.07) |
| 376300-Mains - Plastic | 900681 | 3303L | Inst 1637F 2P Cole & 18th Ph C | 201507 | (174.28) | 3 | 0.0013083 | (0.68) | (2.74) |
| 376300-Mains - Plastic | 900683 | 3303L | Inst 1864F 2P Cole & 18th Ph D | 201507 | (20.47) | 3 | 0.0013083 | (0.08) | (0.32) |
| 376300-Mains - Plastic | 900685 | 3303L | Inst 1550F 2P Cole & 18th PhE | 201507 | 248.17 | 3 | 0.0013083 | 0.97 | 3.90 |
| 376300-Mains - Plastic | 900687 | 3303L | Inst 1096F 2P Cole & 18th PhF | 201507 | 604.84 | 3 | 0.0013083 | 2.37 | 9.50 |
| 376300-Mains - Plastic | 900689 | 3303L | Inst 2434F 2P Cole & 18th PhG | 201507 | 957.47 | 3 | 0.0013083 | 3.76 | 15.03 |
| 376300-Mains - Plastic | 900691 | 3303L | Repl w/ 3458F 2P Cole & 18th Ph H | 201507 | 5,959.44 | 3 | 0.0013083 | 23.39 | 93.56 |
| 376300-Mains - Plastic | 900762 | 3303L | Inst 2069F 2P Earthquake Zone Ph1A | 201507 | (14.42) | 3 | 0.0013083 | (0.06) | (0.23) |
| 376300-Mains - Plastic | 900763 | 3303L | Inst 3508F 2P Earthquake Zone Ph1B | 201507 | (158.81) | 3 | 0.0013083 | (0.62) | (2.49) |
| 376300-Mains - Plastic | 900764 | 3303L | Repl w/758F 2P Earthquake Zone Ph1C | 201507 | (27.39) | 3 | 0.0013083 | (0.11) | (0.43) |
| 376300-Mains - Plastic | 900765 | 3303L | Inst 1899F 4P Earthquake Zone Ph1D | 201507 | (31.38) | 3 | 0.0013083 | (0.12) | (0.49) |
| 376300-Mains - Plastic | 900859 | 3303L | Repl w/ 290F 2P Cabanne | 201507 | (18.85) | 3 | 0.0013083 | (0.07) | (0.30) |
| 376300-Mains - Plastic | 900861 | 3303L | Repl w/ 105F 4P McLaran | 201507 | (1.99) | 3 | 0.0013083 | (0.01) | (0.03) |
| 376300-Mains - Plastic | 900862 | 3303L | Rep w/ 4552F 2P Broadway AOR | 201507 | 2,800.06 | 3 | 0.0013083 | 10.99 | 43.96 |
| 376300-Mains - Plastic | 900890 | 3303L | Repl w/ 2218F 2P Russell & Flora | 201507 | (46.10) | 3 | 0.0013083 | (0.18) | (0.72) |
| 376300-Mains - Plastic | 900895 | 3303L | Repl w/ 828F 2P Marquette | 201507 | (8.28) | 3 | 0.0013083 | (0.03) | (0.13) |
| 376300-Mains - Plastic | 900898 | 3303L | Repl w/ 1220F 2P Ohio | 201507 | (208.82) | 3 | 0.0013083 | (0.82) | (3.28) |
| 376300-Mains - Plastic | 900900 | 3303L | Repl w/ 1075F 2P Washington | 201507 | (51.62) | 3 | 0.0013083 | (0.20) | (0.81) |
| 376300-Mains - Plastic | 900902 | 3303L | Repl w/ 530' 2P Oakland | 201507 | 1,000.69 | 3 | 0.0013083 | 3.93 | 15.71 |
| 376300-Mains - Plastic | 900905 | 3303L | Repl w/ 806F 2P Utah | 201507 | (8.00) | 3 | 0.0013083 | (0.03) | (0.13) |
| 376300-Mains - Plastic | 900908 | 3303L | Repl w/ 460F 2P California | 201507 | (9.34) | 3 | 0.0013083 | (0.04) | (0.15) |
| 376300-Mains - Plastic | 900912 | 3303L | Repl w/ 745F 2P Shaw | 201507 | 47.42 | 3 | 0.0013083 | 0.19 | 0.74 |
| 376300-Mains - Plastic | 900921 | 3303L | Repl w/ 2457F 4P&2P Flad AOR | 201507 | (32.42) | 3 | 0.0013083 | (0.13) | (0.51) |
| 376300-Mains - Plastic | 900932 | 3303L | Repl w/ 160F 2P Cler Ave | 201507 | (0.76) | 3 | 0.0013083 | - | (0.01) |
| 376300-Mains - Plastic | 900977 | 3303L | Repl w/ 1291F 4P Boyle | 201507 | (14.33) | 3 | 0.0013083 | (0.06) | (0.22) |
| 376300-Mains - Plastic | 900986 | 3303L | Repl w/ 2189F 2P Earthquake Zone 2A | 201507 | (374.32) | 3 | 0.0013083 | (1.47) | (5.88) |
| 376300-Mains - Plastic | 900262 | 3304L | Inst 7815F 12P Clifton Hill-Columbi | 201507 | (186.90) | 3 | 0.0013083 | (0.73) | (2.93) |
| 376300-Mains - Plastic | 900393 | 3304L | Inst 3745F 8P Clayton Ave | 201507 | 0.04 | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900456 | 3304L | Inst 8175F 8P Jamieson McCausland | 201507 | (0.06) | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900474 | 3304L | Repl w/ 3774F 8P 8S Mullanphy | 201507 | (0.66) | 3 | 0.0013083 | - | (0.01) |
| 376300-Mains - Plastic | 900475 | 3304L | Inst 1895F 6P Koeln | 201507 | (116.04) | 3 | 0.0013083 | (0.46) | (1.82) |
| 376300-Mains - Plastic | 900479 | 3304L | Inst 3525F 8P Union | 201507 | (318.91) | 3 | 0.0013083 | (1.25) | (5.01) |
| 376300-Mains - Plastic | 900480 | 3304L | Inst 4528 8P Minerva | 201507 | (0.23) | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900481 | 3304L | Inst 3125F 8P Union | 201507 | 0.35 | 3 | 0.0013083 | - | 0.01 |
| 376300-Mains - Plastic | 900484 | 3304L | Inst 5203F 12P Ivanhoe | 201507 | (226.53) | 3 | 0.0013083 | (0.89) | (3.56) |
| 376300-Mains - Plastic | 900485 | 3304L | Inst 4236F 12P Alaska | 201507 | (0.19) | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900486 | 3304L | Inst 6210F 8P Jamieson | 201507 | 0.01 | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900487 | 3304L | Inst 4845F 8P Loughborough | 201507 | (34.40) | 3 | 0.0013083 | (0.14) | (0.54) |
| 376300-Mains - Plastic | 900488 | 3304L | Repl w/ 2873F 6P Hodiament | 201507 | (0.21) | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900585 | 3304L | Inst 8458F 8P 8S Lindell | 201507 | (67.22) | 3 | 0.0013083 | (0.26) | (1.06) |
| 376300-Mains - Plastic | 900595 | 3304L | Inst 4616F 8P Alaska | 201507 | (0.20) | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900596 | 3304L | Inst 3200F 8P Holly Hills | 201507 | (31.69) | 3 | 0.0013083 | (0.12) | (0.50) |

| | | | | | | | | | |
|------------------------|--------|-------|-------------------------------------|--------|-------------|---|-----------|----------|----------|
| 376300-Mains - Plastic | 900597 | 3304L | Inst 5626F 12P Lindell | 201507 | (72.02) | 3 | 0.0013083 | (0.28) | (1.13) |
| 376300-Mains - Plastic | 900598 | 3304L | Inst 5746F 8P Winnebago-Gravois | 201507 | 9,232.56 | 3 | 0.0013083 | 36.24 | 144.95 |
| 376300-Mains - Plastic | 900629 | 3304L | Inst 4820F 8P Kingshighway & McRee | 201507 | (1,609.20) | 3 | 0.0013083 | (6.32) | (25.26) |
| 376300-Mains - Plastic | 900635 | 3304L | Inst 1228F 8P Manchester | 201507 | 0.01 | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900643 | 3304L | Inst 1801F 6P-12P Marmaduke/Hudler | 201507 | (327.00) | 3 | 0.0013083 | (1.28) | (5.13) |
| 376300-Mains - Plastic | 900644 | 3304L | Inst 4190F 8P Evans | 201507 | (6.50) | 3 | 0.0013083 | (0.03) | (0.10) |
| 376300-Mains - Plastic | 900645 | 3304L | Inst 4690F 8P Vandeventer | 201507 | (58.11) | 3 | 0.0013083 | (0.23) | (0.91) |
| 376300-Mains - Plastic | 900668 | 3304L | Inst 5690F 8P Cora | 201507 | 0.41 | 3 | 0.0013083 | - | 0.01 |
| 376300-Mains - Plastic | 900692 | 3304L | Inst 3834F 8P Lindell | 201507 | (3.23) | 3 | 0.0013083 | (0.01) | (0.05) |
| 376300-Mains - Plastic | 900709 | 3304L | Repl w/ 2662F 8P Natural Bridge | 201507 | (37.24) | 3 | 0.0013083 | (0.15) | (0.58) |
| 376300-Mains - Plastic | 900711 | 3304L | Inst 4010F 8P Natural Bridge | 201507 | (188.11) | 3 | 0.0013083 | (0.74) | (2.95) |
| 376300-Mains - Plastic | 900713 | 3304L | Inst 4816F 8P Penrod & Sulphur | 201507 | (69.83) | 3 | 0.0013083 | (0.27) | (1.10) |
| 376300-Mains - Plastic | 900786 | 3304L | Inst 6713F 8P Chippewa & Tholozan | 201507 | (416.13) | 3 | 0.0013083 | (1.63) | (6.53) |
| 376300-Mains - Plastic | 900787 | 3304L | Inst 4235F 8P Beck Ave | 201507 | (303.84) | 3 | 0.0013083 | (1.19) | (4.77) |
| 376300-Mains - Plastic | 900849 | 3304L | Inst 850F 12P Whittier Header | 201507 | (175.12) | 3 | 0.0013083 | (0.69) | (2.75) |
| 376300-Mains - Plastic | 000569 | 3304L | 4015F 6P 2P Lemay Ferry | 201508 | (0.70) | 2 | 0.0013083 | - | (0.01) |
| 376300-Mains - Plastic | 001040 | 3303L | Install 46F 4P Nashville | 201508 | 0.21 | 2 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 001330 | 3303L | Inst 9084F 2P Aberdeen Pl | 201508 | (1,476.20) | 2 | 0.0013083 | (3.86) | (23.18) |
| 376300-Mains - Plastic | 001535 | 3303L | Repl w/ 9098F 2P Arlington | 201508 | (39.32) | 2 | 0.0013083 | (0.10) | (0.62) |
| 376300-Mains - Plastic | 001711 | 3303L | Inst 7023F 2P Northmoor Wydown Ph5 | 201508 | 2.97 | 2 | 0.0013083 | 0.01 | 0.05 |
| 376300-Mains - Plastic | 001712 | 3303L | Inst 16489F 2P Cote Brillante | 201508 | 66,015.76 | 2 | 0.0013083 | 172.74 | 1,036.42 |
| 376300-Mains - Plastic | 002137 | 3303L | Repl w/ 5955F 2P Boneta | 201508 | 844.40 | 2 | 0.0013083 | 2.21 | 13.26 |
| 376300-Mains - Plastic | 002138 | 3303L | Repl w/ 10203F 2P Manchester | 201508 | (14,285.49) | 2 | 0.0013083 | (37.38) | (224.28) |
| 376300-Mains - Plastic | 002139 | 3303L | Inst 3279F 2P MLK-Wellston 1B | 201508 | 253,644.80 | 2 | 0.0013083 | 663.69 | 3,982.12 |
| 376300-Mains - Plastic | 002140 | 3303L | Inst 6894F 2P Bertha-Wellston 1A | 201508 | 247,901.01 | 2 | 0.0013083 | 648.66 | 3,891.95 |
| 376300-Mains - Plastic | 002141 | 3303L | Inst 8161F 2P Marshall-Well. Ph4C | 201508 | 0.36 | 2 | 0.0013083 | - | 0.01 |
| 376300-Mains - Plastic | 002434 | 3303M | Deer Run main replacement | 201508 | (207.84) | 2 | 0.0013083 | (0.54) | (3.26) |
| 376300-Mains - Plastic | 696000 | 3301M | 69600 MAIN VAR INST MTCE | 201508 | (575.20) | 2 | 0.0013083 | (1.51) | (9.03) |
| 376300-Mains - Plastic | 698000 | 3301L | 69800 MAIN VAR INST MTCE | 201508 | (1,934.16) | 2 | 0.0013083 | (5.06) | (30.37) |
| 376300-Mains - Plastic | 699000 | 3301L | 69900 MAIN STL INST MTCE | 201508 | (19.48) | 2 | 0.0013083 | (0.05) | (0.31) |
| 376300-Mains - Plastic | 699220 | 3301L | 69922 MAIN PLS INST MTCE | 201508 | 67,722.25 | 2 | 0.0013083 | 229.53 | 1,377.20 |
| 376300-Mains - Plastic | 699500 | 3301L | 69950 MAIN STL INST MTCE | 201508 | 27,483.78 | 2 | 0.0013083 | 71.91 | 431.48 |
| 376300-Mains - Plastic | 699720 | 3301L | 69972 MAIN PLS INST MTCE | 201508 | 51,605.79 | 2 | 0.0013083 | 135.03 | 810.19 |
| 376300-Mains - Plastic | 900068 | 3303L | Repl w/ 1750F 2P Jefferson Ph 2 | 201508 | (2,411.34) | 2 | 0.0013083 | (6.31) | (37.86) |
| 376300-Mains - Plastic | 900068 | 3303L | Repl w/ 1750F 2P Jefferson Ph 2 | 201508 | (51.39) | 2 | 0.0013083 | (0.13) | (0.81) |
| 376300-Mains - Plastic | 900069 | 3303L | Inst 3539F 2P Jefferson Ph 3 | 201508 | 402,921.89 | 2 | 0.0013083 | 1,054.29 | 6,325.71 |
| 376300-Mains - Plastic | 900069 | 3303L | Inst 3539F 2P Jefferson Ph 3 | 201508 | 12,988.16 | 2 | 0.0013083 | 33.98 | 203.91 |
| 376300-Mains - Plastic | 900072 | 3303L | Repl w 688F 2P & 2527F 4P Lafayette | 201508 | (0.38) | 2 | 0.0013083 | - | (0.01) |
| 376300-Mains - Plastic | 900072 | 3303L | Repl w 688F 2P & 2527F 4P Lafayette | 201508 | (0.04) | 2 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900073 | 3303L | Repl w/ 2520F 2P Jefferson Ph 6 | 201508 | (39,153.80) | 2 | 0.0013083 | (102.45) | (614.70) |
| 376300-Mains - Plastic | 900073 | 3303L | Repl w/ 2520F 2P Jefferson Ph 6 | 201508 | (1,613.17) | 2 | 0.0013083 | (4.22) | (25.33) |
| 376300-Mains - Plastic | 900073 | 3303L | Repl w/ 2520F 2P Jefferson Ph 6 | 201508 | (3,011.05) | 2 | 0.0013083 | (7.88) | (47.27) |
| 376300-Mains - Plastic | 900093 | 3303L | Repl w/ 184F 2P Cass | 201508 | 0.05 | 2 | 0.0013083 | - | - |
| 376100-Mains - Steel | 900169 | 3304L | Inst 6228F 8P Loughborough | 201508 | (0.01) | 2 | 0.0012000 | - | - |
| 376300-Mains - Plastic | 900169 | 3304L | Inst 6228F 8P Loughborough | 201508 | (0.30) | 2 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900170 | 3304L | Inst 3526F 6P Field & Koeln | 201508 | 0.13 | 2 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900262 | 3304L | Inst 7615F 12P Clifton Hill-Columbi | 201508 | (3,178.09) | 2 | 0.0013083 | (8.32) | (49.89) |
| 376300-Mains - Plastic | 900262 | 3304L | Inst 7615F 12P Clifton Hill-Columbi | 201508 | (368.11) | 2 | 0.0013083 | (0.96) | (5.78) |
| 376300-Mains - Plastic | 900264 | 3303L | Int 3087F 4P 2P Baden Grid Ph 5A | 201508 | 36.42 | 2 | 0.0013083 | 0.10 | 0.57 |
| 376300-Mains - Plastic | 900264 | 3303L | Int 3087F 4P 2P Baden Grid Ph 5A | 201508 | 2.43 | 2 | 0.0013083 | 0.01 | 0.04 |
| 376300-Mains - Plastic | 900265 | 3303L | Repl w/ 3337F 2P Baden Ph 5B | 201508 | 1.24 | 2 | 0.0013083 | - | 0.02 |
| 376300-Mains - Plastic | 900265 | 3303L | Repl w/ 3337F 2P Baden Ph 5B | 201508 | 0.06 | 2 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900266 | 3303L | Inst 4640F 2P Baden Ph 5C | 201508 | (0.65) | 2 | 0.0013083 | - | (0.01) |
| 376300-Mains - Plastic | 900266 | 3303L | Inst 4640F 2P Baden Ph 5C | 201508 | 0.01 | 2 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900267 | 3303L | Repl w/ 4536F 2P Baden Ph5D | 201508 | 2.00 | 2 | 0.0013083 | 0.01 | 0.03 |

| | | | | | | | | | |
|------------------------|--------|-------|-------------------------------------|--------|------------|---|-----------|--------|----------|
| 376300-Mains - Plastic | 900267 | 3303L | Repl w/ 4536F 2P Baden Ph5D | 201508 | 0.10 | 2 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900268 | 3303L | Inst 4411F 2P Baden Ph5E | 201508 | 0.77 | 2 | 0.0013083 | - | 0.01 |
| 376300-Mains - Plastic | 900268 | 3303L | Inst 4411F 2P Baden Ph5E | 201508 | 0.11 | 2 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900269 | 3303L | Inst 1150F 4P Walnut Park Ph 5A | 201508 | (527.62) | 2 | 0.0013083 | (1.38) | (8.28) |
| 376300-Mains - Plastic | 900270 | 3303L | Inst 2942F 2P Walnut Park Ph5B | 201508 | 128,782.86 | 2 | 0.0013083 | 336.97 | 2,021.84 |
| 376300-Mains - Plastic | 900270 | 3303L | Inst 2942F 2P Walnut Park Ph5B | 201508 | 622.77 | 2 | 0.0013083 | 1.63 | 9.78 |
| 376300-Mains - Plastic | 900271 | 3303L | Inst 2646F 2P Walnut Park Ph5C | 201508 | 173,328.79 | 2 | 0.0013083 | 453.53 | 2,721.19 |
| 376300-Mains - Plastic | 900271 | 3303L | Inst 2646F 2P Walnut Park Ph5C | 201508 | 7,251.71 | 2 | 0.0013083 | 18.97 | 113.85 |
| 376300-Mains - Plastic | 900274 | 3303L | Repl w/ 3390F 2P Wellington Ph 4D | 201508 | 186,258.17 | 2 | 0.0013083 | 487.36 | 2,924.18 |
| 376300-Mains - Plastic | 900274 | 3303L | Repl w/ 3390F 2P Wellington Ph 4D | 201508 | 9,899.25 | 2 | 0.0013083 | 25.90 | 155.41 |
| 376300-Mains - Plastic | 900275 | 3303L | Repl w/ 4989F 2P Wellington Ph4E | 201508 | (3,805.60) | 2 | 0.0013083 | (9.96) | (59.75) |
| 376300-Mains - Plastic | 900275 | 3303L | Repl w/ 4989F 2P Wellington Ph4E | 201508 | (16.25) | 2 | 0.0013083 | (0.04) | (0.26) |
| 376300-Mains - Plastic | 900277 | 3303L | Repl w/ 1725F 2P Walnut Park Ph4B | 201508 | (26.39) | 2 | 0.0013083 | (0.07) | (0.41) |
| 376300-Mains - Plastic | 900277 | 3303L | Repl w/ 1725F 2P Walnut Park Ph4B | 201508 | (1.30) | 2 | 0.0013083 | - | (0.02) |
| 376300-Mains - Plastic | 900278 | 3303L | Repl w/ 3977F 2P Walnut Park Ph4C | 201508 | (43.82) | 2 | 0.0013083 | (0.11) | (0.69) |
| 376300-Mains - Plastic | 900278 | 3303L | Repl w/ 3977F 2P Walnut Park Ph4C | 201508 | (0.94) | 2 | 0.0013083 | - | (0.01) |
| 376300-Mains - Plastic | 900279 | 3303L | Repl w/ 3345F 2P Walnut Park Ph4D | 201508 | (617.98) | 2 | 0.0013083 | (1.62) | (9.70) |
| 376300-Mains - Plastic | 900279 | 3303L | Repl w/ 3345F 2P Walnut Park Ph4D | 201508 | (0.88) | 2 | 0.0013083 | - | (0.01) |
| 376300-Mains - Plastic | 900281 | 3303L | Inst 4984F 4PWellston Phase 2B | 201508 | (3.14) | 2 | 0.0013083 | (0.01) | (0.05) |
| 376300-Mains - Plastic | 900281 | 3303L | Inst 4984F 4PWellston Phase 2B | 201508 | (0.04) | 2 | 0.0013083 | - | - |
| 376100-Mains - Steel | 900282 | 3303L | Inst 4400F 2P Wellston 2C | 201508 | (1,330.44) | 2 | 0.0012000 | (3.19) | (19.16) |
| 376300-Mains - Plastic | 900282 | 3303L | Inst 4400F 2P Wellston 2C | 201508 | (8.96) | 2 | 0.0013083 | (0.02) | (0.14) |
| 376300-Mains - Plastic | 900283 | 3303L | Inst 5300F 2P Wellston Ph2D | 201508 | 1.01 | 2 | 0.0013083 | - | 0.02 |
| 376300-Mains - Plastic | 900283 | 3303L | Inst 5300F 2P Wellston Ph2D | 201508 | 0.07 | 2 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900284 | 3303L | Inst 5466F 2P Wellston Ph2E | 201508 | (1,087.25) | 2 | 0.0013083 | (2.84) | (17.07) |
| 376300-Mains - Plastic | 900284 | 3303L | Inst 5466F 2P Wellston Ph2E | 201508 | (20.58) | 2 | 0.0013083 | (0.05) | (0.32) |
| 376300-Mains - Plastic | 900310 | 3303L | Inst 2250F 2P Yale Ave Maplewood 1C | 201508 | 126,571.47 | 2 | 0.0013083 | 331.19 | 1,987.12 |
| 376300-Mains - Plastic | 900375 | 3303L | Inst 1747F 6P Litzsinger | 201508 | 2.73 | 2 | 0.0013083 | 0.01 | 0.04 |
| 376300-Mains - Plastic | 900375 | 3303L | Inst 1747F 6P Litzsinger | 201508 | 0.04 | 2 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900377 | 3303L | Repl w/ 978F 2-4P Big Bend | 201508 | (460.81) | 2 | 0.0013083 | (1.21) | (7.23) |
| 376300-Mains - Plastic | 900377 | 3303L | Repl w/ 978F 2-4P Big Bend | 201508 | (5.65) | 2 | 0.0013083 | (0.01) | (0.09) |
| 376300-Mains - Plastic | 900379 | 3303L | Inst 783F 4P & 529F 2P Old Bonhomme | 201508 | (17.94) | 2 | 0.0013083 | (0.05) | (0.28) |
| 376300-Mains - Plastic | 900379 | 3303L | Inst 783F 4P & 529F 2P Old Bonhomme | 201508 | (2.31) | 2 | 0.0013083 | (0.01) | (0.04) |
| 376300-Mains - Plastic | 900379 | 3303L | Inst 783F 4P & 529F 2P Old Bonhomme | 201508 | (0.37) | 2 | 0.0013083 | - | (0.01) |
| 376300-Mains - Plastic | 900388 | 3303L | Repl w/ 332F 2P Tay Rd | 201508 | 2.84 | 2 | 0.0013083 | 0.01 | 0.04 |
| 376100-Mains - Steel | 900390 | 3303L | Inst 205F 1 1/4P Gore | 201508 | 0.10 | 2 | 0.0012000 | - | - |
| 376300-Mains - Plastic | 900390 | 3303L | Inst 205F 1 1/4P Gore | 201508 | 6.25 | 2 | 0.0013083 | 0.02 | 0.10 |
| 376300-Mains - Plastic | 900392 | 3303L | Inst 580F 4P & 255F 2P Ferguson | 201508 | (0.47) | 2 | 0.0013083 | - | (0.01) |
| 376300-Mains - Plastic | 900392 | 3303L | Inst 580F 4P & 255F 2P Ferguson | 201508 | (0.01) | 2 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900393 | 3304L | Inst 3745F 8P Clayton Ave | 201508 | (0.88) | 2 | 0.0013083 | - | (0.01) |
| 376300-Mains - Plastic | 900393 | 3304L | Inst 3745F 8P Clayton Ave | 201508 | (0.05) | 2 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900395 | 3303L | Repl w/ 525F 2P Clay St | 201508 | 0.56 | 2 | 0.0013083 | - | 0.01 |
| 376300-Mains - Plastic | 900412 | 3303L | Repl w/ 412F 6P Holly Hills | 201508 | (58.16) | 2 | 0.0013083 | (0.15) | (0.91) |
| 376300-Mains - Plastic | 900412 | 3303L | Repl w/ 412F 6P Holly Hills | 201508 | (2.64) | 2 | 0.0013083 | (0.01) | (0.04) |
| 376100-Mains - Steel | 900415 | 3303L | Repl w/ 1093F 2P Princeton | 201508 | 1.67 | 2 | 0.0012000 | - | 0.02 |
| 376300-Mains - Plastic | 900420 | 3303L | Repl w/ 520F 2P Oregon | 201508 | 3.89 | 2 | 0.0013083 | 0.01 | 0.06 |
| 376300-Mains - Plastic | 900420 | 3303L | Repl w/ 520F 2P Oregon | 201508 | 0.10 | 2 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900421 | 3303L | Repl w/ 970F 2P Winnebago | 201508 | 4.30 | 2 | 0.0013083 | 0.01 | 0.07 |
| 376300-Mains - Plastic | 900422 | 3303L | Repl w/ 780F 2P Taft | 201508 | 4.23 | 2 | 0.0013083 | 0.01 | 0.07 |
| 376300-Mains - Plastic | 900422 | 3303L | Repl w/ 780F 2P Taft | 201508 | 0.13 | 2 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900423 | 3303L | Repl w/ 1373F 2P Dr MLK | 201508 | (0.14) | 2 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900423 | 3303L | Repl w/ 1373F 2P Dr MLK | 201508 | (0.01) | 2 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900424 | 3303L | Repl w/ 520F 3P Red Bud | 201508 | 6.70 | 2 | 0.0013083 | 0.02 | 0.11 |
| 376300-Mains - Plastic | 900424 | 3303L | Repl w/ 520F 3P Red Bud | 201508 | 0.68 | 2 | 0.0013083 | - | 0.01 |
| 376300-Mains - Plastic | 900430 | 3303L | Repl w/ 654F 2P Maurice | 201508 | 3.34 | 2 | 0.0013083 | 0.01 | 0.05 |

| | | | | | | | | | |
|------------------------|--------|-------|-------------------------------------|--------|--------------|---|-----------|----------|-----------|
| 376300-Mains - Plastic | 900430 | 3303L | Repl w/ 654F 2P Maurice | 201508 | 0.20 | 2 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900432 | 3303L | Repl w/ 503F 2P Gravois | 201508 | (1.89) | 2 | 0.0013083 | - | (0.03) |
| 376300-Mains - Plastic | 900432 | 3303L | Repl w/ 503F 2P Gravois | 201508 | (0.03) | 2 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900433 | 3303L | Repl w/ 570F 4P Chippewa | 201508 | 4.06 | 2 | 0.0013083 | 0.01 | 0.06 |
| 376300-Mains - Plastic | 900433 | 3303L | Repl w/ 570F 4P Chippewa | 201508 | 0.15 | 2 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900439 | 3303L | Repl w/ 269F 2P Ferguson | 201508 | 2.32 | 2 | 0.0013083 | 0.01 | 0.04 |
| 376300-Mains - Plastic | 900439 | 3303L | Repl w/ 269F 2P Ferguson | 201508 | 0.06 | 2 | 0.0013083 | - | - |
| 376100-Mains - Steel | 900456 | 3304L | Inst 8175F 8P Jamieson McCausland | 201508 | 0.07 | 2 | 0.0012000 | - | - |
| 376300-Mains - Plastic | 900456 | 3304L | Inst 8175F 8P Jamieson McCausland | 201508 | 1.53 | 2 | 0.0013083 | - | 0.02 |
| 376300-Mains - Plastic | 900457 | 3303L | Inst 4546F 2P Baden Ph5F | 201508 | 0.11 | 2 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900457 | 3303L | Inst 4546F 2P Baden Ph5F | 201508 | (0.02) | 2 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900458 | 3303L | Repl w/ 2796F 2P Wellington Grd Ph4 | 201508 | 490,566.56 | 2 | 0.0013083 | 1,283.62 | 7,701.70 |
| 376300-Mains - Plastic | 900458 | 3303L | Repl w/ 2796F 2P Wellington Grd Ph4 | 201508 | 4,830.62 | 2 | 0.0013083 | 12.64 | 75.84 |
| 376300-Mains - Plastic | 900460 | 3303L | Inst 3488F 2P Walnut Park Ph4E | 201508 | (2.20) | 2 | 0.0013083 | (0.01) | (0.03) |
| 376300-Mains - Plastic | 900460 | 3303L | Inst 3488F 2P Walnut Park Ph4E | 201508 | (0.12) | 2 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900461 | 3303L | Inst 893F 2P Walnut Park Ph4F | 201508 | 2.29 | 2 | 0.0013083 | 0.01 | 0.04 |
| 376300-Mains - Plastic | 900461 | 3303L | Inst 893F 2P Walnut Park Ph4F | 201508 | 0.01 | 2 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900462 | 3303L | Repl w/ 2240F 2P Walnut Park Ph4G | 201508 | (328.52) | 2 | 0.0013083 | (0.86) | (5.16) |
| 376300-Mains - Plastic | 900462 | 3303L | Repl w/ 2240F 2P Walnut Park Ph4G | 201508 | (7.85) | 2 | 0.0013083 | (0.02) | (0.12) |
| 376300-Mains - Plastic | 900463 | 3303L | Inst 4082F 2P Walnut Park Ph4H | 201508 | (863.23) | 2 | 0.0013083 | (1.74) | (10.41) |
| 376300-Mains - Plastic | 900463 | 3303L | Inst 4082F 2P Walnut Park Ph4H | 201508 | (11.18) | 2 | 0.0013083 | (0.03) | (0.18) |
| 376300-Mains - Plastic | 900464 | 3303L | Inst 4741F 2PWalnut Park Ph 4I | 201508 | (400.78) | 2 | 0.0013083 | (1.05) | (6.29) |
| 376300-Mains - Plastic | 900464 | 3303L | Inst 4741F 2PWalnut Park Ph 4I | 201508 | (6.67) | 2 | 0.0013083 | (0.02) | (0.10) |
| 376300-Mains - Plastic | 900467 | 3303L | Repl w/ 2400F 2-4P Potomac AOR | 201508 | (0.11) | 2 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900467 | 3303L | Repl w/ 2400F 2-4P Potomac AOR | 201508 | (0.01) | 2 | 0.0013083 | - | - |
| 376100-Mains - Steel | 900474 | 3304L | Repl w/ 3774F 8P 8S Mullanphy | 201508 | 0.71 | 2 | 0.0012000 | - | 0.01 |
| 376300-Mains - Plastic | 900474 | 3304L | Repl w/ 3774F 8P 8S Mullanphy | 201508 | 16.61 | 2 | 0.0013083 | 0.04 | 0.26 |
| 376300-Mains - Plastic | 900474 | 3304L | Repl w/ 3774F 8P 8S Mullanphy | 201508 | 5.59 | 2 | 0.0013083 | 0.01 | 0.09 |
| 376300-Mains - Plastic | 900475 | 3304L | Inst 1895F 6P Koeln | 201508 | (5,875.93) | 2 | 0.0013083 | (15.37) | (92.25) |
| 376300-Mains - Plastic | 900475 | 3304L | Inst 1895F 6P Koeln | 201508 | (217.89) | 2 | 0.0013083 | (0.57) | (3.42) |
| 376300-Mains - Plastic | 900476 | 3304L | Inst 3350F 6P Ivory | 201508 | 422,876.81 | 2 | 0.0013083 | 1,106.50 | 6,639.00 |
| 376300-Mains - Plastic | 900476 | 3304L | Inst 3350F 6P Ivory | 201508 | 41,228.82 | 2 | 0.0013083 | 107.88 | 647.28 |
| 376300-Mains - Plastic | 900479 | 3304L | Inst 3525F 8P Union | 201508 | (3,889.92) | 2 | 0.0013083 | (10.18) | (61.07) |
| 376300-Mains - Plastic | 900479 | 3304L | Inst 3525F 8P Union | 201508 | (112.16) | 2 | 0.0013083 | (0.29) | (1.76) |
| 376300-Mains - Plastic | 900479 | 3304L | Inst 3525F 8P Union | 201508 | (249.77) | 2 | 0.0013083 | (0.65) | (3.92) |
| 376300-Mains - Plastic | 900480 | 3304L | Inst 4528 8P Minerva | 201508 | (23.12) | 2 | 0.0013083 | (0.08) | (0.36) |
| 376300-Mains - Plastic | 900480 | 3304L | Inst 4528 8P Minerva | 201508 | (0.64) | 2 | 0.0013083 | - | (0.01) |
| 376100-Mains - Steel | 900481 | 3304L | Inst 3125F 8P Union | 201508 | 0.20 | 2 | 0.0012000 | - | - |
| 376300-Mains - Plastic | 900481 | 3304L | Inst 3125F 8P Union | 201508 | 4.43 | 2 | 0.0013083 | 0.01 | 0.07 |
| 376300-Mains - Plastic | 900484 | 3304L | Inst 5203F 12P Ivanhoe | 201508 | (2,216.25) | 2 | 0.0013083 | (5.80) | (34.79) |
| 376300-Mains - Plastic | 900484 | 3304L | Inst 5203F 12P Ivanhoe | 201508 | (343.17) | 2 | 0.0013083 | (0.90) | (5.39) |
| 376300-Mains - Plastic | 900485 | 3304L | Inst 4236F 12P Alaska | 201508 | (20.52) | 2 | 0.0013083 | (0.05) | (0.32) |
| 376300-Mains - Plastic | 900485 | 3304L | Inst 4236F 12P Alaska | 201508 | (0.14) | 2 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900485 | 3304L | Inst 4236F 12P Alaska | 201508 | (0.37) | 2 | 0.0013083 | - | (0.01) |
| 376300-Mains - Plastic | 900486 | 3304L | Inst 6210F 8P Jamieson | 201508 | (0.29) | 2 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900486 | 3304L | Inst 6210F 8P Jamieson | 201508 | (0.02) | 2 | 0.0013083 | - | - |
| 376100-Mains - Steel | 900487 | 3304L | Inst 4845F 8P Loughborough | 201508 | (45.03) | 2 | 0.0012000 | (0.11) | (0.65) |
| 376300-Mains - Plastic | 900487 | 3304L | Inst 4845F 8P Loughborough | 201508 | (807.77) | 2 | 0.0013083 | (2.11) | (12.68) |
| 376300-Mains - Plastic | 900488 | 3304L | Repl w/ 2873F 6P Hodiament | 201508 | (0.91) | 2 | 0.0013083 | - | (0.01) |
| 376300-Mains - Plastic | 900488 | 3304L | Repl w/ 2873F 6P Hodiament | 201508 | (0.04) | 2 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900520 | 3303L | Repl w/ 6590F 2P Maplewood Ph1C | 201508 | 1,261,466.20 | 2 | 0.0013083 | 3,300.75 | 19,804.51 |
| 376300-Mains - Plastic | 900520 | 3303L | Repl w/ 6590F 2P Maplewood Ph1C | 201508 | 22,863.07 | 2 | 0.0013083 | 59.82 | 358.94 |
| 376300-Mains - Plastic | 900557 | 3303L | Inst 2123F 2P Walnut Park Ph6A | 201508 | (2,796.71) | 2 | 0.0013083 | (7.32) | (43.91) |
| 376300-Mains - Plastic | 900557 | 3303L | Inst 2123F 2P Walnut Park Ph6A | 201508 | (50.25) | 2 | 0.0013083 | (0.13) | (0.79) |
| 376300-Mains - Plastic | 900558 | 3303L | Inst 1859F 2P Walnut Park Ph6B | 201508 | 156,386.58 | 2 | 0.0013083 | 409.20 | 2,455.21 |

| | | | | | | | | | |
|------------------------|--------|-------|------------------------------------|--------|-------------|---|-----------|----------|----------|
| 376300-Mains - Plastic | 900558 | 3303L | Inst 1859F 2P Walnut Park Ph6B | 201508 | 8,748.24 | 2 | 0.0013083 | 22.89 | 137.34 |
| 376300-Mains - Plastic | 900559 | 3303L | Inst 3875F 2P Walnut Park Ph6C | 201508 | 227,652.13 | 2 | 0.0013083 | 595.67 | 3,574.05 |
| 376300-Mains - Plastic | 900559 | 3303L | Inst 3875F 2P Walnut Park Ph6C | 201508 | 4,307.90 | 2 | 0.0013083 | 11.27 | 67.63 |
| 376300-Mains - Plastic | 900585 | 3304L | Inst 8458F 8P 8S Lindell | 201508 | (1,494.79) | 2 | 0.0013083 | (3.91) | (23.47) |
| 376300-Mains - Plastic | 900585 | 3304L | Inst 8458F 8P 8S Lindell | 201508 | 1,795.30 | 2 | 0.0013083 | 4.70 | 28.19 |
| 376300-Mains - Plastic | 900595 | 3304L | Inst 4616F 8P Alaska | 201508 | (45.70) | 2 | 0.0013083 | (0.12) | (0.72) |
| 376300-Mains - Plastic | 900595 | 3304L | Inst 4616F 8P Alaska | 201508 | (1.10) | 2 | 0.0013083 | - | (0.02) |
| 376100-Mains - Steel | 900596 | 3304L | Inst 3200F 8P Holly Hills | 201508 | (36.48) | 2 | 0.0012000 | (0.09) | (0.55) |
| 376300-Mains - Plastic | 900596 | 3304L | Inst 3200F 8P Holly Hills | 201508 | (198.90) | 2 | 0.0013083 | (0.52) | (3.12) |
| 376300-Mains - Plastic | 900596 | 3304L | Inst 3200F 8P Holly Hills | 201508 | (2,405.56) | 2 | 0.0013083 | (6.29) | (37.77) |
| 376300-Mains - Plastic | 900597 | 3304L | Inst 5626F 12P Lindell | 201508 | 3,486.84 | 2 | 0.0013083 | 9.12 | 54.74 |
| 376300-Mains - Plastic | 900597 | 3304L | Inst 5626F 12P Lindell | 201508 | 334.19 | 2 | 0.0013083 | 0.87 | 5.25 |
| 376300-Mains - Plastic | 900597 | 3304L | Inst 5626F 12P Lindell | 201508 | 49.95 | 2 | 0.0013083 | 0.13 | 0.78 |
| 376300-Mains - Plastic | 900598 | 3304L | Inst 5746F 8P Winnebago-Gravois | 201508 | (4,469.63) | 2 | 0.0013083 | (11.70) | (70.17) |
| 376300-Mains - Plastic | 900598 | 3304L | Inst 5746F 8P Winnebago-Gravois | 201508 | 374.85 | 2 | 0.0013083 | 0.98 | 5.88 |
| 376300-Mains - Plastic | 900623 | 3303L | Repl w/ 2852' 2P Wydown Ph 6 | 201508 | (772.80) | 2 | 0.0013083 | (2.02) | (12.13) |
| 376300-Mains - Plastic | 900623 | 3303L | Repl w/ 2852' 2P Wydown Ph 6 | 201508 | (20.31) | 2 | 0.0013083 | (0.05) | (0.32) |
| 376100-Mains - Steel | 900625 | 3304L | Inst 4530F 8P Newstead | 201508 | 25,256.58 | 2 | 0.0012000 | 60.62 | 363.69 |
| 376300-Mains - Plastic | 900625 | 3304L | Inst 4530F 8P Newstead | 201508 | 425,121.06 | 2 | 0.0013083 | 1,112.37 | 6,674.23 |
| 376300-Mains - Plastic | 900629 | 3304L | Inst 4820F 8P Kingshighway & McRee | 201508 | (871.03) | 2 | 0.0013083 | (2.28) | (13.67) |
| 376300-Mains - Plastic | 900629 | 3304L | Inst 4820F 8P Kingshighway & McRee | 201508 | (3,812.72) | 2 | 0.0013083 | (9.98) | (59.86) |
| 376300-Mains - Plastic | 900629 | 3304L | Inst 4820F 8P Kingshighway & McRee | 201508 | (1,030.06) | 2 | 0.0013083 | (2.70) | (16.17) |
| 376300-Mains - Plastic | 900635 | 3304L | Inst 1228F 8P Manchester | 201508 | 2.43 | 2 | 0.0013083 | 0.01 | 0.04 |
| 376300-Mains - Plastic | 900635 | 3304L | Inst 1228F 8P Manchester | 201508 | - | 2 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900643 | 3304L | Inst 1801F 6P-12P Marmaduke/Hudler | 201508 | (9,266.39) | 2 | 0.0013083 | (24.25) | (145.48) |
| 376300-Mains - Plastic | 900643 | 3304L | Inst 1801F 6P-12P Marmaduke/Hudler | 201508 | (713.66) | 2 | 0.0013083 | (1.87) | (11.20) |
| 376300-Mains - Plastic | 900644 | 3304L | Inst 4190F 8P Evans | 201508 | (558.72) | 2 | 0.0013083 | (1.46) | (8.77) |
| 376300-Mains - Plastic | 900644 | 3304L | Inst 4190F 8P Evans | 201508 | (13.60) | 2 | 0.0013083 | (0.04) | (0.21) |
| 376300-Mains - Plastic | 900645 | 3304L | Inst 4690F 8P Vandeventer | 201508 | (2,224.31) | 2 | 0.0013083 | (5.82) | (34.92) |
| 376300-Mains - Plastic | 900645 | 3304L | Inst 4690F 8P Vandeventer | 201508 | (62.43) | 2 | 0.0013083 | (0.16) | (0.98) |
| 376100-Mains - Steel | 900650 | 3303L | Inst 3290F 2P St Louis Hills Ph1A | 201508 | 9,132.10 | 2 | 0.0012000 | 21.92 | 131.50 |
| 376300-Mains - Plastic | 900650 | 3303L | Inst 3290F 2P St Louis Hills Ph1A | 201508 | 214,570.87 | 2 | 0.0013083 | 561.45 | 3,368.68 |
| 376300-Mains - Plastic | 900652 | 3303L | Inst 4435F 2P St Louis Hills Ph1B | 201508 | 176,252.39 | 2 | 0.0013083 | 461.18 | 2,767.09 |
| 376300-Mains - Plastic | 900652 | 3303L | Inst 4435F 2P St Louis Hills Ph1B | 201508 | 6,919.43 | 2 | 0.0013083 | 18.11 | 108.63 |
| 376300-Mains - Plastic | 900653 | 3303L | Inst 2636F 2P St Louis Hills Ph1C | 201508 | 146,247.08 | 2 | 0.0013083 | 382.67 | 2,296.02 |
| 376300-Mains - Plastic | 900653 | 3303L | Inst 2636F 2P St Louis Hills Ph1C | 201508 | 1,490.83 | 2 | 0.0013083 | 3.90 | 23.41 |
| 376300-Mains - Plastic | 900668 | 3304L | Inst 5690F 8P Cora | 201508 | 7.40 | 2 | 0.0013083 | 0.02 | 0.12 |
| 376300-Mains - Plastic | 900668 | 3304L | Inst 5690F 8P Cora | 201508 | 0.06 | 2 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900669 | 3304L | Inst 4565F 8P Page & Evans | 201508 | (4.32) | 2 | 0.0013083 | (0.01) | (0.07) |
| 376300-Mains - Plastic | 900669 | 3304L | Inst 4565F 8P Page & Evans | 201508 | (0.17) | 2 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900675 | 3303L | Inst 250F 2P Humphrey Upgrade | 201508 | 3,625.41 | 2 | 0.0013083 | 9.49 | 56.92 |
| 376300-Mains - Plastic | 900675 | 3303L | Inst 250F 2P Humphrey Upgrade | 201508 | 335.21 | 2 | 0.0013083 | 0.88 | 5.26 |
| 376300-Mains - Plastic | 900677 | 3303L | Repl w/ 1795F 2P Cole & 18th PhA | 201508 | (20,100.10) | 2 | 0.0013083 | (52.59) | (315.56) |
| 376300-Mains - Plastic | 900677 | 3303L | Repl w/ 1795F 2P Cole & 18th PhA | 201508 | (1,935.34) | 2 | 0.0013083 | (5.06) | (30.38) |
| 376300-Mains - Plastic | 900677 | 3303L | Repl w/ 1795F 2P Cole & 18th PhA | 201508 | (1,291.79) | 2 | 0.0013083 | (3.38) | (20.28) |
| 376100-Mains - Steel | 900679 | 3303L | Inst 2312F 4P Cole & 18th PhB | 201508 | (258.42) | 2 | 0.0012000 | (0.62) | (3.72) |
| 376300-Mains - Plastic | 900679 | 3303L | Inst 2312F 4P Cole & 18th PhB | 201508 | (4,218.81) | 2 | 0.0013083 | (11.04) | (66.23) |
| 376300-Mains - Plastic | 900681 | 3303L | Inst 1637F 2P Cole & 18th Ph C | 201508 | (14,858.46) | 2 | 0.0013083 | (38.88) | (233.27) |
| 376300-Mains - Plastic | 900681 | 3303L | Inst 1637F 2P Cole & 18th Ph C | 201508 | (594.74) | 2 | 0.0013083 | (1.56) | (9.34) |
| 376300-Mains - Plastic | 900683 | 3303L | Inst 1864F 2P Cole & 18th Ph D | 201508 | (24,563.61) | 2 | 0.0013083 | (64.27) | (385.64) |
| 376300-Mains - Plastic | 900683 | 3303L | Inst 1864F 2P Cole & 18th Ph D | 201508 | (1,555.79) | 2 | 0.0013083 | (4.07) | (24.43) |
| 376300-Mains - Plastic | 900685 | 3303L | Inst 1550F 2P Cole & 18th PhE | 201508 | (1,905.53) | 2 | 0.0013083 | (4.99) | (29.92) |
| 376300-Mains - Plastic | 900685 | 3303L | Inst 1550F 2P Cole & 18th PhE | 201508 | (136.59) | 2 | 0.0013083 | (0.36) | (2.14) |
| 376300-Mains - Plastic | 900687 | 3303L | Inst 1096F 2P Cole & 18th PhF | 201508 | 2,263.47 | 2 | 0.0013083 | 5.92 | 35.54 |
| 376300-Mains - Plastic | 900687 | 3303L | Inst 1096F 2P Cole & 18th PhF | 201508 | 159.63 | 2 | 0.0013083 | 0.42 | 2.51 |

| | | | | | | | | | |
|------------------------|--------|-------|-------------------------------------|--------|-------------|---|-----------|----------|----------|
| 376300-Mains - Plastic | 900689 | 3303L | Inst 2434F 2P Cole & 18th PhG | 201508 | (10,924.28) | 2 | 0.0013083 | (28.58) | (171.51) |
| 376300-Mains - Plastic | 900689 | 3303L | Inst 2434F 2P Cole & 18th PhG | 201508 | (539.27) | 2 | 0.0013083 | (1.41) | (8.47) |
| 376300-Mains - Plastic | 900691 | 3303L | Repl w/ 3458F 2P Cole & 18th Ph H | 201508 | 103,455.71 | 2 | 0.0013083 | 270.70 | 1,824.21 |
| 376300-Mains - Plastic | 900691 | 3303L | Repl w/ 3458F 2P Cole & 18th Ph H | 201508 | 6,203.05 | 2 | 0.0013083 | 16.23 | 97.39 |
| 376300-Mains - Plastic | 900692 | 3304L | Inst 3834F 8P Lindell | 201508 | (78.19) | 2 | 0.0013083 | (0.20) | (1.23) |
| 376300-Mains - Plastic | 900692 | 3304L | Inst 3834F 8P Lindell | 201508 | (11.14) | 2 | 0.0013083 | (0.03) | (0.17) |
| 376300-Mains - Plastic | 900709 | 3304L | Repl w/ 2662F 8P Natural Bridge | 201508 | (4,773.60) | 2 | 0.0013083 | (12.49) | (74.94) |
| 376300-Mains - Plastic | 900709 | 3304L | Repl w/ 2662F 8P Natural Bridge | 201508 | (197.39) | 2 | 0.0013083 | (0.52) | (3.10) |
| 376300-Mains - Plastic | 900709 | 3304L | Repl w/ 2662F 8P Natural Bridge | 201508 | (149.27) | 2 | 0.0013083 | (0.39) | (2.34) |
| 376300-Mains - Plastic | 900711 | 3304L | Inst 4010F 8P Natural Bridge | 201508 | (8,444.64) | 2 | 0.0013083 | (22.10) | (132.58) |
| 376300-Mains - Plastic | 900711 | 3304L | Inst 4010F 8P Natural Bridge | 201508 | (452.48) | 2 | 0.0013083 | (1.18) | (7.10) |
| 376300-Mains - Plastic | 900713 | 3304L | Inst 4816F 8P Penrod & Sulphur | 201508 | (3,148.76) | 2 | 0.0013083 | (8.24) | (49.43) |
| 376300-Mains - Plastic | 900713 | 3304L | Inst 4816F 8P Penrod & Sulphur | 201508 | (107.84) | 2 | 0.0013083 | (0.28) | (1.89) |
| 376300-Mains - Plastic | 900734 | 3303L | Repl w/ 1717F 2P Hurck | 201508 | 186,352.76 | 2 | 0.0013083 | 487.81 | 2,925.66 |
| 376300-Mains - Plastic | 900734 | 3303L | Repl w/ 1717F 2P Hurck | 201508 | 10,075.97 | 2 | 0.0013083 | 26.36 | 158.19 |
| 376300-Mains - Plastic | 900738 | 3303L | Repl w/ 780F 2P Kingsland MSD | 201508 | 50,723.95 | 2 | 0.0013083 | 132.72 | 796.35 |
| 376300-Mains - Plastic | 900738 | 3303L | Repl w/ 780F 2P Kingsland MSD | 201508 | 4,216.80 | 2 | 0.0013083 | 11.03 | 66.20 |
| 376300-Mains - Plastic | 900759 | 3303L | Repl w/ 2836F 2P Hickory Dale | 201508 | (2,075.32) | 2 | 0.0013083 | (5.43) | (32.58) |
| 376300-Mains - Plastic | 900762 | 3303L | Inst 2069F 2P Earthquake Zone Ph1A | 201508 | (1,738.55) | 2 | 0.0013083 | (4.55) | (27.29) |
| 376300-Mains - Plastic | 900762 | 3303L | Inst 2069F 2P Earthquake Zone Ph1A | 201508 | (56.67) | 2 | 0.0013083 | (0.15) | (0.89) |
| 376300-Mains - Plastic | 900763 | 3303L | Inst 3508F 2P Earthquake Zone Ph1B | 201508 | (4,551.18) | 2 | 0.0013083 | (11.91) | (71.45) |
| 376300-Mains - Plastic | 900763 | 3303L | Inst 3508F 2P Earthquake Zone Ph1B | 201508 | (384.69) | 2 | 0.0013083 | (1.01) | (6.04) |
| 376300-Mains - Plastic | 900764 | 3303L | Repl w/758F 2P Earthquake Zone Ph1C | 201508 | 1,246.40 | 2 | 0.0013083 | 3.26 | 19.57 |
| 376300-Mains - Plastic | 900764 | 3303L | Repl w/758F 2P Earthquake Zone Ph1C | 201508 | 129.92 | 2 | 0.0013083 | 0.34 | 2.04 |
| 376300-Mains - Plastic | 900765 | 3303L | Inst 1899F 4P Earthquake Zone Ph1D | 201508 | (23,620.86) | 2 | 0.0013083 | (61.81) | (370.84) |
| 376300-Mains - Plastic | 900765 | 3303L | Inst 1899F 4P Earthquake Zone Ph1D | 201508 | (460.03) | 2 | 0.0013083 | (1.20) | (7.22) |
| 376300-Mains - Plastic | 900780 | 3304L | Inst 2180F 6P Union Header Main | 201508 | 235,571.68 | 2 | 0.0013083 | 616.40 | 3,698.38 |
| 376300-Mains - Plastic | 900780 | 3304L | Inst 2180F 6P Union Header Main | 201508 | 13,473.33 | 2 | 0.0013083 | 35.25 | 211.53 |
| 376100-Mains - Steel | 900786 | 3304L | Inst 6713F 8P Chippewa & Tholozan | 201508 | (532.01) | 2 | 0.0012000 | (1.28) | (7.66) |
| 376300-Mains - Plastic | 900786 | 3304L | Inst 6713F 8P Chippewa & Tholozan | 201508 | (9,448.83) | 2 | 0.0013083 | (24.72) | (148.34) |
| 376100-Mains - Steel | 900787 | 3304L | Inst 4235F 8P Beck Ave | 201508 | (418.35) | 2 | 0.0012000 | (1.00) | (6.02) |
| 376300-Mains - Plastic | 900787 | 3304L | Inst 4235F 8P Beck Ave | 201508 | (6,283.03) | 2 | 0.0013083 | (16.44) | (98.64) |
| 376300-Mains - Plastic | 900789 | 3304L | Inst 3104F 8P Hampton Header | 201508 | 414,385.57 | 2 | 0.0013083 | 1,084.28 | 6,505.69 |
| 376300-Mains - Plastic | 900789 | 3304L | Inst 3104F 8P Hampton Header | 201508 | 12,380.15 | 2 | 0.0013083 | 32.39 | 194.36 |
| 376300-Mains - Plastic | 900823 | 3303L | Repl w/ 659F 2P Baden Ph6A | 201508 | 32,040.87 | 2 | 0.0013083 | 83.84 | 503.03 |
| 376300-Mains - Plastic | 900823 | 3303L | Repl w/ 659F 2P Baden Ph6A | 201508 | 4,480.06 | 2 | 0.0013083 | 11.72 | 70.34 |
| 376300-Mains - Plastic | 900849 | 3304L | Inst 850F 12P Whittier Header | 201508 | (2,053.26) | 2 | 0.0013083 | (5.37) | (32.24) |
| 376300-Mains - Plastic | 900849 | 3304L | Inst 850F 12P Whittier Header | 201508 | (341.80) | 2 | 0.0013083 | (0.89) | (5.37) |
| 376300-Mains - Plastic | 900859 | 3303L | Repl w/ 290F 2P Cabanne | 201508 | (1,236.81) | 2 | 0.0013083 | (3.24) | (19.42) |
| 376300-Mains - Plastic | 900859 | 3303L | Repl w/ 290F 2P Cabanne | 201508 | (17.89) | 2 | 0.0013083 | (0.05) | (0.28) |
| 376300-Mains - Plastic | 900861 | 3303L | Repl w/ 105F 4P McLaran | 201508 | (100.51) | 2 | 0.0013083 | (0.26) | (1.58) |
| 376300-Mains - Plastic | 900861 | 3303L | Repl w/ 105F 4P McLaran | 201508 | (3.34) | 2 | 0.0013083 | (0.01) | (0.05) |
| 376300-Mains - Plastic | 900862 | 3303L | Rep w/ 4552F 2P Broadway AOR | 201508 | (21,849.79) | 2 | 0.0013083 | (57.17) | (343.03) |
| 376300-Mains - Plastic | 900862 | 3303L | Rep w/ 4552F 2P Broadway AOR | 201508 | (773.08) | 2 | 0.0013083 | (2.02) | (12.14) |
| 376100-Mains - Steel | 900873 | 3303L | Repl w/ 538F 2P Longacre | 201508 | 3,136.25 | 2 | 0.0012000 | 7.53 | 45.16 |
| 376300-Mains - Plastic | 900873 | 3303L | Repl w/ 538F 2P Longacre | 201508 | 53,114.97 | 2 | 0.0013083 | 138.98 | 833.88 |
| 376300-Mains - Plastic | 900876 | 3303L | Repl w/ 1060F 2P Rauschenbach PVC | 201508 | 76,298.33 | 2 | 0.0013083 | 199.64 | 1,197.85 |
| 376300-Mains - Plastic | 900876 | 3303L | Repl w/ 1060F 2P Rauschenbach PVC | 201508 | 1,195.70 | 2 | 0.0013083 | 3.13 | 18.77 |
| 376300-Mains - Plastic | 900890 | 3303L | Repl w/ 2218F 2P Russell & Flora | 201508 | (5,880.23) | 2 | 0.0013083 | (15.39) | (92.32) |
| 376300-Mains - Plastic | 900890 | 3303L | Repl w/ 2218F 2P Russell & Flora | 201508 | (130.21) | 2 | 0.0013083 | (0.34) | (2.04) |
| 376300-Mains - Plastic | 900893 | 3303L | Repl w/ 2486F 6P Arlington | 201508 | 259,412.86 | 2 | 0.0013083 | 678.78 | 4,072.68 |
| 376300-Mains - Plastic | 900893 | 3303L | Repl w/ 2486F 6P Arlington | 201508 | 18,646.82 | 2 | 0.0013083 | 48.79 | 292.75 |
| 376300-Mains - Plastic | 900895 | 3303L | Repl w/ 828F 2P Marquette | 201508 | 6,786.60 | 2 | 0.0013083 | 17.76 | 106.55 |
| 376300-Mains - Plastic | 900895 | 3303L | Repl w/ 828F 2P Marquette | 201508 | 265.27 | 2 | 0.0013083 | 0.69 | 4.16 |
| 376300-Mains - Plastic | 900896 | 3303L | Repl w/ 2990F 2P 4P Maple | 201508 | 173,218.23 | 2 | 0.0013083 | 453.24 | 2,719.46 |

| | | | | | | | | | |
|------------------------|--------|-------|-------------------------------------|--------|------------|---|-----------|----------|-----------|
| 376300-Mains - Plastic | 900896 | 3303L | Repl w/ 2990F 2P 4P Maple | 201508 | 8,172.00 | 2 | 0.0013083 | 21.38 | 128.30 |
| 376300-Mains - Plastic | 900897 | 3303L | Repl w/ 587F 2P Syracuse | 201508 | 51,816.96 | 2 | 0.0013083 | 135.58 | 813.51 |
| 376300-Mains - Plastic | 900898 | 3303L | Repl w/ 1220F 2P Ohio | 201508 | (967.21) | 2 | 0.0013083 | (2.53) | (15.18) |
| 376300-Mains - Plastic | 900898 | 3303L | Repl w/ 1220F 2P Ohio | 201508 | (41.65) | 2 | 0.0013083 | (0.11) | (0.65) |
| 376300-Mains - Plastic | 900900 | 3303L | Repl w/ 1075F 2P Washington | 201508 | 3,157.03 | 2 | 0.0013083 | 8.26 | 49.56 |
| 376300-Mains - Plastic | 900900 | 3303L | Repl w/ 1075F 2P Washington | 201508 | 250.71 | 2 | 0.0013083 | 0.66 | 3.94 |
| 376300-Mains - Plastic | 900902 | 3303L | Repl w/ 530' 2P Oakland | 201508 | (347.25) | 2 | 0.0013083 | (0.91) | (5.45) |
| 376300-Mains - Plastic | 900902 | 3303L | Repl w/ 530' 2P Oakland | 201508 | (31.25) | 2 | 0.0013083 | (0.08) | (0.49) |
| 376300-Mains - Plastic | 900905 | 3303L | Repl w/ 806F 2P Utah | 201508 | (2,155.73) | 2 | 0.0013083 | (5.64) | (33.84) |
| 376300-Mains - Plastic | 900905 | 3303L | Repl w/ 806F 2P Utah | 201508 | (110.11) | 2 | 0.0013083 | (0.29) | (1.73) |
| 376300-Mains - Plastic | 900908 | 3303L | Repl w/ 460F 2P California | 201508 | (674.02) | 2 | 0.0013083 | (1.76) | (10.58) |
| 376300-Mains - Plastic | 900908 | 3303L | Repl w/ 460F 2P California | 201508 | 15.92 | 2 | 0.0013083 | 0.04 | 0.25 |
| 376300-Mains - Plastic | 900912 | 3303L | Repl w/ 745F 2P Shaw | 201508 | (828.29) | 2 | 0.0013083 | (2.17) | (13.00) |
| 376300-Mains - Plastic | 900912 | 3303L | Repl w/ 745F 2P Shaw | 201508 | (19.04) | 2 | 0.0013083 | (0.05) | (0.30) |
| 376300-Mains - Plastic | 900921 | 3303L | Repl w/ 2457F 4P&2P Flad AOR | 201508 | (2,222.31) | 2 | 0.0013083 | (5.81) | (34.89) |
| 376300-Mains - Plastic | 900921 | 3303L | Repl w/ 2457F 4P&2P Flad AOR | 201508 | (159.98) | 2 | 0.0013083 | (0.42) | (2.51) |
| 376300-Mains - Plastic | 900932 | 3303L | Repl w/ 160F 2P Cler Ave | 201508 | (89.47) | 2 | 0.0013083 | (0.23) | (1.40) |
| 376300-Mains - Plastic | 900932 | 3303L | Repl w/ 160F 2P Cler Ave | 201508 | (1.63) | 2 | 0.0013083 | - | (0.03) |
| 376100-Mains - Steel | 900945 | 3304L | Inst 3920F 8P Hampton&Sulpher Headr | 201508 | 37,762.33 | 2 | 0.0012000 | 90.63 | 543.78 |
| 376300-Mains - Plastic | 900945 | 3304L | Inst 3920F 8P Hampton&Sulpher Headr | 201508 | 488,878.02 | 2 | 0.0013083 | 1,279.20 | 7,675.19 |
| 376300-Mains - Plastic | 900948 | 3303L | Repl w/ 132F 2P Southcote | 201508 | 207.93 | 2 | 0.0013083 | 0.54 | 3.26 |
| 376300-Mains - Plastic | 900962 | 3304L | Inst 5842F 6P 4P Newstead -Header | 201508 | 461,478.13 | 2 | 0.0013083 | 1,207.50 | 7,245.02 |
| 376300-Mains - Plastic | 900962 | 3304L | Inst 5842F 6P 4P Newstead -Header | 201508 | 141,130.05 | 2 | 0.0013083 | 369.28 | 2,215.69 |
| 376300-Mains - Plastic | 900977 | 3303L | Repl w/ 1291F 4P Boyle | 201508 | 199.15 | 2 | 0.0013083 | 0.52 | 3.13 |
| 376300-Mains - Plastic | 900977 | 3303L | Repl w/ 1291F 4P Boyle | 201508 | 19.69 | 2 | 0.0013083 | 0.05 | 0.31 |
| 376300-Mains - Plastic | 900978 | 3304L | Inst 3875F 8P Brannon Ave-Header | 201508 | 732,655.19 | 2 | 0.0013083 | 1,917.07 | 11,502.39 |
| 376300-Mains - Plastic | 900978 | 3304L | Inst 3875F 8P Brannon Ave-Header | 201508 | 53,382.41 | 2 | 0.0013083 | 139.68 | 838.08 |
| 376300-Mains - Plastic | 900986 | 3303L | Repl w/ 2189F 2P Earthquake Zone 2A | 201508 | 220.24 | 2 | 0.0013083 | 0.58 | 3.46 |
| 376300-Mains - Plastic | 900986 | 3303L | Repl w/ 2189F 2P Earthquake Zone 2A | 201508 | 11.31 | 2 | 0.0013083 | 0.03 | 0.18 |
| 376300-Mains - Plastic | 901025 | 3303L | Repl w/ 85F 2P Walnut Park | 201508 | 50,809.22 | 2 | 0.0013083 | 132.95 | 797.68 |
| 376300-Mains - Plastic | 901025 | 3303L | Repl w/ 85F 2P Walnut Park | 201508 | 4,640.66 | 2 | 0.0013083 | 12.14 | 72.86 |
| 376300-Mains - Plastic | 901040 | 3303L | Repl w/ 315F 2P Amherst Ave | 201508 | 29,234.07 | 2 | 0.0013083 | 76.49 | 458.96 |
| 376300-Mains - Plastic | 901040 | 3303L | Repl w/ 315F 2P Amherst Ave | 201508 | 686.49 | 2 | 0.0013083 | 1.80 | 10.78 |
| 376300-Mains - Plastic | 901112 | 3303L | UGS Gathering Line Replacement | 201508 | 15,950.41 | 2 | 0.0013083 | 41.74 | 250.42 |
| 376300-Mains - Plastic | | 3303L | | | | | | | |
| 376300-Mains - Plastic | | 3303L | | | | | | | |

9,179,740.95

24,398.41

144,019.92

SERVICE TRANSFER WORK ORDERS

| PLANT ACCOUNT | WORK ORDER | BUDGET PROJECT | DESCRIPTION | IN SERVICE DATE | ADDITION AMOUNT | MONTHS | DEPR. MO. RATE | ACCUM. DEPR. | DEPR. EXPENSE |
|------------------------|------------|----------------|------------------------------------|-----------------|-----------------|--------|----------------|--------------|---------------|
| 376100-Mains - Steel | 900633 | 3403L | Rel w/ 321F 4S 2S Progress Parkway | 201507 | (15.53) | 3 | 0.0012000 | (0.06) | (0.22) |
| 376100-Mains - Steel | 900892 | 3403L | Rel w/ 180F 2S Elaine Drive | 201507 | (24.33) | 3 | 0.0012000 | (0.09) | (0.35) |
| 376100-Mains - Steel | 901019 | 3403L | Rel w/ 80F 6S Fee Fee | 201507 | (6.98) | 3 | 0.0012000 | (0.03) | (0.10) |
| 376300-Mains - Plastic | 001040 | 3303L | Install 46F 4P Nashville | 201507 | (0.18) | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 001330 | 3303L | Inst 9084F 2P Aberdeen Pl | 201507 | (901.35) | 3 | 0.0013083 | (3.54) | (14.15) |
| 376300-Mains - Plastic | 001535 | 3303L | Repl w/ 9098F 2P Arlington | 201507 | (24.17) | 3 | 0.0013083 | (0.09) | (0.36) |
| 376300-Mains - Plastic | 001711 | 3303L | Inst 7023F 2P Northmoor Wydown Ph5 | 201507 | 1.51 | 3 | 0.0013083 | 0.01 | 0.02 |
| 376300-Mains - Plastic | 001712 | 3303L | Inst 16489F 2P Cote Brilliante | 201507 | 61,583.32 | 3 | 0.0013083 | 241.71 | 966.83 |
| 376300-Mains - Plastic | 002137 | 3303L | Repl w/ 5955F 2P Boneta | 201507 | 36.36 | 3 | 0.0013083 | 0.14 | 0.57 |
| 376300-Mains - Plastic | 002138 | 3303L | Repl w/ 10203F 2P Manchester | 201507 | (643.58) | 3 | 0.0013083 | (2.53) | (10.10) |
| 376300-Mains - Plastic | 002141 | 3303L | Inst 6161F 2P Marshall-Well, Ph4C | 201507 | 0.34 | 3 | 0.0013083 | - | 0.01 |

| | | | | | | | | | |
|------------------------|--------|-------|-------------------------------------|--------|------------|---|-----------|---------|---------|
| 376300-Mains - Plastic | 900068 | 3303L | Repl w/ 1750F 2P Jefferson Ph 2 | 201507 | (22.67) | 3 | 0.0013083 | (0.09) | (0.36) |
| 376300-Mains - Plastic | 900093 | 3303L | Repl w/ 184F 2P Cass | 201507 | (0.04) | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900265 | 3303L | Repl w/ 3337F 2P Baden Ph 5B | 201507 | (0.03) | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900266 | 3303L | Inst 4640F 2P Baden Ph 5C | 201507 | (0.04) | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900269 | 3303L | Inst 1150F 4P Walnut Park Ph 5A | 201507 | (159.69) | 3 | 0.0013083 | (0.63) | (2.51) |
| 376300-Mains - Plastic | 900275 | 3303L | Repl w/ 4989F 2P Wellington Ph4E | 201507 | 44.94 | 3 | 0.0013083 | 0.18 | 0.71 |
| 376300-Mains - Plastic | 900278 | 3303L | Repl w/ 3977F 2P Walnut Park Ph4C | 201507 | (0.38) | 3 | 0.0013083 | - | (0.01) |
| 376300-Mains - Plastic | 900279 | 3303L | Repl w/ 3345F 2P Walnut Park Ph4D | 201507 | (225.12) | 3 | 0.0013083 | (0.88) | (3.53) |
| 376300-Mains - Plastic | 900282 | 3303L | Inst 4400F 2P Wellston 2C | 201507 | (25.22) | 3 | 0.0013083 | (0.10) | (0.40) |
| 376300-Mains - Plastic | 900284 | 3303L | Inst 5466F 2P Wellston Ph2E | 201507 | (6.23) | 3 | 0.0013083 | (0.02) | (0.10) |
| 376300-Mains - Plastic | 900375 | 3303L | Inst 1747F 6P Litzsinger | 201507 | (0.15) | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900377 | 3303L | Repl w/ 978F 2-4P Big Bend | 201507 | (65.88) | 3 | 0.0013083 | (0.22) | (0.88) |
| 376300-Mains - Plastic | 900379 | 3303L | Inst 783F 4P & 529F 2P Old Bonhomme | 201507 | 0.73 | 3 | 0.0013083 | - | 0.01 |
| 376300-Mains - Plastic | 900388 | 3303L | Repl w/ 332F 2P Tay Rd | 201507 | 4.56 | 3 | 0.0013083 | 0.02 | 0.07 |
| 376300-Mains - Plastic | 900390 | 3303L | Inst 205F 1 1/4P Gore | 201507 | 0.23 | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900392 | 3303L | Inst 580F 4P & 255F 2P Ferguson | 201507 | (0.04) | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900415 | 3303L | Repl w/ 1093F 2P Princeton | 201507 | 2.34 | 3 | 0.0013083 | 0.01 | 0.04 |
| 376300-Mains - Plastic | 900420 | 3303L | Repl w/ 520F 2P Oregon | 201507 | 8.35 | 3 | 0.0013083 | 0.03 | 0.13 |
| 376300-Mains - Plastic | 900423 | 3303L | Repl w/ 1373F 2P Dr MLK | 201507 | 0.03 | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900430 | 3303L | Repl w/ 654F 2P Maurice | 201507 | 0.73 | 3 | 0.0013083 | - | 0.01 |
| 376300-Mains - Plastic | 900432 | 3303L | Repl w/ 503F 2P Gravois | 201507 | (0.70) | 3 | 0.0013083 | - | (0.01) |
| 376300-Mains - Plastic | 900462 | 3303L | Repl w/ 2240F 2P Walnut Park Ph4G | 201507 | (32.98) | 3 | 0.0013083 | (0.13) | (0.52) |
| 376300-Mains - Plastic | 900463 | 3303L | Inst 4082F 2P Walnut Park Ph4H | 201507 | 39.02 | 3 | 0.0013083 | 0.15 | 0.61 |
| 376300-Mains - Plastic | 900464 | 3303L | Inst 4741F 2P Walnut Park Ph 4I | 201507 | (89.82) | 3 | 0.0013083 | (0.35) | (1.41) |
| 376300-Mains - Plastic | 900557 | 3303L | Inst 2123F 2P Walnut Park Ph6A | 201507 | (521.10) | 3 | 0.0013083 | (2.05) | (8.18) |
| 376300-Mains - Plastic | 900623 | 3303L | Repl w/ 2852' 2P Wydown Ph 6 | 201507 | (3,323.23) | 3 | 0.0013083 | (13.04) | (52.17) |
| 376300-Mains - Plastic | 900759 | 3303L | Repl w/ 2836F 2P Hickory Dale | 201507 | 621.34 | 3 | 0.0013083 | 2.44 | 9.75 |
| 376300-Mains - Plastic | 900762 | 3303L | Inst 2069F 2P Earthquake Zone Ph1A | 201507 | (10.28) | 3 | 0.0013083 | (0.04) | (0.16) |
| 376300-Mains - Plastic | 900859 | 3303L | Repl w/ 290F 2P Cabanne | 201507 | (141.51) | 3 | 0.0013083 | (0.56) | (2.22) |
| 376300-Mains - Plastic | 900861 | 3303L | Repl w/ 105F 4P McLaran | 201507 | (9.97) | 3 | 0.0013083 | (0.04) | (0.16) |
| 376300-Mains - Plastic | 900862 | 3303L | Rep w/ 4552F 2P Broadway AOR | 201507 | 13,849.95 | 3 | 0.0013083 | 54.36 | 217.44 |
| 376300-Mains - Plastic | 900890 | 3303L | Repl w/ 2218F 2P Russell & Flora | 201507 | (1,640.45) | 3 | 0.0013083 | (6.44) | (25.75) |
| 376300-Mains - Plastic | 900895 | 3303L | Repl w/ 828F 2P Marquette | 201507 | (276.29) | 3 | 0.0013083 | (1.08) | (4.34) |
| 376300-Mains - Plastic | 900898 | 3303L | Repl w/ 1220F 2P Ohio | 201507 | (1,970.74) | 3 | 0.0013083 | (7.73) | (30.94) |
| 376300-Mains - Plastic | 900900 | 3303L | Repl w/ 1075F 2P Washington | 201507 | (310.68) | 3 | 0.0013083 | (1.22) | (4.88) |
| 376300-Mains - Plastic | 900902 | 3303L | Repl w/ 530' 2P Oakland | 201507 | 1,531.05 | 3 | 0.0013083 | 6.01 | 24.04 |
| 376300-Mains - Plastic | 900905 | 3303L | Repl w/ 806F 2P Utah | 201507 | (154.90) | 3 | 0.0013083 | (0.61) | (2.43) |
| 376300-Mains - Plastic | 900908 | 3303L | Repl w/ 460F 2P California | 201507 | (118.64) | 3 | 0.0013083 | (0.47) | (1.86) |
| 376300-Mains - Plastic | 900912 | 3303L | Repl w/ 745F 2P Shaw | 201507 | 2,180.08 | 3 | 0.0013083 | 8.56 | 34.23 |
| 376300-Mains - Plastic | 900921 | 3303L | Repl w/ 2457F 4P&2P Flad AOR | 201507 | (883.06) | 3 | 0.0013083 | (3.47) | (13.86) |
| 376300-Mains - Plastic | 900977 | 3303L | Repl w/ 1291F 4P Boyle | 201507 | (16.10) | 3 | 0.0013083 | (0.06) | (0.25) |
| 376300-Mains - Plastic | 900986 | 3303L | Repl w/ 2189F 2P Earthquake Zone 2A | 201507 | (3,824.44) | 3 | 0.0013083 | (15.01) | (60.04) |
| 376300-Mains - Plastic | 900099 | 3403L | Rel 1830F 2P McKnight Rd | 201507 | (14.59) | 3 | 0.0013083 | (0.06) | (0.23) |
| 376300-Mains - Plastic | 900670 | 3403L | Rel w/ 400F 6P Vogel Rd | 201507 | (45.04) | 3 | 0.0013083 | (0.18) | (0.71) |
| 376300-Mains - Plastic | 900723 | 3403L | Rel w/ 3350F 2P Valley Park | 201507 | (1.30) | 3 | 0.0013083 | (0.01) | (0.02) |
| 376300-Mains - Plastic | 900730 | 3403L | Rel w/ 310F 2P Bramblett | 201507 | (49.91) | 3 | 0.0013083 | (0.20) | (0.78) |
| 376300-Mains - Plastic | 900775 | 3403L | Rel w/ 1535F 2P Page&Hodiamont AOR | 201507 | (387.26) | 3 | 0.0013083 | (1.52) | (6.08) |
| 376300-Mains - Plastic | 900822 | 3403L | Rel w/ 130F 6S Price Road | 201507 | (275.08) | 3 | 0.0013083 | (1.08) | (4.32) |
| 376300-Mains - Plastic | 900911 | 3403L | Rel w/ 300F 2P Edgewood | 201507 | (0.07) | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900961 | 3403L | Rel w/ 190F 2P Clay | 201507 | (32.60) | 3 | 0.0013083 | (0.13) | (0.51) |
| 376300-Mains - Plastic | 900841 | 340RL | Rel w/ 57F 4P Ashland AOR | 201507 | (28.57) | 3 | 0.0013083 | (0.11) | (0.45) |
| 376300-Mains - Plastic | 900848 | 340RL | Rel w/ 810F 4P Bircher & Newstead | 201507 | (250.66) | 3 | 0.0013083 | (0.98) | (3.94) |
| 376300-Mains - Plastic | 901015 | 340RL | Rel w/ 35F 4P Elmbank & Taylor AOR | 201507 | 3,046.52 | 3 | 0.0013083 | 11.96 | 47.83 |
| 376300-Mains - Plastic | 000569 | 3304L | 4015F 6P 2P Lemay Ferry | 201508 | (0.01) | 2 | 0.0013083 | - | - |
| 376100-Mains - Steel | 001040 | 3303L | Install 46F 4P Nashville | 201508 | 0.26 | 2 | 0.0012000 | - | - |

| | | | | | | | | | |
|------------------------|--------|-------|-------------------------------------|--------|------------|---|-----------|---------|----------|
| 376300-Mains - Plastic | 001330 | 3303L | Inst 9084F 2P Aberdeen Pl | 201508 | (1,590.98) | 2 | 0.0013083 | (4.16) | (24.98) |
| 376100-Mains - Steel | 001535 | 3303L | Repl w/ 9098F 2P Arlington | 201508 | (45.35) | 2 | 0.0012000 | (0.11) | (0.65) |
| 376300-Mains - Plastic | 001711 | 3303L | Inst 7023F 2P Northmoor Wydown Ph5 | 201508 | 2.14 | 2 | 0.0013083 | 0.01 | 0.03 |
| 376300-Mains - Plastic | 001712 | 3303L | Inst 16489F 2P Cote Brilliante | 201508 | 34,753.99 | 2 | 0.0013083 | 90.94 | 545.62 |
| 376300-Mains - Plastic | 002137 | 3303L | Repl w/ 5955F 2P Boneta | 201508 | 1,435.89 | 2 | 0.0013083 | 3.76 | 22.54 |
| 376300-Mains - Plastic | 002138 | 3303L | Repl w/ 10203F 2P Manchester | 201508 | 12,157.54 | 2 | 0.0013083 | 31.81 | 190.87 |
| 376100-Mains - Steel | 002139 | 3303L | Inst 3278F 2P MLK -Wellston 1B | 201508 | 376,072.61 | 2 | 0.0012000 | 902.57 | 5,415.45 |
| 376300-Mains - Plastic | 002140 | 3303L | Inst 6894F 2P Bertha-Wellston 1A | 201508 | 163,975.30 | 2 | 0.0013083 | 429.06 | 2,574.35 |
| 376100-Mains - Steel | 002141 | 3303L | Inst 6161F 2P Marshall-Well, Ph4C | 201508 | 0.24 | 2 | 0.0012000 | - | - |
| 376300-Mains - Plastic | 900068 | 3303L | Repl w/ 1750F 2P Jefferson Ph 2 | 201508 | (62.67) | 2 | 0.0013083 | (0.16) | (0.98) |
| 376100-Mains - Steel | 900093 | 3303L | Repl w/ 184F 2P Cass | 201508 | 0.02 | 2 | 0.0012000 | - | - |
| 376300-Mains - Plastic | 900099 | 3403L | Rel 1830F 2P McKnight Rd | 201508 | (32.75) | 2 | 0.0013083 | (0.09) | (0.51) |
| 376100-Mains - Steel | 900265 | 3303L | Repl w/ 3337F 2P Baden Ph 5B | 201508 | 0.03 | 2 | 0.0012000 | - | - |
| 376300-Mains - Plastic | 900266 | 3303L | Inst 4640F 2P Baden Ph 5C | 201508 | (0.01) | 2 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900269 | 3303L | Inst 1150F 4P Walnut Park Ph 5A | 201508 | (346.78) | 2 | 0.0013083 | (0.91) | (5.44) |
| 376100-Mains - Steel | 900270 | 3303L | Inst 2942F 2P Walnut Park Ph5B | 201508 | 63,016.34 | 2 | 0.0012000 | 151.24 | 907.44 |
| 376100-Mains - Steel | 900275 | 3303L | Repl w/ 4989F 2P Wellington Ph4E | 201508 | (1,080.47) | 2 | 0.0012000 | (2.59) | (15.56) |
| 376300-Mains - Plastic | 900278 | 3303L | Repl w/ 3977F 2P Walnut Park Ph4C | 201508 | (0.81) | 2 | 0.0013083 | - | (0.01) |
| 376300-Mains - Plastic | 900279 | 3303L | Repl w/ 3345F 2P Walnut Park Ph4D | 201508 | (214.20) | 2 | 0.0013083 | (0.56) | (3.36) |
| 376300-Mains - Plastic | 900282 | 3303L | Inst 4400F 2P Wellston 2C | 201508 | (465.64) | 2 | 0.0013083 | (1.22) | (7.31) |
| 376300-Mains - Plastic | 900284 | 3303L | Inst 5466F 2P Wellston Ph2E | 201508 | (12.22) | 2 | 0.0013083 | (0.03) | (0.19) |
| 376300-Mains - Plastic | 900375 | 3303L | Inst 1747F 6P Litzinger | 201508 | 0.11 | 2 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900377 | 3303L | Repl w/ 978F 2-4P Big Bend | 201508 | (147.69) | 2 | 0.0013083 | (0.39) | (2.32) |
| 376300-Mains - Plastic | 900379 | 3303L | Inst 783F 4P & 529F 2P Old Bonhomme | 201508 | (5.48) | 2 | 0.0013083 | (0.01) | (0.09) |
| 376300-Mains - Plastic | 900388 | 3303L | Repl w/ 332F 2P Tay Rd | 201508 | 4.50 | 2 | 0.0013083 | 0.01 | 0.07 |
| 376300-Mains - Plastic | 900390 | 3303L | Inst 205F 1 1/4P Gore | 201508 | 0.65 | 2 | 0.0013083 | - | 0.01 |
| 376300-Mains - Plastic | 900392 | 3303L | Inst 580F 4P & 255F 2P Ferguson | 201508 | (0.02) | 2 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900415 | 3303L | Repl w/ 1093F 2P Princeton | 201508 | 1.86 | 2 | 0.0013083 | - | 0.03 |
| 376300-Mains - Plastic | 900420 | 3303L | Repl w/ 520F 2P Oregon | 201508 | 7.99 | 2 | 0.0013083 | 0.02 | 0.13 |
| 376300-Mains - Plastic | 900423 | 3303L | Repl w/ 1373F 2P Dr MLK | 201508 | (0.02) | 2 | 0.0013083 | - | - |
| 376100-Mains - Steel | 900430 | 3303L | Repl w/ 654F 2P Maurice | 201508 | 0.82 | 2 | 0.0012000 | - | 0.01 |
| 376300-Mains - Plastic | 900432 | 3303L | Repl w/ 503F 2P Gravois | 201508 | (1.72) | 2 | 0.0013083 | - | (0.03) |
| 376300-Mains - Plastic | 900462 | 3303L | Repl w/ 2240F 2P Walnut Park Ph4G | 201508 | (289.25) | 2 | 0.0013083 | (0.76) | (4.54) |
| 376300-Mains - Plastic | 900463 | 3303L | Inst 4082F 2P Walnut Park Ph4H | 201508 | (53.38) | 2 | 0.0013083 | (0.14) | (0.84) |
| 376100-Mains - Steel | 900464 | 3303L | Inst 4741F 2P Walnut Park Ph 4I | 201508 | (188.47) | 2 | 0.0012000 | (0.45) | (2.71) |
| 376100-Mains - Steel | 900557 | 3303L | Inst 2123F 2P Walnut Park Ph6A | 201508 | (1,603.38) | 2 | 0.0012000 | (3.85) | (23.09) |
| 376100-Mains - Steel | 900559 | 3303L | Inst 3875F 2P Walnut Park Ph6C | 201508 | 162,542.78 | 2 | 0.0012000 | 390.10 | 2,340.62 |
| 376300-Mains - Plastic | 900623 | 3303L | Repl w/ 2852' 2P Wydown Ph 6 | 201508 | (472.15) | 2 | 0.0013083 | (1.24) | (7.41) |
| 376300-Mains - Plastic | 900633 | 3403L | Rel w/ 3211F 4S 2S Progress Parkway | 201508 | 58.36 | 2 | 0.0013083 | 0.15 | 0.92 |
| 376300-Mains - Plastic | 900652 | 3303L | Inst 4435F 2P St Louis Hills Ph1B | 201508 | 126,144.49 | 2 | 0.0013083 | 330.07 | 1,980.42 |
| 376300-Mains - Plastic | 900653 | 3303L | Inst 2636F 2P St Louis Hills Ph1C | 201508 | 129,675.09 | 2 | 0.0013083 | 339.31 | 2,035.85 |
| 376300-Mains - Plastic | 900670 | 3403L | Rel w/ 400F 6P Vogel Rd | 201508 | 283.78 | 2 | 0.0013083 | 0.74 | 4.46 |
| 376300-Mains - Plastic | 900723 | 3403L | Rel w/ 3350F 2P Valley Park | 201508 | 5.63 | 2 | 0.0013083 | 0.01 | 0.09 |
| 376300-Mains - Plastic | 900730 | 3403L | Rel w/ 310F 2P Bramblett | 201508 | 64.45 | 2 | 0.0013083 | 0.17 | 1.01 |
| 376300-Mains - Plastic | 900734 | 3303L | Repl w/ 1717F 2P Hurck | 201508 | 89,389.45 | 2 | 0.0013083 | 233.90 | 1,403.38 |
| 376300-Mains - Plastic | 900738 | 3303L | Repl w/ 780F 2P Kingsland MSD | 201508 | 46,695.23 | 2 | 0.0013083 | 122.18 | 733.10 |
| 376300-Mains - Plastic | 900759 | 3303L | Repl w/ 2836F 2P Hickory Dale | 201508 | (1,510.99) | 2 | 0.0013083 | (3.95) | (23.72) |
| 376300-Mains - Plastic | 900762 | 3303L | Inst 2069F 2P Earthquake Zone Ph1A | 201508 | (51.23) | 2 | 0.0013083 | (0.13) | (0.80) |
| 376100-Mains - Steel | 900775 | 3403L | Rel w/ 1535F 2P Page&Hodiament AOR | 201508 | (257.74) | 2 | 0.0012000 | (0.62) | (3.71) |
| 376300-Mains - Plastic | 900822 | 3403L | Repl w/ 130F 6S Price Road | 201508 | (415.32) | 2 | 0.0013083 | (1.09) | (6.52) |
| 376300-Mains - Plastic | 900841 | 340RL | Rel w/ 57F 4P Ashland AOR | 201508 | (47.27) | 2 | 0.0013083 | (0.12) | (0.74) |
| 376300-Mains - Plastic | 900848 | 340RL | Rel w/ 810F 4P Bircher & Newstead | 201508 | (485.06) | 2 | 0.0013083 | (1.27) | (7.62) |
| 376300-Mains - Plastic | 900859 | 3303L | Repl w/ 290F 2P Cabanne | 201508 | (88.11) | 2 | 0.0013083 | (0.23) | (1.38) |
| 376300-Mains - Plastic | 900861 | 3303L | Repl w/ 105F 4P McLaran | 201508 | (20.05) | 2 | 0.0013083 | (0.05) | (0.31) |
| 376300-Mains - Plastic | 900862 | 3303L | Repl w/ 4552F 2P Broadway AOR | 201508 | (3,823.86) | 2 | 0.0013083 | (10.01) | (60.03) |

| | | | | | | | | |
|------------------------------------|--------|-------------------------------------|--------|-------------|---|-----------|----------|-----------|
| 380200-Services - Plastic & Copper | 697470 | 69747 SVC RNW 5/4 PL MN | 201507 | 26,976.47 | 3 | 0.0031250 | 252.90 | 1,011.62 |
| 380200-Services - Plastic & Copper | 697480 | 69748 SVC RNW 2" & OVR MN | 201507 | 59,253.21 | 3 | 0.0031250 | 555.50 | 2,222.00 |
| 380200-Services - Plastic & Copper | 698400 | 69840 SVC RNW COR TRFR STCH | 201507 | (2,156.29) | 3 | 0.0031250 | (20.22) | (80.88) |
| 380200-Services - Plastic & Copper | 698450 | 69845 SVC RNW 1/2 PL SC | 201507 | 47,375.69 | 3 | 0.0031250 | 444.15 | 1,776.59 |
| 380200-Services - Plastic & Copper | 698460 | 69846 SVC RNW 1IN PL SC | 201507 | 10,429.24 | 3 | 0.0031250 | 97.77 | 391.10 |
| 380200-Services - Plastic & Copper | 698470 | 69847 SV RNW 1-1/4 PL SC | 201507 | 244.39 | 3 | 0.0031250 | 2.29 | 9.16 |
| 380200-Services - Plastic & Copper | 698480 | 69848 SV RNW 2&OVR PL SC | 201507 | (30.83) | 3 | 0.0031250 | (0.29) | (1.16) |
| 380200-Services - Plastic & Copper | 698500 | 69850 RELAY COPPER SVC- ST CHR | 201507 | 0.18 | 3 | 0.0031250 | - | 0.01 |
| 380200-Services - Plastic & Copper | 699300 | 69930 SVC REN 1/2 PL CTY | 201507 | 346,383.50 | 3 | 0.0031250 | 3,247.35 | 12,989.38 |
| 380200-Services - Plastic & Copper | 699310 | 69931 SVC REN 1IN PL CTY | 201507 | 137,806.94 | 3 | 0.0031250 | 1,291.94 | 5,167.78 |
| 380200-Services - Plastic & Copper | 699320 | 69932 SVC REN 1 1/4 PL C | 201507 | 7,409.15 | 3 | 0.0031250 | 69.46 | 277.84 |
| 380200-Services - Plastic & Copper | 699330 | 69933 SVC REN 2&OVR PL C | 201507 | 247.94 | 3 | 0.0031250 | 2.32 | 9.30 |
| 380200-Services - Plastic & Copper | 699400 | 69940 SVC REN COR TRANSFER CI | 201507 | (6,296.18) | 3 | 0.0031250 | (59.03) | (236.11) |
| 380200-Services - Plastic & Copper | 699410 | 69941 SVC REN COR TRANSFER CO | 201507 | (14,113.89) | 3 | 0.0031250 | (132.32) | (529.27) |
| 380200-Services - Plastic & Copper | 900068 | Repl w/ 1750F 2P Jefferson Ph 2 | 201507 | (14.61) | 3 | 0.0031250 | (0.14) | (0.55) |
| 380200-Services - Plastic & Copper | 900072 | Repl w 688F 2P & 2527F 4P Lafayette | 201507 | 0.05 | 3 | 0.0031250 | - | - |
| 380200-Services - Plastic & Copper | 900073 | Repl w/ 2520F 2P Jefferson Ph 6 | 201507 | (1,232.77) | 3 | 0.0031250 | (11.56) | (46.23) |
| 380200-Services - Plastic & Copper | 900093 | Repl w/ 184F 2P Cass | 201507 | (0.05) | 3 | 0.0031250 | - | - |
| 380200-Services - Plastic & Copper | 900099 | Rel 1830F 2P McKnight Rd | 201507 | (17.48) | 3 | 0.0031250 | (0.16) | (0.66) |
| 380200-Services - Plastic & Copper | 900233 | Rel w/ 1924F 6P Fee Fee Road | 201507 | 0.12 | 3 | 0.0031250 | - | - |
| 380200-Services - Plastic & Copper | 900264 | Int 3087F 4P 2P Baden Grid Ph 5A | 201507 | (16.40) | 3 | 0.0031250 | (0.15) | (0.62) |
| 380200-Services - Plastic & Copper | 900265 | Repl w/ 3337F 2P Baden Ph 5B | 201507 | (3.35) | 3 | 0.0031250 | (0.03) | (0.13) |
| 380200-Services - Plastic & Copper | 900266 | Inst 4640F 2P Baden Ph 5C | 201507 | (3.79) | 3 | 0.0031250 | (0.04) | (0.14) |
| 380200-Services - Plastic & Copper | 900267 | Repl w/ 4536F 2P Baden Ph5D | 201507 | (2.96) | 3 | 0.0031250 | (0.03) | (0.11) |
| 380200-Services - Plastic & Copper | 900268 | Inst 4411F 2P Baden Ph5E | 201507 | (3.50) | 3 | 0.0031250 | (0.03) | (0.13) |
| 380200-Services - Plastic & Copper | 900269 | Inst 1150F 4P Walnut Park Ph 5A | 201507 | (205.46) | 3 | 0.0031250 | (1.93) | (7.70) |
| 380200-Services - Plastic & Copper | 900275 | Repl w/ 4989F 2P Wellington Ph4E | 201507 | 79.74 | 3 | 0.0031250 | 0.75 | 2.99 |
| 380200-Services - Plastic & Copper | 900277 | Repl w/ 1725F 2P Walnut Park Ph4B | 201507 | (27.24) | 3 | 0.0031250 | (0.26) | (1.02) |
| 380200-Services - Plastic & Copper | 900278 | Repl w/ 3977F 2P Walnut Park Ph4C | 201507 | (37.87) | 3 | 0.0031250 | (0.36) | (1.42) |
| 380200-Services - Plastic & Copper | 900279 | Repl w/ 3345F 2P Walnut Park Ph4D | 201507 | (802.16) | 3 | 0.0031250 | (7.52) | (30.08) |
| 380200-Services - Plastic & Copper | 900281 | Inst 4984F 4PWellston Phase 2B | 201507 | 0.50 | 3 | 0.0031250 | - | 0.02 |
| 380200-Services - Plastic & Copper | 900282 | Inst 4400F 2P Wellston 2C | 201507 | (91.81) | 3 | 0.0031250 | (0.86) | (3.44) |
| 380200-Services - Plastic & Copper | 900283 | Inst 5300F 2P Wellston Ph2D | 201507 | (1.18) | 3 | 0.0031250 | (0.01) | (0.04) |
| 380200-Services - Plastic & Copper | 900284 | Inst 5466F 2P Wellston Ph2E | 201507 | (447.31) | 3 | 0.0031250 | (4.19) | (16.77) |
| 380200-Services - Plastic & Copper | 900375 | Inst 1747F 6P Litzsinger | 201507 | (0.11) | 3 | 0.0031250 | - | - |
| 380200-Services - Plastic & Copper | 900377 | Repl w/ 978F 2-4P Big Bend | 201507 | (65.91) | 3 | 0.0031250 | (0.62) | (2.47) |
| 380200-Services - Plastic & Copper | 900379 | Inst 783F 4P & 529F 2POld Bonhomme | 201507 | 0.52 | 3 | 0.0031250 | - | 0.02 |
| 380200-Services - Plastic & Copper | 900388 | Repl w/ 332F 2P Tay Rd | 201507 | 1.48 | 3 | 0.0031250 | 0.01 | 0.06 |
| 380200-Services - Plastic & Copper | 900390 | Inst 205F 1 1/4P Gore | 201507 | 0.39 | 3 | 0.0031250 | - | 0.01 |
| 380200-Services - Plastic & Copper | 900392 | Inst 580F 4P & 255F 2P Ferguson | 201507 | (0.04) | 3 | 0.0031250 | - | - |
| 380200-Services - Plastic & Copper | 900395 | Repl w/ 525F 2P Clay St | 201507 | 0.50 | 3 | 0.0031250 | - | 0.02 |
| 380200-Services - Plastic & Copper | 900415 | Repl w/ 1093F 2P Princeton | 201507 | 0.91 | 3 | 0.0031250 | 0.01 | 0.03 |
| 380200-Services - Plastic & Copper | 900420 | Repl w/ 520F 2P Oregon | 201507 | 0.40 | 3 | 0.0031250 | - | 0.02 |
| 380200-Services - Plastic & Copper | 900421 | Repl w/ 970F 2P Winnebago | 201507 | 6.56 | 3 | 0.0031250 | 0.06 | 0.25 |
| 380200-Services - Plastic & Copper | 900422 | Repl w/ 780F 2P Taft | 201507 | 2.93 | 3 | 0.0031250 | 0.03 | 0.11 |
| 380200-Services - Plastic & Copper | 900423 | Repl w/ 1373F 2P Dr MLK | 201507 | 0.05 | 3 | 0.0031250 | - | - |
| 380200-Services - Plastic & Copper | 900424 | Repl w/ 520F 3P Red Bud | 201507 | (0.25) | 3 | 0.0031250 | - | (0.01) |
| 380200-Services - Plastic & Copper | 900430 | Repl w/ 654F 2P Maurice | 201507 | 1.01 | 3 | 0.0031250 | 0.01 | 0.04 |
| 380200-Services - Plastic & Copper | 900432 | Repl w/ 503F 2P Gravois | 201507 | (0.76) | 3 | 0.0031250 | (0.01) | (0.03) |
| 380200-Services - Plastic & Copper | 900433 | Repl w/ 570F 4P Chippewa | 201507 | 4.94 | 3 | 0.0031250 | 0.05 | 0.19 |
| 380200-Services - Plastic & Copper | 900439 | Repl w/ 269F 2P Ferguson | 201507 | 0.28 | 3 | 0.0031250 | - | 0.01 |
| 380200-Services - Plastic & Copper | 900457 | Inst 4546F 2P Baden Ph5F | 201507 | 1.95 | 3 | 0.0031250 | 0.02 | 0.07 |
| 380200-Services - Plastic & Copper | 900460 | Inst 3488F 2P Walnut Park Ph4E | 201507 | 1.66 | 3 | 0.0031250 | 0.02 | 0.06 |
| 380200-Services - Plastic & Copper | 900461 | Inst 893F 2P Walnut Park Ph4F | 201507 | 0.04 | 3 | 0.0031250 | - | - |
| 380200-Services - Plastic & Copper | 900462 | Repl w/ 2240F 2P Walnut Park Ph4G | 201507 | (77.10) | 3 | 0.0031250 | (0.72) | (2.89) |

| | | | | | | | | |
|------------------------------------|--------|-------------------------------------|--------|------------|---|-----------|---------|-----------|
| 380200-Services - Plastic & Copper | 900463 | Inst 4082F 2P Walnut Park Ph4H | 201507 | 372.93 | 3 | 0.0031250 | 3.50 | 13.98 |
| 380200-Services - Plastic & Copper | 900464 | Inst 4741F 2P Walnut Park Ph 4I | 201507 | (122.00) | 3 | 0.0031250 | (1.14) | (4.58) |
| 380200-Services - Plastic & Copper | 900487 | Repl w/ 2400F 2-4P Potomac AOR | 201507 | 0.27 | 3 | 0.0031250 | - | 0.01 |
| 380200-Services - Plastic & Copper | 900485 | Inst 4236F 12P Alaska | 201507 | (0.02) | 3 | 0.0031250 | - | - |
| 380200-Services - Plastic & Copper | 900488 | Repl w/ 2873F 6P Hodiament | 201507 | (0.18) | 3 | 0.0031250 | - | (0.01) |
| 380200-Services - Plastic & Copper | 900536 | Aband 1681F 6CWalnut Park Ph4B | 201507 | (49.69) | 3 | 0.0031250 | (0.47) | (1.88) |
| 380200-Services - Plastic & Copper | 900557 | Inst 2123F 2P Walnut Park Ph6A | 201507 | (689.61) | 3 | 0.0031250 | (6.47) | (25.86) |
| 380200-Services - Plastic & Copper | 900599 | Rel w/ 288F 6P Pitman Hill CJ note | 201507 | (25.03) | 3 | 0.0031250 | (0.23) | (0.94) |
| 380200-Services - Plastic & Copper | 900623 | Repl w/ 2852' 2P Wydown Ph 6 | 201507 | (4,569.34) | 3 | 0.0031250 | (42.84) | (171.35) |
| 380200-Services - Plastic & Copper | 900677 | Inst 1795F 2P Cole & 18th PhA | 201507 | (496.44) | 3 | 0.0031250 | (4.65) | (18.62) |
| 380200-Services - Plastic & Copper | 900679 | Inst 2312F 4P Cole & 18th PhB | 201507 | (200.02) | 3 | 0.0031250 | (1.88) | (7.50) |
| 380200-Services - Plastic & Copper | 900681 | Inst 1637F 2P Cole & 18th Ph C | 201507 | (1,241.37) | 3 | 0.0031250 | (11.64) | (46.55) |
| 380200-Services - Plastic & Copper | 900683 | Inst 1864F 2P Cole & 18th Ph D | 201507 | (65.77) | 3 | 0.0031250 | (0.62) | (2.47) |
| 380200-Services - Plastic & Copper | 900685 | Inst 1550F 2P Cole & 18th PhE | 201507 | 563.29 | 3 | 0.0031250 | 5.28 | 21.12 |
| 380200-Services - Plastic & Copper | 900697 | Inst 1096F 2P Cole & 18th PhF | 201507 | 1,333.49 | 3 | 0.0031250 | 12.50 | 50.01 |
| 380200-Services - Plastic & Copper | 900689 | Inst 2434F 2P Cole & 18th PhG | 201507 | 3,337.12 | 3 | 0.0031250 | 31.29 | 125.14 |
| 380200-Services - Plastic & Copper | 900691 | Repl w/ 3458F 2P Cole & 18th Ph H | 201507 | 43,612.47 | 3 | 0.0031250 | 408.87 | 1,635.47 |
| 380200-Services - Plastic & Copper | 900723 | Rel w/ 3350F 2P Valley Park | 201507 | (1.27) | 3 | 0.0031250 | (0.01) | (0.05) |
| 380200-Services - Plastic & Copper | 900730 | Rel w/ 310F 2P Bramblett | 201507 | (24.50) | 3 | 0.0031250 | (0.23) | (0.92) |
| 380200-Services - Plastic & Copper | 900762 | Inst 2069F 2P Earthquake Zone Ph1A | 201507 | (238.26) | 3 | 0.0031250 | (2.23) | (8.93) |
| 380200-Services - Plastic & Copper | 900763 | Inst 3508F 2P Earthquake Zone Ph1B | 201507 | (2,059.19) | 3 | 0.0031250 | (19.30) | (77.22) |
| 380200-Services - Plastic & Copper | 900764 | Repl w/758F 2P Earthquake Zone Ph1C | 201507 | (346.60) | 3 | 0.0031250 | (3.25) | (13.00) |
| 380200-Services - Plastic & Copper | 900765 | Inst 1899F 4P Earthquake Zone Ph1D | 201507 | (634.79) | 3 | 0.0031250 | (5.95) | (23.80) |
| 380200-Services - Plastic & Copper | 900775 | Rel w/ 1535F 2P Page&Hodiament AOR | 201507 | (207.98) | 3 | 0.0031250 | (1.95) | (7.80) |
| 380200-Services - Plastic & Copper | 900813 | Rel w/ 700F 2P Froesel | 201507 | (0.31) | 3 | 0.0031250 | - | (0.01) |
| 380200-Services - Plastic & Copper | 900822 | Rel w/ 130F 6S Price Road | 201507 | (255.80) | 3 | 0.0031250 | (2.40) | (9.59) |
| 380200-Services - Plastic & Copper | 900848 | Rel w/ 810F 4P Bircher & Newstead | 201507 | (276.00) | 3 | 0.0031250 | (2.59) | (10.35) |
| 380200-Services - Plastic & Copper | 900859 | Repl w/ 290F 2P Cabanne | 201507 | (210.52) | 3 | 0.0031250 | (1.97) | (7.89) |
| 380200-Services - Plastic & Copper | 900861 | Repl w/ 105F 4P McLaran | 201507 | (6.39) | 3 | 0.0031250 | (0.06) | (0.24) |
| 380200-Services - Plastic & Copper | 900890 | Repl w/ 2218F 2P Russell & Flora | 201507 | (9.16) | 3 | 0.0031250 | (0.09) | (0.34) |
| 380200-Services - Plastic & Copper | 900895 | Repl w/ 828F 2P Marquette | 201507 | (359.47) | 3 | 0.0031250 | (3.37) | (13.48) |
| 380200-Services - Plastic & Copper | 900898 | Repl w/ 1220F 2P Ohio | 201507 | (2,564.15) | 3 | 0.0031250 | (24.04) | (96.16) |
| 380200-Services - Plastic & Copper | 900900 | Repl w/ 1075F 2P Washington | 201507 | (404.24) | 3 | 0.0031250 | (3.79) | (15.16) |
| 380200-Services - Plastic & Copper | 900905 | Repl w/ 806F 2P Utah | 201507 | (201.54) | 3 | 0.0031250 | (1.89) | (7.56) |
| 380200-Services - Plastic & Copper | 900907 | Aband 500F 4C Natural Bridge | 201507 | (36.96) | 3 | 0.0031250 | (0.35) | (1.39) |
| 380200-Services - Plastic & Copper | 900908 | Repl w/ 460F 2P California | 201507 | (32.10) | 3 | 0.0031250 | (0.30) | (1.20) |
| 380200-Services - Plastic & Copper | 900912 | Repl w/ 745F 2P Shaw | 201507 | 3,138.67 | 3 | 0.0031250 | 29.43 | 117.70 |
| 380200-Services - Plastic & Copper | 900920 | Rel w/ 32F 2S Burroughs MSD CJ | 201507 | (2,750.41) | 3 | 0.0031250 | (25.79) | (103.14) |
| 380200-Services - Plastic & Copper | 900921 | Repl w/ 2457F 4P&2P Flad AOR | 201507 | (1,148.93) | 3 | 0.0031250 | (10.77) | (43.08) |
| 380200-Services - Plastic & Copper | 900961 | Rel w/ 190F 2P Clay | 201507 | (37.16) | 3 | 0.0031250 | (0.35) | (1.39) |
| 380200-Services - Plastic & Copper | 900977 | Repl w/ 1291F 4P Boyle | 201507 | (35.30) | 3 | 0.0031250 | (0.33) | (1.32) |
| 380200-Services - Plastic & Copper | 900986 | Repl w/ 2189F 2P Earthquake Zone 2A | 201507 | (4,976.01) | 3 | 0.0031250 | (46.65) | (186.60) |
| 380200-Services - Plastic & Copper | 901011 | Rel w/ 450F 4P Sanford AOR | 201507 | (320.32) | 3 | 0.0031250 | (3.00) | (12.01) |
| 380200-Services - Plastic & Copper | 901019 | Rel w/ 80F 6S Fee Fee | 201507 | (10.40) | 3 | 0.0031250 | (0.10) | (0.39) |
| 380200-Services - Plastic & Copper | 694360 | 69436 SVCS RENEW PLS 5/8-1IN | 201508 | (510.00) | | 0.0031250 | - | (19.13) |
| 380200-Services - Plastic & Copper | 694370 | 69437 SVCS RENEW PLS 5/4-2IN | 201508 | (27.42) | | 0.0031250 | - | (1.03) |
| 380200-Services - Plastic & Copper | 695300 | 69530 SVC REN 1/2 PL SO | 201508 | 923,950.02 | | 0.0031250 | - | 34,648.13 |
| 380200-Services - Plastic & Copper | 695310 | 69531 SV REN 1IN PL SO | 201508 | 39,380.44 | | 0.0031250 | - | 1,476.77 |
| 380200-Services - Plastic & Copper | 695320 | 69532 SV REN 1 1/4 PL SO | 201508 | (598.67) | | 0.0031250 | - | (22.45) |
| 380200-Services - Plastic & Copper | 695330 | 69533 SV REN 2&OVR PL SO | 201508 | (2,558.38) | | 0.0031250 | - | (95.86) |
| 380200-Services - Plastic & Copper | 695800 | 69580 SVC REN 1/2 PL NO | 201508 | 24,766.02 | | 0.0031250 | - | 928.73 |
| 380200-Services - Plastic & Copper | 695810 | 69581 SV REN 1IN PL NO | 201508 | 11,157.83 | | 0.0031250 | - | 418.42 |
| 380200-Services - Plastic & Copper | 695820 | 69582 SV REN 1 1/4 PL NO | 201508 | 8,765.96 | | 0.0031250 | - | 328.72 |
| 380200-Services - Plastic & Copper | 695830 | 69583 SV REN 2&OVR PL NO | 201508 | (81.30) | | 0.0031250 | - | (3.05) |
| 380200-Services - Plastic & Copper | 695840 | 69584 RNW COPPER SVCS-NORTH | 201508 | (334.97) | | 0.0031250 | - | (12.56) |

| | | | | | | | |
|------------------------------------|--------|-------------------------------------|--------|-------------|-----------|---|------------|
| 380200-Services - Plastic & Copper | 696400 | 69640 SVC REN COR TRFR MIDW | 201508 | (171.19) | 0.0031250 | - | (6.42) |
| 380200-Services - Plastic & Copper | 696450 | 69645 SVC REN 1/2 PL MW | 201508 | 4,418.24 | 0.0031250 | - | 165.68 |
| 380200-Services - Plastic & Copper | 696460 | 69646 SVC REN 1IN PL MW | 201508 | (30.13) | 0.0031250 | - | (1.13) |
| 380200-Services - Plastic & Copper | 696470 | 69647 SV REN 1-1/4 PL MW | 201508 | (54.86) | 0.0031250 | - | (2.06) |
| 380200-Services - Plastic & Copper | 696480 | 69648 SV REN 2&OVR PL MW | 201508 | 3,425.53 | 0.0031250 | - | 128.46 |
| 380200-Services - Plastic & Copper | 697450 | 69745 SVC REN 1/2 PL MN | 201508 | 2,221.13 | 0.0031250 | - | 83.29 |
| 380200-Services - Plastic & Copper | 697460 | 69746 SVC RNW 1IN PL MN | 201508 | (118.81) | 0.0031250 | - | (4.45) |
| 380200-Services - Plastic & Copper | 697470 | 69747 SVC RNW 5/4 PL MN | 201508 | (8,116.53) | 0.0031250 | - | (304.37) |
| 380200-Services - Plastic & Copper | 697480 | 69748 SVC RNW 2" & OVR MN | 201508 | (30,281.71) | 0.0031250 | - | (1,135.56) |
| 380200-Services - Plastic & Copper | 698400 | 69840 SVC RNW COR TRFR STCH | 201508 | (258.48) | 0.0031250 | - | (9.69) |
| 380200-Services - Plastic & Copper | 698450 | 69845 SVC RNW 1/2 PL SC | 201508 | 64,194.08 | 0.0031250 | - | 2,407.28 |
| 380200-Services - Plastic & Copper | 698460 | 69846 SVC RNW 1IN PL SC | 201508 | (3,527.20) | 0.0031250 | - | (132.27) |
| 380200-Services - Plastic & Copper | 698470 | 69847 SV RNW 1-1/4 PL SC | 201508 | 5,052.14 | 0.0031250 | - | 189.46 |
| 380200-Services - Plastic & Copper | 698480 | 69848 SV RNW 2&OVR PL SC | 201508 | 1,869.02 | 0.0031250 | - | 70.09 |
| 380200-Services - Plastic & Copper | 698500 | 69850 RELAY COPPER SVC- ST CHR | 201508 | 0.23 | 0.0031250 | - | 0.01 |
| 380200-Services - Plastic & Copper | 699300 | 69930 SVC REN 1/2 PL CTY | 201508 | 320,221.96 | 0.0031250 | - | 12,008.32 |
| 380200-Services - Plastic & Copper | 699310 | 69931 SVC REN 1IN PL CTY | 201508 | 147,829.40 | 0.0031250 | - | 5,536.10 |
| 380200-Services - Plastic & Copper | 699320 | 69932 SVC REN 1 1/4 PL C | 201508 | (2,633.97) | 0.0031250 | - | (98.77) |
| 380200-Services - Plastic & Copper | 699330 | 69933 SVC REN 2&OVR PL C | 201508 | (1,346.04) | 0.0031250 | - | (50.48) |
| 380200-Services - Plastic & Copper | 699400 | 69940 SVC REN COR TRANSFER CI | 201508 | (6,330.36) | 0.0031250 | - | (237.39) |
| 380200-Services - Plastic & Copper | 699410 | 69941 SVC REN COR TRANSFER CO | 201508 | (11,718.31) | 0.0031250 | - | (439.44) |
| 380200-Services - Plastic & Copper | 900068 | Repl w/ 1750F 2P Jefferson Ph 2 | 201508 | (41.79) | 0.0031250 | - | (1.57) |
| 380200-Services - Plastic & Copper | 900069 | Inst 3539F 2P Jefferson Ph 3 | 201508 | 493,122.08 | 0.0031250 | - | 18,492.08 |
| 380200-Services - Plastic & Copper | 900072 | Repl w 688F 2P & 2527F 4P Lafayette | 201508 | (0.05) | 0.0031250 | - | - |
| 380200-Services - Plastic & Copper | 900073 | Repl w/ 2520F 2P Jefferson Ph 6 | 201508 | (49,247.33) | 0.0031250 | - | (1,846.77) |
| 380200-Services - Plastic & Copper | 900093 | Repl w/ 184F 2P Cass | 201508 | 0.06 | 0.0031250 | - | - |
| 380200-Services - Plastic & Copper | 900099 | Rel 1830F 2P McKnight Rd | 201508 | (39.27) | 0.0031250 | - | (1.47) |
| 380200-Services - Plastic & Copper | 900233 | Rel w/ 1924F 6P Fee Fee Road | 201508 | (0.09) | 0.0031250 | - | - |
| 380200-Services - Plastic & Copper | 900264 | Int 3087F 4P 2P Baden Grid Ph 5A | 201508 | 14.03 | 0.0031250 | - | 0.53 |
| 380200-Services - Plastic & Copper | 900265 | Repl w/ 3337F 2P Baden Ph 5B | 201508 | 2.70 | 0.0031250 | - | 0.10 |
| 380200-Services - Plastic & Copper | 900266 | Inst 4640F 2P Baden Ph 5C | 201508 | (1.42) | 0.0031250 | - | (0.05) |
| 380200-Services - Plastic & Copper | 900267 | Repl w/ 4536F 2P Baden Ph5D | 201508 | 2.38 | 0.0031250 | - | 0.09 |
| 380200-Services - Plastic & Copper | 900268 | Inst 4411F 2P Baden Ph5E | 201508 | 1.11 | 0.0031250 | - | 0.04 |
| 380200-Services - Plastic & Copper | 900269 | Inst 1150F 4P Walnut Park Ph 5A | 201508 | (447.29) | 0.0031250 | - | (16.77) |
| 380200-Services - Plastic & Copper | 900270 | Inst 2942F 2P Walnut Park Ph5B | 201508 | 93,748.93 | 0.0031250 | - | 3,515.58 |
| 380200-Services - Plastic & Copper | 900271 | Inst 2646F 2P Walnut Park Ph5C | 201508 | 151,654.21 | 0.0031250 | - | 5,687.03 |
| 380200-Services - Plastic & Copper | 900274 | Repl w/ 3390F 2P Wellington Ph 4D | 201508 | 268,017.60 | 0.0031250 | - | 10,050.66 |
| 380200-Services - Plastic & Copper | 900275 | Repl w/ 4989F 2P Wellington Ph4E | 201508 | (1,888.32) | 0.0031250 | - | (70.81) |
| 380200-Services - Plastic & Copper | 900277 | Repl w/ 1725F 2P Walnut Park Ph4B | 201508 | (78.47) | 0.0031250 | - | (2.94) |
| 380200-Services - Plastic & Copper | 900278 | Repl w/ 3977F 2P Walnut Park Ph4C | 201508 | (80.16) | 0.0031250 | - | (3.01) |
| 380200-Services - Plastic & Copper | 900279 | Repl w/ 3345F 2P Walnut Park Ph4D | 201508 | (785.14) | 0.0031250 | - | (29.44) |
| 380200-Services - Plastic & Copper | 900281 | Inst 4984F 4PWellston Phase 2B | 201508 | (0.43) | 0.0031250 | - | (0.02) |
| 380200-Services - Plastic & Copper | 900282 | Inst 4400F 2P Wellston 2C | 201508 | (1,712.71) | 0.0031250 | - | (64.23) |
| 380200-Services - Plastic & Copper | 900283 | Inst 5300F 2P Wellston Ph2D | 201508 | 0.95 | 0.0031250 | - | 0.04 |
| 380200-Services - Plastic & Copper | 900284 | Inst 5466F 2P Wellston Ph2E | 201508 | (881.18) | 0.0031250 | - | (33.04) |
| 380200-Services - Plastic & Copper | 900310 | Inst 2250F 2P Yale Ave Maplewood 1C | 201508 | 52,816.60 | 0.0031250 | - | 1,980.62 |
| 380200-Services - Plastic & Copper | 900375 | Inst 1747F 6P Litzinger | 201508 | 0.09 | 0.0031250 | - | - |
| 380200-Services - Plastic & Copper | 900377 | Repl w/ 978F 2-4P Big Bend | 201508 | (174.59) | 0.0031250 | - | (6.55) |
| 380200-Services - Plastic & Copper | 900379 | Inst 783F 4P & 529F 2P Old Bonhomme | 201508 | (3.85) | 0.0031250 | - | (0.14) |
| 380200-Services - Plastic & Copper | 900388 | Repl w/ 332F 2P Tay Rd | 201508 | 1.46 | 0.0031250 | - | 0.05 |
| 380200-Services - Plastic & Copper | 900390 | Inst 205F 1 1/4P Gore | 201508 | 1.14 | 0.0031250 | - | 0.04 |
| 380200-Services - Plastic & Copper | 900392 | Inst 580F 4P & 255F 2P Ferguson | 201508 | (0.01) | 0.0031250 | - | - |
| 380200-Services - Plastic & Copper | 900393 | Inst 3745F 8P Clayton Ave | 201508 | (0.01) | 0.0031250 | - | - |
| 380200-Services - Plastic & Copper | 900395 | Repl w/ 525F 2P Clay St | 201508 | 0.40 | 0.0031250 | - | 0.02 |
| 380200-Services - Plastic & Copper | 900415 | Repl w/ 1093F 2P Princeton | 201508 | 0.73 | 0.0031250 | - | 0.03 |

| | | | | | | | |
|------------------------------------|--------|-------------------------------------|--------|------------|-----------|---|-----------|
| 380200-Services - Plastic & Copper | 900418 | Aband 867F 6C 30F 12S Dr. ML King | 201508 | (1.47) | 0.0031250 | - | (0.06) |
| 380200-Services - Plastic & Copper | 900420 | Repl w/ 520F 2P Oregon | 201508 | 0.37 | 0.0031250 | - | 0.01 |
| 380200-Services - Plastic & Copper | 900421 | Repl w/ 970F 2P Winnebago | 201508 | 5.60 | 0.0031250 | - | 0.21 |
| 380200-Services - Plastic & Copper | 900422 | Repl w/ 780F 2P Taft | 201508 | 6.32 | 0.0031250 | - | 0.24 |
| 380200-Services - Plastic & Copper | 900423 | Repl w/ 1373F 2P Dr MLK | 201508 | (0.04) | 0.0031250 | - | - |
| 380200-Services - Plastic & Copper | 900424 | Repl w/ 520F 3P Red Bud | 201508 | 0.29 | 0.0031250 | - | 0.01 |
| 380200-Services - Plastic & Copper | 900428 | Aband 214F 4C Hampton | 201508 | (3.71) | 0.0031250 | - | (0.14) |
| 380200-Services - Plastic & Copper | 900430 | Repl w/ 654F 2P Maurice | 201508 | 1.13 | 0.0031250 | - | 0.04 |
| 380200-Services - Plastic & Copper | 900432 | Repl w/ 503F 2P Gravois | 201508 | (2.06) | 0.0031250 | - | (0.08) |
| 380200-Services - Plastic & Copper | 900433 | Repl w/ 570F 4P Chippewa | 201508 | 4.11 | 0.0031250 | - | 0.15 |
| 380200-Services - Plastic & Copper | 900439 | Repl w/ 289F 2P Ferguson | 201508 | 0.29 | 0.0031250 | - | 0.01 |
| 380200-Services - Plastic & Copper | 900447 | Aband 13120F C Jefferson Ph 6 | 201508 | 1,333.57 | 0.0031250 | - | 50.01 |
| 380200-Services - Plastic & Copper | 900457 | Inst 4546F 2P Baden Ph5F | 201508 | 0.19 | 0.0031250 | - | 0.01 |
| 380200-Services - Plastic & Copper | 900460 | Inst 3488F 2P Walnut Park Ph4E | 201508 | (1.32) | 0.0031250 | - | (0.05) |
| 380200-Services - Plastic & Copper | 900461 | Inst 893F 2P Walnut Park Ph4F | 201508 | 0.65 | 0.0031250 | - | 0.02 |
| 380200-Services - Plastic & Copper | 900462 | Repl w/ 2240F 2P Walnut Park Ph4G | 201508 | (675.54) | 0.0031250 | - | (25.37) |
| 380200-Services - Plastic & Copper | 900463 | Inst 4082F 2P Walnut Park Ph4H | 201508 | (509.80) | 0.0031250 | - | (19.12) |
| 380200-Services - Plastic & Copper | 900464 | Inst 4741F 2P Walnut Park Ph 4I | 201508 | (256.64) | 0.0031250 | - | (9.62) |
| 380200-Services - Plastic & Copper | 900467 | Repl w/ 2400F 2-4P Potomac AOR | 201508 | (0.19) | 0.0031250 | - | (0.01) |
| 380200-Services - Plastic & Copper | 900476 | Inst 3350F 6P Ivory | 201508 | 7,634.58 | 0.0031250 | - | 286.30 |
| 380200-Services - Plastic & Copper | 900485 | Inst 4236F 12P Alaska | 201508 | (0.03) | 0.0031250 | - | - |
| 380200-Services - Plastic & Copper | 900488 | Repl w/ 2873F 6P Hodiament | 201508 | (0.07) | 0.0031250 | - | - |
| 380200-Services - Plastic & Copper | 900536 | Aband 1681F 6C Walnut Park Ph4B | 201508 | (13.27) | 0.0031250 | - | (0.50) |
| 380200-Services - Plastic & Copper | 900538 | Aband 3381F 6C Walnut Park Ph4D | 201508 | (4.95) | 0.0031250 | - | (0.19) |
| 380200-Services - Plastic & Copper | 900540 | Aband var Walnut Park Ph4F | 201508 | (11.57) | 0.0031250 | - | (0.43) |
| 380200-Services - Plastic & Copper | 900557 | Inst 2123F 2P Walnut Park Ph6A | 201508 | (2,130.10) | 0.0031250 | - | (79.88) |
| 380200-Services - Plastic & Copper | 900558 | Inst 1859F 2P Walnut Park Ph6B | 201508 | 162,826.70 | 0.0031250 | - | 6,106.00 |
| 380200-Services - Plastic & Copper | 900559 | Inst 3875F 2P Walnut Park Ph6C | 201508 | 241,810.49 | 0.0031250 | - | 9,067.89 |
| 380200-Services - Plastic & Copper | 900580 | Aband 110F 4S Chamberlain Ave | 201508 | (0.47) | 0.0031250 | - | (0.02) |
| 380200-Services - Plastic & Copper | 900623 | Repl w/ 2852' 2P Wydown Ph 6 | 201508 | (649.19) | 0.0031250 | - | (24.34) |
| 380200-Services - Plastic & Copper | 900650 | Inst 3290F 2P St Louis Hills Ph1A | 201508 | 421,507.81 | 0.0031250 | - | 15,806.54 |
| 380200-Services - Plastic & Copper | 900652 | Inst 4435F 2P St Louis Hills Ph1B | 201508 | 187,661.53 | 0.0031250 | - | 7,037.31 |
| 380200-Services - Plastic & Copper | 900653 | Inst 2636F 2P St Louis Hills Ph1C | 201508 | 196,818.77 | 0.0031250 | - | 7,380.70 |
| 380200-Services - Plastic & Copper | 900664 | Aband 724F 4C Tower Grove & Alley | 201508 | 0.34 | 0.0031250 | - | 0.01 |
| 380200-Services - Plastic & Copper | 900675 | Inst 250F 2P Humphrey Upgrade | 201508 | 753.52 | 0.0031250 | - | 28.26 |
| 380200-Services - Plastic & Copper | 900677 | Repl w/ 1795F 2P Cole & 18th PhA | 201508 | (8,119.73) | 0.0031250 | - | (304.49) |
| 380200-Services - Plastic & Copper | 900679 | Inst 2312F 4P Cole & 18th PhB | 201508 | (392.35) | 0.0031250 | - | (14.71) |
| 380200-Services - Plastic & Copper | 900681 | Inst 1637F 2P Cole & 18th Ph C | 201508 | (4,236.46) | 0.0031250 | - | (158.87) |
| 380200-Services - Plastic & Copper | 900683 | Inst 1864F 2P Cole & 18th Ph D | 201508 | (4,996.47) | 0.0031250 | - | (187.37) |
| 380200-Services - Plastic & Copper | 900685 | Inst 1550F 2P Cole & 18th PhE | 201508 | (310.04) | 0.0031250 | - | (11.63) |
| 380200-Services - Plastic & Copper | 900687 | Inst 1096F 2P Cole & 18th PhF | 201508 | 351.94 | 0.0031250 | - | 13.20 |
| 380200-Services - Plastic & Copper | 900689 | Inst 2434F 2P Cole & 18th PhG | 201508 | (1,879.48) | 0.0031250 | - | (70.48) |
| 380200-Services - Plastic & Copper | 900691 | Repl w/ 3458F 2P Cole & 18th Ph H | 201508 | 45,395.24 | 0.0031250 | - | 1,702.32 |
| 380200-Services - Plastic & Copper | 900723 | Rel w/ 3350F 2P Valley Park | 201508 | 5.63 | 0.0031250 | - | 0.21 |
| 380200-Services - Plastic & Copper | 900730 | Rel w/ 310F 2P Bramblett | 201508 | (36.83) | 0.0031250 | - | (1.38) |
| 380200-Services - Plastic & Copper | 900734 | Repl w/ 1717F 2P Hurck | 201508 | 142,175.02 | 0.0031250 | - | 5,331.56 |
| 380200-Services - Plastic & Copper | 900738 | Repl w/ 780F 2P Kingsland MSD | 201508 | 69,467.83 | 0.0031250 | - | 2,605.04 |
| 380200-Services - Plastic & Copper | 900762 | Inst 2069F 2P Earthquake Zone Ph1A | 201508 | (1,189.16) | 0.0031250 | - | (44.59) |
| 380200-Services - Plastic & Copper | 900763 | Inst 3508F 2P Earthquake Zone Ph1B | 201508 | (4,988.14) | 0.0031250 | - | (187.06) |
| 380200-Services - Plastic & Copper | 900764 | Repl w/758F 2P Earthquake Zone Ph1C | 201508 | 1,844.26 | 0.0031250 | - | 61.66 |
| 380200-Services - Plastic & Copper | 900765 | Inst 1899F 4P Earthquake Zone Ph1D | 201508 | (9,305.41) | 0.0031250 | - | (348.95) |
| 380200-Services - Plastic & Copper | 900775 | Rel w/ 1535F 2P Page&Hodiament AOR | 201508 | (138.62) | 0.0031250 | - | (5.20) |
| 380200-Services - Plastic & Copper | 900778 | Aband 80F 4S Greenmar | 201508 | (0.66) | 0.0031250 | - | (0.03) |
| 380200-Services - Plastic & Copper | 900813 | Rel w/ 700F 2P Froesel | 201508 | 1.82 | 0.0031250 | - | 0.07 |
| 380200-Services - Plastic & Copper | 900822 | Rel w/ 130F 6S Price Road | 201508 | (386.47) | 0.0031250 | - | (14.49) |

| | | | | | | | |
|------------------------------------|--------|-------------------------------------|--------|------------|-----------|---|----------|
| 380200-Services - Plastic & Copper | 900823 | Repl w/ 659F 2P Baden Ph6A | 201508 | 3,428.85 | 0.0031250 | - | 128.58 |
| 380200-Services - Plastic & Copper | 900848 | Rel w/ 810F 4P Bircher & Newstead | 201508 | (534.81) | 0.0031250 | - | (20.06) |
| 380200-Services - Plastic & Copper | 900859 | Repl w/ 290F 2P Cabanne | 201508 | (182.41) | 0.0031250 | - | (6.84) |
| 380200-Services - Plastic & Copper | 900861 | Repl w/ 105F 4P McLaren | 201508 | (12.94) | 0.0031250 | - | (0.49) |
| 380200-Services - Plastic & Copper | 900873 | Repl w/ 538F 2P Longacre | 201508 | 50,302.28 | 0.0031250 | - | 1,886.34 |
| 380200-Services - Plastic & Copper | 900876 | Repl w/ 1060F 2P Rauschenbach PVC | 201508 | 24,628.80 | 0.0031250 | - | 923.58 |
| 380200-Services - Plastic & Copper | 900890 | Repl w/ 2218F 2P Russell & Flora | 201508 | (25.93) | 0.0031250 | - | (0.97) |
| 380200-Services - Plastic & Copper | 900893 | Repl w/ 2486F 6P Arlington | 201508 | 43,815.44 | 0.0031250 | - | 1,643.08 |
| 380200-Services - Plastic & Copper | 900895 | Repl w/ 828F 2P Marquette | 201508 | 11,530.70 | 0.0031250 | - | 432.40 |
| 380200-Services - Plastic & Copper | 900896 | Repl w/ 2990F 2P 4P Maple | 201508 | 101,359.44 | 0.0031250 | - | 3,800.98 |
| 380200-Services - Plastic & Copper | 900897 | Repl w/ 587F 2P Syracuse | 201508 | 39,935.24 | 0.0031250 | - | 1,497.57 |
| 380200-Services - Plastic & Copper | 900898 | Repl w/ 1220F 2P Ohio | 201508 | (511.40) | 0.0031250 | - | (19.18) |
| 380200-Services - Plastic & Copper | 900900 | Repl w/ 1075F 2P Washington | 201508 | 1,963.71 | 0.0031250 | - | 73.64 |
| 380200-Services - Plastic & Copper | 900905 | Repl w/ 806F 2P Utah | 201508 | (2,770.64) | 0.0031250 | - | (103.90) |
| 380200-Services - Plastic & Copper | 900907 | Aband 500F 4C Natural Bridge | 201508 | (75.17) | 0.0031250 | - | (2.82) |
| 380200-Services - Plastic & Copper | 900908 | Repl w/ 460F 2P California | 201508 | 4.72 | 0.0031250 | - | 0.18 |
| 380200-Services - Plastic & Copper | 900912 | Repl w/ 745F 2P Shaw | 201508 | (1,260.39) | 0.0031250 | - | (47.26) |
| 380200-Services - Plastic & Copper | 900921 | Repl w/ 2457F 4P&2P Flad AOR | 201508 | (5,667.35) | 0.0031250 | - | (212.53) |
| 380200-Services - Plastic & Copper | 900961 | Rel w/ 190F 2P Clay | 201508 | (16.60) | 0.0031250 | - | (0.62) |
| 380200-Services - Plastic & Copper | 900977 | Repl w/ 1291F 4P Boyle | 201508 | 28.65 | 0.0031250 | - | 1.07 |
| 380200-Services - Plastic & Copper | 900986 | Repl w/ 2189F 2P Earthquake Zone 2A | 201508 | 150.58 | 0.0031250 | - | 5.65 |
| 380200-Services - Plastic & Copper | 901011 | Rel w/ 450F 4P Sanford AOR | 201508 | 3,938.29 | 0.0031250 | - | 147.69 |
| 380200-Services - Plastic & Copper | 901019 | Rel w/ 80F 6S Fee Fee | 201508 | (34.31) | 0.0031250 | - | (1.29) |
| 380200-Services - Plastic & Copper | 901040 | Repl w/ 315F 2P Amherst Ave | 201508 | 17,263.59 | 0.0031250 | - | 647.38 |
| 380200-Services - Plastic & Copper | 901071 | Rel w/ 285F 2P Froesel Ph2 | 201508 | 4,481.86 | 0.0031250 | - | 168.07 |
| 380200-Services - Plastic & Copper | 901107 | Rel w/ 62F 4P Southwest AOR | 201508 | 10,746.25 | 0.0031250 | - | 402.98 |
| 380200-Services - Plastic & Copper | 901173 | Vandeventer - City of St. Louis MRE | 201508 | 2,010.29 | 0.0031250 | - | 75.39 |
| 380200-Services - Plastic & Copper | | Renewed Services | 201507 | | | | |
| 380200-Services - Plastic & Copper | | Renewed Services | 201508 | | | | |

TOTAL 5,718,473.13 13,897.96 214,442.73

Total Service Line Replacements and Insertion Projects: 5,986,383.35 16,831.50 228,454.34

REGULATOR STATIONS - ADDITIONS

LACLEDE DIVISION

| PLANT ACCOUNT | WORK ORDER | BUDGET PROJECT | DESCRIPTION | IN SERVICE DATE | ADDITION AMOUNT | MONTHS | DEPR. MO. RATE | ACCUM. DEPR. | DEPR. EXPENSE |
|-------------------------------------|------------|----------------|------------------------------------|-----------------|-----------------|--------|----------------|--------------|---------------|
| 378000-Meas & Reg Station Equipment | 003306 | | RTU Upgrade Phase 4 | 201507 | | 3 | 0.0030917 | - | - |
| 378000-Meas & Reg Station Equipment | 003305 | | Repl Euclid & Hooke Reg Station | 201507 | (1,350.59) | 3 | 0.0030917 | (12.53) | (50.11) |
| 378000-Meas & Reg Station Equipment | 606330 | | 60633 Inst Reg Sta Jefferson-Rut | 201507 | (66.10) | 3 | 0.0030917 | (0.61) | (2.45) |
| 378000-Meas & Reg Station Equipment | 003402 | | Upgrade ER System Equipment | 201507 | | 3 | 0.0030917 | - | - |
| 378000-Meas & Reg Station Equipment | 005357 | | Refresh Existing TM Stations | 201507 | | 3 | 0.0030917 | - | - |
| 378000-Meas & Reg Station Equipment | 003304 | | Replace Osceola & Virginia Reg Sta | 201507 | (10.85) | 3 | 0.0030917 | (0.10) | (0.40) |
| 378000-Meas & Reg Station Equipment | 001172 | | Refresh TM Regulator Stations | 201507 | | 3 | 0.0030917 | - | - |
| 378000-Meas & Reg Station Equipment | 604190 | | 60419 REPL BRISTOL NETWRK RTU'S | 201309 | | 25 | 0.0030917 | - | - |
| 378000-Meas & Reg Station Equipment | 604180 | | 60418 UPGRADE INSTRUMENTATION | 201310 | | 24 | 0.0030917 | - | - |
| 378000-Meas & Reg Station Equipment | 001172 | | Refresh TM Regulator Stations | 201508 | | 2 | 0.0030917 | - | - |
| 378000-Meas & Reg Station Equipment | 003304 | | Replace Osceola & Virginia Reg Sta | 201508 | 8.17 | 2 | 0.0030917 | 0.05 | 0.30 |
| 378000-Meas & Reg Station Equipment | 003305 | | Repl Euclid & Hooke Reg Station | 201508 | (816.66) | 2 | 0.0030917 | (5.05) | (30.30) |

| | | | | | | | | | |
|-------------------------------------|--------|--|----------------------------------|--------|----------|---|-----------|--------|--------|
| 378000-Meas & Reg Station Equipment | 003306 | | RTU Upgrade Phase 4 | 201508 | | 2 | 0.0030917 | - | - |
| 378000-Meas & Reg Station Equipment | 003402 | | Upgrade ER System Equipment | 201508 | | 2 | 0.0030917 | - | - |
| 378000-Meas & Reg Station Equipment | 005357 | | Refresh Existing TM Stations | 201508 | | 2 | 0.0030917 | - | - |
| 378000-Meas & Reg Station Equipment | 606330 | | 60633 Inst Reg Sta Jefferson-Rut | 201508 | (163.23) | 2 | 0.0030917 | (1.01) | (6.06) |
| 375100-Struct & Impv - Meas & Reg S | 606330 | | 60633 Inst Reg Sta Jefferson-Rut | 201508 | (127.87) | 2 | 0.0025000 | (0.64) | (3.84) |

TOTAL (2,527.13) (19.89) (92.85)

ACCOUNT 379000 MEASURING & REGULATING STATION EQUIPMENT - CITY GATE

| PLANT ACCOUNT | WORK ORDER | BUDGET PROJECT | DESCRIPTION | IN SERVICE DATE | ADDITION AMOUNT | MONTHS | DEPR. MO. RATE | ACCUM. DEPR. | DEPR. EXPENSE |
|-------------------------------------|------------|----------------|------------------------------------|-----------------|-----------------|--------|----------------|--------------|---------------|
| 379000-Meas & Reg Station Eqpt-City | 005045 | | Replace odorant tanks on MoNat Sys | 201507 | (273.02) | 3 | 0.0030917 | (2.53) | (10.13) |
| 379000-Meas & Reg Station Eqpt-City | 005045 | | Replace odorant tanks on MoNat Sys | 201508 | (154.82) | 2 | 0.0030917 | (0.96) | (5.74) |
| 379000-Meas & Reg Station Eqpt-City | 007132 | | Ph 2 - Replace Monat Odorant Tanks | 201508 | 171,469.38 | 2 | 0.0030917 | 1,080.26 | 6,361.58 |

TOTAL 171,041.54 1,056.77 6,345.71

Total Regulator Station Replacements

168,514.41 1,036.88 6,252.86

MAIN RELOCATIONS NET OF REIMBURSEMENTS - NET ADDITIONS

#N/A 0.0013083 #N/A 0

| PLANT ACCOUNT | WORK ORDER | BUDGET PROJECT | DESCRIPTION | IN SERVICE DATE | ADDITION AMOUNT | MONTHS | DEPR. MO. RATE | ACCUM. DEPR. | DEPR. EXPENSE |
|------------------------|------------|----------------|-------------------------------------|-----------------|-----------------|--------|----------------|--------------|---------------|
| 376100-Mains - Steel | 900099 | 3403L | Rel 1830F 2P McKnight Rd | 201507 | (14.27) | 3 | 0.0012000 | (0.05) | (0.21) |
| 376100-Mains - Steel | 900147 | 3403L | Inst 2270F Route 364-Final Phase | 201507 | 4.56 | 3 | 0.0012000 | 0.02 | 0.07 |
| 376100-Mains - Steel | 900319 | 3403L | Repl w/ 50F 6S Old Halls Ferry/Vail | 201507 | (9,633.41) | 3 | 0.0012000 | (34.68) | (138.72) |
| 376100-Mains - Steel | 900602 | 3403L | Rel w/ 24F 8S Natural Bridge | 201507 | (299.05) | 3 | 0.0012000 | (1.08) | (4.31) |
| 376100-Mains - Steel | 900633 | 3403L | Rel w/ 321F 4S 2S Progress Parkway | 201507 | (623.74) | 3 | 0.0012000 | (2.25) | (8.98) |
| 376100-Mains - Steel | 900817 | 3403L | Rel w/ 330F 6P St Cyr Rd Culvert | 201507 | (172.48) | 3 | 0.0012000 | (0.62) | (2.48) |
| 376100-Mains - Steel | 900819 | 3403L | Rel w/ 18F 6S Howdershell Rd | 201507 | (1,641.68) | 3 | 0.0012000 | (5.91) | (23.64) |
| 376100-Mains - Steel | 900822 | 3403L | Rel w/ 130F 6S Price Road | 201507 | (563.32) | 3 | 0.0012000 | (2.03) | (8.11) |
| 376100-Mains - Steel | 900852 | 3403L | Rel w/ 570' 8S Rte100 Great Streets | 201507 | (713.43) | 3 | 0.0012000 | (2.57) | (10.27) |
| 376100-Mains - Steel | 900892 | 3403L | Rel w/ 180F 2S Elaine Drive | 201507 | (231.89) | 3 | 0.0012000 | (0.83) | (3.34) |
| 376100-Mains - Steel | 901019 | 3403L | Rel w/ 80F 6S Fee Fee | 201507 | (267.02) | 3 | 0.0012000 | (0.96) | (3.85) |
| 376100-Mains - Steel | 901109 | 3403L | Rel w/ 18F 2S Madison | 201507 | (573.11) | 3 | 0.0012000 | (2.06) | (8.25) |
| 376100-Mains - Steel | 900319 | 3403L | Repl w/ 50F 6S Old Halls Ferry/Vail | 201507 | (161.54) | 3 | 0.0012000 | (0.58) | (2.33) |
| 376100-Mains - Steel | 900633 | 3403L | Rel w/ 321F 4S 2S Progress Parkway | 201507 | (20.85) | 3 | 0.0012000 | (0.08) | (0.30) |
| 376100-Mains - Steel | 900819 | 3403L | Rel w/ 18F 6S Howdershell Rd | 201507 | (46.98) | 3 | 0.0012000 | (0.17) | (0.68) |
| 376100-Mains - Steel | 900822 | 3403L | Rel w/ 130F 6S Price Road | 201507 | (32.39) | 3 | 0.0012000 | (0.12) | (0.47) |
| 376100-Mains - Steel | 901019 | 3403L | Rel w/ 80F 6S Fee Fee | 201507 | (5.16) | 3 | 0.0012000 | (0.02) | (0.07) |
| 376300-Mains - Plastic | 900099 | 3403L | Rel 1830F 2P McKnight Rd | 201507 | (151.18) | 3 | 0.0013083 | (0.59) | (2.37) |
| 376300-Mains - Plastic | 900147 | 3403L | Inst 2270F Route 364-Final Phase | 201507 | 2.80 | 3 | 0.0013083 | 0.01 | 0.04 |
| 376300-Mains - Plastic | 900233 | 3403L | Rel w/ 1924F 6P Fee Fee Road | 201507 | 1.46 | 3 | 0.0013083 | 0.01 | 0.02 |
| 376300-Mains - Plastic | 900508 | 3403L | Rel w/ 127F 2P Dearborn | 201507 | (49.79) | 3 | 0.0013083 | (0.20) | (0.78) |
| 376300-Mains - Plastic | 900602 | 3403L | Rel w/ 24F 8S Natural Bridge | 201507 | (31.30) | 3 | 0.0013083 | (0.12) | (0.49) |
| 376300-Mains - Plastic | 900670 | 3403L | Rel w/ 400F 6P Vogel Rd | 201507 | (1,083.70) | 3 | 0.0013083 | (4.25) | (17.01) |
| 376300-Mains - Plastic | 900723 | 3403L | Rel w/ 3350F 2P Valley Park | 201507 | (3.65) | 3 | 0.0013083 | (0.01) | (0.06) |
| 376300-Mains - Plastic | 900730 | 3403L | Rel w/ 310F 2P Bramblett | 201507 | (315.56) | 3 | 0.0013083 | (1.24) | (4.95) |
| 376300-Mains - Plastic | 900775 | 3403L | Rel w/ 1535F 2P Page&Hodiamont AOR | 201507 | (740.77) | 3 | 0.0013083 | (2.91) | (11.63) |
| 376300-Mains - Plastic | 900813 | 3403L | Rel w/ 700F 2P Froesel | 201507 | (0.56) | 3 | 0.0013083 | - | (0.01) |
| 376300-Mains - Plastic | 900817 | 3403L | Rel w/ 330F 6P St Cyr Rd Culvert | 201507 | (457.69) | 3 | 0.0013083 | (1.80) | (7.19) |

| | | | | | | | | | |
|------------------------|--------|-------|-------------------------------------|--------|------------|---|-----------|--------|----------|
| 376300-Mains - Plastic | 900820 | 3403L | Rel w/ 410' 6P Willott Rd BridgeCJ | 201507 | (1,297.29) | 3 | 0.0013083 | (5.09) | (20.37) |
| 376300-Mains - Plastic | 900822 | 3403L | Rel w/ 130F 6S Price Road | 201507 | (1,757.87) | 3 | 0.0013083 | (6.90) | (27.60) |
| 376300-Mains - Plastic | 900852 | 3403L | Rel w/ 570' 8S Rte100 Great Streets | 201507 | (31.83) | 3 | 0.0013083 | (0.12) | (0.50) |
| 376300-Mains - Plastic | 900858 | 3403L | Rel w/ 80F 3P Burning Leaf Bridge | 201507 | (22.86) | 3 | 0.0013083 | (0.09) | (0.36) |
| 376300-Mains - Plastic | 900864 | 3403L | Rel w/ 80F 4P St. Louis & Norwood | 201507 | (75.06) | 3 | 0.0013083 | (0.29) | (1.18) |
| 376300-Mains - Plastic | 900911 | 3403L | Rel w/ 300F 2P Edgewood | 201507 | (0.40) | 3 | 0.0013083 | - | (0.01) |
| 376300-Mains - Plastic | 900961 | 3403L | Rel w/ 190F 2P Clay | 201507 | (349.20) | 3 | 0.0013083 | (1.37) | (5.48) |
| 376300-Mains - Plastic | 001494 | 3403M | Relocate along Oak Grove (Phase 2) | 201507 | (292.91) | 3 | 0.0013083 | (1.15) | (4.60) |
| 376300-Mains - Plastic | 002882 | 3403M | FE - American Legion & S Mill St | 201507 | (0.94) | 3 | 0.0013083 | - | (0.01) |
| 376300-Mains - Plastic | 006238 | 3403M | Rel w/ 23F 2P Prairie Dell Rd | 201507 | 932.53 | 3 | 0.0013083 | 3.66 | 14.64 |
| 376300-Mains - Plastic | 900841 | 340RL | Rel w/ 57F 4P Ashland AOR | 201507 | (72.51) | 3 | 0.0013083 | (0.28) | (1.14) |
| 376300-Mains - Plastic | 900845 | 340RL | Rel w/ 85F 4P Russell & Thurman AOR | 201507 | (950.29) | 3 | 0.0013083 | (3.73) | (14.92) |
| 376300-Mains - Plastic | 900848 | 340RL | Rel w/ 810F 4P Bircher & Newstead | 201507 | (483.00) | 3 | 0.0013083 | (1.90) | (7.58) |
| 376300-Mains - Plastic | 900941 | 340RL | Rel w/ 26F 4P Chippewa & Macklind | 201507 | (833.89) | 3 | 0.0013083 | (3.27) | (13.09) |
| 376300-Mains - Plastic | 901011 | 340RL | Rel w/ 450F 4P Sanford AOR | 201507 | (574.43) | 3 | 0.0013083 | (2.25) | (9.02) |
| 376300-Mains - Plastic | 901015 | 340RL | Rel w/ 35F 4P Elmbank & Taylor AOR | 201507 | 13,804.67 | 3 | 0.0013083 | 54.18 | 216.73 |
| 376300-Mains - Plastic | 900099 | 3403L | Rel 1830F 2P McKnight Rd | 201507 | (2.33) | 3 | 0.0013083 | (0.01) | (0.04) |
| 376300-Mains - Plastic | 900233 | 3403L | Rel w/ 1924F 6P Fee Fee Road | 201507 | 0.01 | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900723 | 3403L | Rel w/ 3350F 2P Valley Park | 201507 | (0.05) | 3 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900775 | 3403L | Rel w/ 1535F 2P Page&Hodiamont AOR | 201507 | (39.24) | 3 | 0.0013083 | (0.15) | (0.62) |
| 376300-Mains - Plastic | 900817 | 3403L | Rel w/ 330F 6P St Cyr Rd Culvert | 201507 | (12.25) | 3 | 0.0013083 | (0.05) | (0.19) |
| 376300-Mains - Plastic | 900822 | 3403L | Rel w/ 130F 6S Price Road | 201507 | (70.14) | 3 | 0.0013083 | (0.28) | (1.10) |
| 376300-Mains - Plastic | 900864 | 3403L | Rel w/ 80F 4P St. Louis & Norwood | 201507 | (9.82) | 3 | 0.0013083 | (0.04) | (0.15) |
| 376300-Mains - Plastic | 900841 | 340RL | Rel w/ 57F 4P Ashland AOR | 201507 | (4.32) | 3 | 0.0013083 | (0.02) | (0.07) |
| 376300-Mains - Plastic | 900845 | 340RL | Rel w/ 85F 4P Russell & Thurman AOR | 201507 | (73.31) | 3 | 0.0013083 | (0.29) | (1.15) |
| 376300-Mains - Plastic | 900848 | 340RL | Rel w/ 810F 4P Bircher & Newstead | 201507 | (8.29) | 3 | 0.0013083 | (0.03) | (0.13) |
| 376300-Mains - Plastic | 900941 | 340RL | Rel w/ 26F 4P Chippewa & Macklind | 201507 | (296.09) | 3 | 0.0013083 | (1.16) | (4.65) |
| 376300-Mains - Plastic | 901011 | 340RL | Rel w/ 450F 4P Sanford AOR | 201507 | (38.13) | 3 | 0.0013083 | (0.15) | (0.60) |
| 376300-Mains - Plastic | 901015 | 340RL | Rel w/ 35F 4P Elmbank & Taylor AOR | 201507 | 962.54 | 3 | 0.0013083 | 3.78 | 15.11 |
| 376300-Mains - Plastic | 001494 | 3403M | Relocate along Oak Grove (Phase 2) | 201508 | (160.17) | 2 | 0.0013083 | (0.42) | (2.51) |
| 376300-Mains - Plastic | 002882 | 3403M | FE - American Legion & S Mill St | 201508 | 0.81 | 2 | 0.0013083 | - | 0.01 |
| 376300-Mains - Plastic | 006238 | 3403M | Rel w/ 23F 2P Prairie Dell Rd | 201508 | (12.34) | 2 | 0.0013083 | (0.03) | (0.19) |
| 376300-Mains - Plastic | 900095 | 3403L | Rel w/ 350F 8P Mason Rd Bridge #211 | 201508 | 149,485.09 | 2 | 0.0013083 | 391.14 | 2,346.86 |
| 376300-Mains - Plastic | 900095 | 3403L | Rel w/ 350F 8P Mason Rd Bridge #211 | 201508 | 2,128.64 | 2 | 0.0013083 | 5.57 | 33.42 |
| 376300-Mains - Plastic | 900099 | 3403L | Rel 1830F 2P McKnight Rd | 201508 | (32.10) | 2 | 0.0013083 | (0.08) | (0.50) |
| 376300-Mains - Plastic | 900099 | 3403L | Rel 1830F 2P McKnight Rd | 201508 | (341.17) | 2 | 0.0013083 | (0.89) | (5.36) |
| 376300-Mains - Plastic | 900099 | 3403L | Rel 1830F 2P McKnight Rd | 201508 | (4.80) | 2 | 0.0013083 | (0.01) | (0.08) |
| 376300-Mains - Plastic | 900147 | 3403L | Inst 2270F Route 364-Final Phase | 201508 | (2.24) | 2 | 0.0013083 | (0.01) | (0.04) |
| 376300-Mains - Plastic | 900147 | 3403L | Inst 2270F Route 364-Final Phase | 201508 | (3.76) | 2 | 0.0013083 | (0.01) | (0.06) |
| 376300-Mains - Plastic | 900233 | 3403L | Rel w/ 1924F 6P Fee Fee Road | 201508 | (1.21) | 2 | 0.0013083 | - | (0.02) |
| 376100-Mains - Steel | 900233 | 3403L | Rel w/ 1924F 6P Fee Fee Road | 201508 | (0.02) | 2 | 0.0012000 | - | - |
| 376300-Mains - Plastic | 900319 | 3403L | Repl w/ 50F 6S Old Halls Ferry/Vail | 201508 | (498.57) | 2 | 0.0013083 | (1.30) | (7.83) |
| 376300-Mains - Plastic | 900319 | 3403L | Repl w/ 50F 6S Old Halls Ferry/Vail | 201508 | (8.37) | 2 | 0.0013083 | (0.02) | (0.13) |
| 376300-Mains - Plastic | 900508 | 3403L | Rel w/ 127F 2P Dearborn | 201508 | (76.95) | 2 | 0.0013083 | (0.20) | (1.21) |
| 376300-Mains - Plastic | 900602 | 3403L | Rel w/ 24F 8S Natural Bridge | 201508 | (50.45) | 2 | 0.0013083 | (0.13) | (0.79) |
| 376300-Mains - Plastic | 900602 | 3403L | Rel w/ 24F 8S Natural Bridge | 201508 | (486.91) | 2 | 0.0013083 | (1.27) | (7.64) |
| 376300-Mains - Plastic | 900633 | 3403L | Rel w/ 321F 4S 2S Progress Parkway | 201508 | 2,342.66 | 2 | 0.0013083 | 6.13 | 36.78 |
| 376300-Mains - Plastic | 900633 | 3403L | Rel w/ 321F 4S 2S Progress Parkway | 201508 | 78.30 | 2 | 0.0013083 | 0.20 | 1.23 |
| 376300-Mains - Plastic | 900670 | 3403L | Rel w/ 400F 6P Vogel Rd | 201508 | 6,828.05 | 2 | 0.0013083 | 17.87 | 107.20 |
| 376300-Mains - Plastic | 900723 | 3403L | Rel w/ 3350F 2P Valley Park | 201508 | 15.96 | 2 | 0.0013083 | 0.04 | 0.25 |
| 376300-Mains - Plastic | 900723 | 3403L | Rel w/ 3350F 2P Valley Park | 201508 | 0.18 | 2 | 0.0013083 | - | - |
| 376300-Mains - Plastic | 900730 | 3403L | Rel w/ 310F 2P Bramblett | 201508 | (944.03) | 2 | 0.0013083 | (2.47) | (14.82) |
| 376300-Mains - Plastic | 900732 | 3403L | Rel w/ 120F 6S DeBailiviere Bridge | 201508 | 2,632.55 | 2 | 0.0013083 | 6.89 | 41.33 |
| 376300-Mains - Plastic | 900732 | 3403L | Rel w/ 120F 6S DeBailiviere Bridge | 201508 | 59,110.59 | 2 | 0.0013083 | 154.67 | 928.01 |
| 376300-Mains - Plastic | 900732 | 3403L | Rel w/ 120F 6S DeBailiviere Bridge | 201508 | 2,398.48 | 2 | 0.0013083 | 6.28 | 37.66 |

| | | | | | | | | | |
|------------------------|--------|-------|-------------------------------------|--------|------------|---|-----------|--------|----------|
| 376300-Mains - Plastic | 900775 | 3403L | Rel w/ 1535F 2P Page&Hodiamont AOR | 201508 | (493.81) | 2 | 0.0013083 | (1.29) | (7.75) |
| 376300-Mains - Plastic | 900775 | 3403L | Rel w/ 1535F 2P Page&Hodiamont AOR | 201508 | (23.53) | 2 | 0.0013083 | (0.06) | (0.37) |
| 376300-Mains - Plastic | 900813 | 3403L | Rel w/ 700F 2P Froesel | 201508 | 3.42 | 2 | 0.0013083 | 0.01 | 0.05 |
| 376300-Mains - Plastic | 900817 | 3403L | Rel w/ 330F 6P St Cyr Rd Culvert | 201508 | (791.27) | 2 | 0.0013083 | (2.07) | (12.42) |
| 376300-Mains - Plastic | 900817 | 3403L | Rel w/ 330F 6P St Cyr Rd Culvert | 201508 | (298.17) | 2 | 0.0013083 | (0.78) | (4.68) |
| 376100-Mains - Steel | 900817 | 3403L | Rel w/ 330F 6P St Cyr Rd Culvert | 201508 | (21.19) | 2 | 0.0012000 | (0.05) | (0.31) |
| 376300-Mains - Plastic | 900819 | 3403L | Rel w/ 18F 6S Howdershell Rd | 201508 | (384.63) | 2 | 0.0013083 | (1.01) | (6.04) |
| 376300-Mains - Plastic | 900819 | 3403L | Rel w/ 18F 6S Howdershell Rd | 201508 | (10.37) | 2 | 0.0013083 | (0.03) | (0.16) |
| 376300-Mains - Plastic | 900822 | 3403L | Rel w/ 130F 6S Price Road | 201508 | (846.29) | 2 | 0.0013083 | (2.21) | (13.29) |
| 376300-Mains - Plastic | 900822 | 3403L | Rel w/ 130F 6S Price Road | 201508 | (2,654.69) | 2 | 0.0013083 | (6.95) | (41.68) |
| 376300-Mains - Plastic | 900822 | 3403L | Rel w/ 130F 6S Price Road | 201508 | (98.35) | 2 | 0.0013083 | (0.26) | (1.54) |
| 376300-Mains - Plastic | 900822 | 3403L | Rel w/ 130F 6S Price Road | 201508 | (47.57) | 2 | 0.0013083 | (0.12) | (0.75) |
| 376300-Mains - Plastic | 900837 | 3403L | Rel w/ 1736F 4P Champ Line | 201508 | 15,790.33 | 2 | 0.0013083 | 41.32 | 247.90 |
| 376300-Mains - Plastic | 900837 | 3403L | Rel w/ 1736F 4P Champ Line | 201508 | 109,027.41 | 2 | 0.0013083 | 285.28 | 1,711.69 |
| 376300-Mains - Plastic | 900841 | 340RL | Rel w/ 57F 4P Ashland AOR | 201508 | (118.92) | 2 | 0.0013083 | (0.31) | (1.87) |
| 376300-Mains - Plastic | 900841 | 340RL | Rel w/ 57F 4P Ashland AOR | 201508 | (6.41) | 2 | 0.0013083 | (0.02) | (0.10) |
| 376300-Mains - Plastic | 900845 | 340RL | Rel w/ 85F 4P Russell & Thurman AOR | 201508 | (304.37) | 2 | 0.0013083 | (0.80) | (4.78) |
| 376300-Mains - Plastic | 900845 | 340RL | Rel w/ 85F 4P Russell & Thurman AOR | 201508 | (22.27) | 2 | 0.0013083 | (0.06) | (0.35) |
| 376300-Mains - Plastic | 900848 | 340RL | Rel w/ 810F 4P Bircher & Newstead | 201508 | (931.83) | 2 | 0.0013083 | (2.44) | (14.63) |
| 376300-Mains - Plastic | 900848 | 340RL | Rel w/ 810F 4P Bircher & Newstead | 201508 | (15.43) | 2 | 0.0013083 | (0.04) | (0.24) |
| 376100-Mains - Steel | 900852 | 3403L | Rel w/ 570' 8S Rte100 Great Streets | 201508 | (77.14) | 2 | 0.0012000 | (0.19) | (1.11) |
| 376300-Mains - Plastic | 900852 | 3403L | Rel w/ 570' 8S Rte100 Great Streets | 201508 | (1,687.61) | 2 | 0.0013083 | (4.42) | (26.49) |
| 376300-Mains - Plastic | 900858 | 3403L | Rel w/ 60F 3P Burning Leaf Bridge | 201508 | (29.79) | 2 | 0.0013083 | (0.08) | (0.47) |
| 376300-Mains - Plastic | 900864 | 3403L | Rel w/ 80F 4P St. Louis & Norwood | 201508 | (167.08) | 2 | 0.0013083 | (0.44) | (2.62) |
| 376300-Mains - Plastic | 900864 | 3403L | Rel w/ 80F 4P St. Louis & Norwood | 201508 | (23.21) | 2 | 0.0013083 | (0.06) | (0.36) |
| 376300-Mains - Plastic | 900866 | 3403L | Repl w/ 1480F 6P 4P-IKEA | 201508 | 234,834.06 | 2 | 0.0013083 | 614.47 | 3,686.80 |
| 376300-Mains - Plastic | 900866 | 3403L | Repl w/ 1480F 6P 4P-IKEA | 201508 | 34,925.33 | 2 | 0.0013083 | 91.39 | 548.31 |
| 376300-Mains - Plastic | 900885 | 3403L | Rel w/ 293F 2S Spellman Ph2 | 201508 | 103,626.35 | 2 | 0.0013083 | 271.15 | 1,626.89 |
| 376300-Mains - Plastic | 900885 | 3403L | Rel w/ 293F 2S Spellman Ph2 | 201508 | 2,077.88 | 2 | 0.0013083 | 5.44 | 32.62 |
| 376300-Mains - Plastic | 900892 | 3403L | Rel w/ 180F 2S Elaine Drive | 201508 | (565.76) | 2 | 0.0013083 | (1.48) | (8.88) |
| 376300-Mains - Plastic | 900911 | 3403L | Rel w/ 300F 2P Edgewood | 201508 | 0.34 | 2 | 0.0013083 | - | 0.01 |
| 376300-Mains - Plastic | 900941 | 340RL | Rel w/ 26F 4P Chippewa & Macklind | 201508 | (264.06) | 2 | 0.0013083 | (0.69) | (4.15) |
| 376300-Mains - Plastic | 900941 | 340RL | Rel w/ 26F 4P Chippewa & Macklind | 201508 | (29.03) | 2 | 0.0013083 | (0.08) | (0.46) |
| 376100-Mains - Steel | 900961 | 3403L | Rel w/ 190F 2P Clay | 201508 | (156.06) | 2 | 0.0012000 | (0.37) | (2.25) |
| 376300-Mains - Plastic | 901011 | 340RL | Rel w/ 450F 4P Sanford AOR | 201508 | 7,062.33 | 2 | 0.0013083 | 18.48 | 110.88 |
| 376300-Mains - Plastic | 901011 | 340RL | Rel w/ 450F 4P Sanford AOR | 201508 | 468.92 | 2 | 0.0013083 | 1.23 | 7.36 |
| 376300-Mains - Plastic | 901015 | 340RL | Rel w/ 35F 4P Elmbank & Taylor AOR | 201508 | 2,346.59 | 2 | 0.0013083 | 6.14 | 36.84 |
| 376300-Mains - Plastic | 901015 | 340RL | Rel w/ 35F 4P Elmbank & Taylor AOR | 201508 | 163.62 | 2 | 0.0013083 | 0.43 | 2.57 |
| 376300-Mains - Plastic | 901019 | 3403L | Rel w/ 80F 6S Fee Fee | 201508 | (881.50) | 2 | 0.0013083 | (2.31) | (13.84) |
| 376300-Mains - Plastic | 901019 | 3403L | Rel w/ 80F 6S Fee Fee | 201508 | (17.06) | 2 | 0.0013083 | (0.04) | (0.27) |
| 376300-Mains - Plastic | 901022 | 3403L | Rel w/ 427F 2P Valley Park SE | 201508 | 45,015.12 | 2 | 0.0013083 | 117.79 | 706.72 |
| 376300-Mains - Plastic | 901071 | 3403L | Rel w/ 285F 2P Froesel Ph2 | 201508 | 28,113.44 | 2 | 0.0013083 | 73.56 | 441.37 |
| 376300-Mains - Plastic | 901106 | 3403L | Rel w/ 38F 4P Compton AOR | 201508 | 20,376.70 | 2 | 0.0013083 | 53.32 | 319.91 |
| 376300-Mains - Plastic | 901106 | 3403L | Rel w/ 38F 4P Compton AOR | 201508 | 1,236.67 | 2 | 0.0013083 | 3.24 | 19.42 |
| 376300-Mains - Plastic | 901107 | 3403L | Rel w/ 62F 4P Southwest AOR | 201508 | 35,592.21 | 2 | 0.0013083 | 93.13 | 558.78 |
| 376300-Mains - Plastic | 901107 | 3403L | Rel w/ 62F 4P Southwest AOR | 201508 | 781.94 | 2 | 0.0013083 | 2.05 | 12.28 |
| 376300-Mains - Plastic | 901109 | 3403L | Rel w/ 18F 2S Madison | 201508 | (85.02) | 2 | 0.0013083 | (0.22) | (1.33) |
| 376300-Mains - Plastic | 901173 | 3403L | Vandeventer - City of St. Louis MRE | 201508 | 6,515.63 | 2 | 0.0013083 | 17.05 | 102.29 |
| 376300-Mains - Plastic | 901173 | 3403L | Vandeventer - City of St. Louis MRE | 201508 | 75,336.41 | 2 | 0.0013083 | 197.13 | 1,182.75 |
| 376300-Mains - Plastic | 901173 | 3403L | Vandeventer - City of St. Louis MRE | 201508 | 10,049.85 | 2 | 0.0013083 | 26.30 | 157.78 |
| 376300-Mains - Plastic | | 3403L | Relocation of Distribution System | 201507 | | | | | |
| 376300-Mains - Plastic | | 3403L | Relocation of Distribution System | 201508 | | | | | |

Total Main Relocations Net of Reimbursements

TOTAL 935,268.17 2,439.89 14,703.15

MAIN REINFORCEMENTS RELATED TO OTHER ISRS ELIGIBLE PROJECTS

ACCOUNT 376 PLASTIC MAINS REINFORCEMENT RELATED TO RELOCATION OF GAS MAIN

| PLANT ACCOUNT | WORK ORDER | BUDGET PROJECT | DESCRIPTION | IN SERVICE DATE | ADDITION AMOUNT | MONTHS | DEPR. MO. RATE | ACCUM. DEPR. | DEPR. EXPENSE |
|---------------|------------|----------------|-------------|-----------------|-----------------|--------|----------------|--------------|---------------|
| | | | | | | | | | |

TOTAL - - -

Total Main Reinforcements related to other ISRS-eligible projects

TOTAL - - -

Total ISRS-Eligible Additions

17,991,406.86 49,992.19 422,132.12

MAIN REPLACEMENTS - RETIREMENTS

MAINS - PLASTIC - RETIREMENTS - MAIN REPLACEMENTS

| PLANT ACCOUNT | WORK ORDER | BUDGET PROJECT | RELATED CWO | DESCRIPTION | RETIREMENT DATE | RETIREMENT AMOUNT | MONTHS | DEPR. MO. RATE | ACCUM. DEPR. | DEPR. EXPENSE |
|------------------------|------------|----------------|-------------|------------------------------------|-----------------|-------------------|--------|----------------|--------------|---------------|
| 376300-Mains - Plastic | 900759 | 3303 | 900759 | Repl w/ 2836F 2P Hickory Dale | 201507 | (5,988.53) | 3 | 0.0013083 | (23.50) | (94.02) |
| 376300-Mains - Plastic | 900900 | 3303 | 900900 | Repl w/ 1075F 2P Washington | 201507 | (3,837.68) | 3 | 0.0013083 | (15.06) | (60.25) |
| 376300-Mains - Plastic | 900902 | 3303 | 900902 | Repl w/ 530' 2P Oakland | 201507 | (6,626.33) | 3 | 0.0013083 | (26.01) | (104.03) |
| 376300-Mains - Plastic | 900948 | 3303 | 900948 | Repl w/ 132F 2P Southcote | 201507 | (235.08) | 3 | 0.0013083 | (0.92) | (3.69) |
| 376300-Mains - Plastic | 599020 | 3301 | 599020 | 59902 MAIN PLASTIC CITY | 201508 | (1,946.13) | 2 | 0.0013083 | (5.09) | (30.55) |
| 376300-Mains - Plastic | 001712 | 3303 | 001712 | Inst 16489F 2P Cote Brilliante | 201508 | (4,500.66) | 2 | 0.0013083 | (11.78) | (70.66) |
| 376300-Mains - Plastic | 002139 | 3303 | 002139 | Inst 3278F 2P MLK -Wellston 1B | 201508 | (20,884.06) | 2 | 0.0013083 | (54.65) | (327.87) |
| 376300-Mains - Plastic | 900270 | 3303 | 900270 | Inst 2942F 2P Walnut Park Ph5B | 201508 | (10,734.91) | 2 | 0.0013083 | (28.09) | (188.53) |
| 376300-Mains - Plastic | 900271 | 3303 | 900271 | Inst 2646F 2P Walnut Park Ph5C | 201508 | (38,467.88) | 2 | 0.0013083 | (100.66) | (603.93) |
| 376300-Mains - Plastic | 900447 | 3303 | 900447 | Aband 13120F C Jefferson Ph 6 | 201508 | (15,654.00) | 2 | 0.0013083 | (40.96) | (245.76) |
| 376300-Mains - Plastic | 900559 | 3303 | 900559 | Inst 3875F 2P Walnut Park Ph6C | 201508 | (1,290.24) | 2 | 0.0013083 | (3.38) | (20.26) |
| 376300-Mains - Plastic | 900652 | 3303 | 900652 | Inst 4435F 2P St Louis Hills Ph1B | 201508 | (9,781.44) | 2 | 0.0013083 | (25.59) | (153.56) |
| 376300-Mains - Plastic | 900653 | 3303 | 900653 | Inst 2636F 2P St Louis Hills Ph1C | 201508 | (59,265.93) | 2 | 0.0013083 | (155.08) | (930.45) |
| 376300-Mains - Plastic | 900681 | 3303 | 900681 | Inst 1637F 2P Cole & 18th Ph C | 201508 | (9,252.08) | 2 | 0.0013083 | (24.21) | (145.25) |
| 376300-Mains - Plastic | 900683 | 3303 | 900683 | Inst 1864F 2P Cole & 18th Ph D | 201508 | (10,881.84) | 2 | 0.0013083 | (28.47) | (170.84) |
| 376300-Mains - Plastic | 900687 | 3303 | 900687 | Inst 1096F 2P Cole & 18th Ph F | 201508 | (1,687.30) | 2 | 0.0013083 | (4.41) | (26.49) |
| 376300-Mains - Plastic | 900689 | 3303 | 900689 | Inst 2434F 2P Cole & 18th Ph G | 201508 | (9,812.44) | 2 | 0.0013083 | (25.68) | (154.05) |
| 376300-Mains - Plastic | 900734 | 3303 | 900734 | Repl w/ 1717F 2P Hurck | 201508 | (23,243.40) | 2 | 0.0013083 | (60.82) | (364.91) |
| 376300-Mains - Plastic | 900738 | 3303 | 900738 | Repl w/ 780F 2P Kingsland MSD | 201508 | (271.47) | 2 | 0.0013083 | (0.71) | (4.26) |
| 376300-Mains - Plastic | 900765 | 3303 | 900765 | Inst 1899F 4P Earthquake Zone Ph1D | 201508 | (1,841.96) | 2 | 0.0013083 | (4.82) | (28.92) |
| 376300-Mains - Plastic | 900862 | 3303 | 900862 | Rep w/ 4552F 2P Broadway AOR | 201508 | (47,427.27) | 2 | 0.0013083 | (124.10) | (744.59) |
| 376300-Mains - Plastic | 900893 | 3303 | 900893 | Repl w/ 2486F 6P Arlington | 201508 | (2,635.45) | 2 | 0.0013083 | (6.90) | (41.38) |
| 376300-Mains - Plastic | 901025 | 3303 | 901025 | Repl w/ 85F 2P Walnut Park | 201508 | (45.28) | 2 | 0.0013083 | (0.12) | (0.71) |
| 376300-Mains - Plastic | 900643 | 3304 | 900643 | Inst 1801F 6P-12P Marmaduke/Hudler | 201508 | (13,365.76) | 2 | 0.0013083 | (34.97) | (209.84) |

TOTAL - MAINS - PLASTIC - RETIREMENTS - MAIN REPLACEMENTS

(299,677.12)

(805.98)

(4,704.80)

MAINS - CAST IRON - RETIREMENTS - MAIN REPLACEMENTS

| PLANT ACCOUNT | WORK ORDER | BUDGET PROJECT | RELATED CWO | DESCRIPTION | RETIREMENT DATE | RETIREMENT AMOUNT | MONTHS | DEPR. MO. RATE | ACCUM. DEPR. | DEPR. EXPENSE |
|--------------------------|------------|----------------|-------------|-----------------------------------|-----------------|-------------------|--------|----------------|--------------|---------------|
| 376200-Mains - Cast Iron | 900623 | 3303 | 900623 | Repl w/ 2852' 2P Wydown Ph 6 | 201507 | (5,179.34) | 3 | 0.0027583 | (42.86) | (171.43) |
| 376200-Mains - Cast Iron | 900677 | 3303 | 900677 | Inst 1795F 2P Cole & 18th Ph A | 201507 | (6,416.72) | 3 | 0.0027583 | (53.10) | (212.39) |
| 376200-Mains - Cast Iron | 900898 | 3303 | 900898 | Repl w/ 1220F 2P Ohio | 201507 | (3,082.42) | 3 | 0.0027583 | (25.51) | (102.03) |
| 376200-Mains - Cast Iron | 900900 | 3303 | 900900 | Repl w/ 1075F 2P Washington | 201507 | (1,707.54) | 3 | 0.0027583 | (14.13) | (56.52) |
| 376200-Mains - Cast Iron | 900902 | 3303 | 900902 | Repl w/ 530' 2P Oakland | 201507 | (4,226.74) | 3 | 0.0027583 | (34.98) | (139.90) |
| 376200-Mains - Cast Iron | 599010 | 3301 | 599010 | 59901 CAST IRON MAINS | 201508 | (30.45) | 2 | 0.0027583 | (0.17) | (1.01) |
| 376200-Mains - Cast Iron | 001712 | 3303 | 001712 | Inst 16489F 2P Cote Brilliante | 201508 | (56,908.94) | 2 | 0.0027583 | (313.94) | (1,883.66) |
| 376200-Mains - Cast Iron | 002139 | 3303 | 002139 | Inst 3278F 2P MLK -Wellston 1B | 201508 | (9,228.98) | 2 | 0.0027583 | (50.91) | (305.48) |
| 376200-Mains - Cast Iron | 900270 | 3303 | 900270 | Inst 2942F 2P Walnut Park Ph5B | 201508 | (9,841.88) | 2 | 0.0027583 | (54.29) | (325.76) |
| 376200-Mains - Cast Iron | 900271 | 3303 | 900271 | Inst 2646F 2P Walnut Park Ph5C | 201508 | (7,444.09) | 2 | 0.0027583 | (41.07) | (246.40) |
| 376200-Mains - Cast Iron | 900447 | 3303 | 900447 | Aband 13120F C Jefferson Ph 6 | 201508 | (41,928.19) | 2 | 0.0027583 | (231.30) | (1,387.81) |
| 376200-Mains - Cast Iron | 900559 | 3303 | 900559 | Inst 3875F 2P Walnut Park Ph6C | 201508 | (12,608.56) | 2 | 0.0027583 | (69.56) | (417.34) |
| 376200-Mains - Cast Iron | 900652 | 3303 | 900652 | Inst 4435F 2P St Louis Hills Ph1B | 201508 | (10,033.17) | 2 | 0.0027583 | (55.35) | (332.09) |
| 376200-Mains - Cast Iron | 900653 | 3303 | 900653 | Inst 2636F 2P St Louis Hills Ph1C | 201508 | (8,293.54) | 2 | 0.0027583 | (45.75) | (274.51) |
| 376200-Mains - Cast Iron | 900681 | 3303 | 900681 | Inst 1637F 2P Cole & 18th Ph C | 201508 | (45,293.16) | 2 | 0.0027583 | (249.86) | (1,499.19) |
| 376200-Mains - Cast Iron | 900683 | 3303 | 900683 | Inst 1864F 2P Cole & 18th Ph D | 201508 | (6,253.67) | 2 | 0.0027583 | (34.50) | (206.99) |
| 376200-Mains - Cast Iron | 900687 | 3303 | 900687 | Inst 1096F 2P Cole & 18th Ph F | 201508 | (845.35) | 2 | 0.0027583 | (4.66) | (27.98) |

| | | | | | | | | | | |
|--------------------------|--------|------|--------|-------------------------------------|--------|-------------|---|-----------|----------|------------|
| 376200-Mains - Cast Iron | 900689 | 3303 | 900689 | Inst 2434F 2P Cole & 18th PhG | 201508 | (35,165.36) | 2 | 0.0027583 | (193.99) | (1,163.96) |
| 376200-Mains - Cast Iron | 900734 | 3303 | 900734 | Repl w/ 1717F 2P Hurck | 201508 | (35,158.59) | 2 | 0.0027583 | (193.96) | (1,163.74) |
| 376200-Mains - Cast Iron | 900738 | 3303 | 900738 | Repl w/ 780F 2P Kingsland MSD | 201508 | (1,494.60) | 2 | 0.0027583 | (8.25) | (49.47) |
| 376200-Mains - Cast Iron | 900765 | 3303 | 900765 | Inst 1899F 4P Earthquake Zone Ph1D | 201508 | (5,348.24) | 2 | 0.0027583 | (29.50) | (177.02) |
| 376200-Mains - Cast Iron | 900862 | 3303 | 900862 | Rep w/ 4552F 2P Broadway AOR | 201508 | (21,043.22) | 2 | 0.0027583 | (116.09) | (696.52) |
| 376200-Mains - Cast Iron | 900890 | 3303 | 900890 | Repl w/ 2218F 2P Russell & Flora | 201508 | (4,092.55) | 2 | 0.0027583 | (22.58) | (135.46) |
| 376200-Mains - Cast Iron | 900893 | 3303 | 900893 | Repl w/ 2486F 6P Arlington | 201508 | (4,019.83) | 2 | 0.0027583 | (22.18) | (133.05) |
| 376200-Mains - Cast Iron | 900895 | 3303 | 900895 | Repl w/ 828F 2P Marquette | 201508 | (2,201.50) | 2 | 0.0027583 | (12.14) | (72.87) |
| 376200-Mains - Cast Iron | 900896 | 3303 | 900896 | Repl w/ 2990F 2P 4P Maple | 201508 | (5,142.72) | 2 | 0.0027583 | (28.37) | (170.22) |
| 376200-Mains - Cast Iron | 900897 | 3303 | 900897 | Repl w/ 587F 2P Syracuse | 201508 | (253.02) | 2 | 0.0027583 | (1.40) | (8.37) |
| 376200-Mains - Cast Iron | 900905 | 3303 | 900905 | Repl w/ 806F 2P Utah | 201508 | (2,131.14) | 2 | 0.0027583 | (11.76) | (70.54) |
| 376200-Mains - Cast Iron | 900986 | 3303 | 900986 | Repl w/ 2189F 2P Earthquake Zone 2A | 201508 | (7,456.41) | 2 | 0.0027583 | (41.13) | (246.80) |
| 376200-Mains - Cast Iron | 901040 | 3303 | 901040 | Repl w/ 315F 2P Amherst Ave | 201508 | (362.57) | 2 | 0.0027583 | (2.00) | (12.00) |
| 376200-Mains - Cast Iron | 901062 | 3303 | 901062 | Aband 29F 4C Pershing AOR | 201508 | (49.00) | 2 | 0.0027583 | (0.27) | (1.62) |
| 376200-Mains - Cast Iron | 901176 | 3303 | 901176 | Aband 161F 6C Tamm | 201508 | (351.62) | 2 | 0.0027583 | (1.94) | (11.64) |

TOTAL - MAINS - CAST IRON - RETIREMENTS - MAIN REPLACEMENTS

(353,593.11) (2,007.50) (11,703.77)

MAINS - STEEL - RETIREMENTS - MAIN REPLACEMENTS

| PLANT ACCOUNT | WORK ORDER | BUDGET PROJECT | RELATED CWO | DESCRIPTION | RETIREMENT DATE | RETIREMENT AMOUNT | MONTHS | DEPR. MO. RATE | ACCUM. DEPR. | DEPR. EXPENSE |
|----------------------|------------|----------------|-------------|-------------------------------------|-----------------|-------------------|--------|----------------|--------------|---------------|
| 376100-Mains - Steel | 900319 | 3303 | 900319 | Repl w/ 50F 6S Old Halls Ferry/Vail | 201507 | (1,060.41) | 3 | 0.0012000 | (3.82) | (15.27) |
| 376100-Mains - Steel | 002139 | 3303 | 002139 | Inst 3278F 2P MLK -Wellston 1B | 201508 | (1,929.23) | 2 | 0.0012000 | (4.63) | (27.78) |
| 376100-Mains - Steel | 900447 | 3303 | 900447 | Aband 13120F C Jefferson Ph 6 | 201508 | (9,729.18) | 2 | 0.0012000 | (23.35) | (140.10) |
| 376100-Mains - Steel | 900681 | 3303 | 900681 | Inst 1637F 2P Cole & 18th Ph C | 201508 | (6,946.96) | 2 | 0.0012000 | (16.67) | (100.04) |
| 376100-Mains - Steel | 900689 | 3303 | 900689 | Inst 2434F 2P Cole & 18th PhG | 201508 | (40,244.24) | 2 | 0.0012000 | (96.59) | (579.52) |
| 376100-Mains - Steel | 900734 | 3303 | 900734 | Repl w/ 1717F 2P Hurck | 201508 | (5,373.97) | 2 | 0.0012000 | (12.90) | (77.39) |
| 376100-Mains - Steel | 900738 | 3303 | 900738 | Repl w/ 780F 2P Kingsland MSD | 201508 | (90.14) | 2 | 0.0012000 | (0.22) | (1.30) |
| 376100-Mains - Steel | 900765 | 3303 | 900765 | Inst 1899F 4P Earthquake Zone Ph1D | 201508 | (4,032.03) | 2 | 0.0012000 | (9.68) | (58.06) |
| 376100-Mains - Steel | 900862 | 3303 | 900862 | Rep w/ 4552F 2P Broadway AOR | 201508 | (7,192.47) | 2 | 0.0012000 | (17.26) | (103.57) |
| 376100-Mains - Steel | 900896 | 3303 | 900896 | Repl w/ 2990F 2P 4P Maple | 201508 | (3,938.89) | 2 | 0.0012000 | (9.45) | (56.72) |
| 376100-Mains - Steel | 900897 | 3303 | 900897 | Repl w/ 587F 2P Syracuse | 201508 | (160.77) | 2 | 0.0012000 | (0.39) | (2.32) |
| 376100-Mains - Steel | 901026 | 3303 | 901026 | Aband 420F 2S Westphalia | 201508 | (1,308.91) | 2 | 0.0012000 | (3.14) | (18.85) |
| 376100-Mains - Steel | 901112 | 3303 | 901112 | UGS Gathering Line Replacement | 201508 | (290.46) | 2 | 0.0012000 | (0.70) | (4.18) |

TOTAL MAINS - STEEL - RETIREMENTS - MAIN REPLACEMENTS

(82,297.66) (198.80) (1,185.10)

Distribution Plant - Mains - Replacement

| PLANT ACCOUNT | WORK ORDER | BUDGET PROJECT | DESCRIPTION | IN SERVICE DATE | ADDITION AMOUNT | MONTHS | DEPR. MO. RATE | ACCUM. DEPR. | DEPR. EXPENSE |
|---------------|------------|----------------|-------------|-----------------|-----------------|--------|----------------|--------------|---------------|
| | | | | 201407 | 0 | 15.0 | 0.0012000 | - | - |
| | | | | 201408 | 0 | 14.0 | 0.0012000 | - | - |

Total Distribution Plant - Mains - Replacement

- -

TOTAL MAIN RETIREMENTS - MAIN REPLACEMENTS

(735,567.89) (3,012.28) (17,593.67)

RETIREMENT OF SERVICES

ACCOUNT 38010 SERVICES STEEL

| PLANT ACCOUNT | WORK ORDER | BUDGET PROJECT | DESCRIPTION | RETIREMENT DATE | RETIREMENT AMOUNT | MONTHS | DEPR. MO. RATE | ACCUM. DEPR. | DEPR. EXPENSE |
|-------------------------|------------|----------------|-------------------------------------|-----------------|-------------------|--------|----------------|--------------|---------------|
| 380100-Services - Steel | 599160 | | 59916 SVC RENEW STL CITY | 201507 | (1.66) | 3 | 0.0043583 | (0.02) | (0.09) |
| 380100-Services - Steel | 695160 | | 69516 SVC RENEW STEEL SO | 201507 | (7,675.30) | 3 | 0.0043583 | (100.35) | (401.42) |
| 380100-Services - Steel | 695300 | | 69530 SVC REN 1/2 PL SO | 201507 | (1,297.82) | 3 | 0.0043583 | (16.97) | (67.88) |
| 380100-Services - Steel | 695310 | | 69531 SV REN 1IN PL SO | 201507 | (604.71) | 3 | 0.0043583 | (7.91) | (31.63) |
| 380100-Services - Steel | 695320 | | 69532 SV REN 1 1/4 PL SO | 201507 | (1,222.16) | 3 | 0.0043583 | (15.98) | (63.92) |
| 380100-Services - Steel | 695330 | | 69533 SV REN 2&OVR PL SO | 201507 | (670.77) | 3 | 0.0043583 | (8.77) | (35.08) |
| 380100-Services - Steel | 695660 | | 69566 SVC RENEW STEEL NO | 201507 | (945.65) | 3 | 0.0043583 | (12.36) | (49.46) |
| 380100-Services - Steel | 695800 | | 69580 SVC REN 1/2 PL NO | 201507 | (862.76) | 3 | 0.0043583 | (11.28) | (45.12) |
| 380100-Services - Steel | 698450 | | 69845 SVC RNW 1/2 PL SC | 201507 | (403.03) | 3 | 0.0043583 | (5.27) | (21.08) |
| 380100-Services - Steel | 699160 | | 69916 SVC RENEW STEEL C | 201507 | (10,580.63) | 3 | 0.0043583 | (138.34) | (553.36) |
| 380100-Services - Steel | 699300 | | 69930 SVC REN 1/2 PL CTY | 201507 | (394.34) | 3 | 0.0043583 | (5.16) | (20.62) |
| 380100-Services - Steel | 699310 | | 69931 SVC REN 1IN PL CTY | 201507 | (7,788.17) | 3 | 0.0043583 | (101.83) | (407.32) |
| 380100-Services - Steel | 699320 | | 69932 SVC REN 1 1/4 PL C | 201507 | (3,402.79) | 3 | 0.0043583 | (44.49) | (177.96) |
| 380100-Services - Steel | 900623 | | Repl w/ 2852' 2P Wydown Ph 6 | 201507 | (421.23) | 3 | 0.0043583 | (5.51) | (22.03) |
| 380100-Services - Steel | 900633 | | Rel w/ 321F 4S 2S Progress Parkway | 201507 | (501.85) | 3 | 0.0043583 | (6.56) | (26.24) |
| 380100-Services - Steel | 900677 | | Inst 1795F 2P Cole & 18th PhA | 201507 | (7,064.99) | 3 | 0.0043583 | (92.37) | (369.50) |
| 380100-Services - Steel | 900898 | | Repl w/ 1220F 2P Ohio | 201507 | (3,701.70) | 3 | 0.0043583 | (48.40) | (193.60) |
| 380100-Services - Steel | 900900 | | Repl w/ 1075F 2P Washington | 201507 | (2,345.29) | 3 | 0.0043583 | (30.66) | (122.66) |
| 380100-Services - Steel | 900902 | | Repl w/ 530' 2P Oakland | 201507 | (561.46) | 3 | 0.0043583 | (7.34) | (29.36) |
| 380100-Services - Steel | 901011 | | Rel w/ 450F 4P Sanford AOR | 201507 | (4,473.12) | 3 | 0.0043583 | (58.49) | (233.94) |
| 380100-Services - Steel | 695160 | | 69516 SVC RENEW STEEL SO | 201508 | (7,146.60) | 2 | 0.0043583 | (82.29) | (373.76) |
| 380100-Services - Steel | 695300 | | 69530 SVC REN 1/2 PL SO | 201508 | (357.59) | 2 | 0.0043583 | (3.12) | (18.70) |
| 380100-Services - Steel | 695310 | | 69531 SV REN 1IN PL SO | 201508 | (555.43) | 2 | 0.0043583 | (4.84) | (29.05) |
| 380100-Services - Steel | 695800 | | 69580 SVC REN 1/2 PL NO | 201508 | (272.50) | 2 | 0.0043583 | (2.38) | (14.25) |
| 380100-Services - Steel | 695810 | | 69581 SV REN 1IN PL NO | 201508 | (789.12) | 2 | 0.0043583 | (6.88) | (41.27) |
| 380100-Services - Steel | 699160 | | 69916 SVC RENEW STEEL C | 201508 | (10,580.65) | 2 | 0.0043583 | (92.23) | (553.36) |
| 380100-Services - Steel | 699310 | | 69931 SVC REN 1IN PL CTY | 201508 | (383.86) | 2 | 0.0043583 | (3.35) | (20.08) |
| 380100-Services - Steel | 699330 | | 69933 SVC REN 2&OVR PL C | 201508 | (354.39) | 2 | 0.0043583 | (3.09) | (18.53) |
| 380100-Services - Steel | 900079 | | Repl w/ 2520F 2P Jefferson Ph 6 | 201508 | (4,333.35) | 2 | 0.0043583 | (37.77) | (226.63) |
| 380100-Services - Steel | 900270 | | Inst 2942F 2P Walnut Park Ph5B | 201508 | (1,195.95) | 2 | 0.0043583 | (10.42) | (62.55) |
| 380100-Services - Steel | 900271 | | Inst 2646F 2P Walnut Park Ph5C | 201508 | (1,257.12) | 2 | 0.0043583 | (10.96) | (65.75) |
| 380100-Services - Steel | 900559 | | Inst 3875F 2P Walnut Park Ph6C | 201508 | (3,530.32) | 2 | 0.0043583 | (30.77) | (184.63) |
| 380100-Services - Steel | 900643 | | Inst 1801F 6P-12P Marmaduke/Hudler | 201508 | (42.08) | 2 | 0.0043583 | (0.37) | (2.20) |
| 380100-Services - Steel | 900652 | | Inst 4435F 2P St Louis Hills Ph1B | 201508 | (3,464.74) | 2 | 0.0043583 | (30.20) | (181.20) |
| 380100-Services - Steel | 900653 | | Inst 2638F 2P St Louis Hills Ph1C | 201508 | (5,754.25) | 2 | 0.0043583 | (50.24) | (301.47) |
| 380100-Services - Steel | 900679 | | Inst 2312F 4P Cole & 18th PhB | 201508 | (495.67) | 2 | 0.0043583 | (4.32) | (25.92) |
| 380100-Services - Steel | 900681 | | Inst 1637F 2P Cole & 18th Ph C | 201508 | (4,295.99) | 2 | 0.0043583 | (37.45) | (224.68) |
| 380100-Services - Steel | 900683 | | Inst 1864F 2P Cole & 18th Ph D | 201508 | (2,126.39) | 2 | 0.0043583 | (18.53) | (111.21) |
| 380100-Services - Steel | 900685 | | Inst 1550F 2P Cole & 18th PhE | 201508 | (2,575.15) | 2 | 0.0043583 | (22.45) | (134.68) |
| 380100-Services - Steel | 900687 | | Inst 1096F 2P Cole & 18th PhF | 201508 | (441.99) | 2 | 0.0043583 | (3.85) | (23.12) |
| 380100-Services - Steel | 900689 | | Inst 2434F 2P Cole & 18th PhG | 201508 | (6,565.05) | 2 | 0.0043583 | (57.22) | (343.35) |
| 380100-Services - Steel | 900734 | | Repl w/ 1717F 2P Hurck | 201508 | (4,109.61) | 2 | 0.0043583 | (35.82) | (214.93) |
| 380100-Services - Steel | 900738 | | Repl w/ 780F 2P Kingsland MSD | 201508 | (73.91) | 2 | 0.0043583 | (0.64) | (3.87) |
| 380100-Services - Steel | 900764 | | Repl w/758F 2P Earthquake Zone Ph1C | 201508 | (1,244.48) | 2 | 0.0043583 | (10.85) | (65.09) |
| 380100-Services - Steel | 900765 | | Inst 1899F 4P Earthquake Zone Ph1D | 201508 | (554.67) | 2 | 0.0043583 | (4.83) | (29.01) |
| 380100-Services - Steel | 900862 | | Rep w/ 4552F 2P Broadway AOR | 201508 | (9,480.41) | 2 | 0.0043583 | (82.64) | (495.82) |
| 380100-Services - Steel | 900890 | | Repl w/ 2218F 2P Russell & Flora | 201508 | (16.77) | 2 | 0.0043583 | (0.15) | (0.88) |
| 380100-Services - Steel | 900893 | | Repl w/ 2486F 6P Arlington | 201508 | (938.64) | 2 | 0.0043583 | (8.18) | (49.09) |
| 380100-Services - Steel | 900895 | | Repl w/ 828F 2P Marquette | 201508 | (5,901.73) | 2 | 0.0043583 | (51.44) | (308.66) |

| | | | | | | | | |
|-------------------------|--------|-------------------------------------|--------|------------|---|-----------|---------|----------|
| 380100-Services - Steel | 900896 | Repl w/ 2990F 2P 4P Maple | 201508 | (937.60) | 2 | 0.0043583 | (8.17) | (49.04) |
| 380100-Services - Steel | 900897 | Repl w/ 587F 2P Syracuse | 201508 | (927.69) | 2 | 0.0043583 | (8.09) | (48.52) |
| 380100-Services - Steel | 900905 | Repl w/ 806F 2P Utah | 201508 | (4,226.36) | 2 | 0.0043583 | (36.84) | (221.04) |
| 380100-Services - Steel | 900986 | Repl w/ 2189F 2P Earthquake Zone 2A | 201508 | (1,747.72) | 2 | 0.0043583 | (15.23) | (91.41) |
| 380100-Services - Steel | 901071 | Rel w/ 285F 2P Froesel Ph2 | 201508 | (137.27) | 2 | 0.0043583 | (1.20) | (7.18) |

TOTAL (141,744.28) (1,474.87) (7,413.20)

ACCOUNT 38020 SERVICES PLASTIC & COPPER

| PLANT ACCOUNT | WORK ORDER | BUDGET PROJECT | DESCRIPTION | RETIREMENT DATE | RETIREMENT AMOUNT | MONTHS | DEPR. MO. RATE | ACCUM. DEPR. | DEPR. EXPENSE |
|------------------------------------|------------|----------------|-------------------------------------|-----------------|-------------------|--------|----------------|--------------|---------------|
| 380200-Services - Plastic & Copper | 695160 | | 69516 SVC RENEW STEEL SO | 201507 | (422.35) | 3 | 0.0031250 | (3.96) | (15.84) |
| 380200-Services - Plastic & Copper | 695300 | | 69530 SVC REN 1/2 PL SO | 201507 | (12,404.85) | 3 | 0.0031250 | (116.30) | (465.18) |
| 380200-Services - Plastic & Copper | 695310 | | 69531 SV REN 1IN PL SO | 201507 | (11,592.82) | 3 | 0.0031250 | (108.68) | (434.73) |
| 380200-Services - Plastic & Copper | 695320 | | 69532 SV REN 1 1/4 PL SO | 201507 | (2,221.61) | 3 | 0.0031250 | (20.83) | (83.31) |
| 380200-Services - Plastic & Copper | 695330 | | 69533 SV REN 2&OVR PL SO | 201507 | (10,242.84) | 3 | 0.0031250 | (96.03) | (384.11) |
| 380200-Services - Plastic & Copper | 695800 | | 69580 SVC REN 1/2 PL NO | 201507 | (422.11) | 3 | 0.0031250 | (3.96) | (15.83) |
| 380200-Services - Plastic & Copper | 695810 | | 69581 SV REN 1IN PL NO | 201507 | (285.54) | 3 | 0.0031250 | (2.68) | (10.71) |
| 380200-Services - Plastic & Copper | 696450 | | 69645 SVC REN 1/2 PL MW | 201507 | (67.76) | 3 | 0.0031250 | (0.64) | (2.54) |
| 380200-Services - Plastic & Copper | 696460 | | 69646 SVC REN 1IN PL MW | 201507 | (408.10) | 3 | 0.0031250 | (3.83) | (15.30) |
| 380200-Services - Plastic & Copper | 698450 | | 69845 SVC RNW 1/2 PL SC | 201507 | (2,019.88) | 3 | 0.0031250 | (18.94) | (75.75) |
| 380200-Services - Plastic & Copper | 698460 | | 69846 SVC RNW 1IN PL SC | 201507 | (1,563.32) | 3 | 0.0031250 | (14.65) | (58.61) |
| 380200-Services - Plastic & Copper | 699300 | | 69930 SVC REN 1/2 PL CTY | 201507 | (7,638.60) | 3 | 0.0031250 | (71.61) | (286.45) |
| 380200-Services - Plastic & Copper | 699310 | | 69931 SVC REN 1IN PL CTY | 201507 | (30,410.05) | 3 | 0.0031250 | (285.09) | (1,140.38) |
| 380200-Services - Plastic & Copper | 699320 | | 69932 SVC REN 1 1/4 PL C | 201507 | (1,776.09) | 3 | 0.0031250 | (16.65) | (66.60) |
| 380200-Services - Plastic & Copper | 900623 | | Repl w/ 2852' 2P Wydown Ph 6 | 201507 | (16,739.61) | 3 | 0.0031250 | (156.93) | (627.74) |
| 380200-Services - Plastic & Copper | 900677 | | Inst 1795F 2P Cole & 18th PhA | 201507 | (3,608.01) | 3 | 0.0031250 | (33.83) | (135.30) |
| 380200-Services - Plastic & Copper | 900759 | | Repl w/ 2836F 2P Hickory Dale | 201507 | (8,319.74) | 3 | 0.0031250 | (78.00) | (311.99) |
| 380200-Services - Plastic & Copper | 900898 | | Repl w/ 1220F 2P Ohio | 201507 | (4,113.36) | 3 | 0.0031250 | (38.56) | (154.25) |
| 380200-Services - Plastic & Copper | 900900 | | Repl w/ 1075F 2P Washington | 201507 | (27,593.18) | 3 | 0.0031250 | (258.69) | (1,034.74) |
| 380200-Services - Plastic & Copper | 900902 | | Repl w/ 530' 2P Oakland | 201507 | (95.10) | 3 | 0.0031250 | (0.89) | (3.57) |
| 380200-Services - Plastic & Copper | 900948 | | Repl w/ 132F 2P Southcoate | 201507 | (207.43) | 3 | 0.0031250 | (1.94) | (7.78) |
| 380200-Services - Plastic & Copper | 901011 | | Rel w/ 450F 4P Sanford AOR | 201507 | (13,610.15) | 3 | 0.0031250 | (127.60) | (510.38) |
| 380200-Services - Plastic & Copper | 695160 | | 69516 SVC RENEW STEEL SO | 201508 | (11.50) | 2 | 0.0031250 | (0.07) | (0.43) |
| 380200-Services - Plastic & Copper | 695300 | | 69530 SVC REN 1/2 PL SO | 201508 | (6,257.00) | 2 | 0.0031250 | (39.11) | (234.64) |
| 380200-Services - Plastic & Copper | 695310 | | 69531 SV REN 1IN PL SO | 201508 | (6,222.59) | 2 | 0.0031250 | (38.89) | (233.35) |
| 380200-Services - Plastic & Copper | 695800 | | 69580 SVC REN 1/2 PL NO | 201508 | (85.41) | 2 | 0.0031250 | (0.53) | (3.20) |
| 380200-Services - Plastic & Copper | 695810 | | 69581 SV REN 1IN PL NO | 201508 | (1,139.58) | 2 | 0.0031250 | (7.12) | (42.73) |
| 380200-Services - Plastic & Copper | 698450 | | 69845 SVC RNW 1/2 PL SC | 201508 | (257.67) | 2 | 0.0031250 | (1.61) | (9.66) |
| 380200-Services - Plastic & Copper | 699160 | | 69916 SVC RENEW STEEL C | 201508 | (77.48) | 2 | 0.0031250 | (0.48) | (2.91) |
| 380200-Services - Plastic & Copper | 699300 | | 69930 SVC REN 1/2 PL CTY | 201508 | (1,984.37) | 2 | 0.0031250 | (12.40) | (74.41) |
| 380200-Services - Plastic & Copper | 699310 | | 69931 SVC REN 1IN PL CTY | 201508 | (3,029.34) | 2 | 0.0031250 | (18.93) | (113.60) |
| 380200-Services - Plastic & Copper | 699330 | | 69933 SVC REN 2&OVR PL C | 201508 | (10,411.62) | 2 | 0.0031250 | (65.07) | (390.44) |
| 380200-Services - Plastic & Copper | 900073 | | Repl w/ 2520F 2P Jefferson Ph 6 | 201508 | (72,834.27) | 2 | 0.0031250 | (455.21) | (2,731.29) |
| 380200-Services - Plastic & Copper | 900270 | | Inst 2942F 2P Walnut Park Ph5B | 201508 | (93,332.00) | 2 | 0.0031250 | (583.33) | (3,499.95) |
| 380200-Services - Plastic & Copper | 900271 | | Inst 2646F 2P Walnut Park Ph5C | 201508 | (78,405.82) | 2 | 0.0031250 | (490.04) | (2,940.22) |
| 380200-Services - Plastic & Copper | 900310 | | Inst 2250F 2P Yale Ave Maplewood 1C | 201508 | (16,632.79) | 2 | 0.0031250 | (103.95) | (623.73) |
| 380200-Services - Plastic & Copper | 900447 | | Aband 13120F C Jefferson Ph 6 | 201508 | (6,187.37) | 2 | 0.0031250 | (38.67) | (232.03) |
| 380200-Services - Plastic & Copper | 900476 | | Inst 3350F 6P Ivory | 201508 | (243.54) | 2 | 0.0031250 | (1.52) | (9.13) |
| 380200-Services - Plastic & Copper | 900559 | | Inst 3875F 2P Walnut Park Ph6C | 201508 | (160,480.38) | 2 | 0.0031250 | (1,003.00) | (6,018.01) |
| 380200-Services - Plastic & Copper | 900652 | | Inst 4435F 2P St Louis Hillis Ph1B | 201508 | (127,962.95) | 2 | 0.0031250 | (799.77) | (4,798.61) |

| | | | | | | | | | |
|------------------------------------|--------|-------------------------------------|--------|--------------|---|-----------|-----------------------|-------------------|--------------------|
| 380200-Services - Plastic & Copper | 900653 | Inst 2636F 2P St Louis Hills Ph1C | 201508 | (61,836.41) | 2 | 0.0031250 | (386.48) | (2,318.87) | |
| 380200-Services - Plastic & Copper | 900670 | Rel w/ 400F 6P Vogel Rd | 201508 | (253.68) | 2 | 0.0031250 | (1.59) | (9.51) | |
| 380200-Services - Plastic & Copper | 900679 | Inst 2312F 4P Cole & 18th PhB | 201508 | (2,380.99) | 2 | 0.0031250 | (14.88) | (89.29) | |
| 380200-Services - Plastic & Copper | 900681 | Inst 1637F 2P Cole & 18th Ph C | 201508 | (2,510.46) | 2 | 0.0031250 | (15.69) | (94.14) | |
| 380200-Services - Plastic & Copper | 900683 | Inst 1864F 2P Cole & 18th Ph D | 201508 | (6,758.00) | 2 | 0.0031250 | (42.24) | (253.43) | |
| 380200-Services - Plastic & Copper | 900685 | Inst 1550F 2P Cole & 18th PhE | 201508 | (2,423.89) | 2 | 0.0031250 | (15.15) | (90.90) | |
| 380200-Services - Plastic & Copper | 900687 | Inst 1096F 2P Cole & 18th PhF | 201508 | (3,256.79) | 2 | 0.0031250 | (20.35) | (122.13) | |
| 380200-Services - Plastic & Copper | 900689 | Inst 2434F 2P Cole & 18th PhG | 201508 | (3,969.76) | 2 | 0.0031250 | (24.81) | (148.87) | |
| 380200-Services - Plastic & Copper | 900734 | Repl w/ 1717F 2P Hurck | 201508 | (11,165.37) | 2 | 0.0031250 | (69.78) | (418.70) | |
| 380200-Services - Plastic & Copper | 900738 | Repl w/ 780F 2P Kingsland MSD | 201508 | (12,040.93) | 2 | 0.0031250 | (75.26) | (451.53) | |
| 380200-Services - Plastic & Copper | 900764 | Repl w/758F 2P Earthquake Zone Ph1C | 201508 | (6,786.16) | 2 | 0.0031250 | (42.41) | (254.48) | |
| 380200-Services - Plastic & Copper | 900765 | Inst 1899F 4P Earthquake Zone Ph1D | 201508 | (21,555.12) | 2 | 0.0031250 | (134.72) | (808.32) | |
| 380200-Services - Plastic & Copper | 900823 | Repl w/ 659F 2P Baden Ph6A | 201508 | (5,133.27) | 2 | 0.0031250 | (32.08) | (192.50) | |
| 380200-Services - Plastic & Copper | 900862 | Rep w/ 4552F 2P Broadway AOR | 201508 | (20,888.66) | 2 | 0.0031250 | (130.55) | (783.32) | |
| 380200-Services - Plastic & Copper | 900890 | Repl w/ 2218F 2P Russell & Flora | 201508 | (49,105.57) | 2 | 0.0031250 | (306.91) | (1,841.46) | |
| 380200-Services - Plastic & Copper | 900893 | Repl w/ 2486F 6P Arlington | 201508 | (67,294.80) | 2 | 0.0031250 | (420.59) | (2,523.56) | |
| 380200-Services - Plastic & Copper | 900895 | Repl w/ 828F 2P Marquette | 201508 | (34,825.49) | 2 | 0.0031250 | (217.66) | (1,305.96) | |
| 380200-Services - Plastic & Copper | 900896 | Repl w/ 2990F 2P 4P Maple | 201508 | (72,175.89) | 2 | 0.0031250 | (451.10) | (2,706.60) | |
| 380200-Services - Plastic & Copper | 900897 | Repl w/ 587F 2P Syracuse | 201508 | (583.70) | 2 | 0.0031250 | (3.65) | (21.89) | |
| 380200-Services - Plastic & Copper | 900905 | Repl w/ 806F 2P Utah | 201508 | (5,132.22) | 2 | 0.0031250 | (32.08) | (192.46) | |
| 380200-Services - Plastic & Copper | 900986 | Repl w/ 2189F 2P Earthquake Zone 2A | 201508 | (49,450.32) | 2 | 0.0031250 | (309.06) | (1,854.39) | |
| 380200-Services - Plastic & Copper | 901040 | Repl w/ 315F 2P Amherst Ave | 201508 | (2,166.11) | 2 | 0.0031250 | (13.54) | (81.23) | |
| 380200-Services - Plastic & Copper | 901107 | Rel w/ 62F 4P Southwest AOR | 201508 | (652.02) | 2 | 0.0031250 | (4.08) | (24.45) | |
| | | | | TOTAL | | | (1,183,663.47) | (7,884.65) | (44,387.42) |

Distribution Plant - Services - Renewed

| PLANT ACCOUNT | WORK ORDER | BUDGET PROJECT | RELATED WORK ORDER | IN SERVICE DATE | ADDITION AMOUNT | MONTHS | DEPR. MO. RATE | ACCUM. DEPR. | DEPR. EXPENSE |
|---------------|------------|----------------|--------------------|-----------------|-----------------|--------|----------------|--------------|---------------|
| | | | | | | | | | |
| | | | | | | | | | |

Total Service Line Replacements and Insertion Projects:

- - - - -

TOTAL RETIREMENTS - SERVICES

(1,325,407.75) (9,359.52) (51,800.62)

RETIREMENT - REGULATOR STATIONS

ACCOUNT 37800 MEASURING & REGULATING STATION EQUIPMENT

| PLANT ACCOUNT | WORK ORDER | BUDGET PROJECT | DESCRIPTION | RETIREMENT DATE | RETIREMENT AMOUNT | MONTHS | DEPR. MO. RATE | ACCUM. DEPR. | DEPR. EXPENSE |
|---------------|------------|----------------|-------------|-----------------|-------------------|--------|----------------|--------------|---------------|
| | | | | | | | | | |

TOTAL - - - - -

ACCOUNT 37900 MEASURING & REGULATING STATION EQUIPMENT - CITY GATE

| PLANT ACCOUNT | WORK ORDER | BUDGET PROJECT | | DESCRIPTION | RETIREMENT DATE | RETIREMENT AMOUNT | MONTHS | DEPR. MO. RATE | ACCUM. DEPR. | DEPR. EXPENSE |
|-------------------------------------|------------|----------------|--|--------------------------------|-----------------|-------------------|--------|----------------|--------------|---------------|
| 379000-Meas & Reg Station Eqpt-City | 557290 | | | 55729 UPGRADE TELEMETRIC EQUIP | 201311 | | 23 | 0.0030917 | - | - |
| 379000-Meas & Reg Station Eqpt-City | 557300 | | | 55730 RPL NETWORK RTU'S | 201311 | | 23 | 0.0030917 | - | - |

| | | |
|--|---|---|
| TOTAL | - | - |
| TOTAL RETIREMENTS - REGULATOR STATIONS | - | - |

RETIREMENTS - MAIN RELOCATIONS

MAINS - PLASTIC - RETIREMENTS - MAIN RELOCATIONS

#N/A 0.0013083 #N/A -

| PLANT ACCOUNT | WORK ORDER | BUDGET PROJECT | RELATED CWO | DESCRIPTION | RETIREMENT DATE | RETIREMENT AMOUNT | MONTHS | DEPR. MO. RATE | ACCUM. DEPR. | DEPR. EXPENSE |
|------------------------|------------|----------------|-------------|----------------------------|-----------------|-------------------|--------|----------------|--------------|---------------|
| 376300-Mains - Plastic | 901011 | 3403 | 901011 | Rel w/ 450F 4P Sanford AOR | 201507 | (42,095.65) | 3 | 0.0013083 | (165.22) | (660.88) |

| | | | | |
|--|-------|-------------|----------|----------|
| TOTAL MAINS - PLASTIC - RETIREMENTS - MAIN RELOCATIONS | TOTAL | (42,095.65) | (165.22) | (660.88) |
|--|-------|-------------|----------|----------|

MAINS - CAST IRON - RETIREMENTS - MAIN RELOCATIONS

| PLANT ACCOUNT | WORK ORDER | BUDGET PROJECT | RELATED CWO | DESCRIPTION | RETIREMENT DATE | RETIREMENT AMOUNT | MONTHS | DEPR. MO. RATE | ACCUM. DEPR. | DEPR. EXPENSE |
|--------------------------|------------|----------------|-------------|------------------------------------|-----------------|-------------------|--------|----------------|--------------|---------------|
| 376200-Mains - Cast Iron | 901011 | 3403 | 901011 | Rel w/ 450F 4P Sanford AOR | 201507 | (780.40) | 3 | 0.0027583 | (6.46) | (25.83) |
| 376200-Mains - Cast Iron | 901015 | 3403 | 901015 | Rel w/ 35F 4P Elmbank & Taylor AOR | 201508 | (75.15) | 0 | 0.0027583 | - | (2.49) |
| 376200-Mains - Cast Iron | 901106 | 3403 | 901106 | Rel w/ 38F 4P Compton AOR | 201508 | (53.42) | 0 | 0.0027583 | - | (1.77) |
| 376200-Mains - Cast Iron | 901107 | 3403 | 901107 | Rel w/ 62F 4P Southwest AOR | 201508 | (149.11) | 0 | 0.0027583 | - | (4.94) |
| 376200-Mains - Cast Iron | 901108 | 3403 | 901108 | Aband 155F 6C Newhouse & 20th AOR | 201508 | (240.40) | 0 | 0.0027583 | - | (7.96) |

| | | | | |
|--|-------|------------|--------|---------|
| TOTAL MAINS - CAST IRON - RETIREMENTS - MAIN RELOCATIONS | TOTAL | (1,298.48) | (6.46) | (42.99) |
|--|-------|------------|--------|---------|

MAINS - STEEL - RETIREMENTS - MAIN RELOCATIONS

| PLANT ACCOUNT | WORK ORDER | BUDGET PROJECT | RELATED CWO | DESCRIPTION | RETIREMENT DATE | RETIREMENT AMOUNT | MONTHS | DEPR. MO. RATE | ACCUM. DEPR. | DEPR. EXPENSE |
|----------------------|------------|----------------|-------------|-------------------------------------|-----------------|-------------------|--------|----------------|--------------|---------------|
| 376100-Mains - Steel | 900633 | 3403 | 900633 | Rel w/ 321F 4S 2S Progress Parkway | 201507 | (899.55) | 0 | 0.0012000 | - | (12.95) |
| 376100-Mains - Steel | 901013 | 3403 | 901013 | Rel w/ 1612F 4P Woodstock CJ | 201507 | (4,923.85) | 0 | 0.0012000 | - | (70.90) |
| 376100-Mains - Steel | 900095 | 3403 | 900095 | Rel w/ 350F 8P Mason Rd Bridge #211 | 201508 | (2,135.31) | 0 | 0.0012000 | - | (30.75) |
| 376100-Mains - Steel | 900670 | 3403 | 900670 | Rel w/ 400F 6P Vogel Rd | 201508 | (4,569.16) | 0 | 0.0012000 | - | (65.80) |
| 376100-Mains - Steel | 901071 | 3403 | 901071 | Rel w/ 285F 2P Froesel Ph2 | 201508 | (470.79) | 0 | 0.0012000 | - | (6.78) |
| 376100-Mains - Steel | 901173 | 3403 | 901173 | Vandeventer - City of St. Louis MRE | 201508 | (7,178.18) | 0 | 0.0012000 | - | (103.37) |

| | | | | |
|--|-------|-------------|---|----------|
| TOTAL MAINS - STEEL - RETIREMENTS - MAIN RELOCATIONS | TOTAL | (20,176.84) | - | (290.55) |
|--|-------|-------------|---|----------|

**Laclede Gas Company
ISRS Revenue Requirement Calculation**

ISRS Activity:

Gas Utility Plant Projects - Main Replacements and Other Projects Extending Useful Life of Mains:

Work Orders Placed in Service

| | |
|--------------------------|------------|
| Gross Additions | 10,901,241 |
| Deferred Taxes | (137,446) |
| Accumulated Depreciation | (29,684) |
| | 10,734,111 |

Total Net

10,734,111

Gas Utility Plant Projects - Service Line Replacements and Insertion Projects:

Work Orders Placed in Service

| | |
|--------------------------|-----------|
| Gross Additions | 5,986,383 |
| Deferred Taxes | (86,942) |
| Accumulated Depreciation | (16,832) |
| | 5,882,609 |

Total Net

5,882,609

Gas Utility Plant Projects - Regulator Stations:

Work Orders Placed in Service

| | |
|--------------------------|---------|
| Gross Additions | 168,514 |
| Deferred Taxes | (2,230) |
| Accumulated Depreciation | (1,037) |
| | 165,247 |

Total Net

165,247

Gas Utility Plant Projects - Main Relocations net of Reimbursements:

Work Orders Placed in Service

| | |
|--------------------------|----------|
| Gross Additions | 935,268 |
| Deferred Taxes | (13,656) |
| Accumulated Depreciation | (2,440) |
| | 919,172 |

Total Net

919,172

Gas Utility Plant Projects - Main Reinforcements Related to Other ISRS Eligible Projects:

Work Orders Placed in Service

| | |
|--------------------------|---|
| Gross Additions | - |
| Deferred Taxes | - |
| Accumulated Depreciation | - |
| | - |

Total Net

-

**Increase in Accumulated Deferred Income Taxes and Accumulated Depreciation
Associated with Eligible Infrastructure System Replacements which are included in a
Currently Effective ISRS**

| | |
|--|--|
| Total Incremental Accumulated Depreciation | |
| Total Incremental Accumulated Deferred Taxes | |

| | |
|--|------------|
| Total ISRS Rate Base | 17,701,139 |
| Overall Rate of Return per GR-2010-0171 | 7.1855% |
| UOI Required | 1,271,915 |
| Income Tax Conversion Factor | 1.62674 |
| Revenue Requirement Before Interest Deductibility | 2,069,071 |

| | |
|---|------------|
| Total ISRS Rate Base | 17,701,139 |
| Weighted Cost of Debt per GR-2010-0171 | 2.0445% |
| Interest Deduction | 361,900 |
| Marginal Income Tax Rate | 38.5272% |
| Income Tax Reduction due to Interest | 139,430 |
| Income Tax Conversion Factor | 1.62674 |
| Revenue Requirement Impact of Interest Deductibility | 226,816 |

| | |
|---|-----------|
| Total Revenue Requirement on Capital | 1,842,255 |
| Depreciation Expense | 351,743 |

Total Company ISRS Revenues 2,193,998

Total Staff Expected ISRS Revenues 1,623,658

Average of Company and Staff Recommendations 1,908,828

**Laclede Gas Company
ISRS Depreciation Expense**

| | Additions <u>Annual Depreciation</u> | Retirements <u>Annual Depreciation</u> |
|--|---|---|
| Main Replacements | 172,721.77 | (17,593.67) |
| Service Line Replacements and Insertion Projects | 228,454.34 | (51,800.62) |
| Regulator Stations | 6,252.86 | - |
| Main Relocations net of Reimbursements | 14,703.15 | (994.42) |
| Main Reinforcements | - | - |
| | <hr/> | <hr/> |
| Total | 422,132.12 | (70,388.71) |
| | <hr/> | <hr/> |
| Total Net Increase in Depreciation Expense | <u>351,743.41</u> | |

Laclede Gas Company
ISRS Filing
Incremental Accumulated Deferred Income Taxes and Accumulated Depreciation

| <u>ISRS Activity:</u> | <u>Accumulated</u> | <u>Accumulated</u> |
|---------------------------------|----------------------------|--------------------------|
| <u>Main Replacements, etc.</u> | <u>Depreciation</u> | <u>Deferred</u> |
| | | <u>Income Taxes</u> |
| At May 15, 2015 | 1,359,216.83 | 9,473,892.52 |
| At November 15, 2015 | 1,884,743.68 | 9,810,080.24 |
| Incremental Change | <u>525,526.84</u> | <u>336,187.72</u> |
| <u>Services</u> | | |
| At May 15, 2015 | 2,136,242.69 | 7,669,578.32 |
| At November 15, 2015 | 2,895,189.08 | 7,959,352.24 |
| Incremental Change | <u>758,946.39</u> | <u>289,773.92</u> |
| <u>Regulator Stations</u> | | |
| At May 15, 2015 | 63,996.32 | 232,511.64 |
| At November 15, 2015 | 82,731.86 | 220,953.41 |
| Incremental Change | <u>18,735.54</u> | <u>(11,558.23)</u> |
| <u>Main Relocations</u> | | |
| At May 15, 2015 | 99,421.02 | 1,048,414.73 |
| At November 15, 2015 | 140,928.01 | 1,080,755.83 |
| Incremental Change | <u>41,506.99</u> | <u>32,341.10</u> |
| <u>Main Reinforcements</u> | | |
| At May 15, 2015 | 0 | 0 |
| At November 15, 2015 | 0 | 0 |
| Incremental Change | <u>0.00</u> | <u>0.00</u> |
| TOTAL INCREMENTAL CHANGE | <u><u>1,344,715.76</u></u> | <u><u>646,744.51</u></u> |

Laclede Gas Company
ISRS Deferred Taxes — Rate Base Reduction

| Depreciation for the period for Plant in Service | Sept 1 - May 15 2014 - 2015 | | Sept 1 - May 15 2014 - 2015 | | Total |
|---|--------------------------------|-------------------------------|--------------------------------|-------------------------------|--------------|
| | Sept 2014 | | Oct 1 - Feb 28 2014 - 2015 | | |
| | B 20 Year Life 50% Bonus | C 20 Year Life 0% Bonus | B 20 Year Life 50% Bonus | C 20 Year Life 0% Bonus | |
| <u>Main Replacements, etc.</u> Additions | - | - | - | 9,447,864.89 | 9,447,864.89 |
| Bonus Depreciation | - | - | - | - | - |
| Adjusted Tax Basis on Additions | - | - | - | 9,447,864.89 | 9,447,864.89 |
| Bonus Depreciation for Period | | | | | |
| Sept 1 - Sept 30, 2014 | - | - | - | - | - |
| Oct 1, 2014 - Feb 28, 2015 | - | - | - | - | - |
| Tax Depreciation On Adj. Basis | | | | | |
| Fiscal Year 2014 (Sep 1 - Sep 30) | - | - | - | - | - |
| Fiscal Year 2015 (Oct 1 - May 15) | - | - | - | 354,294.93 | 354,294.93 |
| | - | - | - | 28,418.39 | 28,418.39 |
| Total Tax Depreciation | - | - | - | 382,713.32 | 382,713.32 |
| Total Book Depreciation | | | | | 25,962.91 |
| Difference Between Book and Tax Depreciation | | | | | 356,750.41 |
| Deferred Income Taxes (@38.5272%) | | | | | 137,446.12 |

Laclede Gas Company
ISRS Deferred Taxes — Rate Base Reduction

| Depreciation for the period for Plant in Service | Sept 1 - May 15 2014 - 2015 | | | Sept 1 - May 15 2014 - 2015 | | | Total |
|---|--------------------------------|-------------------------------|---------------------------|--------------------------------|-------------------------------|--------------|--------------|
| | Sept 2014 | | 15 Year Life 50% Bonus | Oct 1 - Feb 28 2014 - 2015 | | Total | |
| | B 20 Year Life 50% Bonus | C 20 Year Life 0% Bonus | | B 20 Year Life 50% Bonus | C 20 Year Life 0% Bonus | | |
| <u>Services</u> | | | | | | | |
| Additions | - | - | - | - | - | 5,986,383.35 | 5,986,383.35 |
| Bonus Depreciation | - | - | - | - | - | - | - |
| Adjusted Tax Basis on Additions | - | - | - | - | - | 5,986,383.35 | 5,986,383.35 |
| Bonus Depreciation for Period | | | | | | | |
| Sept 1 - Sept 30, 2014 | - | - | - | - | - | - | - |
| Oct 1, 2014 - Feb 28, 2015 | - | - | - | - | - | - | - |
| Tax Depreciation On Adj. Basis | | | | | | | |
| Fiscal Year 2014 (Sep 1 - Sep 30) | - | - | - | - | - | - | - |
| Fiscal Year 2015 (Oct 1 - May 15)) | - | - | - | - | - | 224,489.38 | 224,489.38 |
| | - | - | - | - | - | 18,006.54 | 18,006.54 |
| Total Tax Depreciation | - | - | - | - | - | 242,495.92 | 242,495.92 |
| Total Book Depreciation | | | | | | | 16,831.50 |
| Difference Between Book and Tax Depreciation | | | | | | | 225,664.42 |
| Deferred Income Taxes (@38.5272%) | | | | | | | 86,942.29 |

Laclede Gas Company
ISRS Deferred Taxes — Rate Base Reduction

| Depreciation for the period for Plant in Service | Sept 1 - May 15 2014 - 2015 | | | | Sept 1 - May 15 2014 - 2015 | | | Total |
|---|--------------------------------|---------------------------|--------------------------|---------------------------|--------------------------------|---------------------------|--------------------------|------------|
| | FY 2013 Telemetry | Sept 2014 | | | Oct 1 - Feb 28 2014 - 2015 | | | |
| | 20 Year Life 50% Bonus | 20 Year Life 50% Bonus | 20 Year Life 0% Bonus | 15 Year Life 50% Bonus | 20 Year Life 100% Bonus | 20 Year Life 50% Bonus | 20 Year Life 0% Bonus | |
| <u>Regulator Stations</u> | | | | | | | | |
| Additions | - | - | - | - | - | - | 168,514.41 | 168,514.41 |
| Bonus Depreciation | - | - | - | - | - | - | - | - |
| Adjusted Tax Basis on Additions | - | - | - | - | - | - | 168,514.41 | 168,514.41 |
| Bonus Depreciation for Period | | | | | | | | |
| FY 2013 | - | | | | | | | |
| Sept 1 - Sept 30, 2014 | - | - | - | - | - | - | - | - |
| Oct 1, 2014 - Feb 28, 2015 | - | - | - | - | - | - | - | - |
| Tax Depreciation On Adj. Basis | | | | | | | | |
| Fiscal Year 2013 (Sept 1 - Sept 30) | - | | | | | | | |
| Fiscal Year 2014 (Sep 1 - Sep 30) | - | - | - | - | - | - | - | - |
| Fiscal Year 2015 (Oct 1 - May 15) | - | - | - | - | - | - | 6,319.29 | 6,319.29 |
| | - | - | - | - | - | - | 506.88 | 506.88 |
| Total Tax Depreciation | - | - | - | - | - | - | 6,826.17 | 6,826.17 |
| Total Book Depreciation | | | | | | | | 1,036.88 |
| Difference Between Book and Tax Depreciation | | | | | | | | 5,789.29 |
| Deferred Income Taxes (@38.5272%) | | | | | | | | 2,230.45 |

Laclede Gas Company
ISRS Deferred Taxes — Rate Base Reduction

| Depreciation for the period for Plant in Service | Sept 1 - May 15 2014 - 2015 | | | Sept 1 - May 15 2014 - 2015 | | | Total |
|---|--------------------------------|---------------------------|--------------------------|---------------------------------|--------------------------------|-------------------------------|------------|
| | Sept 2014 | | | Oct 1 - Feb 28 2014 - 2015 | | | |
| | 20 Year Life 100% Bonus | 20 Year Life 50% Bonus | 20 Year Life 0% Bonus | 0 20 Year Life 100% Bonus | B 20 Year Life 50% Bonus | C 20 Year Life 0% Bonus | |
| <u>Main Relocations</u> | | | | | | | |
| Additions | - | - | - | - | - | 935,268.17 | 935,268.17 |
| Bonus Depreciation | - | - | - | - | - | - | - |
| Adjusted Tax Basis on Additions | - | - | - | - | - | 935,268.17 | 935,268.17 |
| Bonus Depreciation for Period | | | | | | | |
| Sept 1 - Sept 30, 2014 | - | - | - | - | - | - | - |
| Oct 1, 2014 - Feb 28, 2015 | - | - | - | - | - | - | - |
| Tax Depreciation On Adj. Basis | | | | | | | |
| Fiscal Year 2014 (Sep 1 - Sep 30) | - | - | - | - | - | - | - |
| Fiscal Year 2015 (Oct 1 - May 15) | - | - | - | - | - | 35,072.56 | 35,072.56 |
| | - | - | - | - | - | 2,813.21 | 2,813.21 |
| Total Tax Depreciation | - | - | - | - | - | 37,885.77 | 37,885.77 |
| Total Book Depreciation | | | | | | | 2,439.89 |
| Difference Between Book and Tax Depreciation | | | | | | | 35,445.88 |
| Deferred Income Taxes (@38.5272%) | | | | | | | 13,656.32 |

Laclede Gas Company
Capital Structure/Rate of Return for ISRS
Case GR-2013-0171

| | % of Cap Structure | Embedded Cost | Weighted Cost |
|---------------------------------|--------------------|---------------|----------------|
| LTD | 47.00% | 4.35% | 2.0445% |
| Preferred Stock | 0.00% | 0.00% | 0.0000% |
| Common Equity | 53.00% | 9.70% | 5.1410% |
| Total Capital * | | | <u>7.1855%</u> |
| | | | |
| Tax Multiplier | | | 1.626737 |
| | | | |
| Composite Weighted Cost of Debt | | | 2.0445% |

* Reflects Stipulation and Agreement in GR-2013-0171, Late Filed Exhibit 1

**Laclede Gas Company
ISRS Rate Design**

Total ISRS Revenues 1,908,828

| <u>Customer Rate Class</u> | <u>Number of Customers*</u> | <u>Customer Charge</u> | <u>Ratio to Residential Customer Charge</u> | <u>Weighted Customer Nos.</u> | <u>Customer Percentage</u> | <u>Current ISRS Charge</u> | <u>Current ISRS Revenues</u> |
|----------------------------|-----------------------------|------------------------|---|-------------------------------|----------------------------|----------------------------|------------------------------|
| Residential | 606,244 | 19.50 | 1.0000 | 606,244 | 87.9253% | 0.23 | 1,678,343 |
| C&I 1 | 30,943 | 25.50 | 1.3077 | 40,464 | 5.8686% | 0.30 | 112,021 |
| C&I 2 | 8,961 | 44.29 | 2.2713 | 20,352 | 2.9517% | 0.52 | 56,343 |
| C&I 3 | 600 | 88.57 | 4.5421 | 2,726 | 0.3954% | 1.05 | 7,547 |
| LV | 72 | 874.78 | 44.8605 | 3,245 | 0.4706% | 10.35 | 8,983 |
| Interruptible | 18 | 776.36 | 39.8133 | 720 | 0.1044% | 9.19 | 1,993 |
| Transportation | 148 | 2,069.94 | 106.1508 | 15,675 | 2.2734% | 24.49 | 43,395 |
| Transportation - Other** | 0 | 1,707.94 | 87.5867 | 0 | 0.0000% | 0.00 | 0 |
| Gas Light | 87 | 5.69 | 0.2918 | 26 | 0.0037% | 0.07 | 71 |
| Vehicular Fuel | 9 | 22.09 | 1.1328 | 10 | 0.0014% | 0.26 | 27 |
| Liquid Propane | 44 | 17.00 | 0.8718 | 38 | 0.0055% | 0.20 | 106 |
| Total | 647,126 | | | | 100.0000% | | 1,908,828 |

*Average customers - FY 2014

**Single customers with multiple accounts located on contiguous property.