

**BEFORE THE PUBLIC SERVICE COMMISSION
STATE OF MISSOURI**

Rob Lee

Missouri American Water Company

June 7, 2009

Case # WC-2009-0277

**MOTION TO RENDER A JUDGMENT BY DEFAULT AGAINST
THE DISOBEDIENT PARTY RULE 61.01**

I have no repair records for the three repairs on Coal Bank CT.. One or more repairs on Larimore Ave. and at least two or more repairs on Lilac Ave.

RULE 61.01 For the purpose of this Rule, an evasive or incomplete answer is to be treated as a failure to answer.

1ST REQUEST ATTACHMENT #1 fails to include repair records for Coal Bank CT., Coal Bank Rd, Suntree Dr., Dunklin Dr., Starshier Dr, among others as maintained by MAWC even though they appear inside of the ¼ mile radius on the map that I was provided.

RESPONDENT'S SECOND SUPPLEMENTAL RESPONSES TO COMPLAINANTS'S FIRST DATA REQUEST Fails to list streets Coal Bank CT., Coal Bank Rd., Suntree Dr., Dunklin Dr., Starshier Dr, among others as maintained by MAWC even though they appear inside of the ¼ mile radius on the map that I was provided.

Please see photos. These are only the ones that I know of.

Rob Lee
Pro se
11119 Carl
St Louis Mo 63138
314-412-7016



Fresh concrete at Larimore and Coal Bank after repair No work order in 1ST REQUEST ATTACHMENT #1



Fresh concrete at 1234 Coal Bank Ct. after repair. No work order in 1ST REQUEST ATTACHMENT #1



Flag left behind after repair at 1207 Coal Bank Ct. no mention in 1ST REQUEST ATTACHMENT #1.



Fresh concrete at 1201 Coal Bank Ct after repair. No work order in 1ST REQUEST ATTACHMENT #1



Gravel after repair on Lilac at Coal Bank Rd. No work order in 1ST REQUEST ATTACHMENT #1



Two repairs near 11475 Lilac Rd.. No work order in 1ST REQUEST ATTACHMENT #1