

Commissioners

KELVIN L. SIMMONS Chair

CONNIE MURRAY

SHEILA LUMPE

STEVE GAW

BRYAN FORBIS

# Missouri Bublic Service Commission

POST OFFICE BOX 360 JEFFERSON CITY, MISSOURI 65102 573-751-3234 573-751-1847 (Fax Number) http://www.psc.state.mo.us

February 27, 2003

ROBERT J. QUINN, JR. Executive Director

WESS A. HENDERSON Director, Utility Operations

ROBERT SCHALLENBERG Director, Utility Services

DONNA M. PRENGER Director, Administration

DALE HARDY ROBERTS Secretary/Chief Regulatory Law Judge

> DANA K. JOYCE General Counsel

Ann Rudy — President KMB Utility Corporation 5108 Dulin Creek Road House Springs, MO 63051

RE:

Requests for Increase in Sewer Rates Small Company Rate Case Procedure

Mo. PSC Work ID No. QS-2003-0010 (sewer service)

#### Dear Ann:

Regarding the above-referenced subject, enclosed for your review and comment are the following documents: (1) the Staff's revenue requirement accounting runs, and related supporting documents; (2) the Staff's rate design work papers; and (3) customer bill comparisons based upon the Staff's recommended rates and rate design changes. Staff's audit shows that the Company should have a rate increase to annually generate \$8,511(approximately a 14.4% increase) in additional revenue for its sewer service.

Please look over the detail of the expenses and plant contained in the revenue requirement accounting run. If you find an error or need additional information or explanation regarding the expenses incorporated into the Company's cost of service, our Accounting Staff will be glad to discuss every aspect of its results with you. I have included rate design sheets that show the increase to rates that would affect the increase. The Staff and Company will also be requesting that the Commission authorize the depreciation rates that contained in the abovementioned documents. The Staff is also making the recommendations that the Company's "Late Payment Charge" be amended (see proposed tariff) and that the Company implements a "Bad Check Charge" of \$20 per bad check.

The Staff is requiring that the Company maintain a log recording all revenues and separate occurrences by operating system, related to each type of charge contained on the proposed "Schedule of Service Charges" tariff sheet, with monthly totals also being kept in this "Schedule of Service Charges" log book.

The Staff is seeking the Company agreement that its operator will keep more detailed time records for all future rate cases. Specifically, these time sheets must show the following items: the number of hours worked by the operator, the date the work was

performed, to which specific system these hours relate and the number of hours devoted to capital improvement projects, operation and maintenance, or general office.

In light of the large sewer repair bill that was incurred by KMB at the Cape Rock system, during the test year, the Staff recommends that the Company inspect, clean and repair all manholes on the system annually. In the past KMB routinely performed smoke tests on its lines to locate sources of infiltration and breaks in the mains. The Staff seeks the Company pledge to continue this practice under KMB's new ownership. The Staff is willing to assist in this project if its workload permits it to do so.

Staff is also seeking agreement that when the Company seeks future increases, that it is aware that it must file for rate changes for all of its operating areas: its existing water service areas, sewer service area and its Cedar Hill Estates service area.

On December 9, 2002, KMB and Cedar Hill Estates Water Company, Inc. filed an application (in Case No. WM-2003-0194) requesting the Commission's authority to merge Cedar Hill into KMB. KMB is to carry on the operations of Cedar Hill. The Staff believes that proper rates will be established for both KMB and Cedar Hill as part of this informal rate request process and is of the opinion that merger will not affect the rates recommended by the Staff and Company in these Small Company Rate Increase Procedures.

In the current rate case, the Accounting Staff found that Piffel Excavating, which is an affiliated Company, performed a majority of the capital improvement and repair work for KMB. Although, the Staff found most items to be reasonable, in the future the Staff recommends that KMB promise to solicit a minimum of three competitive bids for all projects that exceed \$2,000. In the future, KMB should not assume that Piffel is its only option to perform repair and improvement work. KMB shall acknowledge that lack of competitive bids will preclude any plant from being included in future rates.

Also attached to this document is a <u>Summary Overview of KMB Utility Corporation's Customer Service Operations</u>. Mr. John Kiebel of the Commission's Engineering and Management Services Department (EMSD) has prepared this document. Please do not be confused by his recommendation that the Company determine an appropriate charge level for returned checks and file a tariff to approve this charge. As you can see above, the charge he recommends that you develop is already being proposed to be changed in this case: therefore, you will not need to determine this charge nor file a tariff sheet in the future to affect these changes.

The following are the recommendations of Mr. Kiebel that have not already been addressed by other members of the staff:

- Make bank deposits on a timelier basis.
- 2) Store customer receipts overnight in a locked fireproof vault.

Ann Rudy KMB Utility Corporation Small Company Rate Increase Procedure Request February 27, 2003 Page 3 of 3

Please feel free to contact me by telephone at (573) 751-3437 if you have questions about any of the enclosed documents or if you need additional information. Please respond to me in writing, on or before March 14, 2003, about whether you agree with the Staff's proposals and which rate alternative you are interested in pursuing.

I am also providing this same information to the Office of the Public Counsel (OPC) for review and comment. After hearing back from you and the OPC, I will schedule a meeting or telephone conference between the Company, the Staff and the OPC to discuss the final resolution of the Company's rate increase requests.

Sincerely,

Wendell R. "Randy" Hubbs Assistant Manager - Rates Water and Sewer Department

enclosures

copy (letter only):

Leasha Teel Paul Adam Lisa Kremer Dale Johansen John Cassidy Roberta McKiddy Cliff Snodgrass

Jeremy Hagemeyer Ron Bible Steve Loethen Joan Wandel John Kiebel Jim Merciel FORM NO. 13

P. S. C. MO. No.

5th Revised

Sheet No. 5

Cancelling

P. S. C. MO. No.

4th Revised

Sheet No. 5

KMB Utility Corporation

For: Cape Rock Village (Cape Girardeau County)

Name of Issuing Company

Community, Town or City

#### **RULES GOVERNING**

# RENDERING OF SEWER SERVICE

+

# SCHEDULE OF SEWER RATES

# Sewer Rate Schedule A: Single Family Dwelling Availability:+

The following rate is applicable to single family residences, including mobile homes not located in mobile home parks, and is applicable to all customers located in the Company's Cape Rock Village certificated service area and adjacent to the Company's collection sewer.

Customer Charge

\$ 26.52 per Month

The Customer Charge will be billed each customer monthly.

# Sewer Rate Schedule B: Multiple Family Dwelling

Availability:+

The following rate is applicable to each rental unit of a multiple family dwelling and for individual mobile homes located in mobile home parks, where customers are located in the Company's Cape Rock Village certificated service area and adjacent to the Company's collection sewer.

Customer Charge \$21.21 per Month
The Customer Charge will be billed each customer monthly.

#### Taxes:

Any applicable Federal, State or local taxes shall be in addition to above charges.

#### Late Charges: +

Billings will be made and distributed at monthly intervals. Bills will be rendered net, bearing the last date on which payment will then be considered delinquent. The period after which the payment is considered delinquent is 21 days after rendition of the bill. A charge of \$5.00 or three percent (3%) per month times the unpaid balance, whichever is more, will be added to delinquent amounts.

- \* Indicates new rate or text
- + Indicates change

Date of Issue

Date Effective

Issued By: Ann Rudy President

510 Dulin Creek Rd., House Springs MO 63501

Name of Officer Title

Address

FORM NO. 13

P. S. C. MO. No.

3rd Revised

Sheet No. 11

Cancelling

P. S. C. MO. No. 1

2nd Revised

Sheet No. 11

KMB Utility Corporation

For: Cape Rock Village (Cape Girardeau County)

Name of Issuing Company

Community, Town or City

#### **RULES GOVERNING**

# RENDERING OF SEWER SERVICE

+

### SCHEDULE OF SERVICE CHARGES

These charges are applicable to the Company's service provided for in the corresponding rules.

#### Bad Check Charge: \*

A bad check charge of \$20 per check will be paid on all checks returned from the bank for insufficient funds.

#### Disconnection/Reconnection:

The Reconnection Charge after service disconnection by the Company for violation of the Company's Rules and Regulations (see Rule 7) shall be the total actual cost of discontinuance and reconnection of service. +

#### Service Connection:

Where the Company performs the construction of the physical connection to its collection system, the Customer shall pay the actual cost of connection.+

Where the Customer is having anyone except the Company install the connection to the system to his premises, the Customer shall notify the Company of such installation and the Customer is required have the Company inspect the connection pipe construction before the ditch is filled in.+

The Company will charge the Customer \$40 for the inspection of the connection pipe construction. +

- \* Indicates new rate or text
- + Indicates change

Date of Issue

**Date Effective** 

Issued By: Ann Rudy President

510 Dulin Creek Rd., House Springs MO 63501

Name of Officer Title

Address

# KMB - Cape Rock Village

Small Company Rate Filing - Sewer Service Work ID # QS-2003-0010

S-1

WOIR ID # Q3-2003-00 10	Deta Malina Inc.	
		ome Statement - Sev
A	As Adjusted	
Annual Revenues	\$59,050	· · · · · · · · · · · · · · · · · · ·
	_ <del>_</del>	Customer
Annual Expenses		Charge
Accounting Fees	\$1,147	\$1,147
Legal Fees	\$153	\$153
Annual Registration	\$106	\$106
Business Insurance	\$1,245	\$1,245
Certification	\$121	\$121
Chemicals	\$125	\$125
Depreciation Expense	\$6,583	\$6,583
Misc. assessments	\$62	, \$62
DNR - Water Testing	\$200	\$200
Electricty Expense	\$6,283	\$6,283
Employee Health Insurance	\$353	\$353
Freight/Postage/PitneyBowes	\$1,070	\$1,070
Miscellaneous	\$835	\$835
Loan Payment - Ann Rudy	\$0	\$0
Office Supplies	\$235	\$235
Officer Salaries	\$3,989	\$3,989
Operating Supplies	\$0	\$0
Outside Services	\$0	\$0
Soutside Services - Mowing	\$1,180	\$1.180
Pager	\$121	\$121
Payroll Taxes	\$1,762	\$1,762
Payroll Billing Expense	\$7,371	\$7,371
Payroll - Operator Expense	\$7,080	\$7,080
DNR - Permit	\$3,000	\$3,000
PSC Assessment	\$3,589	\$3,589
Real Estate Taxes	\$142	\$142
Rent	\$1,405	\$1,405
Repairs & Maintenance & R.M. Payroll	\$11,313	\$11,313
Amortization of Repair & Maintenance	\$1,058	\$1,058
Telephone Expense	\$870	\$870
Vehicle Expense	\$804	\$804
Water Expense	\$258	\$258
Return on Investment	\$5,101	\$5,101
Total Cost of Service	\$67,561	\$67,561
Less: Other Revenues	\$1,503	\$1,503
Cost to Recover in Rates	\$66,058	\$66,058
Increase =	\$8,511 14.	41%

\$9,448

January 27, 2003 Missouri Public Service Commission Staff

Requested Increase

Page 1 of 5 W. R. Hubbs

# KMB - Cape Rock Village

Small Company Rate Filing - Sewer Service Work ID # QS-2003-0010

S-1

# Rate Design

Single Family Residence Multiple Family Residence Total

Billings	Weighting	Weighted Billings
1,896	1.0	1,896
744	0.8	598
2,640		2,49

Sewer Service Rate Development

Customer	Charge	Development

	Cust Chg Costs An	nual Wtd. Billings	Cust Charge Rate
Single Family Customer Charge per Bill	\$66,058	2,491	\$26.52

	(A	A04 04
Mulitiple Family Customer Charge per Bill	(\$26.52 times .8)	\$21.21
manapie i analy odelenier onalge per bill	(Ψεσ.σε mnos.σ)	AP 1:5-1

January 27, 2003 Missouri Public Service Commission Staff Page 2 of 5 W. R. Hubbs

# KMB - Cape Rock Village Small Company Rate Filing - Sewer Service

Work ID # QS-2003-0010

S-1

# Residential Sewer Customer Impact

Single Family Residence Monthly Bill	Customer Charge	Total Bill
Proposed Rates	\$26.52	\$26.52
Current Rates	\$23.10	\$23.10
Difference	\$3.42	\$3.42
Percentage Difference from Current Rates	14.8%	14.8%

Multi Family Residence Monthly Bill	Customer Charge	Total Bill
Proposed Rates	\$21.21	\$21.21
Current Rates	\$18.48	\$18.48
Difference	\$2.73	\$2.73
Percentage Difference from Current Rates	14.8%	14.8%

January 27, 2003 Missouri Public Service Commission Staff Page 3 of 5 W. R. Hubbs

# KMB - Cape Rock Village

Small Company Rate Filing - Sewer Service Work ID # QS-2003-0010

S-1

# Proposed Charges - Sewer Annualized & Normalized Revenues

# **Customer Charge Revenues**

Customer Number - Single Family Dwellings	158
Customer Bills Per Year	1896
Times:	
Proposed Monthly Customer Charge	\$26.52
Equals:	
Annualized Single Family Customer Charge Revenue	\$50,275

Customer Number - Multiple Family Dwellings	62
Customer Bills Per Year	744
Times:	
Proposed Monthly Customer Charge	\$21.21
Equals:	
Annualized Multiple Family Customer Charge Revenue	<u>\$15,783</u>
Total Sewer Rate Revenues	

Miscellaneous Revenues	 \$1,503

Total Sewer Service Revenues	\$67,561

January 27, 2003 Missouri Public Service Commission Staff Page 4 of 5 W. R. Hubbs

\$66,058

# KMB - Cape Rock Village Small Company Rate Filing - Sewer Service

Work ID # QS-2003-0010

# Accounting Department

Test Year Annualized & Normalized Revenues

# **Customer Charge Revenues**

Customer Number - Single Family Dwellings	158
Customer Bills Per Year	1896
Times:	
Existing Monthly Customer Charge	<b>\$23.10</b>
Equals:	
Annualized Single Family Customer Charge Revenue	\$43,798

62
744
\$18.48
\$13,749

Total Sewer Rate Revenues			\$57.547
Trotal Control Rate Revenues		 	<del></del>

Miscellaneous Revenues	\$1,503
Total Sewer Service Revenues	\$59,050

January 29, 2003 Missouri Public Service Commission Staff Page 5 of 5 W. R. Hubbs

## KMB - Cape Rock Village Annualized Revenue Summary

Annualized Customers (12 months)		
Family Dwellings		1896
Multiple Family Dwellings	,	744
Customer Charge		
Family Dwellings	X	\$23.10
Multiple Family Dwellings	×	\$18.48
Annualized Customer Charge Revenues		
Family Dwellings		\$43,797.60
Multiple Family Dwellings		\$13,749.12
Total Annualized Revenues		\$57,546.72

RM NO. 13 P.S.C.MO. N	No1 4th {xxxxxxxxx} SHEET No5 { Revised }
Cancelling P.S.C.MO. I	No. 1 3rd { xxxxxxxx } SHEET No. 5
	{ Revised }
	For FRANCHISED AREAS
Name of Issuing Corporation	Community, Town or City
(Davis Water System)	STATE OF MISSOURI
SCI CAPE ROCK VILLA	HEDULE OF RATES (Sever) AGE (CAPE GIRARDEAU COUNTY) RECEIVED
	JLE A: FAMILY DWELLING
SEWER RATE SCHEDO	APR 16 1997
Availability:	MISSOURI Public Service Comm
The following rate is availal homes not located in mobile h	able for single family residences, including mobile nome parks.
RATE TABLE: Monthly Service (Payable in Adv	e Charge vance) \$23.10 +
SEWER RATE SO	CHEDULE B:
AVAILABILITY:	
The following rate is availa and for mobile homes located	able for each rental unit of a multiple family dwelling in mobile home parks.
RATE TABLE: Monthly Service (Payable in Adv	e Charge vance) \$18.48 +
TAXES:	
Any applicable Federal, St charges.	tate, or Local Taxes shall be in addition to above
	re subject to the terms and conditions of a * proved by the Missouri Public Service * -97-100 and SR-97-101. *
* Indicates new rate or text + Indicates change	PILED 97-1100 APR 2 1 1997 APR 2 1 1997 ANO. PUBLIC SERVICE COMM
ATE OF ISSUE April 16, 1997	DATE EFFECTIVE April 21, 1997  y years month day ye

	CORPORATION		{ xxxxxxxx } SHEET I { Revised } FRANCHISED AREA Community, Town or Cit	<u>s</u> _
(Davis Water	System)		STATE OF MISSO	ÜRI
	SCHEDULE OF S CAPE ROCK VILLAGE (C	ERVICE CHA	ARGES (Sewer) REC	EIVEO
		Company's se	ervices provided for imphe	16 1997
correspondi	ng rules:		MIS	SOUR
			Public Servi	ice Comn
<u>Disconnecti</u>	on/Reconnection:			
	ection Charge after service ny's Rules and Regulations		ion by Company for violat	ion of
Total actua	i cost of discontinuance	and reconn	ection of service.	
SERVICE C	ONNECTION:			
Char	ge for connecting to syste	em	\$ 40.00	
Actual cos	t of connection will be m	ade at Cust	omer's expense.	
	·			
LATE CHAP	RGES:			
For any	bill not paid within the pe	eriod stated t	hereon,	
a late charg	ge in the amount of \$3.00	per month, r	not to exceed	+
	hs or \$9.00 per customer,			+
	nt due plus all disconnecti costs and reasonable attor		•	
Conconon	osis and reasonable allor	neys lees lo	Concendra	
	on this tariff sheet are subj			*
	and Agreement approved			*
Commissio	n in Case Nos. WR-97-10	J aliu SR-9/	.101.	
			FILED 97-10	Û
* Indicates no	ew rate or text		APR 21 199	7
+ Indicates c			MO. PUBLIC SERVICE	COMM
<del></del>		<del></del>		
TE OF ISSUE	April 16, 1997		ECTIVEApril 21, 19	0.7

Cape Rock Village Income Statement- Sewer Informal Rate Case

	DESCRIPTION	COMPANY	STAFF	DIFFERENCE
A-2	Accounting Fees	1,565	1,147	-418
B-2	Legal Fees	1,235	153	-1,082
	Annual Registration	106	106	•
C-2	business insurance	1,136	1,245	109
	Certification	121	121	-
	Chemicals	125	125	-
D-2	Depreciation Expense	5,679	6,583	904
E-2	Misc. Assessment	56	62	6 7
	DNR-Water Testing	200	200_	^ ^
F-2	Electricity Expense	7,129	6,283	-846
G-2	Employee Health Insurance	334	353	19
H-2	Freight/Postage/Pitney Bowes	825	1,070	245
1-2	Misc.	891	835	-56
J-2	Loan Payments-Ann Rudy	2,100	0	-2,100
K-2	Office Supplies	211	235	24
L-2	Officer Salaries	2,835	3,989	1,154
M-2	Operating Supplies	433	0	-433
N-2	Outside Services	22,094	0	-22,094
	Outside Services- Mowing	1,180	1,180	•
0-2	Pager	111	121	10
P-2	Payroli Taxes	4,645	1,762	-2,883
Q-2	Payroll-Billing Expense	5,014	7,371	2,357
R-2	Payroll-Operator Expense	7,270	7,080	-190
	Permit	3,000	3,000	-
S-2	PSC Assessment	3,045	3,589	544
T-2	Real Estate Taxes	140	142	2
U-2	Rent	1,005	1,405	400
V-2	Repairs & Maintenance & R.M. Pay	7,131	11,313	4,183
W-2	Amortization of Repair & Maint.	5,290	1,058	-4,231
X-2	Telephone Expense	790	870	80
Y-2	Vehicle Expense	725	804	79
	Water	258	258	-
	Total Expenses	86,680	62,460	-24,218
	Total Revenues	57,547	57,547	
	Late Fees		1,503	
	Net Income (Loss)	29,134	3,410	
	Revenue Requirement	•	5,101	
	Net Revenue Requirement- Sewer	<del></del> -	8,511	

## 2002 Informal Rate Case Cape Rock

#### Rate Base for KMB

Total Plant in Service	\$ 102,962.00
Less: Depreciation Reserve	\$ 63,068.00
Rate Base	\$ 39,894.00
Less: Customer Contribution in Aid of Construction (overcollected -customer contribution	\$0.00
(ovorconcoted editioned continuation)	\$ 39,894.00
ROR-Equity (Rate Base 39,894 x 8.80 Equity Return Factored for	\$ 3,513
Taxes) ROR-Debt (Rate Base 39,894 x 3.98 ROR Debt)	\$ 1,588
Revenue Requirement	\$ 5,101

•		
KMB 2002 Informal Rate Case		
Adjustment Summaries Cape Rock Village		
Accounting Fees		
Company	1,565	
Staff ^(\$3,574*30.68%) Staff Accounting Fees Adjustment	1,147	A-2
Legal Fees	<del> </del>	
	1,235	
Company		
\$taff ^(\$500*30.68%)	153	
Staff Legal Fees Adjustment	(1,082)	B-2
Business Insurance		
Company	1,136	
Staff	1,245	
^(4058*30.68%) Staff Business Insurance Adjustment	109	C-2
Depreciation Expense		
	r 070	
Company	5,679	
Staff	6,583	
Staff Depreciation Expense Adjustment	904	D-2
Miscettaneous Assessment Adjustment		
Company	56	
Staff	62	
^(\$200.90*30.68%) Mo Rual Assessment Staff Miscellaneous Assessment Adjustment	6	E-2
·		
Electricity Expense		
Company	7,129	
Staff Calculation was based on the rate of reduction provided by AmerenUE	6,283	
(7.14%) * by the Company's energy charges, excluding the service charges which remain unchanged.		
Staff Electricity Expense Adjustment	(846)	F-2
Employee Health Insurance		
Company	334	
Staff	353	
Covers Dannie only- #(\$1192*29.61%)	19	G-2
Staff Employee Health Insurance Adjustment	19	<b>G-2</b>

Freight/Postage/Pitney Bowes

Staff
^(\$3460.80\*30.68%)
Staff Freight/Postage/Pitney Bowes Adjustment

Removed Distributions for Ann Rudy and recategorized them

under Loan Payments-Ann Rudy
Most of the dollars included in Miscetlaneous went into Repairs & Maint.
or were reimbursements for expenses
Staff Misc. Adjustment

Company

Misc.

Company

825

1,070 245

891

835

(56)

G-2

H-2

Company	1,820	
Staff This loan payment will be captured in the Company's rate of return Staff Loan Payments-Ann Rudy Adjustment	(1,820)	J-2
Office Supplies		
Company	211	
Staff 1/\$765°30.68%) Staff Office Supplies Adjustment	235	K-2
Officer Salaries		
Company	2,835	
Staff (\$13,000*30.68%) Staff Officer Salaries Adjustment	3,989 1,154	L∙2
Opperating Supplies		
Company	433	
Staff	0	
Costs in this category were either put into Repairs & Maintenance Costs associated with Tim McKenna were disallowed Staff Outside Services Adjustment	(433)	M-2
<u>Qutside Services</u>		
Company	22,094	
Staff Costs In this category were either put into Repairs & Maintenance Costs associated with Tim McKenna were disallowed Staff Outside Services Adjustment	(22,094)	N-2
Pager		
Company	111	
Staff	121	
\(\sum_{\sum_305.73^30.68\%\)} Staff Pager Adjustment	10	0-2
Payroil-Taxes		
Company	4,645	
Staff	1,762	
(670.86(Donnie)+702.72(Vicki)+(Ann's)388.15) based on Annualizad Salary Amounts Staff Payroll-Taxes Adjustment	(2,883)	P-2
Payroll-Billing Expense		
Company	5,014	
Staff Annualized Salary to \$24,024 ^(\$24,024*30.68%)	7,371	
Staff Payroli-Billing Expense Adjustment	2,357	Q-2
Payroll-Operator Expense		
Company Annualized Salary to \$32,000 ^(\$32,000*30.68%) Staff	7,270 7,080	
Staff Payroll-Operator Expense Adjustment	(190)	R-2
PSC Assessment Expense		
Сотрепу	3,045	
Staff	3,589	
\\$498.29*20.19%)PSC Amount X Allocation % Staff PSC Assessment Adjustment	544	S-2

#### Real Estate Taxes

Company	140	
Staff  '(\$121.71+\$20.01)- Real Estate and Personal Property Tax Staff Real Estate Taxes Adjustment	142	T-2
Rent		
Company	1,005	
Staff (\$4,580*30.68%) Staff Rent Adjustment	1,405 400	U-2
Repairs & Maintenance & R.M. Payable		
Company	7,131	
Staff	11,313	
Staff Repairs & Maintenance Adjustment	4,183	V-2
Amortization of Repair and Maintenance		
Company	5,290	
Staff	1,058	
Staff Amortization of Repairs & Maintenance Adjustment	(4,231)	W-2
Telephone Expense		
Company	790	
Staff ^(\$2,835~30.68%)	870	
Staff Telephone Expense Adjustment	80	X-2
Vehicle Expense		
Company	725	
Staff ^(\$2,619*30.66%) Staff Vehicle Expense Adjustment	804 	Y-2

### Summary Overview of KMB Utility Corporation Customer Service Operations for Water and Sewer

The Engineering and Management Services Department (EMSD) staff initiated a review of customer service processes, procedures and practices at KMB Utility Corporation (KMB or Company) on September 26, 2002. Prior to on-site interviews, the EMSD staff examined Company tariffs, annual reports, Missouri Public Service Commission (Commission) complaint records and other documentation related to the Company's customer service operations.

The objectives of this review were to document and analyze the management control processes, procedures and practices used by the Company to ensure that its customers' service needs are met and to make recommendations, where appropriate, by which the Company may improve the quality of services provided to its customers. The scope of this review focused on processes, procedures and practices related to:

- Meter Reading
- Customer Billing
- Credit and Collections
- Complaint Handling and Recording
- Customer Communications

This overview contains an explanation of the Company's customer service operations.

#### Overview

KMB provides water service to approximately 313 customers in six subdivisions in Franklin and Jefferson Counties, and sewer service to approximately 187 customers in Cape Girardeau County.

The Company's primary office and field reporting locations are based out of the business office in House Springs. The office manager is responsible for the business office function and the plant operator is responsible for the daily operation of the water system. The office manager and the plant operator report to the president of the Company.

According to the Company, there has been minimal customer growth throughout most of its service territory during the last few years. The office manager stated that there has been customer growth in the Company's High Ridge subdivision, primarily from new construction.

#### Meter Reading

The plant operator reads the water meter for High Ridge Manor and Lakewood Hills customers each month. The office manager stated that the customer is responsible for reading the meter each month in Crestview Acres and Hillshine Acres. Scotsdale and Warren Woods meters are not typically read as those customers are charged a flat rate.

The High Ridge Manor and Lakewood Hills meters are read around the 28<sup>th</sup> of each month. The Crestview Acres and Hillshine Acres customers read their own meter around the first of each month. The office manager stated that the Company has not read individual customer meters since at least 1997 for its Crestview Acres, Hillshine Acres, Scotsdale and Warren Woods customers.

The office manager provides the plant operator with a meter reading worksheet that contains the route to be read. The worksheet lists the customers in route sequential order and contains the account number, name, address, meter location, meter number, the reading for the last quarter, and a space for the current reading to be recorded.

The office manager stated that it takes the plant operator about six hours to read the Company's meters each month. The office manager enters the meter reads into the billing system the next day and bills are generated the same day.

#### **Customer Billing**

KMB bills its water customers on a monthly basis. Customer bills are normally generated every 27 to 33 days, which is consistent with the Company's tariff. Customer bills are typically mailed to customers around the first of the month.

The Company has five separate water rate schedules within the six subdivisions that it serves. The following table lists each subdivision, the customer base rate, the usage or commodity charge per 1,000 gallons, and the monthly bill based on a monthly usage of 6,000 gallons:

Water Service Area	Base rate	Rate/1,000 gal	Charge
Crestview Acres	\$10.14	\$2.00	\$22.14
Hillshine Acres/Lakewood Hills	\$ 9.41	\$2.21	\$22.67
High Ridge Manor	\$ 9.41	\$3.05	\$27.71
Scotsdale	\$31.49	flat rate	\$31.49
Warren Woods	\$31.54	flat rate	\$31.54

The Company bills each water and sewer customer on a monthly basis. The Company does have one billing feature that very few other PSC-regulated water and sewer utilities have. According to the office manager, some of KMB's customers have bills that are due approximately 30 days after the end of a usage period while other customers have bills that are due approximately 60 days after the end of a usage period.

The office manager stated that bills are due within 30 days for customers that live in High Ridge Manor, Lakewood Hills, Scotsdale and Warren Woods. According to the office manager, August water usage is billed around September 1 and is due around September 30.

The office manager stated that bills are due within 60 days for customers that live in Crestview Acres and Hillshine Acres. According to the office manager, the actual water usage for August is read by the customer around September 1. The customer sends in the August meter reading along with the amount owed for the actual July usage in early September.

KMB will then calculate the bill for August usage around September 30 and mail the customer a bill for the August usage around October 1. Those customers will have until October 30 to remit the amount owed for August usage and to send in the actual meter read for September. The 60-day cycle continues for each month.

The Company's sewer customers are located primarily in and around the Cape Rock Village mobile home park in Cape Girardeau County. Customers living in singlefamily dwellings or in mobile homes located outside of the mobile home park are charged a flat monthly rate of \$23.10. Customers living in multiple-family dwellings or in mobile homes located inside the mobile home park are charged a flat monthly rate of \$36.96.

The automated billing system was included as part of the current owner's purchase of a sister utility (Cedar Hill Estates Water Company) in April 2001. The office manager stated that paper billing records exist for KMB water and sewer customers dating back to the mid-1990s. A nominal annual software maintenance fee is paid to the vendor to keep the billing system current.

#### **Credit and Collections**

The Company's credit and collection activities are managed through the business office in House Springs. The office manager stated that customers primarily pay their bill by personal check through the mail. Customer payments are posted to the billing system as they are received. The payments are stored overnight in the office manager's unlocked desk drawer and are deposited in the bank on a weekly basis.

The office manager stated that the level of bad debt is reasonable, and that written delinquent notices are not typically used for customers with past due balances. The current policy is for the office manager to call customers to remind them of past due amounts.

The Company's tariff permits a \$50 fee to be charged for service reconnection as well as a late fee of \$3 per month. However, the Company does not charge for handling an insufficient funds check that is returned by the bank other than the \$5 fee that the bank charges the Company.

### **Complaint Handling and Recording**

KMB has experienced few complaints since 1998. The Company's policy is to have the complaint addressed by the appropriate personnel as soon as possible. If the complaint is related to a field activity, the plant operator is dispatched to investigate and resolve. If the complaint is related to a billing or payment concern, the office manager is usually is able to resolve the matter.

#### **Customer Communications**

The KMB business office is open Monday through Friday from 8 a.m. to 5 p.m. KMB customers can contact the business office in House Springs on a 24/7 basis, as after-hours calls are handled by the office manager's pager.

The Company mailed a letter to each customer in September 2002 that described the current request for rate relief. According to the office manager, the Company has received few written complaints since customers were notified.

#### Findings, Conclusions and Recommendations

The following discussion presents a summary of the findings, conclusions and recommendations pertaining to the Company's customer service operations. The information presented in this section focuses on the following three areas that require management's attention:

- Lack of appropriate charges for returned checks
- Lack of timely deposit of customer receipts
- Lack of secured storage area for customer receipts

#### Lack of appropriate charges for returned checks

The Company does not charge a fee to process checks returned from the bank for insufficient funds other than the \$5 fee that the bank charges the Company. The fees should be priced at a level that is reasonable, yet discourages the customer from submitting insufficient funds checks.

The EMSD staff recommends that the Company review the actual costs to process returned checks. The costs that should be considered include the fully loaded wages and benefits of office personnel, as well as the fees charged by the bank. The Company should also consider the fee that area merchants charge for returned checks.

The EMSD staff has found that several regulated Missouri utilities charge approximately \$15 - \$20 to handle returned checks. A tariff should be filed with the PSC to recover these costs after the Company has determined the appropriate amount to charge for processing returned checks.

THE EMSD STAFF RECOMMENDS THAT COMPANY MANAGEMENT:

Determine the appropriate cost to charge for processing returned checks.

File a tariff with the PSC to recover the appropriate costs associated with processing returned checks.

#### Lack of timely deposit of customer receipts

The Company does not deposit customer receipts into the bank on a timely basis. The office manager stated that cash receipts are typically deposited each Thursday. At the time of the EMSD staff review, the office manager stated that there was about \$800 in customer checks that were stored in an unlocked desk drawer.

The EMSD staff believes that bank deposits should be made on a timely basis. The frequency of deposits being made can vary, but should be made at least twice per week.

THE EMSD STAFF RECOMMENDS THAT COMPANY MANAGEMENT:

Make bank deposits on a more timely basis.

#### Lack of secured storage area for customer receipts

The Company does not store customer receipts overnight in a secured storage area. According to the Company, cash receipts are stored overnight in a bank bag that is kept in an unlocked desk drawer.

The EMSD staff believes that customer receipts should be stored in a locked fireproof vault. The EMSD staff observed that there is a locked fireproof vault about 15 feet from the office manager's desk. The locked fireproof vault is an appropriate place for overnight storage of customer receipts.

THE EMSD STAFF RECOMMENDS THAT COMPANY MANAGEMENT:

Store customer receipts overnight in a locked fireproof vault.

# **Staff Report on Service Complaints**

KMB Utility Corp.
Case No. QW 2003 0009 Water
Case No. QS 2003 0010 Sewer
Prepared by Steve Loethen
February 7, 2003

## Customer Responses to Initial Customer Notice:

Note: Cape Rock Village is the only sewer system, the rest are water.

#### Cape Rock Village service complaints:

Karen Weaver 2433 Singing Hills Cape Girardeau, MO 63701 573-334-1362

Phil Denson 2541 Hilltop Lane Cape Girardeau, MO 63701 573-334-6936 Urlsula Wadley 2545 Hilltop Cape Girardeau, MO 63701 573-651-9020

Juanite Brown
1206 Valley Lane
Cape Girardeau, MO 63701
573-651-4478

All four of these customers had complaints of odor problems from the lagoon.

Mr. Denson also has had poor contacts with the company, states no one is there or returns his messages.

Water and Sewer Staff' findings (Steve Loethen and Arlie Smith): Arlie Smith (with the water and sewer department) visited the facilities on 10/17/02 and there was an odor problem at the lagoon specifically around the effluent pipe. There was a considerable amount of duckweed on the lagoon, which can cause a septic condition and create odors. Also, the transfer pipe from the second to the third cell appeared to be clogged. Arlie suggested the company add run time to the aerators, control the duckweed and unclog the transfer pipe. The company increased the run time immediately and unclogged the transfer pipe on November 7, 2002. Arlie returned to that facilities on December 2<sup>nd</sup> and the odors have already diminished greatly.

I talked to the Company and suggested they purchase a dissolved oxygen meter and a Ph meter to help them better operate the system. The Company purchased the meters and has requested my assistance in improving operations in general and to help them set up a program to control duckweed. I will set up a time with the company in the early spring to help them with these issues.

I have no problem contacting the Company at the number that is posted on the bill. Also, if there is no one in the office, there are other numbers on the answering machine to call. I will talk to the Company about customer relations and how it important is to return customer calls.

### **Crestview Acres service complaints:**

Mark Brumley 3869 Jeanette Ave. Pacific, MO 63069 314-423-0558 ext. 123

Mr. Brumley states the company needs to repair meters, 50% don't work. If meters were correct the company wouldn't need a rate increase.

Water and Sewer Staff's findings (Steve Loethen): I visited Mr. Brumley's home on 10/4/02 and left messages on his answering machine, I have not talked to him in person. I question how Mr. Brumley would know if the company's meters are accurate? The Company knows of two meters that are bad and they are both on order to be replaced. The master meter was broke at the time of my inspection. I suggested the Company get the master meter fixed and check the percent of water loss in the system. This would show if the meters are working properly. I also suggested that if there are broken meters in the system they should be fixed.

#### High Ridge Manor service complaints:

Mary Riedler 4306 Arrow Head Place House Springs, MO 63051 636-671-1680 Sharon King 5823 Parkway House Spring, MO 63051 636-671-5403 (# disconnected)

These two customers stated the water quality is poor.

Water and Sewer Staff's findings (Steve Loethen): Mrs. Riedler complained of the water hardness. I have not talked to Mrs. King personally, she was not home on 10/4/02 and the phone number that I have for her is disconnected. I explained to Mrs. Reidler that the water hardness is not regulated. I also checked with the Department of Natural Resources, the company had a coliform positive sample (which is an indicator and doesn't necessarily mean the water was bad) in June and July of 2000. Both were re-sampled and the re-samples were O.K. The water meets DNR requirements. It is my opinion that there is nothing wrong with the water quality.

#### Lakewood Hills

Steve Rufer #37 Hillside Drive Pacific, MO 63069 636-938-4373

Mr. Rufer stated that in the summer when everyone is watering their lawns they have low water pressure and have been completely out.

Water and Sewer Staff's findings (Steve Loethen): I talked to Jim Merciel (an engineer in the water and sewer department) about this issue on 2/6/03. He looked at the capacity of the system and said that there is adequate storage, but it is possible a high demand may cause low-pressure problems because of lack of water volume depending on the sizes of the mains. The company did state that they suggest customers be conservative during watering season. This problem only seems to occur during excessively high demands, I will continue to investigate this issue and if it becomes a reoccurring problem the Company may consider installing a bigger main.

Dennis Copenhaver 9 Dogwood Trails Pacific, MO 63069 636-271-7764

Mr. Copenhaver states that he has low water pressure, he feels it is a volume issue (can't use multiple fixtures at the same time).

Water and Sewer Staff's findings (Steve Loethen): I visited Mr. Copenhaver's house on 10/4/02. I installed a pressure gauge on an outside water faucet. I then had Mr. Copenhaver run the faucet in the kitchen and flush the toilet. My pressure gauge dropped from 58 psi to 38 psi with two fixtures running. This is still very good water pressure. The water company stated that they have replaced several hundred feet of ¾ inch main with 2 inch main to Mr. Copenhaver's house. I feel the company is providing safe and adequate service.

George Kirk 50 Wildwood Drive Pacific, MO 63069 636-271-3420

Mr. Kirk stated that the water is hard and he has low water pressure. He has a booster pump in his home. There used to be a booster pump on the main but it was taken out of service.

Water and Sewer Staff's findings (Steve Loethen): I explained to Mr. Kirk that the water system is not regulated on hardness. I talked with Jim Merciel (an engineer in the water and sewer department) about the pressure issue on 2/6/03. He looked at the capacity of the system and said that there is adequate storage, but it is possible a high demand may cause low-pressure problems because of lack of volume depending on the sizes of the mains. He also stated that this complaint has been investigated in the past and the pressure in this area is marginal as to being adequate. This has been a problem prior to KMB owning the system. I will continue to investigate this problem and if the pressure is

dropping below minimum (20 psi) I will suggest the company install or fix the booster station to this area.

#### **Scottsdale**

John Caola 6994 Bonanza Drive House Springs, MO 63051 636-671-0926

Mr. Caola had a complaint that a fire hydrant was removed.

Water and Sewer Staff's findings (Steve Loethen): When I talked to Mr. Caola on 2/4/03 he stated that he didn't have any problems with the company. Mr. Caola's response was "the new folks are doing better". As for the company removing a fire hydrant, I talked to them on 10/4 about this issue, they informed me that it was leaking and the cost to fix it would have been more expensive than the benefit of having the hydrant. The hydrant was a "flush" hydrant and not for fire protection. I don't see anything wrong with the company's actions as long as adequate flushing can still be performed on the system without this hydrant.

#### Warren Wood

Petition signed by 19 customers

Stated most of the time the water is undrinkable because of over chlorination and that the water is not metered in gallons.

Water and Sewer Staff's findings (Steve Loethen): I talked to Donnie the new operator at KMB (hired 5/14/02) about this issue. He informed me that he has contacted DNR and is adjusting the chlorine level until it is at DNR's recommended level. It was 2.1 (total) at the time of my inspection, which is not excessive. I feel that Donnie will continue to work on the problem until it is fixed. I will suggest the company install meters in the system. It doesn't matter if the meters measure in cubic feet or gallons as long as the system is metered.

Heather Trolinger 5924 Roger Road House Springs, MO 63051 636-677-4677

Mrs. Trolinger had complaints of the water smelling like rotten egg and chlorine. It is discolored and undrinkable. She also had a problem with her line freezing and breaking.

Water and Sewer Staff's findings (Steve Loethen): I checked with the Department of Natural Resources, the company had a coliform positive sample (which is an indicator and doesn't necessarily mean the sample was bad) in March of 2000 and October of 2002, both were re-sampled and the re-samples were O.K. The water meets DNR requirements. As stated above Donnie is working on the chlorine problem. When the chlorine is at the proper level, it should take care of any hydrogen sulfide smell (rotten egg smell). I will follow up on this complaint. The Company may need to flush the system more often. Mrs. Trolinger stated that the line freezing wasn't a problem anymore.

Mary McGuire 3706 Leona Lane House Springs, MO 63051

Mrs. McGuire stated that she has low water pressure but it is not all the time. Stated that when her neighbors use their water her water pressure drops. Because it doesn't do it all the time it is hard for me to see what the problem is. There are several homes on this water main and I didn't receive any other complaints of this nature. Because of this, I believe Mrs. McGuire may be experiencing some plumbing problems in her home. I informed Mrs. McGuire to contact me the next time she is experiencing this problem. I will continue to investigate this complaint to locate where the problem is. Mrs. McGuire also stated that the system should be metered. There are some meters on this system; I am going to suggest to the company that meters should be installed.

Summary: On 10/4/02 I inspected the systems that KMB operates along with Arlie Smith who has been doing the previous inspections on the systems. KMB is under new owner ship and hired a new operator in May. Under this new ownership and management a lot of improvements have been done to the systems. The new operator seems to know what he is doing and is taking the necessary steps to improve the systems. Arlie stated the systems were in better condition now than on any previous inspections. There are improvements that still need to be done, the Company seems to be aware of this and has plans in place to make necessary improvements to the systems. They have worked with the water and sewer staff by making improvements suggested by staff in a timely manor. It is my opinion that the company is doing a good job, they are providing safe and adequate service and they will continue to improve service.

# KMB UTILITY CORP. DEPRECIATION RATES

# (SEWER)

# FILE NO. SW-2003-0010

	MBER ACCOUNT	DEPRECIATION RATE %	AVERAGE SERVICE LIFE (YEARS)
363	Pumping Equipment Oxidation Lagoons	10.0%	10
372		2.0%	25
391.1	Office Computer Equipment Transportation Equipment	14.3%	7
392		12.5%	8
394	Tools, Shop, Garage Equipment	5.0%	20

#### CALCULATION OF EFFECTIVE TAX RATE

FIT · SIT		.15(TI-SIT) .0625*(TI-FIT)
FIT	<b>3</b> .	[TI(10625TI+TI(.0625FIT)]
FiT	=	.15(.9375TI+.0625FIT)
FIT	≖ .	.140625TI+.009375
.990625FIT	=	.140625TI
FIT	=	14.20%
SIT		.0625(1-(.1420TI*.50))
SIT	=	.0625(.929TI)
SIT	=	5.81% TI
FIT	~	(1-SIT)*.15
FIT	=	(10581)*.15
FIT	=	14.13% T!
FIT SIT	= =	14.13% 5.81%
EFFECTIVE TAX RATE	<b>.</b>	19.93%
TAX FACTOR UP CALCULATION		4
1 1-EFFECTIVE TAX RATE	<del></del>	1 = 1.248907 11993
EQUITY *TAX FACTOR UP	·	7.05% 1.248907
TAX FACTORED UP EQUITY RETURN		8.80%

CALCULATION OF EFFECTIVE TAX RATE

# KMB Utility Informal Rate Case Phone Expense

# Ameritech - Pagers

	Current	Late Fees	Total
Aug '01	36.93	0.00	36.93
Sep	40.85	0.00	40.85
Oct	30.90	0.00	30.90
Nov	30.90	0.00	30.90
Dec	30.90	0.00	30.90
Jan '02	30.90	0.00	30.90
Feb	30.90	0.00	30.90
Mar	39.85	0.00	39.85
Apr	30.90	0.00	30.90
May	30.90	0.00	30.90
Jun	30.90	0.00	30.90
Jul	30.90	0.00	30.90
Total	395.73	0.00	395.73

# AT&T

	Current	Late Fees	Total
Aug '01	21.57	0.00	21.57
Sep	23.68	0.00	23.68
Oct	13.81	0.00	13.81
Nov	13.79	0.00	13.79
Dec	15.46	0.00	15.46
Jan '02	34.18	0.00	34.18
Feb	32.90	0.00	32.90
Mar	15.89	0.00	15.89
Арг	15.03	0.00	15.03
May	26.88	0.00	26.88
Jun	32,23	0.00	32.23
Jul	32.28	0.00	32.28
Total	277.70	0.00	277.70

## Nextel

	Phone Charge	Staff Charge	Tax	Company Paid	Late Fees	Total
Aug '01	84.56	2.19	8.47	95.22	0.00	95.22
Sep	53.54	12.04	6.41	71.99	0.00	71,99
Oct	52.50	23.80	7.45	83.75	0.00	83.75
Nov	52.75	21.00	7.20	80.95	0.00	80.95
Dec	60.71	7.91	6.73	75.35	0.00	75.35 *
Jan '02	85.61	0.00	0.00	85.61	0.00	85.61
Feb	61.10	6.09	6.59	73.78	0.00	73.78
Mar	60.04	11.87	7.05	78.96	0.00	78.96
Apr	60.61	8.29	6.75	75.65	0.00	75.65

May	61.10	5.38	6.52	73.00	0.00	73.00
Jun	60.71	7.91	6.73	75.35	0.00	75.35 *
Jul 🕒	60.71	7.91	6.73	75.35	0.00	75.35 *
Total				944.95	0.00	944.95

<sup>\*</sup>Used an average based on Feb 2002 - May 2002

## Southwestern Bell

	Current	Late Fees	Total
Aug '01	130.68	0.00	130.68
Sep -	130.69	0.00	130.69
Oct	140.49	0.00	140.49
Nov	134.65	0.00	134.65
Dec	77.96	0.00	77.96
Jan '02	145.03	0.00	145.03
Feb	135.13	0.00	135.13
Mar	157.82	0.00	157.82
Арг	128.87	0.00	128.87
May	146.19	0.00	146.19
Jun	152.17	0.00	152.17
Jul	133.28	0.00	133.28
Total	1612.96	0.00	1612.96

# KMB Utility Informal Rate Case

PSC Asse	essment		Allocated
·	Amount	Allocation	Amount
CHE	48.29	100.00%	48.29
CRV	3588.91	100.00%	3588.91
CVA	498.29	16.72%	83.31032
HRM	498.29	20.19%	100.6011
HSC	498.29	9.15%	45.58489
LWH	498.29	35.33%	176.052
SCT	498.29	11.67%	58.16003
WWS 1	498.29	6.94%	34.58164
Total		,	4135.49

KMB Utility Informal Rate Case Personal Property and Real Estate Taxes

System	Real Estate Tax	Personal Property Tax
Cedar Hill	893.24	16.37
Cape Rock	121.74	20.01
Crestview Acres	37.72	4.82
High Ridge	741.09	5.82
Hillshine	23.34	2.64
Lakewood Hills	0	10.19
Scotsdale	338.24	3.37
Warren Woods	359.93	2.00
Totals	2515.30	65.21

KMB Utility Informal Rate Case

Misc. Expense Reimbursement

Date	Description	Fuel	Lodging
8/13/2002	Gas T-Rex	8.32	
6/7/2002	Rhodes 101 Stop-Gas	6.01	
5/3/2002	Ace Hardware/Buchheit		
4/4/2002	Texaco-Gas	20.96	
4/8/2002	Sears/True Value/Buchheit	•	
3/27/2002	Walmart-Batteries		
1/14/2002	Walmart-Misc. Cleaning Products		
12/13/2001	County Decorating-Paint		
12/13/2001	Hood's-Misc Painting stuff		
12/5/2001	Hood's/Lewis Electric Motor		
10/12/2001	Hood's		
10/3/2001	Buchheit		
9/17/2001	Buchheit	•	
8/14/2001	Rhodes 101 Stop-Gas	15.83	
7/9/2001	Buchheit		
6/6/2001	Walmart/Buchheit		
5/30/2001	Walmart/Buchheit		
4/30/2001	Outside Labor - Sam Allison		
4/20/2001	Pacific Lumber/Hood's		
3/26/2001	R&S MiniMart		
3/23/2001	Buchheit		
3/12/2001	Buchheit		
	The Family Center Rent's It - Backhoe attachment		
1/3/2001	Hood's - Door for HSC		
11/22/2000	Hill Behan - Nails		
11/16/2000	Paul Piffel Exp. Reimbursement	40.00	43.14
8/10/2000	Jan Dowell Exp. Reimbursement		•
3/4/2000	Scott Robart - Exp. Reimbursement	270.41	
3/4/2000	Scott Robart - Exp. Reimbursement	177.43	
2/9/2000	Scott Robart - Exp. Reimbursement	209.37	
	TOTALS	748.33	43.14

Category

	Office	Travel				
Rep/Maint.	Supplies	Rep/Maint.	Misc.	Tools	Outside Labor	TOTAL
					•	8.32
						6.01
				13.82	13.82	27.64
						20.96
20.09			15.78		å	35.87
			11.03			11.03
			8.84			8.84
			42.30			42.30
			23.82			23.82
			31.80			31.80
				27.88	27.88	55.76
121.42						121.42
177.20						177.20
					•	15.83
31.81						31.81
			18.80	72.31	72.31	163.42
58.61			54.47			113.08
					80.00	80.00
•			47.06			47.06
			6.31			6.31
42.86						42.86
89.51						89.51
•				44.82		44.82
85.37						85.37
			6.32			6.32
35.55			11.62			130.31
			175.00			175.00
			325.00			595.41
			63,44			240.87
			42.2			251.57
662.42	0.00	0.00	883.79	158.83	194.01	2690.52

### KMB Utility Informal Rate Case Electric Expense

### Cedar Hill Estates

	Current	Sales Tax	Late Fees	Total
Aug '01	194.4	11.13	0.00	205,53
Sep	197.11	11.28	0.00	208,39
Oct	131.44	7.52	0.00	138,96
Nov	137.17	7.85	0.00	145.02
Dec	144.03	6.25	0.00	152,28
Jan '02	198.37	11.36	0.00	209.73
Feb	199.34	11.41	0.00	210.75
Mar	215.86	12.36	0.00	228.22
Арг	213.51	12.22	0.00	225,73
May	136.65	7.82	00.00	144.47
Jun	157.56	9.02	0.00	166.58
إلنال	176.74	10.12	0.00	186.86
Total	2102.18	120.34	0.00	2222.52
	Less: U.E.	Customer C	Charge	181.20
	Sub Total	2041,32		
	Less: Pem	145.75		
	TOTAL			1895.57

### Cape Rock Village

	CRV Lift Station			
	Current	Sales Tax	Late Fees	Sub Total
Aug '01	222.68	10.52	0.00	233.20
Sep	227.71	10.76	0.00	238,47
0dt	132.09	6.24	0.00	138.33
Nov	155.00	7.32	0.00	162.32
Dec	177.26	8.38	0.00	185.64
Jan '02	210.27	9.94	0.00	220.21
Feb	317.19	14.99	0.00	332.18
Mar	381.05	18.00	0.00	399.05
Apr	399.68	18.88	00,00	418.56
May	376.28	17.78	0.00	394.06
Jun	595.73	28.15	0.00	623.88
Jul	200.23	9.46	0.00	209.69
Sub Total	3,395,17	160.42	0.00	3,555.59
	Less: U.E.	Customer C	harge	181.20
	Sub Total 3,374.39			
	Less: Permanent Rate reduction 240.93			
	Sub Total			3,133.46

CRV - Lagoons (B & H)				
Current S	ales Tax La	ite Fees	Sub Total	
464.94	21.97	0.00	486.91	
508.80	24.04	0.00	532.84	
317.19	14.99	0.00	332,18	
361.66	17.09	0.00	378.75	
486.83	23.00	0.00	509.83	
260.37	12.30	0.00	272.67	
153.73	7.26	0.00	160.99	
126.79	5.99	0.00	132.78	
127.58	6.03	00.0	133.61	
137.97	6.52	0.00	144.49	
229.87	10.86	0.00	240.73	
236.26	11.16	0.00	247.42	
3,411.99	161,21	0.00	3,573.20	
Less: U.E. Customer Charge181,20				
Sub Total	3,392.00			
Less: Permar	242.19			
Sub Total			3,149.81	

	CRV-T	otal				
Current	Sales Tax Li	ste Fees	Sub Total			
687.62	32.49	00.0	720.11			
736.51	34.80	0.00	771.31			
449.28	21.23	0.00	470.51			
516.66	24.41	0.00	541.07			
664.09	31.38	0.00	695.47			
470.64	22.24	0.00	492.88			
470.92	22.25	0.00	493.17			
507.84	23.99	0.00	531.83			
527.28	24.91	00.0	552.17			
514.25	24.30	0.00	538,55			
825.60	39.01	0.00	864,61			
436.49	20.62	0.00	457,11			
6,807.16	321.63	0.00	7,128,79			
Less: U.E.	Customer Ch	arge _	362.40			
Sub Total	Sub Total 6,766.39					
Less: Perm	Less: Permanent Rate reduction483.1					
TOTAL		_	6,283,27			

### Crestview Acres

	Current	Sales Tax	Late Fees	Total
Aug '01	93.70	5.13	0.00	98.83
Sep	96.50	5.28	0.00	101.78
Oct	58.57	3.21	0.00	61.78
Nov	61.13	3.35	0.00	64.48
Dec	70,92	3,88	0.00	74.80
Jan '02	87.38	4.78	0.00	92,16
Feb	89.48	4.90	0.00	94.38
Mar	96.93	5.31	0.00	102,24
Apr	86.45	4.73	0.00	91.18
May	73.65	4.03	0.00	77.68
Jun	88.43	4.84	0.00	93.27
Jul	95.30	5.22	0.00	100.52
Total	998,44	54.66	0.00	1053.10
	Less: U.E.	Customer 0	Charge	87.00
	Sub Total 966.10			
	Less: Permanent Rate reduction 68.98			
	TOTAL			897.12

# High Ridge Manor

•	Current Sa	les Tax La	te Fees T	otal
Aug '01	133.73	7.66	0.00	141.39
Sep	123.58	7.07	0.00	130.65
Oct	102.31	5.86	0.00	108.17
Nov	72.81	4.17	0.00	76.98
Dec	81.33	4.66	0.00	85.99
Jan '02	104.59	5.99	0.00	110.58

Feb	97.37	5.57	0.00	102.94
Mar ·	114.08	6.53	0.00	120.61
Apr	109.01	6.24	0.00	115.25
May	79.78	4.57	0.00	84.35
Jun	121.91	6.98	0.00	128.89
Jul	148.27	8.49	0.00	156.76
Total	1288.77	73.79	0.00	1362.56
	Less: U.E. Ci	istomer Cha	rge	87.00
	Sub Total		_	1275.56
	Less: Perman	ent Rate red	uction	91.07
	TOTAL		_	1184.49

### Hill Shine Community

		Sales Tax	Late Fees	Total
Aug 'O1	38.25	2.09	0.00	40.34
Sep	40.09	2.19	0.00	42.28
Oct	30.08	1.65	00.00	31.73
Nov	27.93	1.53	0.00	29.46
Dec	31.15	1.71	0.00	32.86
Jan '02	62.56	3.43	0.00	65.99
Feb	77.79	4.26	0.00	82,05
Mar	70.44	3.86	0.00	74,30
Apr	78.72	4.31	0.00	83.03
May	34.84	1.91	0.00	36.75
Jun	36.81	2.02	0.00	38.83
Juj	40.25	2.20	0.00	42.45
Total	568.91	31.16	0.00	600.07
	Less: U.E.	Customer C	Charge	87.00
	Sub Total			513,07
	Less; Perm	36,63		
	TOTAL			476.44

## Lakewood Hitis - Does not include Gem Lake

	Dogwood				1
	Current	Sales Tax	Late Fees	Sub Total	Curr
Aug '01	98.42	5.63	0.00	104.05	24
Sep	139.01	7.96	0.00	145.97	11
Oct	111.43	6,38	0,00	117.81	g
Nov	96.29	5.51	0.00	101.80	7
Dec	105.23	6.02	0.00	111.25	8
Jan '02	103.15	5.91	0.00	109.06	ę
Feb	95.64	5.48	0.00	101.12	12
Mar	81.51	4,67	0.00	86.18	11
Apr	83.72	4.79	0.00	88.51	g
May	87.29	5,00	0.00	92.29	7
Jun	104.09	5.96	0.00	110.05	14
jul	7,25	0.42	0.00	7.67	26
Sub Total	1,113.03	63.73	0.00	1,176.76	1,51
	Less: U.E.	Customer C	harge	87.00	Less:
	Sub Total			1,089.76	Sub T
	Less: Perma	anent Rate i	eduction	77.81	Less:
	Sub TOTAL		•	1,011.95	Sub T

NS Wade				
Current	Sales Tax	Late Fees	Sub Total	
243.83	13.96	0.00	257.79	
113.52	6.50	0.00	120,02	
94.03	5.38	0.00	99.41	
78.23	4.48	0.00	82.71	
85.33	4.89	0.00	90.22	
95.03	5.44	0.00	100.47	
121.87	6.98	0.00	128.85	
111.76	6.40	0.00	118.16	
98.72	5.65	0.00	104,37	
70.19	4.02	0.00	74.21	
144.28	8.26	0.00	152.54	
262.45	15.03	0.00	277,48	
1,519.24	86.99	0.00	1,606,23	
Less: U.E.	Customer (	Charge	87.00	
Sub Total			1,519.23	
Less: Perm	anent Rate	reduction	108.47	
Sub TOTAL	_		1,410.76	

	~ A-11 \		
		wood Hills	
Current	Sales Tax	Late Fees	Total
342.25	19.59	0.00	361.84
252.53	14.46	0.00	266.99
205.46	11.76	. 0.00	217.22
174.52	9.99	0.00	184.51
190.56	10.91	0.00	201.47
198.18	11.35	00.0	209.53
217.51	12.46	0.00	229.97
193.27	11.07	0.00	204.34
182.44	10.44	0.00	192.88
157.48	9.02	0.00	166.50
248.37	14.22	0.00	262.59
269.70	15.45	0.00	285.15
2,632.27	150.72	0.00	2,782.99
Less: U.E.	Customer C	harge	174.00
Sub Total	2,608.99		
Less: Perm	186.28		
TOTAL			2,422.71

### Scotsdale

	Current	Sales Tax	Late Fees	Total
Aug '01	106,99	6.66	0.00	113.65
Sep	111.30	6.93	0.00	118.23
Oct	81,01	5.04	0,00	86.05
Nov	75.46	4.70	0.00	80.16
Dec	80.53	5.01	0.00	85.54
Jan '02	90.02	5.60	0.00	95.62
Feb	112.48	7.00	0.00	119.48
Mar	103.06	6.42	0.00	109,48
Apr	94,68	5.89	0,00	100.57
May	84.88	5,28	0.00	90,16
Jun	81.82	5.09	0.00	86,91
Jul	105.79	6,59	0.00	112.38
Total	1,128.02	70.21	0.00	1,198.23
	Less: U.E.	Customer C	harge	181.20
	Sub Total		-	1017.03
		anent Rate	reduction	72.62
	TOTAL			944.41

## Warren Woods

	Current	Sales Tax	Late Fees	
Aug '01	219.78	12.58	0.00	232.36
Sep	158.34	9,06	0.00	167.40
Oct	200.29	11.47	0.00	211.76
Nov	140.99	8.07	00.0	149.06
Dec	106.07	6.07	0.00	112.14
Jan '02	127.58	7.30	0.00	134.88
Feb	144.48	8.27	0.00	152.75
Mar	118.58	6.79	0.00	125.37
Apr	127.17	7.28	0.00	134.45
May	119.06	6.82	0.00	125.88
Jun	99.15	5.68		104.83
Jul	152.91	8.75	0.00	161.66
Total	1,714.40	98.14	00.0	
	Less: U.E	. Customer (	Charge	87.00
	Sub Total			1725.54
	Less: Pem	nanent Rate	reduction	123.20
	TOTAL			1602.34

KMB Utility Informal Rate Case Legal & Accounting Costs

		ny Actual	Staff A	\djusted
	Blumenfeld, Kaplan &	Stephen Finch	Kaplan &	Stephen Finch
	Sandweiss,	& Associates,	Sandweiss,	& Associates,
SYSTEM	P.C.	inc	P.C.*	Inc.†
Cedar Hill	510.91	750	125.52	900
Cape Rock	494.03	1001.2	153.42	1,147.11
Crestview Acres	141.10	282.8	36.96	276.35
High Ridge	125.16	277.6	44.63	333.71
Hillshine	70.72	134.8	20.22	151.21
Lakewood Hills	282.90	593.2	78.10	583.99
Scotsdale	88.65	203.2	25.80	192.92
Warren Woods	53.15	107.2	15.34	114.71
	1766.62	3350.00	500.00	3700.00

Lakewood Hills Easement Bills

12/31/2001

1498.00

Blumenfeld, Kaplan & Sandweiss, P.C.

1/31/2002

526.50

Blumenfeld, Kaplan & Sandweiss, P.C.

† Estimates are based on 1) CHE: \$75/per month payments 2) KMB: \$200/month and a \$400 payment for tax prep. for KMB

*Customer Allocators	Customers	Customer Allocation	Customer Allocation no CHE
Cedar Hill	180	25.10%	
Cape Rock	220	30.68%	40.97%
Crestview Acres	53	7.39%	9.87%
High Ridge	64	8.93%	11.92%
Hillshine	29	4.04%	5.40%
Lakewood Hills	112	15.62%	20.86%
Scotsdale	37	5.16%	6.89%
Warren Woods	22	3.07%	4.10%
	717	100.00%	100.00%

<sup>\*</sup>Staff has included \$500 as normal and recurring legal expenses

KMB Utility Informal Rate Case Test Year Ending 7/31/02

Salary Allocation and

Capitalization Analysis

	a	Þ	c (*see below)	d (b*c) Reallocate	e (a+d)	f Operator's	g	ħ
	Total			G/O Hours		Reported	Staff	Staff
Total Operator Hours	Reported	General	Customer	By	Reallocated	Salary	Adjusted	Salary
Aug 1, 2001 - Jul 31, 2002	Hours	Office Hours	Allocation	Customers	Hours	Allocation	Hours	Allocation
Cedar Hill	300	102	25.10%	26	326	17.66%	330	17.90%
Cape Rock	489	102	30.68%	31	520	28.22%	546	29.61%
Crestview Acres	130	102	7.39%	8	138	7.46%	150	8.13%
High Ridge	159	102	8.93%	9	168	9.12%	105	5.69%
Hillshine	35	102	4.04%	4	39	2.12%	95	5.15%
Lakewood Hills	301	102	15.62%	16	317	17.19%	506	27.44%
Scotsdale	193	102	5.16%	5	198	10.75%	60	3.25%
Warren Woods	135	102	3.07%	3	138	7.49%	52	2.82%
General Office & Classes	102							
	1844		100.00%	102	1844	100.00%	1844	100.00%

Total Operator Capital Projects	Capitalized Hours	Reallocated Hours	Capitalization Percentage
	<del>~~~~~~</del>		
Cedar Hill	. 6	326	1.84%
Cape Rock	132	520	25.27%
Crestview Acres	17	138	12.00%
High Ridge	41	168	24.24%
Hillshine	9	39	23.00%
Lakewood Hills	41	317	12.78%
Scotsdale	22	198	10.97%
Warren Woods	10	138	7.24%
•	276	1844	•

*Customer Allocators	Customers	Customer Allocation
Cedar Hill	180	25.10%
Cape Rock	220	30.68%
Crestview Acres	53	7.39%
High Ridge	64	8.93%
Hillshine	29	4.04%
Lakewood Hills	112	15.62%
Scotsdale	37	5.16%
Warren Woods	22	3.07%
	717	100.00%

Ann's Salary = \$13,000	Ann's Annualized Salary	Ann's Salary Allocation	Ann's Allocated Salary
Cedar Hill	13,000	25.10%	3,263.60
Cape Rock	13,000	30.68%	3,988.84
Coestview Acres	13,000	7.39%	960.95
High Ridge	13,000	8.93%	1,160.39
Hillshine	13,000	4.04%	525.80
Lakewood Hills	13,000	15.62%	2,030.68
Scotsdale	13,000	5.16%	670.85
Warren Woods	13,000	3.07%	88.88
* * * ***		100.00%	13,000.00

# KMB Utility Informal Rate Case Postage Expense

Postage	25.10% CHE	30.68% CRV	7.39% CVA	8.93% HRM	4.04% HSC	15.62% LWH	5.16% SCT_	3.07% _wws	TOTAL _
Billings	496.8	607.2	146.28	176.64	80.04	309.12	102.12	60.72	1978.92
Other Mailings	15.91	50.17	12.09	14.60	6.61	25.54	8.44	5.02	138.38
Customer Notification	66.60	81.40	19.61	23.68	10.73	41.44	13.69	8.14	265.29
samples (also see testing exp)*									0
Sub Total	579,31	738.77	177.98	214.92	97.38	376.10	124.25	73.88	2382.59
Pitney Bowes Meter Lease	_ 270.68	330.83	79.70	96.24	43.61	168.42	55.64	33.08	1078.21
Total Postage Expense	849.99	1069.61	257.68	311.16	140.99	544,53	179.89	106.96	3460.80

<sup>\*</sup>There was no postage expense for sample mailings

# Postage Meter Lease Pitney Bowes

	Current	Late Fees	Total
Qtr 1 7/20/01-10/20/01	264.73	0.00	264.73
Qtr 2 10/20/01-1/20/02	264.73	0.00	264.73
Qtr 3 1/20/02-4/20/02	264.73	0.00	264.73
Qtr 4 4/20/02-7/20/02	264.73	0.00	264.73
Lease Taxes	19.29	0.00	19.29
Total	1078.21	0.00	1078.21

*Customer Allocators Cedar Hill	Customers 180	Customer Allocation no CHE
Cape Rock	220	40.97%
Crestview Acres	53	9.87%
High Ridge	. 64	11.92%
Hillshine	29	5.40%
Lakewood Hills	112	20.86%
Scotsdale	37	6.89%
Warren Woods	22	_4.10%
	717	100.00%

KMB Utility Informal Rate Case Test year ending 7/31/02 Repairs - Sorted by System & Vendor

Vendor	Description	ORG. CODED	Sry Date	Check #	Date Paid	System	Repairs	Ç/I	Outside of TYM	leter Reading	Vehicle Repairs 1	ools Mis	ic, Supp	Chemicals	Late Fees	Mowing	Misc.	System Repairs
Cedar Hill Hard	Misc.	REPAIRS	9/5/2001	1026	9/7/2001	Cedar Hill Estates	58.81											58.81
Cedar Hill Hard	Chain Proof Sq Pail	REPAIRS	9/6/2001	1029	9/17/2001	Cedar Hill Estates	25.27											25.27
Cedar Hill Hard	Misc.	REPAIRS	9/8/2001	1035	10/23/2001	Cedar Hill Estates	98.67											98.67
Cedar Hill Hard	Fuse	REPAIRS	10/29/2001	1037	11/6/2001	Cedar Hill Estates	12.67											12.67
Cedar Hill Hard	Paint & Stakes	REPAIRS	11/28/2001	1047	12/28/2001	Cedar Hill Estates	32.31											32.31
Cedar Hill Hard	Paint	REPAIRS	2/4/2002	1058	2/15/2002	Cedar Hill Estates	4.58											4.58 56.34
Cedar Hill Hard	Misc.	REPAIRS	3/12/2002	1062	3/22/2002	Cedar Hill Estates	56.34											
Mildford Supply	Misc.	REPAIRS	10/10/2001	1036	10/23/2001	Cedar Hill Estates	221.90											221.90
Piffel-Payable	Vehicle Repair		8/20/2001			Cedar Hill Estates	51.25		51.25		_							00.0 00.0
Piffe⊢Payable	Vehicle Repair		11/27/2001			Cadar Hill Estates	67.87				67.87							0.00
Pittel-Payable	Vehicle Repair	,	11/30/2001			Cedar Hill Estates	12.40				12.40							0.00
Piffet-Payable	Vehicle Repair		1/1/2002			Cedar Hill Estates	101.50				101.50							0.00
Piffel-Payable			11/14/2001			Cedar Hill Estates	7,599.45	7,599.45										0.00
Piffel-Payable	Vehicle Repair		3/14/2002			Cedar Hill Estates	68.25				68.25							0.00
Piffe⊦Payable	Meter Reading		8/20/2001			Cedar Hill Estates	150.00			150.00								157.33
Piffel-Payable	Stock Repair		4/15/2002			Cedar Hill Estates	157.33											12.25
Piffel-Payable	Equipment Repair		5/23/2002			Cedar Hill Estates	12.25											22.98
Cedar Hill Hard	Misc.	1510-operating	9/19/2001			Cedar Hill Estates	22.98											89.53
Erb Equipment	Echo Pump	1510-operating	9/7/2001			Cedar Hill Estates	89.53											0.00
Flynn Drilling	Pump misc.	1509-outside s	4/22/2002			Cedar Hill Estates	3,000.00	3,000.00								7.83		0.00
Jeffco Lawn &	Weed Eater Repair	1509-outside s	6/13/2002			Cedar Hill Estates	7.63									7.00		14.81
Cedar Hill Hard	Misc.	1595-miscellan	10/30/2001	1217		Cedar Hill Estates	14.81										19.11	
Piffel Excavaling	Uniform Cleaning	1595-miscellan	7/10/2002	1485		Cedar Hill Estates	19.11						8.16				10.11	0.00
USA Bluebook	Flags	1595-miscellan	7/12/2002			Cedar Hill Estates	8.16	4 400 00					0.10					0.00
Flynn Drilling	Pump misc.	1509-outside s	4/22/2002			Cedar Hill Estates	1,800.00	1,800.00										0.00
Flynn Drilling	Pump misc.	1509-outside s	4/22/2002	1074		Cedar Hill Estates	1,000.00	1,000.00										75.00
LeBeau & Sons	Test & Certify Backflow	1509-outside s	6/26/2001			Cedar Hill Estates	75.00											106.21
Buchheits	Roundup	1510-operating su		1020		Cedar Hill Estates	108.21 6.569.16	8,589.16										0.00
U.S. Filter	Misc.	1510-operating su	ı. 5/8/2001	1022	8/13/2001	Cedar Hill Estates		19,968.61	51.25	150.00	250.02	0.00	8.16	0.00	0.00	7.83	19.11	
Total Cedar Hill							21,443.02	10,000.01	31,29	.50.00	200.01				_		_	Aller and the second

Television	70.00	1400.72 262.33 1639.44 (639.58) 49.49 (639.58) 49.49	66.53 11.98 98.00 68.25	124.91	·	
Misc.         REPAIRS         91/42001         115         91/42001           Pipe for sast cell         REPAIRS         91/42001         115         91/42001           Aliator Motor for CRV         REPAIRS         91/42001         120         92/2002           Seal & Bearings         REPAIRS         178/2002         130         129/2002           Seal & Bearings         REPAIRS         178/2002         130         129/2002           Seal & Bearings         REPAIRS         179/2002         130         129/2002           Credit-retum of merch         REPAIRS         170/2002         130         120/2002           Vehicle Repair         FEPAIRS         410/2002         130         120/2002           Vehicle Repair         1170/2002         130         120/2002           Vehicle Repair         1170/2002         147         170/2002           Vehicle Repair         171/2002         130         170/2002           Siock Repair         170/2002         147         <	ਜੰਜਾਂ <u>-</u> 10 ਦ		66.53 98.00 98.00 69.25	124.91		
Profest First cell   REPARRS   27192002   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   1300 21482000   13	ਜੰ ਜਾਂ <u>ਪਾ</u> ਦ		65.53 11.98 98.00 68.25	124.9		
Misc.         REPAIRS         64/82/2001         1132         B/10/2002           Alrator Motor for CVP         REPAIRS         64/82/2001         120         92/20/200           Seal & Bearings         REPAIRS         1/10/2002         130         92/20/200           Seal & Bearings         REPAIRS         1/10/2002         130         92/20/200           Vehicle Repair         1/10/2002         130         92/20/200           Vehicle Repair         1/10/2002         130         92/20/200           Vehicle Repair         1/10/2002         1/10/2002         5/10/2002           Vehicle Repair         1/10/2002         1/10/2002         5/10/2002           Vehicle Repair         1/10/2002         1/10/2002         5/10/2002           Vehicle Repair         1/10/2002         1/10/2002         1/10/2002           Vehicle Repair         1/10/2002         1/10/2002         1/10/2002           Jock Control Repair         1/10/2002         1/10/2002         1/	ਦੰਦਾਂ ਹੈ ਪਾਦ		66.53 11.38 98.00 98.25	124.81		
Airator Motor for CRV         REPAIRS         GE28/2001         1200         BE28/2002           Seal & Bearings         REPAIRS         1789/2002         130         12/92/2002           Seal & Bearings         REPAIRS         1789/2002         130         12/92/2002           Seal & Bearings         REPAIRS         21/92/2002         130         12/92/2002           Seal & Bearings         REPAIRS         21/92/2002         130         12/92/2002           Vehicle Repair         11/27/2001         14/2002         14/2002         14/2002           Vehicle Repair         11/27/2001         14/2002         14/2002         14/2002           Vehicle Repair         11/27/2001         14/2002         14/2002         14/2002           Vehicle Repair         2500-0utside s         1/17/2002         14/7         17/20/200           Vehicle Repair         2500-outside s         1/31/2002         14/3         17/20/200           Vehicle Repair         2500-outside s         1/31/2002         14/3         17/20/200           Vehicle Repair         2500-outside s         1/31/2002         130         12/20/200           Vehicle Repair         2500-outside s         1/31/2002         14/3         12/20/200	∵ <del>-</del> υ + υ +		65.53 11.98 98.00 68.25	124.9		
Seal & Bearings         REPAIRS         1/29/2002         130         1/29/2002           Seal & Bearings         REPAIRS         1/19/2002         130         1/29/2003           Seal & Bearings         REPAIRS         2/19/2002         130         1/29/2003           Vehicle Rapair         REPAIRS         2/19/2002         130         1/29/2003           Vehicle Rapair         1/17/2002         148/2002         148/2002         148/2002           Vehicle Rapair         1/17/2002         14/17/2002         14/17/2002         1/17/2002         1/17/2002         1/17/2002         1/17/2002         1/17/2002         1/17/2002         1/17/2002         1/17/2002         1/17/2002         1/17/2002         1/17/2002         1/17/2002         1/17/2002         1/17/2002         1/17/2002         1/17/2002         1/17/2002         1/17/2002         1/17/2002         1/17/2002         1/17/2002         1/17/2002         1/17/2002         1/17/2002         1/17/2002         1/17/2002         1/17/2002         1/17/2002         1/17/2002         1/17/2002         1/17/2002         1/17/2002         1/17/2002         1/17/2002         1/17/2002         1/17/2002         1/17/2002         1/17/2002         1/17/2002         1/17/2002         1/17/2002         1/17/2002         1/17/2002 </td <td>ਜਾਂ <b>ਪ</b>0 ਦਾ</td> <td></td> <td>65.53 11.98 98.00</td> <td>124.99</td> <td>·</td> <td></td>	ਜਾਂ <b>ਪ</b> 0 ਦਾ		65.53 11.98 98.00	124.99	·	
Seal & Bearings	10 +-		65.53 11.88 98.00 98.25	124.91		
Speak of Bearings         REPAIRS         JUN2002         1320         2222020           Vehicle Repair         Vehicle Repair         4/10200         1320         222200           Vehicle Repair         1/2002001         1/2002001         4/2000         5/10200           Vehicle Repair         1/2002001         1/2002001         4/2000         5/10200           Vehicle Repair         1/2002001         1/2002001         4/2000         5/10200           Vehicle Repair         1/2002001         1/2002         5/10200         5/10200           Vehicle Repair         1/20020         1/2002         5/10200         5/10200           Pump Work         2504-cutside s         1/2000         1/3         7/22/200           Pump Work on areator         2509-outside s         2/2000         1/3         7/22/200           Pump Work         2509-outside s         2/2000         1/3         7/2/200           Pump Work         2509-outside s         2/2/2000         1/3         7/2/200           Lif Station Work         2509-outside s         2/2/2000         1/3         2/2/200           Lif Station Work         2509-outside s         2/2/200         1/3         2/2/200           Lif Station Work	n		68.53 11.18 98.00 68.25	124.9	·	
Seal a bearings         NEPARKS         4/102002         1989         4/82002           Vehicle Repair         Vehicle Repair         1/102002         5/102002         5/102002           Vehicle Repair         1/102002         1/102002         5/102002           Vehicle Repair         1/102002         1/102002         5/102002           Vehicle Repair         1/102002         1/102002         1/102002           Slock Repair         1/102002         1/102002         1/102002           Slock Repair         1/102002         1/102002         1/102002           Purp Work an areator         2504-chemicals         1/102002         1/102002           Work on areator         2509-outside s         1/82002         1/102002           Purp Work on areator         2509-outside s         1/82002         1/102002           Work on areator         2509-outside s         1/82002         1/102002           Purp Work         2509-outside s         1/102002         1/102002           Hounthly lispection         2509-outside s         1/102002         1/102002           Hounth Work         2509-outside s         1/102002         1/102002           Monthly lispection         2509-outside s         1/102002         1/1			66.53 11.98 98.00 98.25		<b>-</b>	
Cradit-Return of merch         REPAIRS         5/82/002         5/10/2003           Vehicle Repair         Vehicle Repair         11/20/2001         5/10/2001           Vehicle Repair         11/20/2001         11/20/2001         5/10/2001           Vehicle Rapair         11/20/2001         11/20/2002         5/10/2002           Lagoon Reair         11/20/2002         11/20/2002         1/20/2002           Lagoon Reair         4/15/2002         5/23/2002         1/22/2002           Pump delivery         5/23/2002         1/73         7/22/2002           Pump delivery         5/23/2002         1/73         7/22/2002           Antamor repair         2504-cubemicals         7/15/2002         1/73         7/22/2002           Work on areator         2504-cubemicals         7/15/2002         1/73         7/22/2002           Work on areator         2504-cubiste s         1/31/2002         1/73         7/22/2002           Pump Work         2504-cubiste s         1/22/2002         1/24/2002         1/24/2002           Pump Work         2504-cubiste s         1/22/2002         1/24/2002         1/24/2002           Lif Station Work         2504-cubiste s         1/22/2002         1/24/2002         1/24/2002	- w +		65.53 11.88 98.00 98.25	124.9	·	
Vehicle Rapair         4P202001           Vehicle Rapair         11/27/2001           Vehicle Rapair         11/2002           Vehicle Rapair         11/2002           Stock Rapair         11/2002           Lagoon Reair         41/5/2002           Pump delivery         41/5/2002           Pump delivery         41/5/2002           Pump delivery         7/15/2002           Roundup Weed Killer         2504-chemicals         7/15/2002           Roundup Weed Killer         2504-chemicals         7/15/2002           Bower Back up         2509-outside s         1/8/2002           Work on areator         2509-outside s         1/8/2002           Work on areator         2509-outside s         1/8/2002           Monthly Inspection         2509-outside s         1/8/2002           Monthly Inspection         2509-outside s         1/1/2002           Monthly Inspection         2509-outside s         1/1/2002           Repair Repair         2509-outside s         1/1/2002           Vehicle Monthly Inspection         2509-outside s         1/1/2002           Repair Repair         2509-outside s         1/1/2002           Lift Station Work         2509-outside s         1/1	n 4		65.53 11.98 98.00 68.25		-	
Vehicle Repair         11/27/2001           Vehicle Repair         11/27/2001           Vehicle Repair         11/2002           Vehicle Repair         11/2002           Vehicle Repair         11/2002           Vehicle Repair         2002           Lagoon Reair         2504-chemicals         11/2002           Adriantor repair         2504-chemicals         7/16/2002           Advantor repair         2504-chemicals         7/16/2002           Sewer Back up         2504-chemicals         7/16/2002           Sewer Back up         2504-chemicals         7/16/2002           Work on areator         2509-outside s         1/31/2002         1/73           Pump Work         2509-outside s         1/32/2002         1/32/2002           Pump Work         2509-outside s         2/20/2002         1/32/2002           Repair sewer line         2509-outside s         2/20/2002         1/32/2002           Lift Station Work         2509-outside s         1/20/2002         1/32/2002           Lift Station Work         2509-outside s         1/20/2002         1/32/2002           Lift Station Work         2509-outside s         1/20/2002         1/32/2002           Lift Station Work         2509	W T		68.63 11.88 98.00 68.25	124.91	· · · · · · · · · · · · · · · · · · ·	
Vehicle Repair         11/2002           Vehicle Repair         11/2002           Vehicle Repair         11/2002           Stock Repair         11/2002           Lagoon Reair         24/15/2002           Pump delivery         4/15/2002           Pump delivery         2504-chemicals         7/22/2002           Pump delivery         2504-chemicals         7/15/2002         1473           Roundup Weed Killer         2504-chemicals         7/15/2002         1473         7/22/2002           Bower Back up         2509-outside s         1/31/2002         1473         7/22/2002           Work on areator         2509-outside s         1/81/2002         1478         7/22/2002           Work on areator         2509-outside s         1/81/2002         1478         7/22/2002           Monthly Inspection         2509-outside s         1/32/2002         1478/2002         1478/2002           Repair Sewer line         2509-outside s         1/12/2002         1478/2002         1478/2002           Repair Sewer line         2509-outside s         1/12/2002         1478/2002         1478/2002         1478/2002           Lift Station Work         2509-outside s         1/18/2002         1478/2002         1478/2002	W CO CO CO	360.00 517.50	11:88 88 00 88 20 	124.9	<del>.</del>	
Wehlde Repair         1/10/2002           Vehicle Repair         1/10/2002           Vehicle Repair         1/10/2002           Siock Repair         3/14/2002           Siock Repair         4/15/2002           Full poment Resign         5/20/2002           Adriantor repair         2504-chemicals           Yeast         7/16/2002           Work on areator         2509-outside s.           Work on areator         2509-outside s.           Hump Work         2509-outside s.           Jump Work         2509-outside s.	W W W	360.00 517.50	98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98.68 98 98.68 98 98 98 98 98 98 98 98 98 98 98 98 98			
Vehicle Repair         1/1/2002           Vehicle Repair         1/1/2002           Stock Repair         1/4/2002           Stock Repair         4/1/2002           Foundation Repair         2/23/2002           Pump assilvery         2/23/2002           Pump assilvery         2/23/2002           Pump winder Kepair         2/20/2002           Pump winder Read:         2/20/2002           Roundup Wheed Killer         2/20-cutside s	ν <del>τ</del>	360.00 517.50	00 85 66.25 	124.9	·	
1442002   1442002   1442002   1442002   1442002   1442002   1442002   1442002   1442002   1442002   1442002   1442002   1442002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152002   144152	vî <del>c</del>	360.00 517.50	98.25	. 124.91	· ·	
Vehicle Rapair         31'4/2002           Stock Repair         4152002           Block Repair         4152002           Funth salivery         523/2002           Pump salivery         77222002           Yeast         2504-chemicals         77152002           Roundup Weed Killer         2504-cutside s         1/872002           Sewer Back up         2509-outside s         1/872002           Bump Work         2509-outside s         1/872002           Pump Work         2509-outside s         270/2002           Pump Work         2509-outside s         270/2002           Pump Work         2509-outside s         270/2002           Pump Work         2509-outside s         271/2002           Hill Station Work         2509-outside s         871/2002           Hill Station Work         2509-outside s         271/2002           Lift Station Work         2509-outside s         474/2002           Lift Station Work         2509-outside s         474/2002 <td>ν, τ.</td> <td>360.00 517.50</td> <td></td> <td>124.9</td> <td>·</td> <td></td>	ν, τ.	360.00 517.50		124.9	·	
Stock Repair   A152002   Lagoon Reair   A152	vi e	360.00 517.50		124.84	ę	
Stock Repair   4152002	νο <del>τ</del>	340.00 517.50		124.9	ŧ	
Lagoon Reasin         4/15/2002           Pump delivery         5/20/2002         1/47/2002           Antimor repair         2604-chemicals         7/15/2002         1/72/2002           Roundup Weed Killer         2504-chemicals         7/15/2002         1/73/2002         1/73/2002           Sewer Back up         2509-outside s         1/81/2002         1/73/2002         1/73/2002           Work on areator         2509-outside s         1/81/2002         1/73/2002         1/73/2002           Work on areator         2509-outside s         1/81/2002         1/22/2002         1/22/2002           Hump Work         2509-outside s         5/80/2002         1/22/2002         1/22/2002           Word on areator         2509-outside s         5/80/2002         1/22/2002         1/22/2002           Word work         2509-outside s         1/12/2002         1/22/2002         1/22/2002           Week Station Work         2509-outside s         1/12/2002         1/22/2002         1/22/2002           Ulf Station Work         2509-outside s         1/12/2002         1/12/2002         1/12/2002           Liff Station Work         2509-outside s         2/16/2002         1/12/2002         1/12/2002         1/12/2002           Liff S	νο <del>τ</del>	360.00 517.50		124.91	<del>*</del>	
Equipment Repair 57232002  Autharor repair 2504-chemicals 7/152002  Yeast  Roundup Weed Killar 2504-chemicals 7/152002  Sewer Back up 2509-outside s. 1/212002  Work on areator 2509-outside s. 1/212002  Work on areator 2509-outside s. 1/212002  Work on areator 2509-outside s. 2/210/2002  Work on areator 2509-outside s. 2/11/2002  Work 2509-outsid	νο <del>.</del>	360.00 517.50		124.91	<b>-</b>	
Pump delivery         SCR20202           Aerturfor repair         7/16/2002         1/72/2002           Aerturfor repair         2604-chemicals         7/16/2002         1/73/2002         1/73/2002           Roundup Weed Killar         2504-chemicals         7/15/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002 <td>νο +-</td> <td>360.00 517.50</td> <td></td> <td>124.91</td> <td>-</td> <td></td>	νο +-	360.00 517.50		124.91	-	
Aeritanor repair         7/16/2002         7/16/2002         7/22/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002         1/73/2002	vo ←	517.50		124.91	<b>.</b>	
Average of the Present Page of the Present	νο <del>τ</del>	20.00		124.91	<b></b>	
2509-outside s.   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002   478   7/15/2002	עט בי			!		
Rounduy Weed Riller         2504—Abenicals         7/15/2002         1478         7/25/2002           Sewer Back up         2509-outside s         1/31/2002         1328         2/22/2002           Work on areator         2509-outside s         1/81/2002         1329         2/22/2002           Pump Work         2509-outside s         5/81/2002         1424         5/21/2002           Pump Work         2509-outside s         5/81/2002         1428         5/21/2002           Pump Work         2509-outside s         7/15/2002         14/8         7/21/2002           Work on areator         2509-outside s         7/15/2002         14/8         7/15/2002           Lif Station Work         2509-outside s         1/16/2002         14/8         1/15/2002           Lif Station Work         2509-outside s         1/16/2002	40 F					
Søwer Back up         2508-outside s         1/31/2002         1330         22/22/2002           Work on areator         2508-outside s         1/8002         1358         32/22/2002           York on areator         2509-outside s         1/8002         1358         32/22/2002           Pump Work         2509-outside s         5/80/2002         1424         5/24/2002           Monthly Inspection         2509-outside s         5/80/2002         1424         5/24/2002           Pump Work         2509-outside s         7/8/2002         1428         5/3/2002           Pump Work         2509-outside s         7/8/2002         1428         7/26/2002           Howed Ealer Repair sawer line         2509-outside s         7/8/2002         1424         5/3/2/2002           Liff Station Work         2509-outside s         1/3/2002         142         5/2/2/2002           Liff Station Work         2509-outside s         1/3/2002         142         5/2/2/2002           Liff Station Work         2509-outside s         1/10/2002         142         5/2/2/2002           Liff Shalon Work         2509-outside s         1/10/2002         134         2/2/2/2002           Liff Draws         2509-outside s         1/10/200	40 <del>4</del>					
Work on areator         2509-outside s         1/82002         1158         8631/2001           Work on areator         2509-outside s         2002-0utside s         2509-outside s         2509-2015         335         322/2002           Pump Work         2509-outside s         592/2002         1424         574/2002           Pump Work         2509-outside s         592/2002         1469         574/2002           Pump Work         2509-outside s         715/2002         1469         574/2002           How on areator         2509-outside s         715/2002         1479         774/2002           How on areator         2509-outside s         715/2002         1479         774/200           Ropalis saver line         2509-outside s         712/2002         147         774/200           Lif Station Work         2509-outside s         172/2002         147         771/200           Lif Station Work         2509-outside s         1700/200         147         871/200           Lif Station Work         2509-outside s         171/200         147         871/200           Lif Station Work         2509-outside s         571/200         147         871/200           Lif Station Work         2509-outside						
Work on areatac         2509-outside s         1/8/2002         1326         222/2002           Work on areatac         2509-outside s         5/80/2002         1424         5/22/2002           Pump Work         2509-outside s         5/80/2002         1424         5/22/2002           Monthly Inspection         2509-outside s         5/80/2002         1428         5/31/2002           Work on areatac         2509-outside s         7/15/2002         1428         5/31/2002           Work on areatac         2509-outside s         7/15/2002         143         7/26/2002           Weed Eater Repair         2509-outside s         1/12/2002         134         1/12/2002           Ulf Station Work         2509-outside s         6/13/2002         145         6/22/2002           Ulf Station Work         2509-outside s         1/13/2002         145         6/22/2002           Open Drain Lina         2509-outside s         1/15/2002         134         2/12/2002           Open Drain Lina         2509-outside s         1/15/2002         134         4/16/2002           Labor on Pump         2509-outside s         1/15/2002         134         4/16/2002           Pump Work         2509-outside s         2/16/2002	<b>-</b>					
Work for a season         2009-Outside s.         2009-Out		1345 98				
Work of a faragrant         ZOUS-Questide s         5902002         1424         5042020           Pump Work         2509-outside s         5092002         1424         5247020           Monthly Inspection         2509-outside s         7152002         1428         5312020           Work on areator         2509-outside s         7152002         1478         7126200           Repair Sware line         2509-outside s         7172000         1240         124200           Repair Sware line         2509-outside s         7172000         1478         1726200           Repair Sware line         2509-outside s         6713200         1449         712200           Liff Station Work         2509-outside s         6713200         1449         712200           Liff Station Work         2509-outside s         474200         1452         672200           Liff Station Work         2509-outside s         1716700         139         472200           Deen Drain Line         2509-outside s         1716200         139         472200           Labor on Pump         2509-outside s         216700         139         4718200           Pump Work         2509-outside s         216700         139         4718200		00.08				
Pump Work         2509-outside s         5902002         1424         50240200           Monthly Mork         2509-outside s         5092002         1428         50312000           Pump Work         2509-outside s         6712000         1469         782000           Pump Work         2509-outside s         6712000         1469         782000           Pump Work         2509-outside s         6712000         1478         724200           Lif Station Work         2509-outside s         2722000         1337         31/1200           Lif Station Work         2509-outside s         6713000         142         71/2200           Lif Station Work         2509-outside s         1729/2002         143         71/2200           Lif Station Work         2509-outside s         1729/2002         1331         22/2200           Lif Station Work         2509-outside s         1710/2002         147         871/200           Lif Station Work         2509-outside s         571/2002         147         871/200           Libor on Pump         2509-outside s         571/2002         147         571/200           Pump Work         2509-outside s         571/2002         148         671/200	_	20.00				
Pump Work         2598-outside s         5/8/2002         14/28         5/3/10/2002           Monthly Inspection         2508-outside s         7/15/2002         14/8         5/3/10/2002           Work on areator         2509-outside s         7/15/2002         14/8         7/16/2002           Repair severe line         2509-outside s         7/15/2002         14/8         7/16/2002           Wared Eater Repair         2509-outside s         6/13/2002         14/4         1/12/2002           Liff Station Work         2509-outside s         6/13/2002         14/4         1/12/2002           Liff Station Work         2509-outside s         6/13/2002         14/4         6/12/2002           Liff Station Work         2509-outside s         1/17/2002         14/4         6/12/2002           Liff Station Work         2509-outside s         1/16/2002         13/8         4/22/2002           Liff Station Work         2509-outside s         1/16/2002         13/8         4/16/2002           Labor on Pump         2509-outside s         1/16/2002         13/8         4/16/2002           Pump Work         2509-outside s         2/16/2002         14/8         4/16/2002           Pump Work         2509-outside s		973.05				
Monthly Inspection         2509-outside s.         6/12/2002         1460         7/8/2002           Pump Work         2509-outside s.         1/75/2002         148         7/8/2002           Repair sewer line         2509-outside s.         2/22/2002         1337         3/1/2002           Liff Station Work         2509-outside s.         2/22/2002         1337         3/1/2002           Liff Station Work         2509-outside s.         1/29/2002         142         7/2/2002           Liff Station Work         2509-outside s.         1/29/2002         143         2/2/2002           Liff Station Work         2509-outside s.         1/29/2002         133         2/2/2002           Liff Station Work         2509-outside s.         1/29/2002         134         2/2/2002           Liff Station Work         2509-outside s.         1/16/2002         134         2/2/2002           Liff Station Work         2509-outside s.         5/16/2002         134         2/2/2002           Libor on Pump         2509-outside s.         5/16/2002         134         3/1/2002           Pump Work         2509-outside s.         4/18/2002         149         6/1/2002           Pump Work         2509-outside s.         4/18/2002         149 <td< td=""><td>1,053.05</td><td>1,053.05</td><td>-</td><td></td><td></td><td></td></td<>	1,053.05	1,053.05	-			
Month   Disposation   Constitution			-			
Pump Work						
Work on areatan         2509-outside s         1720/2000         1240         124/2000           Lift Station Work         2509-outside s         2722/2002         1494         7/12/2002           Lift Station Work         2509-outside s         67/12/2002         1494         7/12/2002           Lift Station Work         2509-outside s         1/29/2002         149         7/12/2002           Lift Station Work         2509-outside s         1/29/2002         133         2/22/2002           Lift Station Work         2509-outside s         1/10/2002         139         4/22/2002           Lift Station Work         2509-outside s         1/10/2002         139         4/22/2002           Lift Station Work         2509-outside s         1/10/2002         134         2/22/2002           Lift Station Work         2509-outside s         2/16/2002         134         3/17/2002           Lift Station Work         2509-outside s         2/16/2002         134         4/18/2002           Lift Station Work         2509-outside s         2/16/2002         134         4/18/2002           Pump Work         2509-outside s         4/18/2002         139         4/18/2002           Misc.         2510-operating s         4/	_					
Repair saver line         2509-outside s         272/2002         133         31/2002           Liff Station Work         2509-outside s         674/2002         142         71/2002           Liff Station Work         2509-outside s         1738/2002         143         252/2002           Liff Station Work         2509-outside s         1738/2002         143         252/2002           Liff Station Work         2509-outside s         4/47/2002         139         422/2002           Liff Station Work         2509-outside s         1/10/2002         134         272/2002           High-Prassure Jetting         2509-outside s         1/10/2002         134         3/12/2002           High-Prassure Jetting         2509-outside s         2/16/2002         134         3/12/2002           Pump Work         2509-outside s         5/12/2002         141         5/12/2002           Pump Work         2509-outside s         4/18/2002         143         5/12/2002           Pump Work         2509-outside s         4/18/2002         143         5/12/2002           Misc.         2510-operating         3/14/2002         143         5/12/2002           Misc.         2510-operating         3/14/2002         139						
Lift Station Work         2508-outside s         6224/2002         1444         7/12/2003           Weed Eart Repair         2509-outside s         1/29/2002         1331         222/2002           Lift Station Work         2509-outside s         1/29/2002         1331         222/2002           Lift Station Work         2509-outside s         1/4002         1398         472/2002           Lift Station Work         2509-outside s         1/10/2002         1331         272/2002           High-Pressure Jetting         2509-outside s         1/10/2002         1328         2/2/2006           Ludor on Pump         2509-outside s         5/11/2002         1340         3/1/2002           Pump Work         2509-outside s         5/11/2002         1397         4/2/2/2007           Pump Work         2509-outside s         4/18/2002         1498         6/17/2002           Pump Work         2509-outside s         4/18/2002         1498         6/17/2002           Pump Work         2509-outside s         4/18/2002         1498         6/12/2002           Misc.         2510-operating         3/14/2002         1398         4/18/2002           Misc.         2510-operating         3/14/2002         1398	_					
Weed Eater Repair         2509-outside s         6/13/2002         1452         8/28/2002           Liff Station Work         2509-outside s         1/28/2002         133         22/22/2002           Liff Station Work         2509-outside s         1/10/2002         1399         4/22/2002           Doen Drain Line         2509-outside s         1/10/2002         134         8/22/2002           High-Prassure Jatting         2509-outside s         1/10/2002         134         4/22/2002           Labor on Pump         2509-outside s         5/11/2002         134         4/12/2002           Pump Work         2509-outside s         5/11/2002         138         4/18/2002           Pump Work         2509-outside s         4/18/2002         148         5/17/2003           Pump Work         2509-outside s         4/18/2002         148         6/17/2002           Misc.         2509-outside s         4/18/2002         148         6/17/2002           Misc.         2509-outside s         4/18/2002         148         6/17/2002           Misc.         2510-operating         3/14/2002         139         4/18/2002           Misc.         2510-operating         3/14/2002         139         3/14/200	_				:	
Lift Station Work 2509-outside s. 1729/2002 1331 272/2002 Lift Station Work 2509-outside s. 4/4/2002 1391 272/2002 Lift Station Work 2509-outside s. 1700/2002 1477 873/2000 Libon Drain Line 2509-outside s. 2/16/2002 1340 31/2002 Libon on Pump Work 2509-outside s. 5/1/2002 1340 31/2002 Pump Work 2509-outside s. 4/18/2002 1349 4/18/2002 Pump Work 2509-outside s. 4/18/2002 1349 4/18/2002 Pump Work 2509-outside s. 4/18/2002 1349 4/18/2002 Misc. 25/10-operating. 3/18/2002 1349 4/18/2002 Misc. 25/10-operating. 3/18/2002 1349 4/18/2002 Misc. 25/10-operating. 3/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/2002 1349 4/18/200	7.83				7.83	
Life Station Work 2509-outside s. 1412002 1399 4722/2002 Life Station Work 2509-outside s. 1702002 1399 4722/2002 Life Dean Line 2509-outside s. 1702002 1349 1472/2002 Life Dean North Color on Pump Work 2509-outside s. 2716/2002 1349 4722/2002 Pump Work 2509-outside s. 2716/2002 1349 4722/2002 Pump Work 2509-outside s. 4718/2002 1387 4722/2002 Pump Work 2509-outside s. 4718/2002 1439 6772/2002 Pump Work 2509-outside s. 4718/2002 1394 3772/2002 Pump Work 2510-operating. 3711/2002 1394 3772/2002 Pump 2510-operating. 3711/2002 1394 3772/2002 Pump 2510-operating. 3711/2002 1394 3772/2002 Pump 2510-operating. 3711/2002 1394 371/2002 Pump 2510-operating. 3711/2002 1394 371/2002 Pump 2510-operating. 371/2002 1394 371/2002 Pump 2510-operating						
2509-outside s 1157 8371/2002  2509-outside s 1170/2002 1340  2509-outside s 1170/2002 1340  2509-outside s 2/16/2002 1340  Pump Work 2509-outside s 5/1/2002  Pump Work 2509-outside s 5/1/2002  Pump Work 2509-outside s 4/18/2002 1349  Pump Work 2509-outside s 4/18/2002 1394  Misc. 2510-operating. 3/14/2002 1398  Misc. 2510-operating. 3/14/2002 1399  3/17/2003  Misc. 2510-operating. 1/10/2002 1399  3/17/2003						
2509-outside s 1102002 1329 12222002 2509-outside s 1102002 1329 22222002 2509-outside s 21162002 1430 3172002 2509-outside s 5712002 1430 47222002 2509-outside s 5712002 1439 47222002 2509-outside s 47182002 1439 6772002 2510-operating 37142002 1324 3222002 2510-operating 37142002 1324 3222002 2510-operating 37142002 1324 3222002 2510-operating 11102002 1224 3242001 2510-operating 11102002 1224 11242001 1224 11242001 22510-operating 11102002 1224 11242001 22510-operating 11102002 1224						
2509-outside s 2509-outside s 2509-outside s 2102-0025 s 2509-outside s 2102-002 2509-outside s 2102-002 2509-outside s 2102-002 2509-outside s 4102-002 2509-o						
2509-outside s 1/10/2002 1329 2/22/2002 2509-outside s 5/10/2002 1337 4/22/2003 2509-outside s 5/10/2002 1337 4/22/2003 2509-outside s 5/10/2002 13387 4/22/2003 2509-outside s 4/10/2002 1439 6/7/2002 2510-operating 3/10/2002 1354 3/2/2002 2510-operating 4/10/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/2002 1254 3/2/20	175.00					
2509-outside s 5/16/2002 1340 31/2002 2509-outside s 5/1/2002 1347 5/17/2002 2509-outside s 5/1/2002 1347 5/17/2002 2509-outside s 4/18/2002 1419 6/17/2002 2509-outside s 4/18/2002 1439 6/18/2002 2509-outside s 4/18/2002 1439 6/18/2002 2510-operating. 9/18/2001 1304 3/17/2002 2510-operating. 3/14/2002 1354 3/17/2002 2510-operating. 3/17/2002 1354 3/17/2002 2510-operating. 3/17/2002 1354 3/17/2002 2510-operating. 3/17/2002 1364 3/17/2002 2510-operating. 3/17/2002 1364 3/17/2002 2510-operating. 3/17/2001 1181 9/10/2002 12510-operating. 3/17/2001 1181 9/10/2002 12510-operating. 3/17/2001 1181 9/10/2002 12510-operating. 3/17/2001 1181 9/10/2002 12510-operating. 3/17/2001 1241 12/4/2001						
2509-outside s 5/17202 1417 5/172022 2509-outside s 14/18202 1418 4/18202 2509-outside s 4/18202 1419 4/18202 2509-outside s 4/18202 1419 6/17202 2509-outside s 4/18202 1419 6/17202 2500-outside s 4/18202 1419 6/17202 2500-outside s 4/18202 1419 6/17202 2500-outside s 4/18202 1419 6/17202 2500-operating 22/17202 135 3/17202 2510-operating 3/14202 135 3/17202 2510-operating 4/10202 1354 3/17202 2510-operating 1/10202 1354 3/17202 2510-operating 1/10202 1256 1/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256 4/10202 1256						
Ort Temp 2509-outside 8 31/2002 1337 4/22/2002 2509-outside 8 4/18/2002 1337 4/22/2002 2509-outside 8 4/18/2002 1338 4/18/2002 2509-outside 8 4/18/2002 1439 6/7/2002 2509-operating 27/18/2002 1339 31/2002 2510-operating 27/18/2002 1339 31/2002 2510-operating 37/18/2002 1339 31/2002 2510-operating 37/18/2002 1339 31/2002 2510-operating 37/18/2002 1339 32/2002 2510-operating 37/18/2002 1339 31/2002 2510-operating 37/18/2002 1339 31/2002 2510-operating 37/18/2002 1339 31/2002 2510-operating 37/18/2001 1331 32/2002 2510-operating 37/18/2002 1339 31/2002 2510-operating 37/2001 1331 32/2002 2510-operating 37/2002 1339 31/2002 2510-operating 37/2001 1331 32/2002 2510-operating 37/2002 1339 32/2002 2510-operating 37/2002 2510-operating 37/20		873				
Work         2509-outside s         1387         4222000           2509-outside s         4/192002         1438         4/192002           Work         2509-outside s         4/192002         1438         4/192002           Work         2509-outside s         4/192002         1438         6/172002           Work         2509-outside s         4/192002         1438         6/172002           2510-operating         27/12002         135         3/12002           2510-operating         3/142002         134         3/12002           2510-operating         3/14002         134         3/22002           2510-operating         1/10/2002         134         3/22002           2510-operating         1/10/2002         138         3/22002           2510-operating         1/10/2002         128         1/10/2002           2510-operating         1/10/2002         128         1/10/2002           2510-operating         1/10/2002         128         1/10/2002           2510-operating         1/10/2002         128         1/10/2002           2510-operating         1/10/2002         128         1/10/2001           2510-operating         1/10/2002 </td <td></td> <td>20.50</td> <td></td> <td></td> <td></td> <td></td>		20.50				
2509-outside 3  Work 2509-outside 3  Work 2509-outside 3  4/18/2002 149 577/2002  Work 2509-outside 3  4/18/2002 149 677/2002  2510-operating  27/12/2002 135 37/2002  2510-operating  27/12/2002 135 37/2002  2510-operating  37/12/2002 135 37/2002  2510-operating  37/12/2003 135 37/2002  2510-operating  37/12/2003 135 37/2002  2510-operating  47/18/2001 131 124/2001  47/18/2001 131 124/2001		132.68				
Work         2509-outside a         4/19/2002         1419         5/17/2002           Work         2509-outside a         4/18/2002         1439         6/17/2002           Work         2509-outside a         4/18/2002         1439         6/18/2002           2510-operating         27/18/2001         120         10/23/2007           2510-operating         27/12/2002         1336         3/11/2002           2510-operating         3/14/2002         134         3/22/2002           2510-operating         3/71/2002         134         3/22/2002           2510-operating         1/10/2002         128         4/24/2001           2510-operating         1/10/2002         128         1/10/2002           2510-operating         1/10/2002         128         1/10/2002           2510-operating         1/10/2002         128         1/10/2002           2510-operating         1/10/2002         128         1/10/2002           2510-operating         1/10/2002         128         1/10/2003           2510-operating         1/10/2002         128         1/10/2003	3,500.00	3,500.D0				
Work         Z006-outside 8         4/18/2002         149         67/72/2002           Work         Z509-outside 8         4/18/2002         1439         67/72/2002           Work         Z500-outside 8         4/18/2002         1439         67/18/2002           Z510-operating         2/18/2002         133         3/1/2002           Z510-operating         3/14/2002         134         3/2/2002           Z510-operating         3/2/12/2002         134         3/2/2/2002           Z510-operating         3/2/12/2002         134         3/2/2/2002           Z510-operating         1/10/2/2002         136         3/2/2/2002           Z510-operating         1/10/2/2002         136         3/2/2/2002           Z510-operating         1/10/2/2002         136         3/2/2/2002           Z510-operating         1/10/2/2002         126         1/10/2/2002           Z510-operating         1/10/2/2002         126         1/10/2/2002           Z510-operating         1/10/2/2002         126         1/10/2/2002           Z510-operating         1/10/2/2002         126         1/10/2/2002           Z510-operating         1/10/2/2002         126         1/10/2/2/2002	•	930 14				
Work 2509-outside * 4/18/2002 1439 6/72/002 Work 2509-outside * 4/18/2002 1439 6/18/2002 2510-operating 9/18/2002 1305 3/12/002 2510-operating 2/27/2002 1305 3/12/002 2510-operating 3/4/2002 1304 3/22/2002 2510-operating 3/21/2002 1304 3/22/2002 2510-operating 1/10/2002 1206 1/10/2002	- '	1,000.14				
Work         2509-outside s         4/18/2002         1439         6/18/2002           2510-operating         9/18/2002         122         10/23/2001           2510-operating         27/12/002         1356         37/12/2002           2510-operating         37/12/002         1354         37/22/002           Pump         2510-operating         37/12/002         1354         37/22/002           2510-operating         1/10/2002         1364         37/22/002         1364         37/22/002           2510-operating         1/10/2002         1268         1/10/22/002         1268         1/10/22/002           2510-operating         1/10/2002         1268         1/10/22/002         1268         1/10/22/002           2510-operating         1/10/2002         1268         1/10/22/002         1268         1/10/22/002           2510-operating         1/16/2001         1241         124/2/2001         124/2/2001		00.000,				
2510-operating 9/19/2001 1202 10/23/2001 2510-operating 227/2002 1335 3/12/2002 2510-operating 3/14/2002 1364 3/22/2002 2510-operating 9/7/2001 1341 9/24/2001 2510-operating 1/10/2002 1286 1/10/2003 2510-operating 1/10/2002 1286 1/10/2003 2510-operating 1/10/2002 1286 1/10/2003 2510-operating 1/10/2003 1286 1/10/2003	1,000,00	00.000,1				
2510-operating 22772002 1335 3712002 2510-operating 27772002 1336 3772002 2510-operating 3742002 1336 3222002 2510-operating 3742002 1336 3222002 2510-operating 9772001 1131 9242001 2510-operating 17102002 1288 17102002 2510-operating 17102002 1288 17102002 2510-operating 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288 17102002 1288						
2510-operating 227/12002 1355 9/12002 Cape Rock V 2510-operating 3714/202 1354 3/22/202 Cape Rock V 2510-operating 3712/202 1394 3/22/202 Cape Rock V 2510-operating 1/10/202 1286 1/10/2002 Cape Rock V coping Wand 2510-operating 1/10/2002 1286 1/10/2002 Cape Rock V	•					
2510-operating 31412002 1354 30220002 Cape Rock V Pump 2510-operating 32112002 1364 31292002 Cape Rock V Pump 2510-operating 11102002 1286 1102002 Cape Rock V coping Wand 2510-operating 11102002 1286 1102002 Cape Rock V coping Wand 2510-operating 11102001 1286 1102002 Cape Rock V Coping Wand 2510-operating 11102001 1286 1102002 Cape Rock V Coping Wand 2510-operating 11102001 1286 1102002 Cape Rock V Coping Wand 2510-operating 11102002 1286 1102002 Cape Rock V Coping Wand 2510-operating 11102002 1286 1102002 Cape Rock V Coping Wand 2510-operating 11102002 1286 1102002 Cape Rock V Coping Wand 2510-operating 11102002 1286 1102002 Cape Rock V Coping Wand 2510-operating 11102002 1286 1102002 Cape Rock V Coping Wand 2510-operating 11102002 1286 1102002 Cape Rock V Coping Wand 2510-operating 11102002 1286 1102002 Cape Rock V Coping Wand 2510-operating 11102002 1286 1102002 Cape Rock V Coping Wand 2510-operating 11102002 1286 1102002 Cape Rock V Coping Wand 2510-operating 11102002 1286 1102002 Cape Rock V Coping Wand 2510-operating 11102002 1286 1102002 Cape Rock V Coping Wand 2510-operating 11102002 1286 1102002 Cape Rock V Coping Wand 2510-operating 11102002 1286 1102002 Cape Rock V Coping Wand 2510-operating 11102002 1286 1102002 Cape Rock V Coping Wand 2510-operating 11102002 1286 1102002 Cape Rock V Coping Wand 2510-operating 11102002 1286 1102002 Cape Rock V Coping Wand 2510-operating 11102002 Cape Rock V Coping Wand 2510-operating 1110200						
2510-operating 32712002 1394 37292002 Cape Rock V Pump 2510-operating 11/02/201 1181 9/24/201 Cape Rock V Coping Wand 2510-operating 11/02/201 1288 11/02/202 Cape Rock V Coping Wand 2510-operating 11/05/201 12/4/201 12/4/201 Cape Rock V Coping Wand 2510-operating 11/05/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 12/4/201 1						
Pump 2510-operating 6/7/2001 1181 9/24/2001 Cape Rock V 2510-operating 1/10/2002 1286 1/10/2002 Cape Rock V coping Wand 2510-operating 1/16/2001 1414 1/24/2001 Cape Rock V 2510-operating 1/16/2001 1416 1/24/2001 Cape Rock V 2510-operating 1/16/2001 1416 1/24/2001 Cape Rock V 2510-operating 1/17/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 1416 1/24/2001 14	2.54					
2510-operating 1/10/2002 1286 1/10/2002 Cape Rock V coping Wand 2510-operating 1/10/2001 1249 ROck V 2510-operating 1/10/2001 1240 ROck V	ge 86.44					
coping Wand 2510-operating 11/16/2001 1241 12/4/2001 Cape Rock V	272.12					
coping ward colle-operating 11/16/2001 1241 124/2001 Cabe Rock v	30.40					
COCCUPATION COCCUPATION CANADA	_					
A 1410 STUCIOUS Cape Rock v	_					
Cadar Hill Hard Misc. 2595-miscellan 10/30/2001 1217 11/6/2001 Cape Rock Village	14.30					
Miss 2505 missellan 7/8/000 (478 7/26/2000 Cape Book V	12.18					
Made. And Annual						
Misc. 2595-miscellan //8/2002 1476 //26/2002 Cape Rock V	70.67					19 11
	-					•
Pressure Wash 2521-equipmen 11/15/2001 1222 11/15/2001 Cabe Rock V	•					
The 2524 actions 482000 1308 4040000 Care Book V						
TOURS TOUR TOUR TOUR TOUR TOUR TOUR TOUR TOUR	230					
. Boocat Renial 2221-equipment. 0/4/201 1114 of 12201						
Ni Way Conce Sawar Clashar 2521, adillogan 2715/2002 1332 2/2/2002 Caba Kook Village	23.65			40.0	200	,,,,,,

Vendor	Description	ORG. CODED	Sry Date	Check	Check a Date Paid System	Repairs	5	Outside of TYMeter Reading Vahicle Repairs Tools Misc. Supp Chamicals Late Fees	r Reading Vehic	te Repairs Tools	Misc. Supp	Chemicals	Late Fees	Mowing	Misc	System Repairs
Cedar Hill Hard		REPAIRS	18	1458	7/8/2002 Crestview Acres	13.41										13.41
Pacific Lumber	Well House-Pressurize REPAIRS	REPAIRS	4/2/2002	1397	4	18.35										18.35
Pacific Lumber		REPAIRS	6/13/2002	1449	_	88.51										
Piffel Excavating	Well House	REPAIRS	4/8/2002	1379		5.70										5.70
Piffel Excavating		REPAIRS	3/29/2002	1398		70.66										70.66
USA Bluebook	Well House-Pressurize REPAIRS	REPAIRS	4/1/2002	138	4/12/2002 Crestview Acres	209.70										209.70
USA Bluebook	Well House-Pressurize REPAIRS	REPAIRS	4/10/2002	140	4/24/2002 Crestview Acres	187.88										167.86
USA Bluebook	Well House-Pressurize REPAIRS	REPAIRS	4/29/2002	1418		92.99										92.98
USA Bluebook	Well House-Pressurize REPAIRS	REPAIRS	4/17/2002	444	_	6.67										6.67
Wholsale Plum	Misc.	REPAIRS	9/24/2001	1192	10/9/2001 Crestview Acres	109.88										109.88
Piffel-Payable	Storage Tank Repair		8/20/2001		Crestview Acres	552.50		552.50								8.0
Piffel-Payable	Vehicle Repair		8/20/2001		Crestview Acres	14.14		14.14								00:00
Piffet-Payable			11/14/2001		Crestview Acres	888.40										04.00
Piffel-Payable	Vehicle Repair		11/27/2001		Crestview Acres	18.72				18.72						300
Piffel-Payable	Vehicle Repair		11/30/2001		Crestvlew Acres	3.42				3.42						8.0
Piffel-Payable	Vehicle Repair		1/1/2002		Crestviaw Acres	28.00				28.00						20.0
Piffel-Payable	Vehicle Repair.		3/14/2002		Crestview Acres	19.33				19.33						90.0
Piffel-Payable	Stock repair		4/15/2002		Crestview Acres	44.58										8.4 8.4
Piffel-Payable	Equipment repair		5/23/2002		Crestview Acres	3.47										3.4/
Piffel-Payable	Lesk Repair		5/23/2002		Crestview Acres	1,102.50										1,102.50
Excel Electric	Wiring for Air Pump	3509-outside s	5/22/2002	1443	6/28/2002 Crestview Acres	200.00								;		200:00
Jeffco Lawn &	Weed Ester Repair	3509-outside s	6/13/2002	1452	6/28/2002 Crestview Acres	2.22								2.22		9 6
Cedar Hill Hard	Misc.	3510-operating	9/19/2001	1202	10/23/2001 Crestvlew Acres	<b>8</b> .8										4.
Cedar Hill Hard	Misc.	3510-operating	2/27/2002	1335	3/1/2002 Cresiview Acres	1,47										74.1
Cedar Hill Hard	Misc.	3510-operating	3/14/2002	1354	3/22/2002 Crestview Acres	5.00										3.5
Cedar Hill Hard	Misc.	3510-operating	3/21/2002	1364	3/29/2002 Crestview Acres	0.73										2.0
Cedar Hill Hard	Misc.	3510-operating	4/10/2002	<del>1</del>	5/10/2002 Crestview Acres	12.89										60.71
Cedar Hill Hard	Misc.	3510-operating	4/10/2002	409		16.06										0.00
Erb Equipment	Echo Pump	3510-operating	9/7/2001	1181	9/24/2001 Crestview Acres	24.78										0.47
Northern	Telescoping Wand	3510-operating	11/16/2001	1241		8.63										3 5
Tom Wolf Hard	Misc.	3510-operating	4/17/2002	1410	5/10/2002	2.05										20.7
Cedar Hill Hard	Misc.	3595-miscellan	10/30/2001	1217	11/6/2001 Crestview Acres	4.08							6			0.00
Flynn Drilling	Air Vant For Well Head 3595-miscellan	3595-miscellan	1772002	1318	2/22/2002 Crestview Acres	49.09							2			40.00
Grainger	Air Compressor to press 3595-miscellan	8 3595-miscellan	3/29/2002	1358	3/28/2002 Crestview Acres	389.71									9	2.500
Pacific Lumber	Well House-Pressurize 3595-miscellan	3595-miscellan	4/1/2002	1369	4/5/2002 Crastview Acres	2,33									2.3.7	800
Piffel Excavating	Uniform Cleaning	3595-miscellan	7/10/2002	1485	7/12/2002 Crestview Acres	5.41									-	3.5
Tom Wolf Hard	Well House-Pressurize 7595-miscellan.	3595-miscellan	4/1/2002	1368	4/5/2002 Crestview Acres	7.8										4.5
Tom Wolf Hard	Misc.	3595-miscellan	4/17/2002	1410	5/10/2002 Crestview Acres	46.02										20.02
USA Bluebook	Fiags	3595-miscellan	7/12/2002	1480	7/26/2002 Crastview Acres	2.31				-				100	155	8,500
Total Crestview Acres	Yes					4,310.83	8	586.64	000	69.47 0.00	2.3	30.0	5/5	77.7	,,,	7/100

Vendor	Description	ORG. CODED	Sry Date	Check # D	ate Paid System	Rapairs	C/I	Outside of TY M	eter Reading	Vehicle Repairs Too	als Misc. Supp	Chemicals	Late Fees	Mowing	Misc.	System Repairs
Cedar Hill Hard	Misc.	REPAIRS	9/19/2001		10/23/2001 High Ridge Manor	43.50										43.50
Cedar Hill Hard	Painting Supplies	REPAIRS	12/11/2001	1277	12/28/2001 High Ridge Manor	12.55										12.55
Piffel-Payable	Blow off valve		8/20/2001		High Ridge Manor	525.00		525.00								0.00
Piffel-Payable	Vehicle Repair		8/20/2001		High Ridge Manor	12.37		12.37								- 1
Piffel-Payable	Leak		11/14/2001		High Ridge Manor	2,110.00										2,110.00
Piffel-Payable	Vehicle Repair		11/27/2001		High Ridge Manor	18.38				16.38						0.00
Piffel-Payable	Vehicle Repair		11/30/2001		High Ridge Manor	2.99				2.99						0.00
Piffel-Payable	Vehicle Repair		1/1/2002		High Ridge Manor	24.50				24.50						0.00
Piffel-Payable	New roof on Well House	•	1/4/2002		High Ridge Manor	2,334.00	2,334.00									0.00
Piffel-Payable	Vehicle Repair		3/14/2002		High Ridge Manor	22.27				22.27						0.00 0.00
Piffel-Payable			4/5/2002		High Ridge Manor	85.75			85.75							51.33
Piffel-Payable	Stock repair		4/15/2002		High Ridge Manor	51.33										4.00
Piffel-Payable	Equipment repair		5/23/2002		High Ridge Manor	4.00										0.00
Jeffco Lawn &	Weed Eater Repair	5509-outside s	6/13/2002	1452	6/28/2002 High Ridge Manor	2.55								2.55		5.54
Cedar Hill Hard	Misc.	5510-operating	9/18/2001		10/23/2001 High Ridge Manor	5.54				-						1.29
Cedar Hill Hard	Misc.	5510-operating	2/27/2002	1335	3/1/2002 High Ridge Manor	1.29										1.75
Cedar Hill Hard	Misc.	5510-operating	3/14/2002	1354	3/22/2002 High Ridge Manor	1.75										0.63
Cedar Hill Hard	Misc.	5510-operating	3/21/2002	1364	3/29/2002 High Ridge Manor	0.63			•							14.83
Cedar Hill Hard	Misc.	5510 operating	4/10/2002	1409	5/10/2002 High Ridge Manor	14.83										8.00
Cedar Hill Hard	Paint	5510-operating	5/23/2002	1427	5/31/2002 High Ridge Manor	8.00										5.29
Cedar Hill Hard	Key blank	5510-operating	4/10/2002	1432	6/7/2002 High Ridge Manor	5.29										21,61
Erb Equipment	Echo Pump	5510-operating	9/7/2001	1181	9/24/2001 High Ridge Manor	21.61										7.55
Northern	Telescoping Wand	5510-operating	11/16/2001	1241	12/4/2001 High Ridge Manor	7.55										2.36
Tom Wolf Hard	Misc.	5510-operating	4/17/2002	1410	5/10/2002 High Ridge Manor	2.36										3.58
Cedar Hill Hard	Misc.	5595-miscellan	10/30/2001	1217	11/6/2001 High Ridge Manor	3.58									6.23	0.00
Piffel Excavating	Uniform Cleaning	5595-miscellan	7/10/2002	1485	7/12/2002 High Ridge Manor	6.23					2.6				0.20	0.00
USA BlueBook	Flags	5595-misceltan	7/12/2002	1480	7/26/2002 High Ridge Manor	2.68	2 224 22	537.37	85.75	66.14	0.00 2.6		0.00	2.55	6.23	2,293.81
Total High Ridge &	hanor .				•	5,328.51	2,334.00	337,31	05.73	JO. 14	2.0	0.00	- 0.00	2.50	0.20	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,

Vendor	Description	ORG. CODED	Srv Date	Check #1	Date Paid System	{F	Repairs	CA	Outside of TY	Aeter Readin	g Vehicle Repairs	fools Mi	sc. Supp	Chemicals	Late Fees	Mowing	Misc.	System Repairs
	Paint Supplies	REPAIRS	6/13/2002	1449	6/28/2002 Hillshine A		51.92			_								51.92
	Light Bulb & Padlock	REPAIRS	6/18/2002	1449	8/28/2002 Hillshine A		28.82											28.62
	Vehicle Repair		8/20/2001		Hillshine A	\cres	7.07		7.07									0.00
	Vehicle Repair		11/27/2001		Hillshine A	cres	9.38				9.36							0.00
	Vehicle Repair		11/30/2001		Hillshine A	\cres	1.71				1.71							0.00
Piffel-Payable	Vehicle Repair		1/1/2002		Hillshine A	cres	14.00				14.00							0.00
	Vehicle Repair		3/14/2002		Hillshine A	cres	10.23				10.23							0.00
	Replace Roof	•	4/5/2002		Hillshine A	cres	2,733.50	2,733.50										0.00
Piffel-Payable	Stock repair		4/15/2002		Hillshine A	cres	23.58											23.58
	Equipment repair		5/23/2002		Hillshine A	\cres	1.84											1.84
Jeffco Lawn &	Weed Ester Repair	6509-outside S	6/13/2002	1452	6/28/2002 Hillshine A	cres	1.17									1.17		0.00
Cedar Hill Hard	Misc.	6510-operating	9/19/2001	1202	10/23/2001 Hillshine A	cres	3.18											3.16 0.74
Cedar Hill Hard	Misc.	6510-operating	2/27/2002	1335	3/1/2002 Hillshine A	cres	0.74											1.00
Cedar Hill Hard	Misc.	6510-operating	3/14/2002	1354	3/22/2002 Hillshine A	cres	1.00											0.36
Cedar Hill Hard	Misc.	6510-operating	3/21/2002	1364	3/29/2002 Hiltshine A	cres	0.36											6.81
Cedar Hill Hard	Misc.	6510-operating	4/10/2002	1409	5/10/2002 Hillshine A	/cres	6.81											119.67
Cedar Hill Hard	Misc.	6510-operating	4/10/2002	1409	5/10/2002 Hillshine A	\cres	119.67											12.35
Erb Equipment	Echo Pump	6510-operating	9/7/2001	1181	9/24/2001 Hillshine A		12.35											4.31
Northern	Telescoping Wand	6510-operating	11/16/2001	1241	12/4/2001 Hillshine A	cres	4.31											1.09
Tom Wolf Hard	Misc.	6510-operating	4/17/2002	1410	5/10/2002 Hillshine A		1.09											2.04
	Misc.	6595-miscellan	10/30/2001	1217	11/6/2001 Hillshine A		2.04								0.73			48.36
Flynn Drilling	Air Vent For Well Head	6595-miscellan	1/7/2002	1318	2/22/2002 Hillshine A		49.09								0.13			165.03
Pacific Lumber		6595-miscellan			12/27/2001 Hillshine A		165.03											15.92
	Roof Edge	6595-miscellan	12/27/2001	1273	1/2/2002 Hillshine A		15.92											22.84
	Paint	6595-miscellan	1/11/2002	1289	1/11/2002 Hillshine A		22.84						1.22					0.00
	Flags	6595-miscellan	7/12/2002	1480	7/26/2002 Hillshine A	cres _	1.22	2,733.50	7.07	0.00	35,30	0.00	1.22		0.73	1.17	0.0	0 509.84
Total Hillshine Acres	\$					-	3,288.63	2,733.50	7.07	0.00	, 33,30	V.50		-				

Total I akawood Hills	USA Bluebook	Pacific Lumber	Pacific Lumber	Pacific Lumber	Pacific Lumber	Flynn Drilling	Cedar Hill Hard	Tom Wolf Hard	Tom Wolf Hard	Northern	Mead O'Brian	Grainger	Ero Equipment	Cedar Hill Hard	Cedar Hill Hard	Cedar Hill Hard	Cadar Hill Hard	Cedar Hill Hard	Cedar Hill Hard	Cedar Hij Hard	Municpal Serv	Municpal Serv	Municpal Serv	Jeffco Lawn &	Fiyna Dalling	Piffel-Payable	Piffel-Payable	Piffel-Payable	Piffet-Payable	Piffel-Payable	Piffel-Payable	Piffel-Payable	Piffel-Payable	Piffel-Payable	Piffel-Payable	Piffel-Payable	Piffel Excavating	Piffel Excavating	Pacific Lumber	Pacific Lumber	Cedar Hill Hard	Vendor
	Flags	Misc.	Misc.	Misc	Misc.	Air Vent For Well Head	Misc	Misc	Misc	Telescoping Wand	Liquid Level Cntri		Echo Pump	Misc	Misc.	Misc.	Misc	Misc.	Misc.	Misc	Troubleshoot Probe Sys 7509-outside s	Troubleshoot Probe Sys 7509-outside s	Troubleshoot Probe Sys 7509-outside s	Weed Eater Repair	Labor/Instil Prt	Equipment repair	Stock repair	Meter Reading	Vehicle Repair	Vehicle Repair	Leak Repair	Vehicle Repair	Vehicle Repair	Leaks & Asphalt	Vehicle Repair	Leaks & Asphalt	Misc.	Misc.	Paint Supplies	Paint	•	Description
	7595-miscellane	7595-miscellana	7595-miscellane	7595-miscellane	7595-miscellane	Ξ.		7510-operating	7510-operating	7510-operating	7510-operating	7510-operating	7510-operating	7510-operating	7510-operating	7510-operating	7510-operating	7510-operating	7510-operating	7510-operating	ys 7509-outside s	ys 7509-outside s	ys 7509-outside s	7509-outside s	7509-outside s												REPAIRS	REPAIRS	REPAIRS	REPAIRS	REPAIRS	ORG, CODED
	7/12/2002	. 7/13/2002	7/13/2002				. 10/30/2001	4/17/2002	7/27/2001	11/16/2001	8/28/2001 H		9/7/2001	4/10/2002	4/10/2002	3/21/2002	3/14/2002	2/27/2002	9/19/2001	7/18/2001	7/19/2001	7/19/2001	7/19/2001	•		5/23/2002	4/15/2002	4/5/2002	3/14/2002	1/1/2002	1/4/2002	11/30/2001	11/27/2001	11/14/2001	8/20/2001	8/20/2001	7/25/2001	7/23/2001	6/18/2002	4/30/2002	1/3/2002	Sry Date C
	1480	1477	1477	147/	1477	1318	1217	14 10	1125	1241	₹	690	1161	1409	1409	38		1335	1202 1	1128	1146	1146	1142		85931												1130	138	1449	1418		eç e
	7/26/2002 Lakewood Hills Manor	7/26/2002 Lakewood Hills Manor	7/26/2002 Lakewood Hills Manor	7/26/2002 Lakewood Hills Mano	7/26/2002 Lakewood Hills Manor	2/22/2002 Lakewood Hills Manor	11/6/2001 Lakewood Hills Manor	5/10/2002 Lakewood Hills Marror	8/2/2001 Lakewood Hills Mano	12/4/2001 Lakewood Hills Mano	8/2/2001 Lakewood Hills Manor		9/24/2001 Lakewood Hills Manor	5/10/2002 Lakewood Hills Manor	5/10/2002 Lakewood Hills Manor	3/29/2002 Lakewood Hills Manor	3/22/2002 Lakewood Hills Manor	3/1/2002 Lakewood Hills Manor	0/23/2001 Lakewood Hills Manor	8/2/2001 Lakewood Hills Mano.	8/24/2001 Lakewood Hills Mano	8/24/2001 Lakewood Hills Manor	B/16/2001 Lakewood Hills Mano	6/28/2002 Lakewood Hills Manor	8/2/2001 Lakewood Hills Manor	Lakewood Hills Manor	Lakewood Hills Mano	Lakewood Hills Manor	Lakewood Hills Manor	Lakewood Hills Manor	Lakewood Hills Mano	Lakewood Hills Manor	Lakewood Hills Manor	Lakewood Hills Mano	Lakewood Hills Manor	Lakewood Hills Manor	8/10/2001 Lakewood Hills Manor	8/10/2001 Lakewood Hills Mano	6/28/2002 Lakewood Hills Mano	5/17/2002 Lakewood Hills Manor	2/15/2002 Lakewood Hills Manor	Check # Date Paid System
ı	s Manor	s Manor	S Manor	Manor	s Manor	Mano	sittanor	s Marvor	s Manor	s Manor	Manor	Manor	s Manor	s Manor	Manor	s Mano	Manor	s Marror	s Manor	s Manor	Manor	Manor	s Manor	Manor	s Manor	s Manor	Manor	Manor	s Manor	Manor	Manor	Manor	Manor	5 Manor	s Manor	Manor	s Manor	Manor	s Manoi	Manor		
13,614,69	4.89	36,63	31.84	3/.00	4.40	48.09	8.17	4	75.77	17.25	129.41	33.20	49.40	4.02	27.23	.45	4.01	2.94	27.03	32,48	522.81	772.29	350.00	4.69	300,00	7.34	94.21	159.25	40.87	56.00	525.00	8.84	37.45	903,90	28.28	9 106 90	11.54	33.27	47.02	22.35	2.87	Repairs
0.00																																					•					2
(0,282.77									/5.//	<b>!</b>	129.41	3									522.81	772.29	350.00	:	300.00										28.28	8,059.40	1.5	33.27	:			Outside of TY Meter Readi
159.25																												159 25														er Reading Ve
141.10																													40.87	56.00		0.84	37.45	<b>;</b>								ng Vehicle Repairs T
21.00	3																			27.00	3										-											Tools A
10.07	4.00	. 00																		0,40	n																					Misc Supp (
5.5	3																																									Chemicals La
10.07 0.00	273					9	073																																			Late Fees 1
1.00	ARO																							<b>8</b> 0, <b>9</b>	9																	Butmon
2,000,1	3																																									Misc. Syst
5,000.1	2 999 72	9	36.63	31.84	37.68	4 98	48.38	8 17	4 3 4	9 6	17 25	0 10	3 5	40 1	400	37.2	4 4	2 9	, !	27.03	9 50	2 5	38	98	38	3.5	17.E		8 8	3 8	25.00		3 8	200	9 5	3.5	10.750	000	200	47.02	22.35	tem Repairs

Total Scotsdale	USA Bluebook	Grainger	Flynn Drilling	Cedar Hill Hard	Tom Wolf Hard	Northern	Erb Equipment	Cedar Hill Hard	Cedar Hill Hard	Cedar Hill Hard	Cadar Hill Hard	Cedar Hill Hard	Vopak USA Inc.	Vopak USA Inc.	Piffel-Payable	Piffel-Payable	Piffel-Payable	Piffel-Payable	Piffel-Payable	Piffel-Payable	Piffel-Payable	Piffel-Payable	Piffel-Payable	Piffel-Payable	Tom Wolf Hard	Jeffco Lawn &	Grainger	Grainger	County Decorati	County Decorati	<ul> <li>County Decorati</li> </ul>	Cedar Hill Hard	Cedar Hill Hard	Cedar Hill Hard	Vendor
•	Flaus	Chlorinator Repair	Air Vent For Well Head	Misc.	Misc.	Telescoping Wand	Echo Pump	Misc.	Misc.	Misc.	Misc.	Misc	Chemicals	Chemicals	Road Straightening	Equipment repair	Stock repair	Vehicle Repair	Vehicle Repair	Leak	Vehicle Repair	Vehicle Repair	Building Work	Vehicle Repair	Well House	Weed Eater Repair	Chlorinator	Chlorinator Repair	Paint	Paint	Paint			Misc	Description
	8595-miscellan		_	8595-miscellan	8510-operating	8510-operating	8510-operating	8510-operating	8510-operating	8510-operating	8510-operating	8510-operating	8504-chemicats	8504-chemicals											REPAIRS	REPAIRS	REPAIRS	REPAIRS	ORG. CODED						
	7/12/2002	5/28/2002		10/30/2001	4/17/2002	11/16/2001	9/7/2001	4/10/2002	3/21/2002	3/14/2002	2/27/2002	9/19/2001			5/23/2002	5/23/2002	4/15/2002	3/14/2002	1/1/2002	12/6/2001	11/30/2001	11/27/2001	11/14/2001	8/20/2001	3/20/2002	6/13/2002	6/24/2002	5/22/2002	10/11/2001	9/24/2001		8/11/2002	3/21/2002	3	Sry Date   Cr
	_	1430 5	1318 2	1217 1	1410 5	1241 1	1181 9	1409 5	1364 3	1354 3	1335	1202 10	1454	1208 10											_			1445 6	1197 10	1177 9	1182 9	1450 6	1364 3	1202 10	Check # Date Paid
	7/26/2002 Scotsdale	5/31/2002 Scotsdale	2/22/2002 Scotsdale	11/6/2001 Scotsdale -	5/10/2002 Scotsdale	12/4/2001 Scotsdale	9/24/2001 Scotsdafe	5/10/2002 Scotsdale	3/29/2002 Scotsdale	3/22/2002 Scotsdale	3/1/2002 Scotsdale	10/23/2001 Scotsdale	6/28/2002 Scotsdafe	0/23/2001 Scotsdale	Scotsdale	Scotsdale	Scotsdale	Scotsdale	Scotsdale	Scotsdale	Scotsdale	Scotsdale	Scotsdale	Scotsdale	3/29/2002 Scotsdale	6/28/2002 Scotsdale	7/19/2002 Scotsdale	6/28/2002 Scotsdale	0/11/2001 Scotsdale	9/24/2001 Scotsdale	9/24/2001 Scotsdale	6/28/2002 Scotsdale	3/29/2002 Scotsdale	_	e Paid System
7,896,78	1.61	11.95	49.09	2.58	1.43	5.39	15.44	9.00	0.45	1.25	0.92	9.11	137.65	77.96	511.25	2.43	31.15	13.52	17.50	120.00	2.14	11.70	5,508.50	8.84	26.58	1.55	247.04	29.51	78.23	277.55	192.98	5.81	85.86	200.83	Repairs
5,755.54																							5,508.50				247.04								g
-,																																			Outside
8.84																								8.84											of TYMet
0.00																																			Outside of TY Meter Reading
																																			Vehicle Repairs Tools
44.86																		13.52	17.50	i	2.14	11.70	!												Repairs To
0.00																																			L
1.61	9	•																																	Misc. Supp
215.61													97.92	127.00	1																				Chemicals
0.73			9.70	7																															Late Fees
1.55						-																				1.30	;								Mowing
0.00																																			Misc.
1,808.04	0.00	1.85	100	100	٠ <u>.</u>	1 43	5 (A)	7.00	8 8	2 4 5	3 6	9 5	9 11	9 6		X	3 <u>4</u>	31 16	9.0	20.00	30.00	9 8	3 5	9 5	20.00	30.00	3 8	20.5	30.00	70 22	777 66	100 00	5 G	85 88 86	System Repairs

Vendor	Description	ORG CODED	Sry Date	The chall	Check afriate Paid   System	System	Repairs	δ	Outside of TY Meter Reading Vehicle Repairs Tools	ter Reading V	ehicle Repairs		Misc Supp (	Chemicals Late Fees	Н	Mowing	Misc. S	System Repairs	
Cedar Hill Hend	Alsc.	REPAIRS	ΙĐ	1202	10/23/2001	1202 10/23/2001 Warren Woods	35.91						ı					19.00	
Cedar Hill Hard.	Misc	REPAIRS	12/13/2001	1277	12/28/2001	12/28/2001 Warren Woods	34.75											4,72	_
Cedar Hill Hard.		REPAIRS	1/3/2002		2/15/2002	2/15/2002 Warren Woods	1.32											7.5	
Cedar Hill Hard.		REPAIRS	6/11/2002	1450	6/2E/2002	6/28/2002 Warren Woods	5.87											20.00	_
Grainger	Chlorinator Repair	REPAIRS	5/22/2002	1445	6/28/2002	6/28/2002 Warren Woods	29.50											7.67	
Grainder	Chlorinator	REPAIRS	8/24/2002	1472	7/19/2002	7/19/2002 Warren Woods	247.03	247.03										300	
Piffel-Payable	Water Leak	! !	8/20/2001	!		Warren Woods	485.00		485.00									3 6	
Piffel-Payable	Vehicle Repair		8/20/2001			Warren Woods	5.30		5.30									5 6	, a
Piffel-Payable			11/14/2001			Warren Woods	2,106.25	2,106.25			į							3 8	
Piffel-Payable	Vehicle Repair		11/27/2001			Warren Woods	7.2				7.04							3 8	
Piffel-Payable	Vehicle Repair		11/30/2001			Warren Woods	1.29				1.29							3 6	
Piffel-Payable	Relocate Water line		12/6/2001			Warren Woods	240.00	240.00										476.00	
Piffet-Payable	Well House-Painting		1/4/2002			Warren Woods	175.00											1000 1000	
Piffel-Payable	Vehicle Repair		1/1/2002			Warren Woods	. 10.50				10.50							8.6	
Piffel-Payable	Vahicle Repair		3/14/2002			Warren Woods	8.03				8.03							3 5	٠.
Piffel-Payable	Stock repair		4/15/2002			Warren Woods	18.51											10.31	
Piffel-Payable	Wtr ix & Asphalt ptch		4/15/2002			Warren Woods	1,377.00											2.75	. ~
Piffet-Payable	Equipment repair		5/23/2002			Warren Woods	1.42											4.5	
Vopak USA Inc.	Chemicals	9504-Chemicals		1208	7/19/2002	7/19/2002 Warren Woods	45.78							45.78				5 6	
Vopak USA Inc.	Chemicals	9504-Chemicals		1454	10/23/2001	10/23/2001 Warren Woods	137.84							3/ 05		5		3 8	, -
Jettco Lawn &	Weed Eater Repair	9509-outside s	6/13/2002	1452	6/28/2002	8/28/2002 Warren Woods	0.92									76.0		3 8	۰.
Cedar Hill Hard.	Misc.	9510-operating		12021	10/23/2001	10/23/2001 Warren Woods	2.38											3 2	, .
Cedar Hill Hard	Misc.	9510-operating		1335	3/1/2002	3/1/2002 Warren Woods	3				,							2 6	
Cedar Hill Hard.	Misc.	9510-operating	3/14/2002	1354	3/22/2002	3/22/2002 Warren Woods	0.76											800	,
Cedar Hill Hard	Misc.	9510-operating		1364	3/29/2002	3/29/2002 Warren Woods	0.28											4.0	,
Cedar Hill Hard.	Misc	9510-operating	4/10/2002	1409	5/10/2002	5/10/2002 Warren Woods	5.35											-	, .
Erb Equipment	Echo Pump	9510-operating	9/7/2001	1181	9/24/2001	9/24/2001 Warren Woods	9.17											7.7	. ~
Northern	Telescoping Wand	8510-operating	_	1241	12/4/2001	12/4/2001 Warren Woods	3.23											46	, ~
Tom Wolf Hard	Misc	9510-operating	4/17/2002	1410	5/10/2002	5/10/2002 Warren Woods	0.86											153	, ~
Cedar Hill Hard.	Misc.	9595-miscellan	10/30/2001	1217	11/6/2001	11/6/2001 Warren Woods	1.52											11.95	
Grainger	Chlorinator Repair	9595-miscellan	5/28/2001	1430	5/31/2002	5/31/2002 Warren Woods	1.95						200					900	
USA Blue Book	Flags	8595-miscellan	7/12/2002	1480	7/26/2002	7/26/2002 Wanen Woods	26.0	00000	00.077	9	28 AR	60	260	183.42	000	0.92	000	1,715.26	ماد
Total Warren Woods	× × ×						4 681 01	2,033,48		3	4.5	20.0					đ		Į

KMB Utility Informal Rate Case Test Year Ending 7/31/02

Salary Allocation and

Capitalization Analysis

	а	b	c (*see below)	d (b*c) Reallocate	e (a+d)	f Operator's	g	ħ
	Total			G/O Hours		Reported	Staff	Staff
Total Operator Hours	Reported	General	Customer	By	Reallocated	Salary	Adjusted	Salary
Aug 1, 2001 - Jul 31, 2002	Hours	Office Hours	Allocation	Customers	Hours	Allocation	Hours	Allocation
Cedar Hill	300	102	25,10%	26	326	17.66%	330	17,90%
Cape Rock	489	102	30.68%	31	520	28.22%	546	29,61%
Crestview Acres	130	102	7.39%	8	138	7.46%	150	8,13%
High Ridge	159	102	8.93%	9	168	9.12%	105	5.69%
Hillshine	35	102	4,04%	4	39	2.12%	95	5.15%
Lakewood Hills	301	102	15.62%	16	317	17.19%	506	27.44%
Scotsdale	193	102	5.16%	5	198	10.75%	60	3.25%
Warren Woods	135	102	3.07%	3	138	7.49%	52	2.82%
General Office & Classes	102		pi a, mangga	·	marks and a constraint and			
	1844		100.00%	102	1844	100.00%	1844	100.00%

	Capitalized	Reallocated	Capitalization
Total Operator Capital Projects	Hours	Hours	Percentage
Cedar Hill	6	326	1.84%
Cape Rock	132	520	25.27%
Crestview Acres	17	138	12.00%
High Ridge	41	168	24.24%
Hillshine	9	39	23.00%
Lakewood Hills	41	317	12.78%
Scotsdale	22	198	10.97%
Warren Woods	10	138	7.24%
	276	1844	

		Customer
*Customer Allocators	Customers	Allocation
Cedar Hill	180	25,10%
Cape Rock	220	30.68%
Crestview Acres	53	7.39%
High Ridge	64	8.93%
Hillshine	29	4.04%
Lakewood Hills	112	15.62%
Scotsdale	37	5,16%
Warren Woods	22	3.07%
	717	100.00%

\$	Ann's Annualized	Ann's Salary	Ann's Allocated
Ann's Salary = \$13,000	Salary	Allocation	Salary
Cedar Hill	13,000	25.10%	3,263.60
Cape Rock	13,000	30.68%	3,988.84
Crestview Acres	13,000	7.39%	960.95
High Ridge	13,000	8.93%	1,160.39
Hillshine	13,000	4.04%	525.80
Lakewood Hills	13,000	15.62%	2,030.68
Scotsdale	13,000	5.16%	670.85
Warren Woods	13,000	3.07%	398.88
	.,	100.00%	13,000.00

Vicki's Salary = \$24,024	Vicki's Annualized Salary	Vicki's Salary Allocation	Vicki's Allocated Salary
Cedar Hill	24,024	25.10%	6,031.13
Cape Rock	24,024	30.68%	7,371.38
Crestview Acres	24,024	7,39%	1,775.83
High Ridge	24,024	8.93%	2,144.40
Hilishine	24,024	4.04%	971.68
Lakewood Hills	24,024	15.62%	3,752.70
Scotsdale	24,024	5,16%	1,239.73
Warren Woods	24,024	3.07%	737.14
	=	100.00%	24,024.00

Donnie's Salary = \$32,000	Donnie's Annualized Salary	Donnie's Salary Allocation*	Donnie's Allocated Salary	Capitalization Percentage	Donnie's Capitalized Salary	Donnie's O/M Salary
	32,000	17.90%	5726.68	1,84%		5621.15
	•					
Cape Rock	32,000	29.61%	9475.05	25.27%	2394.73	7080.33
Crestview Acres	32,000	8.13%	2603.04	12.00%	312.27	2290.76
Hìgh Ridge	32,000	5.69%	1822,13	24.24%	441,70	1380.43
Hillshine	32,000	5.15%	1648.59	23.00%	379.22	1269.37
Lakewood Hills	32,000	.27.44%	8780.91	12.78%	1122.09	7658.82
Scotsdale	32,000	3.25%	1041,21	10.97%	114.22	926.99
Warren Woods	32,000	2.82%	902.39	7.24%	65.33	837.06
	· *	100.00%	32,000.00		4,935.09	27,064.91

<sup>\*</sup>Uses Staff Allocation Percentages

Donnie's Salary = \$32,000	Donnie's Allocated P/R Tax	Capitalization Percentage	Capitalized P/R Tax	O&M P/R Tax
Cedar Hill	542.60	1.84%	10.00	532.60
Cape Rock	897,76	25,27%	226.90	670.86
Crestview Acres	246.64	12.00%	29.59	217.05
High Ridge	172.65	24.24%	41.85	130.80
Hillshine	156.20	23.00%	35.93	120.27
Lakewood Hills	831.99	12,78%	106.32	725.67
Scotsdale	98.66	10.97%	10.82	87.83
Warren Woods	85.50	7.24%	6.19	79.31
TOTAL	3032.00		467.60	2564.40

Vicki's Salary = \$24,024	Vicki's Allocated P/R Tax	Capitalization Percentage	Capitalized P/R Tax	O&M _P/R Tax
Cedar Hill	574.95	9993		574.95
Cape Rock	702.72			702.72
Crestview Acres	169.29			169.29
High Ridge	204.43			204.43
Hillshine	92.63			92.63
Lakewood Hills	357,75			357,75
Scotsdale	118.18			118.18
Warren Woods	70.27			70.27
TOTAL	2290.23			2290.23

Ann's Salary = \$13,000	Ann's Allocated P/R Tax	Capitalization Percentage	Capitalized P/R Tax	O&M P/R Tax
Cedar Hill	317.57			317.57
Cape Rock	388.15			388.15
Crestview Acres	93.51			, 93.51
Hìgh Ridge	112.91			112.91
Hillshine	51.16			51,16
Lakewood Hills	197.60			197.60
Scotsdale	65.28			65.28
Warren Woods	38.81			38.81
TOTAL	1265.00			1265.00