ILLINOIS ENVIRONMENTAL PROTECTION AGENCY



1021 NORTH GRAND AVENUE EAST, P.O. BOX 19276, SPRINGFIELD, ILLINOIS 62794-9276 • (217) 782-3397 PAT QUINN, GOVERNOR

JOHN J. KIM, INTERIM DIRECTOR

Filed April 8, 2014 **Data Center** Missouri Public Service Commission

(217) 782-5544

CERTIFIED MAIL RETURN RECEIPT REQUESTED

7010 2780 0002 1167 6062

February 13, 2013

Mr. John C. Pozzo 1 Ameren Plaza 1901 Chouteau Ave. St. Louis, MO 63103

Re:

Notice of Intent to Pursue Legal Action

Ameren Coffeen Generating Station

Identification No.: 6287

Violation Notice: W-2012-00064

Dear Mr. Pozzo:

RECEIVED

FEB 15 2013

IEPA/CAS

This Notice of Intent to Pursue Legal Action is provided pursuant to Section 31(b) of the Illinois Environmental Protection Act ("Act"), 415 ILCS 5/31(b)(2012). The Illinois Environmental Protection Agency ("Illinois EPA") is providing this notice because you have failed to respond adequately to the Violation Notice dated June 27, 2012, and issued by the Illinois EPA within the time frame required by Section 31 of the Act.

The Illinois EPA is providing this notice because it may pursue legal action for the violations of environmental statutes, regulations and permits specified in Attachment A. The Notice of Intent to Pursue Legal Action provides the opportunity to schedule a meeting with representatives of the Illinois EPA to attempt to resolve the violations of the Act, regulations and permits specified in Attachment A. If a meeting is requested, it must be held within thirty (30) days of receipt of this notice unless an extension of time is agreed to by the Illinois EPA.

If you wish to schedule a meeting with representatives of the Illinois EPA or have any questions, please contact Joey Logan-Wilkey at (217) 782-5544 within twenty (20) days of your receipt of this notice.

Sincerely,

Connie L. Tonsor Deputy Counsel

Division of Legal Counsel

Attachment

JLW:jlw'p: Ameren

IEPA - DIVISION OF RECORDS MANAGEMENT RELEASABLE

MAR 28 2013

REVIEWER EAV

4302 N. Main St., Rockford, IL 61103 (815)987-7760 595 S. State, Eigin, IL 60123 (847)608-3131 2125 S. First St., Champaign, IL 61820 (217)278-5800 2009 Mall St., Collinsville, IL 62234 (618)346-5120 9511 Harrison St., Des Plaines, IL 60016 (847)294-4000 5407 N. University St., Arbor 113, Peoria, IL 61614 (309)693-5462 2309 W. Main St., Suite 116, Marion, IL 62959 (618;993-7200 100 W. Randolph, Suite 10-300, Chicago, IL 60601 (312)814-6026

PLEASE PRINT ON RECYCLED PAPER

Intervenor Exhibit No. 312 Date 3:31-2014 Reporter Stewart PAGE NO. 2 OF 3

ATTACHMENT A

AMEREN, COFFEEN GENERATING STATION, ID:6287 VIOLATION NOTICE NO. W-2012-00064:

Violation

Description

APW-2 continued

Parameter	Sample Value	GW Standard	Collection Date
TDS	1700 mg/l	1200 mg/l.	05/04/2011
TDS	1600 mg/l	1200 mg/l	01/26/2011
TDS	1810 mg/l	1200 mg/l	12/01/2010

Rule/Reg. Section 12 of the Act, 415 ILCS 5/12, 35 Ill. Adm. Code 620.115, 620.301, 620.401, 620.405, and 620.410.

Violation

Description

Operations at ash impoundments have resulted in violations of the Groundwater Quality Standards at monitoring well APW-3 for the following constituents:

Parameter	Sample	Value	GW Standard	Collection Date
Boron	2.1	mg/l	2.0 mg/l	01/25/2012
Boron	2.5	mg/l	2.0 mg/l	01/26/2011
Boron	2.07	mg/l	2.0 mg/l	12/01/2010
Manganese	0.37	mg/1	0.150 mg/l	01/25/2012
Manganese	0.866	mg/1	0.150 mg/l	11/11/2011
Manganese	0.84	mg/l	0.150 mg/l	07/28/2011
Manganese	0.85	mg/l	0.150 mg/l	05/04/2011
Manganese	0.44	mg/l	0.150 mg/l	01/26/2011
Manganese	0.866	mg/l	0.150 mg/l	12/01/2010
Sulfate	830	mg/l	400 mg/l	01/25/2012
Sulfate	761	mg/l	400 mg/l	11/11/2011
Sulfate	940	mg/l	400 mg/l	05/04/2011
Sulfate	810	mg/1	400 mg/l	01/26/2011
Sulfate	761	mg/l	400 mg/l	12/01/2010
TDS	1900	mg/l	1200 mg/l	01/25/2012
TDS	1760	mg/l	1200 mg/l	11/11/2011
TDS	2100	mg/l	1200 mg/l	07/28/2011
TDS	1800	mg/l	1200 mg/l	05/04/2011
TDS	1800	mg/l	1200 mg/l	01/26/2011
TDS	1760	mg/1	1200 mg/l	12/01/2010

Rule/Reg. Section 12 of the Act, 415 ILCS 5/12, 35 Ill. Adm. Code 620.115, 620.301, 620.401, 620.405, and 620.410.

PAGE NO. 1 OF 3

ATTACHMENT A

AMEREN, COFFEEN GENERATING STATION, ID: 6287 VIOLATION NOTICE NO. W-2012-00064:

A review of information available to the Illinois EPA indicates the following on-going violations of statutes, regulations, or permits. Included with each type of violation is an explanation of the activities that the Illinois EPA believes may resolve the violation.

Groundwater Quality

No person shall cause, threaten or allow the release of any contaminant to a resource groundwater such that: treatment or additional treatment is necessary to continue an existing use or to assure a potential use of such groundwater; or an existing or potential use of such groundwater is precluded. No person shall cause, threaten or allow the release of any contaminant to groundwater so as to cause a groundwater quality standard to be exceeded. Ameren must take actions to mitigate existing contamination and prevent the continuing release of contaminants into the environment.

Violation Description

Operations at ash impoundments have resulted in violations of the Groundwater Quality Standards at monitoring well APW-2 for the following constituents:

Parameter	Sample	Value	GW Standard	Collection Date
Boron	7.4	mg/l	2.0 mg/l	01/25/2012
Boron	8.1	mg/l	2.0 mg/l	11/11/2011
Boron	6.3	mg/l	2.0 mg/l	07/28/2011
Boron	6.7	mg/l	2.0 mg/l	05/04/2011
Boron	7.2	mg/l	2.0 mg/l	01/26/2011
Boron	7.16	mg/l	2.0 mg/l	12/01/2010
Manganese	0.730	mg/l	0.150 mg/l	01/25/2012
Manganese	0.40	mg/l	0.150 mg/l	11/11/2011
Manganese	0.410	mg/l	0.150 mg/l	07/28/2011
Manganese	0.530	mg/l	0.150 mg/l	05/04/2011
Manganese	0.418	mg/l	0.150 mg/l	12/01/2010
Sulfate	840	mg/l	400 mg/l	01/25/2012
Sulfate	650	mg/l	400 mg/l	11/11/2011
·Sulfate	840	mg/l	400 mg/l	05/04/2011
Sulfate	840	mg/l	400 mg/l	01/26/2011
Sulfate	833	mg/l	400 mg/l	.12/01/2010
TDS	1600	mg/l	1200 mg/l	01/25/2012
TDS	1600	mg/l	1200 mg/l	11/11/2011
TDS	1600	mg/l	1200 mg/l	07/28/2011

PAGE NC. 3 OF 3

ATTACHMENT A

AMEREN, COFFEEN GENERATING STATION, ID:6287 VIOLATION NOTICE NO. W-2012-00064:

Violation

Description

Operations at ash impoundments have resulted in violations of the Groundwater Quality Standards at monitoring well APW-4 for the following constituents:

Parameter	Sample	Value	GW Standard	Collection Date
Boron	3.6	mg/1	2.0 mg/l	01/25/2012
Boron	3.9	mg/1	2.0 mg/1	11/11/2011
Boron	3.2	mg/l	2.0 mg/l	07/25/2011
Boron	3.9	mg/l	2.0 mg/l	05/04/2011
Boron	3.8	mg/l	2.0 mg/l	01/26/2011
Boron	3.54	mg/l	2.0 mg/l	12/01/2010
Manganese	0.460	mg/1	0.150 mg/l	01/25/2012
Manganese	0.670	mg/l	0.150 mg/l	11/11/2011
Manganese	0.740	mg/1	0.150 mg/I	07/25/2011
Manganese	0.81	mg/l	0.150 mg/l	05/04/2011
Manganese	0.240	mg/l	0.150 mg/l	01/26/2011
Manganese	0.78	mg/l	0.150 mg/l	12/01/2010
Sulfate	680	mg/1	400 mg/l	01/25/2012
Sulfate	450	mg/l	400 mg/l	11/11/2011
Sulfate	750	mg/l	400 mg/l	07/25/2011
Sulfate	650	mg/l	400 mg/l	05/04/2011
Sulfate	670	mg/l	400 mg/l	01/26/2011
Sulfate	600	mg/l	400 mg/l	12/01/2010
TDS	1300	mg/l	1200 mg/l	11/11/2011
TDS	1300	mg/l	1200 mg/l	07/25/2011
TDS	1300	mg/1	1200 mg/l	05/04/2011

Rule/Reg. Section 12 of the Act, 415 ILCS 5/12, 35 Ill. Adm. Code 620.115, 620.301, 620.401, 620.405, and 620.410.



Coffeen Power Station (IL0000108) Monitor Wells **Montgomery County**



Legend



Monitor Wells

- Pr-body no CCA -lown form / St.11 using 580 870 1,160 Feet

SOURCE INFORMATION

Monitoring well data obtained from Ameren Energy. Bing maps obtained from ESRI Map compiled and created by the groundwater section.