







































Taum Sauk Upper Reservoir Failure - Parapet Wall Inspection

Photos: Missouri Department of Natural Resources