

Spire
Community Services Department
Missouri Public Service Commission
CASD Investigator: Alicia Johnson for MPSC Investigator: Charmion Osborn

Customer Info:

Account ID: 6645430000
Mary A Jackson
5641 Summit Place
Saint Louis, MO 63136

Complaint ID: C201801374

04/10/18, Meter test results:

Prover # 1574

Operator # 00762

OPEN: 99.4

CHECK: 98.7

Index read 4416

FILED²

OCT 1 2019

Missouri Public
Service Commission

Spire test meters at 100% (open rate) and 20% (check rate) of the capacity of the meter. This is called a two-point check since we are looking at two different flow rates. The meter must be within +/-2% of exact of each of these rates and within +/-2% of each other to be considered a properly operating meter. All meters are tested with equipment which is traceable to the National Bureau of Standards and Testing and are tested in a climate-controlled room.

Spire Exhibit No. 5
Date 9-13-19 Reporter SET
File No. GC-2019-0331

