

Completion Information

Date	02/13/2017	Action	MTRS12 High Bill Investigate	Action Code	12
FAID	6641162517	Employee	00219 - Javaux David J	CGI #	0277
Call Number	6641162517	Helper		FI#	
Action Number	1	Helper Duration			

FILED²

OCT 1 2010

Action Status

Status	COMP	Task	High Bill Investigate
Cancel Reason			

Missouri Public Service Commission

Customer Information

Name	JACKSON, MARY A	Address	5641 SUMMIT PL, SAINT LOUIS
------	-----------------	---------	-----------------------------

Meter Information

Current Meter Information		Meter Status	
Meter Number	000959769	Meter Found	I
Device Number	22274249	Disc Location Found	NA
Meter Size	275-R	SP Source Status Found	C
Number of Dials	4	Meter Left	I
Meter Pressure	7IN WC	Disc Location Left	NA
Meter Location	OUT	SP Source Status Left	C
Operating Pressure	LP	AMR Battery	P
Meter Status	On	Meter Insulated	Y
Disc Location		Removal Reason	
SP Source Status	C	Meter Reads	
Last Front Meter Read	2763	Front	2832
Last 2nd Meter Read		2nd	
		Rear	
		Veeder	

ERT Changed?

New ERT Serial Number

Spire Exhibit No. 4
Date 9-13-19 Reporter SET
File No. GC-2019-0331



New Meter Information

Meter Reads

Number

Front

Rear

Location

2nd

Veeder

New Meter Manufacturer

Company Facility Inspections

Inside Set

Curb Box Survey

Extra Bar Hole

Outside

SEI

Far Curb

Grunsky Config

Outside Wall

Near Curb

Branch/Yard Line

Cone Survey

Tee

Soil Subsidence

Curb Box Survey

Extra Bar Hole

Odorant Inspection

Inside

I/S Inspection

I/S Insp Details

Inside Reading

Reason Not Taken

Regulator

Regulator Manufacturer

Regulator Model Number

Regulator Details Correct?

New Regulator Manufacturer

New Regulator Model Number

Sanitary Sewer

Was the outside sanitary sewer checked located on this premise?

Enter the location of the outside sanitary sewer checked

Fuel Run Inspection

Pressure Test Method

P/T Method

NR

Secondary Meter Number

Secondary Meter Manufacturer

Low Flow

Low Flow

Set Pressure

Set Pressure

0.25

Set Pressure Left

Set Pressure Metric

Lock Up

Lock Up

0.275

Lock Up Left

Lock Up Metric

Fuel Runs

Accessible Visual F/R Inspection

Y

F/R Certification

Appliance Inspections

Appliance	Setting	Appliance left	Pass/Fail	Hazard 1	Hazard 2	Violation 1	Violation 2
D	E	EFC					
HH	NA	ALO					
R	NA	ALO					
WH	N	ALO					

Comments

HBI complete. Clocked meter for range, HH, and WH.

Additional Comments

--

Follow Up**C&M Work Needed**

NO

Need Additional Parts

--

Event Dates

Event	Date/Time	Report Time
Diary		
Dispatch	02/13/2017 06:13:00 AM	02/13/2017 06:13:00 AM
Acknowledge Dispatch	02/13/2017 07:35:00 AM	02/13/2017 07:35:00 AM
En Route	02/13/2017 07:35:00 AM	02/13/2017 07:35:00 AM
Arrival on Site	02/13/2017 08:05:00 AM	02/13/2017 08:05:00 AM
Complete	02/13/2017 09:05:00 AM	02/13/2017 08:59:00 AM
Visited		
Close		
Cancel Action		
Suspend		
No Access		
Vendor Cancel		
Access Left ON		