

Exhibit No:
Issue: Worn Out or Deteriorated
Condition of Cast Iron and Bare
Steel
Witness:
Type of Exhibit: Photographs of Replaced Pipe
Sponsoring Party: Spire Missouri Inc. (Tim Goodson)
Case Nos.: GO-2018-0309, GO-2018-0310
Date Prepared: May 13, 2020

SPIRE MISSOURI INC.

CASE NOS. GO-2018-0309, GO-2018-0310

**PHOTOGRAPHS OF REPLACED PIPE
CAST IRON, SPIRE EAST**

Figure 7, Spire East, Cast Iron, Work Order #14465103




Figure 8, Spire East, Cast Iron, Work Order #14450752



Figure 9, Spire East, Cast Iron



Figure 11, Spire East, Cast Iron



Figure 12, Spire East, Cast Iron, Work Order #13787240



Figure 13, Spire East, Cast Iron



Figure 14, Spire East, Cast Iron, Work Order #14465103



Figure 15, Spire East, Cast Iron, Work Order #14465103




Figure 17, Spire East, Cast Iron



Figure 18, Spire East, Cast Iron



Figure 19, Spire East, Plastic Pipe



Figure 20, Spire East, Plastic Pipe



Figure 25, Spire East, Cast Iron



Figure 26, Spire East, Cast Iron



Figure 27, Spire East, Cast Iron



Figure 28, Spire East, Cast Iron, Work Order #18588610



Figure 49, Spire East, Cast Iron



Figure 50, Spire East, Cast Iron



Figure 52, Spire East, Cast Iron, Work Order #14465103




Figure 53, Spire East, Cast Iron

