

Exhibit No:
Issue: Worn Out or Deteriorated
Condition of Cast Iron and Bare
Steel
Witness:
Type of Exhibit: Photographs of Replaced Pipe
Sponsoring Party: Spire Missouri Inc. (Tim Goodson)
Case Nos.: GO-2018-0309, GO-2018-0310
Date Prepared: May 13, 2020

SPIRE MISSOURI INC.

CASE NOS. GO-2018-0309, GO-2018-0310

**PHOTOGRAPHS OF REPLACED PIPE
SPIRE WEST, BARE STEEL**

Figure 23, Spire West, Bare Steel, Work Order #17219240



Figure 24, Spire West, Bare Steel



Figure 29, Spire West, Bare Steel, Work Order #17612824




Figure 30, Spire West, Bare Steel



Figure 32, Spire West, Bare Steel



Figure 34, Spire West, Bare Steel, Work Order #15800904




Figure 35, Spire West, Bare Steel



Figure 36, Spire West, Bare Steel



Figure 37, Spire West, Bare Steel, Work Order #15800904



Figure 38, Spire West, Bare Steel, Work Order #15107462



Figure 45, Spire West, Bare Steel



Figure 46, Spire West, Bare Steel



Figure 54, Spire West, Bare Steel, Work Order #17611805/17612824

