



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend				10776		Laboratory Name Lakeland Laboratories			
Street Address									
City				Zip		Certification Number 00400			
County Taney				ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results		Chlorine (mg/l)		
					Total Coliform	E.Coli	Total	Free	
11-19-13	10:40	R	Well #1	S	A	A		1.76	
Total Routine Samples Analyzed: 1				Signed: <i>Mark P. Smith</i>			Date: <i>11/20/13</i>		
Monitoring Violation		Yes		x		No			
MCL Violation		Yes		x		No			

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colilert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend					Laboratory Name Lakeland Laboratories				
Street Address 10770									
City			Zip		Certification Number 00400				
County Taney			ID Number MO5036117						
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results		Chlorine (mg/l)		
					Total Colform	E.Coli	Total	Free	
11-19-13	10:15	R	Well #2	S	A	A		.51	
Total Routine Samples Analyzed: 1				Signed: <i>Mark R. Smith</i>			Date: <i>11/20/13</i>		
Monitoring Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No				
MCL Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No				

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colilert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend					Laboratory Name Lakeland Laboratories				
Street Address 10729									
City			Zip		Certification Number 00400				
County Taney			ID Number MO5036117						
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results		Chlorine (mg/l)		
					Total Coliform	E.Coli	Total	Free	
12-03-13	11:00	R	Well #1		A	A		1.15	
Total Routine Samples Analyzed: 1					Signed: <i>Mark P. Smith</i>		Date: 12/5/13		
Monitoring Violation			Yes	x	No				
MCL Violation			Yes	x	No				

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colilert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend				10733		Laboratory Name Lakeland Laboratories			
Street Address									
City				Zip		Certification Number 00400			
County Taney				ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results		Chlorine (mg/l)		
					Total Colform	E.Coli	Total	Free	
12-03-13	10:15	R	Well #2		A	A		.91	
Total Routine Samples Analyzed: 1				Signed: <i>Mark Smith</i>			Date: <i>12/5/13</i>		
Monitoring Violation		Yes	x	No					
MCL Violation		Yes	x	No					

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Collert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend					Laboratory Name Lakeland Laboratories				
Street Address 10770									
City			Zip		Certification Number 00400				
County Taney			ID Number MO5036117						
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results		Chlorine (mg/l)		
					Total Colform	E.Coli	Total	Free	
11-19-13	10:15	R	Well #2	S	A	A		.51	
Total Routine Samples Analyzed: 1				Signed: <i>Mark P. Smith</i>			Date: <i>11/20/13</i>		
Monitoring Violation		Yes	<input checked="" type="checkbox"/>	No					
MCL Violation		Yes	<input checked="" type="checkbox"/>	No					

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colilert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend					Laboratory Name Lakeland Laboratories				
Street Address 10964									
City			Zip		Certification Number 00400				
County Taney			ID Number MO5036117						
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results		Chlorine (mg/l)		
					Total Coliform	E.Coli	Total	Free	
01-25-14	11:30	R	140 Cox	L-03	A	A		1.2	
Total Routine Samples Analyzed: 2				Signed: <i>Mark D. Smith</i>			Date: <i>2/4/14</i>		
Monitoring Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No				
MCL Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No				

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Collert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend					10967					Laboratory Name Lakeland Laboratories			
Street Address													
City					Zip					Certification Number 00400			
County Taney					ID Number MO5036117								
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results		Chlorine (mg/l)						
					Total Coliform	E.Coli	Total	Free					
01-25-14	11:45	R	226 Rogers	L-06	A	A				1.2			
Total Routine Samples Analyzed: 2					Signed: <i>Mark Smith</i>			Date: 2/4/14					
Monitoring Violation			Yes	x	No								
MCL Violation			Yes	x	No								

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Collert*)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 1 well) 11008					Laboratory Name Lakeland Laboratories			
Street Address					Certification Number 00400			
City			Zip					
County Taney			ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Total Coliform	Results E.Coli	Chlorine Total	(mg/l) Free
02-25-14	1625	R	265 Creed	L-	A	A		2.01
Total Routine Samples Analyzed: 2					Signed: <i>Mark D. Smith</i>		Date: <i>3/3/14</i>	
Monitoring Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No			
MCL Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No			

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colifert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report


Public Water System Name Moore Bend (on # 2 well) 11004					Laboratory Name Lakeland Laboratories			
Street Address								
City			Zip		Certification Number 00400			
County Taney			ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results		Chlorine (mg/l)	
					Total Coliform	E.Coli	Total	Free
02-25-14	1630	R	265 Creed	L-	A	A		1.4
Total Routine Samples Analyzed: 2				Signed: <i>Mark Smith</i>		Date: 3/3/14		
Monitoring Violation		Yes	x	No				
MCL Violation		Yes	x	No				

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colilert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report


Public Water System Name Moore Bend (on # 1 well)					11028		Laboratory Name Lakeland Laboratories			
Street Address										
City					Zip		Certification Number 00400			
County Taney					ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results		Chlorine (mg/l)			
					Total Coliform	E.Coli	Total	Free		
03-08-14	1455	R	140 Cox Rd.	L-03	A	A		2.0		
Total Routine Samples Analyzed: 2					Signed: 		Date: 3/12/14			
Monitoring Violation		Yes	x	No						
MCL Violation		Yes	x	No						

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Collert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 2 well) 11078					Laboratory Name Lakeland Laboratories			
Street Address					Certification Number 00400			
City			Zip					
County Taney			ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results Total Colform	E.Coli	Chlorine (mg/l) Total Free	
03-08-14	1500	R	226 Rogers Rd.	L-06	A	A	1.8	
Total Routine Samples Analyzed: 2					Signed: 		Date: 3/12/14	
Monitoring Violation		Yes	x	No				
MCL Violation		Yes	x	No				

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colilert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 2 well) 11185					Laboratory Name Lakeland Laboratories			
Street Address								
City			Zip		Certification Number 00400			
County Taney			ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results		Chlorine (mg/l)	
					Total Coliform	E.Coli	Total	Free
04-06-14	1125	R	226 Rogers Rd.	L-06	A	A		1.71
Total Routine Samples Analyzed: 2					Signed: <i>Mark Smith</i>		Date: 5/5/14	
Monitoring Violation		Yes	x	No				
MCL Violation		Yes	x	No				

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colilert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 1 well) 11152					Laboratory Name Lakeland Laboratories			
Street Address								
City			Zip		Certification Number 00400			
County Taney			ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results Total Colform	E.Coli	Chlorine (mg/l) Total	Free
04-06-14	1140	R	140 Cox Rd.	L-03	A	A		1.66
Total Routine Samples Analyzed: 2					Signed: <i>Mark P. Smith</i>		Date: <i>5/5/14</i>	
Monitoring Violation		Yes	x	No				
MCL Violation		Yes	x	No				

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colliert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 1 well) 11319					Laboratory Name Lakeland Laboratories			
Street Address								
City			Zip		Certification Number 00400			
County Taney			ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Total Coliform	Results E.Coll	Chlorine (mg/l) Total Free	
05-28-14	1200	R	140 Cox Rd.	L-03	A	A		1.50
Total Routine Samples Analyzed: 2					Signed: <i>Mark Smith</i>		Date: <i>6/2/14</i>	
Monitoring Violation		Yes	x	No				
MCL Violation		Yes	x	No				

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Collert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 2 well) 11249					Laboratory Name Lakeland Laboratories			
Street Address								
City			Zip		Certification Number 00400			
County Taney			ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results Total Coliform	E.Coli	Chlorine (mg/l) Total Free	
05-28-14	1220	R	226 Rogers Rd.	L-06	A	A	1.6	
Total Routine Samples Analyzed: 2					Signed: <i>Mark Smith</i>		Date: <i>6-2-14</i>	
Monitoring Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No			
MCL Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No			

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colilert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 1 well) 11356					Laboratory Name Lakeland Laboratories			
Street Address								
City			Zip		Certification Number 00400			
County Taney			ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results		Chlorine (mg/l)	
					Total Coliform	E.Coli	Total	Free
06-15-14	1130	R	432 Cox Rd.	L-11	A	A		1.45
Total Routine Samples Analyzed: 2					Signed: <i>[Signature]</i>		Date: 6/19/14	
Monitoring Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No			
MCL Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No			

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Collert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 2 well) 11361					Laboratory Name Lakeland Laboratories			
Street Address					Certification Number 00400			
City			Zip					
County Taney			ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Total Coliform	Results E.Coli	Chlorine Total	(mg/l) Free
06-22-14	1200	R	336 Dallas	L-07	A	A		1.61
Total Routine Samples Analyzed: 2					Signed: <i>Mark P. Smith</i>		Date: <i>7/3/14</i>	
Monitoring Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No			
MCL Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No			

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colilert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 2 well) 11361					Laboratory Name Lakeland Laboratories			
Street Address								
City			Zip		Certification Number 00400			
County Taney			ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Total Coliform	Results E.Coli	Chlorine (mg/l) Total Free	
07-12-14	1055	R	242 Gregory	L-08	A	A	1.14	
Total Routine Samples Analyzed: 2					Signed: <i>Mark Smith</i>		Date: <i>7/24/14</i>	
Monitoring Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No			
MCL Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No			

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Coliort®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 1 well) 11568					Laboratory Name Lakeland Laboratories					
Street Address										
City				Zip		Certification Number 00400				
County Taney				ID Number MO5036117						
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Total Coliform	Results E.Coli	Chlorine (mg/l) Total Free			
07-27-14	1100	R	140 Cox Rd.	L-03	A	A	1.90			
Total Routine Samples Analyzed: 2					Signed: <i>Mark P. Smith</i>			Date: 7/29/14		
Monitoring Violation		Yes	x	No						
MCL Violation		Yes	x	No						

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Coli-ert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 1 well) 11615					Laboratory Name Lakeland Laboratories			
Street Address								
City				Zip		Certification Number 00400		
County Taney				ID Number MO5036117				
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results Total Coliform	E.Coll	Chlorine (mg/l) Total	Free
08-02-14	1145	R	140 Cox Rd.	L-03	A	A		1.61
Total Routine Samples Analyzed: 2				Signed: <i>Mona Smith</i>		Date: 8/5/14		
Monitoring Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No			
MCL Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No			

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colilert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 2 well) 11625					Laboratory Name Lakeland Laboratories				
Street Address									
City			Zip		Certification Number 00400				
County Taney			ID Number MO5036117						
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results		Chlorine (mg/l)		
					Total Coliform	E.Coli	Total	Free	
08-02-14	1200	R	432 Cox	L-11	A	A		1.52	
Total Routine Samples Analyzed: 2					Signed: <i>Mark J. Smith</i>		Date: <i>8/5/14</i>		
Monitoring Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No				
MCL Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No				

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Collert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 1 well) 11698					Laboratory Name Lakeland Laboratories				
Street Address									
City			Zip		Certification Number 00400				
County Taney			ID Number MO5036117						
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results		Chlorine (mg/l)		
					Total Coliform	E.Coll	Total	Free	
09-17-14	1600	R	140 Cox Rd.	L-03	A	A		1.20	
Total Routine Samples Analyzed: 2				Signed: <i>Mark P. Smith</i>			Date: 9/19/14		
Monitoring Violation		Yes	x	No					
MCL Violation		Yes	x	No					

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colilert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 2 well) 11675					Laboratory Name Lakeland Laboratories			
Street Address								
City			Zip		Certification Number 00400			
County Taney			ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results Total Coliform	E.Coli	Chlorine (mg/l) Total	Free
09-17-14	1630	R	354 Cox Rd.	L-09	A	A		1.41
Total Routine Samples Analyzed: 2				Signed: <i>Mark P. Smith</i>		Date: 9/19/14		
Monitoring Violation		Yes	x	No				
MCL Violation		Yes	x	No				

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colilert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 1 well) 11845					Laboratory Name Lakeland Laboratories			
Street Address					Certification Number 00400			
City			Zip					
County Taney			ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample	Results	Chlorine (mg/l)	
					Total Coliform	E.Coli	Total	Free
10-19-14	1500	R	140 Cox Rd.	L-03	A	A		0.71
Total Routine Samples Analyzed: 2				Signed: <i>Mark P. Smith</i>		Date: <i>10/27/14</i>		
Monitoring Violation		Yes	<input checked="" type="checkbox"/>	No				
MCL Violation		Yes	<input checked="" type="checkbox"/>	No				

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colilert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 2 well) 11914					Laboratory Name Lakeland Laboratories			
Street Address								
City			Zip		Certification Number 00400			
County Taney			ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Total Coliform	Results E.Coli	Chlorine (mg/l) Total Free	
10-19-14	1515	R	336 Dallas	L-07	A	A		0.76
Total Routine Samples Analyzed: 2					Signed: <i>Mark P. Smith</i>		Date: 10-27-14	
Monitoring Violation		Yes	x	No				
MCL Violation		Yes	x	No				

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colilert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 1 well) 11989					Laboratory Name Lakeland Laboratories			
Street Address								
City			Zip		Certification Number 00400			
County Taney			ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results		Chlorine (mg/l)	
					Total Coliform	E.Coli	Total	Free
11-09-14	0930	R	140 Cox Rd.	L-03	A	A		0.83
Total Routine Samples Analyzed: 2					Signed: <i>Mark Smith</i>		Date: 11/24/14	
Monitoring Violation			Yes	x	No			
MCL Violation			Yes	x	No			

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Collert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report


Public Water System Name Moore Bend (on # 2 well) 11990					Laboratory Name Lakeland Laboratories			
Street Address								
City			Zip		Certification Number 00400			
County Taney			ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results Total Coliform	Results E.Coli	Chlorine (mg/l) Total Free	
11-09-14	1000	R	336 Dallas	L-07	A	A		0.78
Total Routine Samples Analyzed: 2					Signed: <i>Mark P. Smith</i>		Date: <i>11/14/14</i>	
Monitoring Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No			
MCL Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No			

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Collert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 1 well) 12035					Laboratory Name Lakeland Laboratories			
Street Address					Certification Number 00400			
City			Zip					
County Taney			ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results Total Coliform	Results E.Coli	Chlorine (mg/l) Total Free	
12-13-14	1200	R	122 Dallas Rd.	L-04	A	A	1.22	1.20
Total Routine Samples Analyzed: 2					Signed: 		Date: 1/5/15	
Monitoring Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No			
MCL Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No			

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colilert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 2 well) 12019					Laboratory Name Lakeland Laboratories			
Street Address								
City			Zip		Certification Number 00400			
County Taney			ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample	Results	Chlorine (mg/l)	
					Total Coliform	E.Coli	Total	Free
12-13-14	1230	R	336 Dallas	L-07	A	A	1.21	1.18
Total Routine Samples Analyzed: 2					Signed: <i>Mark P. Smith</i>		Date: <i>1/5/15</i>	
Monitoring Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No			
MCL Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No			

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Collert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 1 well) 12155					Laboratory Name Lakeland Laboratories			
Street Address								
City			Zip		Certification Number 00400			
County Taney			ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results		Chlorine (mg/l)	
					Total Coliform	E.Coll	Total	Free
01-13-15	1400	R	140 Cox Rd.	L-03	A	A	1.13	1.11
Total Routine Samples Analyzed: 2					Signed: <i>Mark P. Smith</i>		Date: <i>1/26/15</i>	
Monitoring Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No			
MCL Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No			

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colilert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 2 well) 12102					Laboratory Name Lakeland Laboratories			
Street Address								
City			Zip		Certification Number 00400			
County Taney			ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results		Chlorine (mg/l)	
					Total Coliform	E.Coli	Total	Free
01-13-15	1415	R	432 Cox Rd.	L-11	A	A	1.24	1.21
Total Routine Samples Analyzed: 2					Signed <i>Mark S. Smith</i>		Date: <i>1/26/15</i>	
Monitoring Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No			
MCL Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No			

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Collert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 2 well) 12159					Laboratory Name Lakeland Laboratories			
Street Address								
City			Zip		Certification Number 00400			
County Taney			ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results Total Coliform	Results E.Coli	Chlorine (mg/l) Total Free	
02-14-15	1230	R	432 Cox Rd.	L-11	A	A	1.25	1.22
Total Routine Samples Analyzed: 2					Signed: <i>Mark P. Smith</i>		Date: <i>2/17/15</i>	
Monitoring Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No			
MCL Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No			

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Collert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 1 well)					12144					Laboratory Name Lakeland Laboratories			
Street Address													
City					Zip					Certification Number 00400			
County Taney					ID Number MO5036117								
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results		Chlorine (mg/l)						
					Total Colform	E.Coli	Total	Free					
02-14-15	1300	R	140 Cox Rd.	L-03	A	A	1.82	1.80					
Total Routine Samples Analyzed: 2					Signed: <i>Mark P. Smith</i>			Date: <i>2/17/15</i>					
Monitoring Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No								
MCL Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No								

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colifert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report


Public Water System Name Moore Bend (on # 1 well) 12178					Laboratory Name Lakeland Laboratories			
Street Address								
City			Zip		Certification Number 00400			
County Taney			ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample	Results	Chlorine (mg/l)	
					Total Coliform	E.Coli	Total	Free
03-08-15	1200	R	140 Cox Rd.	L-03	A	A	1.53	1.51
Total Routine Samples Analyzed: 2					Signed: <i>Mark Smith</i>		Date: <i>3/11/15</i>	
Monitoring Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No			
MCL Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No			

ENZYME SUBSTRATE COLIFORM TEST
 SM-9223 ESM21 (Collifert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 2 well) 12165					Laboratory Name Lakeland Laboratories			
Street Address					Certification Number 00400			
City			Zip					
County Taney			ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results		Chlorine (mg/l)	
					Total Coliform	E.Coli	Total	Free
03-08-15	1240	R	336 Dallas Rd.	L-07	A	A	1.12	1.10
Total Routine Samples Analyzed: 2					Signed: 		Date: 3/11/15	
Monitoring Violation		<input type="checkbox"/>	Yes	x	No			
MCL Violation		<input type="checkbox"/>	Yes	x	No			

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colilert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 1 well) 12267					Laboratory Name Lakeland Laboratories			
Street Address								
City			Zip		Certification Number 00400			
County Taney			ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample	Results	Chlorine (mg/l)	
					Total Colform	E.Coli	Total	Free
04-02-15	1100	R	140 Cox Rd.	L-03	A	A	1.60	1.56
Total Routine Samples Analyzed: 2					Signed:		Date:	
Monitoring Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No			
MCL Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No			

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Collert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 2 well) 12209					Laboratory Name Lakeland Laboratories			
Street Address								
City			Zip		Certification Number 00400			
County Taney			ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results		Chlorine (mg/l)	
					Total Coliform	E.Coll	Total	Free
04-02-15	1130	R	336 Dallas Rd.	L-07	A	A	2.02	1.99
Total Routine Samples Analyzed: 2					Signed: _____		Date: _____	
Monitoring Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No			
MCL Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No			

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colilert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 1 well) 12426					Laboratory Name Lakeland Laboratories			
Street Address								
City			Zip		Certification Number 00400			
County Taney			ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample	Results	Chlorine (mg/l)	
					Total Colform	E.Coli	Total	Free
05-03-15	1100	R	140 Cox Rd.	L-03	A	A	1.50	1.40
Total Routine Samples Analyzed: 2					Signed: _____		Date: _____	
Monitoring Violation		<input type="checkbox"/>	Yes	x	No			
MCL Violation		<input type="checkbox"/>	Yes	x	No			

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Collert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 2 well) 12452					Laboratory Name Lakeland Laboratories			
Street Address								
City			Zip		Certification Number 00400			
County Taney			ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample	Results	Chlorine (mg/l)	
					Total Colform	E.Coli	Total	Free
05-03-15	1115	R	433 Cox Rd.	L-	A	A	1.6	1.50
Total Routine Samples Analyzed: 2					Signed: _____		Date: _____	
Monitoring Violation		<input type="checkbox"/>	Yes	x	No			
MCL Violation		<input type="checkbox"/>	Yes	x	No			

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Collert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 1 well) 12549					Laboratory Name Lakeland Laboratories					
Street Address										
City				Zip		Certification Number 00400				
County Taney				ID Number MO5036117						
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Total Colform	Results E.Coli	Chlorine (mg/l) Total Free			
06-12-15	1100	R	140 Cox Rd.	L-03	A	A	1.88	1.85		
Total Routine Samples Analyzed: 2					Signed: _____			Date: _____		
Monitoring Violation		<input type="checkbox"/>	Yes	x	No					
MCL Violation		<input type="checkbox"/>	Yes	x	No					

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Collert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 2 well) 12538					Laboratory Name Lakeland Laboratories				
Street Address									
City			Zip		Certification Number 00400				
County Taney			ID Number MO5036117						
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results		Chlorine (mg/l)		
					Total Coliform	E.Coli	Total	Free	
06-12-15	1130	R	433 Cox Rd.	L-	A	A	1.32	1.3	
Total Routine Samples Analyzed: 2					Signed:		Date:		
Monitoring Violation		<input type="checkbox"/>	Yes	x	No				
MCL Violation		<input type="checkbox"/>	Yes	x	No				

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Collert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 1 well) 99454					Laboratory Name Lakeland Laboratories				
Street Address									
City				Zip		Certification Number 00400			
County Taney				ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results		Chlorine (mg/l)		
					Total Colform	E.Coli	Total	Free	
07-19-15	1230	R	140 Cox Rd.	L-03	A	A	1.62	1.6	
Total Routine Samples Analyzed: 2					Signed: <i>Bert Brewer</i>			Date:	
Monitoring Violation		<input type="checkbox"/>	Yes	x	No				
MCL Violation		<input type="checkbox"/>	Yes	x	No				

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colilert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 2 well) 12675					Laboratory Name Lakeland Laboratories			
Street Address								
City			Zip		Certification Number 00400			
County Taney			ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample	Results	Chlorine (mg/l)	
					Total Colform	E.Coli	Total	Free
07-19-15	1300	R	433 Cox Rd.	L-	A	A	1.41	1.4
Total Routine Samples Analyzed: 2					Signed: <i>Bert Brower</i>		Date:	
Monitoring Violation		<input type="checkbox"/>	Yes	x	No			
MCL Violation		<input type="checkbox"/>	Yes	x	No			

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Collert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 1 well) 12705					Laboratory Name Lakeland Laboratories				
Street Address									
City			Zip		Certification Number 00400				
County Taney			ID Number MO5036117						
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results		Chlorine (mg/l)		
					Total Colform	E.Coli	Total	Free	
08/02/15	1045	R	140 Cox Rd.	L-03	A	A	0.92	0.9	
Total Routine Samples Analyzed: 2					Signed: <i>Best Brower</i>		Date: 09/12/15		
Monitoring Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No				
MCL Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No				

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colilert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 2 well) 12707					Laboratory Name Lakeland Laboratories				
Street Address									
City				Zip		Certification Number 00400			
County Taney				ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results		Chlorine (mg/l)		
					Total Coliform	E.Coli	Total	Free	
08/02/15	1110	R	433 Cox Rd.	L-	A	A	1.5	1.49	
Total Routine Samples Analyzed: 2					Signed: <i>Bert Brower</i>			Date: 09/12/15	
Monitoring Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No				
MCL Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No				

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colifert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 1 well) 12807					Laboratory Name Lakeland Laboratories			
Street Address								
City			Zip		Certification Number 00400			
County Taney			ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results		Chlorine (mg/l)	
					Total Coliform	E.Coli	Total	Free
09/10/15	0700	R	140 Cox Rd.	L-03	A	A	1.01	1.0
Total Routine Samples Analyzed: 2					Signed: <i>Best Brower</i>		Date: 10/01/15	
Monitoring Violation			Yes	x	No			
MCL Violation			Yes	x	No			

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colifert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 2 well) 12678					Laboratory Name Lakeland Laboratories				
Street Address									
City				Zip		Certification Number 00400			
County Taney				ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results		Chlorine (mg/l)		
					Total Coliform	E.Coli	Total	Free	
09/10/15	0730	R	433 Cox Rd.	L-	A	A	1.23	1.22	
Total Routine Samples Analyzed: 2					Signed: <i>Best Brower</i>			Date: 10/01/15	
Monitoring Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No				
MCL Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No				

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colilert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 1 well) 12995					Laboratory Name Lakeland Laboratories				
Street Address									
City				Zip		Certification Number 00400			
County Taney				ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results		Chlorine (mg/l)		
					Total Coliform	E.Coli	Total	Free	
10/14/15	1415	R	140 Cox Rd.	L-03	A	A	1.22	1.2	
Total Routine Samples Analyzed: 2					Signed: <i>Bert Brower</i>			Date: 11/01/15	
Monitoring Violation			Yes	x	No				
MCL Violation			Yes	x	No				

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Collert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 2 well) 12878					Laboratory Name Lakeland Laboratories				
Street Address									
City			Zip		Certification Number 00400				
County Taney			ID Number MO5036117						
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results		Chlorine (mg/l)		
					Total Colform	E.Coll	Total	Free	
10/14/15	1430	R	433 Cox Rd.	L-	A	A	1.32	1.3	
Total Routine Samples Analyzed: 2					Signed: <i>Bert Brower</i>		Date: 11/01/15		
Monitoring Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No				
MCL Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No				

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colilert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 2 well) 13123					Laboratory Name Lakeland Laboratories				
Street Address									
City			Zip		Certification Number 00400				
County Taney			ID Number MO5036117						
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results		Chlorine (mg/l)		
					Total Coliform	E.Coll	Total	Free	
11/143/15	1400	R	433 Cox Rd.	L-	A	A	1.34	1.32	
Total Routine Samples Analyzed: 2					Signed: <i>Bert Brewer</i>		Date: 12/01/15		
Monitoring Violation			Yes	x	No				
MCL Violation			Yes	x	No				

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colilert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 1 well) 13125					Laboratory Name Lakeland Laboratories				
Street Address									
City				Zip		Certification Number 00400			
County Taney				ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results		Chlorine (mg/l)		
					Total Colform	E.Coli	Total	Free	
11/13/15	1415	R	140 Cox Rd.	L-03	A	A	1.46	1.44	
Total Routine Samples Analyzed: 2					Signed: <i>Best Brower</i>			Date: 12/01/15	
Monitoring Violation			Yes	x	No				
MCL Violation			Yes	x	No				

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Collert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 1 well) 13166					Laboratory Name Lakeland Laboratories			
Street Address								
City			Zip		Certification Number 00400			
County Taney			ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results		Chlorine (mg/l)	
					Total Colform	E.Coli	Total	Free
12/06/15	0930	R	140 Cox Rd.	L-03	A	A	1.42	1.40
Total Routine Samples Analyzed: 2					Signed: <i>Bert Brower</i>		Date: 01/01/16	
Monitoring Violation		<input type="checkbox"/>	Yes	x	No			
MCL Violation		<input type="checkbox"/>	Yes	x	No			

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Collert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 2 well) 13005					Laboratory Name Lakeland Laboratories			
Street Address								
City			Zip		Certification Number 00400			
County Taney			ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results		Chlorine (mg/l)	
					Total Colform	E.Coli	Total	Free
12/06/15	0945	R	433 Cox Rd.	L-	A	A	1.22	1.20
Total Routine Samples Analyzed: 2					Signed: <i>Bert Brower</i>		Date: 01/01/16	
Monitoring Violation			Yes	x	No			
MCL Violation			Yes	x	No			

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Collert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 1 well) 13272					Laboratory Name Lakeland Laboratories				
Street Address									
City				Zip		Certification Number 00400			
County Taney				ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results		Chlorine (mg/l)		
					Total Coliform	E.Coli	Total	Free	
01/30/16	0930	R	140 Cox Rd.	L-03	A	A	1.66	1.68	
Total Routine Samples Analyzed: 2					Signed: <i>Best Brewer</i>			Date: 02/01/16	
Monitoring Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No				
MCL Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No				

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colifert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 2 well) 13164					Laboratory Name Lakeland Laboratories				
Street Address									
City				Zip		Certification Number 00400			
County Taney				ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results		Chlorine (mg/l)		
					Total Colform	E.Coli	Total	Free	
01/30/16	0945	R	433 Cox Rd.	L-	A	A	1.14	1.16	
Total Routine Samples Analyzed: 2					Signed: <i>Bert Brower</i>			Date: 02/01/16	
Monitoring Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No				
MCL Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No				

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colilert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 2 well) 13276					Laboratory Name Lakeland Laboratories				
Street Address									
City			Zip		Certification Number 00400				
County Taney			ID Number MO5036117						
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results		Chlorine (mg/l)		
					Total Colform	E.Coli	Total	Free	
02/09/16	1030	R	433 Cox Rd.	L-	A	A	1.26	1.24	
Total Routine Samples Analyzed: 2					Signed: <i>Bert Brower</i>		Date: 03/01/16		
Monitoring Violation			Yes	x	No				
MCL Violation			Yes	x	No				

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colilert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 1 well) 13230					Laboratory Name Lakeland Laboratories			
Street Address								
City			Zip		Certification Number 00400			
County Taney			ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results		Chlorine (mg/l)	
					Total Colform	E.Coli	Total	Free
02/09/16	1050	R	140 Cox Rd.	L-03	A	A	1.46	1.44
Total Routine Samples Analyzed: 2					Signed: <i>Best Brewer</i>		Date: 03/01/16	
Monitoring Violation			Yes	x	No			
MCL Violation			Yes	x	No			

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colilert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 2 well) 13343					Laboratory Name Lakeland Laboratories				
Street Address									
City			Zip		Certification Number 00400				
County Taney			ID Number MO5036117						
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results		Chlorine (mg/l)		
					Total Colform	E.Coli	Total	Free	
03/11/16	1435	R	432 Cox Rd.	L-11	A	A	0.95	0.93	
Total Routine Samples Analyzed: 2					Signed: <i>Bert Brower</i>		Date: 04/01/16		
Monitoring Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No				
MCL Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No				

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colilert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 1 well) 13344					Laboratory Name Lakeland Laboratories				
Street Address									
City				Zip		Certification Number 00400			
County Taney				ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results		Chlorine (mg/l)		
					Total Coliform	E.Coll	Total	Free	
03/13/16	1225	R	140 Cox Rd.	L-03	A	A	1.38	1.36	
Total Routine Samples Analyzed: 2					Signed: <i>Bert Bruzver</i>			Date: 04/01/16	
Monitoring Violation			Yes	x	No				
MCL Violation			Yes	x	No				

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colilert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 1 well) 13454					Laboratory Name Lakeland Laboratories				
Street Address									
City				Zip		Certification Number 00400			
County Taney				ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results		Chlorine (mg/l)		
					Total Colform	E.Coli	Total	Free	
04/01/16	1425	R	163 Cox Rd.	12-DS	A	A	1.24	1.22	
Total Routine Samples Analyzed: 2					Signed: <i>Bert Brewer</i>			Date: 05/01/16	
Monitoring Violation			Yes	x	No				
MCL Violation			Yes	x	No				

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Collert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 2 well) 13453					Laboratory Name Lakeland Laboratories				
Street Address									
City				Zip		Certification Number 00400			
County Taney				ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results		Chlorine (mg/l)		
					Total Coliform	E.Coli	Total	Free	
04/01/16	1445	R	336 Dallas	07-DS	A	A	0.84	0.82	
Total Routine Samples Analyzed: 2					Signed: <i>Best Brewer</i>			Date: 05/01/16	
Monitoring Violation			Yes	x	No				
MCL Violation			Yes	x	No				

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colilert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 1 well)					13612					Laboratory Name Lakeland Laboratories			
Street Address										Certification Number 00400			
City					Zip								
County Taney					ID Number MO5036117								
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results		Chlorine (mg/l)						
					Total Colform	E.Coli	Total	Free					
05/21/16	1430	R	163 Cox Rd.	12-DS	A	A	1.64	1.62					
Total Routine Samples Analyzed: 2					Signed: <i>Bert Brower</i>				Date: 06/01/16				
Monitoring Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No								
MCL Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No								

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colilert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 1 well) 13653					Laboratory Name Lakeland Laboratories			
Street Address								
City			Zip		Certification Number 00400			
County Taney			ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample	Results	Chlorine (mg/l)	
					Total Colform	E.Coli	Total	Free
06/28/16	1430	R	163 Cox Rd.	12-DS	A	A	1.93	1.91
Total Routine Samples Analyzed: 2					Signed: <i>Bert Brower</i>		Date: 07/01/16	
Monitoring Violation		<input type="checkbox"/>	Yes	x	No			
MCL Violation		<input type="checkbox"/>	Yes	x	No			

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colilert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 1 well)					Laboratory Name Lakeland Laboratories				
Street Address 13771					Certification Number 00400				
City			Zip						
County Taney			ID Number MO5036117						
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results		Chlorine (mg/l)		
					Total Colform	E.Coli	Total	Free	
07/06/16	0800	R	163 Cox Rd.	12-DS	A	A	1.41	1.40	
Total Routine Samples Analyzed: 2					Signed: <i>Bert Brower</i>		Date: 08/01/16		
Monitoring Violation		<input type="checkbox"/>	Yes	x	No				
MCL Violation		<input type="checkbox"/>	Yes	x	No				

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colilert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 1 well)					Laboratory Name Lakeland Laboratories				
Street Address 13866									
City			Zip		Certification Number 00400				
County Taney			ID Number MO5036117						
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Total Colform	Results E.Coli	Chlorine (mg/l)		
08/02/16	0754	R	163 Cox Rd.	12-DS	A	A	1.41	1.57	
Total Routine Samples Analyzed: 2					Signed: <i>Bert Brower</i>		Date: 09/01/16		
Monitoring Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No				
MCL Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No				

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colilert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 1 well)					Laboratory Name Lakeland Laboratories			
Street Address 13984								
City			Zip		Certification Number 00400			
County Taney			ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample	Results	Chlorine (mg/l)	
					Total Colform	E.Coli	Total	Free
09/24/16	1710	R	140 Cox Rd.	03-DS	A	A	1.04	1.02
Total Routine Samples Analyzed: 2					Signed: <i>Bert Brower</i>		Date: 10/01/16	
Monitoring Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No			
MCL Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No			

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colilert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 1 well)					14025					Laboratory Name Lakeland Laboratories			
Street Address										Certification Number 00400			
City					Zip								
County Taney					ID Number MO5036117								
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample	Results	Chlorine (mg/l)						
					Total Colform	E.Coli	Total	Free					
10/20/16	1715	R	140 Cox Rd.	03-DS	A	A	1.44	1.42					
Total Routine Samples Analyzed: 2					Signed: <i>Bert Brower</i>			Date: 11/01/16					
Monitoring Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No								
MCL Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No								

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colilert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 2 well)					13621					Laboratory Name Lakeland Laboratories			
Street Address													
City					Zip					Certification Number 00400			
County Taney					ID Number MO5036117								
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results		Chlorine (mg/l)						
					Total Colform	E.Coli	Total	Free					
05/21/16	1435	R	336 Dallas	07-DS	A	A	1.52	1.50					
Total Routine Samples Analyzed: 2					Signed: <i>Bert Brower</i>				Date: 06/01/16				
Monitoring Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No								
MCL Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No								

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colilert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 2 well) 13724					Laboratory Name Lakeland Laboratories			
Street Address								
City			Zip		Certification Number 00400			
County Taney			ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample	Results	Chlorine (mg/l)	
					Total Colform	E.Coli	Total	Free
06/28/16	1030	R	336 Dallas	07-DS	A	A	0.74	0.72
Total Routine Samples Analyzed: 2					Signed: <i>Bert Brower</i>		Date: 07/01/16	
Monitoring Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No			
MCL Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No			

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colilert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 2 well) 13784					Laboratory Name Lakeland Laboratories			
Street Address								
City			Zip		Certification Number 00400			
County Taney			ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Total Colform	Results E.Coli	Chlorine (mg/l) Total Free	
07/06/16	0830	R	336 Dallas	07-DS	A	A	1.65	1.63
Total Routine Samples Analyzed: 2					Signed: <i>Bert Brower</i>		Date: 08/01/16	
Monitoring Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No			
MCL Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No			

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colilert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 2 well) 13864					Laboratory Name Lakeland Laboratories			
Street Address								
City			Zip		Certification Number 00400			
County Taney			ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample	Results	Chlorine (mg/l)	
					Total Colform	E.Coli	Total	Free
08/02/16	0810	R	336 Dallas	07-DS	A	A	0.90	1.45
Total Routine Samples Analyzed: 2					Signed: <i>Bert Brower</i>		Date: 09/01/16	
Monitoring Violation			Yes	x	No			
MCL Violation			Yes	x	No			

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Collert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 2 well)					13985					Laboratory Name Lakeland Laboratories			
Street Address													
City					Zip					Certification Number 00400			
County Taney					ID Number MO5036117								
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample Results		Chlorine (mg/l)						
					Total Coliform	E.Coli	Total	Free					
09/24/16	1720	R	163 Cox Rd.	12-DS	A	A	0.97	0.94					
Total Routine Samples Analyzed: 2					Signed: <i>Bert Brower</i>				Date: 10/01/16				
Monitoring Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No								
MCL Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No								

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colilert®)



786 Croley Blvd. • P.O. Box 1080 • Nixa, MO 65714 • 417 725-2670

Missouri Department of Natural Resources
 Division of Environmental Quality
Microbiological Analysis Report

Public Water System Name Moore Bend (on # 2 well) 13986					Laboratory Name Lakeland Laboratories			
Street Address								
City			Zip		Certification Number 00400			
County Taney			ID Number MO5036117					
Sample Date Mo/Day/Yr	Time	Sample Type	Collection Point	Sample Location ID	Sample	Results	Chlorine (mg/l)	
					Total Colform	E.Coli	Total	Free
10/20/16	1720	R	551 Dallas Road	17-DS	A	A	1.60	1.56
Total Routine Samples Analyzed: 2					Signed: <i>Bert Brower</i>		Date: 11/01/16	
Monitoring Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No			
MCL Violation		<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No			

ENZYME SUBSTRATE COLIFORM TEST
 SM 9223 ESM21 (Colilert®)