


Appendix:

Valve installation 12/26/24

Old valve:




Shelving was disassembled prior to installation of new valve.



12/26/24. New Valve Installation by Loellke plumbing/ American MO Water.



Installed Valve




Water Flood incident 2/26/2026











Hvac and water tank under water







2/9/2026: the curbside valve was also shut off by Am Mo Water company. However, water was still flowing out of the pipes (slow dribble) when I was there between 3/3/2026 and 3/5/2026 (below). Saturation and mold everywhere upstairs and down. Kitchen sink and basement below.



4/4/2026 my own photo. This is the water from the main curbside shutoff being off since Feb 9/2026



Examples of Mold between Feb 9 and March 5 2026.




My Personal photo on March 4th, 2026 of the defective valve



3/10/2026: Valve replaced by Aria Plumbing.

Tuesday 3/10/2026, the dysfunctional valve was extracted and replaced with a 3/4 ball valve as described above.



And the extracted valve from MO American Water Company:

