LNC CONTRACTING LLC

Property Maintenance & Renovation Services

Property Visit and Water Pressure Test Documentation

Property: 9707 Portage
Visit: October 12, 2026, approximately 5:00 PM

Hi Andrew,

Per your request, I am providing written documentation of my visit to the property located at **9707 Portage on October 12, 2026, at approximately 5:00 PM.**

During this visit, I conducted a water pressure test using a pressure-testing gauge. **The gauge registered a reading of 120 PSI (pounds per square inch).**

I recorded video footage documenting the pressure test and the gauge reading.

During the same visit, I also observed that the **curb stop appeared to have been recently capped, locked, and marked with blue paint.** These conditions differed from my previous observations of the property.

This statement is provided as a factual record of the testing performed and the conditions I personally observed at the property on the date and time indicated above.

Sincerely,

LNC Contracting LLC
Property Maintenance & Renovation Services